



Coastal Protection and
Restoration Authority of Louisiana

State of Louisiana

Coastal Protection and Restoration Authority

2012 Operations, Maintenance, and Monitoring Report

for

East Sabine Lake Hydrologic Restoration (CS-32)

State Project Number CS-32
Priority Project List 10

July 2012
Cameron Parish

Prepared by:
Tommy McGinnis
Darrell Pontiff
And
Jody White



Operations Division
Lafayette Field Office
635 Cajundome Boulevard
Lafayette, LA 70506



Suggested Citation:

McGinnis, T., Pontiff, T., and White, J. 2012. *2012 Operations, Maintenance and Monitoring Report for East Sabine Lake Hydrologic Restoration (CS-32)*. Coastal Protection and Restoration Authority of Louisiana, Lafayette, Louisiana. 26 pp plus Appendices.

2012 Operations, Maintenance, and Monitoring Report
For
East Sabine Lake Hydrologic Restoration (CS-32)

Table of Contents

I. Introduction.....	1
II. Maintenance Activity.....	4
a. Project Feature Inspection Procedures	4
b. Inspection Results	5
c. Maintenance Recommendations	5
i. Immediate/Emergency	5
ii. Programmatic/Routine.....	5
d. Maintenance History	5
III. Operation Activity	6
a. Operation Plan.....	6
b. Actual operations	6
IV. Monitoring Activity	6
a. Monitoring Goals	6
b. Monitoring Elements	7
c. Preliminary Monitoring Results and Discussion.....	8
V. Conclusions.....	25
a. Project Effectiveness.....	25
b. Recommended Improvements	25
c. Lessons Learned.....	25
VI. References.....	25
VII. Appendices	28
a. Appendix A (Inspection Photographs).....	28
b. Appendix B (Three Year Budget Projection)	33
c. Appendix C (Field Inspection Notes)	34
d. Appendix D (NRCS Terrace Inspection Field Notes)	35

Preface

The East Sabine Lake Hydrologic Restoration Project (CS-32) 2012 Operations, Maintenance, and Monitoring (OM&M) report includes monitoring data collected through September 2011. A field inspection was not conducted by CPRA staff in the 2011-2012 inspection period; however, the Maintenance History is included.

This report is the 1st report in a series of OM&M reports. For additional information on environmental assessments, ecological reviews, and annual inspection reports (2009/2010 and 2010/2011) please refer to the LDNR-SONRIS web site (http://sonris.com/direct.asp?path=/sundown/cart_prod/cart_bms_avail_documents_f).

I. Introduction

The CS-32 project area is parceled throughout the Sabine National Wildlife Refuge (NWR) in western Cameron Parish, Louisiana. The area is bounded on the west by the east shoreline of Sabine Lake, on the north by the approximate northern boundary of Sabine NWR, on the east by the Burton-Sutton Canal, and on the south by Starks South Canal (figure 1). The project area is comprised of approximately 8,248 acres (3,338 ha) of intermediate and brackish marsh (Sasser et al. 2008), the latter generally located along the shoreline of Sabine Lake and extending inland for 1 to 2 miles (1.6 to 3.2 km). In 2004, approximately 66% of the project area was shallow open water habitat (Balkum et al. 2003; Clark and Mazourek 2004).

Land loss within the project area has been attributed to saltwater intrusion from Sabine Lake and Calcasieu Ship Channel via Black Bayou, Green's Bayou, Willow Bayou, the Gulf Intracoastal Waterway (GIWW), and the construction of oilfield and boundary/drainage canals (Louisiana Coastal Wetlands Conservation and Restoration Task Force 2002). The average land loss rate for the project area from 1983 to 1990 has been estimated at 0.2% per year (Dunbar et al. 1992). Coast 2050 analysis predicted continued land loss within the project area and identified Sabine Lake shoreline erosion, interior marsh loss along the edges of open water areas, and altered hydrologic regimes as the primary causes (Louisiana Coastal Wetlands Conservation and Restoration Task Force and the Wetlands Conservation and Restoration Authority [LCWCRTF & WCRA] 1999).

The East Sabine Lake Hydrologic Restoration project (CS-32) is designed to address these causes of land loss by controlling channel-induced saltwater intrusion and water-level fluctuations, by creating marsh in shallow open water areas, and by reducing and/or stopping erosion at a critical reach along the eastern Sabine Lake shoreline. These proposed approaches are consistent with the Coast-wide Common Strategies and Regional Ecosystem Strategies identified in Coast 2050 (LCWCRTF & WCRA 1998). The CS-32 project is from Project Priority List 10 of the Coastal Wetlands Planning, Protection, and Restoration Act (CWPPRA) and is federally co-sponsored by the US Fish and Wildlife Service and USDA – Natural Resource Conservation Service.

Project Goals and Strategies

1. Reduce salinity and water level variability by constructing a rock weir at 1 ft below average water elevation (or 0.0 ft NAVD 88) in Pines Ridge Bayou at the intersection of an east-west oil and gas canal that connects Pines Ridge Bayou to Sabine Lake.
2. Reduce salinity and water level variability through the construction of a rock weir at 1 ft below average water elevation (or 0.0 feet NAVD 88) at Double Island Gully intersection with Starks South Canal. This goal is no longer valid because the weir was removed in 2010 by the Cameron Parish Drainage District.
3. Stop Sabine Lake shoreline erosion by constructing a 3,000 linear ft, foreshore, rock dike (3 ft NAVD 88 in elevation) north of the mouth of Willow Bayou at Sabine Lake.
4. Create 127 acres (51.3 ha) of emergent marsh and reduce area salinity through the construction of approximately 229,000 linear feet (69,062 m) of vegetated earthen terraces in open water areas north and south of Greens Lake.
5. Increase opportunity for fisheries and estuarine organism access into the western portion of Sabine NWR and restore Bridge Bayou's hydrologic integrity through the installation of three 24-inch diameter culverts with stop logs and flapgates at the intersection of Bridge Bayou, the cattle walkway, and Grays Ditch.




Figure 1. East Sabine Hydrologic Restoration (CS-32) project area showing project boundaries, project features, and monitoring (CS-32 and CRMS) stations in or near the project area.

II. Maintenance Activity

a. Project Feature Inspection Procedures

The purpose of the annual inspection of the East Sabine Lake Hydrologic Restoration Project (CS-32) is to evaluate the constructed project features to identify any deficiencies and prepare a report detailing the condition of project features and recommended corrective actions needed. Should it be determined that corrective actions are needed, CPRA shall provide, in the report, a detailed cost estimate for engineering, design, supervision, inspection, and construction contingencies, and an assessment of the urgency of such repairs. As noted in Appendices B, C, and D, initial project goals included documenting inspections with photographs, creating a three-year budget projection, and taking field inspection notes.

Typically, an inspection team consisting of two representatives of CPRA and one representative of the Natural Resources Conservation Service (NRCS) and US Fish and Wildlife Service (USFWS) perform annual visual inspections. If damage is apparent, CPRA, NRCS, and USFWS assign a team to perform a detailed inspection and report on the findings. The team documents the condition of the project features and may employ a survey party to make detailed measurements. An annual inspection of all project features was not performed in the 2011-2012 cycle; however, a brief reconnaissance trip to view the vegetation on the terraces was conducted on November 1, 2011 by CPRA, NRCS and USFWS personnel.

Primary Project Features:

1. A 40-ft wide, low-level (0.0 ft, NAVD88) rock weir in Pines Ridge Bayou was constructed in 2005 to attenuate water fluctuations from Sabine Lake.
2. 3000 linear feet, rock, dike along Sabine Lake shoreline north of the mouth of Willow Bayou was constructed in 2005 to prevent erosion and was segmented to allow for fish and wildlife access in 2007.
3. A low-level (0.0 ft, NAVD88) rock weir at the Double Island Gully and Starks South Canal intersection was constructed in 2005; however, it was removed by the Cameron Parish Drainage District in 2010.
4. Approximately 229,000 feet of vegetated earthen terraces in large, shallow, open-water areas north and south of Greens Lake were constructed from 2005-2009 to increase marsh acreage, disrupt wind fetch waves, improve water quality, and reduce erosion of surrounding shorelines. Two phases of terraces were constructed as a result of a reallocation of funds within the project features. The originally planned terraces, (CU-1) constructed from 2005-2006, had a 15 foot-wide crown width and 4:1 side slopes; the additional section of terraces (CU-1A), constructed from 2008-2009, were constructed with a 9 foot-wide crown width and 3:1 side slope. Both construction phases were interrupted by hurricanes.

CU-1	2005 Installation of 171,000 LF of terraces and 142,500 vegetative transplants was 54 % complete when interrupted by Hurricanes Katrina and Rita.
------	---

CU-1	2006	Resumed work post Hurricane Rita to complete the remaining terraces and to replant damaged terraces with an additional 42,500 transplants.
CU-1A	2008	An additional 50,000 LF of terraces with 41,000 transplants was nearly complete when interrupted by Hurricane Ike; the northern most row was not completed.
CU-1A	2009	Replanted damaged CU-1A terraces with 32,200 transplants.

5. Three, 24-inch diameter culverts with sluice gates in Bridge Bayou at Grays Ditch were constructed in 2005 to improve fish and wildlife access.

b. Inspection Results

An annual field inspection was not conducted by CPRA staff in the 2011-2012 inspection period. However, a reconnaissance trip to assess the vegetation on the terraces was conducted on November 1, 2011. Due to the time constraints, the whole project area was traveled but an intense row by row assay of conditions was not performed. Findings of the plant condition and percent cover were mixed. Some rows and terrace segments had 100% cover with robust plant growth at the toes of the terrace segments, some had short to long stretches where vegetation remained and the plantings appeared vigorous, but much intermixed with dead material. Some segments had partial cover with the plant condition ranging from poor to very good, and a few segments had almost no cover. It was decided that because the area was still being impacted by a prolonged exceptional drought, the plantings would be evaluated again at the end of the 2012 growing season.

c. Maintenance Recommendations

- i. Immediate/ Emergency Repairs**
- ii. Programmatic/ Routine Repairs**

No maintenance is recommended.

d. Maintenance History

General Maintenance: Below is a summary of completed maintenance projects and operation tasks performed on the constructed project features since completion of the East Sabine Lake Hydrologic Restoration Project (CS-32).

2007 - Hurricane Rita Repairs to Pines Ridge Bayou Weir and Willow Bayou Rock Realignment – F. Miller Construction - This maintenance project included placing 146 tons of R-300 rock rip-rap along with 794 LF of PVC sheet pile wall at Pines Ridge Bayou Weir. Rock realignment was performed at each end of the dike and rock gaps were placed in two other locations along the shoreline. This maintenance project was a result of damages sustained from Hurricane Rita in 2005 and other maintenance work required.

The costs associated with the engineering, design and construction of the Pines Ridge Bayou and Willow Bayou Maintenance Project are as follows:

Construction (CWPPRA)	\$ 74,700.00
Construction (FEMA: Pines Ridge Weir repair)	\$143,032.00
E & D, construction oversight, as-builts	\$ 35,026.65
Project Total	\$252,758.65

III. Operation Activity

a. Operation Plan

b. Actual Operations

There are no active operations associated with this project.

IV. Monitoring Activity

The CWPPRA projects authorized for construction after August 14, 2003 are monitored with Coastwide Reference Monitoring System - *Wetlands* (CRMS) stations, other existing data collection, and any additional data collection specifically added to the project and funded separately from the normal monitoring. One CRMS site (CRMS0660) is located within the Greens Lake terrace area, and seven sites (CRMS0665, 0665, 0669, 0683, 0684, 2154, 2156, and 2189) located in the surrounding marsh serve as suitable references (figure 1). No CRMS sites are within the small area of impact area around the weirs; therefore, project-specific sondes will be deployed for a year (October 2012 – September 2013) at the Pines Ridge structure to monitor salinity and water-level variability differences inside and outside of the affected area.

a. Monitoring Goals

The East Sabine Lake (CS-32) project is classified as a marsh restoration, hydrologic restoration, and shoreline protection project. Land area is expected to increase with the addition of terraces north and south of Greens Lake. Through the use of passive water control structures and terraces, a more beneficial hydrology is expected in the vicinity of Pines Ridge and Greens Lake. In the Pines Ridge area, the low-level weir is expected to attenuate rapid water fluctuations and salt water intrusion from Sabine Lake caused by artificial channel connections that unnaturally increase hydrologic exchange. The rock dike along Sabine Lake is expected to stop erosion.

The specific measurable goals established to evaluate the effectiveness of the project are:

1. Evaluate land area changes in the project area, especially the terraced areas around Greens Lake.
2. Evaluate water-level variability within Pines Ridge and Greens Lake area.
3. Evaluate water salinity within Pines Ridge area and Greens Lake.
4. Evaluate shoreline change along Sabine Lake behind the gapped, foreshore, rock dike.

b. Monitoring Elements

The following monitoring elements will provide the information necessary to evaluate the specific goals listed above:

CS-32 Land Change

To evaluate land area changes in the project area, land/water ratio will be estimated for each project area (Greens Lake terraces, foreshore dike along Sabine Lake, and water control structures at Pines Ridge, Double Island Gully, and Bridge Bayou) from available aerial photography minimum of 1 m² resolution collected around years 1 (2008), 5, 10, and 20 post construction. The photography will be processed by National Wetlands Research Center (NWRC) personnel using standard operating procedures through GIS analysis (Steyer et al. 1995, revised 2000). In addition, land change of the project area as a whole will be assessed from land/water data interpreted from TM satellite imagery (30 m² resolution) which is stored on the CRMS Viewer website (http://www.lacoast.gov/crms_viewer/); pre and post construction comparisons will be made, and inferences will be drawn from project area (CS-32) and basin (Calcasieu/Sabine) comparisons.

CS-32 Hydrology

To assess the effectiveness of Greens Lake terraces on decreasing water-level variability and salinity, hourly water-level and salinity recordings were collected from hydrologic sondes near the Sabine Lake rim (lake), interior marsh ponds (reference), and a large, interior open water area around Greens Lake where the CS-32 terrace field was constructed (CS-32 terraces). The hydrologic data were grouped over time by a preconstruction time period and three post construction periods (one before and two after Hurricane Ike); each time period covered 1 year except the first post construction/pre Hurricane Ike period was 7 months. Time periods were used that had sufficient data from all three locations; reconstruction of CRMS sites following Hurricane Ike was not complete until the summer of 2009. The preconstruction time period was collected from project specific sondes that were used for project planning purposes, and the post construction periods were collected from CRMS sites in similar hydrologic settings (Table 1, figure 1). Data were summarized on a daily basis; water-level range was calculated for each day, and salinity was averaged for each day. The daily data were analyzed with a full-factorial (location × time period) Analysis of Variance (ANOVA). Differences within significant effects were determined with a Tukey's Honest Significant Difference (HSD) post test.

Table 1. Water level and salinity data were collected hourly from different sets of hydrologic sondes within similar hydrologic settings during preconstruction (project-specific planning stations) and post construction (CRMS stations).

Location	Preconstruction	Post Construction
Sabine Lake Rim (Lake)	CS32-03	CRMS0684
CS-32 Terrace Area	CS32-05	CRMS0660
Marsh Reference	CS32-06	CRMS0683

To assess the effectiveness of the Pines Ridge weir on decreasing water-level variability and salinity, hourly water-level and salinity recordings will be collected from a pair of sondes

positioned on either side of the structure from October 2012 through September 2013. Daily water-level range and mean salinity will be compared.

CS-32 Terrace Condition and Vegetation

The conditions of the natural and planted vegetation on the terraces have been qualitatively assessed by NRCS staff during O&M inspections. Field trip reports by Cindy Steyer detailing post Hurricane Rita assessments (October 27, 2005 and April 03, 2006), post Hurricane Ike assessment (February 06, 2009); replacement planting assessment (March 18, 2010), and a terrace assessment (October 06, 2010) are summarized, and the full reports are included as Appendix D.

CRMS Supplemental

Additional data are collected at CRMS-*Wetlands* stations which can be used as supporting or contextual information for this project. In addition to project/reference comparisons within the vicinity of project, comparisons to CRMS sites at hydrologic basin and marsh type scales coastwide can also be made. Spatial, vegetative, and hydrologic (surface and porewater) data representing the 1 km² area encompassing the CRMS stations were used in this report (Folse et al. 2012).

c. Preliminary Monitoring Results and Discussion

CS-32 Land Change

Prior to construction, the CS-32 project area lost land at a rate of 1.4% per year from 1956, when the project area was 97.8 % land, through 2004, when the project area was 41.5% land. Most of this historical loss occurred between 1956 and 1988 and was stimulated by damage from Hurricane Audrey in 1957 (Barras 2009) (figure 2). The land loss was further exacerbated by increased tidal influence (higher water-level and salinity fluctuations) into the interior marshes via the installation of interior canals that created hydraulic connectivity with perimeter water bodies including Sabine Lake to the west, the Calcasieu Ship Channel to the east, and Black Bayou to the north (figure 1).



Figure 2. Land change in the Calcasieu/Sabine basin 1956-2006 (adapted from Barras 2009).

Land change trends over the past 25 years show that CS-32 project area was slowly losing land prior to construction from 1985-2004 (figure 3). The construction of 127 acres of terraces around Greens Lake resulted in small land gains for CS-32 from 1985-2010 despite hurricanes Rita in 2005 and Ike in 2008 as land change increased by 0.08%/y (figure 3). During the same periods, the Calcasieu/Sabine (CS) basin was slowly gaining land prior to the hurricanes but lost land from 1985-2010 because of the hurricanes, and the land change rate changed by -0.15% per year (data modified with permission from Couvillion et al. 2011). Although the land loss trend in the time period following the hurricanes (2005-2010) is greater in the project area than in the CS basin, the addition of the terraces buffered the CS-32 project area against net land loss since 1985 (figure 3). A stronger recovery CS basin wide than in the CS-32 project area from 2009-2010 resulted in the difference between loss rates since 2005. Additional time will be helpful for assessing hurricane impacts and recovery.




Figure 3. Land area (%) was analyzed over 25 years (1985-2010) from satellite imagery for the Calcasieu/Sabine (CS) basin (solid lines) and the CS-32 project area (dashed lines). The trend lines represent the linear rate of land change (% land/y) prior to CS-32 construction and the hurricanes (1985-2004; blue lines), including CS-32 construction and hurricanes Rita in 2005 and Ike in 2008 (1985-2010; purple lines), and effects of the hurricanes (2005-2010; red lines). Positive land change rates indicate land gain whereas negative rates indicate land loss. The CS basin data was modified with permission from Couvillion et al. 2011.

Land area of the five CS-32 project areas is assessed from a minimum of 1 m² resolution aerial photography. Land and water was classified by USGS-NWRC from photography acquired in 2008 following construction of project features. The CS-32 project was 33.5 % (2764 acres) land in 2008 (figure 4). Land change in the project areas will be assessed over time.

Land expansion in the Sabine Lake Rock Dike area (Area 5) will be limited by the rock dike. Much of the area had converted from open water to land between construction in 2005 and the 2008 photography for the land-water classification. Mud flats have formed and vegetation has established behind the rock dike except for areas behind the gaps in the rock dike (both ends and two in the middle) which allow for fish and estuarine organisms access to the shoreline (figure 5). The rock dike did not prevent the breaching of Sabine Lake and Willow Bayou; however, subsequent mud flat formation and vegetation in the vicinity of the breach behind the rock dike is expected to diminish hydrologic exchange between the two water bodies.




Figure 4. Land and water classification of the CS-32 project areas (Area 1 – Pines Ridge, Area 2 – Bridge Bayou at Grays Ditch, Area 3 – Double Island Gully, Area 4 – Greens Lake Terraces, Area 5 – Sabine Lake Rock Dike at Willow Bayou) from 2008 (post construction Year 1).



Figure 5. Sabine Lake rock dike near Willow Bayou before construction in 2004 and after construction in 2005 (full rock dike), 2007 (gapped rock dike), and 2010 (vegetation and mud flat expansion). Note thin strip of land between Sabine Lake and Willow Bayou in 2004 and 2005 and subsequent breach in 2007 and 2010. Also note the conversion of open water to land over time.

CS-32 Hydrology

Water-level variability decreased in the Greens Lake area after construction of the terrace field. The statistical model was robust (adjusted $R^2 = 0.71$) and significant ($F_{11} = 833$; $p < 0.0001$), and the location \times time period interaction was significantly different ($F_6 = 183$; $p < 0.0001$). Water-level ranges near Sabine Lake were greater than the interior areas and slightly differed over time which is typical annual variability for open tidal systems. Water-level ranges in the reference interior marsh site were similar over all the time periods and were typically about 0.6 ft less than Sabine Lake. The significant interaction was driven by water-level ranges around Greens Lake that decreased by 0.38 ft following construction of the terraces to similar water-level ranges of the reference interior marsh (figure 6). Theoretically, both tidal and wind-driven water are less efficient at going around terraces than emptying in and retreating out of open water; therefore, the range of water level decreases over a set amount of time (1 day). During the preconstruction period, the water-level range in the area around Greens Lake was 2.5 times more variable than the reference interior marsh area and just over twice as variable as time periods after installation of the terraces (figure 6, note the standard deviations). Debris from Hurricanes Rita and Ike inevitably settled into canals disrupting hydrologic connectivity between perimeter and interior waterways; however, water-level range in the reference interior marsh location actually increased slightly in the time period between Hurricanes Rita and Ike (Postconstruction 1) before returning to preconstruction ranges following Hurricane Ike.

The terraces in open water surrounding Greens Lake did not substantially affect mean salinity relative to other locations; however, the variability of salinity decreased after construction of the terraces. The statistical model was robust (adjusted $R^2 = 0.76$) and significant ($F_{11} = 1077$; $p < 0.0001$), and the location \times time period interaction was significantly different ($F_6 = 36$; $p < 0.001$). At all locations, salinity increased over the time periods with a larger shift during Postconstruction 3 (09/2010-08/2011) during which a drought occurred. Although mean salinity was not consistently different between the interior marsh locations (Terraces and Reference), the terraced area has a marked decrease in salinity variability (note standard deviation bars on graph) from Preconstruction to Postconstruction 1 (between Hurricanes Rita and Ike) compared to the Reference (38 % difference) and itself (55 %); salinity variability was similar between the two locations during Postconstruction 3 and 4 (figure 7).




Figure 6. Water-level ranges were collected from the west Sabine Lake rim (Lake), a reference interior marsh (Reference), and the CS-32 terrace field around Greens Lake (Terraces) over different time periods (one preconstruction and three postconstruction time periods). The values are mean ± 1 standard deviation of daily water-level range for each location and time period combination. The columns with separate letters are significantly different as determined by a Tukey's Honest Significant Difference post-test of least square means and standard errors.




Figure 7. Salinity was collected from the west Sabine Lake rim (Lake), a reference interior marsh (Reference), and the CS-32 terrace field around Greens Lake (Terraces) over different time periods (one preconstruction and three postconstruction time periods). The values are mean \pm 1 standard deviation daily salinity for each location and time period combination; columns with a different are significantly different as determined by a Tukey's Honest Significant Difference post-test of least square means and standard errors.

CS-32 Terrace Condition and Vegetation

The terraces were constructed in two phases; the originally planned terraces (CU-1) were constructed from 2005-2006, and an additional section of terraces (CU-1A) were constructed from 2008-2009. Construction progressed from the south to north for each group (CU-1 and CU-1A). 'Vermilion' smooth cordgrass was planted along the toe of all sides within fifteen days after construction of each 1,000 linear feet of terrace. Construction was interrupted by hurricanes during both phases of construction.

Monitoring of the terrace vegetation was performed during annual inspections. The following information was summarized from field trip reports by Cindy Steyer of the USDA-Natural Resource Conservation Service (see Appendix D for complete field trip reports).

Post Hurricane Rita Assessment - 10/27/2005

- All of the vegetation was considerably browned.
- The southernmost/older terrace rows appeared to have produced significant growth and spread prior to the storm and new shoots were found emerging from the roots.
- Proceeding northward, the number of plants missing on each terrace segment progressively increased and new growth declined.
- On the northernmost/newest terraces, the number of remaining plantings was very low with no new growth.

Post Hurricane Rita Growing Season Assessment – 04/03/2006

- The southern/oldest terrace plantings (SE of CRMS0660) recovered very well, having produced significant new growth and lateral spread.
- Proceeding northward to newer rows, mortality increased, until the plantings no longer formed a continuous vegetative hedge at the toe of the terrace segments.
- On the northernmost/newest terraces, plantings were very sparsely distributed live clumps or single plants with a couple of stems each
- Recommendation to replace missing plantings which extend northward from the southern alignment of Greens Lake was done in 2007.

Post Hurricane Ike Assessment - 02/26/2009

- Overall mortality rate of the CU-1A plantings appeared to be more severe than in CU-1.
- Mortality increased and recovery decreased as the age of the plantings decreased south to north.
- Plantings on the north sides of the rows fared better than on the south sides.
- CU-1 replacement plantings: all emergent stems that remained post storm were completely browned but most were recovering with new growth
- Recommendation to replace all dead/missing plantings in CU-1A (77% of the original plantings) was completed by the July 2009.

Post Hurricane Plantings Replacement Assessment - 03/18/2010

- The CU-1A replacement plantings appeared very poor and severely browned, similar to the original plantings following hurricanes Rita and Ike.
- The replacement plantings did not produce any new stems prior to winter. Weather is suspected to have caused the failure for bare-root plantings; following the Hurricane Ike storm surge, the area was in a severe drought conditions in the first half of 2009 which was followed by the unusually cold winter of 2009/2010.
- Recommendation was to reassess the situation at the end of the growing season in 2010 because the cold winter may have cause a delay in plant productivity.

Overall Terrace Vegetation Assessment – 10/06/2010

- CU-1 Rows 16 to 25 and CU-1A Rows 11 to 8 (southernmost terraces) looked excellent and the coverage was nearly 100% as seashore paspalum filled in some gaps.
- Survival dropped dramatically (5% to 50%) on the northern rows of CU-1. The remaining vegetation looked very healthy except on eroded terraces with lower crown elevation.

- The older, large CU-1 Row 14A terraces along the southern alignment of Greens Lake was very good shape with a high diversity of new vegetation on the broad crown, but the planted smooth cordgrass at the toe provided sparse cover.
- Northern terraces in CU-1 were highly variable with no apparent pattern. Many terrace segments were much narrower and had poor to no cover, while other terraces retained their width and had good vegetative cover. Overall, smooth cordgrass plantings were not as robust as those to the south.
- Recommendation was to not replace missing plantings at this time and close-out the construction phase of the CS-32 project. Large gaps of missing vegetation should be given priority during the Operations and Management phase of the project.

Terrace Assessment - November 1, 2011


- Airboat restrictions did not allow for an efficient and thorough inspection of the terraces in the time allotted; therefore, a trip summary with general observations was provided.
- Plant conditions and percent cover were mixed ranging from robust plant growth with 100% cover to very sparse vegetation providing little to no cover; no spatial trends were observed.
- A high amount of observable standing dead vegetation and sections of terraces with sprouting vegetation at the end of the growing season indicate that the area was still being impacted by a prolonged exceptional drought.

CRMS Supplemental

The Coastwide Reference Monitoring System – Wetlands (CRMS) is a large repository of monitoring information at the CRMS site and CWPPRA project levels covering a variety of spatial scales. The following data and graphics are all available through the CRMS website (http://lacoast.gov/crms_viewer/).

Spatial

Land and water classifications of 2005 and 2008 aerial photography (1:40,000 resolution) were performed on the 1 km² (247 acre) area encompassing CRMS sites by the USGS-National Wetlands Research Center. CRMS0660 is within the CS-32 terrace field; the broader CU-1 terraces, constructed in 2005, are in the southeast corner of both frames, and the narrower CU-1A terraces, constructed in 2008, are along the north and northeast of the 2008 frame (figure 8). Hurricane Ike had a marked effect on the geomorphology of the sites; marsh was displaced by the storm surge and either removed from the area, deposited elsewhere on previously existing marsh, or deposited in the open water. CRMS0660 (project site), which added land from 2005 to 2008, had more open water for marsh to be displaced into than CRMS0683 (reference site), which lost land. Also, the terraces may have created a lower energy environment that allowed the displaced marsh to settle and establish in the shallow open water.



Land	2005 % (ac)	2008 % (ac)	Change % (ac)
CRMS0660	47 (117)	48 (120)	+2.6 (+6.3)
CRMS0683	72 (177)	60 (147)	-16.8 (-41.6)

Figure 8. Land and water were classified from 2005 and 2008 aerial photography (1:40,000 resolution) by the USGS-National Wetlands Research Center for CRMS0660 (project) and CRMS0683 (reference). The aerial photography was collected post hurricane in 2005 (Hurricane Rita) and 2008 (Hurricane Ike). Note the vegetation transects represented by green and red lines. The original transect at CRMS0660 (red line) was scoured by Hurricane Ike in 2008 relocated to its current location (green line). Sufficient land remained at CRMS0683 to continue using the vegetation transect.

Vegetation

The vegetative community composition within the CS-32 project area has vacillated between being predominantly intermediate and brackish from 1949-2007 (Table 5) as has the western Calcasieu-Sabine (CS) basin. Since 2006, vegetation composition and cover has been estimated at CRMS sites from 10 stations (4 m²) randomly distributed along a vegetated transect. Individual species' cover data and quality were summarized according to the Floristic Quality Index (FQI) method (Cretini and Steyer 2011); the quality score is based on whether the species is typical for a disturbed area (low score) or of mature vegetation (higher score) for a vegetation type. Averaged CRMS sites within the vicinity of the CS-32 project area have had lower floristic quality than other CWPPRA project sites and reference sites within intermediate and brackish marsh of the CS Basin, but they have an average distribution (between the 25th and 75th percentile) relative to sites coastwide (figure 9). Sites in the vicinity of the CS-32 project area were recovering from Hurricane Rita in 2005 when Hurricane Ike impacted them in 2008. Although the vegetation was negatively impacted by Hurricane Ike and a subsequent drought in the first half of 2009, vegetation at the CRMS sites recovered by 2011 (figures 9 and 10). The hurricane effect was especially evident at CRMS0660, the only site within project boundaries (CS-32 terraces), as the FQI dropped to 0 in 2009 because the plots were completely scoured away; a new vegetation transect was established in adjacent marsh in 2011 (figures 10, 11, and 8). CRMS0660 is classified as an intermediate marsh; the shift in vegetative composition and percent coverage (figure 11) resulted from recovery since Hurricane Ike (as occurred at the other sites) and/or changing the sampling location (figure 8). CRMS0683 and CRMS2189 are intermediate and brackish marsh sites, respectively, outside of the CS-32 project boundaries. The intermediate reference shifted species composition to more salt tolerant vegetation in 2011 as *Spartina patens* (marsh hay) and *Distichlis spicata* (salt grass) increased in coverage (figure 11).

Table 5. Vegetation classifications of the East Sabine Lake Hydrologic Restoration (CS-32) project area from historical surveys. Vegetation Class “Other” includes water, swamp, and developed land. The data was obtained from the Coastwide Reference Monitoring System (CRMS) website (http://www.lacoast.gov/crms_viewer/) on August 04, 2011.

Year	Vegetation Classification - % area (acres)			Source
	Fresh	Intermediate	Brackish	
1949	---	86.6 (7142)	13.4 (1106)	O'Neil 1949
1968	---	46.7 (3851)	53.3 (4397)	Chabreck et al. 1968
1978	0.1 (6)	75.3 (6210)	24.6 (2032)	Chabreck and Linscombe 1978
1988	0.3 (27)	---	99.7 (8221)	Chabreck and Linscombe 1988
1997	---	99.1 (8175)	0.9 (73)	Chabreck and Linscombe 1997
2001	---	94.5 (7798)	5.5 (450)	Linscombe and Chabreck n.d.
2007	---	88.7 (7315)	11.3 (933)	Sasser et al. 2008




Figure 9. Floristic Quality Index scores of CRMS sites averaged within the vicinity of CS-32 are shown over time relative to all other CRMS sites (Reference and CWPPPA Projects) within intermediate and brackish marsh of the Calcasieu/Sabine hydrologic basin. The green, yellow, and red background represents the coastwide distribution of all CRMS site since 2006.




Figure 10. Floristic Quality Index scores for the CRMS sites within the vicinity of the CS-32 project area are shown over time. The CRMS0660 vegetation stations, the only stations within the project area (terraces), were scoured away during Hurricane Ike after the 2008 sampling (note 0 for 2009); new stations were established in 2011 after giving time for potential recovery.




Figure 11. Species composition, total percent cover, and the floristic quality index (FQI) of vegetation observed at CRMS0660 (CS-32 terrace, intermediate marsh), CRMS0683 (intermediate marsh reference), and CRMS2189 (brackish marsh reference). The original CRMS0660 vegetation stations were scoured away during Hurricane Ike prior to the 2009 sampling, and new stations were established in 2011 after giving time for potential recovery.

Hydrology

Hydrologic data has been collected on an hourly basis at CRMS sites in the vicinity of the CS-32 project area since November 2006. During this time, the hydrology of the area in western Calcasieu/Sabine hydrologic basin (CS basin) has been largely affected by climatological events, Hurricane Ike and drought (figure 12). After settling into seasonal water-level patterns and lower salinities following Hurricane Rita in 2005, Hurricane Ike ushered in another large storm surge with the associated inundation of salty water in September 2008. After salinities returned to pre Hurricane Ike concentrations (< 5 ppt) aided by a large rain event in September 2009 that increased water levels while decreasing salinity, a drought lasting over 1.5 years lowered water levels and increased salinities to beyond 20 ppt during the summer of 2011 at most of the CRMS stations. The drought lasted from 5/22/2010 to 01/07/2012; based on the Palmer Drought Severity Index, the drought typically fluctuated between moderate and severe and reached extreme drought conditions during most of the summer of 2011 (5/7/2011 to 8/27/2011) (NOAA-NWS Climate Prediction Center n.d.).

As with many areas in the CS basin, Hurricane Ike and the drought drove the hydrology at CRMS0660. Along with hourly water level and salinity data collected from surface water, porewater salinity at 10 cm is collected when continuous sondes are serviced which is approximately monthly. Surface water and soil porewater salinity decrease (~ 6 ppt to ~ 3 ppt) over the 2.5 years before Hurricane Ike following the Hurricane Rita storm surge (figure 13 a). Following Hurricane Ike, elevated soil porewater salinity was more conservative to change than surface water as porewater salinity only slightly decrease following the September 2009 rain event and did not increase as much during the drought (figure 13 b). The prolonged period of elevated porewater salinity may have caused the shift to more salt tolerant plant species at CRMS0660 and CRMS0683 (figure 11).




Figure 12. Surface water level (top) and salinity (bottom) data collected at CRMS sites within the vicinity of CS-32; CRMS0660 is within the CS-32 terrace area whereas all other CRMS sites are outside. The average marsh elevation from the CRMS sites (1.1 ft, NAVD88) is represented by the green, level line in the water level graph. Hurricane Ike made landfall on September 13, 2008. A continuous drought spanned from May 2010 – January 2011.

http://www.cpc.ncep.noaa.gov/products/monitoring_and_data/drought.shtml




Figure 13. Hydrologic data (surface water-level and salinity) and porewater salinity was collected from the CS-32 terrace area (CRMS0660) from April 26, 2006 through September 30, 2011. Note that marsh elevation was adjusted when the marsh sampling stations were re-established following Hurricane Ike.

V. Conclusions

a. Project Effectiveness

The CS-32 project has progressed towards most project goals three years into the 20 year life.

The addition of terraces in the large open-water area around Greens Lake has not changed salinity relative to other locations near the project area. Salinity reduction at Pines Ridge will be evaluated after data collection from October 01, 2012 through September 30, 2013.

The addition of terraces in the large open-water area around Greens Lake has been effective at reducing the water level variability as the daily water-level range decreased following the construction of the terraces fields. Project effectiveness towards reducing water at Pines Ridge will be evaluated after data collection from October 01, 2012 through September 30, 2013.

Erosion has been stopped along a 3,000 ft length of Sabine Lake shoreline west of Willow Bayou. Mud flats have formed and vegetation has established behind the rock dike protection structure except for areas behind the gaps in the rock dike (both ends and two in the middle) which allow for fish and estuarine organism access to the shoreline. The rock dike did not prevent the breaching of Sabine Lake and Willow Bayou; however, subsequent mud flat and vegetative formation in the vicinity of the breach behind the rock dike is expected to diminish hydrologic exchange between the two water bodies.

Future land to water analyses over time will be used to assess the project goal of creating 127 acres (51.3 ha) of emergent marsh in shallow open water areas by the end of the 20-year project life. The terraces installed around Greens Lake added approximately 117 acres (47.3 ha) of emergent marsh in shallow open water areas. The addition of terraces changed the trajectory of land change since 1985 from slow land loss through 2004 (prior to project construction) to slightly slow land gain through 2010 (including project construction); however, the project area, along with the rest of the CS basin, has been significantly losing land since Hurricanes Rita and Ike which occurred during the project construction.

b. Recommended Improvements

Adding a land-to-water change analysis map would detect where change is occurring in addition to how much land has changed overall. This would be helpful for assessing shoreline protection and marsh area creation functions of the terraces.

An elevation survey of the terrace areas would be beneficial for examining changes in the terrace and borrow area geometries overall and between the different sized terraces.

c. Lessons Learned

The addition of terraces to open water areas can reduce water-level variability within the terraced area.

The timing of vegetative planting on terraces is critical. Successive high salinity events and long periods of inundation are stressful to newly planted vegetation.

VI. References

- Balkum, K.F., J.L.W. Cowan, M.A. Stead, and K. Belhadjali. 2003. Ecological Review, East Sabine Lake Hydrologic Restoration (CS-32), Construction Unit 1. Louisiana Department of Natural Resources – Coastal Restoration Division, Baton Rouge, LA. 13 pp.
- Barras, J.A. 2009. Land area change and overview of major hurricane impacts in coastal Louisiana, 2004-2008. U.S. Geological Survey Scientific Investigations Map 3080, scale 1:250,000. 6 p. pamphlet.
- Chabreck, R.H., and G. Linscombe 1978. Vegetation type map of the Louisiana coastal marshes. Louisiana Department of Wildlife and Fisheries, New Orleans. Scale: 1:62,500.
- 1988. Vegetation type map of the Louisiana coastal marshes. Louisiana Department of Wildlife and Fisheries, New Orleans. Scale: 1:62,500.
- 1997. Vegetative type map of the Louisiana coastal marshes. Louisiana Department of Wildlife and Fisheries, Baton Rouge.
- Chabreck, R.H., T. Joanen, and A.W. Palmisano 1968. Vegetation type map of the Louisiana coastal marshes. Louisiana Department of Wildlife and Fisheries, New Orleans. Scale: 1:62,500.
- Clark, D. and J. Mazourek. 2004. Final Environmental Assessment: East Sabine Lake Hydrologic Restoration Project Construction Unit 1 (CS-32), Cameron Parish, Louisiana. U.S. Fish and Wildlife Service, Lafayette, LA. 32 pp. plus appendices.
- Couvillion, B.R., J.A. Barras, G.D. Steyer, W. Sleavin, M. Fischer, H. Beck, N. Trahan, B. Griffin, and D. Heckman. 2011. Land area change in coastal Louisiana from 1932 to 2010. U.S. Geological Survey Scientific Investigations Map 3164, scale 1:265,000. 12 p. pamphlet.
- Cretini, K.F., and Steyer, G.D. 2011. Floristic Quality Index-An assessment tool for restoration project and monitoring sites in coastal Louisiana: U.S. Geological Survey Fact Sheet 2011-3044, 4p.
- Dunbar, J.B., L.D. Britsch, and E.R. Kemp III. 1992. Land loss rates. Report 3, Louisiana coastal plain. U.S. Army Engineer District, New Orleans, Louisiana.
- Folse, T.M., J.L. West, M.K. Hymel, J.P. Troutman, L.A. Sharp, D. Weifenbach, T.E. McGinnis, L.B. Rodrigue, W.M. Boshart, D.C. Richardi, C.M. Miller, and W.B. Wood. 2012. A Standard Operating Procedures Manual for the Coast-wide Reference Monitoring System-*Wetlands*: Methods for Site Establishment, Data Collection, and Quality Assurance/Quality Control. Louisiana Coastal Protection and Restoration Authority. Baton Rouge, LA. 207 pp.

- Linscombe, G. and R. Chabreck. n.d. Task III.8—Coastwide aerial survey, brown marsh 2001 assessment: Salt marsh dieback in Louisiana—Brown marsh data information management system, accessed June 4, 2006, at http://brownmarsh.net/data/III_8.htm
- Louisiana Coastal Wetlands Conservation and Restoration Task Force. 2002. Hydrologic Investigation of the Louisiana Chenier Plain. Baton Rouge, Louisiana: Louisiana Department of Natural Resources, Coastal Restoration Division. 135 pp. plus appendices.
- Louisiana Coastal Wetlands Conservation and Restoration Task Force and the Wetlands Conservation and Restoration Authority. 1998. Coast 2050: Toward a sustainable coastal Louisiana. Louisiana Department of Natural Resources. Baton Rouge, Louisiana. 161 pp.
- Louisiana Coastal Wetlands Conservation and Restoration Task Force and the Wetlands Conservation and Restoration Authority. 1999. Coast 2050: Toward a sustainable coastal Louisiana, the appendices. Appendix F—Region 4 supplemental information. Louisiana Department of Natural Resources. Baton Rouge, Louisiana. 224 pp.
- National Oceanographic and Atmospheric Administration - National Weather Service (NOAA-NWS). n.d. Climate Prediction Center, Drought Monitoring. Past Palmer Drought Severity Index Maps by Week (1998 - current). Accessed June 11, 2012, at http://www.cpc.ncep.noaa.gov/products/monitoring_and_data/drought.shtml
- O'Neil, T., 1949, The muskrat in Louisiana coastal marshes: New Orleans, Louisiana Wildlife and Fisheries Commission, 28 p.
- Sasser, C.E., J.M. Visser, E.C. Mouton, J. Linscombe, and S.B. Hartley. 2008. Vegetation types in coastal Louisiana in 2007: U.S. Geological Survey Open-File Report 2008-1224, 1 sheet, scale 1:550,000.
- Steyer, G.D., R.C. Raynie, D.L. Steller, D. Fuller, and E. Swenson. 1995. Quality management plan for Coastal Wetlands Planning, Protection, and Restoration Act monitoring plan. Open-file series 95-01. Baton Rouge: Louisiana Department of Natural Resources, Coastal Restoration Division.

Appendix A

Inspection Photographs

An annual inspection was not performed during the 2011-2012 period.

Appendix B

Three Year Budget Projection

EAST SABINE LAKE HR/ CS-32 / PPL 10
Three-Year Operations & Maintenance Budgets 07/01/2012 - 06/30/2015

<u>Project Manager</u>	<u>O & M Manager</u>	<u>Federal Sponsor</u>	<u>Prepared By</u>
Pat Landry	Dewey Billodeau	USFWS	Dewey Billodeau

	2012/2013 (-3)	2013/2014 (-4)	2014/2015 (-5)
Maintenance Inspection	\$ 6,269.00	\$ 6,457.00	\$ 6,651.00
Structure Operation			
State Administration		\$ -	\$ -
Federal Administration		\$ -	\$ -
Maintenance/Rehabilitation			

12/13 Description:

E&D	
Construction	
Construction Oversight	
Sub Total - Maint. And Rehab.	\$ -

13/14 Description

E&D	\$ -
Construction	\$ -
Construction Oversight	\$ -
Sub Total - Maint. And Rehab.	\$ -

14/15 Description:

E&D	\$ -
Construction	\$ -
Construction Oversight	\$ -
Sub Total - Maint. And Rehab.	\$ -

	2012/2013 (-3)	2013/2014 (-4)	2014/2015 (-5)
Total O&M Budgets	\$ 6,269.00	\$ 6,457.00	\$ 6,651.00

O & M Budget (3 yr Total)	\$ 19,377.00
Unexpended O & M Budget	\$ 240,574.00
Remaining O & M Budget (Projected)	\$ 221,197.00



OPERATION AND MAINTENANCE BUDGET WORKSHEET
EAST SABINE LAKE HYDROLOGIC RESTORATION / PROJECT NO. CS-32 / PPL NO. 10 / 2012/2013

DESCRIPTION	UNIT	EST. QTY.	UNIT PRICE	ESTIMATED TOTAL
O&M Inspection and Report	EACH	1	\$6,269.00	\$6,269.00
General Structure Maintenance	LUMP	0	\$0.00	\$0.00
Engineering and Design	LUMP	0	\$0.00	\$0.00
Operations Contract	LUMP	0	\$0.00	\$0.00
Construction Oversight	LUMP	0	\$0.00	\$0.00

ADMINISTRATION

LDNR / CRD Admin.	LUMP	0	\$0.00	\$0.00
FEDERAL SPONSOR Admin.	LUMP	0	\$0.00	\$0.00
SURVEY Admin.	LUMP	0	\$0.00	\$0.00
OTHER				\$0.00
TOTAL ADMINISTRATION COSTS:				\$0.00

MAINTENANCE / CONSTRUCTION

SURVEY

SURVEY DESCRIPTION:	Add staff gage.				
	Secondary Monument	EACH	0	\$0.00	\$0.00
	Staff Gauge / Recorders	EACH	0	\$0.00	\$0.00
	Marsh Elevation / Topography	LUMP	0	\$0.00	\$0.00
	TBM Installation	EACH	0	\$0.00	\$0.00
	OTHER				\$0.00
	TOTAL SURVEY COSTS:				\$0.00

GEOTECHNICAL

GEOTECH DESCRIPTION:					
	Borings	EACH	0	\$0.00	\$0.00
	OTHER				\$0.00
	TOTAL GEOTECHNICAL COSTS:				\$0.00

CONSTRUCTION

CONSTRUCTION DESCRIPTION:						
	Rip Rap	LIN FT	TON / FT	TONS	UNIT PRICE	
	Rock Rip rap	0	0.0	0	\$0.00	\$0.00
	Aggregate Surface Course	0	0.0	0	\$0.00	\$0.00
		0	0.0	0	\$0.00	\$0.00
	Filter Cloth / Geogrid Fabric		SQ YD	0	\$0.00	\$0.00
	Navigation Aid		EACH	0	\$0.00	\$0.00
	Signage		EACH	0	\$0.00	\$0.00
	General Excavation / Fill		CU YD	0	\$0.00	\$0.00
	Dredging		CU YD	0	\$0.00	\$0.00
	Sheet Piles (Lin Ft or Sq Yds)			0	\$0.00	\$0.00
	Timber Piles (each or lump sum)			0	\$0.00	\$0.00
	Timber Members (each or lump sum)			0	\$0.00	\$0.00
	Hardware		LUMP	0	\$0.00	\$0.00
	Materials		LUMP	0	\$0.00	\$0.00
	Mob / Demob		LUMP	0	\$0.00	\$0.00
	Contingency		LUMP	0	\$0.00	\$0.00
	General Structure Maintenance		LUMP	0	\$0.00	\$0.00
	OTHER				\$0.00	\$0.00
	OTHER				\$0.00	\$0.00
OTHER				\$0.00	\$0.00	
TOTAL CONSTRUCTION COSTS:					\$0.00	

TOTAL OPERATIONS AND MAINTENANCE BUDGET: **\$6,269.00**

OPERATION AND MAINTENANCE BUDGET WORKSHEET

EAST SABINE LAKE HYDROLOGIC RESTORATION / PROJECT NO. CS-32 / PPL NO. 10 / 2013/2014

DESCRIPTION	UNIT	EST. QTY.	UNIT PRICE	ESTIMATED TOTAL
O&M Inspection and Report	EACH	1	\$6,457.00	\$6,457.00
General Structure Maintenance	LUMP	0	\$0.00	\$0.00
Engineering and Design	LUMP	0	\$0.00	\$0.00
Operations Contract	LUMP	0	\$0.00	\$0.00
Construction Oversight	LUMP	0	\$0.00	\$0.00

ADMINISTRATION

LDNR / CRD Admin.	LUMP	0	\$0.00	\$0.00
FEDERAL SPONSOR Admin.	LUMP	0	\$0.00	\$0.00
SURVEY Admin.	LUMP	0	\$0.00	\$0.00
OTHER				\$0.00
TOTAL ADMINISTRATION COSTS:				\$0.00

MAINTENANCE / CONSTRUCTION

SURVEY

SURVEY DESCRIPTION:					
	Secondary Monument	EACH	0	\$0.00	\$0.00
	Staff Gauge / Recorders	EACH	0	\$0.00	\$0.00
	Marsh Elevation / Topography	LUMP	0	\$0.00	\$0.00
	TBM Installation	EACH	0	\$0.00	\$0.00
	OTHER				\$0.00
	TOTAL SURVEY COSTS:				\$0.00

GEOTECHNICAL

GEOTECH DESCRIPTION:					
	Borings	EACH	0	\$0.00	\$0.00
	OTHER				\$0.00
	TOTAL GEOTECHNICAL COSTS:				\$0.00

CONSTRUCTION

CONSTRUCTION DESCRIPTION:						
	Rip Rap	LIN FT	TON / FT	TONS	UNIT PRICE	
	Rock Rip rap	0	0.0	0	\$0.00	\$0.00
	Aggregate Surface Course	0	0.0	0	\$0.00	\$0.00
		0	0.0	0	\$0.00	\$0.00
	Filter Cloth / Geogrid Fabric		SQ YD	0	\$0.00	\$0.00
	Navigation Aid		EACH	0	\$0.00	\$0.00
	Signage		EACH	0	\$0.00	\$0.00
	General Excavation / Fill		CU YD	0	\$0.00	\$0.00
	Dredging		CU YD	0	\$0.00	\$0.00
	Sheet Piles (Lin Ft or Sq Yds)			0	\$0.00	\$0.00
	Timber Piles (each or lump sum)			0	\$0.00	\$0.00
	Timber Members (each or lump sum)			0	\$0.00	\$0.00
	Hardware		LUMP	0	\$0.00	\$0.00
	Materials		LUMP	0	\$0.00	\$0.00
	Mob / Demob		LUMP	0	\$0.00	\$0.00
	Contingency		LUMP	0	\$0.00	\$0.00
	General Structure Maintenance		LUMP	0	\$0.00	\$0.00
	OTHER				\$0.00	\$0.00
	OTHER				\$0.00	\$0.00
OTHER				\$0.00	\$0.00	
TOTAL CONSTRUCTION COSTS:					\$0.00	

TOTAL OPERATIONS AND MAINTENANCE BUDGET: **\$6,457.00**

OPERATION AND MAINTENANCE BUDGET WORKSHEET

EAST SABINE LAKE HYDROLOGIC RESTORATION / PROJECT NO. CS-32 / PPL NO. 10 / 2014/2015

DESCRIPTION	UNIT	EST. QTY.	UNIT PRICE	ESTIMATED TOTAL
O&M Inspection and Report	EACH	1	\$6,651.00	\$6,651.00
General Structure Maintenance	LUMP	0	\$0.00	\$0.00
Engineering and Design	LUMP	0	\$0.00	\$0.00
Operations Contract	LUMP	0	\$0.00	\$0.00
Construction Oversight	LUMP	0	\$0.00	\$0.00

ADMINISTRATION

LDNR / CRD Admin.	LUMP	0	\$0.00	\$0.00
FEDERAL SPONSOR Admin.	LUMP	0	\$0.00	\$0.00
SURVEY Admin.	LUMP	0	\$0.00	\$0.00
OTHER				\$0.00
TOTAL ADMINISTRATION COSTS:				\$0.00

MAINTENANCE / CONSTRUCTION

SURVEY

SURVEY DESCRIPTION:	Add staff gage.				
	Secondary Monument	EACH	0	\$0.00	\$0.00
	Staff Gauge / Recorders	EACH	0	\$0.00	\$0.00
	Marsh Elevation / Topography	LUMP	0	\$0.00	\$0.00
	TBM Installation	EACH	0	\$0.00	\$0.00
	OTHER				\$0.00
TOTAL SURVEY COSTS:					\$0.00

GEOTECHNICAL

GEOTECH DESCRIPTION:					
	Borings	EACH	0	\$0.00	\$0.00
	OTHER				\$0.00
TOTAL GEOTECHNICAL COSTS:					\$0.00

CONSTRUCTION

CONSTRUCTION DESCRIPTION:						
	Rip Rap	LIN FT	TON / FT	TONS	UNIT PRICE	
	Rock Rip rap	0	0.0	0	\$0.00	\$0.00
	Aggregate Surface Course	0	0.0	0	\$0.00	\$0.00
		0	0.0	0	\$0.00	\$0.00
	Filter Cloth / Geogrid Fabric		SQ YD	0	\$0.00	\$0.00
	Navigation Aid		EACH	0	\$0.00	\$0.00
	Signage		EACH	0	\$0.00	\$0.00
	General Excavation / Fill		CU YD	0	\$0.00	\$0.00
	Dredging		CU YD	0	\$0.00	\$0.00
	Sheet Piles (Lin Ft or Sq Yds)			0	\$0.00	\$0.00
	Timber Piles (each or lump sum)			0	\$0.00	\$0.00
	Timber Members (each or lump sum)			0	\$0.00	\$0.00
	Hardware		LUMP	0	\$0.00	\$0.00
	Materials		LUMP	0	\$0.00	\$0.00
	Mob / Demob		LUMP	0	\$0.00	\$0.00
	Contingency		LUMP	0	\$0.00	\$0.00
	General Structure Maintenance		LUMP	0	\$0.00	\$0.00
	OTHER				\$0.00	\$0.00
	OTHER				\$0.00	\$0.00
	OTHER				\$0.00	\$0.00
	TOTAL CONSTRUCTION COSTS:					\$0.00

TOTAL OPERATIONS AND MAINTENANCE BUDGET: \$6,651.00

Appendix C

Field Inspection Notes

An annual inspection was not performed during the 2011-2012 period.

Appendix D

NRCS Terrace Inspection Field Reports

TRIP REPORT

To: Brad Sticker, CE, NRCS, Alexandria

From: Cindy Steyer, CVS, NRCS, Baton Rouge

Date: May 24, 2006

Subject: East Sabine Lake Hydrologic Restoration Project (CS-32)
Post-Hurricane Damage Assessment of Terrace Vegetation
October 27, 2005 and April 3, 2006

Attending Agencies: Louisiana Department of Natural Resources, CED and CRD
US Fish and Wildlife Service
USDA Natural Resources Conservation Service

The CS-32 East Sabine Hydrologic Restoration Project lies east of Sabine Lake in Cameron Parish, Louisiana. The project area lies within brackish marsh habitat where average monthly water salinity ranges from 3 to 8 ppt throughout the year. This report summarizes an investigation of hurricane damage to the vegetated terrace component of this project (Figure 1). In May 2005, terrace construction commenced at the southernmost row of terrace sections and proceeded to the north (Figure 2). The earthen terraces were planted with 'Vermilion' smooth cordgrass (*Spartina alterniflora* var. Vermilion), at the toe on all sides within fifteen days after construction of each 1,000 linear feet of terrace. Construction of this component was interrupted in August 2005 by Hurricanes Katrina and Rita that impacted Louisiana's coastal area. Due to the order of construction, the oldest and more well-established transplants were on the southern terraces, and the most recent transplants were on the northernmost terrace segments. Approximately 54% of the total contracted linear footage of terrace segments was constructed and planted by the contractor and was inspected and considered completed by the NRCS Contracting Officer's Technical Representative (COTR). The project area was severely impacted by excessive flooding from the storm surge associated with Hurricane Rita which made landfall to the immediate east. Following the storm, the project area remained inundated with highly saline water for some period, and since the hurricane until present, there has been little rainfall resulting in highly saline soil conditions.

Vermilion' smooth cordgrass is very salt tolerant and naturally occurs in the intertidal zones (approx. between mean high and mean low water) of brackish and saline wetland habitats. Nevertheless, a significant abrupt increase in salinity and prolonged elevation of water levels can severely impact smooth cordgrass plants, causing die-back of plant portions or complete mortality. Specific effects are influenced by degree and duration of the increase in water salinity, depth and duration of flooding, temperature, season, and condition of the plants (for example, recently planted vs. established).




Figure 1. CS-32 East Sabine Project Earthen Terrace




Figure 2. Layout of north unit terraces. Terrace segments shown in red were not constructed at the time of hurricane impact. Construction and planting was completed on all terrace segments shown in green on this map plus those in the southern unit.

On the October 2005 trip, the investigating party traveled west by airboat, from near USFWS Sabine Refuge Headquarters on Hwy 27, across Refuge marshes to the project area. Huge swaths of wrack, composed of vegetative and anthropogenic material (tanks, lumber, 18-wheeler trailers, etc.), had been deposited on top of the marshes. All emergent marsh vegetation that could be seen was completely brown and much of it was covered with what appeared to be fine-grained sediment and precipitated salt (below).





At the project area, although the plants on the southernmost terrace rows appeared to have produced significant growth and spread prior to the storm and the plants' physical structure was mostly intact, we found that all contract plantings on all of the terraces were considerably browned (below).



On the southern terraces, a few very young green stems were found emerging from the roots or stem tips of the plants, with the oldest transplants showing the most new growth.



Proceeding northward, we began to note gaps in the planted rows and the number of plants missing on each terrace segment progressively increased.



In addition, the younger a transplant was, the less old and new growth was present. From oldest to youngest, mortality increased, and the base of the plant stems ranged in color from pale yellow/green to brown/black and rotten at the base.





On the most recently built terrace segments, the number of live plants remaining appeared very low. Because I was unable to determine whether some plants were at the point of decline or

recovery, and the growing season was over and conditions had not yet returned to normal (water salinities were found to be 19 to 22 ppt in the terraced ponds), I recommended that another field investigation be conducted in the spring to more accurately determine the amount of plant mortality.

On April 3, 2006, we again traveled to the project area. The condition of the marshes between the launch site and the project area generally remained the same as in October 2005. However, as we approached the project area and a closer proximity to Sabine Lake, signs of green-up in the native vegetation increased. This may likely be the result of increased flushing from water exchange with the lake. Salinities were 8.5 to 10 ppt.

The oldest vegetative plantings on the southern terraces appeared to have recovered very well, having produced significant new growth and lateral spread (below).



However, moving northward, we found that as age of the plantings decreased, mortality increased, until the plantings no longer formed a continuous vegetative hedge at the toe of the terrace segments. On the newest terrace segments, remaining plants formed very sparsely

distributed live clumps, or single plants with a couple of stems each. There was no longer difficulty in calculating the plant mortality.











Plant mortality was estimated for each row of constructed terrace segments, and ranged from zero to 92%. All mortality was found to have occurred within the plantings on terrace rows 6 through 15. The plantings on rows 16 through 25 had 100% survival and were producing new growth. Based on the known constructed lengths of each terrace segment within the rows, the total linear footage of terrace edge that will require replanting was calculated by row and totals 103,022 linear feet. To replace the destroyed plantings on the 2.5 foot center spacing, per the contract specifications, will require 41,209 plants. To allow for changes in field conditions, a three percent allowance should be added for a total of 42,500 plants to be replaced. The original government cost estimate for the contract planting component was approximately three dollars per plant installed plus mobilization and demobilization. Based on recent successful bids for post-hurricane vegetative planting contracts, increases in local labor and fuel costs, and damages reported by Louisiana wetland plant nurseries, the government cost estimate for the replacement planting would be \$3.50 per plant installed for a total of \$148,750 plus mobilization and demobilization.

It is recommended that the destroyed plantings be replaced as soon as possible, in order to achieve the necessary stabilizing vegetative cover on the exposed tops and edges of the earthen terraces, particularly now that the start of hurricane season is days away. Please contact me and the LDNR and USFWS project and O&M managers to discuss how, and how soon, this can be accomplished.

Trip Attendees by Date:

October 27, 2005: Dewey Billodeau, O&M Manager, LDNR CED, Lafayette
Justin Price, Monitoring Manager, LDNR, CRD, Lafayette
Ralph Libersat, Project Manager, LDNR CRD, Baton Rouge
Wayne Melancon, CE, NRCS, Crowley
Cindy Steyer, NRCS, Baton Rouge

April 3, 2006: Dewey Billodeau, O&M Manager, LDNR CED, Lafayette
Darryl Clark, Project Mgr, USFWS, Lafayette
Dale Garber, CE, NRCS, Crowley
Donald Taffi, Jr., CET, NRCS, Crowley
Cindy S. Steyer, CVS, NRCS, Baton Rouge

cc: Dale Garber, CE, NRCS, Crowley
Britt Paul, ASTC/WR, NRCS, Alexandria
Quin Kinler, RC, NRCS, Baton Rouge
Darryl Clark, Biologist, USFWS, Lafayette
Dewey Billodeau, O&M Manager, LDNR CED, Lafayette

TRIP REPORT – via Electronic Mail
--

To: Brad Sticker, CE, NRCS, Alexandria

From: Cindy Steyer, CVS, NRCS, Baton Rouge

Date: March 16, 2009

Subject: East Sabine Lake Hydrologic Restoration Project (CS-32), CU-1A
Post-Hurricane Damage Assessment of Terrace Vegetation
February 26, 2009

Attendees: Darryl Clark, USFWS, Lafayette
Dewey Billodeaux, O&M Manager, OCPR, Abbeville
Mark Mouledous, OCPR, Monitoring Manager, Abbeville
Dale Garber, CE, NRCS, Crowley
Cindy S. Steyer, CVS, NRCS, Baton Rouge

cc: Britt Paul, ASTC-WR, NRCS, Alexandria
Ronnie Faulkner, CE, NRCS, Alexandria
Attendees

Background: The CS-32 East Sabine Hydrologic Restoration Project lies east of Sabine Lake in Cameron Parish, Louisiana. The project area lies within brackish marsh habitat where average monthly water salinity normally ranges from 3 to 8 ppt throughout the year. This report summarizes an investigation of hurricane damage to the most recently constructed vegetated terrace component of this project, Construction Unit 1A (Figures 1 and 2). After the Notice to Proceed was issued in March 2008, terrace construction commenced at the southernmost row of terrace segments and proceeded to the north. Beginning in early June, the earthen terraces were planted with ‘Vermilion’ smooth cordgrass (*Spartina alterniflora* var. Vermilion) at approximately mean high water level on all sides of each segment on 2 ½-foot centers. Due to the order of construction, the oldest and more well-established transplants were on the southern terraces, and the most recently planted transplants were on the northernmost terrace segments. Construction of this component was suspended in late August 2008 due to the approach of Hurricane Ike. At that point, the terrace work was complete on all but Row 1 of the terrace segments. In Row 1, the two westernmost terrace segments were not yet completed, and the remaining segments lacked the final finishing work necessary to meet the specified lines & grades. Also, none of the Row 1 segments had been planted.

The Sabine Lake area lies within the swath of Louisiana-Texas coastal area most severely impacted by Hurricane Ike (Figure 3). The project area was inundated by the storm surge that exceeded 10 feet, and then remained submerged under unusually high water levels for over a month following landfall (Figures 4 and 5). In addition, elevated salinities well above normal have persisted in the project area to date. Vermilion' smooth cordgrass is very flood and salt tolerant, and naturally occurs in the intertidal zones (approx. between mean high and mean low water) of brackish and saline wetland habitats. Nevertheless, a significant abrupt increase in salinity and prolonged elevation of water levels can severely impact smooth cordgrass plants, causing die-back of plant portions or complete mortality. The specific effects of any particular event are influenced by the degree and duration of the increase in water and soil salinity, depth and duration of flooding, temperature, season, and condition of the plants (for example, recently transplanted vs. established).



Figure 1. CS-32 East Sabine Hydrologic Restoration Project Plan Map – CU-1A.




Figure 3. Provisional Estimate of the Extent of Hurricane Ike's surge.



Figure 4. Project terraces remained flooded one month following Hurricane Ike landfall.



Figure 5. Project terraces remained flooded one month following Hurricane Ike landfall.

Findings: To determine the extent of storm damage to the project area, the investigating team of above attendees traveled to the project site on February 26, 2009 to assay the condition of the terraces and plantings. While traveling to the project area from the Cameron-Meadows boat launch, significant damage was observed to the Sabine area marshes in the form of extensive, browning, breakup and reconfiguration of emergent areas. Salinities within the project area on that date ranged from 13 ppt from south to north respectively. The condition of the newest CU-1A plantings was similar to that of the CU-1 plantings following hurricane Rita (see April 3, 2006 Trip Report, Subject: *CS-32 Post Hurricane Plant Damage Assessment of Terrace Vegetation*), but the overall mortality rate of the CU-1A plantings appeared to be more severe. All of the adjacent natural herbaceous marsh and all contract plantings that remained had been completely browned. Many contract plants were missing or appeared dead. The bases of some of the plants that were believed dead were black and rotten-looking and the root material did not appear to be viable (Figure 6). For many of the other contract plants that remained, a few stems of very new, tender growth were observed just emerging from the base (Figure 7).



Figure 6. Composite examples of dead plants.



Figure 7. Composite of typical examples of surviving plants.

Plant mortality and loss appeared to generally follow three patterns: One, over all rows, mortality or loss was the greatest on those terrace segments that were exposed to open water with longer fetch lengths, especially to the south (i.e., Row 10) (Figure 8). Plantings seemed to fare better when there was at least some emergent marsh adjacent to the terrace segment, even when the marsh consisted of very small fragments (Figure 9). Two, within each row, plantings on the north sides of the rows/segments fared better than on the south sides (Figure 10). Three, over all rows, mortality appears to increase as the age of the plantings decrease (Figure 11).



Figure 8. Greater mortality and loss seen where exposed to open water with longer fetch.



Figure 9. Survival tended to be greater on terrace segments where there was some adjacent fragmented marsh.



Figure 10. Comparison of mortality and loss on a terrace segment's south (left) side vs. the north (right) side.



Figure 11. Less evidence of recovery was seen from the most recently planted transplants.

The plants on the Construction Unit 1 terraces that were completed in 2007 were also significantly impacted. The vegetation had obviously spread and was forming fairly dense cover on those terrace segments prior to the storm, but all emergent stems that remained post storm were completely browned. Nevertheless, new plant growth emerging at sufficient density was observed on all the CU-1 terrace segments (Figures 12 through 14).



Figure 12. Post hurricane condition of vegetation on CU 1 terraces.



Figure 13. Post hurricane condition of vegetation on CU 1 terraces.



Figure 14. Post hurricane condition of vegetation on CU 1 terraces.

Project plant mortality/loss was estimated for each row of the CU-1A constructed terrace segments, and ranged from 40% to 95% as follows:

Row #	Mortality
Row 1 (segmts 1-7 only)	not planted
Row 2	95%
Row 3	95%
Row 4	75%
Row 5	90%
Row 6	60% (varied a lot – from 30% to 70%)
Row 7	60%
Row 8	60%
Row 9	40%
Row 10	70%
Row 11	70%

Recommendations: I do not recommend that any CU-1 terrace segments be replanted, since the density of the new growth we found there indicates that sufficient cover will likely be achieved from the remaining plant material. I do recommend that the dead and missing CU-1A plants be replaced as soon as possible, in order to achieve the necessary stabilizing vegetative cover on the exposed tops and edges of the earthen terraces. I also recommend that all Row 1 terrace segments that were built (segments 1 through 7) be planted, whether or not the construction work on this row was completed.

Based on known constructed dimensions of each CU-1A terrace segment within the rows, and the estimated mortality and loss, the linear footage of terrace edge that requires replanting was calculated by row and totals approximately 80,500 linear feet. To replace the destroyed plants on the 2.5-foot-center spacing, per the contract specifications, will require approximately 32,200 plants – about 77% of the original CU-1A contract plant total. I am not adding an allowance to this estimate because I believe this to be a conservative estimate. This field trip was very early in the growing season, so it's possible that some of the plants originally counted as dead were alive but the recovering growth hadn't emerged yet. In addition, it is not strictly necessary to replace a plant that was located in stretches where it is the only plant missing.

At this time, I recommend that the government cost estimate for the replacement planting be \$3.50 per plant installed, for a total of \$112,700, plus mobilization and demobilization cost of approximately \$15,000. This does not include S & I or administration costs.

Follow Up: The OCPR and USFWS project sponsors have reviewed this report and concur with the recommendation to replace all dead or missing CS-32 CU-1A plants. Darryl Clark, USFWS, has recommended that NRCS begin the contracting process immediately to have the replacement plantings installed as soon as possible in the 2009 growing season. Please contact Dewey Billodeaux, OCPR project manager, Darryl Clark, USFWS project manager, Dale Garber and me to discuss how, and how soon, this can be accomplished.

TRIP REPORT – via Electronic Mail
--

To: Brad Sticker, CE, NRCS, Alexandria

From: Cindy Steyer, CVS, NRCS, Baton Rouge

Date: April 1, 2010

Subject: East Sabine Lake Hydrologic Restoration Project (CS-32), CU-1A
Field Check of Terrace Vegetation
March 18, 2010

Attendees: Dewey Billodeaux, PE, O&M Manager, OCPR, Lafayette
Darrell Pontiff, PE, Project Engineer, OCPR Lafayette
Mark Mouledous, OCPR, Monitoring Manager, Lafayette
Mike Miller, OCPR, Monitoring Manager, Lafayette
Dale Garber, CE, NRCS, Crowley
Cindy S. Steyer, CVS, NRCS, Baton Rouge

cc: Britt Paul, ASTC-WR, NRCS, Alexandria
Darryl Clark, Project Manager, USFWS, Lafayette
Attendees

Background: The CS-32 East Sabine Hydrologic Restoration Project lies east of Sabine Lake in Cameron Parish, Louisiana. The project area lies within brackish marsh habitat where the typical average monthly water salinity normally ranges from 3 to 8 ppt throughout the year. This report summarizes a field check of the vegetation component of this project, particularly of the most recent Construction Unit 1B planting installed in July 2009 to complete or replace the CU 1A terrace (Figures 1 and 2) vegetation damaged or destroyed by hurricane Ike (see Feb 2009 Trip Report, Subject: *CU-1A Post-Hurricane Damage Assessment of Terrace Vegetation*).

The Sabine Lake area was severely impacted by Hurricane Ike in September 2008. The project area was inundated by storm surge exceeding 10 feet, and then remained submerged under unusually high water levels for over a month following landfall. In addition, elevated salinities well above normal persisted in the project area until the fall of 2009. Smooth cordgrass, including the ‘Vermilion’ ecotype, is very flood and salt tolerant, and naturally occurs in the intertidal zones (approx. between mean high and mean low water) of brackish and saline wetland habitats. Nevertheless, the combination of a significant abrupt increase in salinity and prolonged elevation of water levels can severely impact smooth cordgrass plants,

causing die-back of plant portions or complete mortality. The specific effects of any particular event are influenced by the degree and duration of the increase in water and soil salinity, depth and duration of flooding, temperature, season, and condition of the plants (for example, recently transplanted vs. established).




Figure 1. CS-32 East Sabine Hydrologic Restoration Project Plan Map – CU-1A.




Figure 2. CS-32 East Sabine Hydrologic Restoration Project CU-1A Terrace Layout.

Findings: The team of above attendees traveled to the project site on March 18, 2010 to check the condition of the terraces and plantings. While traveling to the project area from the Cameron-Meadows boat launch, the area marshes were observed to be characteristic of very brown, late-winter vegetation, likely due to the especially severe winter season which was still persisting with frequent, unusually low minimum temperatures. Salinities within the project area on that date ranged from 2.9 ppt to 3.3 ppt from south to north respectively. The condition of the newest CU-1B plantings appeared very poor and severely browned – surprisingly similar to that of the CU-1 and CU-1A plantings following hurricanes Ike and Rita (see 2006 and 2008 Trip Reports). Many contract plants appeared missing or dead without having produced any new stems prior to winter. A very few stems of just emerging, tender growth were observed at the base of a small percentage of newest contract plants. But also, severe die-back of the above-ground plant tissue was evident throughout most of the earlier plantings that had previously recovered well and were spreading, as well as in the natural adjacent herbaceous marsh.

Condition of existing natural emergent marsh next to terraces:





Examples of condition of older plantings when appeared to be recovering well in August 2009:





Contrast above with the appearance of the condition of those older plantings in March 2010:















March 2010 condition of terrace segments with combination of older and recent plantings:







March 2010 condition of newest plantings:











For the newest CU-1B plantings, it is not likely that the source of the plants is a factor contributing to their current state, as the contract plants came from two different nurseries, one in Cameron Parish and one in Lafourche Parish, and all of the remaining plants from the other CU's generally appeared to be in the same condition on the date of this field trip.

Although mainly conjecture, weather could have played a causative role in the overall plant condition we observed. Installation of the CU-1B plantings was completed in July 2009 which turned out to be less than an ideal time for bare-root plant establishment. Following the extreme and prolonged saltwater inundation from hurricane Ike surge in September 2008, southwest LA experienced severe drought conditions in the first half of 2009, with a precipitation deficit persisting until October. In addition, discreet and continuous measurements during the summer revealed that salinities in the project area were significantly higher than normal - greater than 12ppt, and with water temperatures remaining around 85°F until September (CRMS). This may have led to stagnant or phytotoxic soil conditions until precipitation levels returned to normal in October, but by that time it was already at the end of the growing season when plants are beginning to senesce. This period was then followed by an unusually cold winter pattern that began in late November and persisted throughout south Louisiana. Minimum temperatures frequently dropped into the 30's or below for at least half of Jan and Feb 2010 dates (NWS monthly summaries for the Lake Charles/Port Arthur area). It is possible that the newest plantings experienced higher mortality or dieback of aboveground tissue from the combination of elevated stress during initial acclimation and then additional impact by the ensuing cold temperatures to any new shoot growth that did occur. Further, following a typical winter season, robust new growth is not usually seen in smooth cordgrass until March when warmer spring temperatures become entrenched. So it is also possible that this year's new growth expected for all plants in the area may still be absent because it's been retarded by the persistent winter weather pattern and the late freeze in early March.

Because of the high uncertainty at this date of what below-ground tissue remains viable, a mortality rate or pattern cannot reasonably be determined for any of the plantings, regardless of age. I recommend returning to the project site in September near the end of this year's growing season when a much more accurate assessment of the extent of plant survival can be made. Collection and analysis of soil samples may also provide additional insight in discerning actual causes of the apparent poor performance of all the plants.

TRIP REPORT – via Electronic Mail

To: Brad Sticker, CE, NRCS, Alexandria

From: Cindy Steyer, CVS, NRCS, Baton Rouge

Date: October 6, 2010

Subject: East Sabine Lake Hydrologic Restoration Project (CS-32), CU-1A
Field Check of Terrace Vegetation
October 28, 2010

Attendees: Dewey Billodeaux, PE, O&M Manager, OCPR, Lafayette
Mark Mouldous, OCPR, Monitoring Manager, Lafayette
Mike Miller, OCPR, Monitoring Manager, Lafayette
Dale Garber, CE, NRCS, Crowley
Cindy S. Steyer, CVS, NRCS, Baton Rouge
Darryl Clark, Project Manager, USFWS, Lafayette

cc: Britt Paul, ASTC-WR, NRCS, Alexandria
Attendees

Background: The CS-32 East Sabine Hydrologic Restoration Project lies east of Sabine Lake in Cameron Parish, Louisiana. The project area lies within brackish marsh habitat where the typical average monthly water salinity normally ranges from 3 to 8 ppt throughout the year. This report summarizes a field check of the vegetation component of this project, particularly of the most recent Construction Unit 1B planting installed in July 2009.

This project's construction and plantings were implemented in multiple actions as a result of interruptions and impacts from hurricanes, and a surplus of project funds later allowed for construction of additional terraces. The following is a summary list of the actions to build, and plant or replant the project terraces:

CU-1	2005	Original contract work to install 171,000 LF of terraces and 142,500 transplants (Figure 1) was 54% complete when interrupted by hurricanes Katrina and Rita.
CU-1	2006	Resumed work Post-Rita to complete the remaining 46% of terraces, and the contract was modified to replant damaged terraces with an additional 42,500 transplants.
CU-1A	2008	Contract to install an additional 50,000 LF of terraces with 41,000 transplants (Figure 2) was nearly complete when interrupted by hurricane Ike (two Row 1 segments not constructed, remainder of Row 1 not finished to grade or planted).
CU-1B	2009	Contract to replant damaged CU-1A terraces with 32,200 transplants.




Figure 1. CU-1 contract plan for 171,000 LF terraces and vegetative plantings.




Figure 2. CU-1A contract plan for 50,000 LF terraces and vegetative plantings.

For details of hurricane damage and vegetative planting assessments, and recommendations throughout this project's construction phase to date, see May 2006 Trip Report - Subject: *East Sabine Lake Hydrologic Restoration Project (CS-32) Post-Hurricane Damage Assessment of Terrace Vegetation October 27, 2005 and April 3, 2005*; and February 2009 Trip Report - Subject: *CU-1A Post-Hurricane Damage Assessment of Terrace Vegetation*; and April 2010 Trip Report – Subject: *CU-1A Field Check of Terrace Vegetation March 18, 2010*.

Findings: On October 6, 2010, the team of above attendees traveled by two airboats from the Cameron Meadows boat landing to the project site to check the condition of the terraces and plantings. The field party generally moved from south to north through the entire project area– from CU-1 Rows 16 to 25, to CU-1A/B Rows 11 to 1, to CU-1 Rows 14A to 1B. Water salinity and soil EC was measured at sites along a north-south transect, and six soil samples from within the CU-1A/B terraces were collected for Mike Lindsay, NRCS soil scientist, to perform a lab check on EC using a saturated paste method of analysis. Water salinity within the project area on that date ranged from 7.5 ppt to 9.8 ppt.

The vegetative growth of smooth cordgrass on the oldest and southeasternmost CU-1 Rows 16 to 25 looked excellent, as did that on newer CU-1A/B Rows 11 to 8, and the coverage was nearly 100%. The few gaps that were occasionally present on a few segments were minor and some gaps were occupied by other species such as seashore paspalum (*Paspalum vaginatum*) where the terrace crown was above the water elevation on this date.







The estimated survival of the newer CU-1A/B plantings was very good in Rows 5 to 11 (greater than 80%), although the size of the gaps were more significant and narrowing of some terrace segments became more noticeable as we neared Row 5.







As the party continued north, the survival estimates for the rows dropped dramatically and ranged from fair to poor (5% to 50%) on the CU-1A/B Rows 4 to 2, but the vegetation that did remain appeared to be recovering well and for the most part looked very healthy.





There were a few exceptions however where some plants appeared to be struggling, but those were generally found where the terrace segments were severely impacted and were obviously narrowed with lower crown elevation.



The survival on CU-1A/B Row 1, south of Green's Lake, was about 75%. Here again, the surviving plants looked very healthy and provided nearly 100% cover across the crown in some spots, but there were also other stretches bare of vegetation more than 100 feet long on this row.







The older CU-1 Row 14A terraces continue to be in very good shape, and well covered with vegetation (below). Most of the crown cover however was from a variety of other pioneering species, mainly seashore paspalum and marshhay cordgrass (*Spartina patens*), but seashore elder (*Iva imbricata*), leafy three-square (*Schoenoplectus maritimus*), goldenrod (*Solidago* sp.) and sedges (*Cyperus* spp.) were also present, as well as saltmarsh aster (*aster tenuifolius*), cattail (*Typha* spp.), camphorweed (*Pluchea camphorata*) and marsh morningglory (*Ipomoea sagittata*), and walter's millet (*Echinochloa walteri*). The smooth cordgrass at the toe of this row's segments actually looked in poor shape, and the cover it provided was sparse along some edges.





Overall, the southern rows of CU-1 group looked stable though some had obviously narrowed. There were some areas of loss observed, but there was no discernable pattern that might explain the loss, or why the smooth cordgrass was not recovering well on some segments or in spots, but on others, though providing thin cover, the individual plants looked fairly robust.





Continuing north, the survival and cover on the CU-1 terraces was found to vary quite a lot. Many terrace segments were much narrower and had poor to no cover, but there were other segments where the cover was good and the terraces retained their width. Overall though, there were only a few sites found where individual smooth cordgrass plants looked as robust as those seen to the south. It almost appeared that some plantings were just beginning to re-emerge and expand the cover.















The water salinity and soil EC data, and the vegetative coverage estimates recorded by the field party are attached. A lot of photographs have been included in this report to fully illustrate just how widely

the condition of the terraces and plantings ranged over the 221,000 LF (nearly 42 miles) of terraces. Over the entire project, I would estimate that vegetative cover of the terraces is at approximately 50%. The impact of the combination of storms and repeated years of drought had been extreme, although the current soil and water salinity/EC conditions on this date were well within tolerable ranges for smooth cordgrass. A large portion of the remaining plantings still appear to be in a recovery mode and may just require more time to achieve desired vigor and expansion.

Recommendation: The project team discussed options and it is recommended that the construction phase of this project be closed out. The remaining plantings are expected to continue to recover and expand but where there are large stretches of missing plants, it is advisable to re-vegetate with additional plantings that can be conducted through O&M. I recommend that an O&M planting to target areas with poor to no cover be planned for TY1 or 2, and could probably be accomplished for less than \$100,000 (not amortized \$). To provide for adequate cover to be maintained throughout the 20-year project life, O&M funds should also be available for an additional O&M planting event if it becomes necessary later in the project life. Darryl Clark has confirmed that there currently is \$254,428.04 in the project O&M budget, which is sufficient to fund a TY1 or 2 planting. OCPR typically implements the O&M activities, but if USFWS & OCPR agree, NRCS can design and implement the planting.

The condition of the terraces and plantings should be reassessed again by the end of October 2011 at which time a more accurate estimate of the replanting needs will be made.

**U.S. FISH AND WILDLIFE SERVICE
ECOLOGICAL SERVICES**

646 Cajundome Blvd. Suite 400

Lafayette, LA 70506
(337) 291-3111 (Clark), 3100 (Main)
FAX (337) 291-3139
E-mail: Darryl_Clark@fws.gov

October 26, 2010

TO: East Sabine Lake Project Team

RE: East Sabine Lake Hydrologic Restoration Project October 6, 2010, Terrace Field Trip

Over 45 miles (237,600 linear feet) of vegetated earthen terraces were constructed mostly in 2005 adjacent to the Green Lake area of Sabine National Wildlife Refuge. The second group of 50,000 linear feet of terraces were constructed and planted in 2008 with a lower elevation and smaller crown (9-feet wide) than the original terraces. CRMS station No. 660 water level and salinity data equaled 1.3 feet NAVD and 9.1 ppt respectively. The following are notes from the October 6, 2010 field trip.

Terrace Row	Percent Vegetated	Condition of Plantings	Salinity (ppt)
11	100%	Smooth cordgrass ins in good condition.	8.8
10		Some portions thinly vegetated	
7-4	> 80%	Narrow terrace some bare sections > 50 to 100 feet bare	7.9
7-3	> 80%		
7-2	> 80%		
7-1	> 80%		
5-1	> 70%		
5-2	50%		
5-3?	> 80%		
5-4	> 80%	Good re-vegetation	
5-5	> 80%	Some thin spots	
5-6	> 80%		
5-7	> 80%	Minor bare spots	
5-8	> 80%		
3-1	10%		
3-2	20%		9.3
3-3	25%		

3-4	50%		
3-5	50%		
3-6	10%		
3-7	5%		9.7
3-8	25%		
1-1 & 1-2	N/A	Terraces not constructed.	
1-3	75%	Bare spots > 100 feet long	
1-4	75%		
1-5	50%		
1-6	20%	1,000 unvegetated	
1-7	20%	1,000 unvegetated	
1-8		submerged	
Green Lake Terraces	50%	Most terraces were 15 – 20 feet wide with bare spots. Stubble remains of some vegetation. Some vegetation spread > 5 feet from the terrace platform.	8.4

Overall on some of the poorer terraces the vegetative cover was 20% or less, on others greater than 80%. The overall mean vegetative cover may be closer to about 50%. It is hopeful that in the near future terraces with poor vegetative cover will recover with natural re-vegetation.

The project team decided not to do a third planting of the lasts 2008 constructed terraces. We will close out project first construction costs and E&D and begin the O&M phase. Some vegetative planting O&M may be added in the future to the O&M budget if necessary.


Darryl Clark
Project Manager/Senior Fish and Wildlife Biologist

CS-32 East Sabine Terraces Field Trip October 6, 2010


Water & Soil Salinities & Notes

Table 1. Water & Soil Salinities, etc.

Way-point	Water Salinity (ppt)	Soil Depth (in)	Soil EC Field Probe (mS/cm ³)	Soil EC* Lab Sat Paste (mS/cm ³)	Temp (°C)	Notes
N/A	8.3					At Cameron-Meadows boat landing
632	7.5					CU-1 row 22 segment 3(?); pre-Rita
635		4"	6.02		24.5	CU-1A row 11 segment 1 (south of Row 10); post-Rita, pre-Ike
		12"	6.95			
636		6"	5.55	6.85		CU-1A row 8 segment 5; post-Rita, pre-Ike; (soil sample labeled 'row 8')
		12"	5.35			
637	9.5	6"	6.78			CU-1A row 5 segment 5; post-Rita, pre-Ike
		12"	8.00			
638	8.3	6"	5.46	6.77	23.6	CU-1A row 2 segment 5; post-Rita, pre-Ike: Water EC 14.7 (soil sample labeled 'row 2')
		12"	4.27			
639	9.6	6"	4.57	4.41	24.0	CU-1 row 14(A) noted as segment 5 but segment 4; pre-Rita (soil sample labeled 'row 14')
		12"	6.54			
640	8.4	6"	6.21	7.68	23.5	CU-1 noted as row 7- but row 8 segmt 6; pre-Rita; water EC 14.9; (soil sample labeled 'row 7')
		12"	3.50			
641	8.6	6"	5.68	6.82	23.9	CU-1 noted as row 3- but row 4 segment 4; post-Rita, pre-Ike; (soil sample labeled 'row 3')
		12"	5.66			
642	8.0	6"	3.55	6.98		CU-1 noted as row 1B- but row 1A segment 2; post-Rita, pre-Ike; (soil sample labeled 'row 1B')
		12"	3.65			
CRMS 660	9.1	*6"	13.5			WL 1.3' @ 3:15 pm; *soil EC reading from native soil; site S of WP 632 & 635
		*12"	6.0			
643	7.4					Location in marsh area just west of Burton-Sutton Canal
644	7.9					At intersection of Burton-Sutton and Starks Canals
						*EC Lab reading is an average of two samples



Waypoint Map for October 6, 2010 Field Data from NRCS for Table 1



Map for October 6, 2010 Salinity Data from OCPR – Mike Miller, Monitoring Manager, OCPR Lafayette Field Office