

### State of Louisiana Department of Natural Resources Coastal Engineering Division

# 2005/2006 Annual Inspection Report

for

# PERRY RIDGE SHORELINE PROTECTION PROJECT (CS-24)

State Project Number CS-24 Priority Project List 4

October 6, 2005 Calcasieu Parish

Prepared by:

Mel Guidry, CS-24 O & M Manager LDNR/Coastal Engineering Division Lafayette Field Office 635 Cajundome Blvd.

#### **Table Of Contents**

I. Introduct	tion	1					
II. Inspection Purpose and Procedures							
III. Project Description and History							
IV. Summary of Past Operation and Maintenance Projects							
V. Inspection Results							
VI Conclusi	ons and Recommendations	2					
	Appendices						
Appendix A	Project Features Map						
Appendix B	Photographs						
Appendix C	Three Year Budget Projections						
Appendix D	Appendix D Field Inspection Notes						
Appendix E	Appendix E Map showing areas to be monitored						

#### I. Introduction

The Perry Ridge Shoreline Protection Project (CS-24) is located in the Calcasieu-Sabine Basin on the northern bank of the Gulf Intracoastal Waterway in Calcasieu Parish. The 1,203 acre project area extends from the Perry Ridge on the northern shore of the GIWW eastward to the Vinton Drainage Canal. (See Appendix A).

The Perry Ridge Shoreline Project (CS-24) was authorized by Section 303(a) of Title III Public Law 101-646, the Coastal Wetlands Planning Protection and Restoration Act (CWPPRA) enacted on November 29, 1990 as amended and approved on the fourth Priority Project List. The Perry Ridge Shoreline Project has a twenty –year (20 year) economic life, which began in February 1999.

#### II. Project Description and History

The Perry Ridge Shore Protection project provides features to protect 1,203 ac (481 ha) of vegetated shoreline along the Gulf Intracoastal Waterway (GIWW), which in turn will benefit 5,945 ac (2,378 ha) of predominantly intermediate marsh located north of the shoreline. The project is on the north bank of the GIWW from Perry Ridge to the Vinton Drainage Canal in Calcasieu Parish, Louisiana. The project area is bounded on the north by an arbitrary line connecting the north tip of Big Island and the Gray Canal, on the south by the GIWW, on the east by the Vinton Drainage Canal and the Gray Canal, and on the west by Perry Ridge and Big Island. Approximately 12,000 linear ft (3.7 km) of free-standing rock dike was constructed along the north bank of the GIWW from Perry Ridge to the Vinton Drainage Canal.

The Project has twenty-year (20 year) economic life, which began in February 1999.

The principal project features include:

• Site 1 - Foreshore Rock Dike (approximately 12,000 linear feet)

#### III. Inspection Purpose and Procedures

The purpose of the annual inspection of the Perry Ridge Shoreline Protection Project (CS-24) is to evaluate the constructed project features and identify any deficiencies and prepare a report detailing the condition of project features and recommended corrective actions needed. Should it be determined that corrective actions are needed, LDNR shall provide, in the report, a detailed cost estimate for engineering, design, supervision, inspection, and construction contingencies, and an assessment of the urgency of such repairs (O&M Plan, 2002). The annual inspection report also contains a summary of maintenance projects which were completed since completion of constructed project features and an estimated projected budget for the upcoming three (3) years for operation, maintenance and rehabilitation. The three (3)

year projected operation and maintenance budget is shown in Appendix C. A summary of past operation and maintenance projects completed since completion of the Perry Ridge Shoreline Project(CS-24) are outlined in Section IV.

In 2003, the CWPPRA Task Force determined, due to the fact that LDNR was responsible for the operation and maintenance phase of the vast majority of CWPPRA projects, that LDNR would be the responsible party for all Post Storm/Hurricane Assessments. After Hurricanes Katrina and Rita, every project appeared to have been impacted by the storms; therefore, LDNR determined that all projects should be assessed for damages (Broussard, 2006). With concurrence from the federal sponsor, LDNR has decided to use the information obtained during this post hurricane assessment in this Annual Maintenance Inspection.

An annual O & M inspection of the Perry Ridge Shoreline Project (CS-24) was held on October 6, 2005 under sunny skies and mild temperatures. In attendance were Mel Guidry, Stan Aucoin, Mark Mouledous, and Ricky Brouillette of LDNR, along with Cindy Steyer representing NRCS, and Joy Merino representing NMFS (for other inspections). The field inspection included a complete visual inspection on the entire project site. Staff gauge readings and existing benchmarks were used to determine approximate water elevation and existing elevation of the foreshore rock dike and earthen terraces. Photographs were taken at each project feature (see Appendix B) and field inspection notes were compiled to record measurement and deficiencies (Appendix D).

#### IV. Summary of Past Operation and Maintenance Projects

**General Maintenance:** There has been no required maintenance as of yet on this project.

**2005 Structure Operations:** There are no active operations associated with this project.

#### V. Inspection Results

#### Site 1—Foreshore rock dike

The dike is in good condition and appears to be in the same condition as to what existed prior to the storm and did not sustain any discernable damage from the storm. No maintenance is recommended at this time. (Photos: Appendix B, Photos 1 & 2)

#### VI. Conclusions and Recommendations

The Perry Ridge Shoreline Protection Project is in good condition and functioning as designed and did not sustain any major damage from Hurricane RITA.

# Appendix A

**Project Features Map** 



# Perry Ridge Shore Protection (CS-24)



Fish Dip


Rock Dike

**Project Boundary** 











Appendix B

**Photographs** 



Photo 1, Typical rock dike.



Photo 2, Rock dike tie-in.

# **Appendix C**

**Three Year Budget Projection** 

# PERRY RIDGE SHORELINE PROTECTION/ CS-24 /PPL 4 Three-Year Operations & Maintenance Budgets 07/01/2005 - 06/30/08

Project Manager	O & M Manager	Federal Sponsor	Prepared By					
Pat Landry	Mel Guidry	NRCS	Mel Guidry					
	2005/2006	2006/2007	2007/2008					
Maintenance Inspection	\$ 4,955.00	\$ 5,250.00	\$ 5,407.00					
Structure Operation								
Administration		\$ -	\$ -					
Maintenance/Rehabilitation								
05/06 Description:								
E&D								
Construction								
Construction Oversight								
Sub Total - Maint. And Rehab.	\$ -							
06/07 Description								
E&D		\$ -						
Construction		\$ -						
		,						
Construction Oversight		-						
	Sub Total - Maint. And Rehab.	\$ -						
07/08 Description:								
E&D			-					
Construction			-					
Construction Oversight			\$ -					
		Sub Total - Maint. And Rehab.	\$					
	2005/2006	2006/2007	2007/2008					
Total O&M Budgets	\$ 4,955.00	\$ 5,250.00	\$ 5,407.00					
O &M Budget (3 yr Tota	al)		\$ 15,612.0 <u>0</u>					
Existing O & M Budget	\$ 398,883.00							
Remaining O & M Budg		\$ 383,271.00						

# Appendix D

**Field Inspection Form** 

#### MAINTENANCE INSPECTION REPORT CHECK SHEET

Project No. / Name: CS-24 Perry Ridge Shoreline Protection Date of Inspection: October 6, 2005

Structure No. Inspector(s): Stan Aucoin, Herb Juneau, Mark Mouledous

Ricky Brouillette(LDNR); Cindy Steyer (NRCS), Joy Merino (NMFS) Structure Description: Rock Dike

Water Level +2.6

Type of Inspection: Weather Conditions: Clear & mild Annual

Item	Condition	Physical Damage	Corrosion	Photo #	Observations and Remarks
·	N/A				
Steel Bulkhead					
/ Caps					
Steel Grating	N/A				
Stop Logo	N/A				
Stop Logs	IN/A				
Hardware	N/A				
Timber Piles	N/A				
T:	N1/A				
Timber Wales	N/A				
Galv. Pile Caps	N/A				
Gaiv. File Caps	14//				
Cables	N/A				
Signage	N/A				
/Supports					
Rip Rap (fill)	Good			1 & 2	
(foreshore dike)	G000			10.2	
(ioresnote dike)					
Earthen	N/A				
Embankment					

What are the conditions of the existing levees? Are there any noticeable breaches? Settlement of rock plugs and rock weirs? Position of stoplogs at the time of the inspection? Are there any signs of vandalism?

# Appendix E

**Locations to be Monitored**