


SURVEY REPORT

WEST BELLE PASS BARRIER HEADLAND RESTORATION (TE-52) PROJECT – BATHYMETRIC AND TOPOGRAPHIC SURVEYS

Lafourche Parish, Louisiana

Contract No. 2503-14-24 – Task #6

Attention:
Mr. Travis Byland
Coastal Protection & Restoration Authority
1440 Tiger Drive, Suite B
Thibodaux, LA 70301
985-449-5073 (office)
985-447-0997 (Fax)
Travis.Byland@LA.GOV

STATE OF LOUISIANA
Ricardo M. Johnson
REG No. 4767
REGISTERED PROFESSIONAL
LAND SURVEYOR

Ricardo M. Johnson, PLS LA Reg. 4767
Sr. Project Manager of Government Services
John Chance Land Surveys, Inc.
200 Dulles Drive
Lafayette, Louisiana 70506

February 25, 2015

JCLS REF. No. 20140587

Contacts:	Jimmie Stoute	President	(337) 268-3231	jstoute@fugro.com
	Robert Price	Vice President	(337) 268-3265	rprice@fugro.com
	Ricardo Johnson	Sr. Project Manager	(337) 268-3151	rjohnson@fugro.com

TABLE OF CONTENTS

SECTION A	**Scope of Work**
SECTION B	**Methodology Report**
SECTION C	**Static GPS Report**
SECTION D	**RTK Survey**
SECTION E	**Bathymetric Survey**
SECTION F	**Fieldnotes**
SECTION G	**Photos**
SECTION H	**Maps**

SECTION A

Scope of Work

SCOPE OF SERVICES
FOR TOPOGRAPHIC AND BATHYMETRIC SURVEY

WEST BELLE PASS BARRIER HEADLAND
RESTORATION (TE-52) PROJECT
LAFOURCHE PARISH, LOUISIANA

November 24, 2014

1.0 INTRODUCTION

The Operations Division of the Coastal Protection and Restoration Authority of Louisiana (CPRA) is responsible for monitoring, maintaining, and operating projects that restore, create, enhance, and maintain coastal wetlands in Louisiana. Tasked with these functions, CPRA periodically evaluate orthometric heights to determine project success and ecosystem sustainability. Analysis of elevation change is an important tool used to evaluate geomorphic alterations in headland and barrier island systems because these ephemeral environments are shaped by erosional and longshore transport processes. This Scope of Services will provide for topographic and bathymetric orthometric height surveys of littoral, beach, washover, marsh, and bay environments for the West Belle Pass Barrier Headland Restoration (TE-52) project. Specifically, previously established cross sectional transects will be reoccupied and surveyed using Real Time Kinematic (RTK) methods and the Louisiana Coastal Zone (LCZ) GPS Network. The environmental consulting company hereafter referred to as the "Contracting Party", will perform the specified services according to this Scope of Services.

2.0 LOCATION & ACCESS

The West Belle Pass Barrier Headland Restoration (TE-52) project is located approximately 2 miles southwest of Port Fourchon and is positioned 0.3 miles west of the Belle Pass Rock Jetties in Lafourche Parish, Louisiana (figure 1 of appendix A). The TE-52 project area occupies 411 acres (166 ha) and created or enhanced beach, dune, and marsh habitats. The location of the specific survey transects to be occupied by the Contracting Party are graphically illustrated in figure 2 of appendix A. The coordinates for these monitoring stations were established using the UTM NAD 83 Coordinate System in meters and will be provided to the Contracting Party in ESRI shapefile (.shp) and Google Earth (.kml) formats. Figure 1 also depicts the location of highway and boat access in the vicinity of this restoration project. Shape (.shp) and Google Earth (.kml) files (UTM NAD 83) will also be made available to the Contracting Party to locate highway, boat launch, and nautical routes. Further boat launch information can be found at: http://lamarinas.losco.lsu.edu/

Permission to access the West Belle Pass Barrier Headland Restoration (TE-52) project area is required from Mr. Lawrence "Les" Rosso of the Louisiana Office of

State Lands (Les.Rosso@la.gov) at least 48 hours prior to beginning any work in the field. He is to be notified each time the Contracting Party visits the property except where advance notice has been given for consecutive day visits. Further contact information for Mr. Rosso is listed in appendix B.

3.0 SCOPE OF WORK

3.1 Minimum Standards

All topographic and bathymetric RTK surveys shall be conducted as per the January 2013 Contractors Guide to Minimum Standards as required by the Coastal Protection and Restoration Authority of Louisiana (CPRA). A digital and/or paper copy of this document will be provided to the contractor.

3.2 Control

Static monuments used as a control are tied into the CPRA - Louisiana Coastal Zone (LCZ) GPS Network. The Contracting Party shall conduct all surveying activities using the TE23-SM-01 monument, which was statically surveyed into the LCZ GPS network using the Geoid12A model. This monument is identified by the Louisiana State Plane Coordinate System South Zone (LSZ), the North American Horizontal Datum of 1983 (NAD 83), and the North American Vertical Datum of 1988 (NAVD88). Monument LSZ and UTM NAD 83 coordinates are listed in table 1 of appendix A, and the official data sheet is exhibited in figure 3 of appendix A. ESRI shapefiles (.shp) and Google Earth (.kml) files (UTM NAD 83 in meters) will also be provided to locate TE23-SM-01 monument.

3.3 Survey Overview

This scope of work includes completing topographic and bathymetric surveys of littoral, beach, dune, marsh, and bay environments. These surveys will be conducted on 26 cross sectional transects. These transects will be separated by 500 ft (152 m) intervals (figure 2). In addition, ten (10) settlement plates installed for the TE-52 project in 2012 will be surveyed. This survey is the first in a series of five post-construction surveys to be conducted for the West Belle Pass Barrier Headland Restoration (TE-52) project. A pre-construction survey was completed in Aug 2008, and the as-built survey was completed in Oct 2012. Elevation data collected as part of this scope will be used to evaluate the created environments and detect shoreface and headland migration trends. The TE-52 project is located on the downdrift side of the Belle Pass Jetties; and as a result, very little sediment is expected to nourish the project area from the larger eastern portion of the Caminada-Moreau Headland.

3.4 RTK Topographic Survey

The Contracting Party shall reference horizontal survey coordinates to the North American Horizontal Datum of 1983 (NAD 83) using the Lambert Conformal Conic Projection and the Louisiana State Plane South Zone (LSZ) Coordinate System. Vertical elevation surveys shall be referenced to the North American Vertical Datum of 1988 (NAVD 88) and will utilize the Geoid 12A model to determine orthometric heights. The data shall be reported in feet to two decimal places.

The Contracting Party will topographically survey the subaerial (terrestrial) segments of the 26 survey transects defined in figure 2 using Real Time Kinematic (RTK) methods. The topographic portions of all transects will merge with the bathymetric portions at the land/water interfaces. The topographic portions will begin in the wading depth part of the shoreface and will extend landward along the survey transects. Moreover, the topographic and bathymetric portions of these transects will be separated by no more than 25 ft. All topographic points shall be collected at significant breaks in the slope (i.e., dune crests; dune toes; seaward berm; at all changes in elevation of 0.5 feet or greater, etc.) so that the resulting data accurately depict the headland morphology. Survey points shall be no more than 25 feet apart and may be closer depending on island topography. Transects 8-21 bisect the northern containment dike and will extend 100 ft past the edge of the bay shoreline. All other cross sections (1-7 and 22-26) will terminate at the northern limits of their respective transect line. ESRI shapefiles (.shp) and Google Earth (.kml) files (UTM NAD 83 in meters) will be provided to locate all 26 transects.

3.5 RTK Bathymetric Survey

The Contracting Party shall reference horizontal survey coordinates to the North American Horizontal Datum of 1983 (NAD 83) using the Lambert Conformal Conic Projection and the Louisiana State Plane South Zone (LSZ) Coordinate System. Vertical elevation surveys shall be referenced to the North American Vertical Datum of 1988 (NAVD 88) and will utilize the Geoid 12A model to determine orthometric heights. The data shall be reported in feet to two decimal places.

The Contracting Party will collect bathymetric data using a standard echo-based surveying technique (fathometer) and Real Time Kinematic (RTK) methods. Boat-based echo soundings data shall be corrected to compensate for water-level fluctuations caused by surface waves, list, and astronomical tides. In addition, a sampling rate of at least 5 Hz (5 points/second) should be used during data collection. The tide correction shall be determined from an electronic water level recorder which continuously records the water elevation and is installed or located near the project area.

The Contracting Party shall bathymetrically survey the subaqueous (aquatic) segments of the 26 cross sectional transects defined in figure 2. The survey will begin at the southern boundary of each transect line and proceed north for all 26 transects. The bathymetric segments will merge with the topographic survey at the land/water interface. Moreover, the point separation between the topographic and bathymetric portions of each transect will not exceed 25 ft. For the transects that intersect the western spit (22-26) the survey can be conducted entirely bathymetrically if water depth allows as long as the cross sections terminate at the northern limits of their respective transect line. Likewise, the last 100 ft of transects 8-21 can also be surveyed bathymetrically if water depth allows. ESRI shapefiles (.shp) and Google Earth (.kml) files (UTM NAD 83 in meters) will be provided to locate the survey transects for the 26 transects. Either during data collection or post-processing, the Contracting Party will filter the bathymetric data to a 5 foot resolution.

3.6 RTK Topographic Settlement Plate Survey

The Contracting Party shall reference horizontal survey coordinates to the North American Horizontal Datum of 1983 (NAD 83) using the Lambert Conformal Conic Projection and the Louisiana State Plane South Zone (LSZ) Coordinate System. Vertical elevation surveys shall be referenced to the North American Vertical Datum of 1988 (NAVD 88) and will utilize the Geoid 12A model to determine orthometric heights. The data shall be reported in feet to two decimal places.

The Contracting Party will survey ten (10) settlement plates inside the TE-52 project area using Real Time Kinematic (RTK) methods (figure 4). A single elevation point will be taken at the top of each settlement plate pipe on the threaded or welded cap (figure 5) (SP1-SP10). Also, the condition of the settlement plates shall be described (is the pipe leaning, damaged, etc…) in the field notes. ESRI shapefiles (.shp) and Google Earth (.kml) files (UTM NAD 83 in meters) will be provided to locate all settlement plates. If settlement plates are not located, those individual plate(s) do not need to be surveyed.

4.0 DELIVERABLES

GPS Survey Report
Upon completion of the survey, a GPS Survey Report shall be provided to OCPR in Microsoft Word format and written to a compact disc (CD) inserted within the 8 ½" x 11" bound hard copy of the report.

The GPS Survey Report shall contain and not be limited to the following information:

4.1 Methodology Report

The Methodology Report shall be in Microsoft Word format and written to the compact

disc (CD). The hard copies shall be signed and stamped by the Registered/Professional Land Surveyor in the State of Louisiana who was directly involved with the project. The hard copies shall be bound in the GPS Survey Report.

The report shall contain but not be limited to the following information:
(Include dates for each job task and key personnel involved)

- ***Project Description***
- ***Planning and layout of the GPS Survey***
- ***Chronological Summary of Work***
- ***Information on Secondary Monuments used as reference stations***
- ***The GPS RTK Survey including quality control (elevation check) procedures***
- ***Equipment used for data collection***
- ***Downloading and Processing procedures***

4.2 Field Notebook Records

The information to be included in the field notebook will be as follows:

- ***Project name***
- ***Date of survey***
- ***Crew members***
- ***RTK Base Monument name***
- ***Sketch of Location***
- ***RTK point numbers, descriptions, and elevations observed***

4.3 Drawing Files

The following two 11"x17" drawings shall be completed as a requirement of this scope, a plan view drawing and an elevation contour drawing. The plan view drawing shall include a recent aerial image of the West Belle Pass vicinity, the survey transects, settlement plates, and the TE23-SM-01 benchmark. The contour drawing will topographically illustrate the elevation contour results from the survey. The elevation contour drawing shall include a recent aerial image of the West Belle Pass vicinity and the contour lines. All variables will be clearly labeled and accurately plotted. The drawing files shall be in a digital format such as AutoCAD (*.dwg or *.dxf) and written to the compact disk (CD) along with hard copies each bound in the final GPS Survey Report and folded to fit within the 8 ½" x 11" methodology report. ESRI shapefiles (.shp) showing the UTM NAD 83 (m) location of the breakwater and groin structures will be provided to the Contracting Party to create the drawings. Plan view and elevation contour drawing examples will also be given to the Contracting Party in AutoCAD (.dwg) formats.

Additional information to be included on the Plan View and Elevation Contour Drawings will be as follows:

- ***Project Name***
- ***Contractor Name***
- ***Digital aerial or USGS Quadrangle with monuments plotted correctly***
- ***Monument Names***
- ***Horizontal and Vertical Datum***
- ***Map Date***
- ***Map Scale***
- ***North Arrow***

4.4 Survey Data

The RTK survey data results shall be reported in Microsoft Excel format arranged in columns and written to the compact disc (CD). The file will contain the following columns: project number, group, date, point #; adjusted NAD83 Geodetic, Lambert Coordinate (LSZ, ft), and **UTM (meters)** positions; adjusted NAVD88 elevation (ft); NAVD88 elevation (m); and description. Table 2 of appendix C illustrates and defines the correct data format. An example Excel (.xls) file will also be provided to the Contracting Party.

The Contracting Party shall prepare and deliver one (1) draft copy of the deliverables (including the inserted CD) described above to CPRA. This draft copy will be sent to the following CPRA representative for review:

Travis Byland
CPRA
1440 Tiger Drive, Suite B
Thibodaux, LA 70301

TEL: (985) 449-5073
FAX: (985) 447-0997

Drafts will be reviewed by CPRA and four (4) final deliverables will be delivered to CPRA two weeks after receipt of comments.

5.0 CERTIFICATION

All deliverables shall be certified by a professional land surveyor licensed by the State of Louisiana.

APPENDIX A

WEST BELLE PASS, SURVEY TRANSECT, & STATIC MONUMENT LOCATION MAPS & TABLES



Figure 1. Location, route, and vicinity of the West Belle Pass Barrier Headland Restoration (TE-52) project.




Figure 2. Location of the survey transects to be occupied by the Contracting Party at the West Belle Pass Barrier Headland Restoration (TE-52) project.



VICINITY MAP Scale: 1" = 2000'

2013 NAIP imagery provided by USDA Farm Service Agency

Station Name: "TE23-SM-01"

Location: Station is located southeast of Port Fourchon, 40' east of the centerline of La. Hwy. 3090 and 65' northeast of bridge approach near Pass Fourchon.

Monument Description: NGS style floating sleeve monument; datum point set on 9/16" stainless steel sectional rods driven 96 feet to refusal, set in sand filled 6" PVC pipe set in concrete with access cover.

Stamping: TE23-SM-01

Installation Date: September 2003 **Date of Survey:** May 2014

Monument Established By: Morris P. Hebert, Inc.

For: *Louisiana Department of Natural Resources, CRD*

Adjusted NAD 83 Geodetic Position
Lat. 29°06'42.2851" N
Long.90°11'26.9637"W

Adjusted NAD 83 Datum LSZ (1702) Feet
N= 224,296.37
E= 3,645,688.81

Adjusted UTM, NAD 83 Datum (Zone 15) Meters
N = 3,223,628.371
E= 773,376.916

Adjusted NAVD88 (2011) Height
Elevation Geoid12A = 7.30 ft (2.224 mtrs)
Elevation Geoid99 = 8.05 feet (2.454 Mtrs)

Ellipsoid Height = -21.569 mtrs
Geoid 12A Height = -23.793 mtrs

Ellipsoid Height = -21.569 Mtrs
Geoid99 Height = -24.023 Mtrs



Adjusted Position Established by T. Baker Smith, LLC for the Coastal Protection and Restoration Authority.

Figure 3. **Data sheet for static monument TE23-SM-01.**

Table 1. **LSZ and UTM NAD 83 coordinates for the TE48-SM-01 (COON) static monument.**

Static Monument	*Coordinate System*	*x=Easting*	*y=Northing*
TE23-SM-01	LSZ NAD 83 (ft)	3,645,688.81	224,296.37
TE23-SM-01	UTM NAD 83 (m)	773,376.916	3,223,628.371




Figure 4. **Location of the West Belle Pass Barrier Headland Restoration (TE-52) project Settlement Plates.**




Figure 5. **Typical View of the West Belle Pass Barrier Headland Restoration (TE-52) project Settlement Plates.**

APPENDIX B

LANDOWNER CONTACT INFOMATION

Contact:

Mr. Lawrence "Les" Rosso
Louisiana Office of State Lands
P.O. Box 44124
Baton Rouge, Louisiana 70804

Phone: (225) 342-4600
Fax: (225) 342-5458
E-mail: Les.Rosso@la.gov

APPENDIX C

RTK DATA FORMATS

Table 2. Example spreadsheet showing required RTK survey data formats.

Project Number	Group	Date (MM/DD/YYYY)	Point #	Easting_LSZ NAD83 (ft)	Northing_LSZ NAD83 (ft)	Easting_UTM NAD83 (m)	Northing_UTM NAD83 (m)	Elevation_NAVD88 (ft)	Elevation_NAVD88 (m)	Description
AT-03	DA-1	11/13/2003	15353	3426061.465	537721.7721	705056.893	3318229.978	1.929	0.588	EL
AT-03	DA-1	11/13/2003	15354	3426083.115	537734.2721	705063.437	3318233.884	4.28	1.305	EL
AT-03	DA-1	11/13/2003	15355	3426081.383	537733.2721	705062.913	3318233.571	7.14	2.176	EL
AT-03	DA-1	11/13/2003	15356	3426074.455	537729.2721	705060.819	3318232.321	2.759	0.841	EL
AT-03	DA-1	11/13/2003	15357	3426065.795	537724.2721	705058.202	3318230.759	4.17	1.271	EL
AT-03	DA-1	11/13/2003	15358	3426057.134	537719.2721	705055.584	3318229.196	6.32	1.926	EL
AT-03	DA-1	11/13/2003	15359	3426048.474	537714.2721	705052.966	3318227.634	4.398	1.341	EL
AT-03	DA-1	11/13/2003	15360	3426039.814	537709.2721	705050.348	3318226.071	4.65	1.417	EL
AT-03	DA-1	11/13/2003	15361	3426031.154	537704.2721	705047.731	3318224.509	8.44	2.573	EL
AT-03	DA-1	11/13/2003	15362	3426022.493	537699.2721	705045.113	3318222.946	3.945	1.202	EL
AT-03	DA-1	11/13/2003	15363	3426013.833	537694.2721	705042.495	3318221.384	4.85	1.478	EL
AT-03	DA-1	11/13/2003	15364	3426005.173	537689.2721	705039.877	3318219.821	7.13	2.174	EL
AT-03	DA-1	11/13/2003	15365	3425996.513	537684.2721	705037.26	3318218.259	6.707	2.044	EL
AT-03	DA-1	11/13/2003	15366	3425994.781	537683.2721	705036.736	3318217.946	4.45	1.356	EL
AT-03	DA-1	11/13/2003	15367	3425974.862	537671.7721	705030.715	3318214.353	6.02	1.835	EL
AT-03	DA-1	11/13/2003	15368	3427983.208	535250.6157	705653.644	3317485.217	3.631	1.107	EL
AT-03	DA-1	11/13/2003	15369	3427969.228	535229.8698	705649.474	3317478.837	5.08	1.548	EL
AT-03	DA-1	11/13/2003	15370	3427968.669	535229.0607	705649.308	3317478.582	6.40	1.951	EL
AT-03	DA-1	11/13/2003	15371	3427963.637	535221.5994	705647.807	3317476.285	4.037	1.230	EL
AT-03	DA-1	11/13/2003	15372	3427958.045	535213.309	705646.139	3317473.733	4.66	1.420	EL
AT-03	DA-1	11/13/2003	15373	3427952.453	535205.0186	705644.471	3317471.181	7.72	2.353	EL
AT-03	DA-1	11/13/2003	15374	3427946.861	535196.7283	705642.803	3317468.629	4.037	1.230	EL
AT-03	DA-1	11/13/2003	15375	3427941.269	535188.4379	705641.135	3317466.078	3.44	1.049	EL
AT-03	DA-1	11/13/2003	15376	3427935.677	535180.1475	705639.467	3317463.526	4.72	1.439	EL
AT-03	DA-1	11/13/2003	15377	3427930.085	535171.8571	705637.799	3317460.974	3.565	1.087	EL
AT-03	DA-1	11/13/2003	15378	3427924.493	535163.5668	705636.132	3317458.422	4.53	1.381	EL
AT-03	DA-1	11/13/2003	15379	3427918.901	535155.2764	705634.464	3317455.87	6.80	2.073	EL
AT-03	DA-1	11/13/2003	15380	3427913.309	535146.986	705632.796	3317453.318	8.536	2.602	EL
AT-03	DA-1	11/13/2003	15381	3427912.75	535146.157	705632.629	3317453.063	4.62	1.408	EL
AT-03	DA-1	11/13/2003	15382	3427899.329	535126.2601	705628.626	3317446.938	7.66	2.335	EL

Where

Project Number is TE-52,
Group is the Transect Number,
Date (MM/DD/YYYY) is the date the point was collected,
Point # is the Survey Point Number,
Easting LSZ NAD83 (ft) is the easting coordinate in State Plane, NAD83 – LA South 1702 in Feet,
Northing LSZ NAD83 (ft) is the northing coordinate in State Plane, NAD83 – LA South 1702 in Feet,
Easting UTM NAD83 (m) is the easting coordinate in Universal Transverse Mercator Zone 15, NAD83 – in Meters,
Northing UTM NAD83(m) is the northing coordinate in Universal Transverse Mercator Zone 15, NAD83 – in Meters,
Elevation NAVD88 (ft) is the orthometric height at a specific coordinate referenced to the NAVD88 and the Geoid12A Model – in Feet,
Elevation NAVD88 (m) is the orthometric height at a specific coordinate referenced to the NAVD88 and the Geoid12A Model – in Meters, and
Description describes the location where the point was taken.

SECTION B

Methodology Report

SURVEY METHODOLOGY REPORT

Prepared for

Coastal Protection & Restoration Authority of Louisiana

in Support of

WEST BELLE PASS BARRIER HEADLAND RESTORATION (TE-52) PROJECT

Lafourche Parish, Louisiana

January 2015

Introduction

The Operations Division of the Coastal Protection and Restoration Authority of Louisiana (CPRA) is responsible for monitoring, maintaining, and operating projects that restore, create, enhance, and maintain coastal wetlands in Louisiana. Tasks with these functions, CPRA periodically evaluate orthometric heights to determine project success and ecosystem sustainability. Analysis of elevation change is an important tool used to evaluate geomorphic alterations in headland and barrier island systems because these ephemeral environments are shaped by erosional and longshore transport processes. This Scope of Services will provide for topographic and bathymetric orthometric height surveys of littoral, breach, washover, marsh, and bay environments for the West Belle Pass Barrier Headland Restoration (TE-52) project. Specifically, previously established cross-sectional transects will be reoccupied and surveyed using Real-time Kinematic (RTK) methods and the Louisiana Coastal Zone (LCZ) Network.

Pre-Planning and Static GPS Survey

On Monday, January 12, 2015, topographic and bathymetric survey crews mobilized all necessary equipment for the project and traveled from the Lafayette office of John Chance Land Surveys, Inc. (JCLS). Coordinates for the pre-plotted transect lines, reference monuments, were all setup in the Trimble Business Center (TBC) project file, then uploaded into the positioning devices. Upon completing the mobilization, the survey crew made the 4-hour drive to Fourchon, Louisiana to locate accommodations and commence the survey on the following day.



Once at the project site, the topographic crew located an existing deep rod monument to be used as the project reference control. GPS monument "TE23-SM-01" was located along Louisiana Highway 3090 near West Belle Pass on the northeast bridge approach near Pass Fourchon. Established by CPRA, this monument consisted of a 9/16 inch diameter spherical datum point attached to a 9/16-inch stainless steel sectional rods within a grease filled floating sleeve and driven 96 feet to refusal. This monument is encased within a 6-inch PVC pipe filled with sand and set in concrete with a protective aluminum access cover. JCLS had most recently updated the elevation of this monument with NAVD88 values using Geoid12A by performing Static GPS network adjustment using CORS in support of the East Timbalier Island Restoration Project (TE-118).

To begin the static survey, the survey crew located the GPS/RTK base station at monument. “TE23-SM-01”. A two-meter fixed height tripod was used to eliminate human error that could have been introduced by miss-measurement of the GPS antenna height. Once all necessary equipment was installed, the base unit was initialized with its coordinates and elevation and a static GPS session began. This static GPS data would later be used as a quality control check of the coordinates and elevation used.

During each daily session, a raw data file was created on the RTK base receiver. The monument name, Julian date, session number and antenna height was keyed into each receiver. The survey technician completed a GPS logsheet, while in the field, to document information about the survey as well as other pertinent monument details. Information on the log sheets included the monument stamping, actual survey start and stop times, the GPS antenna height measurements, weather conditions, satellite information as well as any problems that may be encountered during the survey. The log sheets also serve as a quality control check by the data processor when the data is downloaded from the GPS receiver, confirming that the monument names and antenna heights were keyed in correctly.

Upon completing the static GPS survey at the end of each day, GPS log sheets and GPS raw data files were sent back the Lafayette office via e-mail, then checked into the project file. All GPS raw data files were converted to RINEX format then submitted to the NGS Online Positioning User Service (OPUS) Program [1] for an independent solution. Comparisons were made between the OPUS results at each GPS base station control point and the final adjustment results. The final tabulated OPUS adjustment results can be located in this report.

It should be noted that monument “TE23-SM-01” was updated to the latest epoch with Static GPS observations being performed on October 10 and 11, 2015 in support of the East Timbalier Island Restoration Project (TE118). The following procedure was performed to update monument “TE23-SM-01” with the latest elevation and positions.

Static GPS Downloading, Processing & Adjustments

Upon completing the static GPS survey, GPS log sheets were checked and compared to the data files on the receivers. The raw GPS data was then downloaded into the project file created in Trimble Business Center (TBC) software. The IGS Precise Ephemeris was also downloaded from the NOAA/NGS Internet website for each day that GPS data was collected. All CORS[2] stations which were located nearest to or within the project area were also downloaded from the Center for Geoinfomatics (C4G) website and processed with the static GPS data.

After processing each day of data one at a time, a report was then generated in the TBC program and reviewed to determine satellite cycle slips so as to avoid baseline float solutions in the processed data. Each daily session was then re-processed independently using Precise Ephemeris and eliminating satellites determined to be unusable or too noisy.

Upon completing the processing phase, the data was loaded into the adjustment program and adjusted. All necessary adjustments were performed using the TBC Network Adjustment software.

The initial adjustment for the GPS network was minimally constrained to the published adjusted NAD83 (2011) Epoch 2010.00 and the published ellipsoid height at the antenna reference point (ARP) for CORS Station “ENG5”. A re-adjustment was performed and all outliners removed from the adjustment. A scale factor was

[1] The National Geodetic Survey operates the On-line Positioning User Service (OPUS) as a means to provide GPS users easier access to the National Spatial Reference System (NSRS). OPUS allows users to submit their GPS data files to NGS, where the data will be processed to determine a position using NGS computers and software. Each data file that is submitted will be processed with respect to 3 CORS sites.

[2] The National Geodetic Survey (NGS) coordinates two networks of continuously operating reference stations (CORS): the National CORS network and the Cooperative CORS network. Each CORS site provides Global Positioning System (GPS) carrier phase and code range measurements in support of 3-dimensional positioning activities throughout the United States and its territories. Surveyors, GIS/LIS professionals, engineers, scientists, and others can apply CORS data to position points at which GPS data have been collected. The CORS system enables positioning accuracies that approach a few centimeters relative to the National Spatial Reference System, both horizontally and vertically.

determined from the Statistics Summary and applied to the network and re-adjusted until the Chi-Square Test passed with a 95% confidence level.

The final fully constrained adjustment was performed by holding to the published values for specific CORS Station antenna reference points (ARP). Orthometric heights (elevations) were calculated using the Geoid12A model. Adjusted orthometric heights on the NGS benchmarks were compared with their published NAVD88 values as a quality control check. Additionally, all GPS files were submitted to the NGS Online Positioning User Service (OPUS) Program for an independent solution and comparisons made with the final adjustment results.

The published horizontal datum for OPUS is based on the Continuously Operating Reference Stations (CORS) which is NAD83 (2011) 2010.00 epoch. The vertical datum is North American Vertical Datum of 1988 (NAVD88) using Geoid 12A.

GPS and RTK Survey Equipment

The equipment used for the static GPS survey consisted of a Trimble© Navigation's dual-frequency R8 GNSS GPS receivers with an integrated GPS antenna and/or Trimble R7 GNSS with Zephyr Geodetic Antennas, also called the base station. A two-meter fixed height tripod was used to eliminate human error that could be introduced by miss-measurement of the GPS antenna heights. The GPS data was downloaded, processed and adjusted using Trimble© Business Center Software. The Geoid12A model was used to determine the geoid separation and applied to the ellipsoid heights for elevation determination as specified in the scope.

To perform the Real-time Kinematic (RTK) survey, a rover consisting of a Trimble© Navigation's dual-frequency R8 GNSS GPS receiver with an integrated GPS antenna and a Pacific Crest radio link was employed to transmit corrections to the rover from the base setup. A two-meter fixed height rod was used at the rover, except for shots taken at RSETS which required a modified adapter pole. The data was collected and stored on a Trimble© TSC3 datalogger and downloaded using Trimble© Business Center (TBC), version 3.2.



RTK Survey of Topographic Features

At the commencement of the project, the RTK base unit was installed at monument "TE23-SM-01". Once all necessary equipment is installed, the base unit will be initialized with its coordinates and elevation. A quality control shot was measured near the base monument with the roving unit to verify that the system was operational and delivering corrected positions. The base unit was then activated to begin additional static data collection while simultaneously transmitting DGPS corrections to the RTK rover. The crew then navigated to pre-plotted transects locations to survey the topographic features which consisted of measuring the 3-D position of each point and storing it on the collector. Tasks also included the surveying the top of existing Settlement Plates which were installed in 2012.

As an additional quality control check, static GPS was collected at the base station concurrent with the RTK survey so that post processing could be performed utilizing the NGS Online Positioning User Service (OPUS) Program as an independent check. Upon completion of the RTK survey, the data logger was downloaded and the information checked.

Bathymetric Survey of Water Bottoms

Bathymetry survey to locate water bottoms along the transect lines was performed by keying-in the transect end point coordinates to generate the pre-plot transect lines as well as existing pipeline locations from previous surveys into the onboard navigation program.

Back at the office, all the raw data was imported into Starfix.nav program, which includes the raw bathymetry data, the corrected tide file, and the CRP/transducer offset file. The tide files were applied to the sounder data to correct the water depths. A graphic file was generated so that the digital sounder data could be "despiked" to remove outliers. The final adjusted and edited file was exported in ascii format then imported into TBC to generate contours.

Sub-centimeter horizontal positioning was logged real-time using a Trimble AG132 GPS Receiver integrated with RTK for DGPS corrections from monument "TE23-SM-01". The 28-foot marine vessel was equipped with a Hydrotrac portable echo sounder with heave input from a TSS DMS-05 Motion Sensor for vertical motion corrections. Using the Hypack software, all single-beam data was digitally logged real-time, while Hydrotrac simultaneous charted the water depths on a paper scroll.

FINAL NOTE

Please be advised that the data which was collected during the survey of this project represents an epoch, a snapshot at the time that the survey was performed. Due to the effects of crustal motion, subsidence, upheaval, drought and other conditions which influence the physical position and stability of surface monuments, topographic features, and other structures within the Louisiana Coastal Zone, it is recommended that GPS monuments used for this project be re-observed an reprocessed on future surveys using the same reference control, if possible, for the purpose of updating the three dimensional position of the reference monuments.

The GPS/RTK Survey protocols performed in support of this project was in accordance with the Coastal Protection & Restoration Authority of Louisiana requirements as described in "*A Contractor's Guide to the Standards of Practice Required by Louisiana Department of Natural Resources, Coastal Restoration Division for Contractor's Performing GPS Surveys and Establishing GPS Derived Orthometric Heights Within the Louisiana Coastal Zone Primary GPS Network*" dated August 2013. All Static GPS was adjusted using Trimble Business Center software to determine the final reference control monument positions.

JOHN CHANCE LAND SURVEYS, INC.

Ricardo M. Johnson, PLS LA Reg. 4767
Sr. Project Manager of Government Services

SECTION C

Static GPS & OPUS Solutions

GPS Logsheets
OPUS Solutions
OPUS Average Comparisons to Published Benchmark
Static GPS Adjustment
Monument Datasheets

USE THIS FORM IF USING FIXED HEIGHT TRIPODS TO DOCUMENT STATIC SURVEYS ON BASE POINTS FOR ALL RTK SURVEYS

GPS LOG SHEET

Job No.	20140587	Date	1/13/2015	Operator	R. Mckeivier
Client	CPRA	Job Description	WEST BELLE PASS (TE-52)		
Location	LAFOURCHE			Proj. Mgr.	RICARDO JOHNSON

SESSION INFO

	4 Characters		3 Characters		1 Character
File Name	8994	**Julian Date**	013	**Session No.**	1

Long Name	TE23-SM-01		
Mon. Description	NGS FLOATING SLEEVE MONUMENT DATUM POINT SET ON 9/16 SS RODS DRIVEN TO 96' TO REFUSAL		
Rec. Base Type	TRIMBLE R8 MODEL 3	**Rec Serial #**	5037448994
Base Ant Type		**Base Ant Ser #**	
Rover Ant Type	TRIMBLE R8 MODEL 3	**Rover Ant Ser #**	5051458175

Antenna Height Measurement is **TRUE VERTICAL** to the Bottom of Antenna Mount if Using Fixed Hgt Tripod

Fixed Hgt 2 Meter Tripod	2.000	**Mtrs**
Tripod Number	RP 45	

Actual Start Time	7:35	Actual Stop Time	12:53	Session Time (Min 2:01 Hr)	5:18

BASE STATION INFORMATION

	NAD 83 or NAD 27		***Example**: LA South Zone or TX South Central Zone*
DATUM	NAD 83	**ZONE**	**LA SOUTH ZONE**
Northing/Lat	224296.37		
Easting/Long.	3645688.81		
Elevation	7.30		

Coordinate Origin-*Where did you get your positions?*

OFFICE

Note any power problems, obstructions, weather issues, etc.

ALL WHITE BOXES MUST BE FILLED IN WITH INFORMATION. A MINIMUM OBSERVATION OF 2 HOURS IS REQUIRED TO DETERMINE THE 3-D POSITION OF AN UNKNOWN POINT USING NGS-OPUS

USE BACK OF THIS SHEET TO MAKE STATION SKETCH, REFERENCE TIES & DESCRIPTION

Johnson, Ricardo

From: opus <opus@ngs.noaa.gov>
Sent: Wednesday, February 25, 2015 4:41 PM
To: Johnson, Ricardo
Subject: OPUS solution : 89940131.15o OP1424903968752

FILE: 89940131.15o OP1424903968752

NGS OPUS SOLUTION REPORT
==========

All computed coordinate accuracies are listed as peak-to-peak values.
For additional information: http://www.ngs.noaa.gov/OPUS/about.jsp#accuracy

USER: rjohnson@fugro.com DATE: February 25, 2015
RINEX FILE: 8994013n.15o TIME: 22:41:01 UTC

SOFTWARE: page5 1209.04 master91.pl 022814 START: 2015/01/13 13:36:00
EPHEMERIS: igs18272.eph [precise] STOP: 2015/01/13 18:53:00
NAV FILE: brdc0130.15n OBS USED: 11851 / 12327 : 96%
ANT NAME: TRMR8_GNSS3 NONE # FIXED AMB: 82 / 86 : 95%
ARP HEIGHT: 2.000 OVERALL RMS: 0.013(m)

REF FRAME: NAD_83(2011)(EPOCH:2010.0000) IGS08 (EPOCH:2015.0347)

X:	-18573.482(m)	0.004(m)	-18574.258(m)	0.004(m)
Y:	-5576773.234(m)	0.005(m)	-5576771.725(m)	0.005(m)
Z:	3084717.467(m)	0.011(m)	3084717.280(m)	0.011(m)

LAT:	29 6 42.28472	0.012(m)	29 6 42.30322	0.012(m)
E LON:	269 48 33.03617	0.004(m)	269 48 33.00728	0.004(m)
W LON:	90 11 26.96383	0.004(m)	90 11 26.99272	0.004(m)
EL HGT:	-21.580(m)	0.003(m)	-22.987(m)	0.003(m)
ORTHO HGT:	2.213(m)	0.013(m)	[NAVD88 (Computed using GEOID12A)]	

	UTM COORDINATES (UTM (Zone 15))	STATE PLANE COORDINATES (SPC (1702 LA S))
Northing (Y) [meters]	3223628.359	68365.660
Easting (X) [meters]	773376.912	1111208.167
Convergence [degrees]	1.36755457	0.57126952
Point Scale	1.00052233	1.00004518
Combined Factor	1.00052572	1.00004857

US NATIONAL GRID DESIGNATOR: 15RYN7337623628(NAD 83)

BASE STATIONS USED

PID	DESIGNATION	LATITUDE	LONGITUDE	DISTANCE(m)
DF5771	LMCN LUMCON CORS ARP	N291517.904	W0903940.652	48436.0
DG5315	HOUM HOUMA CORS ARP	N293532.109	W0904324.988	74251.2
DK3577	ENG5 ENGLISH TURN 5 CORS ARP	N295244.246	W0895630.197	88403.8

NEAREST NGS PUBLISHED CONTROL POINT

DJ9376	TE23 SM 01	N290642.285	W0901126.964	0.0

This position and the above vector components were computed without any knowledge by the National Geodetic Survey regarding the equipment or field operating procedures used.

USE THIS FORM IF USING FIXED HEIGHT TRIPODS TO DOCUMENT STATIC SURVEYS ON BASE POINTS FOR ALL RTK SURVEYS

GPS LOG SHEET

Job No.	20140587	Date	1/14/2015	Operator	R. Mckeivier
Client	CPRA	Job Description	WEST BELLE PASS (TE-52)		
Location	LAFOURCHE			Proj. Mgr.	RICARDO JOHNSON

SESSION INFO

	4 Characters		3 Characters		1 Character
File Name	8994	**Julian Date**	014	**Session No.**	1

Long Name	TE23-SM-01		
Mon. Description	NGS FLOATING SLEEVE MONUMENT DATUM POINT SET ON 9/16 SS RODS DRIVEN TO 96' TO REFUSAL		
Rec. Base Type	TRIMBLE R8 MODEL 3	**Rec Serial #**	5037448994
Base Ant Type		**Base Ant Ser #**	
Rover Ant Type	TRIMBLE R8 MODEL 3	**Rover Ant Ser #**	5051458175

Antenna Height Measurement is **TRUE VERTICAL** to the Bottom of Antenna Mount if Using Fixed Hgt Tripod

Fixed Hgt 2 Meter Tripod: 2.000 **Mtrs**

Tripod Number: RP 45

Actual Start Time	Actual Stop Time	Session Time (Min 2:01 Hr)
7:43	14:31	6:48

BASE STATION INFORMATION

	NAD 83 or NAD 27		***Example**: LA South Zone or TX South Central Zone*
DATUM	NAD 83	**ZONE**	**LA SOUTH ZONE**
Northing/Lat	224296.37		
Easting/Long.	3645688.81		
Elevation	7.30		

Coordinate Origin-*Where did you get your positions?*

OFFICE

Note any power problems, obstructions, weather issues, etc.

ALL WHITE BOXES MUST BE FILLED IN WITH INFORMATION. A MINIMUM OBSERVATION OF 2 HOURS IS REQUIRED TO DETERMINE THE 3-D POSITION OF AN UNKNOWN POINT USING NGS-OPUS

USE BACK OF THIS SHEET TO MAKE STATION SKETCH, REFERENCE TIES & DESCRIPTION

Johnson, Ricardo

From: opus <opus@ngs.noaa.gov>
Sent: Wednesday, February 25, 2015 4:41 PM
To: Johnson, Ricardo
Subject: OPUS solution : 89940140.15o OP1424903968752

FILE: 89940140.15o OP1424903968752

NGS OPUS SOLUTION REPORT
==========

All computed coordinate accuracies are listed as peak-to-peak values.
For additional information: http://www.ngs.noaa.gov/OPUS/about.jsp#accuracy

USER: rjohnson@fugro.com DATE: February 25, 2015
RINEX FILE: 8994014n.15o TIME: 22:41:02 UTC

SOFTWARE: page5 1209.04 master51.pl 022814 START: 2015/01/14 13:43:00
EPHEMERIS: igs18273.eph [precise] STOP: 2015/01/14 20:31:00
NAV FILE: brdc0140.15n OBS USED: 15908 / 16635 : 96%
ANT NAME: TRMR8_GNSS3 NONE # FIXED AMB: 92 / 98 : 94%
ARP HEIGHT: 2.000 OVERALL RMS: 0.015(m)

REF FRAME: NAD_83(2011)(EPOCH:2010.0000) IGS08 (EPOCH:2015.0376)

X:	-18573.478(m)	0.006(m)	-18574.254(m)	0.006(m)
Y:	-5576773.239(m)	0.008(m)	-5576771.730(m)	0.008(m)
Z:	3084717.471(m)	0.007(m)	3084717.284(m)	0.007(m)

LAT:	29 6 42.28475	0.008(m)	29 6 42.30325	0.008(m)
E LON:	269 48 33.03632	0.006(m)	269 48 33.00743	0.006(m)
W LON:	90 11 26.96368	0.006(m)	90 11 26.99257	0.006(m)
EL HGT:	-21.574(m)	0.007(m)	-22.981(m)	0.007(m)
ORTHO HGT:	2.219(m)	0.017(m)	[NAVD88 (Computed using GEOID12A)]	

	UTM COORDINATES (UTM (Zone 15))	STATE PLANE COORDINATES (SPC (1702 LA S))
Northing (Y) [meters]	3223628.360	68365.661
Easting (X) [meters]	773376.916	1111208.171
Convergence [degrees]	1.36755459	0.57126954
Point Scale	1.00052233	1.00004518
Combined Factor	1.00052572	1.00004857

US NATIONAL GRID DESIGNATOR: 15RYN7337623628(NAD 83)

BASE STATIONS USED

PID	DESIGNATION	LATITUDE	LONGITUDE	DISTANCE(m)
DK3577	ENG5 ENGLISH TURN 5 CORS ARP	N295244.246	W0895630.197	88403.8
DH7121	GRIS GRAND ISLE CORS ARP	N291555.883	W0895726.262	28397.2
DG5315	HOUM HOUMA CORS ARP	N293532.109	W0904324.988	74251.2

NEAREST NGS PUBLISHED CONTROL POINT

DJ9376	TE23 SM 01	N290642.285	W0901126.964	0.0

This position and the above vector components were computed without any knowledge by the National Geodetic Survey regarding the equipment or field operating procedures used.

USE THIS FORM IF USING FIXED HEIGHT TRIPODS TO DOCUMENT STATIC SURVEYS ON BASE POINTS FOR ALL RTK SURVEYS

GPS LOG SHEET

Job No.	20140587	Date	1/19/2015	Operator	R. Mckeivier
Client	CPRA	Job Description	WEST BELLE PASS RESTORATION		
Location	LAFOURCHE			Proj. Mgr.	RICARDO JOHNSON

SESSION INFO

	4 Characters		3 Characters		1 Character
File Name	8175	**Julian Date**	019	**Session No.**	0

Long Name	TE23-SM-01		
Mon. Description	NGS FLOATING SLEEVE MONUMENT DATUM POINT SET ON 9/16 SS RODS DRIVEN TO 96' TO REFUSAL		
Rec. Base Type	TRIMBLE R8 MODEL 3	**Rec Serial #**	5051458175
Base Ant Type		**Base Ant Ser #**	
Rover Ant Type	TRIMBLE R8 MODEL 3	**Rover Ant Ser #**	5037448994

Antenna Height Measurement is **TRUE VERTICAL** to the Bottom of Antenna Mount if Using Fixed Hgt Tripod

Fixed Hgt 2 Meter Tripod	2.000	**Mtrs**
Tripod Number	RP 45	

Actual Start Time	10:25	Actual Stop Time	16:54	Session Time (Min 2:01 Hr)	6:29

BASE STATION INFORMATION

	NAD 83 or NAD 27		***Example**: LA South Zone or TX South Central Zone*
DATUM	NAD 83	**ZONE**	**LA SOUTH ZONE**
Northing/Lat	224296.37		
Easting/Long.	3645688.81		
Elevation	7.30		

Coordinate Origin-*Where did you get your positions?*

OFFICE

Note any power problems, obstructions, weather issues, etc.

ALL WHITE BOXES MUST BE FILLED IN WITH INFORMATION. A MINIMUM OBSERVATION OF 2 HOURS IS REQUIRED TO DETERMINE THE 3-D POSITION OF AN UNKNOWN POINT USING NGS-OPUS

USE BACK OF THIS SHEET TO MAKE STATION SKETCH, REFERENCE TIES & DESCRIPTION

Johnson, Ricardo

From: opus <opus@ngs.noaa.gov>
Sent: Wednesday, February 25, 2015 4:41 PM
To: Johnson, Ricardo
Subject: OPUS solution : 81750190.15o OP1424903968752

FILE: 81750190.15o OP1424903968752

NGS OPUS SOLUTION REPORT
==========

All computed coordinate accuracies are listed as peak-to-peak values.
For additional information: http://www.ngs.noaa.gov/OPUS/about.jsp#accuracy

USER: rjohnson@fugro.com DATE: February 25, 2015
RINEX FILE: 8175019q.15o TIME: 22:41:03 UTC

SOFTWARE: page5 1209.04 master92.pl 022814 START: 2015/01/19 16:25:00
EPHEMERIS: igs18281.eph [precise] STOP: 2015/01/19 22:54:00
NAV FILE: brdc0190.15n OBS USED: 16820 / 17628 : 95%
ANT NAME: TRMR8_GNSS3 NONE # FIXED AMB: 81 / 82 : 99%
ARP HEIGHT: 2.000 OVERALL RMS: 0.015(m)

REF FRAME: NAD_83(2011)(EPOCH:2010.0000) IGS08 (EPOCH:2015.0516)

X:	-18573.481(m)	0.004(m)	-18574.257(m)	0.004(m)
Y:	-5576773.231(m)	0.005(m)	-5576771.722(m)	0.005(m)
Z:	3084717.471(m)	0.003(m)	3084717.284(m)	0.003(m)

LAT:	29 6 42.28488	0.001(m)	29 6 42.30338	0.001(m)
E LON:	269 48 33.03621	0.004(m)	269 48 33.00732	0.004(m)
W LON:	90 11 26.96379	0.004(m)	90 11 26.99268	0.004(m)
EL HGT:	-21.581(m)	0.006(m)	-22.988(m)	0.006(m)
ORTHO HGT:	2.212(m)	0.015(m) [NAVD88 (Computed using GEOID12A)]		

	UTM COORDINATES (UTM (Zone 15))	STATE PLANE COORDINATES (SPC (1702 LA S))
Northing (Y) [meters]	3223628.364	68365.665
Easting (X) [meters]	773376.913	1111208.168
Convergence [degrees]	1.36755458	0.57126953
Point Scale	1.00052233	1.00004518
Combined Factor	1.00052572	1.00004857

US NATIONAL GRID DESIGNATOR: 15RYN7337623628(NAD 83)

BASE STATIONS USED

PID	DESIGNATION	LATITUDE	LONGITUDE	DISTANCE(m)
DE8091	BVHS BOOTHVILLE CORS ARP	N292012.489	W0892423.010	80243.4
DF5771	LMCN LUMCON CORS ARP	N291517.904	W0903940.652	48436.0
DG5315	HOUM HOUMA CORS ARP	N293532.109	W0904324.988	74251.2

NEAREST NGS PUBLISHED CONTROL POINT

DJ9376	TE23 SM 01	N290642.285	W0901126.964	0.0

This position and the above vector components were computed without any knowledge by the National Geodetic Survey regarding the equipment or field operating procedures used.

USE THIS FORM IF USING FIXED HEIGHT TRIPODS TO DOCUMENT STATIC SURVEYS ON BASE POINTS FOR ALL RTK SURVEYS

GPS LOG SHEET

Job No.	20140587	Date	1/20/2015	Operator	R. Mckeivier
Client	CPRA	Job Description	WEST BELLE PASS RESTORATION		
Location	LAFOURCHE			Proj. Mgr.	RICARDO JOHNSON

SESSION INFO

	4 Characters		3 Characters		1 Character
File Name	8175	**Julian Date**	020	**Session No.**	0

Long Name	TE23-SM-01		
Mon. Description	DATUM POINT SET ON 9/16 STAINLESS RODS DRIVEN TO 96' TO REFUSAL SET IN SAND FILL		
Rec. Base Type	TRIMBLE R8 MODEL 3	**Rec Serial #**	5051458175
Base Ant Type		**Base Ant Ser #**	
Rover Ant Type	TRIMBLE R8 MODEL 3	**Rover Ant Ser #**	5037448994

Antenna Height Measurement is **TRUE VERTICAL** to the Bottom of Antenna Mount if Using Fixed Hgt Tripod

Fixed Hgt 2 Meter Tripod	2 meters	**Mtrs or Ft**
Tripod Number	RP 45	

Actual Start Time	7:34	Actual Stop Time	11:22	Session Time (Min 2:01 Hr)	3:48

BASE STATION INFORMATION

	NAD 83 or NAD 27		***Example**: LA South Zone or TX South Central Zone*
DATUM	NAD 83	**ZONE**	**LA SOUTH ZONE**
Northing/Lat	224296.37		
Easting/Long.	3645688.81	**Coordinate Origin**-*Where did you get your positions?*	OFFICE
Elevation	7.30		

Note any power problems, obstructions, weather issues, etc.

ALL WHITE BOXES MUST BE FILLED IN WITH INFORMATION. A MINIMUM OBSERVATION OF 2 HOURS IS REQUIRED TO DETERMINE THE 3-D POSITION OF AN UNKNOWN POINT USING NGS-OPUS

USE BACK OF THIS SHEET TO MAKE STATION SKETCH, REFERENCE TIES & DESCRIPTION

Johnson, Ricardo

From: opus <opus@ngs.noaa.gov>
Sent: Wednesday, February 25, 2015 4:41 PM
To: Johnson, Ricardo
Subject: OPUS solution : 81750200.15o OP1424903968752

FILE: 81750200.15o OP1424903968752

NGS OPUS SOLUTION REPORT
==========

All computed coordinate accuracies are listed as peak-to-peak values.
For additional information: http://www.ngs.noaa.gov/OPUS/about.jsp#accuracy

USER: rjohnson@fugro.com DATE: February 25, 2015
RINEX FILE: 8175020n.15o TIME: 22:41:00 UTC

SOFTWARE: page5 1209.04 master52.pl 022814 START: 2015/01/20 13:35:00
EPHEMERIS: igs18282.eph [precise] STOP: 2015/01/20 17:22:00
NAV FILE: brdc0200.15n OBS USED: 8732 / 8926 : 98%
ANT NAME: TRMR8_GNSS3 NONE # FIXED AMB: 46 / 46 : 100%
ARP HEIGHT: 2.000 OVERALL RMS: 0.015(m)

REF FRAME: NAD_83(2011)(EPOCH:2010.0000) IGS08 (EPOCH:2015.0538)

X:	-18573.487(m)	0.004(m)	-18574.263(m)	0.004(m)
Y:	-5576773.243(m)	0.005(m)	-5576771.734(m)	0.005(m)
Z:	3084717.474(m)	0.008(m)	3084717.287(m)	0.008(m)

LAT:	29 6 42.28478	0.006(m)	29 6 42.30327	0.006(m)
E LON:	269 48 33.03599	0.004(m)	269 48 33.00710	0.004(m)
W LON:	90 11 26.96401	0.004(m)	90 11 26.99290	0.004(m)
EL HGT:	-21.569(m)	0.008(m)	-22.976(m)	0.008(m)
ORTHO HGT:	2.224(m)	0.017(m)	[NAVD88 (Computed using GEOID12A)]	

	UTM COORDINATES (UTM (Zone 15))	STATE PLANE COORDINATES (SPC (1702 LA S))
Northing (Y) [meters]	3223628.361	68365.662
Easting (X) [meters]	773376.907	1111208.162
Convergence [degrees]	1.36755455	0.57126950
Point Scale	1.00052233	1.00004518
Combined Factor	1.00052572	1.00004857

US NATIONAL GRID DESIGNATOR: 15RYN7337623628(NAD 83)

BASE STATIONS USED

PID	DESIGNATION	LATITUDE	LONGITUDE	DISTANCE(m)
DG5315	HOUM HOUMA CORS ARP	N293532.109	W0904324.988	74251.2
DH7121	GRIS GRAND ISLE CORS ARP	N291555.883	W0895726.262	28397.2
DE8091	BVHS BOOTHVILLE CORS ARP	N292012.489	W0892423.010	80243.4

NEAREST NGS PUBLISHED CONTROL POINT

DJ9376	TE23 SM 01	N290642.285	W0901126.964	0.0

This position and the above vector components were computed without any knowledge by the National Geodetic Survey regarding the equipment or field operating procedures used.

USE THIS FORM IF USING FIXED HEIGHT TRIPODS TO DOCUMENT STATIC SURVEYS ON BASE POINTS FOR ALL RTK SURVEYS

GPS LOG SHEET

Job No.	20140587	Date	1/20/2015	Operator	R. Mckeivier
Client	CPRA	Job Description	WEST BELLE PASS RESTORATION		
Location	LAFOURCHE			Proj. Mgr.	RICARDO JOHNSON

SESSION INFO

	4 Characters		3 Characters		1 Character
File Name	8175	**Julian Date**	020	**Session No.**	4

Long Name	TE23-SM-01		
Mon. Description	DATUM POINT SET ON 9/16 STAINLESS RODS DRIVEN TO 96' TO REFUSAL SET IN SAND FILL		
Rec. Base Type	TRIMBLE R8 MODEL 3	**Rec Serial #**	5051458175
Base Ant Type		**Base Ant Ser #**	
Rover Ant Type	TRIMBLE R8 MODEL 3	**Rover Ant Ser #**	5037448994

Antenna Height Measurement is **TRUE VERTICAL** to the Bottom of Antenna Mount if Using Fixed Hgt Tripod

Fixed Hgt 2 Meter Tripod	2.000	**Mtrs**
Tripod Number	RP 45	

Actual Start Time	12:01	Actual Stop Time	16:05	Session Time (Min 2:01 Hr)	4:04

BASE STATION INFORMATION

	NAD 83 or NAD 27		***Example**: LA South Zone or TX South Central Zone*
DATUM	NAD 83	**ZONE**	**LA SOUTH ZONE**
Northing/Lat	224296.37		
Easting/Long.	3645688.81		
Elevation	7.30		

Coordinate Origin-*Where did you get your positions?*

OFFICE

Note any power problems, obstructions, weather issues, etc.

ALL WHITE BOXES MUST BE FILLED IN WITH INFORMATION. A MINIMUM OBSERVATION OF 2 HOURS IS REQUIRED TO DETERMINE THE 3-D POSITION OF AN UNKNOWN POINT USING NGS-OPUS

USE BACK OF THIS SHEET TO MAKE STATION SKETCH, REFERENCE TIES & DESCRIPTION

Johnson, Ricardo

From: opus <opus@ngs.noaa.gov>
Sent: Wednesday, February 25, 2015 4:41 PM
To: Johnson, Ricardo
Subject: OPUS solution : 81750204.15o OP1424903968752

FILE: 81750204.15o OP1424903968752

NGS OPUS SOLUTION REPORT
==========

All computed coordinate accuracies are listed as peak-to-peak values.
For additional information: http://www.ngs.noaa.gov/OPUS/about.jsp#accuracy

USER: rjohnson@fugro.com DATE: February 25, 2015
RINEX FILE: 8175020s.15o TIME: 22:41:06 UTC

SOFTWARE: page5 1209.04 master50.pl 022814 START: 2015/01/20 18:01:00
EPHEMERIS: igs18282.eph [precise] STOP: 2015/01/20 22:05:00
NAV FILE: brdc0200.15n OBS USED: 11155 / 11543 : 97%
ANT NAME: TRMR8_GNSS3 NONE # FIXED AMB: 59 / 61 : 97%
ARP HEIGHT: 2.000 OVERALL RMS: 0.015(m)

REF FRAME: NAD_83(2011)(EPOCH:2010.0000) IGS08 (EPOCH:2015.0544)

X:	-18573.484(m)	0.005(m)	-18574.260(m)	0.005(m)
Y:	-5576773.237(m)	0.013(m)	-5576771.728(m)	0.013(m)
Z:	3084717.480(m)	0.003(m)	3084717.293(m)	0.003(m)

LAT:	29 6 42.28504	0.006(m)	29 6 42.30354	0.006(m)
E LON:	269 48 33.03610	0.005(m)	269 48 33.00721	0.005(m)
W LON:	90 11 26.96390	0.005(m)	90 11 26.99279	0.005(m)
EL HGT:	-21.571(m)	0.012(m)	-22.978(m)	0.012(m)
ORTHO HGT:	2.222(m)	0.024(m)	[NAVD88 (Computed using GEOID12A)]	

	UTM COORDINATES (UTM (Zone 15))	STATE PLANE COORDINATES (SPC (1702 LA S))
Northing (Y) [meters]	3223628.369	68365.670
Easting (X) [meters]	773376.910	1111208.165
Convergence [degrees]	1.36755457	0.57126951
Point Scale	1.00052233	1.00004518
Combined Factor	1.00052572	1.00004857

US NATIONAL GRID DESIGNATOR: 15RYN7337623628(NAD 83)

BASE STATIONS USED

PID	DESIGNATION	LATITUDE	LONGITUDE	DISTANCE(m)
DE8091	BVHS BOOTHVILLE CORS ARP	N292012.489	W0892423.010	80243.4
DF5771	LMCN LUMCON CORS ARP	N291517.904	W0903940.652	48436.0
DG5315	HOUM HOUMA CORS ARP	N293532.109	W0904324.988	74251.2

NEAREST NGS PUBLISHED CONTROL POINT

DJ9376	TE23 SM 01	N290642.285	W0901126.964	0.0

This position and the above vector components were computed without any knowledge by the National Geodetic Survey regarding the equipment or field operating procedures used.

USE THIS FORM IF USING FIXED HEIGHT TRIPODS TO DOCUMENT STATIC SURVEYS ON BASE POINTS FOR ALL RTK SURVEYS

GPS LOG SHEET

Job No.	20140587	Date	1/21/2015	Operator	R. Mckeivier
Client	CPRA	Job Description	WEST BELLE PASS RESTORATION		
Location	LAFOURCHE			Proj. Mgr.	RICARDO JOHNSON

SESSION INFO

	4 Characters		3 Characters		1 Character
File Name	8175	**Julian Date**	021	**Session No.**	0

Long Name	TE23-SM-01		
Mon. Description	NGS FLOATING SLEEVE MONUMENT DATUM POINT SET ON 9/16 SS RODS DRIVEN TO 96' TO REFUSAL		
Rec. Base Type	TRIMBLE R8 MODEL 3	**Rec Serial #**	5051458175
Base Ant Type		**Base Ant Ser #**	
Rover Ant Type	TRIMBLE R8 MODEL 3	**Rover Ant Ser #**	5037448994

Antenna Height Measurement is **TRUE VERTICAL** to the Bottom of Antenna Mount if Using Fixed Hgt Tripod

Fixed Hgt 2 Meter Tripod	2.000	**Mtrs**
Tripod Number	RP 45	

Actual Start Time	7:30	Actual Stop Time	16:26	Session Time (Min 2:01 Hr)	8:56

BASE STATION INFORMATION

	NAD 83 or NAD 27		***Example**: LA South Zone or TX South Central Zone*
DATUM	NAD 83	**ZONE**	**LA SOUTH ZONE**
Northing/Lat	224296.37		
Easting/Long.	3645688.81	**Coordinate Origin**-*Where did you get your positions?*	OFFICE
Elevation	7.30		

Note any power problems, obstructions, weather issues, etc.

ALL WHITE BOXES MUST BE FILLED IN WITH INFORMATION. A MINIMUM OBSERVATION OF 2 HOURS IS REQUIRED TO DETERMINE THE 3-D POSITION OF AN UNKNOWN POINT USING NGS-OPUS

USE BACK OF THIS SHEET TO MAKE STATION SKETCH, REFERENCE TIES & DESCRIPTION

Johnson, Ricardo

From: opus <opus@ngs.noaa.gov>
Sent: Wednesday, February 25, 2015 4:41 PM
To: Johnson, Ricardo
Subject: OPUS solution : 81750210.15o OP1424903968752

FILE: 81750210.15o OP1424903968752

NGS OPUS SOLUTION REPORT
==========

All computed coordinate accuracies are listed as peak-to-peak values.
For additional information: http://www.ngs.noaa.gov/OPUS/about.jsp#accuracy

USER: rjohnson@fugro.com DATE: February 25, 2015
RINEX FILE: 8175021n.15o TIME: 22:41:09 UTC

SOFTWARE: page5 1209.04 master53.pl 022814 START: 2015/01/21 13:30:00
EPHEMERIS: igs18283.eph [precise] STOP: 2015/01/21 22:26:00
NAV FILE: brdc0210.15n OBS USED: 22693 / 23149 : 98%
ANT NAME: TRMR8_GNSS3 NONE # FIXED AMB: 94 / 94 : 100%
ARP HEIGHT: 2.000 OVERALL RMS: 0.016(m)

REF FRAME: NAD_83(2011)(EPOCH:2010.0000) IGS08 (EPOCH:2015.0569)

X:	-18573.475(m)	0.006(m)	-18574.251(m)	0.006(m)
Y:	-5576773.234(m)	0.010(m)	-5576771.725(m)	0.010(m)
Z:	3084717.460(m)	0.004(m)	3084717.273(m)	0.004(m)

LAT:	29 6 42.28452	0.004(m)	29 6 42.30302	0.004(m)
E LON:	269 48 33.03643	0.006(m)	269 48 33.00754	0.006(m)
W LON:	90 11 26.96357	0.006(m)	90 11 26.99246	0.006(m)
EL HGT:	-21.584(m)	0.011(m)	-22.991(m)	0.011(m)
ORTHO HGT:	2.209(m)	0.021(m)	[NAVD88 (Computed using GEOID12A)]	

	UTM COORDINATES (UTM (Zone 15))	STATE PLANE COORDINATES (SPC (1702 LA S))
Northing (Y) [meters]	3223628.353	68365.654
Easting (X) [meters]	773376.919	1111208.174
Convergence [degrees]	1.36755461	0.57126956
Point Scale	1.00052233	1.00004518
Combined Factor	1.00052572	1.00004857

US NATIONAL GRID DESIGNATOR: 15RYN7337623628(NAD 83)

BASE STATIONS USED

PID	DESIGNATION	LATITUDE	LONGITUDE	DISTANCE(m)
DF5771	LMCN LUMCON CORS ARP	N291517.904	W0903940.652	48436.0
DE8091	BVHS BOOTHVILLE CORS ARP	N292012.489	W0892423.010	80243.4
DG5315	HOUM HOUMA CORS ARP	N293532.109	W0904324.988	74251.2

NEAREST NGS PUBLISHED CONTROL POINT

DJ9376	TE23 SM 01	N290642.285	W0901126.964	0.0

This position and the above vector components were computed without any knowledge by the National Geodetic Survey regarding the equipment or field operating procedures used.

USE THIS FORM IF USING FIXED HEIGHT TRIPODS TO DOCUMENT STATIC SURVEYS ON BASE POINTS FOR ALL RTK SURVEYS

GPS LOG SHEET

Job No.	20140587	Date	1/22/2015	Operator	R. Mckeivier
Client	CPRA	Job Description	WEST BELLE PASS RESTORATION		
Location	LAFOURCHE			Proj. Mgr.	RICARDO JOHNSON

SESSION INFO

	4 Characters		3 Characters		1 Character
File Name	8175	**Julian Date**	022	**Session No.**	0

Long Name	TE23-SM-01		
Mon. Description	NGS FLOATING SLEEVE MONUMENT DATUM POINT SET ON 9/16 SS RODS DRIVEN TO 96' TO REFUSAL		
Rec. Base Type	TRIMBLE R8 MODEL 3	**Rec Serial #**	5051458175
Base Ant Type		**Base Ant Ser #**	
Rover Ant Type	TRIMBLE R8 MODEL 3	**Rover Ant Ser #**	5037448994

Antenna Height Measurement is **TRUE VERTICAL** to the Bottom of Antenna Mount if Using Fixed Hgt Tripod

Fixed Hgt 2 Meter Tripod	2.000	**Mtrs**
Tripod Number	RP 45	

Actual Start Time	7:45	Actual Stop Time	15:23	Session Time (Min 2:01 Hr)	7:38

BASE STATION INFORMATION

	NAD 83 or NAD 27		***Example**: LA South Zone or TX South Central Zone*
DATUM	NAD 83	**ZONE**	**LA SOUTH ZONE**
Northing/Lat	224296.37		
Easting/Long.	3645688.81		
Elevation	7.30		

Coordinate Origin-*Where did you get your positions?*

OFFICE

Note any power problems, obstructions, weather issues, etc.

ALL WHITE BOXES MUST BE FILLED IN WITH INFORMATION. A MINIMUM OBSERVATION OF 2 HOURS IS REQUIRED TO DETERMINE THE 3-D POSITION OF AN UNKNOWN POINT USING NGS-OPUS

USE BACK OF THIS SHEET TO MAKE STATION SKETCH, REFERENCE TIES & DESCRIPTION

Johnson, Ricardo

From: opus <opus@ngs.noaa.gov>
Sent: Wednesday, February 25, 2015 4:41 PM
To: Johnson, Ricardo
Subject: OPUS solution : 81750220.15o OP1424903968752

FILE: 81750220.15o OP1424903968752

NGS OPUS SOLUTION REPORT
==========

All computed coordinate accuracies are listed as peak-to-peak values.
For additional information: http://www.ngs.noaa.gov/OPUS/about.jsp#accuracy

USER: rjohnson@fugro.com DATE: February 25, 2015
RINEX FILE: 8175022n.15o TIME: 22:41:05 UTC

SOFTWARE: page5 1209.04 master90.pl 022814 START: 2015/01/22 13:45:00
EPHEMERIS: igs18284.eph [precise] STOP: 2015/01/22 21:23:00
NAV FILE: brdc0220.15n OBS USED: 18873 / 19630 : 96%
ANT NAME: TRMR8_GNSS3 NONE # FIXED AMB: 101 / 105 : 96%
ARP HEIGHT: 2.000 OVERALL RMS: 0.016(m)

REF FRAME: NAD_83(2011)(EPOCH:2010.0000) IGS08 (EPOCH:2015.0596)

X:	-18573.479(m)	0.002(m)	-18574.255(m)	0.002(m)
Y:	-5576773.238(m)	0.003(m)	-5576771.729(m)	0.003(m)
Z:	3084717.458(m)	0.007(m)	3084717.271(m)	0.007(m)

LAT:	29 6 42.28440	0.007(m)	29 6 42.30290	0.007(m)
E LON:	269 48 33.03628	0.002(m)	269 48 33.00739	0.002(m)
W LON:	90 11 26.96372	0.002(m)	90 11 26.99261	0.002(m)
EL HGT:	-21.581(m)	0.003(m)	-22.988(m)	0.003(m)
ORTHO HGT:	2.212(m)	0.012(m)	[NAVD88 (Computed using GEOID12A)]	

	UTM COORDINATES (UTM (Zone 15))	STATE PLANE COORDINATES (SPC (1702 LA S))
Northing (Y) [meters]	3223628.350	68365.650
Easting (X) [meters]	773376.915	1111208.170
Convergence [degrees]	1.36755458	0.57126954
Point Scale	1.00052233	1.00004518
Combined Factor	1.00052572	1.00004857

US NATIONAL GRID DESIGNATOR: 15RYN7337623628(NAD 83)

BASE STATIONS USED

PID	DESIGNATION	LATITUDE	LONGITUDE	DISTANCE(m)
DF5771	LMCN LUMCON CORS ARP	N291517.904	W0903940.652	48436.0
DH7121	GRIS GRAND ISLE CORS ARP	N291555.883	W0895726.262	28397.2
DK3577	ENG5 ENGLISH TURN 5 CORS ARP	N295244.246	W0895630.197	88403.8

NEAREST NGS PUBLISHED CONTROL POINT

DJ9376	TE23 SM 01	N290642.285	W0901126.964	0.0

This position and the above vector components were computed without any knowledge by the National Geodetic Survey regarding the equipment or field operating procedures used.

TE-52 WEST BELLE PASS BARRIER HEADLAND RESTORATION PROJECT

Average of OPUS Solutions at Monument TE23-SM-01 (Point 200)

Horizontal Datum: NAD83 (2011) Epoch 2010.00 LA South Zone (1702) - Vertical Datum: NAVD88 (GEOID12A)

GPS File	Latitude	Longitude	Northing Mtrs	Easting Mtrs	Northing Ft	Easting Ft	Ellipsoid Hgt Mtrs	Elevation Mtrs	Elevation Hgt Ft
89940131	29 6 42.28472	90 11 26.96383	68,365.660	1,111,208.167	224,296.34	3,645,688.79	-21.580	2.213	7.26
89940140	29 6 42.28475	90 11 26.96368	68,365.661	1,111,208.171	224,296.34	3,645,688.80	-21.574	2.219	7.28
81750190	29 6 42.28488	90 11 26.96379	68,365.665	1,111,208.168	224,296.35	3,645,688.79	-21.581	2.212	7.26
81750200	29 6 42.28478	90 11 26.96401	68,365.662	1,111,208.162	224,296.34	3,645,688.77	-21.569	2.224	7.30
81750204	29 6 42.28504	90 11 26.96390	68,365.670	1,111,208.165	224,296.37	3,645,688.78	-21.571	2.222	7.29
81750210	29 6 42.28452	90 11 26.96357	68,365.654	1,111,208.174	224,296.32	3,645,688.81	-21.584	2.209	7.25
81750220	29 6 42.28440	90 11 26.96372	68,365.650	1,111,208.170	224,296.30	3,645,688.80	-21.581	2.212	7.26
OPUS Average	**29 06 42.28473**	**90 11 26.96379**	**68,365.660**	**1,111,208.168**	**224,296.34**	**3,645,688.79**	**-21.577**	**2.216**	**7.27**
GPS ADJUSTED	**29°06'42.28465"**	**90°11'26.96408"**	**68,365.658**	**1,111,208.161**	**224,296.33**	**3,645,688.77**	**-21.567**	**2.226**	**7.30**
DIFFERENCE =	**0.00008"**	**0.00029"**	**-0.002**	**-0.008**	**-0.01**	**-0.02**	**0.010**	**0.010**	**0.03**

John Chance Land Surveys, Inc.
200 Dulles Drive
Lafayette, LA 70506
USA
Phone: 337-237-1300
Fax: 337-268-3281
www.jclsurvey.com

Project file data		Coordinate System	
Name:	L:\2014\140457\Data\Gps\Static \East_Timbalier_Static.vce	Name:	US State Plane 1983
Size:	1 MB	Datum:	NAD 1983 (Conus)
Modified:	10/22/2014 11:01:11 AM (UTC:-5)	Zone:	Louisiana South 1702
Time zone:	Central Standard Time	Geoid:	GEOID12A (Conus)
Reference number:		Vertical datum:	NAVD88 (2011)
Description:			

Point List

ID	Northing (US survey foot)	Easting (US survey foot)	Elevation (US survey foot)	Feature Code
BM3	209278.585	3603659.439	7.271	MAG NAIL
DEV1	-117001.451	3152130.325	113.003	
GRIS	281033.475	3719590.183	27.283	
H359	240894.772	3650437.336	4.399	MON
LMCN	275191.094	3495143.496	31.681	
PAUL	353430.322	3606321.437	39.085	
TE23 SM 01	224296.329	3645688.772	7.304	MON
TE118-SM-01	207570.438	3601096.024	2.158	DEEP ROD
TE118-SM-02	207952.337	3604313.921	3.057	DEEP ROD

East Timbalier Island Reference Control

Static GPS Adjustment Using Geoid12A (Rapid Ephemeris)

Station Name	NAD83 (2011) 2010.00				Louisiana South Zone (1702)				NAVD88 (2011)		Description
	Latitude	Longitude	Ellipsoid Hgt (mtr)	Ellipsoid Hgt (ft)	Northing (mtr)	Easting (mtr)	Northing (ft)	Easting (ft)	Elevation (mtr)	Elevation (Ft)	
BM3	29d04'17.53265"	-90d19'22.22983"	-21.541	-70.67	63,788.240	1,098,397.594	209,278.59	3,603,659.44	2.216	7.27	MAG NAIL
H359	29d09'26.12060"	-90d10'31.54616"	-22.517	-73.87	73,424.873	1,112,655.525	240,894.77	3,650,437.34	1.341	4.40	MON
TE23 SM 01	29d06'42.28465"	-90d11'26.96408"	-21.567	-70.76	68,365.658	1,111,208.160	224,296.33	3,645,688.77	2.226	7.30	MON
TE118-SM-01	29d04'00.84655"	-90d19'51.28260"	-23.093	-75.76	63,267.596	1,097,616.263	207,570.44	3,601,096.02	0.658	2.16	DEEP ROD
TE118-SM-02	29d04'04.34691"	-90d19'14.98723"	-22.817	-74.86	63,383.999	1,098,597.080	207,952.34	3,604,313.92	0.932	3.06	DEEP ROD



VICINITY MAP Not to Scale Reproduced from Louisiana 2005 DOQQ

Station Name: "TE23 SM 01"

Location: This Station is located southeast of Port Fourchon, 40 feet east of the centerline of La Hwy. 3090 and 65 feet northeast of the bridge approach near Pass Fourchon, Louisiana.

Monument Description: NGS Style floating sleeve monument; 9/16" stainless steel rods driven 96 feet to refusal, set in a sand filled 6" PVC pipe with access cover set flush with the ground.



Stamping: TE23 SM 01

Installation Date: 2003 **Date of Survey:** October 2014

Monument Established By: Morris P. Hebert, Inc.

NAD83 (2011) 2010.00 Geodetic Position
Lat. 29° 06' 42.28465" N
Long. 90° 11' 26.96408" W

NAD83 (2011) 2010.00 Datum LSZ (1702) Ft
N= 224,296.33
E= 3,645,688.77

NAVD88 Height (2011)
Elevation = 7.30 feet (2.226 mtrs)

Ellipsoid Height = -21.567 mtrs.
Geoid12A Height = -23.793 mtrs.

FOR REFERENCE ONLY
LCZ Adjusted NAVD88 Height (Geoid09)
Elevation = 7.46 feet (2.273 mtrs)

LCZ Adjusted NAVD88 Height (Geoid03)
Elevation = 7.61 feet (2.321 mtrs)

LCZ Adjusted NAVD88 Height (Geoid99)
Elevation = 8.21 feet (2.502 mtrs)



Adjusted Position Established John Chance Land Surveys, Inc. for the Coastal Protection & Restoration Authority of Louisiana



VICINITY MAP Not to Scale Reproduced from Louisiana 2005 DOQQ

Station Name: "TE23 SM 01"

Location: This Station is located southeast of Port Fourchon, 40 feet east of the centerline of La Hwy. 3090 and 65 feet northeast of the bridge approach near Pass Fourchon, Louisiana.

Monument Description: NGS Style floating sleeve monument; 9/16" stainless steel rods driven 96 feet to refusal, set in a sand filled 6" PVC pipe with access cover set flush with the ground.



Stamping: TE23 SM 01

Installation Date: 2003 **Date of Survey:** May 2008

Monument Established By: Morris P. Hebert, Inc.

Adjusted NAD83 Geodetic Position (NSRS2007)
Lat. 29° 06' 42.28538" N
Long. 90° 11' 26.96472" W

Adjusted NAD83 Datum LSZ (1702) Ft (NSRS2007)
N= 224,296.40
E= 3,645,688.72

Adjusted NAVD88 Height (Epoch 2006.81)
Elevation = 7.46 feet (2.273 mtrs)

Ellipsoid Height = -21.546 mtrs.
Geoid09 Height = -23.819 mtrs.

FOR REFERENCE ONLY
LCZ Adjusted NAVD88 Height (Geoid99)
Elevation = 8.21 feet (2.502 mtrs)

LCZ Adjusted NAVD88 Height (Geoid03)
Elevation = 7.61 feet (2.321 mtrs)



Adjusted Position Established John Chance Land Surveys, Inc. for the Coastal Protection & Restoration Authority of Louisiana, OCPR



VICINITY MAP Not to Scale

Image Reproduced from Google Earth Pro ©2008 Google™

Station Name: TE23-SM-01

Monument Location: This Station is located southeast of Port Fourchon, 40 feet east of the centerline of La Hwy. 3090 and 65 feet northeast of the bridge approach near Pass Fourchon, Louisiana.

Monument Description: NGS Style floating sleeve monument; 9/16" stainless steel rods driven 96 feet to refusal, set in a sand filled 6" PVC pipe with access cover set flush with the ground.

Stamping: "TE23 SM 01"

Re-Adjusted: May 2008

Monument Established By: Morris P. Hebert, Inc.



Adjusted NAD83 Geodetic Position (NSRS2007)
Lat. 29° 06' 42.28538"N
Long. 90° 11' 26.96472"W

Adjusted NAD83 Datum LSZ (1702) Ft (NSRS2007)
N= 224,296.40
E= 3,645,688.72


Adjusted NAVD88 Height (2006.81)
Elevation = 7.61 feet (2.321 mtrs)

Ellipsoid Hgt: -21.546 mtrs
Geoid03 Hgt: -23.867 mtrs (2004.65)



FOR REFERENCE ONLY
LCZ Adjusted NAVD88 Height (Geoid99)
Elevation = 8.21 feet (2.502 mtrs)

Adjusted position determined by John Chance Land Surveys, Inc. for the Louisiana Department of Natural Resources, CRD



VICINITY MAP Scale: 1" = 2000' Reproduced from USC&GS "Belle Pass, La" Quadrangle

Station Name: "TE23-SM-01"

Location: Station is located southeast of Port Fourchon, 40' East of the centerline of La. Hwy. 3090 and 65' Northeast of bridge approach near Pass Fourchon.

Monument Description: NGS style floating sleeve monument; datum point set on 9/16" stainless steel sectional rods driven 96 feet to refusal, set in sand filled 6" PVC pipe set in concrete with access cover.

Stamping: TE23-SM-01

Installation Date: September 2003 **Date of Survey:** September 2003

Monument Established By: Morris P. Hebert, Inc.

For: *Louisiana Department of Natural Resources, CRD*

Adjusted NAD 83 Geodetic Position
Lat. 29°06'42.28522" N
Long. 90°11'26.96444" W

Adjusted NAD 83 Datum LSZ (1702) Feet
N= 224,296.39
E= 3,645,688.74

Adjusted NAVD88 Height
Elevation = 8.21 feet (2.502 Mtrs)

Ellipsoid Height = -21.522 Mtrs.
Geoid99 Height = -24.024 Mtrs.





Adjusted Position Established for Louisiana Department of Natural Resources, Coastal Restoration Division by Morris P. Hebert Inc.

SECTION D

RTK Survey
Pre-Plot Transect Lines
RTK Topo Survey Points Listing
Settlement Plates

West Belle Pass Headland Restoration Project-Transects

Point No.	Northing	Easting	Elevation	Description
301	217882.29	3632792.02	0	Transect 1 N
302	215654.26	3632787.16	0	Transect 1 S
303	217897.75	3632273.64	0	Transect 2 N
304	215668.63	3632295.24	0	Transect 2 S
305	217904.61	3631783.81	0	Transect 3 N
306	215676.06	3631772.43	0	Transect 3 S
307	218164.23	3631292.67	0	Transect 4 N
308	215681.17	3631276.88	0	Transect 4 S
309	218325.60	3630780.77	0	Transect 5 N
310	215692.17	3630776.65	0	Transect 5 S
311	218540.82	3630280.85	0	Transect 6 N
312	215696.13	3630284.89	0	Transect 6 S
313	219480.55	3629786.44	0	Transect 7 N
314	215703.28	3629780.19	0	Transect 7 S
315	219951.66	3629280.71	0	Transect 8 N
316	215711.88	3629284.45	0	Transect 8 S
317	219955.70	3628785.73	0	Transect 9 N
318	215716.67	3628778.46	0	Transect 9 S
319	219962.08	3628288.05	0	Transect 10 N
320	215725.42	3628276.21	0	Transect 10 S
321	219966.63	3627790.01	0	Transect 11 N
322	215730.66	3627781.04	0	Transect 11 S
323	219977.64	3627284.12	0	Transect 12 N
324	215742.17	3627288.90	0	Transect 12 S
325	219984.41	3626785.01	0	Transect 13 N
326	215749.76	3626783.07	0	Transect 13 S
327	219992.42	3626284.90	0	Transect 14 N
328	215758.53	3626284.49	0	Transect 14 S
329	219998.94	3625786.87	0	Transect 15 N
330	215765.75	3625774.68	0	Transect 15 S
331	220006.31	3625281.66	0	Transect 16 N
332	215773.79	3625284.96	0	Transect 16 S
333	220017.42	3624786.23	0	Transect 17 N
334	215783.85	3624781.10	0	Transect 17 S
335	220019.73	3624288.15	0	Transect 18 N
336	215786.85	3624285.15	0	Transect 18 S
337	220030.57	3623781.93	0	Transect 19 N
338	215798.35	3623783.33	0	Transect 19 S
339	220039.38	3623284.55	0	Transect 20 N
340	215806.08	3623281.89	0	Transect 20 S
341	220043.80	3622783.59	0	Transect 21 N
342	215811.22	3622790.21	0	Transect 21 S
343	220125.14	3622283.42	0	Transect 22 N
344	215819.41	3622290.90	0	Transect 22 S
345	220140.33	3621779.86	0	Transect 23 N
346	215827.81	3621786.97	0	Transect 23 S
347	220149.37	3621277.24	0	Transect 24 N
348	215833.96	3621286.45	0	Transect 24 S
349	220150.21	3620775.53	0	Transect 25 N
350	215840.07	3620787.82	0	Transect 25 S
351	220169.44	3620276.12	0	Transect 26 N
352	215845.62	3620286.60	0	Transect 26 S

West Belle Pass Headland Restoration - RTK Survey

RTK Pt No	Northing	Easting	Elevation	Description
200	224296.33	3645688.77	7.304	MON TE23-SM-01
500	217882.88	3632791.97	0.85	MANG
501	217865.18	3632791.85	0.84	MANG
502	217846.39	3632792.02	0.77	MANG
503	217826.70	3632791.81	0.72	MANG
504	217809.15	3632792.19	0.69	MANG
505	217796.74	3632791.64	0.73	MANG
506	217779.66	3632791.80	0.69	MANG
507	217764.70	3632791.13	0.65	MANG
508	217737.81	3632791.79	0.69	MANG
509	217724.38	3632791.90	0.71	MANG
510	217713.13	3632791.59	0.53	MANG
511	217697.73	3632791.65	0.67	MANG
512	217679.63	3632791.76	0.54	MANG
513	217659.87	3632791.72	0.66	MANG
514	217643.62	3632791.30	0.68	MANG
515	217626.98	3632791.36	0.68	MANG
516	217609.36	3632791.55	0.79	MANG
517	217590.72	3632791.39	0.38	MANG
518	217573.57	3632791.29	0.49	MANG
519	217559.75	3632791.21	0.53	MANG
520	217545.91	3632791.28	0.43	MANG
521	217532.59	3632791.44	0.51	MANG
522	217514.69	3632791.06	0.64	MANG
523	217499.21	3632791.45	0.63	MANG
524	217474.88	3632791.23	0.63	MANG
525	217454.66	3632791.12	0.64	MANG
526	217439.99	3632791.18	0.63	MANG
527	217421.36	3632790.92	0.72	MANG
528	217403.85	3632791.13	0.77	MANG
529	217390.52	3632791.10	0.74	MANG
530	217375.03	3632790.78	0.78	MANG
531	217351.93	3632790.91	0.59	MANG
532	217333.60	3632790.88	0.98	MANG
533	217310.24	3632790.87	1.02	MANG
534	217292.58	3632790.68	0.93	MANG
535	217270.46	3632790.85	0.86	MANG
536	217249.66	3632790.75	0.86	MANG
537	217228.08	3632790.55	0.92	MANG
538	217206.66	3632790.58	0.88	MANG
539	217189.33	3632790.45	1.02	MANG
540	217179.55	3632790.60	0.87	WES
541	217172.75	3632790.15	-0.06	WB
542	217159.70	3632791.03	0.00	WB

West Belle Pass Headland Restoration - RTK Survey

RTK Pt No	Northing	Easting	Elevation	Description
543	217148.99	3632790.57	0.79	WES
544	217142.12	3632790.52	1.01	MANG
545	217115.24	3632790.38	0.86	MANG
546	217096.52	3632790.39	0.93	MANG
547	217078.98	3632790.23	0.84	MANG
548	217059.52	3632790.30	0.83	MANG
549	217033.51	3632790.15	0.86	MANG
550	217012.60	3632790.00	0.87	MANG
551	216996.04	3632790.00	0.79	MANG
552	216975.96	3632790.04	0.79	MANG
553	216956.19	3632789.90	0.77	MANG
554	216933.21	3632790.00	0.64	WES
555	216916.93	3632790.64	-0.09	WB
556	216905.25	3632791.05	0.65	WES
557	216876.34	3632790.15	0.83	MANG
558	216854.43	3632789.73	0.79	MANG
559	216830.72	3632789.88	0.89	MANG
560	216815.19	3632789.78	0.82	MANG
561	216796.32	3632789.66	0.95	MANG
562	216778.79	3632789.62	0.91	MANG
563	216759.61	3632789.56	1.04	MANG
564	216739.84	3632789.69	0.93	MANG
565	216720.59	3632789.55	1.10	MANG
566	216700.15	3632789.39	1.28	MANG
567	216679.23	3632789.53	1.42	MANG
568	216659.47	3632789.32	1.82	MANG
569	216640.68	3632789.23	2.56	MANG
570	216619.03	3632789.33	2.96	MANG
571	216602.03	3632789.30	3.23	MANG
572	216579.10	3632789.23	3.12	MANG
573	216578.95	3632789.24	3.13	NG
574	216557.09	3632789.20	3.55	NG
575	216535.21	3632789.07	3.39	NG
576	216518.85	3632789.16	3.81	NG
577	216504.90	3632789.14	2.78	NG
578	216483.74	3632788.94	1.51	NG
579	216462.71	3632789.09	0.94	NG
580	216446.24	3632788.61	0.09	WES
581	216415.80	3632788.85	-0.94	WB
582	216401.39	3632788.47	-1.07	WB
583	216378.03	3632788.71	-1.23	WB
584	216361.68	3632788.74	-1.33	WB
585	216349.81	3632788.64	-1.46	WB
586	216339.25	3632788.69	-1.53	WB

West Belle Pass Headland Restoration - RTK Survey

RTK Pt No	Northing	Easting	Elevation	Description
587	216327.80	3632788.65	-1.69	WB
588	216317.54	3632788.62	-1.97	WB
589	216303.99	3632788.61	-2.04	WB
590	216291.07	3632788.49	-2.29	WB
591	216279.94	3632788.61	-2.48	WB
592	216270.28	3632788.57	-2.65	WB
593	216259.65	3632788.50	-2.75	WB
594	216248.27	3632788.45	-2.92	WB
595	216237.71	3632788.43	-3.10	WB
596	216222.72	3632788.44	-3.31	WB
597	216720.44	3632284.76	1.57	NG
598	216707.50	3632284.84	1.22	NG
599	216693.26	3632285.28	0.65	NG
600	216684.31	3632285.18	-0.12	WES
601	216668.80	3632285.66	-1.09	WB
602	216654.60	3632285.46	-1.42	WB
603	216638.99	3632285.67	-1.85	WB
604	216623.30	3632285.22	-1.66	WB
605	216600.79	3632285.95	-1.67	WB
606	216584.69	3632285.98	-1.81	WB
607	216562.35	3632286.40	-2.08	WB
608	216548.62	3632286.61	-2.13	WB
609	216531.55	3632286.55	-2.27	WB
610	216512.20	3632286.51	-2.71	WB
611	216494.35	3632286.79	-2.88	WB
612	216910.16	3631778.81	2.49	NG
613	216896.25	3631778.66	1.21	NG
614	216878.38	3631778.13	-0.01	WES
615	216865.35	3631778.69	-0.65	WB
616	216851.47	3631778.27	-1.05	WB
617	216837.37	3631778.85	-1.63	WB
618	216822.54	3631778.16	-2.08	WB
619	216808.24	3631778.40	-2.35	WB
620	216792.68	3631778.53	-2.60	WB
621	216778.23	3631778.04	-2.80	WB
622	216767.23	3631777.96	-2.68	WB
623	217045.64	3631285.96	5.87	NG
624	217045.00	3631286.05	3.00	NG
625	217032.75	3631285.04	1.86	NG
626	217018.71	3631285.26	0.88	NG
627	217008.13	3631285.34	0.23	WES
628	216995.46	3631284.65	-0.54	WB
629	216979.78	3631285.13	-1.17	WB
630	216959.45	3631285.11	-2.01	WB

West Belle Pass Headland Restoration - RTK Survey

RTK Pt No	Northing	Easting	Elevation	Description
631	216941.38	3631284.62	-2.66	WB
632	216919.39	3631284.90	-2.46	WB
633	216899.42	3631284.69	-2.58	WB
634	217167.10	3630779.08	6.01	NG
635	217165.41	3630778.66	2.95	NG
636	217151.31	3630778.84	1.98	NG
637	217136.47	3630778.95	1.63	NG
638	217128.00	3630778.93	1.71	NG
639	217118.08	3630778.91	1.79	NG
640	217104.02	3630778.88	0.85	NG
641	217094.20	3630778.77	0.30	WES
642	217078.48	3630778.82	-0.70	WB
643	217067.96	3630778.98	-0.99	WB
644	217057.99	3630779.54	-1.28	WB
645	217048.09	3630779.39	-1.74	WB
646	217035.07	3630778.52	-2.52	WB
647	217024.50	3630777.74	-2.71	WB
648	217014.12	3630778.61	-2.91	WB
649	217167.63	3630250.67	8.71	SP-8
650	217235.11	3630283.02	5.51	NG
651	217233.79	3630282.92	3.22	NG
652	217219.62	3630282.64	1.91	NG
653	217205.92	3630282.79	1.30	NG
654	217189.24	3630282.74	-0.05	WES
655	217177.72	3630283.35	-0.77	WB
656	217164.46	3630283.01	-1.26	WB
657	217150.94	3630281.55	-1.68	WB
658	217139.19	3630280.95	-2.32	WB
659	217127.09	3630281.63	-2.55	WB
660	217112.22	3630282.98	-2.69	WB
661	217100.61	3630283.93	-1.96	WB
662	217089.55	3630283.04	-2.04	WB
663	217078.65	3630281.47	-2.30	WB
664	217067.70	3630281.68	-2.55	WB
665	217167.31	3630250.04	-1.43	NG
666	217289.94	3629783.25	5.93	NG
667	217288.86	3629782.71	2.35	NG
668	217271.19	3629782.85	1.88	NG
669	217256.99	3629782.71	0.88	NG
670	217244.91	3629782.69	0.23	WES
671	217230.42	3629782.99	-0.70	WB
672	217219.32	3629782.57	-1.02	WB
673	217197.46	3629784.04	-2.10	WB
674	217182.94	3629782.69	-2.53	WB

West Belle Pass Headland Restoration - RTK Survey

RTK Pt No	Northing	Easting	Elevation	Description
675	217165.80	3629781.35	-3.09	WB
676	217151.73	3629782.51	-3.66	WB
677	217295.58	3629282.23	6.24	NG
678	217294.18	3629282.64	2.55	NG
679	217273.34	3629283.41	1.47	NG
680	217256.98	3629283.08	0.71	NG
681	217245.95	3629282.92	0.21	WES
682	217229.96	3629283.15	-0.44	WB
683	217215.51	3629283.20	-1.02	WB
684	217198.54	3629282.83	-1.83	WB
685	217181.26	3629282.14	-2.73	WB
686	217165.31	3629281.94	-3.44	WB
687	217154.29	3629282.34	-3.94	WB
688	217317.62	3628780.83	6.18	NG
689	217316.62	3628780.78	3.19	NG
690	217293.60	3628781.34	1.66	NG
691	217273.86	3628781.23	0.77	NG
692	217259.45	3628780.99	0.13	WES
693	217243.90	3628781.05	-0.42	WB
694	217228.69	3628781.20	-1.12	WB
695	217211.37	3628780.48	-1.29	WB
696	217195.15	3628779.63	-2.30	WB
697	217182.31	3628778.77	-2.98	WB
698	217172.34	3628780.14	-3.41	WB
699	217163.66	3628780.50	-3.72	WB
700	217314.59	3628285.96	1.76	NG
701	217314.93	3628286.24	11.64	SP-6
703	217333.81	3628280.76	2.94	NG
704	217312.35	3628280.56	1.71	NG
705	217295.13	3628280.71	1.27	NG
706	217272.27	3628280.52	0.13	WES
707	217256.15	3628280.77	-0.52	WB
708	217236.48	3628280.24	-0.88	WB
709	217221.20	3628282.05	-1.20	WB
710	217207.41	3628280.81	-1.35	WB
711	217192.29	3628281.82	-2.08	WB
712	217179.09	3628280.00	-2.76	WB
713	217168.26	3628278.41	-3.40	WB
714	217364.31	3627784.59	5.93	NG
715	217363.22	3627784.64	3.17	NG
716	217350.01	3627784.61	2.02	NG
717	217332.66	3627784.56	1.54	NG
718	217317.14	3627784.48	0.95	NG
719	217302.97	3627784.21	0.44	NG

West Belle Pass Headland Restoration - RTK Survey

RTK Pt No	Northing	Easting	Elevation	Description
720	217283.89	3627784.26	-0.31	WES
721	217283.77	3627784.98	-0.34	WB
722	217267.26	3627784.34	-0.80	WB
723	217251.38	3627782.75	-0.95	WB
724	217234.24	3627782.41	-1.15	WB
725	217221.06	3627783.91	-1.42	WB
726	217202.06	3627787.20	-1.61	WB
727	217183.43	3627786.83	-2.57	WB
728	217169.82	3627785.25	-3.13	WB
729	217386.54	3627287.26	6.25	NG
730	217384.57	3627287.25	3.46	NG
731	217368.59	3627287.13	1.93	NG
732	217353.02	3627286.92	1.23	NG
733	217334.46	3627286.76	0.34	WES
734	217318.60	3627286.94	-0.72	WB
735	217301.51	3627287.49	-0.89	WB
736	217284.31	3627286.73	-0.90	WB
737	217269.86	3627286.02	-1.02	WB
738	217254.70	3627284.89	-1.13	WB
739	217232.32	3627287.98	-1.38	WB
740	217211.23	3627289.47	-1.80	WB
741	217196.24	3627289.99	-2.38	WB
742	217180.85	3627290.56	-3.04	WB
743	217411.17	3626783.90	5.50	NG
744	217410.84	3626784.05	3.32	NG
745	217393.94	3626784.46	1.78	NG
746	217377.57	3626783.74	1.48	NG
747	217362.06	3626783.72	0.63	NG
748	217354.21	3626783.76	0.08	WES
749	217337.31	3626783.76	-1.16	WB
750	217325.75	3626783.48	-1.60	WB
751	217311.49	3626782.14	-1.71	WB
752	217295.55	3626780.88	-0.98	WB
753	217274.75	3626781.82	-1.39	WB
754	217256.75	3626781.64	-1.31	WB
755	217236.18	3626784.02	-1.48	WB
756	217217.41	3626785.90	-2.09	WB
757	217203.53	3626787.07	-1.74	WB
758	217182.76	3626783.07	-3.31	WB
759	217462.14	3626286.72	5.65	NG
760	217462.85	3626286.88	10.07	SP-3
761	217439.23	3626284.74	5.02	NG
762	217437.74	3626284.99	2.45	NG
763	217421.32	3626284.53	1.63	NG

West Belle Pass Headland Restoration - RTK Survey

RTK Pt No	Northing	Easting	Elevation	Description
764	217408.10	3626284.21	0.99	NG
765	217392.94	3626284.52	0.26	WES
766	217377.88	3626283.97	-0.78	WB
767	217363.74	3626284.57	-1.42	WB
768	217344.96	3626282.85	-1.77	WB
769	217327.26	3626281.93	-1.66	WB
770	217308.36	3626283.17	-1.47	WB
771	217288.57	3626283.32	-1.58	WB
772	217267.51	3626283.67	-1.77	WB
773	217245.82	3626285.39	-1.69	WB
774	217226.44	3626287.85	-2.03	WB
775	217211.84	3626287.70	-2.69	WB
776	217196.20	3626286.11	-2.91	WB
777	217195.75	3626286.65	-3.38	WB
778	217466.82	3625779.58	4.33	NG
779	217465.02	3625779.56	3.07	NG
780	217444.41	3625779.47	1.81	NG
781	217423.83	3625779.47	0.75	NG
782	217407.98	3625779.63	-0.18	WES
783	217385.95	3625779.46	-1.40	WB
784	217366.62	3625777.78	-1.99	WB
785	217351.01	3625777.73	-2.45	WB
786	217332.39	3625778.29	-1.49	WB
787	217313.33	3625778.46	-2.06	WB
788	217300.88	3625777.33	-2.41	WB
789	217283.39	3625777.31	-1.83	WB
790	217267.71	3625777.26	-1.92	WB
791	217246.68	3625777.72	-2.13	WB
792	217227.88	3625778.66	-2.79	WB
793	217513.89	3625283.88	3.94	NG
794	217513.01	3625283.43	2.83	NG
795	217492.80	3625283.58	1.72	NG
796	217473.80	3625283.54	1.31	NG
797	217449.05	3625283.63	0.12	WES
798	217433.65	3625283.90	-0.80	WB
799	217416.09	3625283.81	-1.66	WB
800	217401.09	3625282.78	-2.44	WB
801	217390.03	3625281.38	-3.09	WB
802	217371.74	3625282.22	-1.62	WB
803	217341.29	3625284.21	-2.13	WB
804	217319.79	3625284.01	-2.10	WB
805	217301.68	3625282.34	-1.86	WB
806	217281.32	3625284.52	-2.38	WB
807	217266.21	3625285.27	-2.30	WB

West Belle Pass Headland Restoration - RTK Survey

RTK Pt No	Northing	Easting	Elevation	Description
808	217562.50	3624782.94	3.94	NG
809	217561.70	3624782.86	2.09	NG
810	217543.11	3624783.15	1.26	NG
811	217523.03	3624783.03	1.17	NG
812	217503.26	3624783.64	0.14	WES
813	217482.83	3624782.79	-0.72	WB
814	217460.46	3624784.21	-1.43	WB
815	217441.29	3624784.10	-1.83	WB
816	217422.18	3624784.34	-2.21	WB
817	217404.19	3624782.78	-2.26	WB
818	217386.68	3624782.25	-2.45	WB
819	217368.81	3624781.54	-2.71	WB
820	217352.36	3624781.19	-1.98	WB
821	217327.60	3624780.07	-2.01	WB
822	217311.20	3624779.47	-2.60	WB
823	217295.92	3624780.03	-3.19	WB
824	217604.06	3624282.24	2.04	NG
825	217604.92	3624283.11	10.26	SP-1
826	217610.84	3624286.57	6.08	NG
827	217610.29	3624286.70	4.27	NG
828	217606.63	3624286.13	2.51	NG
829	217590.24	3624286.49	1.57	NG
830	217574.53	3624286.14	0.91	NG
831	217559.68	3624286.43	0.31	WES
832	217539.94	3624286.61	-0.69	WB
833	217522.39	3624286.33	-1.13	WB
834	217504.96	3624286.84	-1.86	WB
835	217481.88	3624287.52	-2.45	WB
836	217455.33	3624286.15	-2.08	WB
837	217432.78	3624287.49	-2.48	WB
838	217410.67	3624286.68	-2.38	WB
839	217385.16	3624285.15	-1.99	WB
840	217367.49	3624285.60	-2.40	WB
841	217352.70	3624286.11	-2.99	WB
842	217669.28	3623783.30	2.75	NG
843	217650.51	3623782.69	1.65	NG
844	217632.76	3623782.66	0.80	NG
845	217617.79	3623782.74	0.08	WES
846	217596.90	3623783.31	-0.75	WB
847	217578.08	3623782.98	-1.13	WB
848	217560.24	3623784.30	-1.91	WB
849	217541.73	3623784.58	-2.52	WB
850	217526.53	3623784.47	-2.83	WB
851	217750.77	3623282.88	2.41	NG

West Belle Pass Headland Restoration - RTK Survey

RTK Pt No	Northing	Easting	Elevation	Description
852	217733.45	3623283.07	1.55	NG
853	217717.51	3623282.93	1.49	NG
854	217702.13	3623282.90	0.82	NG
855	217686.92	3623283.18	0.05	WES
856	217669.82	3623282.83	-0.68	WB
857	217652.42	3623284.31	-0.92	WB
858	217632.95	3623284.31	-1.92	WB
859	217622.35	3623284.14	-2.15	WB
860	217602.96	3623282.00	-2.66	WB
861	217591.75	3623280.57	-2.96	WB
862	217835.50	3622787.21	2.56	NG
863	217814.34	3622787.33	1.85	NG
864	217791.15	3622787.06	1.35	NG
865	217773.51	3622787.20	0.64	NG
866	217762.38	3622787.26	0.27	WES
867	217741.40	3622787.13	-0.68	WB
868	217724.69	3622784.37	-0.90	WB
869	217696.61	3622785.41	-1.83	WB
870	217681.50	3622787.48	-2.53	WB
871	217662.64	3622786.50	-3.04	WB
872	217937.36	3622287.65	2.46	NG
873	217920.38	3622287.12	1.88	NG
874	217904.91	3622287.56	1.47	NG
875	217881.83	3622287.30	0.94	NG
876	217865.73	3622287.40	0.56	NG
877	217854.19	3622287.10	-0.02	WES
878	217838.07	3622286.81	-0.68	WB
879	217821.16	3622285.27	-0.97	WB
880	217798.09	3622285.23	-1.11	WB
881	217775.01	3622287.12	-2.23	WB
882	217759.43	3622288.44	-2.91	WB
883	217744.20	3622289.87	-3.23	WB
884	218055.50	3621783.46	2.18	NG
885	218039.62	3621783.38	1.58	NG
886	218021.73	3621783.40	1.27	NG
887	218005.23	3621783.61	1.30	NG
888	217985.98	3621783.27	0.57	NG
889	217973.50	3621783.59	0.23	WES
890	217960.80	3621783.63	-0.70	WB
891	217939.16	3621781.30	-0.85	WB
892	217911.82	3621783.93	-0.99	WB
893	217886.59	3621783.02	-1.70	WB
894	217864.94	3621782.63	-2.75	WB
895	217851.53	3621783.11	-3.11	WB

West Belle Pass Headland Restoration - RTK Survey

RTK Pt No	Northing	Easting	Elevation	Description
896	218223.57	3621281.32	2.46	NG
897	218206.18	3621280.99	1.96	NG
898	218186.01	3621281.65	1.14	NG
899	218171.59	3621281.48	1.20	NG
900	218153.16	3621281.38	1.17	NG
901	218137.15	3621281.38	0.50	NG
902	218126.23	3621281.47	-0.07	WES
903	218110.55	3621281.63	-0.80	WB
904	218087.83	3621280.87	-0.96	WB
905	218062.84	3621280.74	-1.06	WB
906	218042.84	3621279.58	-1.23	WB
907	218023.86	3621278.87	-1.38	WB
908	218006.36	3621281.39	-2.30	WB
909	217983.41	3621280.45	-3.03	WB
910	218376.56	3620780.95	2.19	NG
911	218360.15	3620780.44	1.42	NG
912	218345.21	3620780.92	1.02	NG
913	218331.78	3620781.06	0.19	WES
914	218313.24	3620781.06	-0.73	WB
915	218288.56	3620779.34	-0.63	WB
916	218271.33	3620780.41	-0.68	WB
917	218252.66	3620779.17	-0.78	WB
918	218235.84	3620780.45	-1.00	WB
919	218218.73	3620781.32	-1.14	WB
920	218202.64	3620781.06	-1.37	WB
921	218183.03	3620781.24	-1.50	WB
922	218164.75	3620781.27	-2.08	WB
923	218148.87	3620780.05	-2.80	WB
924	218132.65	3620780.90	-3.23	WB
925	218575.64	3620280.27	2.24	NG
926	218557.95	3620279.76	2.21	NG
927	218537.61	3620280.18	1.52	NG
928	218522.31	3620280.26	0.90	NG
929	218511.94	3620280.33	-0.04	WES
930	218496.61	3620279.69	-0.96	WB
931	218474.65	3620280.17	-0.75	WB
932	218453.45	3620279.57	-0.68	WB
933	218429.75	3620280.66	-0.79	WB
934	218410.73	3620281.93	-1.01	WB
935	218384.94	3620278.83	-1.06	WB
936	218365.43	3620279.10	-1.11	WB
937	218348.85	3620277.84	-1.29	WB
938	218329.34	3620280.93	-1.68	WB
939	218310.38	3620279.86	-2.33	WB

West Belle Pass Headland Restoration - RTK Survey

RTK Pt No	Northing	Easting	Elevation	Description
940	218296.77	3620278.89	-2.76	WB
941	218284.54	3620278.38	-3.28	WB
942	218840.26	3634997.55	1.44	CHK
943	218840.30	3634997.51	1.49	CHK
944	217823.40	3632274.33	0.69	MANG
945	217785.04	3632274.36	0.76	MANG
946	217758.69	3632275.13	0.86	MANG
947	217737.53	3632274.97	0.81	MANG
948	217711.41	3632275.62	0.78	MANG
949	217687.94	3632275.59	0.73	MANG
950	217661.05	3632275.99	0.77	MANG
951	217619.55	3632276.17	0.66	MANG
952	217588.93	3632276.88	0.76	MANG
953	217561.79	3632277.14	0.63	MANG
954	217539.78	3632277.15	0.65	MANG
955	217513.99	3632277.47	0.69	MANG
956	217488.23	3632277.68	0.78	MANG
957	217465.49	3632277.77	0.70	MANG
958	217440.58	3632278.04	0.81	MANG
959	217420.55	3632278.32	0.70	MANG
960	217393.90	3632278.63	0.69	MANG
961	217368.75	3632278.85	0.68	MANG
962	217352.31	3632278.76	0.68	MANG
963	217333.67	3632278.67	0.69	MANG
964	217298.06	3632279.30	0.72	MANG
965	217280.56	3632279.57	0.74	MANG
966	217256.78	3632279.63	0.82	MANG
967	217237.30	3632280.22	0.82	MANG
968	217218.88	3632280.05	0.70	MANG
969	217201.87	3632280.58	0.77	MANG
970	217185.41	3632280.57	0.83	MANG
971	217169.99	3632280.80	0.76	MANG
972	217151.93	3632281.22	0.81	MANG
973	217131.64	3632280.87	0.84	MANG
974	217101.83	3632281.60	0.93	MANG
975	217086.98	3632281.37	0.82	MANG
976	217073.08	3632281.72	0.88	MANG
977	217052.12	3632281.92	0.90	MANG
978	217036.65	3632282.05	0.93	MANG
979	217019.52	3632282.14	0.84	MANG
980	216999.59	3632282.28	0.96	MANG
981	216981.47	3632282.90	0.88	MANG
982	216971.97	3632284.06	0.29	WB
983	216964.05	3632282.80	0.88	WB

West Belle Pass Headland Restoration - RTK Survey

RTK Pt No	Northing	Easting	Elevation	Description
984	216953.94	3632282.76	0.97	NG
985	216938.80	3632283.03	0.98	NG
986	216923.85	3632283.01	0.92	NG
987	216906.01	3632283.13	1.05	NG
988	216892.21	3632283.47	1.05	NG
989	216875.46	3632283.67	1.08	NG
990	216856.87	3632283.63	1.26	NG
991	216835.12	3632282.31	1.65	NG
992	216813.74	3632284.26	1.76	NG
993	216792.14	3632284.50	2.02	NG
994	216770.55	3632284.41	2.77	NG
995	216749.66	3632284.75	3.22	NG
996	216738.77	3632285.03	3.80	NG
997	216913.66	3631778.80	2.88	NG
998	216936.90	3631778.86	3.43	NG
999	216962.58	3631779.00	3.29	NG
1000	216985.28	3631779.10	3.12	NG
1001	217004.65	3631779.25	2.58	NG
1002	217025.16	3631779.21	2.86	NG
1003	217045.87	3631779.53	2.60	NG
1004	217066.84	3631779.40	2.41	NG
1005	217087.89	3631779.66	2.42	NG
1006	217112.49	3631779.82	1.46	NG
1007	217147.43	3631780.01	1.12	NG
1008	217173.06	3631780.29	0.94	MANG
1009	217196.48	3631780.06	0.94	MANG
1010	217213.50	3631780.45	0.88	MANG
1011	217237.17	3631780.60	0.87	MANG
1012	217258.58	3631780.46	0.84	MANG
1013	217277.36	3631780.77	0.52	MANG
1014	217298.12	3631780.64	0.67	MANG
1015	217316.04	3631780.53	0.74	MANG
1016	217335.22	3631780.92	0.73	MANG
1017	217362.19	3631781.06	0.68	MANG
1018	217383.54	3631781.17	0.94	MANG
1019	217396.74	3631781.14	0.32	WES
1020	217406.45	3631781.16	0.04	WB
1021	217413.34	3631781.27	0.31	WES
1022	217418.29	3631781.52	0.84	MANG
1023	217439.38	3631781.01	1.03	MANG
1024	217460.24	3631781.86	0.84	MANG
1025	217482.26	3631781.80	0.73	NG
1026	217506.03	3631781.95	0.71	NG
1027	217528.48	3631782.25	0.64	NG

West Belle Pass Headland Restoration - RTK Survey

RTK Pt No	Northing	Easting	Elevation	Description
1028	217548.54	3631782.06	0.74	NG
1029	217565.89	3631781.83	0.65	NG
1030	217584.10	3631782.27	0.75	NG
1031	217607.22	3631782.54	0.87	NG
1032	217627.74	3631782.34	0.37	NG
1033	217632.34	3631782.38	0.13	WES
1034	217632.39	3631782.11	0.10	WES
1035	217645.86	3631783.10	0.40	WB
1036	217664.79	3631782.62	0.36	NG
1037	217687.41	3631782.38	0.96	NG
1038	217703.76	3631782.44	0.91	MANG
1039	217722.46	3631783.09	0.89	MANG
1040	217745.92	3631782.91	0.86	MANG
1041	217756.47	3631783.21	0.85	MANG
1042	217767.98	3631782.97	0.84	MANG
1043	217790.89	3631783.14	0.88	MANG
1044	217810.79	3631783.37	0.87	MANG
1045	217827.41	3631783.37	0.95	MANG
1046	217848.81	3631783.61	0.96	MANG
1047	217866.90	3631783.49	1.15	MANG
1048	217904.84	3631783.72	1.10	MANG
1049	218163.42	3631292.80	0.75	NG
1050	218147.70	3631292.73	0.83	NG
1051	218122.12	3631292.64	0.95	NG
1052	218102.66	3631292.48	1.03	NG
1053	218084.61	3631292.21	0.93	NG
1054	218069.70	3631291.99	0.88	NG
1055	218049.14	3631292.03	0.90	NG
1056	218028.20	3631291.73	1.00	NG
1057	218005.44	3631291.58	1.06	NG
1058	217987.67	3631291.81	1.26	NG
1059	217965.60	3631291.65	1.00	NG
1060	217945.25	3631291.37	1.19	NG
1061	217937.69	3631291.15	0.69	WES
1062	217918.28	3631289.50	-0.17	TR HIT
1063	217905.06	3631290.74	0.72	WES
1064	217892.04	3631290.94	1.13	NG
1065	217875.01	3631290.82	1.15	NG
1066	217858.01	3631290.77	1.19	NG
1067	217843.31	3631290.59	1.15	NG
1068	217822.03	3631290.42	1.20	NG
1069	217799.43	3631290.37	1.21	NG
1070	217775.28	3631289.56	1.30	NG
1071	217751.07	3631289.89	1.29	NG

West Belle Pass Headland Restoration - RTK Survey

RTK Pt No	Northing	Easting	Elevation	Description
1072	217725.25	3631289.79	1.41	NG
1073	217705.02	3631289.91	1.37	NG
1074	217685.69	3631289.74	1.34	NG
1075	217666.51	3631289.62	1.28	NG
1076	217646.47	3631289.35	1.32	NG
1077	217624.81	3631289.50	0.97	NG
1078	217607.23	3631288.94	0.66	NG
1079	217589.38	3631289.16	0.38	NG
1080	217570.18	3631289.02	0.71	NG
1081	217540.06	3631288.72	0.72	NG
1082	217517.13	3631288.50	1.82	NG
1083	217496.99	3631288.46	1.99	NG
1084	217469.49	3631288.37	2.06	NG
1085	217437.43	3631288.01	1.98	NG
1086	217402.39	3631287.68	2.30	NG
1087	217364.10	3631287.89	2.46	NG
1088	217336.97	3631287.63	2.57	NG
1089	217315.10	3631287.25	2.64	NG
1090	217293.99	3631287.24	2.73	NG
1091	217272.91	3631286.98	2.92	NG
1092	217251.73	3631286.84	3.07	NG
1093	217230.24	3631286.79	3.65	NG
1094	217208.34	3631286.56	3.84	NG
1095	217183.81	3631286.45	3.87	NG
1096	217160.06	3631286.31	4.12	NG
1097	217135.92	3631286.19	4.82	NG
1098	217110.60	3631286.03	5.00	NG
1099	217084.43	3631285.79	5.54	NG
1100	217061.39	3631285.67	5.75	NG
1101	217170.93	3630778.77	6.09	NG
1102	217194.74	3630778.85	6.26	NG
1103	217219.23	3630779.03	6.05	NG
1104	217241.00	3630778.95	5.38	NG
1105	217261.51	3630779.10	4.78	NG
1106	217283.15	3630779.03	4.42	NG
1107	217305.63	3630778.97	4.21	NG
1108	217329.18	3630779.23	3.68	NG
1109	217354.25	3630779.18	3.34	NG
1110	217377.09	3630779.27	3.16	NG
1111	217401.93	3630779.24	3.13	NG
1112	217422.28	3630778.90	3.08	NG
1113	217447.15	3630779.41	2.88	NG
1114	217468.85	3630779.50	2.70	NG
1115	217492.35	3630779.37	2.52	NG

West Belle Pass Headland Restoration - RTK Survey

RTK Pt No	Northing	Easting	Elevation	Description
1116	217516.21	3630779.75	2.33	NG
1117	217540.87	3630779.39	2.25	NG
1118	217561.43	3630779.57	2.11	NG
1119	217587.51	3630779.62	2.01	NG
1120	217615.84	3630779.80	2.00	NG
1121	217644.63	3630779.62	1.57	NG
1122	217685.05	3630779.87	1.20	NG
1123	217704.69	3630779.64	1.17	NG
1124	217725.42	3630779.63	1.07	NG
1125	217747.30	3630779.79	1.00	NG
1126	217776.38	3630779.76	0.77	NG
1127	217794.36	3630779.54	1.48	NG
1128	217823.34	3630779.93	1.00	NG
1129	217844.91	3630780.05	1.19	NG
1130	217862.34	3630779.91	1.41	NG
1131	217884.80	3630779.90	1.51	NG
1132	217905.64	3630779.86	1.37	NG
1133	217928.80	3630779.98	1.19	NG
1134	217944.75	3630780.17	1.19	NG
1135	217967.67	3630780.37	1.08	NG
1136	217988.58	3630779.95	1.07	NG
1137	218013.07	3630780.15	1.19	NG
1138	218037.15	3630780.11	1.20	NG
1139	218049.86	3630779.87	0.74	WES
1140	218063.93	3630780.79	-0.03	WB
1141	218072.09	3630779.55	0.54	WES
1142	218096.93	3630780.13	1.39	NG
1143	218121.79	3630780.35	1.33	NG
1144	218143.12	3630780.34	1.29	NG
1145	218159.31	3630780.59	1.25	NG
1146	218177.88	3630780.65	1.21	NG
1147	218194.36	3630780.46	1.17	NG
1148	218210.93	3630780.50	1.20	NG
1149	218226.58	3630780.68	1.20	NG
1150	218246.19	3630780.87	1.31	NG
1151	218278.05	3630780.61	0.98	NG
1152	218301.00	3630782.82	0.60	NG
1153	218329.65	3630780.38	0.35	WB
1154	218540.31	3630280.84	0.93	NG
1155	218513.88	3630280.77	1.03	NG
1156	218489.05	3630280.79	0.93	NG
1157	218488.91	3630280.86	0.94	NG
1158	218465.46	3630280.94	0.90	NG
1159	218445.73	3630281.06	0.92	NG

West Belle Pass Headland Restoration - RTK Survey

RTK Pt No	Northing	Easting	Elevation	Description
1160	218421.57	3630281.05	0.92	NG
1161	218401.08	3630280.93	0.90	NG
1162	218381.44	3630281.30	0.94	NG
1163	218355.48	3630280.92	0.98	NG
1164	218329.05	3630281.00	1.03	NG
1165	218305.27	3630281.07	1.01	NG
1166	218271.95	3630281.23	1.01	NG
1167	218239.42	3630281.24	1.05	NG
1168	218215.81	3630281.66	1.10	NG
1169	218193.03	3630281.05	1.13	NG
1170	218168.92	3630281.64	1.21	NG
1171	218151.13	3630281.31	1.32	NG
1172	218128.34	3630281.58	1.32	NG
1173	218107.29	3630281.59	1.37	NG
1174	218088.14	3630281.65	2.03	NG
1175	218071.84	3630281.45	3.73	NG
1176	218062.03	3630283.16	6.02	NG
1177	218068.95	3630289.83	3.71	PIPE
1178	218045.06	3630281.50	3.29	NG
1179	218019.96	3630281.57	2.15	NG
1180	217998.50	3630281.60	1.48	NG
1181	217971.38	3630281.53	0.57	NG
1182	218069.08	3630290.36	3.44	NG
1183	218069.24	3630289.88	7.67	SP-10
1184	217955.79	3630179.15	5.42	SP-9
1185	217955.19	3630179.38	0.69	NG
1186	217919.36	3630284.03	-1.10	NG
1187	217918.76	3630282.06	-0.28	WES
1188	217865.85	3630282.01	2.83	NG
1189	217851.38	3630281.84	3.70	NG
1190	217825.30	3630281.98	2.73	NG
1191	217797.44	3630281.71	1.95	NG
1192	217758.20	3630281.08	1.40	NG
1193	217715.69	3630282.17	1.84	NG
1194	217695.78	3630281.81	1.82	NG
1195	217674.83	3630282.04	1.80	NG
1196	217653.09	3630282.09	1.80	NG
1197	217632.02	3630281.96	1.79	NG
1198	217605.58	3630282.31	1.79	NG
1199	217581.04	3630282.34	1.82	NG
1200	217560.21	3630282.39	1.85	NG
1201	217534.81	3630282.15	1.89	NG
1202	217508.18	3630282.30	1.93	NG
1203	217482.57	3630282.40	1.98	NG

West Belle Pass Headland Restoration - RTK Survey

RTK Pt No	Northing	Easting	Elevation	Description
1204	217455.02	3630282.36	2.15	NG
1205	217432.83	3630282.39	2.31	NG
1206	217402.90	3630282.30	2.65	NG
1207	217378.46	3630282.38	3.16	NG
1208	217354.08	3630282.49	3.86	NG
1209	217327.98	3630282.60	3.81	NG
1210	217306.91	3630282.53	4.17	NG
1211	217281.30	3630282.66	4.99	NG
1212	217259.62	3630282.81	5.33	NG
1213	217239.14	3630282.73	5.45	NG
1214	217293.65	3629782.88	5.70	NG
1215	217321.07	3629782.89	5.55	NG
1216	217346.05	3629782.72	4.75	NG
1217	217372.76	3629782.91	4.49	NG
1218	217398.26	3629783.01	4.03	NG
1219	217419.32	3629782.97	3.82	NG
1220	217446.69	3629783.07	3.66	NG
1221	217472.32	3629782.98	3.62	NG
1222	217500.60	3629783.16	3.27	NG
1223	217527.72	3629783.07	3.17	NG
1224	217554.11	3629783.11	3.12	NG
1225	217580.06	3629783.22	3.08	NG
1226	217605.56	3629783.50	3.03	NG
1227	217632.05	3629783.35	3.04	NG
1228	217658.89	3629783.56	2.99	NG
1229	217685.39	3629783.25	2.99	NG
1230	217708.43	3629783.57	2.99	NG
1231	217734.85	3629783.57	3.00	NG
1232	217761.32	3629783.47	2.81	NG
1233	217787.84	3629783.71	2.90	NG
1234	217787.76	3629783.69	2.91	NG
1235	217816.73	3629783.68	2.54	NG
1236	217843.81	3629783.86	2.34	NG
1237	217870.96	3629783.88	2.07	NG
1238	217899.03	3629783.56	1.80	NG
1239	217899.25	3629783.92	1.80	NG
1240	217927.39	3629784.03	1.73	NG
1241	217953.06	3629783.84	1.76	NG
1242	217953.07	3629783.87	1.75	NG
1243	217978.91	3629783.80	1.79	NG
1244	218005.33	3629783.87	1.71	NG
1245	218032.31	3629784.02	1.68	NG
1246	218059.50	3629783.97	1.59	NG
1247	218085.05	3629784.24	1.59	NG

West Belle Pass Headland Restoration - RTK Survey

RTK Pt No	Northing	Easting	Elevation	Description
1248	218111.08	3629784.10	1.55	NG
1249	218137.65	3629784.35	1.53	NG
1250	218162.31	3629784.34	1.49	NG
1251	218188.57	3629784.24	1.45	NG
1252	218214.70	3629784.31	1.46	NG
1253	218235.30	3629784.14	1.50	NG
1254	218262.12	3629784.47	1.32	NG
1255	218287.77	3629784.12	1.71	NG
1256	218323.30	3629784.70	1.05	NG
1257	218323.26	3629784.60	1.08	NG
1258	218379.93	3629784.59	0.52	NG
1259	218934.80	3629785.48	0.41	NG
1260	218982.65	3629785.62	1.51	NG
1261	219007.16	3629785.70	2.01	NG
1262	219024.07	3629785.66	2.37	NG
1263	219049.55	3629785.67	3.39	NG
1264	219062.77	3629785.73	6.07	NG
1265	219085.81	3629785.79	4.15	NG
1266	219104.59	3629785.78	2.86	NG
1267	219127.54	3629785.85	1.51	NG
1268	219150.43	3629785.87	1.16	NG
1269	219179.41	3629785.96	1.09	NG
1270	219201.87	3629785.99	1.04	NG
1271	219221.58	3629786.00	1.08	NG
1272	219241.01	3629786.07	1.02	NG
1273	219259.40	3629786.05	0.97	NG
1274	219278.77	3629786.12	0.95	NG
1275	219296.62	3629786.07	0.91	NG
1276	219316.82	3629786.14	0.88	NG
1277	219334.63	3629786.25	0.92	NG
1278	219350.78	3629786.22	0.86	NG
1279	219369.78	3629786.26	0.92	NG
1280	219392.67	3629786.34	0.81	NG
1281	219415.43	3629786.30	0.76	NG
1282	219436.57	3629786.35	0.70	NG
1283	219451.60	3629786.36	0.68	NG
1284	219466.38	3629786.41	0.65	NG
1285	219480.59	3629786.39	0.58	NG
1286	219469.33	3629281.17	0.00	WES
1287	218840.29	3634997.51	1.43	CHK
1288	219490.20	3629281.13	-0.61	WES
1289	219473.69	3629281.16	-0.17	NG
1290	219457.73	3629281.17	0.76	NG
1291	219445.88	3629281.09	2.39	NG

West Belle Pass Headland Restoration - RTK Survey

RTK Pt No	Northing	Easting	Elevation	Description
1292	219442.77	3629281.19	2.87	NG
1293	219440.20	3629281.18	4.66	NG
1294	219436.71	3629281.09	6.21	NG
1295	219434.33	3629281.11	5.44	NG
1296	219432.62	3629281.19	4.81	NG
1297	219431.09	3629281.20	3.65	NG
1298	219427.53	3629281.22	2.82	NG
1299	219414.37	3629281.21	1.93	NG
1300	219404.07	3629281.19	1.63	NG
1301	219393.05	3629281.21	1.51	NG
1302	219382.41	3629281.20	1.07	NG
1303	219370.75	3629281.27	0.23	WES
1304	219402.97	3628784.78	0.27	WES
1305	219417.98	3628784.82	1.13	NG
1306	219432.24	3628784.81	1.45	NG
1307	219444.18	3628784.81	1.80	NG
1308	219454.75	3628784.82	2.39	NG
1309	219463.75	3628784.84	3.22	NG
1310	219467.09	3628784.83	4.96	NG
1311	219470.45	3628784.99	6.34	NG
1312	219473.95	3628784.86	4.55	NG
1313	219476.12	3628784.93	1.75	NG
1314	219481.99	3628784.93	0.55	NG
1315	219495.58	3628784.92	-0.08	NG
1316	219503.06	3628784.95	-0.51	WES
1317	219536.18	3628286.85	-0.49	WES
1318	219521.77	3628286.82	-0.29	NG
1319	219510.60	3628286.79	0.19	NG
1320	219501.48	3628286.77	0.85	NG
1321	219494.88	3628286.69	6.49	NG
1322	219487.33	3628286.69	4.14	NG
1323	219477.23	3628286.68	2.79	NG
1324	219468.37	3628286.70	2.08	NG
1325	219459.73	3628286.65	1.65	NG
1326	219448.32	3628286.57	1.24	NG
1327	219432.79	3628286.55	0.29	WES
1328	219462.90	3627788.98	0.27	WES
1329	219478.94	3627788.96	1.14	NG
1330	219494.77	3627789.03	1.48	NG
1331	219507.96	3627789.00	2.05	NG
1332	219519.42	3627789.05	3.02	NG
1333	219524.08	3627788.99	4.41	NG
1334	219528.35	3627789.09	6.17	NG
1335	219532.96	3627789.14	3.70	NG

West Belle Pass Headland Restoration - RTK Survey

RTK Pt No	Northing	Easting	Elevation	Description
1336	219536.06	3627789.09	1.05	NG
1337	219548.14	3627789.06	0.26	NG
1338	219560.10	3627789.14	-0.35	WES
1339	219595.56	3627284.54	-0.32	WES
1340	219583.74	3627284.53	0.20	NG
1341	219572.29	3627284.52	1.04	NG
1342	219566.33	3627284.57	3.27	NG
1343	219559.25	3627284.66	6.84	NG
1344	219553.46	3627284.59	4.93	NG
1345	219540.75	3627284.60	2.95	NG
1346	219529.63	3627284.67	2.35	NG
1347	219517.49	3627284.63	1.98	NG
1348	219505.46	3627284.65	1.73	NG
1349	219491.74	3627284.66	1.22	NG
1350	219475.52	3627284.69	1.06	NG
1351	219460.83	3627284.72	1.12	NG
1352	219446.14	3627284.72	0.93	NG
1353	219432.08	3627284.71	0.93	NG
1354	219519.86	3626784.83	0.88	WES
1355	219537.51	3626784.78	1.72	NG
1356	219552.81	3626784.85	2.55	NG
1357	219568.07	3626784.82	3.33	NG
1358	219581.50	3626784.82	4.57	NG
1359	219591.28	3626784.81	6.75	NG
1360	219599.56	3626784.83	4.41	NG
1361	219606.73	3626784.80	1.53	NG
1362	219621.94	3626784.83	0.27	NG
1363	219637.55	3626784.80	-0.23	WES
1364	219741.03	3626284.90	-0.22	WES
1365	219723.34	3626284.87	-0.10	NG
1366	219709.57	3626284.84	-0.07	NG
1367	219692.44	3626284.86	-0.01	NG
1368	219677.85	3626284.88	0.10	NG
1369	219657.66	3626284.86	0.67	NG
1370	219644.28	3626284.85	2.21	NG
1371	219635.17	3626284.86	4.02	NG
1372	219627.62	3626284.81	6.89	NG
1373	219623.49	3626284.82	4.99	NG
1374	219613.18	3626284.85	3.59	NG
1375	219600.76	3626284.86	2.96	NG
1376	219588.39	3626284.87	2.35	NG
1377	219575.49	3626284.88	1.70	NG
1378	219560.77	3626284.84	0.78	WES
1379	219632.19	3626280.78	4.64	NG

West Belle Pass Headland Restoration - RTK Survey

RTK Pt No	Northing	Easting	Elevation	Description
1380	219631.41	3626280.31	9.84	SP-5
1381	219753.57	3625786.09	-0.24	WES
1382	219736.78	3625786.10	-0.10	NG
1383	219727.26	3625786.01	-0.02	NG
1384	219703.33	3625786.08	0.17	NG
1385	219685.28	3625786.03	1.11	NG
1386	219667.96	3625785.97	3.02	NG
1387	219658.31	3625786.14	4.83	NG
1388	219653.48	3625785.54	7.06	NG
1389	219653.65	3625785.41	7.07	NG
1390	219650.52	3625785.80	5.52	NG
1391	219646.84	3625785.85	4.33	NG
1392	219627.50	3625785.96	2.87	NG
1393	219607.55	3625785.90	1.74	NG
1394	219598.14	3625785.83	1.18	NG
1395	219624.37	3625282.29	0.88	WES
1396	219629.18	3625281.77	1.23	NG
1397	219646.13	3625281.84	2.20	NG
1398	219666.19	3625281.91	3.44	NG
1399	219678.68	3625282.09	4.67	NG
1400	219681.32	3625282.53	6.10	NG
1401	219684.68	3625281.87	6.67	NG
1402	219689.14	3625282.11	5.20	NG
1403	219700.12	3625281.71	3.06	NG
1404	219718.67	3625281.51	0.51	NG
1405	219738.36	3625281.88	-0.14	NG
1406	219757.26	3625281.85	-0.18	NG
1407	219766.45	3625281.62	-0.19	WES
1408	219804.89	3624785.90	-0.14	WES
1409	219783.54	3624786.02	-0.07	NG
1410	219758.33	3624785.89	0.39	NG
1411	219744.55	3624785.89	1.65	NG
1412	219728.56	3624786.16	2.93	NG
1413	219722.40	3624786.17	5.46	NG
1414	219716.12	3624786.05	7.39	NG
1415	219712.00	3624786.19	5.82	NG
1416	219707.83	3624785.77	4.15	NG
1417	219689.57	3624785.86	2.81	NG
1418	219667.24	3624785.73	1.88	NG
1419	219653.74	3624785.75	0.91	WES
1420	219679.48	3624287.92	1.18	WES
1421	219695.18	3624287.86	1.75	NG
1422	219716.11	3624287.88	2.42	NG
1423	219736.31	3624287.98	2.89	NG

West Belle Pass Headland Restoration - RTK Survey

RTK Pt No	Northing	Easting	Elevation	Description
1424	219754.69	3624288.03	4.09	NG
1425	219760.68	3624287.98	4.74	NG
1426	219764.51	3624287.67	6.14	NG
1427	219770.20	3624287.83	7.55	NG
1428	219776.75	3624287.94	6.82	NG
1429	219784.14	3624287.90	3.57	NG
1430	219798.74	3624287.98	1.98	NG
1431	219818.93	3624287.79	0.42	NG
1432	219839.08	3624287.85	-0.05	NG
1433	219849.34	3624288.17	-0.16	WES
1434	219900.53	3623781.80	-0.12	WES
1435	219888.63	3623781.96	0.49	NG
1436	219881.76	3623781.89	1.36	NG
1437	219880.28	3623781.81	5.67	NG
1438	219870.43	3623782.08	3.65	NG
1439	219857.34	3623781.80	2.33	NG
1440	219843.86	3623782.08	1.56	WES
1441	219929.60	3623284.57	-0.06	WES
1442	220039.39	3623284.54	-0.32	WB
1443	220026.86	3623284.57	-0.29	WB
1444	220014.22	3623284.56	-0.34	WB
1445	220002.14	3623284.51	-0.31	WB
1446	219990.22	3623284.51	-0.30	WB
1447	219976.02	3623284.51	-0.37	WB
1448	219962.50	3623284.51	-0.34	WB
1449	219948.52	3623284.47	-0.17	WB
1450	219936.45	3623284.52	-0.10	WB
1451	219909.69	3623284.48	0.02	NG
1452	219896.33	3623284.46	0.26	NG
1453	219883.63	3623284.41	0.39	NG
1454	219870.03	3623284.44	0.80	NG
1455	219856.90	3623284.44	1.88	NG
1456	219844.36	3623284.47	1.96	NG
1457	219831.09	3623284.46	2.84	NG
1458	219821.33	3623284.42	4.11	NG
1459	219815.70	3623284.42	5.77	NG
1460	219812.59	3623284.38	7.33	NG
1461	219808.27	3623284.36	5.96	NG
1462	219796.65	3623284.42	3.94	NG
1463	219782.29	3623284.39	3.08	NG
1464	219767.80	3623284.40	2.57	NG
1465	219752.06	3623284.37	1.99	WES
1466	220043.78	3622783.61	-0.17	WB
1467	220031.89	3622783.75	-0.10	WB

West Belle Pass Headland Restoration - RTK Survey

RTK Pt No	Northing	Easting	Elevation	Description
1468	220019.10	3622783.63	-0.07	WB
1469	220004.19	3622783.59	-0.09	WB
1470	219990.21	3622783.71	-0.09	WB
1471	219978.07	3622783.67	-0.02	WB
1472	219962.84	3622783.76	0.00	WB
1473	219945.03	3622783.78	0.07	WES
1474	219929.01	3622783.79	0.11	NG
1475	219911.42	3622783.78	0.38	NG
1476	219895.71	3622783.85	0.65	NG
1477	219864.48	3622783.85	1.40	NG
1478	219850.97	3622783.85	2.52	NG
1479	219833.72	3622783.91	2.79	NG
1480	219820.00	3622783.94	2.70	NG
1481	219805.15	3622783.96	2.50	NG
1482	219791.59	3622784.02	2.53	NG
1483	219774.88	3622783.99	2.30	NG
1484	219759.19	3622783.99	2.09	NG
1485	219740.95	3622784.06	1.86	NG
1486	219719.74	3622784.03	2.00	NG
1487	219701.45	3622784.21	2.76	NG
1488	219686.35	3622784.16	2.85	NG
1489	219663.58	3622784.18	2.17	NG
1490	219639.94	3622784.15	2.72	NG
1491	219613.47	3622784.29	2.66	NG
1492	219589.16	3622784.30	2.80	NG
1493	219563.76	3622784.30	2.18	NG
1494	219537.61	3622784.35	2.37	NG
1495	219510.83	3622784.42	2.06	NG
1496	219486.72	3622784.51	2.11	NG
1497	219473.44	3622784.42	1.99	NG
1498	219445.44	3622784.54	1.91	NG
1499	219427.60	3622784.57	1.80	NG
1500	219411.59	3622784.62	1.75	NG
1501	219389.45	3622784.63	1.61	NG
1502	219367.86	3622784.55	1.50	NG
1503	219345.60	3622784.68	1.42	NG
1504	219322.16	3622784.76	1.30	NG
1505	219301.24	3622784.76	1.19	NG
1506	219281.40	3622784.78	1.11	NG
1507	219255.20	3622784.83	1.03	NG
1508	219229.47	3622784.91	0.93	NG
1509	219208.57	3622784.94	0.89	NG
1510	219179.25	3622784.91	0.84	NG
1511	219157.75	3622785.00	0.75	NG

West Belle Pass Headland Restoration - RTK Survey

RTK Pt No	Northing	Easting	Elevation	Description
1512	219135.62	3622785.02	0.67	NG
1513	219112.09	3622785.08	0.63	NG
1514	219091.76	3622785.09	0.56	NG
1515	219073.13	3622785.12	0.51	NG
1516	219050.83	3622785.12	0.49	NG
1517	219031.93	3622785.14	0.46	NG
1518	219003.48	3622785.26	0.40	NG
1519	218965.41	3622785.25	0.41	NG
1520	218945.37	3622785.24	0.33	NG
1521	218911.18	3622785.32	0.21	NG
1522	218891.34	3622785.37	0.18	NG
1523	218865.89	3622785.43	0.17	NG
1524	218841.00	3622785.48	0.23	NG
1525	218815.67	3622785.55	-0.06	WES
1526	218792.20	3622785.48	0.05	WB
1527	218771.70	3622785.51	0.10	WB
1528	218749.52	3622785.56	-0.18	WB
1529	218731.70	3622785.64	-0.06	WB
1530	218707.48	3622785.68	-0.21	WB
1531	218680.68	3622785.67	-0.34	WB
1532	218661.59	3622785.81	-0.43	WB
1533	218641.72	3622785.80	-0.14	WB
1534	218622.31	3622785.86	-0.17	WB
1535	218603.80	3622785.89	-0.24	WB
1536	218576.53	3622785.90	-0.09	WB
1537	218553.61	3622785.93	0.10	WB
1538	218531.33	3622785.98	0.21	WES
1539	218511.70	3622786.11	0.33	NG
1540	218491.16	3622786.07	0.49	NG
1541	218473.06	3622786.01	0.83	NG
1542	218454.39	3622786.03	0.96	NG
1543	218429.60	3622786.12	1.10	NG
1544	218410.10	3622786.19	1.06	NG
1545	218381.81	3622786.03	1.14	NG
1546	218365.10	3622786.25	1.19	NG
1547	218341.40	3622786.26	1.29	NG
1548	218319.00	3622786.24	1.34	NG
1549	218288.61	3622786.40	1.42	NG
1550	218271.73	3622786.38	1.44	NG
1551	218253.36	3622786.33	1.48	NG
1552	218236.73	3622786.40	1.54	NG
1553	218218.91	3622786.38	1.63	NG
1554	218202.78	3622786.46	1.63	NG
1555	218171.51	3622786.47	1.69	NG

West Belle Pass Headland Restoration - RTK Survey

RTK Pt No	Northing	Easting	Elevation	Description
1556	218152.13	3622786.56	1.65	NG
1557	218124.53	3622786.63	1.76	NG
1558	218106.14	3622786.65	1.80	NG
1559	218088.99	3622786.70	1.84	NG
1560	218065.42	3622786.75	1.92	NG
1561	218044.20	3622786.69	1.95	NG
1562	218026.09	3622786.77	2.00	NG
1563	218006.42	3622786.78	2.22	NG
1564	217986.28	3622786.82	2.27	NG
1565	217961.27	3622786.87	2.43	NG
1566	217932.26	3622786.98	2.69	NG
1567	217898.31	3622786.99	3.01	NG
1568	217875.42	3622787.01	2.84	NG
1569	217853.81	3622787.00	3.02	NG
1570	217833.16	3622787.05	2.53	NG
1571	217803.55	3622787.14	1.59	NG
1572	217785.42	3622787.09	1.61	NG
1573	218840.34	3634997.54	1.47	CHK
1574	220121.30	3622283.50	-1.64	WB
1575	220106.05	3622283.31	-1.61	WB
1576	220088.27	3622279.94	-1.66	WB
1577	220068.10	3622279.94	-1.63	WB
1578	220051.51	3622280.98	-1.69	WB
1579	220034.87	3622282.87	-1.56	WB
1580	220019.36	3622286.05	-1.55	WB
1581	219997.80	3622283.71	-1.51	WB
1582	219978.02	3622283.76	-1.43	WB
1583	219958.62	3622283.68	-1.35	WB
1584	219936.68	3622283.40	-1.27	WB
1585	219917.20	3622283.84	-1.28	WB
1586	219898.60	3622284.02	-1.22	WB
1587	219879.70	3622283.55	-1.17	WB
1588	219864.53	3622283.48	-1.05	WES
1589	219848.26	3622283.92	-0.94	NG
1590	219833.31	3622284.01	-0.86	NG
1591	219815.41	3622284.02	-0.90	NG
1592	219797.28	3622284.04	-1.00	NG
1593	219778.56	3622284.11	-0.99	NG
1594	219755.32	3622283.83	-0.75	NG
1595	219736.12	3622283.95	-0.57	NG
1596	219715.50	3622284.05	-0.40	NG
1597	219695.28	3622284.20	-0.31	NG
1598	219671.41	3622284.17	-0.08	NG
1599	219649.23	3622284.15	0.06	NG

West Belle Pass Headland Restoration - RTK Survey

RTK Pt No	Northing	Easting	Elevation	Description
1600	219627.21	3622284.15	0.07	NG
1601	219605.35	3622284.17	-0.18	NG
1602	219583.44	3622284.17	-0.31	NG
1603	219560.68	3622284.35	-0.40	NG
1604	219539.79	3622284.71	-0.37	NG
1605	219517.80	3622284.43	-0.22	NG
1606	219496.39	3622284.48	-0.06	NG
1607	219472.99	3622284.39	0.07	NG
1608	219450.58	3622284.34	0.14	NG
1609	219425.50	3622284.57	0.28	NG
1610	219401.87	3622284.75	0.34	NG
1611	219379.50	3622284.61	0.28	NG
1612	219355.38	3622284.75	0.53	NG
1613	219333.89	3622284.79	0.39	NG
1614	219312.07	3622284.96	-0.08	NG
1615	219289.96	3622284.77	-0.15	NG
1616	219269.37	3622285.35	-0.24	NG
1617	219247.95	3622285.03	-0.31	NG
1618	219226.72	3622284.81	-0.30	NG
1619	219204.11	3622285.02	-0.34	NG
1620	219179.51	3622284.81	-0.44	NG
1621	219155.04	3622284.95	-0.46	NG
1622	219129.74	3622285.48	-0.52	NG
1623	219105.80	3622285.25	-0.46	NG
1624	219080.59	3622285.13	-0.46	NG
1625	219056.20	3622285.08	-0.43	NG
1626	219031.36	3622285.20	-0.28	NG
1627	219007.19	3622285.25	-0.27	NG
1628	218983.94	3622285.60	-0.22	NG
1629	218960.85	3622285.57	-0.10	NG
1630	218933.58	3622285.78	-0.04	NG
1631	218907.83	3622285.53	0.02	NG
1632	218889.06	3622285.92	-0.01	NG
1633	218865.73	3622285.59	-0.17	NG
1634	218842.14	3622285.69	-0.07	NG
1635	218821.29	3622285.73	-0.43	WES
1636	218808.54	3622285.34	-1.59	WB
1637	218717.04	3622286.34	-2.19	WB
1638	218702.78	3622286.18	-0.46	WES
1639	218676.89	3622285.95	0.14	NG
1640	218650.27	3622285.88	0.20	NG
1641	218626.42	3622285.95	0.16	NG
1642	218603.79	3622286.19	0.07	NG
1643	218581.00	3622286.01	0.39	NG

West Belle Pass Headland Restoration - RTK Survey

RTK Pt No	Northing	Easting	Elevation	Description
1644	218561.30	3622285.99	0.54	NG
1645	218541.82	3622286.30	0.71	NG
1646	218520.98	3622286.08	0.78	NG
1647	218498.59	3622286.08	0.90	NG
1648	218479.24	3622286.37	0.95	NG
1649	218456.32	3622286.28	0.97	NG
1650	218435.61	3622286.64	1.00	NG
1651	218413.29	3622286.49	1.03	NG
1652	218390.58	3622286.42	1.05	NG
1653	218368.38	3622286.22	1.08	NG
1654	218346.35	3622286.62	1.09	NG
1655	218324.71	3622286.31	1.19	NG
1656	218302.40	3622286.45	1.59	NG
1657	218277.95	3622286.85	1.38	NG
1658	218255.40	3622287.00	1.47	NG
1659	218232.34	3622286.97	1.74	NG
1660	218210.23	3622286.56	1.86	NG
1661	218190.30	3622286.84	2.00	NG
1662	218166.75	3622287.16	1.92	NG
1663	218142.58	3622286.78	2.07	NG
1664	218119.04	3622286.95	2.11	NG
1665	218092.68	3622286.90	2.31	NG
1666	218068.19	3622287.03	2.53	NG
1667	218043.62	3622287.07	2.60	NG
1668	218019.86	3622287.14	2.66	NG
1669	217997.92	3622287.25	2.79	NG
1670	217973.61	3622287.34	2.81	NG
1671	217951.56	3622287.42	2.82	NG
1672	218071.56	3621783.32	2.42	NG
1673	218092.13	3621783.14	2.66	NG
1674	218112.32	3621783.07	2.59	NG
1675	218134.63	3621783.11	2.45	NG
1676	218157.30	3621783.21	2.28	NG
1677	218181.55	3621783.43	1.98	NG
1678	218204.04	3621783.14	2.04	NG
1679	218227.81	3621783.25	2.30	NG
1680	218246.83	3621782.96	2.31	NG
1681	218268.83	3621782.78	2.30	NG
1682	218288.29	3621782.73	2.33	NG
1683	218310.19	3621782.90	2.17	NG
1684	218329.50	3621782.80	2.17	NG
1685	218350.64	3621782.80	2.05	NG
1686	218369.90	3621782.79	1.94	NG
1687	218390.58	3621782.41	1.86	NG

West Belle Pass Headland Restoration - RTK Survey

RTK Pt No	Northing	Easting	Elevation	Description
1688	218412.69	3621782.55	1.69	NG
1689	218435.28	3621782.75	1.45	NG
1690	218458.66	3621782.51	1.14	NG
1691	218482.08	3621782.46	0.67	NG
1692	218503.90	3621782.49	0.24	NG
1693	218526.66	3621782.39	0.14	NG
1694	218549.93	3621782.19	0.06	NG
1695	218570.94	3621782.57	-0.14	NG
1696	218586.84	3621782.53	-0.42	NG
1697	218602.81	3621782.38	-0.42	NG
1698	218623.02	3621782.59	-0.29	NG
1699	218644.76	3621782.22	-0.18	NG
1700	218667.73	3621782.80	0.02	NG
1701	218691.42	3621782.34	0.32	NG
1702	218714.88	3621782.36	1.05	NG
1703	218732.44	3621782.47	1.85	NG
1704	218755.98	3621782.30	1.84	NG
1705	218780.29	3621782.13	1.63	NG
1706	218803.71	3621782.06	1.44	NG
1707	218825.77	3621782.19	1.29	NG
1708	218850.26	3621781.86	1.10	NG
1709	218872.78	3621781.78	0.91	NG
1710	218894.45	3621781.84	0.81	NG
1711	218917.23	3621781.69	0.75	NG
1712	218939.43	3621781.83	0.75	NG
1713	218960.61	3621782.00	0.69	NG
1714	218984.22	3621781.64	0.42	NG
1715	219005.13	3621781.89	0.24	NG
1716	219025.90	3621781.81	0.19	NG
1717	219047.43	3621781.68	0.28	NG
1718	219068.89	3621781.34	0.90	NG
1719	219091.49	3621781.51	0.48	NG
1720	219113.98	3621781.19	0.02	NG
1721	219136.45	3621781.56	-0.12	NG
1722	219158.57	3621781.43	-0.27	NG
1723	219181.46	3621781.53	-0.28	NG
1724	219204.21	3621781.29	-0.19	NG
1725	219227.72	3621781.45	-0.26	NG
1726	219249.82	3621781.20	-0.23	NG
1727	219272.02	3621781.09	-0.24	NG
1728	219295.37	3621781.32	-0.35	NG
1729	219318.68	3621780.98	-0.36	NG
1730	219340.53	3621781.11	-0.39	NG
1731	219363.07	3621780.56	-0.40	NG

West Belle Pass Headland Restoration - RTK Survey

RTK Pt No	Northing	Easting	Elevation	Description
1732	219385.55	3621781.03	-0.55	NG
1733	219408.29	3621780.86	-0.53	NG
1734	219430.15	3621781.38	-0.61	NG
1735	219454.69	3621781.16	-0.69	NG
1736	219476.27	3621781.15	-0.75	NG
1737	219498.93	3621781.02	-0.86	NG
1738	219523.38	3621780.98	-0.92	WES
1739	219547.17	3621780.87	-1.03	WB
1740	219571.48	3621780.70	-1.10	WB
1741	219589.64	3621780.72	-1.26	WB
1742	219612.25	3621780.52	-1.32	WB
1743	219627.38	3621780.86	-1.40	WB
1744	219647.98	3621781.33	-1.50	WB
1745	220141.62	3621777.96	-1.21	WB
1746	220118.24	3621780.86	-1.20	WB
1747	220101.33	3621781.56	-1.25	WB
1748	220085.83	3621783.38	-1.20	WB
1749	220069.82	3621784.06	-1.24	WB
1750	220045.96	3621784.59	-1.24	WB
1751	220034.61	3621784.96	-0.65	WB
1752	220006.82	3621784.40	-1.19	WB
1753	219996.94	3621785.25	-1.08	WB
1754	219969.97	3621784.47	-1.22	WB
1755	219956.60	3621784.25	-1.11	WB
1756	219938.91	3621784.43	-1.18	WB
1757	219878.18	3621785.66	-1.35	WB
1758	219877.11	3621785.82	-1.33	WB
1759	219855.03	3621785.07	-1.54	WB
1760	219816.31	3621785.68	-0.20	WB
1761	219804.41	3621784.98	-1.24	WB
1762	219775.08	3621785.18	-1.45	WB
1763	219747.81	3621783.31	-1.48	WB
1764	219719.12	3621782.17	-1.47	WB
1765	219690.78	3621781.41	-1.72	WB
1766	219663.78	3621781.36	-1.71	WB
1767	220178.07	3621275.83	-2.15	WB
1768	220159.88	3621275.99	-2.18	WB
1769	220141.85	3621275.18	-2.04	WB
1770	220124.65	3621275.61	-1.87	WB
1771	220104.81	3621275.61	-1.93	WB
1772	220089.32	3621276.46	-1.84	WB
1773	220066.32	3621277.07	-2.09	WB
1774	220047.75	3621278.58	-1.80	WB
1775	220027.92	3621277.58	-1.82	WB

West Belle Pass Headland Restoration - RTK Survey

RTK Pt No	Northing	Easting	Elevation	Description
1776	220008.25	3621275.98	-1.77	WB
1777	219986.49	3621275.33	-1.88	WB
1778	219950.99	3621276.52	-1.69	WB
1779	219933.59	3621276.97	-1.66	WB
1780	219912.67	3621277.80	-1.72	WB
1781	219894.03	3621277.84	-1.71	WB
1782	219876.70	3621278.20	-1.78	WB
1783	219859.74	3621277.39	-1.92	WB
1784	219841.42	3621276.53	-1.99	WB
1785	219817.38	3621277.43	-1.85	WB
1786	219798.27	3621278.04	-2.05	WB
1787	219780.98	3621278.55	-2.02	WB
1788	219763.84	3621277.24	-2.09	WB
1789	219747.62	3621276.38	-2.19	WB
1790	219733.48	3621276.24	-2.04	WB
1791	219713.98	3621276.93	-2.04	WB
1792	219700.33	3621276.99	-2.17	WB
1793	219685.44	3621278.43	-1.84	WB
1794	219670.70	3621278.71	-1.58	WB
1795	219658.51	3621278.37	-1.32	WB
1796	219642.71	3621278.66	-1.15	WB
1797	219626.06	3621278.92	-1.05	WB
1798	219609.64	3621277.70	-0.98	WB
1799	219592.21	3621277.95	-0.97	WB
1800	219571.89	3621278.30	-0.90	WES
1801	219555.25	3621278.53	-0.91	NG
1802	219536.94	3621278.56	-0.90	NG
1803	219521.72	3621278.62	-0.88	NG
1804	219507.82	3621278.58	-0.86	NG
1805	219495.27	3621278.65	-0.84	NG
1806	219480.76	3621278.64	-0.77	NG
1807	219465.08	3621278.70	-0.76	NG
1808	219452.25	3621278.77	-0.76	NG
1809	219439.50	3621278.76	-0.80	NG
1810	219425.38	3621278.77	-0.79	NG
1811	219412.96	3621278.78	-0.82	NG
1812	219399.93	3621278.82	-0.72	NG
1813	219382.76	3621278.92	-0.74	NG
1814	219366.79	3621278.89	-0.69	NG
1815	219351.20	3621278.91	-0.62	NG
1816	219332.77	3621278.99	-0.55	NG
1817	219317.01	3621279.01	-0.54	NG
1818	219302.28	3621279.08	-0.49	NG
1819	219285.11	3621279.10	-0.47	NG

West Belle Pass Headland Restoration - RTK Survey

RTK Pt No	Northing	Easting	Elevation	Description
1820	219267.88	3621279.04	-0.40	NG
1821	219251.73	3621279.16	-0.33	NG
1822	219232.63	3621279.23	-0.26	NG
1823	219215.75	3621279.20	-0.21	NG
1824	219199.69	3621279.25	-0.19	NG
1825	219181.82	3621279.32	-0.15	NG
1826	219162.54	3621279.35	-0.08	NG
1827	219145.53	3621279.37	-0.01	NG
1828	219127.96	3621279.43	0.11	NG
1829	219107.61	3621279.44	0.18	NG
1830	219081.03	3621279.53	0.38	NG
1831	219061.55	3621279.60	0.50	NG
1832	219045.58	3621279.61	0.82	NG
1833	219030.77	3621279.62	1.00	NG
1834	219014.21	3621279.67	1.13	NG
1835	218994.01	3621279.71	1.22	NG
1836	218971.77	3621279.75	1.31	NG
1837	218952.05	3621279.81	1.42	NG
1838	218923.84	3621279.87	1.47	NG
1839	218907.20	3621279.86	1.46	NG
1840	218884.10	3621279.95	1.47	NG
1841	218837.46	3621280.04	1.41	NG
1842	218812.36	3621280.12	1.34	NG
1843	218785.71	3621280.17	1.27	NG
1844	218767.32	3621280.18	1.18	NG
1845	218737.90	3621280.28	1.00	NG
1846	218719.97	3621280.29	0.83	NG
1847	218703.29	3621280.33	0.77	NG
1848	218684.81	3621280.37	0.65	NG
1849	218664.77	3621280.39	0.62	NG
1850	218647.99	3621280.48	0.69	NG
1851	218633.41	3621280.51	0.77	NG
1852	218617.18	3621280.51	0.80	NG
1853	218596.79	3621280.55	0.76	NG
1854	218578.45	3621280.59	0.75	NG
1855	218560.61	3621280.59	0.79	NG
1856	218543.52	3621280.62	0.75	NG
1857	218525.08	3621280.68	0.78	NG
1858	218508.00	3621280.73	0.75	NG
1859	218494.83	3621280.84	0.76	NG
1860	218478.29	3621280.78	0.85	NG
1861	218461.98	3621280.85	1.02	NG
1862	218443.10	3621280.90	1.11	NG
1863	218426.02	3621280.90	1.13	NG

West Belle Pass Headland Restoration - RTK Survey

RTK Pt No	Northing	Easting	Elevation	Description
1864	218405.69	3621280.96	1.16	NG
1865	218387.53	3621281.00	1.17	NG
1866	218367.24	3621281.05	1.21	NG
1867	218347.65	3621281.11	1.22	NG
1868	218330.25	3621281.13	1.64	NG
1869	218307.39	3621281.18	2.10	NG
1870	218288.92	3621281.19	2.17	NG
1871	218270.05	3621281.26	2.33	NG
1872	218241.07	3621281.29	2.97	NG
1873	218346.42	3620780.60	1.01	NG
1874	218365.33	3620780.60	1.61	NG
1875	218379.11	3620778.18	2.30	NG
1876	218403.12	3620780.40	2.52	NG
1877	218428.97	3620780.45	2.14	NG
1878	218452.67	3620780.37	1.84	NG
1879	218478.88	3620780.34	1.78	NG
1880	218503.64	3620780.16	1.17	NG
1881	218528.27	3620780.18	1.14	NG
1882	218553.00	3620779.86	1.22	NG
1883	218578.07	3620779.99	1.22	NG
1884	218603.29	3620779.76	1.24	NG
1885	218629.18	3620779.72	1.09	NG
1886	218653.77	3620779.91	0.78	NG
1887	218679.92	3620779.71	0.27	NG
1888	218705.15	3620779.82	0.02	NG
1889	218731.25	3620779.51	0.01	NG
1890	218756.72	3620779.39	0.07	NG
1891	218782.34	3620779.39	0.04	NG
1892	218805.68	3620779.34	-0.01	NG
1893	218829.41	3620779.22	-0.05	NG
1894	218854.17	3620778.98	-0.01	NG
1895	218878.99	3620778.97	0.01	NG
1896	218904.10	3620779.09	0.01	NG
1897	218929.45	3620778.95	-0.01	NG
1898	218955.19	3620778.82	0.02	NG
1899	218980.59	3620778.70	-0.06	NG
1900	219004.87	3620778.86	-0.03	NG
1901	219029.17	3620778.69	0.02	NG
1902	219052.53	3620778.52	0.11	NG
1903	219075.62	3620778.59	0.15	NG
1904	219098.34	3620778.63	0.12	NG
1905	219122.97	3620778.28	0.13	NG
1906	219148.16	3620778.38	0.12	NG
1907	219173.17	3620778.27	0.06	NG

West Belle Pass Headland Restoration - RTK Survey

RTK Pt No	Northing	Easting	Elevation	Description
1908	219197.27	3620778.21	0.02	NG
1909	219221.23	3620777.94	-0.03	NG
1910	219245.87	3620778.29	-0.06	NG
1911	219270.87	3620777.85	-0.13	NG
1912	219293.96	3620777.89	-0.07	NG
1913	219317.99	3620777.69	-0.11	NG
1914	219341.95	3620777.92	-0.12	NG
1915	219366.61	3620777.90	-0.17	NG
1916	219391.90	3620777.77	-0.15	NG
1917	219416.93	3620777.51	-0.14	NG
1918	219441.92	3620777.56	-0.19	NG
1919	219464.51	3620777.65	-0.24	NG
1920	219488.13	3620777.19	-0.23	NG
1921	219512.78	3620777.24	-0.30	NG
1922	219537.60	3620777.46	-0.37	NG
1923	219559.92	3620777.14	-0.39	NG
1924	219589.80	3620777.11	-0.57	WES
1925	219606.06	3620777.07	-0.63	WB
1926	219624.78	3620776.99	-0.74	WB
1927	219643.34	3620777.00	-0.72	WB
1928	219661.61	3620776.92	-0.71	WB
1929	219680.38	3620776.87	-0.75	WB
1930	219701.28	3620776.82	-0.86	WB
1931	219718.84	3620776.66	-0.85	WB
1932	219733.74	3620776.68	-0.97	WB
1933	219751.52	3620776.67	-0.98	WB
1934	219769.60	3620776.65	-1.00	WB
1935	219788.64	3620776.59	-1.01	WB
1936	219805.37	3620776.50	-1.01	WB
1937	219822.36	3620776.46	-1.00	WB
1938	219842.76	3620776.41	-1.01	WB
1939	219859.46	3620776.34	-1.14	WB
1940	219879.80	3620776.31	-1.15	WB
1941	219897.04	3620776.24	-1.15	WB
1942	219912.11	3620776.20	-1.08	WB
1943	219933.94	3620776.10	-1.08	WB
1944	219955.63	3620776.06	-1.04	WB
1945	219971.54	3620776.09	-1.03	WB
1946	219991.25	3620776.04	-1.03	WB
1947	220016.78	3620775.92	-1.05	WB
1948	220036.64	3620775.89	-1.04	WB
1949	220057.53	3620775.82	-1.02	WB
1950	220076.60	3620775.72	-1.07	WB
1951	220092.99	3620775.69	-1.12	WB

West Belle Pass Headland Restoration - RTK Survey

RTK Pt No	Northing	Easting	Elevation	Description
1952	220108.04	3620775.58	-1.12	WB
1953	220119.85	3620775.61	-1.06	WB
1954	220134.10	3620775.54	-1.11	WB
1955	220150.18	3620775.52	-1.17	WB
1956	220169.52	3620276.12	-1.12	WB
1957	220156.70	3620276.14	-0.91	WB
1958	220141.82	3620276.21	-0.97	WB
1959	220127.18	3620276.19	-1.05	WB
1960	220112.21	3620276.26	-1.00	WB
1961	220094.01	3620276.31	-0.98	WB
1962	220079.44	3620276.36	-0.99	WB
1963	220062.41	3620276.38	-0.98	WB
1964	220045.11	3620276.46	-1.09	WB
1965	220024.15	3620276.48	-1.03	WB
1966	220007.33	3620276.52	-1.06	WB
1967	219988.63	3620276.54	-1.00	WB
1968	219969.75	3620276.58	-1.00	WB
1969	219949.17	3620276.62	-0.96	WB
1970	219929.01	3620276.75	-0.87	WB
1971	219911.04	3620276.73	-0.86	WB
1972	219894.53	3620276.83	-0.88	WB
1973	219876.98	3620276.85	-0.75	WB
1974	219858.26	3620276.87	-0.65	WB
1975	219838.63	3620276.85	-0.56	WB
1976	219821.87	3620276.99	-0.48	WB
1977	219796.36	3620277.09	-0.36	WB
1978	219770.27	3620277.07	-0.36	WB
1979	219738.99	3620277.34	-0.10	NG
1980	219707.74	3620277.10	-0.09	NG
1981	219680.83	3620277.17	-0.04	NG
1982	219654.88	3620277.64	0.02	NG
1983	219628.58	3620277.57	0.06	NG
1984	219602.58	3620277.64	0.04	NG
1985	219575.59	3620277.66	0.06	NG
1986	219548.32	3620277.58	0.00	NG
1987	219520.21	3620277.62	0.07	NG
1988	219492.10	3620277.78	0.09	NG
1989	219466.38	3620277.88	0.20	NG
1990	219439.75	3620277.97	0.15	NG
1991	219412.16	3620277.81	0.15	NG
1992	219385.37	3620278.16	0.14	NG
1993	219360.15	3620278.02	0.19	NG
1994	219333.03	3620278.19	0.04	NG
1995	219305.98	3620278.28	0.07	NG

West Belle Pass Headland Restoration - RTK Survey

RTK Pt No	Northing	Easting	Elevation	Description
1996	219279.82	3620278.23	0.13	NG
1997	219252.61	3620278.27	0.18	NG
1998	219226.33	3620278.30	0.18	NG
1999	219199.12	3620278.46	0.12	NG
2000	219172.50	3620278.80	0.09	NG
2001	219145.71	3620278.87	-0.20	NG
2002	219112.66	3620278.48	-0.17	NG
2003	219107.26	3620279.04	-0.26	WES
2004	219090.73	3620278.83	-0.51	WB
2005	219061.30	3620278.86	-0.20	WES
2006	219033.09	3620278.95	-0.08	NG
2007	219007.14	3620279.06	-0.08	NG
2008	218979.84	3620279.21	-0.06	NG
2009	218952.60	3620278.93	-0.17	NG
2010	218925.09	3620279.11	-0.12	NG
2011	218898.47	3620279.37	-0.10	NG
2012	218871.01	3620279.30	0.04	NG
2013	218844.77	3620279.44	0.43	NG
2014	218815.22	3620279.39	0.81	NG
2015	218790.25	3620279.55	0.87	NG
2016	218763.35	3620279.62	0.98	NG
2017	218737.40	3620279.77	1.10	NG
2018	218709.72	3620279.64	1.70	NG
2019	218686.94	3620279.74	1.53	NG
2020	218660.53	3620279.85	2.42	NG
2021	218633.41	3620279.72	2.24	NG
2022	218608.97	3620279.93	2.31	NG
2023	218583.05	3620280.06	2.40	NG
2024	220047.14	3623779.47	-1.64	WB
2025	220030.50	3623783.21	-1.65	WB
2026	220009.81	3623783.42	-1.72	WB
2027	219990.94	3623783.10	-1.80	WB
2028	219971.67	3623783.71	-1.23	WB
2029	219956.96	3623784.54	-1.05	WB
2030	219943.64	3623784.97	-0.80	WB
2031	219933.76	3623785.50	-0.60	WB
2032	219920.91	3623785.17	-0.53	WB
2033	219909.18	3623783.39	-0.32	WB
2034	220029.06	3624287.33	-0.71	WB
2035	220012.43	3624287.93	-0.72	WB
2036	219995.49	3624288.18	-0.72	WB
2037	219984.45	3624288.83	-0.69	WB
2038	219960.86	3624289.26	-0.69	WB
2039	219944.06	3624288.08	-0.67	WB

West Belle Pass Headland Restoration - RTK Survey

RTK Pt No	Northing	Easting	Elevation	Description
2040	219931.59	3624288.10	-0.64	WB
2041	219917.26	3624287.40	-0.43	WB
2042	219900.82	3624287.88	-0.30	WB
2043	219884.61	3624287.82	-0.26	WB
2044	219871.24	3624287.83	-0.20	WB
2045	219856.55	3624287.65	-0.14	WB
2046	220019.77	3624786.58	-0.51	WB
2047	220003.63	3624786.29	-0.47	WB
2048	219986.65	3624786.10	-0.51	WB
2049	219970.68	3624787.57	-0.53	WB
2050	219954.60	3624787.34	-0.54	WB
2051	219938.70	3624786.51	-0.59	WB
2052	219924.61	3624786.75	-0.58	WB
2053	219910.16	3624786.63	-0.57	WB
2054	219895.96	3624786.73	-0.56	WB
2055	219881.03	3624787.21	-0.62	WB
2056	219865.47	3624787.54	-0.64	WB
2057	219850.44	3624788.00	-0.66	WB
2058	219836.56	3624786.20	-0.64	WB
2059	219822.76	3624785.86	-0.41	WB
2060	219809.46	3624785.69	-0.22	WB
2061	220017.97	3625282.27	-0.80	WB
2062	220005.57	3625281.60	-0.74	WB
2063	219991.96	3625282.17	-0.73	WB
2064	219978.93	3625281.65	-0.76	WB
2065	219966.97	3625282.12	-0.83	WB
2066	219955.04	3625282.61	-0.74	WB
2067	219941.91	3625282.62	-0.74	WB
2068	219928.65	3625282.41	-0.74	WB
2069	219915.76	3625282.70	-0.69	WB
2070	219904.43	3625282.13	-0.66	WB
2071	219889.69	3625282.00	-0.64	WB
2072	219875.58	3625281.70	-0.64	WB
2073	219862.81	3625281.98	-0.63	WB
2074	219849.85	3625282.06	-0.57	WB
2075	219836.52	3625282.16	-0.58	WB
2076	219823.20	3625282.47	-0.58	WB
2077	219808.73	3625282.71	-0.36	WB
2078	219794.64	3625281.84	-0.28	WB
2079	219778.94	3625282.09	-0.22	WB
2080	220000.74	3625787.68	-0.71	WB
2081	219986.06	3625788.59	-0.67	WB
2082	219971.94	3625788.82	-0.64	WB
2083	219956.10	3625788.88	-0.58	WB

West Belle Pass Headland Restoration - RTK Survey

RTK Pt No	Northing	Easting	Elevation	Description
2084	219941.02	3625787.87	-0.62	WB
2085	219927.77	3625787.75	-0.65	WB
2086	219916.69	3625788.04	-0.64	WB
2087	219902.37	3625788.02	-0.60	WB
2088	219888.70	3625787.52	-0.55	WB
2089	219875.88	3625787.85	-0.66	WB
2090	219860.16	3625787.54	-0.58	WB
2091	219846.19	3625786.83	-0.58	WB
2092	219833.34	3625786.66	-0.54	WB
2093	219819.62	3625786.93	-0.60	WB
2094	219805.34	3625786.11	-0.56	WB
2095	219790.17	3625786.56	-0.47	WB
2096	219776.40	3625786.49	-0.37	WB
2097	219762.27	3625786.07	-0.28	WB
2098	219992.34	3626284.08	-0.64	WB
2099	219978.34	3626284.79	-0.55	WB
2100	219963.81	3626285.32	-0.65	WB
2101	219950.16	3626285.75	-0.71	WB
2102	219936.51	3626285.31	-0.64	WB
2103	219923.22	3626285.98	-0.59	WB
2104	219909.98	3626285.96	-0.57	WB
2105	219899.28	3626285.34	-0.69	WB
2106	219886.34	3626286.08	-0.58	WB
2107	219874.21	3626286.25	-0.49	WB
2108	219860.91	3626285.70	-0.54	WB
2109	219848.17	3626285.81	-0.47	WB
2110	219835.32	3626285.44	-0.51	WB
2111	219820.16	3626285.40	-0.44	WB
2112	219806.21	3626285.75	-0.42	WB
2113	219792.74	3626285.71	-0.47	WB
2114	219780.35	3626285.60	-0.55	WB
2115	219765.19	3626285.74	-0.43	WB
2116	219753.02	3626285.06	-0.24	WB
2117	219969.58	3626786.18	-1.14	WB
2118	219952.20	3626786.74	-1.04	WB
2119	219936.83	3626785.68	-1.19	WB
2120	219922.12	3626783.98	-1.21	WB
2121	219906.27	3626782.74	-1.07	WB
2122	219889.46	3626781.87	-1.08	WB
2123	219873.24	3626781.55	-1.02	WB
2124	219857.33	3626781.88	-1.15	WB
2125	219838.76	3626781.68	-1.06	WB
2126	219819.75	3626781.71	-1.13	WB
2127	219802.23	3626781.11	-1.14	WB

West Belle Pass Headland Restoration - RTK Survey

RTK Pt No	Northing	Easting	Elevation	Description
2128	219783.45	3626781.66	-1.10	WB
2129	219763.95	3626783.01	-0.93	WB
2130	219746.76	3626783.70	-1.15	WB
2131	219728.20	3626783.94	-0.72	WB
2132	219711.84	3626783.91	-0.65	WB
2133	219687.21	3626784.57	-0.39	WB
2134	219662.73	3626784.84	-0.37	WB
2135	219979.48	3627282.23	-1.79	WB
2136	219965.69	3627282.22	-1.35	WB
2137	219954.60	3627281.64	-1.80	WB
2138	219942.86	3627282.08	-1.73	WB
2139	219930.92	3627282.97	-1.68	WB
2140	219917.99	3627282.10	-1.60	WB
2141	219904.73	3627281.57	-1.63	WB
2142	219889.98	3627280.88	-1.54	WB
2143	219875.80	3627279.96	-1.57	WB
2144	219863.34	3627279.61	-1.54	WB
2145	219848.08	3627281.95	-1.52	WB
2146	219830.70	3627283.22	-1.52	WB
2147	219814.21	3627285.06	-1.67	WB
2148	219797.58	3627285.76	-1.58	WB
2149	219780.21	3627286.20	-1.45	WB
2150	219762.47	3627286.67	-1.41	WB
2151	219745.06	3627287.41	-1.21	WB
2152	219726.49	3627287.59	-1.27	WB
2153	219708.69	3627287.14	-1.04	WB
2154	219693.77	3627286.85	-1.07	WB
2155	219677.71	3627286.34	-1.02	WB
2156	219661.14	3627286.41	-1.06	WB
2157	219634.37	3627286.93	-1.46	WB
2158	219614.80	3627286.15	-0.73	WB
2159	219966.70	3627793.63	-2.15	WB
2160	219942.99	3627791.96	-2.08	WB
2161	219920.04	3627789.69	-2.07	WB
2162	219895.22	3627787.81	-2.22	WB
2163	219871.32	3627787.92	-2.05	WB
2164	219844.90	3627786.38	-1.99	WB
2165	219826.04	3627786.85	-2.06	WB
2166	219805.27	3627785.43	-1.93	WB
2167	219784.23	3627784.72	-1.75	WB
2168	219764.99	3627786.63	-1.66	WB
2169	219746.96	3627787.91	-1.75	WB
2170	219730.68	3627788.32	-1.65	WB
2171	219712.04	3627788.37	-1.68	WB

West Belle Pass Headland Restoration - RTK Survey

RTK Pt No	Northing	Easting	Elevation	Description
2172	219696.56	3627789.19	-1.59	WB
2173	219676.45	3627789.67	-1.28	WB
2174	219657.60	3627789.45	-1.18	WB
2175	219638.56	3627788.61	-1.08	WB
2176	219618.09	3627788.56	-0.91	WB
2177	219600.43	3627788.61	-0.95	WB
2178	219579.30	3627789.82	-0.64	WB
2179	219944.49	3628289.84	-2.32	WB
2180	219927.75	3628291.41	-2.32	WB
2181	219903.49	3628291.62	-2.16	WB
2182	219882.26	3628291.97	-2.13	WB
2183	219859.53	3628293.19	-2.15	WB
2184	219842.13	3628292.11	-2.25	WB
2185	219819.64	3628289.99	-2.24	WB
2186	219797.94	3628287.11	-2.15	WB
2187	219779.60	3628285.11	-2.11	WB
2188	219751.96	3628283.22	-2.05	WB
2189	219725.55	3628281.71	-2.13	WB
2190	219699.76	3628283.75	-1.96	WB
2191	219679.30	3628284.77	-2.12	WB
2192	219657.48	3628284.14	-2.11	WB
2193	219638.17	3628285.78	-1.64	WB
2194	219590.62	3628287.05	-1.25	WB
2195	219574.16	3628286.96	-0.98	WB
2196	219558.44	3628286.40	-0.76	WB
2197	219546.46	3628287.33	-0.58	WB
2198	219953.76	3628794.05	-2.11	WB
2199	219939.02	3628793.13	-2.06	WB
2200	219922.80	3628793.21	-2.14	WB
2201	219906.56	3628791.19	-2.08	WB
2202	219891.14	3628789.70	-2.04	WB
2203	219873.39	3628786.44	-2.25	WB
2204	219853.41	3628785.32	-2.18	WB
2205	219834.66	3628783.51	-2.06	WB
2206	219817.17	3628782.88	-2.09	WB
2207	219800.03	3628780.40	-2.05	WB
2208	219781.29	3628779.79	-2.21	WB
2209	219763.70	3628779.72	-2.03	WB
2210	219747.96	3628779.84	-2.07	WB
2211	219734.20	3628781.89	-2.12	WB
2212	219720.01	3628783.91	-2.13	WB
2213	219705.54	3628785.02	-1.96	WB
2214	219688.96	3628785.89	-2.01	WB
2215	219667.41	3628785.08	-1.88	WB

West Belle Pass Headland Restoration - RTK Survey

RTK Pt No	Northing	Easting	Elevation	Description
2216	219640.29	3628783.56	-1.94	WB
2217	219612.43	3628783.96	-1.88	WB
2218	219587.85	3628784.86	-1.54	WB
2219	219565.97	3628783.63	-1.23	WB
2220	219541.48	3628785.00	-1.11	WB
2221	219523.37	3628785.31	-0.89	WB
2222	219510.22	3628786.10	-0.65	WB
2223	219940.55	3629279.29	-2.03	WB
2224	219919.67	3629278.07	-2.14	WB
2225	219883.85	3629277.76	-2.00	WB
2226	219869.76	3629278.37	-1.88	WB
2227	219852.23	3629278.35	-2.32	WB
2228	219832.74	3629277.91	-1.98	WB
2229	219816.17	3629278.10	-1.81	WB
2230	219796.78	3629278.43	-2.06	WB
2231	219780.17	3629278.35	-1.88	WB
2232	219764.16	3629279.09	-1.89	WB
2233	219743.86	3629278.31	-1.87	WB
2234	219728.80	3629278.13	-2.11	WB
2235	219712.73	3629278.18	-1.84	WB
2236	219690.94	3629279.10	-1.85	WB
2237	219673.15	3629279.16	-1.88	WB
2238	219649.75	3629279.87	-1.73	WB
2239	219628.79	3629280.02	-1.74	WB
2240	219606.52	3629280.55	-1.72	WB
2241	219586.76	3629280.58	-1.87	WB
2242	219570.63	3629280.42	-1.82	WB
2243	219548.92	3629281.21	-1.57	WB
2244	219534.81	3629282.11	-1.56	WB
2245	219517.25	3629282.51	-1.16	WB
2246	219498.71	3629281.76	-0.80	WB
2247	218790.16	3622285.55	-2.51	WB
2248	218746.60	3622285.93	-3.32	WB
2249	218761.64	3624285.76	2.04	NG
2250	218761.44	3624285.70	7.51	SP-2
2251	218840.33	3634997.50	1.49	CHK
2252	219717.80	3623284.41	1.43	WB
2253	219744.51	3623284.41	1.19	WB
2254	219707.28	3623284.30	1.80	WES
2255	219683.93	3623284.36	2.11	NG
2256	219658.51	3623284.31	2.12	NG
2257	219639.26	3623284.34	2.20	NG
2258	219619.24	3623284.25	2.19	NG
2259	219598.84	3623284.23	2.38	NG

West Belle Pass Headland Restoration - RTK Survey

RTK Pt No	Northing	Easting	Elevation	Description
2260	219579.04	3623284.20	2.42	NG
2261	219559.26	3623284.25	2.40	NG
2262	219538.95	3623284.23	2.39	NG
2263	219516.45	3623284.32	2.38	NG
2264	219496.60	3623284.20	2.39	NG
2265	219476.38	3623284.21	2.39	NG
2266	219456.42	3623284.12	2.36	NG
2267	219436.18	3623284.14	2.34	NG
2268	219416.32	3623284.27	2.35	NG
2269	219397.09	3623284.16	2.37	NG
2270	219376.47	3623284.09	2.38	NG
2271	219355.76	3623284.17	2.38	NG
2272	219336.51	3623283.99	2.38	NG
2273	219316.82	3623284.17	2.39	NG
2274	219296.53	3623284.11	2.40	NG
2275	219276.95	3623284.19	2.44	NG
2276	219257.02	3623284.11	2.42	NG
2277	219236.43	3623283.97	2.44	NG
2278	219216.22	3623283.98	2.44	NG
2279	219196.84	3623284.05	2.68	NG
2280	219176.58	3623284.07	2.51	NG
2281	219156.44	3623284.09	2.55	NG
2282	219137.17	3623283.95	2.55	NG
2283	219116.45	3623284.09	2.58	NG
2284	219096.66	3623283.88	2.64	NG
2285	219076.98	3623283.93	2.85	NG
2286	219056.50	3623284.07	2.75	NG
2287	219036.04	3623283.85	2.74	NG
2288	219017.01	3623283.99	2.84	NG
2289	218995.73	3623283.95	2.86	NG
2290	218976.11	3623283.88	2.97	NG
2291	218956.57	3623284.02	3.11	NG
2292	218936.69	3623283.81	3.33	NG
2293	218916.79	3623283.83	3.44	NG
2294	218896.43	3623283.84	3.53	NG
2295	218876.10	3623283.86	3.61	NG
2296	218856.49	3623283.90	3.75	NG
2297	218836.39	3623283.76	3.78	NG
2298	218816.78	3623283.76	3.94	NG
2299	218795.91	3623283.84	4.32	NG
2300	218776.74	3623283.71	4.69	NG
2301	218756.64	3623283.89	4.93	NG
2302	218736.28	3623283.83	4.39	NG
2303	218716.99	3623283.71	4.73	NG

West Belle Pass Headland Restoration - RTK Survey

RTK Pt No	Northing	Easting	Elevation	Description
2304	218696.54	3623283.79	4.80	NG
2305	218676.91	3623283.68	4.86	NG
2306	218657.27	3623283.73	5.09	NG
2307	218636.44	3623283.82	5.30	NG
2308	218616.58	3623283.81	6.09	NG
2309	218596.89	3623283.79	6.13	NG
2310	218576.80	3623283.54	5.25	NG
2311	218556.47	3623283.78	4.71	NG
2312	218536.10	3623283.54	4.37	NG
2313	218516.88	3623283.59	4.08	NG
2314	218496.90	3623283.66	4.15	NG
2315	218476.61	3623283.60	3.87	NG
2316	218456.33	3623283.60	3.87	NG
2317	218437.25	3623283.46	3.74	NG
2318	218417.16	3623283.46	3.48	NG
2319	218397.18	3623283.48	3.36	NG
2320	218376.95	3623283.48	3.27	NG
2321	218356.76	3623283.55	3.05	NG
2322	218336.65	3623283.59	2.97	NG
2323	218316.82	3623283.55	3.03	NG
2324	218297.07	3623283.52	2.63	NG
2325	218276.48	3623283.40	2.59	NG
2326	218255.71	3623283.51	2.51	NG
2327	218237.05	3623283.38	2.36	NG
2328	218216.79	3623283.36	2.41	NG
2329	218196.30	3623283.50	2.20	NG
2330	218175.69	3623283.29	2.08	NG
2331	218156.81	3623283.32	2.02	NG
2332	218136.62	3623283.43	1.95	NG
2333	218116.51	3623283.32	1.95	NG
2334	218096.35	3623283.50	1.97	NG
2335	218076.78	3623283.31	1.84	NG
2336	218056.64	3623283.31	1.76	NG
2337	218036.16	3623283.31	1.70	NG
2338	218015.35	3623283.35	1.74	NG
2339	217996.47	3623283.32	1.81	NG
2340	217976.54	3623283.38	1.88	NG
2341	217955.92	3623283.37	2.00	NG
2342	217935.70	3623283.25	2.01	NG
2343	217916.60	3623283.22	2.05	NG
2344	217896.86	3623283.24	2.15	NG
2345	217876.69	3623283.27	2.27	NG
2346	217856.30	3623283.19	2.44	NG
2347	217836.44	3623283.24	2.65	NG

West Belle Pass Headland Restoration - RTK Survey

RTK Pt No	Northing	Easting	Elevation	Description
2348	217816.20	3623283.23	2.79	NG
2349	217796.77	3623283.12	3.01	NG
2350	217776.67	3623283.08	3.00	NG
2351	217759.52	3623283.20	2.64	NG
2352	217689.33	3623782.73	3.25	NG
2353	217709.79	3623782.75	2.84	NG
2354	217728.64	3623782.59	2.67	NG
2355	217747.77	3623782.71	2.30	NG
2356	217768.42	3623782.62	2.30	NG
2357	217789.32	3623782.63	2.60	NG
2358	217809.47	3623782.73	3.31	NG
2359	217828.69	3623782.63	5.53	NG
2360	217848.80	3623782.70	5.10	NG
2361	217869.32	3623782.55	6.15	NG
2362	217889.03	3623782.65	4.00	NG
2363	217908.48	3623782.60	3.94	NG
2364	217929.17	3623782.67	3.95	NG
2365	217950.02	3623782.60	3.95	NG
2366	217969.18	3623782.55	3.90	NG
2367	217989.29	3623782.68	3.76	NG
2368	218009.02	3623782.53	3.61	NG
2369	218028.96	3623782.50	3.43	NG
2370	218049.22	3623782.62	3.30	NG
2371	218068.57	3623782.59	3.17	NG
2372	218089.12	3623782.55	3.18	NG
2373	218109.19	3623782.53	3.07	NG
2374	218129.09	3623782.47	3.02	NG
2375	218148.36	3623782.53	3.01	NG
2376	218169.13	3623782.54	2.92	NG
2377	218189.35	3623782.55	2.87	NG
2378	218208.66	3623782.49	2.75	NG
2379	218229.06	3623782.54	2.62	NG
2380	218249.34	3623782.59	2.67	NG
2381	218268.74	3623782.53	2.55	NG
2382	218288.07	3623782.52	2.49	NG
2383	218309.30	3623782.48	2.46	NG
2384	218328.97	3623782.57	2.42	NG
2385	218348.43	3623782.49	2.37	NG
2386	218368.70	3623782.43	2.25	NG
2387	218389.27	3623782.42	2.13	NG
2388	218408.97	3623782.58	2.04	NG
2389	218428.54	3623782.55	1.96	NG
2390	218449.30	3623782.47	1.92	NG
2391	218468.08	3623782.45	1.88	NG

West Belle Pass Headland Restoration - RTK Survey

RTK Pt No	Northing	Easting	Elevation	Description
2392	218489.15	3623782.46	1.82	NG
2393	218508.18	3623782.36	1.80	NG
2394	218528.91	3623782.50	1.80	NG
2395	218548.36	3623782.43	1.72	NG
2396	218569.11	3623782.39	1.76	NG
2397	218588.47	3623782.44	1.77	NG
2398	218607.99	3623782.43	1.78	NG
2399	218629.15	3623782.33	1.78	NG
2400	218649.00	3623782.36	1.80	NG
2401	218668.79	3623782.34	1.84	NG
2402	218688.67	3623782.28	1.81	NG
2403	218708.75	3623782.29	1.79	NG
2404	218728.41	3623782.25	1.80	NG
2405	218748.57	3623782.34	1.81	NG
2406	218768.49	3623782.32	1.79	NG
2407	218788.47	3623782.28	1.79	NG
2408	218809.14	3623782.28	1.77	NG
2409	218829.23	3623782.21	1.79	NG
2410	218848.42	3623782.36	1.79	NG
2411	218868.35	3623782.37	1.77	NG
2412	218888.47	3623782.32	1.75	NG
2413	218908.55	3623782.24	1.75	NG
2414	218929.32	3623782.21	1.73	NG
2415	218949.81	3623782.15	1.74	NG
2416	218969.33	3623782.25	1.83	NG
2417	218988.27	3623782.21	1.94	NG
2418	219008.44	3623782.28	1.98	NG
2419	219028.58	3623782.18	1.97	NG
2420	219049.30	3623782.21	1.88	NG
2421	219069.19	3623782.14	1.72	NG
2422	219088.53	3623782.18	1.61	NG
2423	219099.60	3623782.23	1.52	WES
2424	219119.37	3623782.25	1.43	WB
2425	219138.88	3623782.14	1.38	WB
2426	219158.75	3623782.10	1.34	WB
2427	219178.71	3623782.15	1.29	WB
2428	219200.01	3623782.22	1.27	WB
2429	219218.06	3623782.26	1.25	WB
2430	219239.98	3623782.05	1.23	WB
2431	219259.80	3623782.19	1.20	WB
2432	219278.86	3623782.05	1.23	WB
2433	219299.75	3623782.07	1.24	WB
2434	219320.73	3623782.04	1.25	WB
2435	219342.18	3623782.14	1.25	WB

West Belle Pass Headland Restoration - RTK Survey

RTK Pt No	Northing	Easting	Elevation	Description
2436	219360.75	3623782.11	1.24	WB
2437	219380.76	3623781.99	1.27	WB
2438	219400.66	3623782.00	1.49	WB
2439	219415.47	3623781.95	1.53	WES
2440	219435.00	3623782.04	1.66	NG
2441	219455.38	3623782.09	1.76	NG
2442	219476.22	3623782.07	1.90	NG
2443	219496.29	3623782.00	2.01	NG
2444	219514.18	3623782.05	2.11	NG
2445	219535.80	3623782.02	2.27	NG
2446	219554.25	3623782.04	2.41	NG
2447	219575.61	3623782.08	2.60	NG
2448	219595.21	3623782.03	2.65	NG
2449	219616.10	3623782.02	2.36	NG
2450	219636.61	3623782.08	2.20	NG
2451	219655.04	3623782.07	1.92	NG
2452	219675.13	3623782.08	1.68	NG
2453	219695.95	3623782.03	1.60	NG
2454	219715.89	3623782.05	1.53	NG
2455	219722.32	3623782.01	1.49	WES
2456	219746.81	3623782.04	1.50	WB
2457	219765.46	3623781.95	1.34	WB
2458	219785.32	3623782.05	1.22	WB
2459	219804.70	3623781.97	1.12	WB
2460	219821.75	3623781.76	0.96	WB
2461	219698.24	3624288.08	1.88	NG
2462	219680.71	3624288.00	1.21	NG
2463	219654.33	3624287.67	1.36	NG
2464	219629.85	3624287.90	1.34	NG
2465	219603.98	3624288.05	1.44	NG
2466	219579.57	3624288.04	1.68	NG
2467	219551.64	3624287.83	1.75	NG
2468	219527.23	3624287.97	1.77	NG
2469	219501.57	3624287.78	1.80	NG
2470	219478.26	3624287.83	1.82	NG
2471	219452.65	3624287.94	1.67	NG
2472	219428.60	3624287.80	1.47	NG
2473	219408.26	3624287.83	1.40	NG
2474	219385.59	3624287.91	1.29	NG
2475	219363.40	3624287.83	1.30	NG
2476	219333.24	3624287.82	1.44	NG
2477	219309.80	3624287.81	1.70	NG
2478	219285.12	3624287.69	1.96	NG
2479	219259.32	3624287.67	2.19	NG

West Belle Pass Headland Restoration - RTK Survey

RTK Pt No	Northing	Easting	Elevation	Description
2480	219232.44	3624287.75	2.34	NG
2481	219207.79	3624287.63	2.46	NG
2482	219182.56	3624287.48	2.45	NG
2483	219157.16	3624287.67	2.33	NG
2484	219129.73	3624287.57	2.21	NG
2485	219104.53	3624287.58	2.09	NG
2486	219081.12	3624287.53	2.01	NG
2487	219057.34	3624287.39	1.98	NG
2488	219031.34	3624287.34	2.18	NG
2489	219004.90	3624287.31	2.33	NG
2490	218978.23	3624287.48	2.41	NG
2491	218951.60	3624287.53	2.54	NG
2492	218924.86	3624287.35	2.64	NG
2493	218898.18	3624287.29	2.59	NG
2494	218870.88	3624287.17	2.42	NG
2495	218845.22	3624287.26	2.28	NG
2496	218818.97	3624287.32	2.15	NG
2497	218792.07	3624287.23	2.04	NG
2498	218765.24	3624287.29	2.05	NG
2499	218738.77	3624287.29	2.02	NG
2500	218711.09	3624287.32	2.02	NG
2501	218684.05	3624287.35	1.99	NG
2502	218657.06	3624287.26	1.95	NG
2503	218630.68	3624287.34	1.96	NG
2504	218605.07	3624287.21	1.95	NG
2505	218578.60	3624287.36	1.94	NG
2506	218555.70	3624287.08	1.96	NG
2507	218529.47	3624286.99	2.08	NG
2508	218504.03	3624287.06	2.15	NG
2509	218478.51	3624287.00	2.19	NG
2510	218453.59	3624286.95	2.17	NG
2511	218427.40	3624287.29	2.16	NG
2512	218400.02	3624287.31	2.15	NG
2513	218373.63	3624286.96	2.19	NG
2514	218346.50	3624286.94	2.22	NG
2515	218320.31	3624286.97	2.29	NG
2516	218293.54	3624286.85	2.30	NG
2517	218266.00	3624286.91	2.29	NG
2518	218239.55	3624286.88	2.34	NG
2519	218213.04	3624286.89	2.35	NG
2520	218186.45	3624286.95	2.56	NG
2521	218162.19	3624286.77	2.35	NG
2522	218137.84	3624286.76	2.36	NG
2523	218113.56	3624286.93	2.39	NG

West Belle Pass Headland Restoration - RTK Survey

RTK Pt No	Northing	Easting	Elevation	Description
2524	218090.00	3624286.84	2.38	NG
2525	218063.94	3624286.94	2.40	NG
2526	218038.38	3624286.76	2.47	NG
2527	218012.43	3624286.67	2.47	NG
2528	217990.06	3624286.70	2.37	NG
2529	217969.76	3624286.65	2.40	NG
2530	217947.11	3624286.58	2.41	NG
2531	217922.39	3624286.50	3.17	NG
2532	217896.18	3624286.68	2.90	NG
2533	217870.31	3624286.65	2.86	NG
2534	217842.91	3624286.65	3.15	NG
2535	217816.65	3624286.47	3.21	NG
2536	217790.62	3624287.71	3.54	NG
2537	217766.44	3624287.03	3.81	NG
2538	217739.57	3624286.63	4.04	NG
2539	217712.90	3624287.02	3.92	NG
2540	217684.65	3624286.67	4.36	NG
2541	217659.03	3624286.69	5.08	NG
2542	217639.64	3624286.69	5.46	NG
2543	217636.01	3624286.62	6.37	NG
2544	217630.43	3624286.50	7.73	NG
2545	217623.04	3624286.61	6.57	NG
2546	217581.90	3624783.63	4.49	NG
2547	217604.00	3624783.33	4.26	NG
2548	217626.44	3624783.31	4.16	NG
2549	217649.34	3624783.40	4.18	NG
2550	217673.02	3624783.54	4.19	NG
2551	217695.96	3624783.44	4.26	NG
2552	217718.84	3624783.52	3.94	NG
2553	217743.38	3624783.58	3.85	NG
2554	217789.66	3624783.47	3.36	NG
2555	217814.29	3624783.48	3.03	NG
2556	217839.19	3624783.70	2.78	NG
2557	217863.37	3624783.79	2.63	NG
2558	217887.93	3624783.73	2.60	NG
2559	217911.54	3624783.51	2.63	NG
2560	217935.47	3624783.76	2.61	NG
2561	217959.69	3624783.77	2.53	NG
2562	217983.66	3624783.67	2.43	NG
2563	218006.91	3624783.80	2.35	NG
2564	218030.38	3624783.79	2.29	NG
2565	218054.25	3624783.97	2.27	NG
2566	218078.14	3624784.00	2.23	NG
2567	218101.77	3624783.95	2.29	NG

West Belle Pass Headland Restoration - RTK Survey

RTK Pt No	Northing	Easting	Elevation	Description
2568	218126.23	3624783.96	2.26	NG
2569	218151.06	3624784.14	2.27	NG
2570	218176.34	3624784.02	2.25	NG
2571	218200.79	3624783.90	2.26	NG
2572	218227.09	3624784.05	2.27	NG
2573	218252.96	3624784.11	2.33	NG
2574	218282.25	3624784.02	2.40	NG
2575	218305.98	3624784.12	2.38	NG
2576	218329.05	3624784.30	2.43	NG
2577	218353.65	3624784.20	2.49	NG
2578	218378.59	3624784.10	2.55	NG
2579	218403.74	3624784.20	2.57	NG
2580	218427.67	3624784.20	2.56	NG
2581	218451.56	3624784.15	2.54	NG
2582	218473.15	3624784.44	2.53	NG
2583	218497.28	3624784.49	2.49	NG
2584	218520.51	3624784.45	2.50	NG
2585	218543.08	3624784.52	2.51	NG
2586	218567.65	3624784.61	2.48	NG
2587	218591.73	3624784.59	2.44	NG
2588	218615.26	3624784.43	2.44	NG
2589	218638.78	3624784.61	2.42	NG
2590	218662.50	3624784.41	2.41	NG
2591	218686.45	3624784.47	2.42	NG
2592	218709.72	3624784.56	2.41	NG
2593	218733.10	3624784.59	2.40	NG
2594	218757.08	3624784.72	2.32	NG
2595	218781.13	3624784.82	2.24	NG
2596	218805.70	3624784.81	2.28	NG
2597	218829.44	3624784.86	2.37	NG
2598	218854.11	3624784.83	2.34	NG
2599	218874.13	3624784.86	2.34	NG
2600	218894.88	3624784.72	2.34	NG
2601	218918.71	3624784.61	2.37	NG
2602	218942.80	3624784.65	2.40	NG
2603	218966.18	3624784.96	2.38	NG
2604	218989.95	3624785.11	2.36	NG
2605	219012.31	3624785.20	2.35	NG
2606	219034.51	3624784.91	2.33	NG
2607	219056.08	3624785.02	2.29	NG
2608	219079.93	3624785.19	2.25	NG
2609	219103.22	3624784.70	2.18	NG
2610	219125.60	3624785.16	2.14	NG
2611	219149.75	3624785.15	2.08	NG

West Belle Pass Headland Restoration - RTK Survey

RTK Pt No	Northing	Easting	Elevation	Description
2612	219173.66	3624785.47	1.96	NG
2613	219198.96	3624785.30	1.83	NG
2614	219221.08	3624785.37	1.78	NG
2615	219244.52	3624785.48	1.75	NG
2616	219268.29	3624785.62	1.70	NG
2617	219291.67	3624785.31	1.67	NG
2618	219316.75	3624785.42	1.56	NG
2619	219338.90	3624785.46	1.57	NG
2620	219363.58	3624785.31	1.59	NG
2621	219388.06	3624785.49	1.60	NG
2622	219412.03	3624785.64	1.62	NG
2623	219434.79	3624785.57	1.57	NG
2624	219458.60	3624785.61	1.53	NG
2625	219483.60	3624785.51	1.98	NG
2626	219507.93	3624785.64	2.95	NG
2627	219531.80	3624785.72	1.66	NG
2628	219556.59	3624785.90	1.45	NG
2629	219569.49	3624785.82	0.91	WES
2630	219538.13	3625281.87	0.89	WES
2631	219511.50	3625282.06	1.61	NG
2632	219488.19	3625282.02	1.79	NG
2633	219467.29	3625282.03	1.76	NG
2634	219444.49	3625281.67	1.65	NG
2635	219421.53	3625281.89	1.64	NG
2636	219398.51	3625282.31	1.64	NG
2637	219377.51	3625282.27	1.62	NG
2638	219356.25	3625282.42	1.62	NG
2639	219337.48	3625282.46	1.60	NG
2640	219319.74	3625282.51	1.57	NG
2641	219297.14	3625282.48	1.55	NG
2642	219274.87	3625282.12	1.60	NG
2643	219254.13	3625282.27	1.66	NG
2644	219230.63	3625282.34	1.69	NG
2645	219207.10	3625282.36	1.70	NG
2646	219186.17	3625282.10	1.73	NG
2647	219164.55	3625282.26	1.78	NG
2648	219143.10	3625282.24	1.80	NG
2649	219121.72	3625282.35	1.84	NG
2650	219102.56	3625282.21	1.87	NG
2651	219078.76	3625282.25	1.89	NG
2652	219055.46	3625282.37	1.92	NG
2653	219031.91	3625282.42	1.95	NG
2654	219007.71	3625282.38	2.03	NG
2655	218991.44	3625282.66	2.12	NG

West Belle Pass Headland Restoration - RTK Survey

RTK Pt No	Northing	Easting	Elevation	Description
2656	218971.51	3625282.69	2.21	NG
2657	218951.19	3625282.34	2.32	NG
2658	218934.38	3625282.58	2.39	NG
2659	218914.81	3625282.47	2.41	NG
2660	218890.86	3625282.54	2.45	NG
2661	218871.79	3625282.56	2.48	NG
2662	218850.58	3625282.48	2.49	NG
2663	218829.17	3625282.77	2.48	NG
2664	218806.87	3625282.59	2.45	NG
2665	218783.96	3625282.74	2.42	NG
2666	218764.04	3625282.87	2.40	NG
2667	218744.37	3625282.62	2.42	NG
2668	218720.39	3625282.59	2.43	NG
2669	218698.79	3625282.76	2.43	NG
2670	218679.32	3625282.83	2.46	NG
2671	218660.21	3625282.79	2.46	NG
2672	218638.17	3625282.87	2.50	NG
2673	218616.14	3625282.97	2.54	NG
2674	218597.54	3625282.75	2.54	NG
2675	218573.23	3625282.95	2.52	NG
2676	218550.52	3625282.92	2.51	NG
2677	218528.20	3625283.00	2.52	NG
2678	218504.54	3625282.89	2.53	NG
2679	218487.65	3625282.74	2.56	NG
2680	218465.83	3625282.63	2.50	NG
2681	218443.13	3625283.12	2.45	NG
2682	218423.75	3625283.08	2.42	NG
2683	218401.59	3625283.04	2.45	NG
2684	218378.69	3625283.11	2.50	NG
2685	218354.89	3625283.08	2.46	NG
2686	218332.71	3625283.15	2.39	NG
2687	218309.11	3625283.16	2.37	NG
2688	218284.86	3625283.27	2.35	NG
2689	218260.24	3625282.84	2.36	NG
2690	218237.07	3625282.85	2.39	NG
2691	218213.59	3625283.27	2.38	NG
2692	218191.39	3625283.10	2.59	NG
2693	218167.20	3625283.28	2.41	NG
2694	218143.18	3625283.31	2.42	NG
2695	218118.45	3625283.31	2.40	NG
2696	218095.68	3625283.41	2.41	NG
2697	218072.91	3625283.29	2.38	NG
2698	218052.97	3625283.21	2.53	NG
2699	218030.50	3625283.19	2.65	NG

West Belle Pass Headland Restoration - RTK Survey

RTK Pt No	Northing	Easting	Elevation	Description
2700	218008.71	3625283.35	2.83	NG
2701	217988.56	3625283.38	3.02	NG
2702	217965.54	3625283.29	3.35	NG
2703	217943.48	3625283.44	2.89	WES
2704	217913.87	3625283.55	2.53	WB
2705	217889.85	3625283.28	2.46	WB
2706	217877.41	3625283.49	2.83	WES
2707	217853.85	3625283.57	2.76	NG
2708	217837.28	3625283.37	2.85	NG
2709	217819.41	3625283.33	3.03	NG
2710	217798.02	3625283.33	3.05	NG
2711	217777.89	3625283.28	2.98	NG
2712	217756.56	3625283.32	3.20	NG
2713	217734.05	3625283.38	3.35	NG
2714	217711.75	3625283.72	3.64	NG
2715	217689.55	3625283.41	3.95	NG
2716	217666.00	3625283.32	4.22	NG
2717	217642.40	3625283.36	4.69	NG
2718	217620.60	3625283.78	5.00	NG
2719	217596.96	3625283.59	5.12	NG
2720	217575.19	3625283.38	5.18	NG
2721	217555.63	3625283.74	5.36	NG
2722	217539.87	3625283.41	5.73	NG
2723	217526.62	3625283.43	4.93	NG
2724	217477.95	3625779.36	4.60	NG
2725	217498.03	3625779.78	6.67	NG
2726	217515.99	3625779.93	5.35	NG
2727	217533.79	3625779.87	4.99	NG
2728	217554.03	3625779.85	4.73	NG
2729	217574.98	3625779.94	4.68	NG
2730	217594.34	3625779.88	4.43	NG
2731	217616.16	3625780.14	4.45	NG
2732	217636.82	3625779.96	4.28	NG
2733	217657.47	3625780.16	3.88	NG
2734	217681.13	3625780.14	3.61	NG
2735	217702.50	3625780.13	3.35	NG
2736	217722.34	3625780.17	3.15	NG
2737	217743.04	3625780.55	3.00	NG
2738	217765.44	3625780.61	2.73	NG
2739	217782.77	3625780.67	2.69	NG
2740	217807.90	3625780.35	2.80	NG
2741	217826.40	3625780.72	2.78	NG
2742	217846.41	3625780.81	2.69	NG
2743	217868.68	3625780.84	2.65	NG

West Belle Pass Headland Restoration - RTK Survey

RTK Pt No	Northing	Easting	Elevation	Description
2744	217890.86	3625780.63	2.63	NG
2745	217913.30	3625780.72	2.59	NG
2746	217935.18	3625780.91	2.58	NG
2747	217953.43	3625781.02	2.57	NG
2748	217971.78	3625780.86	2.55	NG
2749	217991.43	3625781.20	2.52	NG
2750	218011.44	3625781.17	2.49	NG
2751	218030.41	3625781.10	2.46	NG
2752	218051.12	3625781.35	2.44	NG
2753	218072.09	3625781.31	2.42	NG
2754	218095.10	3625781.26	2.42	NG
2755	218117.87	3625781.44	2.42	NG
2756	218140.50	3625781.57	2.42	NG
2757	218164.36	3625781.48	2.51	NG
2758	218186.47	3625781.62	2.73	NG
2759	218207.79	3625781.65	2.50	NG
2760	218228.11	3625781.67	2.52	NG
2761	218250.16	3625781.64	2.56	NG
2762	218270.92	3625782.01	2.61	NG
2763	218291.14	3625781.82	2.61	NG
2764	218316.26	3625781.91	2.61	NG
2765	218339.38	3625781.80	2.61	NG
2766	218362.07	3625782.19	2.67	NG
2767	218385.23	3625782.07	2.64	NG
2768	218406.69	3625782.32	2.64	NG
2769	218428.97	3625782.56	2.61	NG
2770	218453.25	3625782.38	2.56	NG
2771	218477.12	3625782.30	2.53	NG
2772	218499.66	3625782.51	2.48	NG
2773	218518.92	3625782.49	2.42	NG
2774	218542.39	3625782.82	2.36	NG
2775	218566.08	3625782.78	2.33	NG
2776	218588.52	3625782.79	2.36	NG
2777	218612.65	3625782.78	2.26	NG
2778	218635.31	3625782.97	2.17	NG
2779	218659.54	3625783.09	2.04	NG
2780	218682.58	3625783.19	1.96	NG
2781	218703.82	3625783.06	1.90	NG
2782	218726.73	3625783.29	1.84	NG
2783	218750.27	3625783.27	1.81	NG
2784	218774.30	3625783.49	1.79	NG
2785	218795.80	3625783.44	1.80	NG
2786	218819.63	3625783.43	1.78	NG
2787	218843.41	3625783.57	1.76	NG

West Belle Pass Headland Restoration - RTK Survey

RTK Pt No	Northing	Easting	Elevation	Description
2788	218865.94	3625783.81	1.78	NG
2789	218888.39	3625783.69	1.73	NG
2790	218910.16	3625783.79	1.74	NG
2791	218934.44	3625783.91	1.73	NG
2792	218956.78	3625783.85	1.79	NG
2793	218976.69	3625783.78	1.85	NG
2794	218998.39	3625784.07	1.83	NG
2795	219020.17	3625783.83	1.84	NG
2796	219044.32	3625784.04	1.83	NG
2797	219065.53	3625784.10	1.83	NG
2798	219089.78	3625784.24	1.81	NG
2799	219113.11	3625784.46	1.78	NG
2800	219137.92	3625784.48	1.79	NG
2801	219161.00	3625784.41	1.78	NG
2802	219183.67	3625784.35	1.75	NG
2803	219208.37	3625784.73	1.69	NG
2804	219231.49	3625784.85	1.68	NG
2805	219254.68	3625784.51	1.68	NG
2806	219277.20	3625784.92	1.67	NG
2807	219300.33	3625784.97	1.65	NG
2808	219323.78	3625784.94	1.65	NG
2809	219345.97	3625784.99	1.71	NG
2810	219369.17	3625785.02	1.74	NG
2811	219392.57	3625785.18	1.77	NG
2812	219413.69	3625785.41	2.01	NG
2813	219433.63	3625785.39	2.54	NG
2814	219453.68	3625785.15	3.48	NG
2815	219475.49	3625785.34	3.09	NG
2816	219498.82	3625785.20	1.14	NG
2817	219503.49	3625785.37	0.77	WES
2818	218614.00	3626279.64	2.03	NG
2819	218615.34	3626278.66	8.10	SP-4
2820	217450.99	3626284.94	5.30	NG
2821	217471.16	3626284.75	6.68	NG
2822	217480.54	3626284.87	5.97	NG
2823	217504.18	3626284.66	5.06	NG
2824	217528.12	3626284.72	4.97	NG
2825	217555.34	3626284.80	4.80	NG
2826	217578.33	3626284.68	4.50	NG
2827	217601.72	3626284.74	4.17	NG
2828	217626.22	3626284.78	3.84	NG
2829	217650.47	3626284.84	3.54	NG
2830	217673.44	3626284.73	3.45	NG
2831	217696.01	3626284.63	3.30	NG

West Belle Pass Headland Restoration - RTK Survey

RTK Pt No	Northing	Easting	Elevation	Description
2832	217721.02	3626284.65	3.19	NG
2833	217746.31	3626284.74	3.15	NG
2834	217768.48	3626284.67	3.13	NG
2835	217791.25	3626284.62	3.08	NG
2836	217815.22	3626284.71	2.89	NG
2837	217837.20	3626284.73	2.79	NG
2838	217860.35	3626284.62	2.77	NG
2839	217885.12	3626284.68	2.77	NG
2840	217909.60	3626284.56	2.77	NG
2841	217932.65	3626284.86	2.75	NG
2842	217956.06	3626284.71	2.75	NG
2843	217978.55	3626284.67	2.75	NG
2844	218000.73	3626284.81	2.77	NG
2845	218023.99	3626284.71	2.84	NG
2846	218046.46	3626284.89	2.77	NG
2847	218069.24	3626284.90	2.78	NG
2848	218092.15	3626284.82	2.77	NG
2849	218116.39	3626284.61	2.77	NG
2850	218139.89	3626284.77	2.75	NG
2851	218161.61	3626284.89	2.72	NG
2852	218183.80	3626284.75	2.71	NG
2853	218206.42	3626284.72	2.70	NG
2854	218225.74	3626284.53	2.66	NG
2855	218246.51	3626284.75	2.66	NG
2856	218266.35	3626284.70	2.66	NG
2857	218287.36	3626284.84	2.60	NG
2858	218309.96	3626284.53	2.57	NG
2859	218334.58	3626284.82	2.55	NG
2860	218360.82	3626284.61	2.51	NG
2861	218385.81	3626284.60	2.45	NG
2862	218412.69	3626284.55	2.38	NG
2863	218440.61	3626284.94	2.31	NG
2864	218463.46	3626284.64	2.27	NG
2865	218491.27	3626284.73	2.19	NG
2866	218519.16	3626284.66	2.16	NG
2867	218547.14	3626284.84	2.09	NG
2868	218574.74	3626284.87	2.07	NG
2869	218602.41	3626284.82	2.03	NG
2870	218632.36	3626284.78	2.02	NG
2871	218658.66	3626284.80	2.00	NG
2872	218683.26	3626284.80	1.99	NG
2873	218712.16	3626284.84	2.00	NG
2874	218738.81	3626284.75	1.99	NG
2875	218766.70	3626284.71	2.00	NG

West Belle Pass Headland Restoration - RTK Survey

RTK Pt No	Northing	Easting	Elevation	Description
2876	218792.63	3626284.96	1.97	NG
2877	218816.67	3626284.57	1.96	NG
2878	218845.31	3626284.87	1.98	NG
2879	218872.51	3626284.73	2.00	NG
2880	218899.24	3626284.75	2.01	NG
2881	218924.20	3626284.71	1.99	NG
2882	218950.93	3626284.78	1.97	NG
2883	218977.62	3626284.80	1.96	NG
2884	219002.74	3626284.75	1.95	NG
2885	219029.28	3626284.79	1.94	NG
2886	219056.57	3626284.80	1.94	NG
2887	219083.09	3626284.92	1.95	NG
2888	219105.83	3626284.90	1.96	NG
2889	219132.22	3626284.80	1.99	NG
2890	219158.67	3626284.71	1.95	NG
2891	219185.30	3626284.78	1.96	NG
2892	219211.90	3626284.82	1.97	NG
2893	219236.59	3626284.74	1.92	NG
2894	219263.52	3626284.73	1.91	NG
2895	219291.18	3626284.74	1.93	NG
2896	219314.85	3626284.82	1.92	NG
2897	219340.04	3626284.77	1.88	NG
2898	219366.11	3626284.83	1.88	NG
2899	219392.60	3626284.82	1.99	NG
2900	219420.76	3626284.71	3.14	NG
2901	219444.32	3626284.92	2.87	NG
2902	219469.18	3626284.81	1.25	NG
2903	219477.01	3626284.79	0.74	WES
2904	219589.03	3624783.29	0.30	WB
2905	219627.83	3624788.06	0.20	WB
2906	219622.65	3624869.79	1.08	WB
2907	219558.93	3625278.80	0.39	WB
2908	219601.27	3625282.61	0.35	WB
2909	219526.25	3625779.77	0.23	WB
2910	219569.77	3625783.80	0.04	WB
2911	219496.11	3626288.88	0.45	WB
2912	219534.35	3626283.70	-0.35	WB
2913	219508.24	3626784.53	0.64	WB
2914	219499.95	3626784.67	0.72	WB
2915	218840.27	3634997.54	1.48	CHK
2916	219479.18	3626784.59	0.83	WES
2917	219459.06	3626784.61	1.01	NG
2918	219433.34	3626784.90	1.72	NG
2919	219410.69	3626784.65	2.27	NG

West Belle Pass Headland Restoration - RTK Survey

RTK Pt No	Northing	Easting	Elevation	Description
2920	219389.41	3626784.69	2.18	NG
2921	219366.26	3626784.69	1.93	NG
2922	219347.50	3626784.75	1.92	NG
2923	219323.03	3626784.71	1.94	NG
2924	219299.33	3626784.63	1.92	NG
2925	219274.36	3626784.51	1.91	NG
2926	219252.57	3626784.70	1.93	NG
2927	219230.23	3626784.58	1.94	NG
2928	219210.70	3626784.64	1.91	NG
2929	219188.50	3626784.51	1.85	NG
2930	219164.88	3626784.72	1.99	NG
2931	219141.77	3626784.67	2.00	NG
2932	219117.78	3626784.61	2.02	NG
2933	219093.00	3626784.75	2.06	NG
2934	219068.13	3626784.58	2.19	NG
2935	219041.26	3626784.74	2.29	NG
2936	219017.71	3626784.51	2.39	NG
2937	218991.86	3626784.73	2.44	NG
2938	218971.17	3626784.66	2.45	NG
2939	218947.34	3626784.61	2.50	NG
2940	218921.82	3626784.53	2.60	NG
2941	218896.31	3626784.42	2.61	NG
2942	218872.21	3626784.53	2.67	NG
2943	218847.20	3626784.59	2.74	NG
2944	218821.51	3626784.52	2.71	NG
2945	218796.70	3626784.52	2.70	NG
2946	218772.97	3626784.50	2.66	NG
2947	218749.58	3626784.53	2.90	NG
2948	218728.91	3626784.46	2.57	NG
2949	218699.77	3626784.53	2.48	NG
2950	218674.32	3626784.47	2.40	NG
2951	218653.59	3626784.38	2.35	NG
2952	218629.55	3626784.35	2.34	NG
2953	218609.08	3626784.29	2.38	NG
2954	218582.46	3626784.41	2.39	NG
2955	218559.48	3626784.35	2.35	NG
2956	218537.40	3626784.19	2.35	NG
2957	218514.17	3626784.32	2.32	NG
2958	218493.13	3626784.39	2.31	NG
2959	218467.74	3626784.40	2.34	NG
2960	218444.44	3626784.15	2.37	NG
2961	218417.40	3626784.15	2.40	NG
2962	218391.16	3626784.13	2.45	NG
2963	218363.61	3626784.46	2.47	NG

West Belle Pass Headland Restoration - RTK Survey

RTK Pt No	Northing	Easting	Elevation	Description
2964	218338.26	3626784.17	2.48	NG
2965	218314.22	3626784.33	2.57	NG
2966	218290.26	3626784.09	2.59	NG
2967	218265.26	3626784.20	2.59	NG
2968	218240.19	3626784.17	2.61	NG
2969	218215.80	3626784.23	2.61	NG
2970	218189.84	3626784.26	2.66	NG
2971	218164.88	3626784.15	2.69	NG
2972	218140.04	3626784.14	2.71	NG
2973	218113.09	3626784.07	2.78	NG
2974	218090.82	3626783.93	2.81	NG
2975	218067.80	3626784.14	2.87	NG
2976	218040.83	3626784.04	2.91	NG
2977	218017.07	3626784.14	2.94	NG
2978	217992.15	3626784.06	2.94	NG
2979	217970.25	3626783.90	2.99	NG
2980	217948.14	3626784.13	3.02	NG
2981	217919.21	3626784.00	3.05	NG
2982	217893.54	3626783.84	3.00	NG
2983	217867.64	3626783.96	3.02	NG
2984	217842.65	3626783.91	3.00	NG
2985	217816.64	3626783.92	2.97	NG
2986	217787.96	3626783.95	2.98	NG
2987	217757.69	3626784.07	3.03	NG
2988	217735.66	3626783.93	2.99	NG
2989	217722.33	3626784.09	2.75	NG
2990	217701.28	3626784.10	2.73	NG
2991	217678.94	3626783.98	3.22	NG
2992	217651.40	3626783.89	3.38	NG
2993	217621.11	3626783.86	3.85	NG
2994	217595.37	3626783.87	4.00	NG
2995	217573.49	3626783.93	4.23	NG
2996	217548.76	3626783.87	4.43	NG
2997	217522.14	3626783.79	4.70	NG
2998	217497.05	3626783.85	4.93	NG
2999	217470.18	3626783.95	5.20	NG
3000	217446.69	3626783.86	6.27	NG
3001	217426.63	3626783.73	6.35	NG
3002	217398.07	3627287.10	6.48	NG
3003	217418.79	3627286.96	5.30	NG
3004	217445.14	3627286.97	5.31	NG
3005	217469.28	3627286.84	5.21	NG
3006	217493.02	3627286.72	5.21	NG
3007	217521.33	3627286.86	4.71	NG

West Belle Pass Headland Restoration - RTK Survey

RTK Pt No	Northing	Easting	Elevation	Description
3008	217550.76	3627286.94	4.35	NG
3009	217577.83	3627286.91	3.64	NG
3010	217606.34	3627286.78	3.47	NG
3011	217630.24	3627286.71	3.24	NG
3012	217656.47	3627286.52	3.07	NG
3013	217680.03	3627286.83	2.89	NG
3014	217708.20	3627286.64	3.12	NG
3015	217736.36	3627286.72	3.33	NG
3016	217762.38	3627286.59	3.80	NG
3017	217785.41	3627286.69	4.43	NG
3018	217814.23	3627286.61	3.81	NG
3019	217844.74	3627286.54	3.51	NG
3020	217872.22	3627286.58	3.40	NG
3021	217902.48	3627286.55	3.41	NG
3022	217924.87	3627286.31	3.48	NG
3023	217946.51	3627286.27	3.53	NG
3024	217969.88	3627286.39	3.57	NG
3025	217992.45	3627286.40	3.68	NG
3026	218014.35	3627286.39	3.90	NG
3027	218038.26	3627286.27	3.78	NG
3028	218059.48	3627286.27	3.67	NG
3029	218085.44	3627286.09	3.56	NG
3030	218106.91	3627286.18	3.28	NG
3031	218134.30	3627286.37	3.24	NG
3032	218161.13	3627286.29	3.13	NG
3033	218188.13	3627286.18	3.02	NG
3034	218217.33	3627286.09	2.98	NG
3035	218245.77	3627286.14	2.94	NG
3036	218269.76	3627285.93	2.90	NG
3037	218296.38	3627286.10	2.78	NG
3038	218323.28	3627285.97	2.75	NG
3039	218348.88	3627285.96	2.65	NG
3040	218380.06	3627285.79	2.56	NG
3041	218412.30	3627285.62	2.53	NG
3042	218444.62	3627285.80	2.45	NG
3043	218475.64	3627285.76	2.38	NG
3044	218501.44	3627285.72	2.33	NG
3045	218526.71	3627285.74	2.37	NG
3046	218555.13	3627285.66	2.39	NG
3047	218580.53	3627285.63	2.39	NG
3048	218606.71	3627285.64	2.34	NG
3049	218630.38	3627285.65	2.22	NG
3050	218653.40	3627285.61	2.24	NG
3051	218678.03	3627285.45	2.22	NG

West Belle Pass Headland Restoration - RTK Survey

RTK Pt No	Northing	Easting	Elevation	Description
3052	218702.02	3627285.41	2.21	NG
3053	218724.36	3627285.51	2.25	NG
3054	218747.62	3627285.41	2.35	NG
3055	218771.37	3627285.36	2.42	NG
3056	218796.39	3627285.49	2.51	NG
3057	218822.61	3627285.35	2.52	NG
3058	218849.14	3627285.33	2.55	NG
3059	218875.00	3627285.37	2.56	NG
3060	218900.90	3627285.24	2.47	NG
3061	218929.19	3627285.10	2.59	NG
3062	218956.49	3627285.22	2.53	NG
3063	218986.23	3627285.20	2.43	NG
3064	219012.14	3627284.93	2.41	NG
3065	219036.28	3627285.21	2.41	NG
3066	219065.80	3627285.21	2.37	NG
3067	219093.44	3627284.97	2.38	NG
3068	219122.68	3627285.09	2.37	NG
3069	219148.84	3627284.88	2.42	NG
3070	219179.04	3627284.99	2.21	NG
3071	219206.61	3627284.89	2.08	NG
3072	219234.30	3627284.87	2.13	NG
3073	219263.62	3627284.91	2.08	NG
3074	219289.91	3627284.92	2.04	NG
3075	219314.36	3627284.63	2.01	NG
3076	219342.43	3627284.74	2.03	NG
3077	219365.45	3627284.80	2.31	NG
3078	219391.31	3627284.65	1.83	NG
3079	219416.10	3627284.72	1.15	NG
3080	219434.87	3627284.79	0.85	NG
3081	219452.06	3627284.63	1.01	NG
3082	219441.73	3627788.19	-0.29	WB
3083	219404.46	3627788.05	-0.14	WB
3084	219414.07	3628286.31	-0.44	WB
3085	219376.00	3628287.44	-0.03	WB
3086	219377.31	3628783.83	-0.37	WB
3087	219344.77	3628786.48	0.06	WB
3088	219353.50	3629282.60	-0.51	WB
3089	219317.44	3629282.15	0.00	WB
3090	218883.91	3629785.93	-0.03	WB
3091	218833.40	3629787.76	0.19	WB
3092	218795.96	3629784.90	0.25	WB
3093	218745.76	3629784.85	-0.16	WB
3094	218696.54	3629786.18	-0.37	WB
3095	218618.03	3629785.54	-0.11	WB

West Belle Pass Headland Restoration - RTK Survey

RTK Pt No	Northing	Easting	Elevation	Description
3096	218560.13	3629786.35	-0.26	WB
3097	218489.77	3629784.18	0.41	WB
3098	218434.62	3629785.77	0.22	WB
3099	219386.30	3627789.16	0.68	WES
3100	219386.28	3627789.19	0.67	WES
3101	219358.99	3627788.61	1.48	NG
3102	219309.66	3627788.72	1.60	NG
3103	219283.37	3627788.88	1.66	NG
3104	219258.00	3627788.63	1.83	NG
3105	219233.08	3627788.32	1.89	NG
3106	219207.31	3627788.54	1.98	NG
3107	219179.38	3627788.34	2.08	NG
3108	219151.54	3627787.96	2.17	NG
3109	219123.95	3627788.12	2.25	NG
3110	219096.27	3627788.04	2.29	NG
3111	219069.24	3627788.10	2.14	NG
3112	219043.06	3627788.07	2.16	NG
3113	219015.73	3627787.90	2.18	NG
3114	218992.97	3627787.77	2.20	NG
3115	218968.44	3627787.97	2.27	NG
3116	218942.75	3627787.79	2.31	NG
3117	218918.06	3627787.75	2.36	NG
3118	218890.87	3627787.57	2.32	NG
3119	218863.37	3627787.88	2.37	NG
3120	218835.88	3627787.46	2.41	NG
3121	218809.42	3627787.61	2.26	NG
3122	218784.19	3627787.38	2.32	NG
3123	218757.26	3627787.65	2.29	NG
3124	218731.37	3627787.40	2.33	NG
3125	218705.68	3627787.34	2.37	NG
3126	218677.50	3627787.37	2.35	NG
3127	218651.25	3627787.08	2.31	NG
3128	218625.33	3627787.29	2.24	NG
3129	218598.79	3627787.23	2.62	NG
3130	218578.12	3627787.09	2.63	NG
3131	218554.18	3627787.02	2.60	NG
3132	218528.59	3627787.31	2.63	NG
3133	218502.91	3627787.02	2.67	NG
3134	218477.26	3627786.97	2.75	NG
3135	218452.22	3627786.95	2.76	NG
3136	218427.41	3627786.82	2.78	NG
3137	218402.88	3627786.77	2.83	NG
3138	218378.11	3627786.57	2.90	NG
3139	218351.78	3627786.42	2.98	NG

West Belle Pass Headland Restoration - RTK Survey

RTK Pt No	Northing	Easting	Elevation	Description
3140	218328.11	3627786.59	2.93	NG
3141	218301.98	3627786.41	2.94	NG
3142	218276.16	3627786.64	3.35	NG
3143	218251.12	3627786.27	3.31	NG
3144	218224.76	3627786.18	3.45	NG
3145	218202.60	3627786.11	3.47	NG
3146	218177.63	3627786.17	3.56	NG
3147	218152.31	3627786.05	3.53	NG
3148	218127.37	3627786.27	3.55	NG
3149	218105.67	3627786.02	3.59	NG
3150	218080.19	3627786.16	3.52	NG
3151	218059.42	3627785.72	3.50	NG
3152	218037.34	3627786.17	3.42	NG
3153	218014.01	3627786.01	3.35	NG
3154	217990.75	3627785.83	3.27	NG
3155	217967.69	3627785.57	3.14	NG
3156	217942.48	3627785.61	3.02	NG
3157	217919.99	3627785.60	3.03	NG
3158	217897.00	3627785.54	3.07	NG
3159	217871.24	3627785.40	3.16	NG
3160	217845.24	3627785.44	3.18	NG
3161	217821.54	3627785.42	3.35	NG
3162	217798.01	3627785.64	3.39	NG
3163	217775.18	3627785.29	3.49	NG
3164	217752.32	3627785.39	3.57	NG
3165	217729.77	3627785.52	3.58	NG
3166	217706.29	3627785.44	3.60	NG
3167	217680.86	3627784.99	3.60	NG
3168	217659.52	3627785.04	3.64	NG
3169	217637.12	3627785.21	3.68	NG
3170	217615.72	3627785.09	3.71	NG
3171	217592.55	3627785.10	3.84	NG
3172	217592.52	3627784.87	3.84	NG
3173	217570.25	3627785.08	3.94	NG
3174	217547.48	3627784.90	4.03	NG
3175	217524.17	3627784.96	4.38	NG
3176	217500.77	3627784.78	4.55	NG
3177	217476.84	3627784.81	4.97	NG
3178	217452.20	3627784.79	4.96	NG
3179	217428.58	3627784.70	5.19	NG
3180	217405.91	3627784.73	5.15	NG
3181	217382.48	3627784.56	5.00	NG
3182	217370.62	3627784.96	5.46	NG
3183	217336.87	3628280.61	5.54	NG

West Belle Pass Headland Restoration - RTK Survey

RTK Pt No	Northing	Easting	Elevation	Description
3184	217361.22	3628280.65	5.32	NG
3185	217386.45	3628280.96	5.38	NG
3186	217410.51	3628280.70	5.34	NG
3187	217435.06	3628280.96	4.93	NG
3188	217458.94	3628281.16	4.74	NG
3189	217482.61	3628281.22	4.64	NG
3190	217507.00	3628281.43	4.36	NG
3191	217530.85	3628281.37	4.14	NG
3192	217556.38	3628281.30	3.97	NG
3193	217582.96	3628281.38	3.92	NG
3194	217607.12	3628281.44	3.80	NG
3195	217631.69	3628281.72	3.79	NG
3196	217657.87	3628281.74	3.64	NG
3197	217684.92	3628281.73	3.42	NG
3198	217709.89	3628281.64	3.34	NG
3199	217734.54	3628281.85	3.31	NG
3200	217760.48	3628282.01	3.33	NG
3201	217785.05	3628281.92	3.22	NG
3202	217810.46	3628282.05	3.08	NG
3203	217835.60	3628282.16	2.92	NG
3204	217860.07	3628282.10	2.89	NG
3205	217887.24	3628282.46	2.87	NG
3206	217912.17	3628282.35	2.96	NG
3207	217936.76	3628282.39	2.87	NG
3208	217959.09	3628282.64	2.78	NG
3209	217984.15	3628282.49	2.76	NG
3210	218009.34	3628282.49	2.76	NG
3211	218033.35	3628282.67	2.76	NG
3212	218058.18	3628282.76	2.76	NG
3213	218081.99	3628283.02	2.73	NG
3214	218107.10	3628282.93	2.66	NG
3215	218132.64	3628282.83	2.61	NG
3216	218157.63	3628283.02	2.55	NG
3217	218180.83	3628283.05	2.54	NG
3218	218205.19	3628283.09	2.50	NG
3219	218229.86	3628283.21	2.45	NG
3220	218253.01	3628283.60	2.39	NG
3221	218276.04	3628283.09	2.40	NG
3222	218300.32	3628283.72	2.36	NG
3223	218323.11	3628283.50	2.36	NG
3224	218355.87	3628283.41	2.34	NG
3225	218381.05	3628283.44	2.34	NG
3226	218407.68	3628283.85	2.37	NG
3227	218433.26	3628284.11	2.34	NG

West Belle Pass Headland Restoration - RTK Survey

RTK Pt No	Northing	Easting	Elevation	Description
3228	218456.85	3628283.95	2.37	NG
3229	218448.96	3628281.27	2.36	NG
3230	218448.40	3628281.28	8.18	SP-7
3231	218483.21	3628284.09	2.34	NG
3232	218516.38	3628284.13	2.47	NG
3233	218542.78	3628284.04	2.35	NG
3234	218568.78	3628284.30	2.33	NG
3235	218595.77	3628284.04	1.83	NG
3236	218619.63	3628284.36	1.81	NG
3237	218648.06	3628284.55	1.73	NG
3238	218676.93	3628284.58	1.68	NG
3239	218701.50	3628284.99	1.66	NG
3240	218724.96	3628284.66	1.64	NG
3241	218750.85	3628284.67	1.65	NG
3242	218777.89	3628284.66	1.61	NG
3243	218804.38	3628284.92	1.61	NG
3244	218830.00	3628285.05	1.56	NG
3245	218855.90	3628285.00	1.51	NG
3246	218883.03	3628284.93	1.55	NG
3247	218905.46	3628285.37	1.56	NG
3248	218930.99	3628285.21	1.57	NG
3249	218955.23	3628285.59	1.50	NG
3250	218979.65	3628284.75	1.52	NG
3251	219005.26	3628285.31	1.46	NG
3252	219031.58	3628285.55	1.47	NG
3253	219057.26	3628285.69	1.52	NG
3254	219082.26	3628285.75	1.53	NG
3255	219108.60	3628285.50	1.70	NG
3256	219134.45	3628285.96	1.93	NG
3257	219160.62	3628285.66	1.83	NG
3258	219186.86	3628286.06	1.67	NG
3259	219211.25	3628286.12	1.45	NG
3260	219237.24	3628285.69	1.28	NG
3261	219263.51	3628286.24	1.30	NG
3262	219288.00	3628285.58	1.21	NG
3263	219314.25	3628286.37	1.12	NG
3264	219333.53	3628286.29	1.09	NG
3265	219350.73	3628286.57	0.88	NG
3266	219357.65	3628286.14	0.55	WES
3267	219331.92	3628784.39	0.44	WES
3268	219318.53	3628784.65	0.82	NG
3269	219303.12	3628784.70	0.78	NG
3270	219288.78	3628784.70	0.74	NG
3271	219271.38	3628784.51	0.88	NG

West Belle Pass Headland Restoration - RTK Survey

RTK Pt No	Northing	Easting	Elevation	Description
3272	219246.97	3628784.40	1.02	NG
3273	219229.98	3628784.50	1.01	NG
3274	219212.81	3628784.60	1.02	NG
3275	219196.71	3628784.55	1.02	NG
3276	219179.80	3628784.24	0.99	NG
3277	219162.56	3628784.20	1.00	NG
3278	219146.03	3628784.23	1.01	NG
3279	219129.82	3628784.34	1.05	NG
3280	219113.85	3628784.27	1.06	NG
3281	219097.41	3628784.20	1.08	NG
3282	219080.71	3628784.15	1.09	NG
3283	219064.05	3628784.08	1.10	NG
3284	219047.39	3628784.29	1.10	NG
3285	219031.51	3628784.07	1.10	NG
3286	219016.28	3628784.12	1.12	NG
3287	219002.75	3628784.22	1.12	NG
3288	218987.77	3628783.99	1.16	NG
3289	218971.81	3628783.97	1.17	NG
3290	218954.84	3628784.14	1.17	NG
3291	218940.35	3628783.67	1.17	NG
3292	218925.73	3628783.91	1.18	NG
3293	218910.78	3628783.85	1.21	NG
3294	218895.67	3628783.77	1.19	NG
3295	218881.02	3628783.85	1.22	NG
3296	218865.81	3628784.00	1.23	NG
3297	218849.92	3628783.91	1.29	NG
3298	218834.87	3628783.92	1.30	NG
3299	218820.34	3628783.84	1.32	NG
3300	218804.69	3628783.98	1.34	NG
3301	218788.96	3628783.80	1.34	NG
3302	218773.36	3628783.74	1.35	NG
3303	218756.48	3628783.61	1.36	NG
3304	218739.65	3628783.73	1.39	NG
3305	218723.97	3628783.75	1.41	NG
3306	218707.81	3628783.43	1.43	NG
3307	218691.24	3628783.60	1.45	NG
3308	218675.44	3628783.55	1.43	NG
3309	218659.04	3628783.54	1.45	NG
3310	218643.49	3628783.37	1.48	NG
3311	218627.30	3628783.61	1.50	NG
3312	218610.82	3628783.48	1.53	NG
3313	218593.55	3628783.38	1.55	NG
3314	218577.02	3628783.44	1.54	NG
3315	218559.60	3628783.28	1.54	NG

West Belle Pass Headland Restoration - RTK Survey

RTK Pt No	Northing	Easting	Elevation	Description
3316	218541.71	3628783.28	1.54	NG
3317	218524.92	3628783.20	1.56	NG
3318	218506.97	3628783.13	1.56	NG
3319	218489.82	3628783.31	1.59	NG
3320	218472.22	3628783.02	1.60	NG
3321	218453.45	3628783.15	1.71	NG
3322	218435.43	3628783.36	1.64	NG
3323	218419.03	3628783.18	1.64	NG
3324	218400.65	3628783.04	1.59	NG
3325	218384.05	3628783.02	1.57	NG
3326	218365.45	3628782.83	1.62	NG
3327	218348.72	3628783.09	1.65	NG
3328	218332.40	3628783.15	1.69	NG
3329	218316.33	3628782.80	1.69	NG
3330	218299.79	3628782.97	1.68	NG
3331	218283.99	3628783.09	1.69	NG
3332	218266.28	3628782.88	1.73	NG
3333	218249.88	3628782.66	1.85	NG
3334	218229.69	3628782.77	1.68	NG
3335	218213.03	3628782.59	1.70	NG
3336	218198.51	3628782.48	1.69	NG
3337	218181.76	3628782.70	1.66	NG
3338	218163.40	3628782.68	1.68	NG
3339	218149.60	3628782.44	1.70	NG
3340	218135.34	3628782.66	1.71	NG
3341	218119.60	3628782.69	1.70	NG
3342	218101.19	3628783.08	1.71	NG
3343	218082.75	3628782.66	1.71	NG
3344	218065.79	3628782.55	1.73	NG
3345	218049.12	3628782.45	1.76	NG
3346	218032.21	3628782.30	1.79	NG
3347	218014.33	3628782.56	1.83	NG
3348	217996.10	3628782.70	1.85	NG
3349	217979.97	3628782.21	1.89	NG
3350	217962.98	3628782.49	1.91	NG
3351	217947.23	3628782.41	1.92	NG
3352	217929.12	3628782.33	1.98	NG
3353	217911.50	3628782.21	2.01	NG
3354	217894.72	3628782.30	2.01	NG
3355	217878.44	3628782.20	2.09	NG
3356	217863.78	3628781.97	2.12	NG
3357	217848.68	3628782.13	2.00	NG
3358	217834.05	3628782.17	2.08	NG
3359	217817.17	3628782.07	2.24	NG

West Belle Pass Headland Restoration - RTK Survey

RTK Pt No	Northing	Easting	Elevation	Description
3360	217801.10	3628782.17	2.34	NG
3361	217787.98	3628781.97	2.36	NG
3362	217772.91	3628782.05	2.38	NG
3363	217757.73	3628781.92	2.38	NG
3364	217741.69	3628781.83	2.44	NG
3365	217725.14	3628782.01	2.53	NG
3366	217709.11	3628781.79	2.56	NG
3367	217693.70	3628781.98	2.65	NG
3368	217679.98	3628781.93	2.78	NG
3369	217664.80	3628781.73	2.94	NG
3370	217650.88	3628781.86	2.96	NG
3371	217634.16	3628781.79	3.01	NG
3372	217618.26	3628781.54	3.07	NG
3373	217602.93	3628781.55	3.12	NG
3374	217587.79	3628781.51	3.13	NG
3375	217570.68	3628781.56	3.18	NG
3376	217557.70	3628781.46	3.23	NG
3377	217542.75	3628781.68	3.25	NG
3378	217527.52	3628781.61	3.36	NG
3379	217512.02	3628781.54	3.46	NG
3380	217496.47	3628781.32	3.62	NG
3381	217481.42	3628781.74	3.74	NG
3382	217465.71	3628781.58	3.94	NG
3383	217448.66	3628781.65	4.33	NG
3384	217433.34	3628781.24	4.58	NG
3385	217417.48	3628781.18	4.93	NG
3386	217401.04	3628781.18	5.32	NG
3387	217385.14	3628781.30	5.07	NG
3388	217365.31	3628781.20	5.60	NG
3389	217348.60	3628781.57	6.07	NG
3390	217333.16	3628781.19	6.23	NG
3391	217307.44	3629283.33	6.05	NG
3392	217322.88	3629283.14	5.88	NG
3393	217346.95	3629282.94	5.31	NG
3394	217362.92	3629283.10	5.14	NG
3395	217376.92	3629283.20	4.90	NG
3396	217394.74	3629283.24	4.63	NG
3397	217411.43	3629282.77	4.50	NG
3398	217427.41	3629282.89	4.34	NG
3399	217444.61	3629282.99	4.86	NG
3400	217451.24	3629282.94	5.19	NG
3401	217453.11	3629283.39	4.16	NG
3402	217467.03	3629283.10	4.01	NG
3403	217482.42	3629282.85	3.75	NG

West Belle Pass Headland Restoration - RTK Survey

RTK Pt No	Northing	Easting	Elevation	Description
3404	217496.89	3629282.92	3.64	NG
3405	217512.41	3629282.88	3.49	NG
3406	217530.14	3629283.21	3.32	NG
3407	217548.65	3629282.90	3.33	NG
3408	217570.47	3629283.00	3.41	NG
3409	217587.81	3629282.75	3.32	NG
3410	217603.11	3629282.65	3.31	NG
3411	217623.20	3629282.81	3.37	NG
3412	217638.70	3629282.66	3.28	NG
3413	217656.21	3629282.80	3.25	NG
3414	217672.73	3629282.73	3.26	NG
3415	217690.32	3629282.70	2.86	NG
3416	217707.36	3629282.55	2.57	NG
3417	217724.71	3629282.44	2.45	NG
3418	217742.56	3629282.44	2.29	NG
3419	217760.13	3629282.51	2.03	NG
3420	217775.30	3629282.55	1.90	NG
3421	217788.49	3629282.77	1.98	NG
3422	217810.49	3629282.65	2.00	NG
3423	217828.52	3629282.39	1.99	NG
3424	217844.17	3629282.62	2.19	NG
3425	217857.46	3629282.52	2.12	NG
3426	217870.32	3629282.31	2.23	NG
3427	217883.06	3629282.55	1.98	NG
3428	217896.94	3629282.52	1.99	NG
3429	217912.59	3629282.35	1.82	NG
3430	217929.74	3629282.56	1.83	NG
3431	217943.69	3629282.09	1.85	NG
3432	217963.12	3629282.47	1.85	NG
3433	217980.03	3629282.53	1.93	NG
3434	218000.17	3629282.37	1.81	NG
3435	218014.98	3629282.54	1.78	NG
3436	218033.58	3629282.68	1.74	NG
3437	218052.49	3629282.21	1.76	NG
3438	218072.39	3629282.54	1.75	NG
3439	218091.86	3629282.44	1.71	NG
3440	218110.87	3629282.62	1.74	NG
3441	218131.70	3629282.57	1.64	NG
3442	218154.48	3629282.44	1.60	NG
3443	218176.16	3629282.38	1.57	NG
3444	218198.40	3629282.34	1.51	NG
3445	218220.76	3629282.26	1.49	NG
3446	218243.53	3629282.25	1.50	NG
3447	218265.74	3629282.27	1.53	NG

West Belle Pass Headland Restoration - RTK Survey

RTK Pt No	Northing	Easting	Elevation	Description
3448	218284.46	3629282.16	1.50	NG
3449	218305.59	3629282.21	1.50	NG
3450	218326.48	3629282.07	1.52	NG
3451	218345.29	3629282.26	1.52	NG
3452	218367.33	3629282.19	1.52	NG
3453	218386.14	3629282.16	1.95	NG
3454	218402.56	3629282.08	1.51	NG
3455	218421.50	3629282.03	1.51	NG
3456	218445.25	3629282.24	1.54	NG
3457	218467.01	3629281.84	1.49	NG
3458	218487.44	3629281.87	1.50	NG
3459	218508.45	3629282.04	1.50	NG
3460	218527.26	3629282.03	1.52	NG
3461	218547.52	3629282.00	1.60	NG
3462	218568.98	3629281.79	1.56	NG
3463	218589.44	3629281.97	1.55	NG
3464	218611.19	3629282.06	1.56	NG
3465	218634.39	3629281.84	1.50	NG
3466	218657.29	3629281.93	1.45	NG
3467	218677.14	3629281.87	1.40	NG
3468	218700.19	3629281.87	1.36	NG
3469	218722.54	3629282.04	1.28	NG
3470	218743.88	3629281.70	1.24	NG
3471	218766.30	3629281.83	1.21	NG
3472	218787.93	3629281.78	1.20	NG
3473	218812.77	3629281.78	1.18	NG
3474	218835.46	3629281.70	1.20	NG
3475	218858.75	3629281.82	1.22	NG
3476	218879.53	3629281.61	1.25	NG
3477	218901.51	3629281.62	1.21	NG
3478	218919.69	3629281.40	1.23	NG
3479	218940.26	3629281.47	1.24	NG
3480	218958.32	3629281.78	1.28	NG
3481	218979.72	3629281.49	1.31	NG
3482	218999.43	3629281.67	1.31	NG
3483	219020.73	3629281.56	1.28	NG
3484	219041.55	3629281.38	1.27	NG
3485	219062.81	3629281.31	1.28	NG
3486	219083.32	3629281.47	1.30	NG
3487	219104.43	3629281.29	1.32	NG
3488	219125.42	3629281.85	1.31	NG
3489	219146.43	3629281.43	1.32	NG
3490	219168.02	3629281.25	1.30	NG
3491	219189.62	3629281.37	1.28	NG

West Belle Pass Headland Restoration - RTK Survey

RTK Pt No	Northing	Easting	Elevation	Description
3492	219211.10	3629281.52	1.25	NG
3493	219232.20	3629281.38	1.08	NG
3494	219252.71	3629281.27	0.68	NG
3495	219265.82	3629281.18	0.58	NG
3496	219280.90	3629281.27	0.72	NG
3497	219291.37	3629281.17	0.73	NG
3498	219298.58	3629281.23	0.47	WES

West Belle Pass Headland Restoration Project - Comparisons between Geoid12A and Geoid09

Point	Northing	Easting	Elevation Geoid12A	Description	Point	Northing	Easting	Elevation Geoid09	Description	Y Diff	X Diff	Z Diff
200	224296.329	3645688.772	7.304	MON TE23-SM-01	200	224296.402	3645688.715	7.459	MON TE23-SM-01	-0.07	0.06	-0.15
									AVERAGE TOPO SURVEY DIFFERENCE =	**-0.07**	**0.06**	**-0.19**

West Belle Pass Headland Restoration Project - Comparisons between Geoid12A and Geoid03-2004.65

Point	Northing	Easting	Elevation Geoid12A	Description	Point	Northing	Easting	Elevation Geoid03	Description	Y Diff	X Diff	Z Diff
200	224296.329	3645688.772	7.304	MON TE23-SM-01	200	224296.402	3645688.715	7.615	MON TE23-SM-01	-0.07	0.06	-0.31
									AVERAGE TOPO SURVEY DIFFERENCE =	**-0.07**	**0.06**	**-0.35**

WEST BELLE PASS HEADLAND RESTORATION - SETTLEMENT PLATES 2015

Settlement Plate-1

RTK Point#	Northing	Easting	Elevation (NAVD88-Geoid09)	Date of installation - Date Surveyed	RTK Point#	Northing	Easting	Ground Elevation
171	217605.3	3624282.6	11.5	3/10/2012				
825	217605.00	3624283.06	10.45	1/13/2015	824	217604.14	3624282.19	2.23
Difference	**-0.3**	**0.5**	**-1.1**					

Settlement Plate-2

RTK Point#	Northing	Easting	Elevation (NAVD88-Geoid09)	Date of installation - Date Surveyed	RTK Point#	Northing	Easting	Ground Elevation
172	218760.5	3624284.4	7.8	3/6/2012				
2250	218761.52	3624285.64	7.70	1/20/2015	2249	218761.71	3624285.70	2.23
Difference	**1.0**	**1.2**	**-0.1**					

Settlement Plate-3

RTK Point#	Northing	Easting	Elevation (NAVD88-Geoid09)	Date of installation - Date Surveyed	RTK Point#	Northing	Easting	Ground Elevation
173	217462.0	3626286.6	12.5	3/6/2012				
760	217462.93	3626286.82	10.26	1/13/2015	759	217462.21	3626286.66	5.83
Difference	**0.9**	**0.2**	**-2.2**					

Settlement Plate-4

RTK Point#	Northing	Easting	Elevation (NAVD88-Geoid09)	Date of installation - Date Surveyed	RTK Point#	Northing	Easting	Ground Elevation
174	218631.8	3626280.6	7.7	3/6/2012				
2819	218615.41	3626278.60	8.29	1/21/2015	2818	218614.07	3626279.59	2.21
Difference	**-16.4**	**-2.0**	**0.6**					

Settlement Plate-5

RTK Point#	Northing	Easting	Elevation (NAVD88-Geoid09)	Date of installation - Date Surveyed	RTK Point#	Northing	Easting	Ground Elevation
175	219632.3	3626281.7	11.5	1/20/2012				
1380	219631.48	3626280.26	10.03	1/19/2015	1379	219632.26	3626280.73	4.82
Difference	**-0.8**	**-1.4**	**-1.5**					

WEST BELLE PASS HEADLAND RESTORATION - SETTLEMENT PLATES 2015

Settlement Plate-6

RTK Point#	Northing	Easting	Elevation (NAVD88-Geoid09)	Date of installation - Date Surveyed	RTK Point#	Northing	Easting	Ground Elevation
176	217313.8	3628286.8	13.3	4/29/2012				
701	217315.00	3628286.18	11.83	1/13/2015	700	217314.67	3628285.91	1.95
Difference	**1.2**	**-0.6**	**-1.5**					

Settlement Plate-7

RTK Point#	Northing	Easting	Elevation (NAVD88-Geoid09)	Date of installation - Date Surveyed	RTK Point#	Northing	Easting	Ground Elevation
177	218448.4	3628281.1	9.0	3/6/2012				
3230	218448.47	3628281.22	8.36	1/22/2015	3229	218449.04	3628281.21	2.54
Difference	**0.1**	**0.1**	**-0.6**					

Settlement Plate-8

RTK Point#	Northing	Easting	Elevation (NAVD88-Geoid09)	Date of installation - Date Surveyed	RTK Point#	Northing	Easting	Ground Elevation
178	217167.1	3630250.4	10.4	5/15/2012				
649	217167.70	3630250.61	8.89	1/13/2015	665	217167.38	3630249.99	-1.25
Difference	**0.6**	**0.2**	**-1.5**					

Settlement Plate-9

RTK Point#	Northing	Easting	Elevation (NAVD88-Geoid09)	Date of installation - Date Surveyed	RTK Point#	Northing	Easting	Ground Elevation
179	217954.6	3630180.2	5.9	3/6/2012				
1184	217955.86	3630179.09	5.60	1/14/2015	1185	217955.27	3630179.33	0.87
Difference	**1.3**	**-1.1**	**-0.3**					

Settlement Plate-10

RTK Point#	Northing	Easting	Elevation (NAVD88-Geoid09)	Date of installation - Date Surveyed	RTK Point#	Northing	Easting	Ground Elevation
180	218068.8	3630287.0	9.9	2/8/2012				
1183	218069.32	3630289.83	7.85	1/14/2015	1182	218069.15	3630290.31	3.62
Difference	**0.5**	**2.8**	**-2.1**					

John Chance Land Surveys, Inc.
200 Dulles Drive
Lafayette, LA 70506
USA
Phone: 337-237-1300
Fax: 337-268-3281
www.jclsurvey.com

Project file data		Coordinate System	
Name:	L:\2014\140587\Data\Gps\Rtk\WBP-2015_SURVEY-1.vce	Name:	US State Plane 1983
Size:	56 MB	Datum:	NAD 1983 (Conus)
Modified:	2/10/2015 3:55:01 PM (UTC:-6)	Zone:	Default
Time zone:	Central Standard Time	Geoid:	GEOID12A (Conus)
Reference number:		Vertical datum:	NAVD88 (2011)
Description:			

Additional Coordinate System Details

Local Site Settings			
Project latitude:	?	Ground scale factor:	1
Project longitude:	?	False northing offset:	0.000
Project height:	0.000	False easting offset:	0.000

Point List

ID	Northing (US survey foot)	Easting (US survey foot)	Elevation (US survey foot)	Feature Code
171	217605.300	3624282.600	11.500	SP-1
172	218760.500	3624284.400	7.800	SP-2
173	217462.000	3626286.600	12.500	SP-3
174	218631.800	3626280.600	7.700	SP-4
175	219632.300	3626281.700	11.500	SP-5
176	217313.800	3628286.800	13.300	SP-6
177	218448.400	3628281.100	9.000	SP-7
178	217167.100	3630250.400	10.400	SP-8
179	217954.600	3630180.200	5.900	SP-9
180	218068.800	3630287.000	9.900	SP-10
649	217167.629	3630250.666	8.709	SP-8
700	217314.593	3628285.962	1.764	NG
701	217314.925	3628286.239	11.643	SP-6
759	217462.138	3626286.720	5.645	NG
760	217462.854	3626286.879	10.073	SP-3
824	217604.064	3624282.243	2.041	NG

825	217604.923	3624283.113	10.257	SP-1
1177	218068.948	3630289.832	3.714	PIPE
1182	218069.076	3630290.362	3.439	NG
1183	218069.244	3630289.884	7.667	SP-10
1184	217955.791	3630179.147	5.416	SP-9
1185	217955.194	3630179.383	0.685	NG
1379	219632.191	3626280.784	4.640	NG
1380	219631.411	3626280.314	9.843	SP-5
2249	218761.636	3624285.757	2.043	NG
2250	218761.444	3624285.701	7.507	SP-2
2818	218613.998	3626279.643	2.028	NG
2819	218615.335	3626278.655	8.103	SP-4
3229	218448.963	3628281.271	2.357	NG
3230	218448.395	3628281.281	8.180	SP-7

2/25/2015 10:16:55 AM	L:\2014\140587\Data\Gps\Rtk\WBP-2015_SURVEY-1.vce	Trimble Business Center

SECTION E

Bathymetric Survey

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
5000	3632788.68	215608.20	-5.10	WB
5001	3632788.58	215611.60	-5.09	WB
5002	3632788.49	215614.99	-5.08	WB
5003	3632788.42	215618.28	-5.07	WB
5004	3632788.37	215621.50	-5.05	WB
5005	3632788.34	215624.68	-5.04	WB
5006	3632788.33	215627.78	-5.03	WB
5007	3632788.33	215629.64	-5.02	WB
5008	3632788.33	215630.78	-5.02	WB
5009	3632788.28	215633.73	-5.01	WB
5010	3632788.23	215636.70	-5.00	WB
5011	3632788.14	215639.63	-4.99	WB
5012	3632787.98	215642.59	-4.98	WB
5013	3632787.81	215645.61	-4.98	WB
5014	3632787.58	215648.55	-4.97	WB
5015	3632787.34	215651.56	-4.96	WB
5016	3632787.12	215654.23	-4.96	WB
5017	3632787.10	215654.59	-4.95	WB
5018	3632786.86	215657.68	-4.94	WB
5019	3632786.63	215660.74	-4.93	WB
5020	3632786.43	215663.85	-4.93	WB
5021	3632786.24	215666.96	-4.91	WB
5022	3632786.03	215670.14	-4.90	WB
5023	3632785.80	215673.38	-4.89	WB
5024	3632785.56	215676.55	-4.88	WB
5025	3632785.32	215679.37	-4.86	WB
5026	3632785.28	215679.76	-4.85	WB
5027	3632784.97	215683.13	-4.84	WB
5028	3632784.66	215686.34	-4.83	WB
5029	3632784.32	215689.63	-4.82	WB
5030	3632783.99	215692.95	-4.81	WB
5031	3632783.79	215696.15	-4.80	WB
5032	3632783.61	215699.33	-4.79	WB
5033	3632783.52	215702.45	-4.78	WB
5034	3632783.50	215704.43	-4.77	WB
5035	3632783.49	215705.52	-4.76	WB
5036	3632783.46	215708.54	-4.75	WB
5037	3632783.45	215711.60	-4.74	WB
5038	3632783.44	215714.57	-4.73	WB
5039	3632783.42	215717.65	-4.72	WB
5040	3632783.39	215720.65	-4.71	WB
5041	3632783.35	215723.66	-4.70	WB
5042	3632783.25	215726.73	-4.69	WB
5043	3632783.17	215729.08	-4.68	WB
5044	3632783.14	215729.82	-4.67	WB
5045	3632782.90	215732.94	-4.65	WB
5046	3632782.59	215736.16	-4.64	WB
5047	3632782.23	215739.39	-4.63	WB
5048	3632781.81	215742.64	-4.62	WB
5049	3632781.38	215745.91	-4.60	WB
5050	3632780.95	215749.13	-4.59	WB
5051	3632780.52	215752.40	-4.58	WB
5052	3632780.28	215754.41	-4.56	WB
5053	3632780.21	215755.56	-4.55	WB
5054	3632780.01	215758.79	-4.54	WB
5055	3632779.84	215761.96	-4.53	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
5056	3632779.80	215765.02	-4.52	WB
5057	3632779.78	215768.22	-4.51	WB
5058	3632779.84	215771.35	-4.50	WB
5059	3632779.97	215774.44	-4.50	WB
5060	3632780.11	215777.59	-4.49	WB
5061	3632780.20	215779.95	-4.49	WB
5062	3632780.23	215780.76	-4.49	WB
5063	3632780.36	215783.93	-4.49	WB
5064	3632780.50	215787.16	-4.49	WB
5065	3632780.64	215790.36	-4.50	WB
5066	3632780.77	215793.58	-4.50	WB
5067	3632780.83	215796.97	-4.50	WB
5068	3632780.87	215800.32	-4.51	WB
5069	3632780.85	215803.70	-4.51	WB
5070	3632780.84	215804.53	-4.52	WB
5071	3632780.80	215807.17	-4.52	WB
5072	3632780.74	215810.68	-4.52	WB
5073	3632780.68	215814.19	-4.52	WB
5074	3632780.62	215817.70	-4.52	WB
5075	3632780.64	215821.19	-4.52	WB
5076	3632780.68	215824.72	-4.51	WB
5077	3632780.76	215828.09	-4.50	WB
5078	3632780.83	215829.81	-4.49	WB
5079	3632780.89	215831.52	-4.48	WB
5080	3632781.03	215834.90	-4.47	WB
5081	3632781.21	215838.19	-4.46	WB
5082	3632781.39	215841.44	-4.44	WB
5083	3632781.57	215844.62	-4.43	WB
5084	3632781.76	215847.80	-4.42	WB
5085	3632781.95	215851.02	-4.40	WB
5086	3632782.09	215854.03	-4.39	WB
5087	3632782.13	215854.80	-4.38	WB
5088	3632782.24	215857.08	-4.36	WB
5089	3632782.38	215860.13	-4.35	WB
5090	3632782.52	215863.04	-4.33	WB
5091	3632782.65	215866.04	-4.32	WB
5092	3632782.77	215868.89	-4.30	WB
5093	3632782.90	215871.70	-4.28	WB
5094	3632783.08	215874.48	-4.26	WB
5095	3632783.30	215877.20	-4.24	WB
5096	3632783.49	215879.60	-4.22	WB
5097	3632783.50	215879.92	-4.21	WB
5098	3632783.67	215882.58	-4.19	WB
5099	3632783.84	215885.24	-4.18	WB
5100	3632783.95	215887.91	-4.17	WB
5101	3632784.03	215890.58	-4.16	WB
5102	3632784.07	215893.28	-4.16	WB
5103	3632783.99	215896.02	-4.15	WB
5104	3632783.90	215898.82	-4.13	WB
5105	3632783.64	215901.58	-4.12	WB
5106	3632783.37	215904.09	-4.11	WB
5107	3632783.34	215904.43	-4.09	WB
5108	3632782.96	215907.36	-4.07	WB
5109	3632782.50	215910.27	-4.06	WB
5110	3632782.02	215913.25	-4.06	WB
5111	3632781.48	215916.40	-4.06	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
5112	3632780.94	215919.52	-4.06	WB
5113	3632780.44	215922.84	-4.05	WB
5114	3632780.03	215926.06	-4.03	WB
5115	3632779.61	215929.36	-3.99	WB
5116	3632779.30	215932.81	-3.95	WB
5117	3632779.00	215936.16	-3.90	WB
5118	3632778.77	215939.67	-4.05	WB
5119	3632778.59	215943.15	-4.18	WB
5120	3632778.44	215946.57	-4.39	WB
5121	3632778.48	215953.93	-4.59	WB
5122	3632778.50	215954.75	-4.92	WB
5123	3632778.66	215957.31	-5.00	WB
5124	3632778.88	215960.68	-5.10	WB
5125	3632779.13	215964.07	-5.10	WB
5126	3632779.43	215967.28	-4.60	WB
5127	3632779.74	215970.54	-4.40	WB
5128	3632780.07	215973.78	-4.29	WB
5129	3632780.39	215976.91	-4.23	WB
5130	3632780.73	215980.06	-4.15	WB
5131	3632781.09	215983.15	-4.09	WB
5132	3632781.45	215986.15	-4.07	WB
5133	3632781.75	215989.14	-4.04	WB
5134	3632782.06	215992.08	-4.04	WB
5135	3632782.32	215994.91	-4.05	WB
5136	3632782.57	215997.87	-4.06	WB
5137	3632782.80	216000.69	-4.05	WB
5138	3632782.96	216003.51	-4.04	WB
5139	3632783.02	216004.60	-4.01	WB
5140	3632783.12	216006.37	-3.98	WB
5141	3632783.23	216009.10	-3.96	WB
5142	3632783.32	216011.90	-3.93	WB
5143	3632783.40	216014.68	-3.91	WB
5144	3632783.43	216017.40	-3.88	WB
5145	3632783.46	216020.12	-3.84	WB
5146	3632783.40	216022.83	-3.81	WB
5147	3632783.31	216025.58	-3.78	WB
5148	3632783.19	216028.39	-3.75	WB
5149	3632783.12	216029.43	-3.72	WB
5150	3632783.01	216031.19	-3.69	WB
5151	3632782.84	216034.00	-3.66	WB
5152	3632782.66	216036.86	-3.63	WB
5153	3632782.49	216039.62	-3.60	WB
5154	3632782.33	216042.48	-3.57	WB
5155	3632782.20	216045.35	-3.55	WB
5156	3632782.06	216048.21	-3.52	WB
5157	3632782.02	216051.14	-3.50	WB
5158	3632782.00	216053.96	-3.47	WB
5159	3632781.99	216054.70	-3.45	WB
5160	3632782.01	216056.81	-3.43	WB
5161	3632782.06	216059.77	-3.41	WB
5162	3632782.11	216062.59	-3.39	WB
5163	3632782.19	216065.40	-3.37	WB
5164	3632782.28	216068.36	-3.35	WB
5165	3632782.37	216071.14	-3.33	WB
5166	3632782.46	216074.01	-3.31	WB
5167	3632782.54	216076.82	-3.29	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
5168	3632782.64	216079.56	-3.26	WB
5169	3632782.74	216082.38	-3.24	WB
5170	3632782.87	216085.13	-3.21	WB
5171	3632783.01	216087.83	-3.18	WB
5172	3632783.16	216090.52	-3.15	WB
5173	3632783.34	216093.16	-3.12	WB
5174	3632783.52	216095.78	-3.09	WB
5175	3632783.65	216098.38	-3.06	WB
5176	3632783.78	216100.96	-3.03	WB
5177	3632783.90	216103.53	-3.00	WB
5178	3632783.93	216104.53	-2.98	WB
5179	3632783.98	216106.15	-2.94	WB
5180	3632784.05	216108.71	-2.92	WB
5181	3632783.99	216111.43	-2.91	WB
5182	3632783.90	216114.22	-2.89	WB
5183	3632783.76	216116.99	-2.89	WB
5184	3632783.56	216119.85	-2.85	WB
5185	3632783.35	216122.76	-2.85	WB
5186	3632783.17	216125.66	-2.89	WB
5187	3632782.99	216128.65	-2.98	WB
5188	3632782.97	216128.99	-2.98	WB
5189	3632782.80	216131.62	-3.00	WB
5190	3632782.60	216134.59	-3.04	WB
5191	3632782.39	216137.66	-3.14	WB
5192	3632782.08	216140.79	-3.27	WB
5193	3632781.76	216143.95	-3.70	WB
5194	3632781.38	216147.17	-4.00	WB
5195	3632780.93	216150.50	-4.13	WB
5196	3632780.45	216153.85	-4.06	WB
5197	3632779.90	216157.20	-4.06	WB
5198	3632779.33	216160.59	-4.03	WB
5199	3632778.82	216163.99	-3.93	WB
5200	3632778.35	216167.41	-3.86	WB
5201	3632777.94	216170.70	-3.81	WB
5202	3632777.71	216173.95	-3.77	WB
5203	3632777.50	216177.15	-3.72	WB
5204	3632777.47	216179.78	-3.68	WB
5205	3632777.48	216180.13	-3.65	WB
5206	3632777.54	216183.09	-3.64	WB
5207	3632777.65	216185.88	-3.63	WB
5208	3632777.87	216188.58	-3.62	WB
5209	3632778.10	216191.30	-3.61	WB
5210	3632778.38	216193.90	-3.59	WB
5211	3632778.67	216196.50	-3.58	WB
5212	3632778.97	216199.10	-3.56	WB
5213	3632779.27	216201.61	-3.54	WB
5214	3632779.59	216204.22	-3.51	WB
5215	3632779.67	216204.81	-3.49	WB
5216	3632779.91	216206.68	-3.46	WB
5217	3632780.23	216209.19	-3.43	WB
5218	3632780.54	216211.75	-3.39	WB
5219	3632780.80	216214.23	-3.36	WB
5220	3632781.08	216216.78	-3.32	WB
5221	3632781.34	216219.25	-3.29	WB
5222	3632781.60	216221.68	-3.25	WB
5223	3632781.84	216224.17	-3.22	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
5224	3632782.05	216226.57	-3.18	WB
5225	3632782.25	216229.00	-3.15	WB
5226	3632782.26	216229.29	-3.12	WB
5227	3632782.33	216231.47	-3.08	WB
5228	3632782.41	216233.96	-3.05	WB
5229	3632782.41	216236.44	-3.02	WB
5230	3632782.37	216238.94	-2.99	WB
5231	3632782.31	216241.44	-2.96	WB
5232	3632782.22	216243.92	-2.94	WB
5233	3632782.13	216246.44	-2.91	WB
5234	3632782.04	216248.91	-2.88	WB
5235	3632781.95	216251.46	-2.85	WB
5236	3632781.85	216254.00	-2.82	WB
5237	3632781.83	216254.35	-2.80	WB
5238	3632781.74	216256.59	-2.77	WB
5239	3632781.61	216259.24	-2.75	WB
5240	3632781.52	216261.92	-2.72	WB
5241	3632781.44	216264.64	-2.70	WB
5242	3632781.39	216267.43	-2.69	WB
5243	3632781.38	216270.20	-2.69	WB
5244	3632781.37	216273.02	-2.64	WB
5245	3632304.39	215617.07	-6.60	WB
5246	3632303.53	215619.30	-6.60	WB
5247	3632303.04	215620.57	-6.59	WB
5248	3632301.66	215624.22	-6.59	WB
5249	3632300.53	215627.73	-6.59	WB
5250	3632299.49	215631.28	-6.59	WB
5251	3632298.52	215634.81	-6.59	WB
5252	3632297.74	215638.22	-6.58	WB
5253	3632296.96	215641.72	-6.57	WB
5254	3632296.37	215644.65	-6.56	WB
5255	3632296.28	215645.11	-6.55	WB
5256	3632295.64	215648.43	-6.53	WB
5257	3632294.93	215651.86	-6.51	WB
5258	3632294.11	215655.26	-6.49	WB
5259	3632293.27	215658.69	-6.47	WB
5260	3632292.45	215662.13	-6.45	WB
5261	3632291.66	215665.50	-6.42	WB
5262	3632290.91	215668.91	-6.40	WB
5263	3632290.75	215669.74	-6.38	WB
5264	3632290.28	215672.21	-6.36	WB
5265	3632289.65	215675.51	-6.34	WB
5266	3632289.16	215678.78	-6.33	WB
5267	3632288.69	215682.07	-6.31	WB
5268	3632288.30	215685.39	-6.30	WB
5269	3632288.01	215688.67	-6.28	WB
5270	3632287.73	215692.02	-6.27	WB
5271	3632287.58	215695.27	-6.26	WB
5272	3632287.44	215698.56	-6.24	WB
5273	3632287.31	215701.94	-6.24	WB
5274	3632287.20	215705.27	-6.23	WB
5275	3632287.09	215708.68	-6.22	WB
5276	3632287.03	215712.15	-6.21	WB
5277	3632286.96	215715.57	-6.21	WB
5278	3632286.97	215719.13	-6.20	WB
5279	3632286.98	215720.45	-6.20	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
5280	3632287.01	215722.68	-6.19	WB
5281	3632287.07	215726.24	-6.19	WB
5282	3632287.22	215729.88	-6.18	WB
5283	3632287.38	215733.50	-6.18	WB
5284	3632287.63	215737.16	-6.17	WB
5285	3632287.91	215740.88	-6.17	WB
5286	3632288.20	215744.45	-6.16	WB
5287	3632288.29	215745.43	-6.16	WB
5288	3632288.54	215748.10	-6.15	WB
5289	3632288.89	215751.79	-6.15	WB
5290	3632289.29	215755.38	-6.14	WB
5291	3632289.71	215758.97	-6.13	WB
5292	3632290.13	215762.60	-6.13	WB
5293	3632290.51	215766.04	-6.12	WB
5294	3632290.91	215769.58	-6.11	WB
5295	3632290.99	215770.34	-6.11	WB
5296	3632291.23	215772.90	-6.10	WB
5297	3632291.55	215776.20	-6.09	WB
5298	3632291.80	215779.67	-6.08	WB
5299	3632291.93	215782.94	-6.07	WB
5300	3632292.04	215786.23	-6.06	WB
5301	3632291.95	215789.67	-6.05	WB
5302	3632291.86	215792.98	-6.04	WB
5303	3632291.79	215795.04	-6.03	WB
5304	3632291.75	215796.32	-6.02	WB
5305	3632291.63	215799.63	-6.01	WB
5306	3632291.51	215802.88	-5.99	WB
5307	3632291.36	215806.18	-5.98	WB
5308	3632291.21	215809.43	-5.97	WB
5309	3632291.07	215812.59	-5.96	WB
5310	3632290.93	215815.76	-5.95	WB
5311	3632290.79	215818.92	-5.93	WB
5312	3632290.74	215820.09	-5.92	WB
5313	3632290.66	215822.05	-5.91	WB
5314	3632290.53	215825.18	-5.90	WB
5315	3632290.39	215828.35	-5.89	WB
5316	3632290.26	215831.43	-5.87	WB
5317	3632290.14	215834.55	-5.86	WB
5318	3632290.06	215837.77	-5.85	WB
5319	3632289.99	215840.94	-5.84	WB
5320	3632289.90	215844.17	-5.83	WB
5321	3632289.88	215844.99	-5.82	WB
5322	3632289.81	215847.39	-5.81	WB
5323	3632289.74	215850.60	-5.80	WB
5324	3632289.68	215853.82	-5.79	WB
5325	3632289.64	215857.04	-5.77	WB
5326	3632289.53	215860.23	-5.76	WB
5327	3632289.42	215863.40	-5.75	WB
5328	3632289.29	215866.59	-5.74	WB
5329	3632289.13	215869.78	-5.72	WB
5330	3632288.97	215872.99	-5.71	WB
5331	3632288.68	215876.27	-5.69	WB
5332	3632288.39	215879.46	-5.68	WB
5333	3632288.04	215882.70	-5.67	WB
5334	3632287.64	215885.97	-5.65	WB
5335	3632287.27	215889.14	-5.64	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
5336	3632286.92	215892.40	-5.62	WB
5337	3632286.67	215894.78	-5.61	WB
5338	3632286.59	215895.60	-5.59	WB
5339	3632286.31	215898.70	-5.58	WB
5340	3632286.07	215901.87	-5.57	WB
5341	3632285.84	215904.95	-5.55	WB
5342	3632285.66	215908.03	-5.54	WB
5343	3632285.48	215911.11	-5.53	WB
5344	3632285.35	215914.18	-5.52	WB
5345	3632285.23	215917.23	-5.51	WB
5346	3632285.13	215919.98	-5.50	WB
5347	3632285.12	215920.34	-5.49	WB
5348	3632285.01	215923.47	-5.49	WB
5349	3632284.89	215926.58	-5.48	WB
5350	3632284.79	215929.81	-5.48	WB
5351	3632284.69	215933.05	-5.47	WB
5352	3632284.62	215936.29	-5.47	WB
5353	3632284.62	215939.70	-5.47	WB
5354	3632284.61	215943.07	-5.46	WB
5355	3632284.63	215945.24	-5.46	WB
5356	3632284.64	215946.48	-5.46	WB
5357	3632284.68	215950.01	-5.45	WB
5358	3632284.75	215953.50	-5.45	WB
5359	3632284.84	215956.99	-5.45	WB
5360	3632284.94	215960.48	-5.44	WB
5361	3632285.05	215963.91	-5.44	WB
5362	3632285.17	215967.33	-5.43	WB
5363	3632285.26	215970.33	-5.42	WB
5364	3632285.27	215970.73	-5.41	WB
5365	3632285.37	215974.11	-5.40	WB
5366	3632285.47	215977.43	-5.39	WB
5367	3632285.58	215980.72	-5.38	WB
5368	3632285.69	215984.01	-5.36	WB
5369	3632285.79	215987.17	-5.35	WB
5370	3632285.88	215990.38	-5.33	WB
5371	3632285.96	215993.53	-5.32	WB
5372	3632285.96	215995.06	-5.30	WB
5373	3632285.96	215996.57	-5.28	WB
5374	3632285.96	215999.71	-5.27	WB
5375	3632285.88	216002.74	-5.25	WB
5376	3632285.79	216005.66	-5.23	WB
5377	3632285.67	216008.64	-5.21	WB
5378	3632285.54	216011.51	-5.19	WB
5379	3632285.41	216014.33	-5.18	WB
5380	3632285.26	216017.19	-5.16	WB
5381	3632285.11	216019.97	-5.15	WB
5382	3632284.95	216022.71	-5.13	WB
5383	3632284.78	216025.54	-5.12	WB
5384	3632284.61	216028.34	-5.11	WB
5385	3632284.45	216031.12	-5.10	WB
5386	3632284.27	216034.10	-5.09	WB
5387	3632284.10	216036.99	-5.09	WB
5388	3632283.92	216039.92	-5.08	WB
5389	3632283.73	216042.99	-5.07	WB
5390	3632283.62	216045.28	-5.07	WB
5391	3632283.58	216046.08	-5.06	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
5392	3632283.43	216049.24	-5.06	WB
5393	3632283.29	216052.53	-5.05	WB
5394	3632283.17	216055.80	-5.04	WB
5395	3632283.05	216059.13	-5.04	WB
5396	3632283.02	216062.62	-5.03	WB
5397	3632283.00	216066.01	-5.02	WB
5398	3632283.06	216069.47	-5.01	WB
5399	3632283.09	216070.34	-5.00	WB
5400	3632283.17	216072.93	-4.98	WB
5401	3632283.31	216076.28	-4.97	WB
5402	3632283.55	216079.62	-4.95	WB
5403	3632283.79	216082.99	-4.94	WB
5404	3632284.08	216086.15	-4.92	WB
5405	3632284.40	216089.30	-4.90	WB
5406	3632284.72	216092.44	-4.88	WB
5407	3632285.00	216095.36	-4.86	WB
5408	3632285.29	216098.36	-4.84	WB
5409	3632285.53	216101.23	-4.82	WB
5410	3632285.75	216104.04	-4.80	WB
5411	3632285.94	216106.88	-4.78	WB
5412	3632286.08	216109.62	-4.76	WB
5413	3632286.21	216112.36	-4.74	WB
5414	3632286.23	216115.08	-4.73	WB
5415	3632286.23	216117.81	-4.71	WB
5416	3632286.19	216119.90	-4.69	WB
5417	3632286.15	216120.57	-4.68	WB
5418	3632285.98	216123.40	-4.66	WB
5419	3632285.80	216126.15	-4.65	WB
5420	3632285.54	216129.09	-4.63	WB
5421	3632285.28	216132.01	-4.62	WB
5422	3632284.97	216135.00	-4.60	WB
5423	3632284.64	216137.98	-4.59	WB
5424	3632284.30	216140.95	-4.58	WB
5425	3632283.95	216144.10	-4.57	WB
5426	3632283.87	216144.85	-4.55	WB
5427	3632283.60	216147.22	-4.54	WB
5428	3632283.29	216150.32	-4.53	WB
5429	3632283.01	216153.45	-4.52	WB
5430	3632282.75	216156.58	-4.51	WB
5431	3632282.57	216159.70	-4.50	WB
5432	3632282.40	216162.83	-4.49	WB
5433	3632282.32	216165.96	-4.48	WB
5434	3632282.28	216169.07	-4.47	WB
5435	3632282.27	216170.22	-4.47	WB
5436	3632282.28	216172.21	-4.46	WB
5437	3632282.35	216175.24	-4.45	WB
5438	3632282.43	216178.26	-4.44	WB
5439	3632282.56	216181.36	-4.44	WB
5440	3632282.71	216184.44	-4.43	WB
5441	3632282.84	216187.53	-4.42	WB
5442	3632282.94	216190.63	-4.41	WB
5443	3632283.04	216193.74	-4.40	WB
5444	3632283.05	216194.86	-4.40	WB
5445	3632283.06	216196.88	-4.38	WB
5446	3632283.08	216200.04	-4.37	WB
5447	3632283.11	216203.17	-4.36	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
5448	3632283.16	216206.28	-4.35	WB
5449	3632283.21	216209.40	-4.34	WB
5450	3632283.25	216212.43	-4.33	WB
5451	3632283.28	216215.42	-4.31	WB
5452	3632283.34	216218.51	-4.29	WB
5453	3632283.37	216220.28	-4.27	WB
5454	3632283.40	216221.36	-4.25	WB
5455	3632283.47	216224.25	-4.23	WB
5456	3632283.54	216227.10	-4.21	WB
5457	3632283.61	216229.86	-4.18	WB
5458	3632283.67	216232.71	-4.16	WB
5459	3632283.72	216235.49	-4.14	WB
5460	3632283.78	216238.22	-4.12	WB
5461	3632283.88	216241.07	-4.11	WB
5462	3632283.99	216243.87	-4.10	WB
5463	3632284.04	216245.28	-4.12	WB
5464	3632284.07	216246.77	-4.14	WB
5465	3632284.14	216249.70	-4.16	WB
5466	3632284.21	216252.67	-4.18	WB
5467	3632284.26	216255.74	-4.19	WB
5468	3632284.31	216258.86	-4.20	WB
5469	3632284.25	216262.02	-4.21	WB
5470	3632284.16	216265.30	-4.22	WB
5471	3632284.06	216268.67	-4.23	WB
5472	3632284.02	216269.88	-4.24	WB
5473	3632283.96	216272.04	-4.25	WB
5474	3632283.86	216275.41	-4.24	WB
5475	3632283.83	216278.80	-4.21	WB
5476	3632283.80	216282.16	-4.19	WB
5477	3632283.82	216285.49	-4.16	WB
5478	3632283.92	216288.80	-4.14	WB
5479	3632284.01	216292.10	-4.12	WB
5480	3632284.21	216295.23	-4.09	WB
5481	3632284.41	216298.29	-4.06	WB
5482	3632284.62	216301.34	-4.04	WB
5483	3632284.82	216304.26	-4.01	WB
5484	3632285.03	216307.13	-3.99	WB
5485	3632285.24	216309.92	-3.96	WB
5486	3632285.46	216312.65	-3.94	WB
5487	3632285.67	216315.23	-3.91	WB
5488	3632285.90	216317.82	-3.88	WB
5489	3632286.14	216320.37	-3.86	WB
5490	3632286.41	216322.81	-3.84	WB
5491	3632286.69	216325.24	-3.84	WB
5492	3632286.94	216327.64	-3.86	WB
5493	3632287.17	216330.01	-3.89	WB
5494	3632287.40	216332.45	-3.92	WB
5495	3632287.56	216334.87	-3.95	WB
5496	3632287.72	216337.37	-3.97	WB
5497	3632287.75	216340.03	-3.98	WB
5498	3632287.75	216342.75	-4.00	WB
5499	3632287.74	216344.42	-4.01	WB
5500	3632287.67	216345.53	-4.02	WB
5501	3632287.44	216348.46	-4.03	WB
5502	3632287.20	216351.40	-4.03	WB
5503	3632286.85	216354.47	-4.02	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
5504	3632286.49	216357.56	-4.02	WB
5505	3632286.09	216360.68	-4.00	WB
5506	3632285.65	216363.87	-3.99	WB
5507	3632285.23	216366.95	-3.98	WB
5508	3632284.90	216369.72	-3.96	WB
5509	3632284.85	216370.10	-3.95	WB
5510	3632284.47	216373.30	-3.94	WB
5511	3632284.14	216376.37	-3.92	WB
5512	3632283.83	216379.52	-3.91	WB
5513	3632283.53	216382.60	-3.90	WB
5514	3632283.26	216385.57	-3.88	WB
5515	3632282.98	216388.62	-3.87	WB
5516	3632282.75	216391.60	-3.85	WB
5517	3632282.54	216394.62	-3.84	WB
5518	3632282.51	216394.98	-3.82	WB
5519	3632282.35	216397.63	-3.81	WB
5520	3632282.21	216400.63	-3.79	WB
5521	3632282.09	216403.62	-3.77	WB
5522	3632282.04	216406.65	-3.76	WB
5523	3632282.04	216409.56	-3.74	WB
5524	3632282.06	216412.56	-3.73	WB
5525	3632282.11	216415.51	-3.71	WB
5526	3632282.18	216418.44	-3.70	WB
5527	3632282.21	216419.94	-3.68	WB
5528	3632282.25	216421.42	-3.67	WB
5529	3632282.32	216424.42	-3.66	WB
5530	3632282.39	216427.42	-3.65	WB
5531	3632282.44	216430.52	-3.64	WB
5532	3632282.48	216433.53	-3.63	WB
5533	3632282.44	216436.71	-3.63	WB
5534	3632282.38	216439.87	-3.62	WB
5535	3632282.29	216443.02	-3.60	WB
5536	3632282.23	216444.56	-3.59	WB
5537	3632282.16	216446.16	-3.57	WB
5538	3632282.03	216449.30	-3.56	WB
5539	3632281.78	216452.41	-3.53	WB
5540	3632281.52	216455.60	-3.51	WB
5541	3632281.26	216458.74	-3.47	WB
5542	3632281.02	216461.91	-3.44	WB
5543	3632280.78	216465.10	-3.40	WB
5544	3632280.64	216468.10	-3.36	WB
5545	3632280.54	216470.41	-3.31	WB
5546	3632280.51	216471.18	-3.27	WB
5547	3632280.52	216474.04	-3.23	WB
5548	3632280.61	216476.75	-3.18	WB
5549	3632280.74	216479.48	-3.14	WB
5550	3632280.97	216481.94	-3.10	WB
5551	3632281.21	216484.42	-3.06	WB
5552	3632281.51	216486.78	-3.03	WB
5553	3632281.81	216489.00	-3.00	WB
5554	3632282.13	216491.24	-2.97	WB
5555	3632282.46	216493.36	-2.94	WB
5556	3632282.80	216495.45	-2.92	WB
5557	3632282.84	216495.70	-2.90	WB
5558	3632283.17	216497.50	-2.87	WB
5559	3632283.55	216499.53	-2.83	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
5560	3632283.91	216501.58	-2.79	WB
5561	3632284.24	216503.68	-2.75	WB
5562	3631768.83	215627.57	-7.60	WB
5563	3631768.23	215630.34	-7.60	WB
5564	3631767.65	215633.15	-7.61	WB
5565	3631767.32	215636.00	-7.61	WB
5566	3631767.14	215638.71	-7.62	WB
5567	3631767.04	215641.48	-7.62	WB
5568	3631767.22	215644.17	-7.63	WB
5569	3631767.41	215646.79	-7.63	WB
5570	3631767.77	215649.51	-7.63	WB
5571	3631768.17	215652.10	-7.64	WB
5572	3631768.33	215653.07	-7.64	WB
5573	3631768.62	215654.69	-7.64	WB
5574	3631769.16	215657.30	-7.64	WB
5575	3631769.69	215659.81	-7.64	WB
5576	3631770.29	215662.27	-7.64	WB
5577	3631770.93	215664.77	-7.63	WB
5578	3631771.55	215667.21	-7.63	WB
5579	3631772.14	215669.68	-7.62	WB
5580	3631772.74	215672.12	-7.61	WB
5581	3631773.18	215674.50	-7.60	WB
5582	3631773.64	215677.01	-7.59	WB
5583	3631774.02	215679.52	-7.58	WB
5584	3631774.34	215682.01	-7.57	WB
5585	3631774.66	215684.51	-7.56	WB
5586	3631774.92	215687.06	-7.55	WB
5587	3631775.18	215689.61	-7.55	WB
5588	3631775.43	215692.26	-7.54	WB
5589	3631775.67	215694.86	-7.54	WB
5590	3631775.91	215697.52	-7.53	WB
5591	3631776.13	215700.30	-7.52	WB
5592	3631776.24	215701.64	-7.52	WB
5593	3631776.36	215702.98	-7.51	WB
5594	3631776.51	215705.76	-7.50	WB
5595	3631776.62	215708.52	-7.50	WB
5596	3631776.71	215711.24	-7.49	WB
5597	3631776.71	215714.01	-7.48	WB
5598	3631776.72	215716.75	-7.47	WB
5599	3631776.57	215719.38	-7.46	WB
5600	3631776.34	215722.11	-7.46	WB
5601	3631776.08	215724.78	-7.45	WB
5602	3631775.91	215726.06	-7.44	WB
5603	3631775.73	215727.35	-7.43	WB
5604	3631775.37	215729.97	-7.42	WB
5605	3631774.89	215732.65	-7.41	WB
5606	3631774.41	215735.26	-7.40	WB
5607	3631773.84	215737.97	-7.39	WB
5608	3631773.16	215740.78	-7.38	WB
5609	3631772.50	215743.52	-7.37	WB
5610	3631771.68	215746.42	-7.36	WB
5611	3631770.86	215749.34	-7.35	WB
5612	3631770.34	215751.18	-7.34	WB
5613	3631770.02	215752.31	-7.34	WB
5614	3631769.16	215755.34	-7.33	WB
5615	3631768.28	215758.42	-7.33	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
5616	3631767.35	215761.54	-7.32	WB
5617	3631766.40	215764.68	-7.32	WB
5618	3631765.57	215767.86	-7.31	WB
5619	3631764.85	215771.04	-7.30	WB
5620	3631764.14	215774.26	-7.30	WB
5621	3631763.72	215776.69	-7.29	WB
5622	3631763.58	215777.56	-7.28	WB
5623	3631763.05	215780.73	-7.27	WB
5624	3631762.60	215784.00	-7.26	WB
5625	3631762.19	215787.38	-7.25	WB
5626	3631761.80	215790.67	-7.24	WB
5627	3631761.49	215794.15	-7.23	WB
5628	3631761.18	215797.58	-7.22	WB
5629	3631760.92	215800.96	-7.21	WB
5630	3631760.85	215801.88	-7.19	WB
5631	3631760.65	215804.45	-7.18	WB
5632	3631760.41	215807.87	-7.16	WB
5633	3631760.23	215811.22	-7.14	WB
5634	3631760.05	215814.57	-7.13	WB
5635	3631760.09	215821.61	-7.11	WB
5636	3631760.21	215824.53	-7.09	WB
5637	3631760.40	215827.52	-7.07	WB
5638	3631760.60	215830.33	-7.05	WB
5639	3631760.85	215833.08	-7.04	WB
5640	3631761.11	215835.90	-7.02	WB
5641	3631761.41	215838.67	-7.00	WB
5642	3631761.73	215841.43	-6.99	WB
5643	3631762.06	215844.20	-6.97	WB
5644	3631762.38	215846.99	-6.96	WB
5645	3631762.71	215849.73	-6.94	WB
5646	3631763.00	215852.23	-6.93	WB
5647	3631763.04	215852.56	-6.92	WB
5648	3631763.38	215855.42	-6.91	WB
5649	3631763.72	215858.17	-6.90	WB
5650	3631764.06	215861.01	-6.90	WB
5651	3631764.40	215863.82	-6.89	WB
5652	3631764.61	215866.62	-6.88	WB
5653	3631764.81	215869.57	-6.88	WB
5654	3631764.95	215872.55	-6.88	WB
5655	3631765.01	215875.47	-6.87	WB
5656	3631765.03	215876.99	-6.87	WB
5657	3631765.04	215878.52	-6.87	WB
5658	3631764.92	215881.57	-6.87	WB
5659	3631764.78	215884.67	-6.87	WB
5660	3631764.63	215887.82	-6.87	WB
5661	3631764.49	215891.04	-6.87	WB
5662	3631764.34	215894.32	-6.87	WB
5663	3631764.31	215897.56	-6.87	WB
5664	3631764.28	215900.79	-6.86	WB
5665	3631764.29	215902.38	-6.86	WB
5666	3631764.36	215904.04	-6.86	WB
5667	3631764.53	215907.35	-6.85	WB
5668	3631764.73	215910.54	-6.85	WB
5669	3631765.02	215913.78	-6.84	WB
5670	3631765.33	215917.05	-6.84	WB
5671	3631765.64	215920.27	-6.83	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
5672	3631765.96	215923.48	-6.82	WB
5673	3631766.29	215926.79	-6.80	WB
5674	3631766.33	215927.19	-6.79	WB
5675	3631766.61	215930.02	-6.78	WB
5676	3631766.94	215933.29	-6.76	WB
5677	3631767.25	215936.44	-6.74	WB
5678	3631767.57	215939.56	-6.72	WB
5679	3631767.87	215942.68	-6.70	WB
5680	3631768.14	215945.63	-6.68	WB
5681	3631768.41	215948.54	-6.66	WB
5682	3631768.55	215951.41	-6.64	WB
5683	3631768.57	215951.76	-6.62	WB
5684	3631768.67	215954.26	-6.60	WB
5685	3631768.71	215957.08	-6.57	WB
5686	3631768.65	215959.85	-6.55	WB
5687	3631768.57	215962.62	-6.53	WB
5688	3631768.48	215965.39	-6.50	WB
5689	3631768.38	215968.19	-6.48	WB
5690	3631768.29	215970.94	-6.45	WB
5691	3631768.19	215973.77	-6.44	WB
5692	3631768.09	215976.67	-6.42	WB
5693	3631768.09	215977.02	-6.41	WB
5694	3631768.06	215979.56	-6.39	WB
5695	3631768.03	215982.46	-6.39	WB
5696	3631768.02	215985.49	-6.38	WB
5697	3631768.02	215988.56	-6.37	WB
5698	3631768.05	215991.63	-6.37	WB
5699	3631768.19	215994.74	-6.34	WB
5700	3631768.34	215997.84	-6.34	WB
5701	3631768.61	216000.97	-6.33	WB
5702	3631768.77	216002.54	-6.34	WB
5703	3631768.93	216004.06	-6.36	WB
5704	3631769.27	216007.15	-6.38	WB
5705	3631769.64	216010.31	-6.40	WB
5706	3631770.02	216013.52	-6.43	WB
5707	3631770.30	216016.68	-6.48	WB
5708	3631770.55	216019.95	-6.53	WB
5709	3631770.78	216023.35	-6.56	WB
5710	3631770.94	216026.73	-6.57	WB
5711	3631770.96	216027.18	-6.57	WB
5712	3631771.09	216030.22	-6.56	WB
5713	3631771.15	216033.71	-6.54	WB
5714	3631771.18	216037.18	-6.53	WB
5715	3631771.20	216040.78	-6.51	WB
5716	3631771.22	216044.19	-6.47	WB
5717	3631771.24	216047.60	-6.44	WB
5718	3631771.17	216050.98	-6.41	WB
5719	3631771.16	216051.77	-6.38	WB
5720	3631771.11	216054.30	-6.35	WB
5721	3631771.06	216057.53	-6.32	WB
5722	3631771.03	216060.67	-6.29	WB
5723	3631771.01	216063.78	-6.25	WB
5724	3631770.95	216066.72	-6.22	WB
5725	3631770.90	216069.66	-6.19	WB
5726	3631770.82	216072.58	-6.16	WB
5727	3631770.73	216075.43	-6.12	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
5728	3631770.69	216076.83	-6.09	WB
5729	3631770.64	216078.30	-6.06	WB
5730	3631770.56	216081.02	-6.03	WB
5731	3631770.47	216083.78	-6.00	WB
5732	3631770.36	216086.54	-5.97	WB
5733	3631770.24	216089.24	-5.94	WB
5734	3631770.11	216092.02	-5.91	WB
5735	3631769.93	216094.75	-5.89	WB
5736	3631769.75	216097.44	-5.88	WB
5737	3631769.49	216100.26	-5.88	WB
5738	3631769.36	216101.64	-5.89	WB
5739	3631769.22	216103.07	-5.90	WB
5740	3631768.90	216105.87	-5.91	WB
5741	3631768.48	216108.83	-5.92	WB
5742	3631768.06	216111.85	-5.93	WB
5743	3631767.64	216114.97	-5.94	WB
5744	3631767.22	216118.12	-5.97	WB
5745	3631766.85	216121.41	-5.97	WB
5746	3631766.60	216124.67	-5.97	WB
5747	3631766.40	216127.18	-5.98	WB
5748	3631766.34	216127.97	-6.01	WB
5749	3631766.20	216131.46	-6.03	WB
5750	3631766.06	216134.84	-6.07	WB
5751	3631765.98	216138.35	-6.08	WB
5752	3631765.93	216141.84	-6.09	WB
5753	3631765.89	216145.27	-6.10	WB
5754	3631765.87	216148.76	-6.10	WB
5755	3631765.84	216152.25	-6.10	WB
5756	3631765.81	216155.67	-6.08	WB
5757	3631765.77	216159.23	-6.03	WB
5758	3631765.73	216162.62	-5.99	WB
5759	3631765.75	216166.02	-5.93	WB
5760	3631765.78	216169.34	-5.90	WB
5761	3631765.87	216172.55	-5.87	WB
5762	3631766.01	216175.69	-5.83	WB
5763	3631766.08	216177.29	-5.80	WB
5764	3631766.17	216178.76	-5.78	WB
5765	3631766.39	216181.74	-5.76	WB
5766	3631766.62	216184.71	-5.76	WB
5767	3631766.85	216187.67	-5.75	WB
5768	3631767.07	216190.53	-5.74	WB
5769	3631767.28	216193.44	-5.73	WB
5770	3631767.47	216196.34	-5.72	WB
5771	3631767.65	216199.16	-5.70	WB
5772	3631767.82	216202.05	-5.68	WB
5773	3631767.98	216204.91	-5.67	WB
5774	3631768.14	216207.76	-5.66	WB
5775	3631768.29	216210.67	-5.65	WB
5776	3631768.45	216213.53	-5.64	WB
5777	3631768.65	216216.36	-5.63	WB
5778	3631768.87	216219.31	-5.62	WB
5779	3631769.11	216222.12	-5.62	WB
5780	3631769.37	216225.01	-5.61	WB
5781	3631769.54	216226.75	-5.60	WB
5782	3631769.64	216227.82	-5.59	WB
5783	3631769.87	216230.71	-5.58	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
5784	3631770.11	216233.70	-5.57	WB
5785	3631770.28	216236.67	-5.55	WB
5786	3631770.39	216239.70	-5.54	WB
5787	3631770.47	216242.77	-5.53	WB
5788	3631770.44	216245.88	-5.52	WB
5789	3631770.40	216249.00	-5.50	WB
5790	3631770.33	216251.75	-5.49	WB
5791	3631770.32	216252.13	-5.48	WB
5792	3631770.22	216255.25	-5.46	WB
5793	3631770.12	216258.43	-5.44	WB
5794	3631770.00	216261.64	-5.43	WB
5795	3631769.88	216264.77	-5.41	WB
5796	3631769.72	216272.76	-5.39	WB
5797	3631769.77	216275.80	-5.38	WB
5798	3631769.81	216277.06	-5.36	WB
5799	3631769.86	216278.95	-5.35	WB
5800	3631769.98	216282.03	-5.33	WB
5801	3631770.15	216285.05	-5.31	WB
5802	3631770.33	216288.15	-5.30	WB
5803	3631770.57	216291.19	-5.29	WB
5804	3631770.82	216294.22	-5.27	WB
5805	3631771.07	216297.21	-5.26	WB
5806	3631771.33	216300.18	-5.25	WB
5807	3631771.49	216302.04	-5.24	WB
5808	3631771.59	216303.14	-5.23	WB
5809	3631771.82	216306.07	-5.22	WB
5810	3631772.05	216308.99	-5.21	WB
5811	3631772.25	216311.90	-5.20	WB
5812	3631772.42	216314.85	-5.19	WB
5813	3631772.58	216317.72	-5.19	WB
5814	3631772.63	216320.64	-5.18	WB
5815	3631772.67	216323.61	-5.17	WB
5816	3631772.64	216326.57	-5.17	WB
5817	3631772.56	216329.64	-5.16	WB
5818	3631772.46	216332.68	-5.15	WB
5819	3631772.30	216335.70	-5.15	WB
5820	3631772.14	216338.84	-5.14	WB
5821	3631771.99	216341.96	-5.13	WB
5822	3631771.85	216345.03	-5.13	WB
5823	3631771.72	216348.24	-5.12	WB
5824	3631771.59	216351.41	-5.11	WB
5825	3631771.57	216351.79	-5.10	WB
5826	3631771.46	216354.59	-5.09	WB
5827	3631771.34	216357.79	-5.08	WB
5828	3631771.20	216361.05	-5.07	WB
5829	3631771.07	216364.31	-5.05	WB
5830	3631770.94	216367.60	-5.04	WB
5831	3631770.81	216370.91	-5.03	WB
5832	3631770.69	216374.24	-5.01	WB
5833	3631770.61	216376.72	-5.00	WB
5834	3631770.58	216377.62	-4.98	WB
5835	3631770.48	216380.84	-4.97	WB
5836	3631770.41	216384.05	-4.95	WB
5837	3631770.35	216387.32	-4.93	WB
5838	3631770.32	216390.36	-4.91	WB
5839	3631770.28	216393.45	-4.90	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
5840	3631770.28	216396.57	-4.88	WB
5841	3631770.31	216399.56	-4.86	WB
5842	3631770.34	216402.19	-4.84	WB
5843	3631770.35	216402.53	-4.83	WB
5844	3631770.44	216405.38	-4.81	WB
5845	3631770.53	216408.22	-4.80	WB
5846	3631770.65	216411.00	-4.78	WB
5847	3631770.78	216413.75	-4.77	WB
5848	3631770.90	216416.51	-4.76	WB
5849	3631770.96	216419.26	-4.75	WB
5850	3631771.01	216422.06	-4.73	WB
5851	3631771.06	216424.82	-4.72	WB
5852	3631771.10	216426.92	-4.72	WB
5853	3631771.12	216427.62	-4.71	WB
5854	3631771.17	216430.38	-4.70	WB
5855	3631771.20	216433.18	-4.69	WB
5856	3631771.22	216436.04	-4.68	WB
5857	3631771.23	216438.87	-4.68	WB
5858	3631771.23	216441.74	-4.67	WB
5859	3631771.23	216444.70	-4.66	WB
5860	3631771.22	216447.65	-4.65	WB
5861	3631771.18	216450.76	-4.65	WB
5862	3631771.17	216451.84	-4.64	WB
5863	3631771.14	216453.82	-4.63	WB
5864	3631771.08	216456.96	-4.62	WB
5865	3631771.04	216460.23	-4.61	WB
5866	3631771.01	216463.40	-4.60	WB
5867	3631770.98	216466.68	-4.58	WB
5868	3631770.99	216469.93	-4.57	WB
5869	3631771.01	216473.13	-4.56	WB
5870	3631771.03	216476.46	-4.54	WB
5871	3631771.04	216477.22	-4.53	WB
5872	3631771.07	216479.61	-4.52	WB
5873	3631771.13	216482.82	-4.50	WB
5874	3631771.26	216485.94	-4.49	WB
5875	3631771.39	216489.00	-4.47	WB
5876	3631771.52	216492.13	-4.46	WB
5877	3631771.65	216495.15	-4.45	WB
5878	3631771.78	216498.08	-4.44	WB
5879	3631771.92	216501.08	-4.43	WB
5880	3631771.98	216502.18	-4.42	WB
5881	3631772.07	216504.03	-4.41	WB
5882	3631772.19	216506.95	-4.40	WB
5883	3631772.30	216509.86	-4.39	WB
5884	3631772.41	216512.79	-4.38	WB
5885	3631772.48	216515.75	-4.38	WB
5886	3631772.54	216518.76	-4.37	WB
5887	3631772.61	216521.92	-4.36	WB
5888	3631772.66	216525.03	-4.36	WB
5889	3631772.68	216527.03	-4.35	WB
5890	3631772.69	216528.30	-4.34	WB
5891	3631772.69	216531.58	-4.34	WB
5892	3631772.70	216534.81	-4.33	WB
5893	3631772.75	216538.18	-4.32	WB
5894	3631772.80	216541.47	-4.32	WB
5895	3631772.87	216544.72	-4.31	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
5896	3631772.96	216548.06	-4.30	WB
5897	3631773.04	216551.35	-4.29	WB
5898	3631773.08	216552.18	-4.27	WB
5899	3631773.19	216554.69	-4.26	WB
5900	3631773.33	216557.99	-4.24	WB
5901	3631773.48	216561.25	-4.22	WB
5902	3631773.64	216564.48	-4.19	WB
5903	3631773.80	216567.67	-4.17	WB
5904	3631774.02	216570.80	-4.14	WB
5905	3631774.25	216573.93	-4.11	WB
5906	3631774.48	216577.04	-4.08	WB
5907	3631774.70	216579.97	-4.05	WB
5908	3631774.91	216582.97	-4.02	WB
5909	3631775.08	216585.85	-3.99	WB
5910	3631775.25	216588.72	-3.96	WB
5911	3631775.41	216591.52	-3.93	WB
5912	3631775.57	216594.20	-3.90	WB
5913	3631775.71	216596.85	-3.87	WB
5914	3631775.81	216599.55	-3.84	WB
5915	3631775.89	216601.79	-3.82	WB
5916	3631775.90	216602.14	-3.79	WB
5917	3631775.96	216604.76	-3.76	WB
5918	3631776.01	216607.33	-3.74	WB
5919	3631776.02	216609.86	-3.71	WB
5920	3631775.97	216612.45	-3.69	WB
5921	3631775.92	216615.01	-3.67	WB
5922	3631775.83	216617.49	-3.64	WB
5923	3631775.72	216620.11	-3.62	WB
5924	3631775.60	216622.65	-3.60	WB
5925	3631775.45	216625.30	-3.57	WB
5926	3631775.37	216626.58	-3.54	WB
5927	3631775.29	216627.95	-3.51	WB
5928	3631775.16	216630.58	-3.48	WB
5929	3631775.02	216633.29	-3.45	WB
5930	3631774.94	216635.99	-3.42	WB
5931	3631774.90	216638.74	-3.39	WB
5932	3631774.87	216641.53	-3.36	WB
5933	3631774.88	216644.35	-3.32	WB
5934	3631774.89	216647.15	-3.29	WB
5935	3631774.95	216649.99	-3.26	WB
5936	3631774.99	216651.86	-3.22	WB
5937	3631775.02	216652.89	-3.19	WB
5938	3631775.11	216655.81	-3.16	WB
5939	3631775.22	216658.88	-3.12	WB
5940	3631775.34	216661.85	-3.09	WB
5941	3631775.47	216664.93	-3.05	WB
5942	3631775.61	216668.06	-3.01	WB
5943	3631775.76	216671.11	-2.98	WB
5944	3631775.91	216674.32	-2.94	WB
5945	3631776.01	216676.61	-2.90	WB
5946	3631776.05	216677.40	-2.87	WB
5947	3631776.10	216680.50	-2.83	WB
5948	3631776.13	216683.76	-2.80	WB
5949	3631776.08	216686.87	-2.77	WB
5950	3631775.90	216690.11	-2.74	WB
5951	3631775.72	216693.29	-2.72	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
5952	3631775.48	216696.37	-2.70	WB
5953	3631775.24	216699.54	-2.68	WB
5954	3631775.08	216701.51	-2.66	WB
5955	3631774.97	216702.62	-2.65	WB
5956	3631774.70	216705.56	-2.64	WB
5957	3631774.42	216708.61	-2.64	WB
5958	3631773.89	216714.99	-2.63	WB
5959	3631773.68	216717.78	-2.63	WB
5960	3631773.45	216720.63	-2.62	WB
5961	3631773.22	216723.38	-2.62	WB
5962	3631772.99	216726.18	-2.62	WB
5963	3631772.74	216728.96	-2.62	WB
5964	3631772.53	216731.68	-2.62	WB
5965	3631772.31	216734.46	-2.62	WB
5966	3631772.14	216737.08	-2.62	WB
5967	3631772.03	216739.70	-2.61	WB
5968	3631771.94	216742.35	-2.61	WB
5969	3631772.00	216744.80	-2.61	WB
5970	3631772.07	216747.19	-2.62	WB
5971	3631772.25	216749.39	-2.62	WB
5972	3631772.50	216751.47	-2.62	WB
5973	3631772.60	216752.23	-2.63	WB
5974	3631772.78	216753.49	-2.64	WB
5975	3631773.09	216755.25	-2.65	WB
5976	3631773.42	216757.01	-2.66	WB
5977	3631773.70	216758.64	-2.67	WB
5978	3631773.96	216760.30	-2.69	WB
5979	3631774.19	216761.91	-2.70	WB
5980	3631774.36	216763.50	-2.72	WB
5981	3631774.52	216765.11	-2.74	WB
5982	3631774.60	216766.68	-2.76	WB
5983	3631774.65	216768.27	-2.77	WB
5984	3631774.68	216769.95	-2.79	WB
5985	3631774.67	216771.69	-2.81	WB
5986	3631774.64	216773.47	-2.83	WB
5987	3631774.54	216775.27	-2.85	WB
5988	3631774.45	216776.66	-2.86	WB
5989	3631774.42	216777.11	-2.87	WB
5990	3631774.30	216779.04	-2.87	WB
5991	3631774.18	216781.02	-2.87	WB
5992	3631272.09	215630.75	-7.96	WB
5993	3631270.88	215633.57	-7.96	WB
5994	3631269.71	215636.39	-7.96	WB
5995	3631268.90	215638.99	-7.97	WB
5996	3631268.33	215641.46	-7.97	WB
5997	3631267.85	215643.87	-7.97	WB
5998	3631267.80	215645.99	-7.98	WB
5999	3631267.77	215648.05	-7.98	WB
6000	3631267.89	215650.07	-7.99	WB
6001	3631268.06	215651.98	-8.00	WB
6002	3631268.30	215653.93	-8.01	WB
6003	3631268.72	215655.97	-8.02	WB
6004	3631269.13	215657.95	-8.03	WB
6005	3631269.65	215660.18	-8.04	WB
6006	3631270.18	215662.44	-8.05	WB
6007	3631270.25	215662.72	-8.06	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
6008	3631270.73	215664.73	-8.07	WB
6009	3631271.36	215667.34	-8.08	WB
6010	3631272.00	215669.89	-8.08	WB
6011	3631272.63	215672.63	-8.09	WB
6012	3631273.30	215675.48	-8.09	WB
6013	3631273.93	215678.34	-8.10	WB
6014	3631274.50	215681.21	-8.10	WB
6015	3631275.12	215684.15	-8.10	WB
6016	3631275.58	215686.56	-8.09	WB
6017	3631275.65	215686.93	-8.09	WB
6018	3631276.19	215689.73	-8.08	WB
6019	3631276.64	215692.48	-8.07	WB
6020	3631276.98	215695.12	-8.06	WB
6021	3631277.27	215697.81	-8.05	WB
6022	3631277.19	215700.41	-8.03	WB
6023	3631277.09	215702.97	-8.02	WB
6024	3631276.93	215705.46	-8.01	WB
6025	3631276.71	215708.04	-7.99	WB
6026	3631276.49	215710.56	-7.98	WB
6027	3631276.45	215710.90	-7.96	WB
6028	3631276.19	215713.11	-7.95	WB
6029	3631275.88	215715.67	-7.94	WB
6030	3631275.53	215718.27	-7.93	WB
6031	3631275.14	215720.91	-7.92	WB
6032	3631274.76	215723.59	-7.91	WB
6033	3631274.42	215726.24	-7.90	WB
6034	3631274.08	215728.91	-7.89	WB
6035	3631273.71	215731.77	-7.88	WB
6036	3631273.35	215734.57	-7.88	WB
6037	3631273.16	215736.00	-7.88	WB
6038	3631272.98	215737.45	-7.87	WB
6039	3631272.13	215744.21	-7.87	WB
6040	3631271.74	215747.33	-7.87	WB
6041	3631271.33	215750.51	-7.86	WB
6042	3631270.90	215753.81	-7.86	WB
6043	3631270.48	215757.04	-7.85	WB
6044	3631270.04	215760.34	-7.85	WB
6045	3631269.88	215761.53	-7.84	WB
6046	3631269.61	215763.56	-7.83	WB
6047	3631269.19	215766.73	-7.82	WB
6048	3631268.87	215769.82	-7.81	WB
6049	3631268.57	215772.92	-7.80	WB
6050	3631268.32	215775.92	-7.79	WB
6051	3631268.15	215778.84	-7.78	WB
6052	3631267.98	215781.80	-7.76	WB
6053	3631267.91	215784.66	-7.75	WB
6054	3631267.88	215786.48	-7.74	WB
6055	3631267.86	215787.61	-7.73	WB
6056	3631267.81	215790.56	-7.71	WB
6057	3631267.79	215793.49	-7.70	WB
6058	3631267.77	215796.51	-7.69	WB
6059	3631267.79	215799.49	-7.68	WB
6060	3631267.82	215802.48	-7.68	WB
6061	3631267.87	215805.43	-7.67	WB
6062	3631267.96	215808.34	-7.66	WB
6063	3631268.06	215811.24	-7.66	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
6064	3631268.09	215811.98	-7.65	WB
6065	3631268.18	215814.13	-7.65	WB
6066	3631268.31	215817.01	-7.65	WB
6067	3631268.46	215819.86	-7.65	WB
6068	3631268.64	215822.81	-7.65	WB
6069	3631268.82	215825.68	-7.65	WB
6070	3631269.02	215828.60	-7.65	WB
6071	3631269.24	215831.56	-7.65	WB
6072	3631269.48	215834.46	-7.66	WB
6073	3631269.67	215836.71	-7.66	WB
6074	3631269.73	215837.42	-7.66	WB
6075	3631269.97	215840.42	-7.65	WB
6076	3631270.14	215843.41	-7.64	WB
6077	3631270.31	215846.55	-7.63	WB
6078	3631270.43	215849.54	-7.62	WB
6079	3631270.53	215852.50	-7.61	WB
6080	3631270.63	215855.57	-7.59	WB
6081	3631270.73	215858.46	-7.58	WB
6082	3631270.83	215861.41	-7.58	WB
6083	3631270.84	215861.76	-7.57	WB
6084	3631270.97	215864.34	-7.56	WB
6085	3631271.10	215867.17	-7.55	WB
6086	3631271.26	215870.09	-7.54	WB
6087	3631271.45	215872.95	-7.53	WB
6088	3631271.63	215875.77	-7.52	WB
6089	3631271.88	215878.59	-7.52	WB
6090	3631272.14	215881.47	-7.51	WB
6091	3631272.42	215884.26	-7.51	WB
6092	3631272.73	215887.07	-7.51	WB
6093	3631273.06	215889.90	-7.50	WB
6094	3631273.38	215892.65	-7.50	WB
6095	3631273.73	215895.45	-7.50	WB
6096	3631274.04	215898.34	-7.50	WB
6097	3631274.32	215901.17	-7.49	WB
6098	3631274.59	215904.13	-7.49	WB
6099	3631274.67	215907.16	-7.49	WB
6100	3631274.75	215910.15	-7.49	WB
6101	3631274.78	215911.33	-7.49	WB
6102	3631274.77	215913.29	-7.48	WB
6103	3631274.75	215916.40	-7.48	WB
6104	3631274.71	215919.56	-7.48	WB
6105	3631274.59	215922.65	-7.47	WB
6106	3631274.47	215925.75	-7.46	WB
6107	3631274.33	215928.84	-7.45	WB
6108	3631274.19	215931.92	-7.44	WB
6109	3631274.05	215934.98	-7.43	WB
6110	3631273.99	215936.46	-7.42	WB
6111	3631273.92	215938.00	-7.41	WB
6112	3631273.79	215941.07	-7.39	WB
6113	3631273.70	215943.96	-7.38	WB
6114	3631273.62	215946.87	-7.36	WB
6115	3631273.55	215949.80	-7.34	WB
6116	3631273.49	215952.61	-7.33	WB
6117	3631273.43	215955.47	-7.31	WB
6118	3631273.40	215958.31	-7.29	WB
6119	3631273.37	215961.07	-7.27	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
6120	3631273.37	215961.45	-7.26	WB
6121	3631273.34	215963.91	-7.24	WB
6122	3631273.30	215966.70	-7.23	WB
6123	3631273.26	215969.46	-7.21	WB
6124	3631273.30	215972.25	-7.20	WB
6125	3631273.34	215975.00	-7.19	WB
6126	3631273.45	215977.72	-7.18	WB
6127	3631273.60	215980.46	-7.17	WB
6128	3631273.77	215983.21	-7.16	WB
6129	3631274.02	215985.94	-7.15	WB
6130	3631274.10	215986.68	-7.14	WB
6131	3631274.29	215988.69	-7.14	WB
6132	3631274.54	215991.56	-7.13	WB
6133	3631274.77	215994.41	-7.13	WB
6134	3631274.97	215997.36	-7.12	WB
6135	3631275.09	216000.53	-7.11	WB
6136	3631275.19	216003.63	-7.11	WB
6137	3631275.25	216006.98	-7.10	WB
6138	3631275.29	216010.21	-7.10	WB
6139	3631275.31	216011.83	-7.09	WB
6140	3631275.32	216013.48	-7.08	WB
6141	3631275.34	216016.94	-7.07	WB
6142	3631275.36	216020.25	-7.06	WB
6143	3631275.38	216023.59	-7.05	WB
6144	3631275.41	216026.93	-7.03	WB
6145	3631275.45	216030.07	-7.02	WB
6146	3631275.54	216033.21	-7.00	WB
6147	3631275.63	216036.37	-6.99	WB
6148	3631275.76	216039.25	-6.97	WB
6149	3631275.89	216042.16	-6.95	WB
6150	3631276.03	216045.06	-6.93	WB
6151	3631276.19	216047.72	-6.91	WB
6152	3631276.35	216050.43	-6.89	WB
6153	3631276.56	216053.07	-6.87	WB
6154	3631276.75	216055.65	-6.86	WB
6155	3631276.95	216058.27	-6.84	WB
6156	3631277.13	216060.92	-6.82	WB
6157	3631277.15	216061.27	-6.80	WB
6158	3631277.29	216063.50	-6.78	WB
6159	3631277.34	216066.28	-6.77	WB
6160	3631277.39	216068.94	-6.75	WB
6161	3631277.40	216071.69	-6.74	WB
6162	3631277.39	216074.51	-6.72	WB
6163	3631277.38	216077.26	-6.71	WB
6164	3631277.41	216080.16	-6.70	WB
6165	3631277.43	216083.02	-6.69	WB
6166	3631277.35	216085.92	-6.68	WB
6167	3631277.34	216086.32	-6.66	WB
6168	3631277.23	216088.93	-6.65	WB
6169	3631277.11	216091.91	-6.65	WB
6170	3631277.00	216094.91	-6.64	WB
6171	3631276.90	216097.90	-6.63	WB
6172	3631276.79	216100.95	-6.63	WB
6173	3631276.68	216103.98	-6.63	WB
6174	3631276.57	216107.04	-6.63	WB
6175	3631276.46	216110.02	-6.62	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
6176	3631276.41	216111.55	-6.62	WB
6177	3631276.35	216113.08	-6.62	WB
6178	3631276.23	216116.20	-6.62	WB
6179	3631276.11	216119.28	-6.62	WB
6180	3631275.98	216122.34	-6.61	WB
6181	3631275.83	216125.42	-6.61	WB
6182	3631275.67	216128.50	-6.61	WB
6183	3631275.50	216131.68	-6.61	WB
6184	3631275.32	216134.78	-6.61	WB
6185	3631275.24	216136.33	-6.60	WB
6186	3631275.13	216137.93	-6.60	WB
6187	3631274.90	216141.14	-6.60	WB
6188	3631274.70	216144.27	-6.59	WB
6189	3631274.63	216147.48	-6.59	WB
6190	3631274.55	216150.73	-6.58	WB
6191	3631274.51	216153.95	-6.57	WB
6192	3631274.50	216157.30	-6.56	WB
6193	3631274.51	216160.49	-6.55	WB
6194	3631274.54	216161.70	-6.54	WB
6195	3631274.58	216163.67	-6.52	WB
6196	3631274.64	216167.00	-6.51	WB
6197	3631274.71	216170.19	-6.49	WB
6198	3631274.79	216173.49	-6.47	WB
6199	3631274.88	216176.66	-6.46	WB
6200	3631275.21	216184.09	-6.44	WB
6201	3631275.33	216186.72	-6.43	WB
6202	3631275.35	216187.07	-6.41	WB
6203	3631275.51	216190.14	-6.40	WB
6204	3631275.70	216193.05	-6.38	WB
6205	3631275.92	216195.94	-6.37	WB
6206	3631276.14	216198.75	-6.36	WB
6207	3631276.35	216201.51	-6.34	WB
6208	3631276.57	216204.26	-6.33	WB
6209	3631276.70	216206.96	-6.32	WB
6210	3631276.82	216209.62	-6.30	WB
6211	3631276.89	216211.29	-6.29	WB
6212	3631276.90	216212.28	-6.28	WB
6213	3631276.93	216214.93	-6.27	WB
6214	3631276.94	216217.59	-6.26	WB
6215	3631276.83	216220.24	-6.25	WB
6216	3631276.70	216222.96	-6.24	WB
6217	3631276.52	216225.61	-6.24	WB
6218	3631276.28	216228.32	-6.23	WB
6219	3631276.04	216231.07	-6.22	WB
6220	3631275.71	216233.80	-6.22	WB
6221	3631275.45	216235.93	-6.21	WB
6222	3631275.36	216236.68	-6.21	WB
6223	3631274.96	216239.49	-6.20	WB
6224	3631274.49	216242.39	-6.20	WB
6225	3631274.01	216245.33	-6.20	WB
6226	3631273.52	216248.34	-6.20	WB
6227	3631273.01	216251.45	-6.20	WB
6228	3631272.57	216254.54	-6.19	WB
6229	3631272.15	216257.64	-6.19	WB
6230	3631271.75	216260.86	-6.19	WB
6231	3631271.67	216261.63	-6.19	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
6232	3631271.43	216264.07	-6.19	WB
6233	3631271.12	216267.27	-6.19	WB
6234	3631270.88	216270.56	-6.19	WB
6235	3631270.67	216273.82	-6.18	WB
6236	3631270.47	216277.11	-6.18	WB
6237	3631270.29	216280.50	-6.17	WB
6238	3631270.10	216283.90	-6.17	WB
6239	3631270.00	216286.56	-6.16	WB
6240	3631269.97	216287.40	-6.15	WB
6241	3631269.83	216290.94	-6.14	WB
6242	3631269.73	216294.51	-6.12	WB
6243	3631269.69	216298.11	-6.11	WB
6244	3631269.65	216301.76	-6.09	WB
6245	3631269.73	216305.17	-6.08	WB
6246	3631269.81	216308.62	-6.06	WB
6247	3631269.97	216312.01	-6.04	WB
6248	3631270.18	216315.16	-6.02	WB
6249	3631270.39	216318.42	-5.99	WB
6250	3631270.59	216321.40	-5.97	WB
6251	3631270.79	216324.33	-5.95	WB
6252	3631271.02	216327.18	-5.93	WB
6253	3631271.26	216329.93	-5.90	WB
6254	3631271.51	216332.65	-5.88	WB
6255	3631271.74	216335.26	-5.86	WB
6256	3631271.87	216336.86	-5.84	WB
6257	3631271.96	216337.88	-5.81	WB
6258	3631272.13	216340.48	-5.80	WB
6259	3631272.28	216343.02	-5.78	WB
6260	3631272.42	216345.56	-5.76	WB
6261	3631272.56	216348.12	-5.75	WB
6262	3631272.69	216350.67	-5.73	WB
6263	3631272.82	216353.29	-5.72	WB
6264	3631272.96	216355.90	-5.71	WB
6265	3631273.11	216358.61	-5.70	WB
6266	3631273.30	216361.30	-5.69	WB
6267	3631273.35	216361.98	-5.69	WB
6268	3631273.49	216364.02	-5.68	WB
6269	3631273.72	216366.88	-5.68	WB
6270	3631273.96	216369.67	-5.68	WB
6271	3631274.20	216372.62	-5.68	WB
6272	3631274.43	216375.63	-5.67	WB
6273	3631274.66	216378.59	-5.67	WB
6274	3631274.86	216381.78	-5.67	WB
6275	3631275.06	216384.91	-5.67	WB
6276	3631275.17	216386.89	-5.67	WB
6277	3631275.22	216388.11	-5.67	WB
6278	3631275.35	216391.38	-5.67	WB
6279	3631275.47	216394.66	-5.67	WB
6280	3631275.54	216397.97	-5.67	WB
6281	3631275.61	216401.29	-5.67	WB
6282	3631275.68	216404.56	-5.67	WB
6283	3631275.75	216407.85	-5.66	WB
6284	3631275.83	216411.14	-5.66	WB
6285	3631275.84	216411.56	-5.65	WB
6286	3631275.89	216414.21	-5.65	WB
6287	3631275.97	216417.36	-5.64	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
6288	3631275.98	216420.42	-5.64	WB
6289	3631275.98	216423.36	-5.63	WB
6290	3631275.94	216426.36	-5.62	WB
6291	3631275.82	216429.28	-5.61	WB
6292	3631275.68	216432.18	-5.60	WB
6293	3631275.47	216435.17	-5.60	WB
6294	3631275.38	216436.21	-5.59	WB
6295	3631275.23	216438.03	-5.58	WB
6296	3631274.98	216440.93	-5.57	WB
6297	3631274.70	216443.92	-5.55	WB
6298	3631274.44	216446.78	-5.54	WB
6299	3631274.18	216449.79	-5.53	WB
6300	3631273.93	216452.76	-5.51	WB
6301	3631273.69	216455.70	-5.49	WB
6302	3631273.43	216458.76	-5.47	WB
6303	3631273.21	216461.38	-5.45	WB
6304	3631273.17	216461.79	-5.43	WB
6305	3631272.93	216464.85	-5.40	WB
6306	3631272.68	216467.92	-5.37	WB
6307	3631272.45	216470.96	-5.35	WB
6308	3631272.26	216473.98	-5.33	WB
6309	3631272.07	216477.05	-5.30	WB
6310	3631271.96	216480.11	-5.28	WB
6311	3631271.85	216483.08	-5.25	WB
6312	3631271.84	216486.06	-5.23	WB
6313	3631271.86	216487.18	-5.21	WB
6314	3631271.90	216488.99	-5.18	WB
6315	3631271.98	216491.78	-5.16	WB
6316	3631272.17	216494.58	-5.14	WB
6317	3631272.38	216497.32	-5.12	WB
6318	3631272.62	216500.01	-5.10	WB
6319	3631272.88	216502.73	-5.09	WB
6320	3631273.16	216505.40	-5.08	WB
6321	3631273.51	216508.06	-5.07	WB
6322	3631273.86	216510.70	-5.06	WB
6323	3631274.10	216512.39	-5.05	WB
6324	3631274.24	216513.40	-5.05	WB
6325	3631274.63	216516.09	-5.05	WB
6326	3631275.02	216518.82	-5.05	WB
6327	3631275.44	216521.63	-5.04	WB
6328	3631275.85	216524.43	-5.04	WB
6329	3631276.24	216527.30	-5.04	WB
6330	3631276.62	216530.22	-5.04	WB
6331	3631277.00	216533.14	-5.03	WB
6332	3631277.38	216536.11	-5.03	WB
6333	3631277.47	216536.80	-5.03	WB
6334	3631277.75	216538.99	-5.03	WB
6335	3631278.07	216541.95	-5.02	WB
6336	3631278.40	216544.92	-5.02	WB
6337	3631278.69	216547.80	-5.02	WB
6338	3631278.98	216550.79	-5.02	WB
6339	3631279.27	216553.75	-5.02	WB
6340	3631279.55	216556.58	-5.02	WB
6341	3631279.83	216559.49	-5.02	WB
6342	3631279.98	216561.29	-5.01	WB
6343	3631280.04	216562.37	-5.00	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
6344	3631280.19	216565.30	-4.99	WB
6345	3631280.32	216568.25	-4.98	WB
6346	3631280.31	216571.24	-4.97	WB
6347	3631280.30	216574.23	-4.96	WB
6348	3631280.22	216577.32	-4.94	WB
6349	3631280.11	216580.40	-4.93	WB
6350	3631279.98	216583.52	-4.91	WB
6351	3631279.83	216586.33	-4.90	WB
6352	3631279.81	216586.72	-4.88	WB
6353	3631279.64	216589.90	-4.87	WB
6354	3631279.48	216593.04	-4.85	WB
6355	3631279.32	216596.36	-4.83	WB
6356	3631279.17	216599.51	-4.82	WB
6357	3631279.01	216602.67	-4.80	WB
6358	3631278.85	216605.87	-4.78	WB
6359	3631278.70	216608.92	-4.76	WB
6360	3631278.58	216611.27	-4.74	WB
6361	3631278.54	216612.05	-4.72	WB
6362	3631278.37	216615.08	-4.70	WB
6363	3631277.95	216622.25	-4.68	WB
6364	3631277.77	216625.22	-4.67	WB
6365	3631277.59	216628.23	-4.65	WB
6366	3631277.34	216631.19	-4.63	WB
6367	3631277.05	216634.28	-4.62	WB
6368	3631276.87	216636.12	-4.61	WB
6369	3631276.76	216637.25	-4.59	WB
6370	3631276.47	216640.30	-4.58	WB
6371	3631276.16	216643.40	-4.56	WB
6372	3631275.90	216646.43	-4.55	WB
6373	3631275.64	216649.56	-4.53	WB
6374	3631275.41	216652.67	-4.51	WB
6375	3631275.24	216655.76	-4.49	WB
6376	3631275.07	216658.94	-4.47	WB
6377	3631275.06	216661.61	-4.45	WB
6378	3631275.06	216662.02	-4.43	WB
6379	3631275.06	216665.11	-4.40	WB
6380	3631275.15	216668.15	-4.38	WB
6381	3631275.29	216671.17	-4.36	WB
6382	3631275.45	216674.13	-4.34	WB
6383	3631275.73	216677.05	-4.32	WB
6384	3631276.02	216679.94	-4.30	WB
6385	3631276.39	216682.72	-4.29	WB
6386	3631276.81	216685.51	-4.27	WB
6387	3631277.07	216687.22	-4.25	WB
6388	3631277.23	216688.19	-4.24	WB
6389	3631277.67	216690.86	-4.22	WB
6390	3631278.11	216693.49	-4.20	WB
6391	3631278.53	216696.14	-4.19	WB
6392	3631278.93	216698.77	-4.18	WB
6393	3631279.32	216701.43	-4.17	WB
6394	3631279.66	216704.18	-4.16	WB
6395	3631280.00	216706.99	-4.16	WB
6396	3631280.24	216709.79	-4.15	WB
6397	3631280.42	216711.96	-4.15	WB
6398	3631280.47	216712.65	-4.16	WB
6399	3631280.70	216715.64	-4.16	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
6400	3631280.91	216718.58	-4.16	WB
6401	3631281.14	216721.64	-4.16	WB
6402	3631281.30	216724.58	-4.16	WB
6403	3631281.48	216727.60	-4.16	WB
6404	3631281.58	216730.68	-4.15	WB
6405	3631281.61	216733.75	-4.15	WB
6406	3631281.63	216736.13	-4.14	WB
6407	3631281.63	216736.93	-4.13	WB
6408	3631281.52	216740.14	-4.12	WB
6409	3631281.40	216743.31	-4.11	WB
6410	3631281.25	216746.62	-4.10	WB
6411	3631281.08	216749.86	-4.09	WB
6412	3631280.89	216753.12	-4.07	WB
6413	3631280.69	216756.46	-4.05	WB
6414	3631280.48	216759.71	-4.03	WB
6415	3631280.40	216760.99	-4.01	WB
6416	3631280.30	216763.01	-3.98	WB
6417	3631280.14	216766.23	-3.95	WB
6418	3631279.96	216769.46	-3.91	WB
6419	3631279.77	216772.58	-3.87	WB
6420	3631279.59	216775.70	-3.83	WB
6421	3631279.46	216778.62	-3.79	WB
6422	3631279.34	216781.62	-3.75	WB
6423	3631279.24	216784.52	-3.70	WB
6424	3631279.20	216786.27	-3.66	WB
6425	3631279.18	216787.31	-3.61	WB
6426	3631279.13	216790.09	-3.57	WB
6427	3631279.15	216792.68	-3.52	WB
6428	3631279.19	216795.24	-3.47	WB
6429	3631279.28	216797.73	-3.43	WB
6430	3631279.41	216800.03	-3.38	WB
6431	3631279.55	216802.34	-3.33	WB
6432	3631279.67	216804.61	-3.28	WB
6433	3631279.79	216806.82	-3.24	WB
6434	3631279.89	216809.11	-3.19	WB
6435	3631279.97	216811.32	-3.15	WB
6436	3631280.05	216813.59	-3.11	WB
6437	3631280.07	216815.95	-3.07	WB
6438	3631280.09	216818.24	-3.04	WB
6439	3631280.09	216820.64	-3.00	WB
6440	3631280.10	216823.06	-2.97	WB
6441	3631280.10	216825.49	-2.95	WB
6442	3631280.10	216828.08	-2.92	WB
6443	3631280.10	216830.62	-2.89	WB
6444	3631280.09	216833.28	-2.87	WB
6445	3631280.08	216836.02	-2.85	WB
6446	3631280.07	216836.35	-2.83	WB
6447	3631280.05	216838.85	-2.82	WB
6448	3631279.97	216841.74	-2.80	WB
6449	3631279.89	216844.73	-2.79	WB
6450	3631279.71	216847.82	-2.78	WB
6451	3631279.50	216850.90	-2.77	WB
6452	3631279.28	216853.94	-2.76	WB
6453	3631279.04	216856.97	-2.76	WB
6454	3631278.80	216859.99	-2.75	WB
6455	3631278.72	216861.16	-2.74	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
6456	3631278.59	216862.99	-2.73	WB
6457	3631278.39	216865.92	-2.73	WB
6458	3631278.19	216868.82	-2.72	WB
6459	3631278.01	216871.70	-2.72	WB
6460	3631277.82	216874.58	-2.71	WB
6461	3631277.64	216877.49	-2.71	WB
6462	3631277.45	216880.32	-2.70	WB
6463	3631277.32	216883.16	-2.70	WB
6464	3631277.22	216886.06	-2.69	WB
6465	3631277.19	216886.79	-2.69	WB
6466	3631277.14	216888.86	-2.68	WB
6467	3631277.20	216891.70	-2.68	WB
6468	3631277.25	216894.42	-2.67	WB
6469	3631277.42	216897.09	-2.66	WB
6470	3631277.65	216899.75	-2.66	WB
6471	3631277.90	216902.32	-2.65	WB
6472	3631278.25	216904.70	-2.64	WB
6473	3631278.60	216907.01	-2.64	WB
6474	3631279.00	216909.06	-2.63	WB
6475	3631279.43	216911.00	-2.63	WB
6476	3631279.70	216912.20	-2.62	WB
6477	3631279.86	216912.84	-2.62	WB
6478	3631280.29	216914.52	-2.61	WB
6479	3631280.72	216916.13	-2.61	WB
6480	3631281.10	216917.67	-2.61	WB
6481	3631281.47	216919.16	-2.61	WB
6482	3631281.84	216920.63	-2.61	WB
6483	3631282.20	216922.09	-2.61	WB
6484	3631282.54	216923.52	-2.61	WB
6485	3631282.84	216924.97	-2.62	WB
6486	3631283.13	216926.45	-2.62	WB
6487	3631283.42	216927.88	-2.63	WB
6488	3631283.70	216929.37	-2.63	WB
6489	3631283.98	216930.83	-2.63	WB
6490	3631284.26	216932.21	-2.63	WB
6491	3631284.55	216933.65	-2.64	WB
6492	3631284.75	216934.93	-2.65	WB
6493	3631284.91	216936.23	-2.65	WB
6494	3631284.94	216936.54	-2.66	WB
6495	3631285.05	216937.47	-2.67	WB
6496	3631285.18	216938.62	-2.67	WB
6497	3631285.32	216939.79	-2.66	WB
6498	3631285.44	216941.01	-2.65	WB
6499	3631285.55	216942.24	-2.64	WB
6500	3631285.66	216943.53	-2.63	WB
6501	3631285.73	216944.87	-2.62	WB
6502	3631285.81	216946.25	-2.61	WB
6503	3630778.40	215639.98	-8.72	WB
6504	3630777.38	215643.00	-8.71	WB
6505	3630776.37	215646.05	-8.71	WB
6506	3630775.88	215647.59	-8.70	WB
6507	3630775.55	215649.02	-8.69	WB
6508	3630774.89	215651.92	-8.69	WB
6509	3630774.27	215654.83	-8.68	WB
6510	3630773.95	215657.43	-8.68	WB
6511	3630773.65	215660.04	-8.67	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
6512	3630773.53	215662.55	-8.66	WB
6513	3630773.52	215664.92	-8.66	WB
6514	3630773.54	215667.34	-8.65	WB
6515	3630773.64	215669.70	-8.65	WB
6516	3630773.75	215672.01	-8.65	WB
6517	3630773.81	215673.18	-8.65	WB
6518	3630773.88	215674.44	-8.65	WB
6519	3630774.02	215676.86	-8.65	WB
6520	3630774.14	215679.23	-8.66	WB
6521	3630774.25	215681.75	-8.66	WB
6522	3630774.35	215684.24	-8.66	WB
6523	3630774.38	215686.85	-8.66	WB
6524	3630774.39	215689.52	-8.66	WB
6525	3630774.40	215692.16	-8.65	WB
6526	3630774.39	215694.95	-8.65	WB
6527	3630774.39	215697.69	-8.65	WB
6528	3630774.32	215700.52	-8.65	WB
6529	3630774.25	215703.47	-8.64	WB
6530	3630774.14	215706.42	-8.64	WB
6531	3630774.02	215709.41	-8.63	WB
6532	3630773.90	215712.40	-8.62	WB
6533	3630773.78	215715.42	-8.61	WB
6534	3630773.66	215718.41	-8.60	WB
6535	3630773.44	215721.48	-8.59	WB
6536	3630773.33	215722.61	-8.58	WB
6537	3630773.14	215724.50	-8.56	WB
6538	3630772.84	215727.50	-8.55	WB
6539	3630772.63	215730.43	-8.54	WB
6540	3630772.42	215733.32	-8.52	WB
6541	3630772.24	215736.07	-8.51	WB
6542	3630772.08	215738.87	-8.49	WB
6543	3630771.96	215741.56	-8.48	WB
6544	3630771.98	215744.13	-8.46	WB
6545	3630772.01	215746.71	-8.45	WB
6546	3630772.07	215748.22	-8.44	WB
6547	3630772.13	215749.14	-8.43	WB
6548	3630772.29	215751.58	-8.41	WB
6549	3630772.43	215754.07	-8.41	WB
6550	3630772.54	215756.54	-8.40	WB
6551	3630772.66	215759.04	-8.39	WB
6552	3630772.78	215761.65	-8.38	WB
6553	3630772.89	215764.19	-8.38	WB
6554	3630772.94	215766.82	-8.37	WB
6555	3630772.91	215769.59	-8.37	WB
6556	3630772.87	215772.28	-8.37	WB
6557	3630772.86	215772.63	-8.36	WB
6558	3630772.75	215775.15	-8.36	WB
6559	3630772.63	215778.02	-8.36	WB
6560	3630772.43	215780.90	-8.36	WB
6561	3630772.15	215783.94	-8.35	WB
6562	3630771.85	215786.96	-8.35	WB
6563	3630771.55	215790.04	-8.35	WB
6564	3630771.24	215793.20	-8.34	WB
6565	3630770.92	215796.32	-8.34	WB
6566	3630770.75	215797.86	-8.33	WB
6567	3630770.59	215799.45	-8.32	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
6568	3630770.28	215802.56	-8.32	WB
6569	3630770.06	215805.57	-8.31	WB
6570	3630769.86	215808.53	-8.30	WB
6571	3630769.72	215811.42	-8.29	WB
6572	3630769.63	215814.31	-8.28	WB
6573	3630769.54	215817.09	-8.27	WB
6574	3630769.49	215819.85	-8.26	WB
6575	3630769.44	215822.57	-8.25	WB
6576	3630769.40	215825.16	-8.23	WB
6577	3630769.36	215827.81	-8.22	WB
6578	3630769.28	215830.42	-8.21	WB
6579	3630769.13	215832.99	-8.20	WB
6580	3630768.97	215835.66	-8.19	WB
6581	3630768.70	215838.37	-8.18	WB
6582	3630768.40	215841.11	-8.17	WB
6583	3630768.04	215843.94	-8.16	WB
6584	3630767.61	215846.92	-8.15	WB
6585	3630767.44	215848.07	-8.14	WB
6586	3630767.17	215849.90	-8.13	WB
6587	3630766.77	215853.06	-8.12	WB
6588	3630766.39	215856.17	-8.11	WB
6589	3630766.10	215859.34	-8.10	WB
6590	3630765.93	215862.53	-8.09	WB
6591	3630765.77	215865.59	-8.08	WB
6592	3630765.83	215868.63	-8.07	WB
6593	3630765.90	215871.67	-8.06	WB
6594	3630765.98	215873.54	-8.04	WB
6595	3630766.07	215874.53	-8.03	WB
6596	3630766.32	215877.37	-8.02	WB
6597	3630766.58	215880.03	-8.01	WB
6598	3630766.91	215882.59	-8.00	WB
6599	3630767.24	215885.19	-7.99	WB
6600	3630767.56	215887.68	-7.98	WB
6601	3630767.88	215890.17	-7.97	WB
6602	3630768.18	215892.76	-7.95	WB
6603	3630768.42	215895.39	-7.94	WB
6604	3630768.65	215898.05	-7.93	WB
6605	3630768.67	215898.36	-7.92	WB
6606	3630768.88	215900.76	-7.91	WB
6607	3630769.11	215903.52	-7.90	WB
6608	3630769.35	215906.27	-7.89	WB
6609	3630769.66	215909.12	-7.87	WB
6610	3630769.98	215911.96	-7.86	WB
6611	3630770.35	215914.75	-7.86	WB
6612	3630770.75	215917.56	-7.85	WB
6613	3630771.16	215920.29	-7.85	WB
6614	3630771.59	215923.02	-7.86	WB
6615	3630771.71	215923.77	-7.87	WB
6616	3630772.05	215925.87	-7.87	WB
6617	3630772.47	215928.69	-7.89	WB
6618	3630772.87	215931.47	-7.89	WB
6619	3630773.24	215934.34	-7.90	WB
6620	3630773.56	215937.22	-7.90	WB
6621	3630773.87	215940.08	-7.90	WB
6622	3630774.15	215942.86	-7.90	WB
6623	3630774.45	215945.62	-7.89	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
6624	3630774.67	215947.98	-7.89	WB
6625	3630774.70	215948.31	-7.87	WB
6626	3630774.92	215951.00	-7.86	WB
6627	3630775.13	215953.71	-7.84	WB
6628	3630775.22	215956.37	-7.83	WB
6629	3630775.29	215959.15	-7.81	WB
6630	3630775.23	215961.88	-7.79	WB
6631	3630775.07	215964.58	-7.77	WB
6632	3630774.88	215967.43	-7.75	WB
6633	3630774.62	215970.30	-7.73	WB
6634	3630774.41	215972.46	-7.71	WB
6635	3630774.34	215973.16	-7.70	WB
6636	3630774.07	215976.16	-7.68	WB
6637	3630773.81	215979.14	-7.67	WB
6638	3630773.59	215982.15	-7.65	WB
6639	3630773.50	215985.15	-7.64	WB
6640	3630773.42	215988.13	-7.63	WB
6641	3630773.51	215991.08	-7.61	WB
6642	3630773.66	215993.99	-7.60	WB
6643	3630773.83	215996.87	-7.59	WB
6644	3630773.93	215998.28	-7.57	WB
6645	3630774.03	215999.72	-7.56	WB
6646	3630774.24	216002.61	-7.54	WB
6647	3630774.44	216005.37	-7.53	WB
6648	3630774.65	216008.14	-7.52	WB
6649	3630774.87	216010.93	-7.51	WB
6650	3630775.07	216013.61	-7.51	WB
6651	3630775.28	216016.37	-7.51	WB
6652	3630775.40	216019.11	-7.52	WB
6653	3630775.53	216021.82	-7.53	WB
6654	3630775.58	216022.93	-7.54	WB
6655	3630775.63	216024.64	-7.55	WB
6656	3630775.81	216031.37	-7.57	WB
6657	3630775.84	216034.26	-7.58	WB
6658	3630775.85	216037.20	-7.59	WB
6659	3630775.86	216040.28	-7.59	WB
6660	3630775.88	216043.31	-7.59	WB
6661	3630775.88	216046.47	-7.59	WB
6662	3630775.88	216047.63	-7.58	WB
6663	3630775.88	216049.59	-7.57	WB
6664	3630775.88	216052.71	-7.56	WB
6665	3630775.84	216055.90	-7.54	WB
6666	3630775.80	216059.05	-7.52	WB
6667	3630775.73	216062.16	-7.50	WB
6668	3630775.65	216065.24	-7.49	WB
6669	3630775.57	216068.30	-7.47	WB
6670	3630775.47	216071.31	-7.45	WB
6671	3630775.43	216072.84	-7.44	WB
6672	3630775.38	216074.32	-7.43	WB
6673	3630775.29	216077.30	-7.41	WB
6674	3630775.20	216080.24	-7.41	WB
6675	3630775.10	216083.22	-7.40	WB
6676	3630774.99	216086.12	-7.40	WB
6677	3630774.87	216089.02	-7.39	WB
6678	3630774.74	216092.02	-7.39	WB
6679	3630774.60	216094.96	-7.39	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
6680	3630774.48	216097.84	-7.38	WB
6681	3630774.40	216100.80	-7.38	WB
6682	3630774.32	216103.76	-7.37	WB
6683	3630774.20	216106.69	-7.35	WB
6684	3630774.08	216109.62	-7.34	WB
6685	3630773.97	216112.61	-7.32	WB
6686	3630773.89	216115.52	-7.30	WB
6687	3630773.79	216118.48	-7.28	WB
6688	3630773.70	216121.58	-7.27	WB
6689	3630773.67	216122.67	-7.25	WB
6690	3630773.61	216124.59	-7.24	WB
6691	3630773.55	216127.64	-7.22	WB
6692	3630773.53	216130.74	-7.21	WB
6693	3630773.52	216133.73	-7.20	WB
6694	3630773.58	216136.75	-7.18	WB
6695	3630773.64	216139.70	-7.17	WB
6696	3630773.72	216142.54	-7.16	WB
6697	3630773.80	216145.36	-7.15	WB
6698	3630773.87	216147.76	-7.14	WB
6699	3630773.87	216148.12	-7.13	WB
6700	3630773.88	216150.74	-7.12	WB
6701	3630773.89	216153.36	-7.12	WB
6702	3630773.83	216155.95	-7.11	WB
6703	3630773.74	216158.47	-7.10	WB
6704	3630773.61	216161.02	-7.10	WB
6705	3630773.38	216163.66	-7.09	WB
6706	3630773.16	216166.21	-7.09	WB
6707	3630772.89	216168.81	-7.08	WB
6708	3630772.61	216171.49	-7.08	WB
6709	3630772.54	216172.16	-7.07	WB
6710	3630772.29	216174.15	-7.07	WB
6711	3630771.87	216177.01	-7.06	WB
6712	3630771.45	216179.84	-7.06	WB
6713	3630770.97	216182.86	-7.05	WB
6714	3630770.46	216186.02	-7.05	WB
6715	3630769.92	216189.26	-7.04	WB
6716	3630769.33	216192.72	-7.03	WB
6717	3630768.73	216196.19	-7.02	WB
6718	3630768.49	216197.59	-7.01	WB
6719	3630768.11	216199.87	-7.00	WB
6720	3630767.50	216203.50	-6.99	WB
6721	3630766.99	216207.15	-6.98	WB
6722	3630766.57	216210.77	-6.97	WB
6723	3630766.17	216214.34	-6.95	WB
6724	3630765.87	216217.82	-6.94	WB
6725	3630765.59	216221.19	-6.92	WB
6726	3630765.46	216222.86	-6.90	WB
6727	3630765.37	216224.40	-6.89	WB
6728	3630765.20	216227.56	-6.87	WB
6729	3630765.04	216230.63	-6.85	WB
6730	3630764.95	216233.49	-6.83	WB
6731	3630764.84	216236.40	-6.81	WB
6732	3630764.74	216239.12	-6.80	WB
6733	3630764.63	216241.87	-6.78	WB
6734	3630764.53	216244.54	-6.76	WB
6735	3630764.50	216247.06	-6.74	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
6736	3630764.49	216248.09	-6.73	WB
6737	3630764.47	216249.64	-6.71	WB
6738	3630764.51	216252.16	-6.70	WB
6739	3630764.57	216254.68	-6.68	WB
6740	3630764.62	216257.21	-6.67	WB
6741	3630764.67	216259.82	-6.66	WB
6742	3630764.71	216262.45	-6.65	WB
6743	3630764.83	216265.10	-6.64	WB
6744	3630764.97	216267.77	-6.63	WB
6745	3630765.14	216270.42	-6.63	WB
6746	3630765.35	216273.17	-6.62	WB
6747	3630765.56	216275.95	-6.62	WB
6748	3630765.85	216278.79	-6.61	WB
6749	3630766.16	216281.70	-6.61	WB
6750	3630766.45	216284.67	-6.61	WB
6751	3630766.74	216287.70	-6.60	WB
6752	3630767.03	216290.87	-6.60	WB
6753	3630767.29	216294.09	-6.60	WB
6754	3630767.55	216297.42	-6.60	WB
6755	3630767.61	216298.20	-6.60	WB
6756	3630767.77	216300.81	-6.60	WB
6757	3630767.97	216304.23	-6.60	WB
6758	3630768.15	216307.78	-6.60	WB
6759	3630768.31	216311.32	-6.60	WB
6760	3630768.48	216314.84	-6.60	WB
6761	3630768.67	216318.28	-6.59	WB
6762	3630768.88	216321.66	-6.58	WB
6763	3630768.96	216322.92	-6.57	WB
6764	3630769.09	216324.96	-6.55	WB
6765	3630769.32	216328.14	-6.54	WB
6766	3630769.55	216331.32	-6.53	WB
6767	3630769.75	216334.31	-6.52	WB
6768	3630769.95	216337.29	-6.51	WB
6769	3630770.08	216340.13	-6.50	WB
6770	3630770.13	216342.92	-6.48	WB
6771	3630770.15	216345.70	-6.47	WB
6772	3630770.10	216347.39	-6.46	WB
6773	3630770.05	216348.39	-6.45	WB
6774	3630769.93	216351.11	-6.44	WB
6775	3630769.77	216353.78	-6.43	WB
6776	3630769.56	216356.42	-6.42	WB
6777	3630769.33	216359.17	-6.40	WB
6778	3630769.11	216361.93	-6.39	WB
6779	3630768.89	216364.66	-6.38	WB
6780	3630768.69	216367.50	-6.38	WB
6781	3630768.53	216370.31	-6.37	WB
6782	3630768.39	216373.12	-6.36	WB
6783	3630768.39	216375.89	-6.35	WB
6784	3630768.40	216378.65	-6.34	WB
6785	3630768.45	216381.39	-6.33	WB
6786	3630768.54	216384.12	-6.33	WB
6787	3630768.64	216386.88	-6.32	WB
6788	3630768.79	216389.75	-6.31	WB
6789	3630768.94	216392.66	-6.31	WB
6790	3630769.09	216395.62	-6.30	WB
6791	3630769.22	216398.31	-6.30	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
6792	3630769.24	216398.68	-6.29	WB
6793	3630769.38	216401.80	-6.28	WB
6794	3630769.50	216405.04	-6.28	WB
6795	3630769.62	216408.31	-6.27	WB
6796	3630769.78	216411.67	-6.27	WB
6797	3630769.95	216414.92	-6.26	WB
6798	3630770.13	216418.32	-6.25	WB
6799	3630770.32	216421.66	-6.25	WB
6800	3630770.41	216423.32	-6.24	WB
6801	3630770.51	216424.96	-6.23	WB
6802	3630770.67	216428.17	-6.22	WB
6803	3630770.84	216431.34	-6.21	WB
6804	3630771.00	216434.42	-6.21	WB
6805	3630771.16	216437.44	-6.20	WB
6806	3630771.32	216440.50	-6.19	WB
6807	3630771.36	216443.32	-6.18	WB
6808	3630771.39	216446.19	-6.17	WB
6809	3630771.40	216447.70	-6.15	WB
6810	3630771.38	216449.09	-6.14	WB
6811	3630771.32	216451.87	-6.13	WB
6812	3630771.25	216454.71	-6.12	WB
6813	3630771.09	216457.54	-6.11	WB
6814	3630770.93	216460.32	-6.10	WB
6815	3630770.72	216463.21	-6.09	WB
6816	3630770.18	216470.24	-6.07	WB
6817	3630770.02	216472.96	-6.06	WB
6818	3630769.88	216475.62	-6.05	WB
6819	3630769.81	216478.32	-6.04	WB
6820	3630769.75	216480.98	-6.03	WB
6821	3630769.66	216483.66	-6.02	WB
6822	3630769.56	216486.40	-6.01	WB
6823	3630769.45	216489.20	-6.00	WB
6824	3630769.34	216492.05	-5.99	WB
6825	3630769.22	216494.94	-5.98	WB
6826	3630769.10	216498.05	-5.97	WB
6827	3630768.98	216501.09	-5.96	WB
6828	3630768.86	216504.22	-5.96	WB
6829	3630768.74	216507.51	-5.95	WB
6830	3630768.63	216510.70	-5.94	WB
6831	3630768.55	216514.07	-5.93	WB
6832	3630768.47	216517.40	-5.92	WB
6833	3630768.41	216520.65	-5.91	WB
6834	3630768.37	216523.18	-5.91	WB
6835	3630768.35	216524.02	-5.90	WB
6836	3630768.31	216527.32	-5.89	WB
6837	3630768.33	216530.52	-5.88	WB
6838	3630768.35	216533.70	-5.87	WB
6839	3630768.38	216536.80	-5.86	WB
6840	3630768.40	216539.86	-5.85	WB
6841	3630768.42	216542.89	-5.84	WB
6842	3630768.40	216545.82	-5.84	WB
6843	3630768.38	216547.66	-5.83	WB
6844	3630768.37	216548.72	-5.82	WB
6845	3630768.31	216551.62	-5.81	WB
6846	3630768.23	216554.55	-5.80	WB
6847	3630768.13	216557.38	-5.79	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
6848	3630767.97	216560.24	-5.78	WB
6849	3630767.82	216563.04	-5.77	WB
6850	3630767.72	216565.82	-5.76	WB
6851	3630767.66	216568.64	-5.76	WB
6852	3630767.62	216571.38	-5.75	WB
6853	3630767.64	216573.07	-5.74	WB
6854	3630767.65	216574.07	-5.73	WB
6855	3630767.69	216576.75	-5.73	WB
6856	3630767.81	216579.53	-5.72	WB
6857	3630767.95	216582.31	-5.71	WB
6858	3630768.12	216585.15	-5.71	WB
6859	3630768.31	216588.10	-5.70	WB
6860	3630768.51	216591.03	-5.69	WB
6861	3630768.72	216594.23	-5.69	WB
6862	3630768.94	216597.36	-5.68	WB
6863	3630769.00	216598.21	-5.67	WB
6864	3630769.14	216600.64	-5.66	WB
6865	3630769.31	216604.11	-5.66	WB
6866	3630769.49	216607.47	-5.65	WB
6867	3630769.62	216611.10	-5.64	WB
6868	3630769.74	216614.58	-5.63	WB
6869	3630769.84	216618.02	-5.62	WB
6870	3630769.91	216621.61	-5.61	WB
6871	3630769.94	216622.93	-5.59	WB
6872	3630769.99	216625.12	-5.58	WB
6873	3630770.00	216628.40	-5.57	WB
6874	3630770.02	216631.78	-5.55	WB
6875	3630769.97	216634.96	-5.53	WB
6876	3630769.89	216638.05	-5.52	WB
6877	3630769.78	216641.09	-5.50	WB
6878	3630769.61	216643.91	-5.48	WB
6879	3630769.43	216646.74	-5.46	WB
6880	3630769.38	216647.46	-5.44	WB
6881	3630769.20	216649.45	-5.43	WB
6882	3630768.94	216652.10	-5.41	WB
6883	3630768.66	216654.73	-5.39	WB
6884	3630768.35	216657.28	-5.37	WB
6885	3630768.03	216659.76	-5.35	WB
6886	3630767.73	216662.25	-5.33	WB
6887	3630767.42	216664.74	-5.32	WB
6888	3630767.16	216667.14	-5.30	WB
6889	3630766.96	216669.54	-5.28	WB
6890	3630766.77	216671.96	-5.27	WB
6891	3630766.73	216673.14	-5.26	WB
6892	3630766.71	216674.32	-5.24	WB
6893	3630766.67	216676.75	-5.23	WB
6894	3630766.67	216679.12	-5.22	WB
6895	3630766.71	216681.44	-5.21	WB
6896	3630766.75	216683.81	-5.21	WB
6897	3630766.91	216686.16	-5.20	WB
6898	3630767.07	216688.47	-5.19	WB
6899	3630767.30	216690.90	-5.19	WB
6900	3630767.58	216693.47	-5.18	WB
6901	3630767.85	216695.98	-5.18	WB
6902	3630768.13	216698.64	-5.17	WB
6903	3630768.16	216698.99	-5.17	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
6904	3630768.48	216702.07	-5.17	WB
6905	3630768.82	216705.37	-5.16	WB
6906	3630769.19	216708.97	-5.16	WB
6907	3630769.58	216712.66	-5.15	WB
6908	3630770.03	216716.56	-5.15	WB
6909	3630770.51	216720.55	-5.14	WB
6910	3630770.97	216723.93	-5.14	WB
6911	3630771.04	216724.46	-5.13	WB
6912	3630771.61	216728.27	-5.12	WB
6913	3630772.21	216732.07	-5.11	WB
6914	3630772.78	216735.57	-5.09	WB
6915	3630773.37	216739.05	-5.08	WB
6916	3630773.79	216742.24	-5.07	WB
6917	3630774.16	216745.33	-5.05	WB
6918	3630774.41	216747.62	-5.03	WB
6919	3630774.43	216748.26	-5.01	WB
6920	3630774.51	216750.92	-4.99	WB
6921	3630774.58	216753.65	-4.97	WB
6922	3630774.51	216755.94	-4.95	WB
6923	3630774.39	216758.23	-4.92	WB
6924	3630774.20	216760.43	-4.90	WB
6925	3630773.91	216762.41	-4.87	WB
6926	3630773.59	216764.47	-4.85	WB
6927	3630773.20	216766.36	-4.82	WB
6928	3630772.79	216768.28	-4.79	WB
6929	3630772.34	216770.26	-4.76	WB
6930	3630771.88	216772.18	-4.73	WB
6931	3630771.40	216774.14	-4.70	WB
6932	3630770.92	216776.21	-4.68	WB
6933	3630770.45	216778.27	-4.65	WB
6934	3630769.97	216780.51	-4.62	WB
6935	3630769.53	216782.71	-4.59	WB
6936	3630769.11	216785.00	-4.56	WB
6937	3630768.82	216787.28	-4.53	WB
6938	3630768.55	216789.52	-4.51	WB
6939	3630768.33	216791.86	-4.50	WB
6940	3630768.16	216794.17	-4.49	WB
6941	3630767.99	216796.48	-4.49	WB
6942	3630767.90	216797.88	-4.49	WB
6943	3630767.84	216798.77	-4.49	WB
6944	3630767.70	216801.08	-4.48	WB
6945	3630767.61	216803.37	-4.48	WB
6946	3630767.55	216805.71	-4.49	WB
6947	3630767.48	216808.12	-4.49	WB
6948	3630767.41	216810.60	-4.50	WB
6949	3630767.33	216813.14	-4.51	WB
6950	3630767.31	216816.02	-4.52	WB
6951	3630767.28	216818.87	-4.53	WB
6952	3630767.26	216822.03	-4.54	WB
6953	3630767.25	216823.23	-4.55	WB
6954	3630767.24	216825.33	-4.56	WB
6955	3630767.22	216828.68	-4.57	WB
6956	3630767.24	216832.57	-4.57	WB
6957	3630767.28	216836.31	-4.57	WB
6958	3630767.35	216840.36	-4.57	WB
6959	3630767.47	216844.37	-4.57	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
6960	3630767.59	216848.43	-4.57	WB
6961	3630767.73	216852.61	-4.56	WB
6962	3630767.88	216856.66	-4.54	WB
6963	3630768.03	216860.81	-4.52	WB
6964	3630768.19	216864.86	-4.50	WB
6965	3630768.33	216868.84	-4.47	WB
6966	3630768.40	216872.82	-4.43	WB
6967	3630768.41	216873.28	-4.39	WB
6968	3630768.47	216876.74	-4.35	WB
6969	3630768.52	216880.53	-4.30	WB
6970	3630768.58	216884.20	-4.24	WB
6971	3630768.63	216887.73	-4.19	WB
6972	3630768.68	216891.09	-4.13	WB
6973	3630768.74	216894.42	-4.06	WB
6974	3630768.84	216901.48	-4.00	WB
6975	3630768.87	216904.14	-3.93	WB
6976	3630768.91	216906.70	-3.86	WB
6977	3630768.95	216909.17	-3.80	WB
6978	3630769.01	216911.44	-3.73	WB
6979	3630769.06	216913.70	-3.66	WB
6980	3630769.12	216915.79	-3.60	WB
6981	3630769.18	216917.83	-3.53	WB
6982	3630769.28	216919.78	-3.47	WB
6983	3630769.45	216921.63	-3.41	WB
6984	3630769.61	216923.23	-3.35	WB
6985	3630769.64	216923.47	-3.30	WB
6986	3630769.91	216925.20	-3.25	WB
6987	3630770.19	216926.92	-3.20	WB
6988	3630770.46	216928.65	-3.15	WB
6989	3630770.71	216930.36	-3.11	WB
6990	3630770.96	216932.08	-3.07	WB
6991	3630771.20	216933.81	-3.03	WB
6992	3630771.45	216935.55	-3.00	WB
6993	3630771.71	216937.37	-2.96	WB
6994	3630771.97	216939.23	-2.93	WB
6995	3630772.23	216941.09	-2.90	WB
6996	3630772.51	216943.11	-2.87	WB
6997	3630772.80	216945.13	-2.84	WB
6998	3630773.13	216947.31	-2.82	WB
6999	3630773.25	216948.16	-2.81	WB
7000	3630773.47	216949.58	-2.81	WB
7001	3630773.83	216951.97	-2.81	WB
7002	3630774.17	216954.65	-2.82	WB
7003	3630774.51	216957.33	-2.83	WB
7004	3630774.82	216960.32	-2.85	WB
7005	3630775.13	216963.36	-2.86	WB
7006	3630775.43	216966.51	-2.88	WB
7007	3630775.70	216969.75	-2.90	WB
7008	3630775.97	216972.98	-2.92	WB
7009	3630776.08	216976.24	-2.94	WB
7010	3630776.17	216979.49	-2.97	WB
7011	3630776.22	216982.74	-2.99	WB
7012	3630776.21	216986.12	-3.01	WB
7013	3630776.20	216989.34	-3.04	WB
7014	3630776.03	216992.40	-3.07	WB
7015	3630775.84	216995.65	-3.07	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
7016	3630775.71	216997.57	-3.08	WB
7017	3630775.60	216998.70	-3.08	WB
7018	3630775.31	217001.74	-3.09	WB
7019	3630775.01	217004.81	-3.06	WB
7020	3630774.70	217007.67	-3.04	WB
7021	3630774.38	217010.60	-3.02	WB
7022	3630774.02	217013.40	-3.00	WB
7023	3630773.62	217016.17	-2.95	WB
7024	3630773.21	217018.93	-2.92	WB
7025	3630772.78	217021.58	-2.89	WB
7026	3630772.66	217022.26	-2.85	WB
7027	3630772.32	217024.26	-2.81	WB
7028	3630771.83	217026.88	-2.76	WB
7029	3630771.34	217029.39	-2.72	WB
7030	3630770.85	217031.93	-2.68	WB
7031	3630770.47	217034.24	-2.63	WB
7032	3630770.11	217036.49	-2.59	WB
7033	3630284.27	215647.40	-9.10	WB
7034	3630283.67	215650.52	-9.12	WB
7035	3630283.07	215653.63	-9.12	WB
7036	3630282.40	215656.76	-9.12	WB
7037	3630281.69	215659.87	-9.11	WB
7038	3630281.07	215662.58	-9.10	WB
7039	3630280.96	215663.01	-9.09	WB
7040	3630280.25	215666.02	-9.08	WB
7041	3630279.52	215669.10	-9.07	WB
7042	3630278.83	215672.17	-9.06	WB
7043	3630278.17	215675.15	-9.06	WB
7044	3630277.50	215678.21	-9.05	WB
7045	3630276.88	215681.28	-9.04	WB
7046	3630276.28	215684.29	-9.03	WB
7047	3630275.85	215687.33	-9.02	WB
7048	3630275.75	215688.10	-9.01	WB
7049	3630275.49	215690.34	-9.00	WB
7050	3630275.20	215693.27	-8.99	WB
7051	3630275.08	215696.10	-8.98	WB
7052	3630274.98	215698.92	-8.97	WB
7053	3630275.08	215701.44	-8.96	WB
7054	3630275.24	215703.97	-8.95	WB
7055	3630275.41	215706.41	-8.94	WB
7056	3630275.62	215708.76	-8.93	WB
7057	3630275.84	215711.18	-8.92	WB
7058	3630276.11	215713.61	-8.91	WB
7059	3630276.40	215716.06	-8.90	WB
7060	3630276.65	215718.69	-8.90	WB
7061	3630276.83	215721.32	-8.89	WB
7062	3630277.03	215724.00	-8.88	WB
7063	3630277.16	215726.91	-8.87	WB
7064	3630277.30	215729.72	-8.86	WB
7065	3630277.43	215732.60	-8.86	WB
7066	3630277.56	215735.53	-8.85	WB
7067	3630277.66	215738.00	-8.84	WB
7068	3630277.67	215738.35	-8.84	WB
7069	3630277.74	215741.25	-8.83	WB
7070	3630277.80	215744.22	-8.82	WB
7071	3630277.81	215747.15	-8.81	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
7072	3630277.79	215750.15	-8.81	WB
7073	3630277.74	215753.18	-8.80	WB
7074	3630277.67	215756.24	-8.79	WB
7075	3630277.59	215759.31	-8.78	WB
7076	3630277.50	215762.39	-8.78	WB
7077	3630277.47	215763.11	-8.77	WB
7078	3630277.40	215765.38	-8.76	WB
7079	3630277.32	215768.34	-8.75	WB
7080	3630277.26	215771.32	-8.75	WB
7081	3630277.22	215774.19	-8.74	WB
7082	3630277.21	215777.01	-8.73	WB
7083	3630277.23	215779.77	-8.72	WB
7084	3630277.24	215782.45	-8.72	WB
7085	3630277.26	215785.16	-8.71	WB
7086	3630277.27	215787.83	-8.70	WB
7087	3630277.28	215788.15	-8.69	WB
7088	3630277.32	215790.54	-8.68	WB
7089	3630277.36	215793.26	-8.68	WB
7090	3630277.38	215796.09	-8.67	WB
7091	3630277.36	215798.98	-8.66	WB
7092	3630277.35	215801.87	-8.65	WB
7093	3630277.30	215804.90	-8.64	WB
7094	3630277.27	215807.92	-8.64	WB
7095	3630277.24	215810.99	-8.63	WB
7096	3630277.21	215813.25	-8.62	WB
7097	3630277.21	215813.97	-8.61	WB
7098	3630277.18	215817.02	-8.60	WB
7099	3630277.19	215820.12	-8.60	WB
7100	3630277.19	215823.13	-8.59	WB
7101	3630277.13	215826.28	-8.58	WB
7102	3630277.04	215829.42	-8.57	WB
7103	3630276.92	215832.60	-8.56	WB
7104	3630276.75	215835.92	-8.55	WB
7105	3630276.63	215838.38	-8.54	WB
7106	3630276.59	215839.16	-8.54	WB
7107	3630276.42	215842.52	-8.53	WB
7108	3630276.26	215845.93	-8.52	WB
7109	3630276.15	215849.17	-8.51	WB
7110	3630276.17	215852.44	-8.50	WB
7111	3630276.21	215855.62	-8.49	WB
7112	3630276.37	215858.60	-8.48	WB
7113	3630276.56	215861.57	-8.47	WB
7114	3630276.68	215863.40	-8.46	WB
7115	3630276.78	215864.42	-8.45	WB
7116	3630277.06	215867.23	-8.44	WB
7117	3630277.33	215870.04	-8.43	WB
7118	3630277.65	215873.01	-8.42	WB
7119	3630277.95	215875.98	-8.41	WB
7120	3630278.23	215878.99	-8.40	WB
7121	3630278.50	215882.08	-8.39	WB
7122	3630278.79	215885.19	-8.38	WB
7123	3630279.11	215888.29	-8.37	WB
7124	3630279.43	215891.38	-8.36	WB
7125	3630279.74	215894.42	-8.35	WB
7126	3630280.03	215897.42	-8.34	WB
7127	3630280.31	215900.35	-8.33	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
7128	3630280.61	215903.19	-8.33	WB
7129	3630280.89	215906.00	-8.32	WB
7130	3630281.10	215908.78	-8.31	WB
7131	3630281.26	215911.60	-8.30	WB
7132	3630281.36	215913.30	-8.30	WB
7133	3630281.40	215914.34	-8.29	WB
7134	3630281.47	215917.31	-8.28	WB
7135	3630281.54	215920.32	-8.28	WB
7136	3630281.57	215923.33	-8.27	WB
7137	3630281.59	215926.43	-8.26	WB
7138	3630281.62	215929.52	-8.26	WB
7139	3630281.66	215932.56	-8.25	WB
7140	3630281.71	215935.67	-8.25	WB
7141	3630281.75	215937.78	-8.24	WB
7142	3630281.76	215938.56	-8.23	WB
7143	3630281.82	215941.43	-8.23	WB
7144	3630281.85	215944.25	-8.22	WB
7145	3630281.83	215947.05	-8.22	WB
7146	3630281.81	215949.84	-8.21	WB
7147	3630281.63	215952.77	-8.20	WB
7148	3630281.44	215955.69	-8.20	WB
7149	3630281.16	215958.68	-8.19	WB
7150	3630280.81	215961.80	-8.18	WB
7151	3630280.67	215962.97	-8.18	WB
7152	3630280.44	215964.98	-8.17	WB
7153	3630280.00	215968.28	-8.16	WB
7154	3630279.55	215971.62	-8.15	WB
7155	3630279.15	215974.88	-8.14	WB
7156	3630278.78	215978.19	-8.13	WB
7157	3630278.42	215981.52	-8.12	WB
7158	3630278.16	215984.62	-8.12	WB
7159	3630277.89	215987.80	-8.11	WB
7160	3630277.73	215990.84	-8.10	WB
7161	3630277.61	215993.78	-8.09	WB
7162	3630277.49	215996.79	-8.08	WB
7163	3630277.32	215999.77	-8.07	WB
7164	3630277.15	216002.76	-8.06	WB
7165	3630276.93	216005.82	-8.05	WB
7166	3630276.70	216008.78	-8.04	WB
7167	3630276.44	216011.80	-8.04	WB
7168	3630276.33	216012.99	-8.03	WB
7169	3630276.15	216014.86	-8.02	WB
7170	3630275.86	216017.92	-8.01	WB
7171	3630275.61	216020.93	-8.01	WB
7172	3630275.38	216023.86	-8.00	WB
7173	3630275.24	216026.72	-7.99	WB
7174	3630275.20	216029.52	-7.99	WB
7175	3630275.18	216032.34	-7.98	WB
7176	3630275.20	216035.03	-7.98	WB
7177	3630275.22	216037.74	-7.97	WB
7178	3630275.22	216038.12	-7.97	WB
7179	3630275.22	216040.68	-7.96	WB
7180	3630275.19	216043.61	-7.95	WB
7181	3630275.14	216046.63	-7.95	WB
7182	3630275.05	216050.01	-7.94	WB
7183	3630274.95	216053.41	-7.94	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
7184	3630274.88	216056.97	-7.93	WB
7185	3630274.84	216060.64	-7.92	WB
7186	3630274.81	216063.80	-7.92	WB
7187	3630274.82	216064.29	-7.91	WB
7188	3630274.93	216067.86	-7.90	WB
7189	3630275.06	216071.40	-7.89	WB
7190	3630275.28	216074.67	-7.88	WB
7191	3630275.56	216077.83	-7.87	WB
7192	3630275.86	216080.92	-7.86	WB
7193	3630276.21	216083.63	-7.85	WB
7194	3630276.56	216086.42	-7.83	WB
7195	3630276.76	216088.16	-7.82	WB
7196	3630276.86	216089.16	-7.81	WB
7197	3630277.13	216091.82	-7.80	WB
7198	3630277.36	216094.65	-7.78	WB
7199	3630277.52	216097.49	-7.77	WB
7200	3630277.67	216100.31	-7.76	WB
7201	3630277.76	216103.24	-7.75	WB
7202	3630277.85	216106.17	-7.73	WB
7203	3630277.99	216109.08	-7.72	WB
7204	3630278.21	216111.93	-7.71	WB
7205	3630278.32	216113.30	-7.70	WB
7206	3630278.43	216114.66	-7.69	WB
7207	3630278.70	216117.21	-7.68	WB
7208	3630278.98	216119.77	-7.67	WB
7209	3630279.28	216122.22	-7.66	WB
7210	3630279.61	216124.66	-7.66	WB
7211	3630279.92	216127.14	-7.65	WB
7212	3630280.15	216129.85	-7.64	WB
7213	3630280.37	216132.58	-7.64	WB
7214	3630280.55	216135.52	-7.63	WB
7215	3630280.69	216138.21	-7.63	WB
7216	3630280.71	216138.63	-7.62	WB
7217	3630280.85	216141.72	-7.62	WB
7218	3630280.94	216145.19	-7.61	WB
7219	3630281.03	216148.60	-7.61	WB
7220	3630281.09	216152.04	-7.60	WB
7221	3630281.13	216155.53	-7.60	WB
7222	3630281.17	216159.00	-7.59	WB
7223	3630281.18	216162.38	-7.59	WB
7224	3630281.18	216162.78	-7.58	WB
7225	3630281.19	216165.76	-7.57	WB
7226	3630281.12	216169.06	-7.57	WB
7227	3630281.00	216172.31	-7.56	WB
7228	3630280.87	216175.52	-7.55	WB
7229	3630280.67	216178.66	-7.54	WB
7230	3630280.47	216181.80	-7.53	WB
7231	3630280.23	216184.94	-7.52	WB
7232	3630280.01	216187.60	-7.51	WB
7233	3630279.98	216187.97	-7.49	WB
7234	3630279.70	216191.03	-7.48	WB
7235	3630279.37	216194.05	-7.47	WB
7236	3630279.04	216196.98	-7.45	WB
7237	3630278.71	216199.82	-7.44	WB
7238	3630278.38	216202.65	-7.43	WB
7239	3630278.04	216205.36	-7.41	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
7240	3630277.67	216208.06	-7.40	WB
7241	3630277.30	216210.73	-7.39	WB
7242	3630277.08	216212.72	-7.37	WB
7243	3630277.00	216213.34	-7.36	WB
7244	3630276.70	216215.95	-7.35	WB
7245	3630276.41	216218.61	-7.34	WB
7246	3630276.13	216221.29	-7.33	WB
7247	3630275.85	216224.02	-7.32	WB
7248	3630275.59	216226.84	-7.31	WB
7249	3630275.34	216229.64	-7.30	WB
7250	3630275.15	216232.50	-7.29	WB
7251	3630275.01	216235.38	-7.28	WB
7252	3630274.91	216238.32	-7.28	WB
7253	3630274.91	216238.67	-7.27	WB
7254	3630274.96	216241.37	-7.26	WB
7255	3630275.02	216244.34	-7.26	WB
7256	3630275.16	216247.47	-7.25	WB
7257	3630275.34	216250.70	-7.24	WB
7258	3630275.53	216253.93	-7.24	WB
7259	3630275.81	216257.44	-7.23	WB
7260	3630276.09	216260.90	-7.22	WB
7261	3630276.41	216264.53	-7.21	WB
7262	3630276.77	216268.30	-7.21	WB
7263	3630277.17	216272.00	-7.20	WB
7264	3630277.67	216275.70	-7.19	WB
7265	3630278.17	216279.34	-7.18	WB
7266	3630278.73	216282.67	-7.17	WB
7267	3630279.32	216285.94	-7.15	WB
7268	3630279.82	216288.65	-7.14	WB
7269	3630279.89	216288.99	-7.13	WB
7270	3630280.45	216291.79	-7.12	WB
7271	3630281.01	216294.60	-7.10	WB
7272	3630281.52	216297.02	-7.09	WB
7273	3630282.03	216299.48	-7.08	WB
7274	3630282.43	216301.85	-7.06	WB
7275	3630282.76	216304.20	-7.05	WB
7276	3630283.05	216306.50	-7.04	WB
7277	3630283.30	216308.82	-7.02	WB
7278	3630283.55	216311.18	-7.01	WB
7279	3630283.65	216312.65	-7.00	WB
7280	3630283.67	216313.49	-6.99	WB
7281	3630283.74	216315.91	-6.98	WB
7282	3630283.79	216318.29	-6.97	WB
7283	3630283.79	216320.69	-6.97	WB
7284	3630283.80	216323.15	-6.96	WB
7285	3630283.74	216325.62	-6.96	WB
7286	3630283.67	216328.09	-6.95	WB
7287	3630283.58	216330.57	-6.95	WB
7288	3630283.43	216333.13	-6.95	WB
7289	3630283.28	216335.68	-6.94	WB
7290	3630283.11	216337.71	-6.94	WB
7291	3630283.04	216338.47	-6.94	WB
7292	3630282.80	216341.22	-6.94	WB
7293	3630282.47	216344.14	-6.94	WB
7294	3630282.01	216347.33	-6.94	WB
7295	3630281.55	216350.53	-6.94	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
7296	3630280.99	216354.00	-6.94	WB
7297	3630280.40	216357.58	-6.94	WB
7298	3630279.80	216361.18	-6.94	WB
7299	3630279.47	216363.10	-6.94	WB
7300	3630279.15	216364.98	-6.93	WB
7301	3630278.50	216368.83	-6.93	WB
7302	3630277.92	216372.59	-6.92	WB
7303	3630277.33	216376.42	-6.92	WB
7304	3630276.80	216380.14	-6.91	WB
7305	3630276.33	216383.69	-6.90	WB
7306	3630275.85	216387.34	-6.89	WB
7307	3630275.75	216388.13	-6.88	WB
7308	3630275.46	216390.57	-6.86	WB
7309	3630275.07	216393.85	-6.85	WB
7310	3630274.75	216397.00	-6.83	WB
7311	3630274.46	216399.99	-6.82	WB
7312	3630274.18	216403.01	-6.80	WB
7313	3630273.96	216405.89	-6.78	WB
7314	3630273.72	216408.74	-6.77	WB
7315	3630273.52	216411.62	-6.75	WB
7316	3630273.42	216413.03	-6.73	WB
7317	3630273.31	216414.48	-6.71	WB
7318	3630273.12	216417.34	-6.69	WB
7319	3630272.99	216420.22	-6.68	WB
7320	3630272.86	216423.11	-6.66	WB
7321	3630272.84	216425.90	-6.64	WB
7322	3630272.86	216428.69	-6.63	WB
7323	3630272.98	216431.41	-6.61	WB
7324	3630273.24	216434.04	-6.60	WB
7325	3630273.53	216436.69	-6.59	WB
7326	3630274.01	216439.16	-6.57	WB
7327	3630274.52	216441.64	-6.56	WB
7328	3630275.10	216444.20	-6.55	WB
7329	3630275.74	216446.75	-6.54	WB
7330	3630276.39	216449.37	-6.54	WB
7331	3630277.07	216452.18	-6.53	WB
7332	3630277.74	216454.95	-6.52	WB
7333	3630278.43	216457.90	-6.52	WB
7334	3630279.14	216461.00	-6.51	WB
7335	3630279.85	216464.02	-6.51	WB
7336	3630279.96	216464.44	-6.50	WB
7337	3630280.65	216467.15	-6.50	WB
7338	3630281.46	216470.19	-6.49	WB
7339	3630282.26	216473.20	-6.49	WB
7340	3630283.05	216476.14	-6.48	WB
7341	3630283.84	216479.03	-6.48	WB
7342	3630284.55	216481.83	-6.47	WB
7343	3630285.27	216484.63	-6.46	WB
7344	3630285.90	216487.40	-6.46	WB
7345	3630286.06	216488.15	-6.45	WB
7346	3630286.48	216490.19	-6.44	WB
7347	3630286.97	216493.02	-6.43	WB
7348	3630287.26	216495.72	-6.42	WB
7349	3630287.53	216498.55	-6.41	WB
7350	3630287.66	216501.20	-6.40	WB
7351	3630287.76	216503.80	-6.39	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
7352	3630287.82	216506.43	-6.38	WB
7353	3630287.81	216508.94	-6.37	WB
7354	3630287.79	216511.42	-6.36	WB
7355	3630287.76	216512.70	-6.35	WB
7356	3630287.73	216513.97	-6.34	WB
7357	3630287.65	216516.44	-6.33	WB
7358	3630287.54	216519.02	-6.31	WB
7359	3630287.39	216521.59	-6.30	WB
7360	3630287.25	216524.14	-6.29	WB
7361	3630287.08	216526.81	-6.29	WB
7362	3630286.93	216529.44	-6.28	WB
7363	3630286.79	216532.09	-6.27	WB
7364	3630286.67	216534.74	-6.26	WB
7365	3630286.54	216537.42	-6.25	WB
7366	3630286.53	216537.75	-6.25	WB
7367	3630286.41	216540.09	-6.24	WB
7368	3630286.28	216542.80	-6.24	WB
7369	3630286.13	216545.45	-6.23	WB
7370	3630285.97	216548.19	-6.23	WB
7371	3630285.76	216550.94	-6.23	WB
7372	3630285.44	216553.79	-6.23	WB
7373	3630285.12	216556.65	-6.22	WB
7374	3630284.70	216559.72	-6.22	WB
7375	3630284.26	216562.86	-6.22	WB
7376	3630283.79	216566.08	-6.22	WB
7377	3630283.28	216569.49	-6.22	WB
7378	3630282.77	216572.92	-6.22	WB
7379	3630282.22	216576.54	-6.21	WB
7380	3630281.68	216580.14	-6.21	WB
7381	3630281.17	216583.75	-6.21	WB
7382	3630280.68	216587.52	-6.21	WB
7383	3630280.62	216587.96	-6.21	WB
7384	3630280.20	216591.12	-6.20	WB
7385	3630279.73	216594.62	-6.20	WB
7386	3630279.27	216598.07	-6.20	WB
7387	3630278.87	216601.33	-6.19	WB
7388	3630278.55	216604.45	-6.19	WB
7389	3630278.22	216607.56	-6.18	WB
7390	3630277.95	216610.42	-6.18	WB
7391	3630277.70	216612.94	-6.17	WB
7392	3630277.67	216613.28	-6.17	WB
7393	3630277.42	216616.11	-6.16	WB
7394	3630277.20	216618.82	-6.15	WB
7395	3630276.98	216621.62	-6.15	WB
7396	3630276.81	216624.44	-6.14	WB
7397	3630276.64	216627.24	-6.13	WB
7398	3630276.54	216630.24	-6.13	WB
7399	3630276.49	216633.28	-6.12	WB
7400	3630276.48	216636.30	-6.11	WB
7401	3630276.60	216638.72	-6.10	WB
7402	3630276.64	216639.57	-6.10	WB
7403	3630276.80	216642.68	-6.09	WB
7404	3630277.09	216645.79	-6.08	WB
7405	3630277.45	216649.01	-6.07	WB
7406	3630277.84	216652.07	-6.07	WB
7407	3630278.35	216655.14	-6.07	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
7408	3630278.87	216658.15	-6.07	WB
7409	3630279.48	216661.03	-6.07	WB
7410	3630280.13	216663.96	-6.07	WB
7411	3630280.21	216664.31	-6.07	WB
7412	3630280.79	216666.83	-6.06	WB
7413	3630281.48	216669.66	-6.05	WB
7414	3630282.18	216672.48	-6.04	WB
7415	3630282.87	216675.27	-6.03	WB
7416	3630283.57	216678.03	-6.03	WB
7417	3630284.22	216680.74	-6.02	WB
7418	3630284.84	216683.39	-6.01	WB
7419	3630285.44	216686.05	-6.00	WB
7420	3630285.88	216688.33	-5.99	WB
7421	3630285.94	216688.64	-5.98	WB
7422	3630286.43	216691.26	-5.97	WB
7423	3630286.83	216693.91	-5.96	WB
7424	3630287.16	216696.61	-5.95	WB
7425	3630287.46	216699.27	-5.94	WB
7426	3630287.70	216702.02	-5.93	WB
7427	3630287.95	216704.82	-5.92	WB
7428	3630288.19	216707.58	-5.92	WB
7429	3630288.43	216710.42	-5.91	WB
7430	3630288.70	216713.19	-5.91	WB
7431	3630288.73	216713.53	-5.91	WB
7432	3630288.99	216715.96	-5.92	WB
7433	3630289.30	216718.76	-5.93	WB
7434	3630289.61	216721.62	-5.94	WB
7435	3630289.92	216724.51	-5.95	WB
7436	3630290.23	216727.41	-5.97	WB
7437	3630290.51	216730.41	-5.99	WB
7438	3630290.79	216733.41	-6.02	WB
7439	3630290.92	216736.57	-6.04	WB
7440	3630290.96	216737.84	-6.07	WB
7441	3630291.02	216739.93	-6.09	WB
7442	3630290.99	216743.24	-6.11	WB
7443	3630290.76	216746.69	-6.12	WB
7444	3630290.52	216750.20	-6.12	WB
7445	3630290.11	216753.60	-6.11	WB
7446	3630289.66	216757.12	-6.09	WB
7447	3630289.17	216760.56	-6.06	WB
7448	3630288.90	216762.19	-6.03	WB
7449	3630288.63	216763.84	-5.98	WB
7450	3630288.06	216767.22	-5.93	WB
7451	3630287.36	216770.33	-5.87	WB
7452	3630286.66	216773.41	-5.81	WB
7453	3630285.94	216776.35	-5.74	WB
7454	3630285.22	216779.14	-5.68	WB
7455	3630284.51	216781.88	-5.61	WB
7456	3630283.82	216784.32	-5.55	WB
7457	3630283.12	216786.77	-5.48	WB
7458	3630283.02	216787.10	-5.42	WB
7459	3630282.44	216789.09	-5.35	WB
7460	3630281.75	216791.35	-5.29	WB
7461	3630281.08	216793.59	-5.23	WB
7462	3630280.45	216795.75	-5.18	WB
7463	3630279.79	216798.02	-5.13	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
7464	3630279.15	216800.25	-5.09	WB
7465	3630278.50	216802.56	-5.06	WB
7466	3630277.85	216804.97	-5.03	WB
7467	3630277.24	216807.44	-5.02	WB
7468	3630276.62	216809.98	-5.00	WB
7469	3630276.06	216812.64	-5.00	WB
7470	3630275.53	216815.25	-4.99	WB
7471	3630275.03	216817.92	-4.99	WB
7472	3630274.59	216820.69	-4.99	WB
7473	3630274.17	216823.38	-5.00	WB
7474	3630273.78	216826.10	-4.99	WB
7475	3630273.40	216828.77	-4.99	WB
7476	3630273.06	216831.40	-4.98	WB
7477	3630272.74	216833.99	-4.98	WB
7478	3630272.43	216836.59	-4.97	WB
7479	3630272.28	216837.88	-4.96	WB
7480	3630272.14	216839.17	-4.95	WB
7481	3630271.84	216841.80	-4.95	WB
7482	3630271.52	216844.60	-4.95	WB
7483	3630271.18	216847.42	-4.95	WB
7484	3630270.82	216850.38	-4.96	WB
7485	3630270.43	216853.60	-4.97	WB
7486	3630270.03	216856.80	-4.98	WB
7487	3630269.64	216860.30	-5.00	WB
7488	3630269.31	216863.53	-5.02	WB
7489	3630269.26	216863.96	-5.03	WB
7490	3630268.88	216867.65	-5.04	WB
7491	3630268.50	216871.59	-5.06	WB
7492	3630268.12	216875.55	-5.07	WB
7493	3630267.85	216879.62	-5.08	WB
7494	3630267.64	216883.65	-5.09	WB
7495	3630267.47	216887.71	-5.10	WB
7496	3630267.46	216888.66	-5.11	WB
7497	3630267.43	216891.62	-5.12	WB
7498	3630267.39	216895.57	-5.12	WB
7499	3630267.37	216899.54	-5.13	WB
7500	3630267.34	216903.38	-5.13	WB
7501	3630267.33	216907.25	-5.13	WB
7502	3630267.36	216910.91	-5.11	WB
7503	3630267.38	216913.63	-5.09	WB
7504	3630267.39	216914.50	-5.06	WB
7505	3630267.54	216917.90	-5.02	WB
7506	3630267.70	216921.17	-4.97	WB
7507	3630267.92	216924.29	-4.90	WB
7508	3630268.18	216927.22	-4.83	WB
7509	3630268.44	216930.18	-4.75	WB
7510	3630268.79	216932.83	-4.67	WB
7511	3630269.14	216935.61	-4.59	WB
7512	3630269.57	216938.22	-4.50	WB
7513	3630269.75	216939.15	-4.41	WB
7514	3630270.05	216940.66	-4.32	WB
7515	3630270.57	216943.12	-4.23	WB
7516	3630271.24	216945.28	-4.15	WB
7517	3630271.93	216947.39	-4.08	WB
7518	3630272.68	216949.28	-4.01	WB
7519	3630273.44	216950.96	-3.96	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
7520	3630274.21	216952.57	-3.91	WB
7521	3630274.96	216953.96	-3.88	WB
7522	3630275.69	216955.29	-3.85	WB
7523	3630276.43	216956.52	-3.83	WB
7524	3630277.17	216957.69	-3.81	WB
7525	3630277.87	216958.84	-3.78	WB
7526	3630278.46	216959.99	-3.76	WB
7527	3630279.03	216961.14	-3.74	WB
7528	3630279.53	216962.41	-3.72	WB
7529	3630279.89	216963.39	-3.70	WB
7530	3630280.02	216963.75	-3.69	WB
7531	3630280.43	216965.16	-3.67	WB
7532	3630280.77	216966.82	-3.66	WB
7533	3630281.08	216968.47	-3.65	WB
7534	3630281.29	216970.59	-3.64	WB
7535	3630281.48	216972.78	-3.63	WB
7536	3630281.65	216975.19	-3.61	WB
7537	3630281.78	216977.87	-3.60	WB
7538	3630281.92	216980.58	-3.58	WB
7539	3630282.02	216983.55	-3.56	WB
7540	3630282.14	216986.56	-3.54	WB
7541	3630282.21	216988.35	-3.51	WB
7542	3630282.27	216989.51	-3.48	WB
7543	3630282.41	216992.47	-3.45	WB
7544	3630282.53	216995.43	-3.42	WB
7545	3630282.53	216998.21	-3.38	WB
7546	3630282.52	217001.00	-3.34	WB
7547	3630282.42	217003.58	-3.30	WB
7548	3630282.27	217006.08	-3.26	WB
7549	3630282.09	217008.50	-3.22	WB
7550	3630281.85	217010.65	-3.18	WB
7551	3630281.64	217012.49	-3.14	WB
7552	3630281.61	217012.74	-3.10	WB
7553	3630281.37	217014.61	-3.06	WB
7554	3630281.11	217016.43	-3.02	WB
7555	3630280.86	217018.15	-2.99	WB
7556	3630280.62	217019.78	-2.95	WB
7557	3630280.37	217021.38	-2.92	WB
7558	3630280.15	217022.90	-2.89	WB
7559	3630279.92	217024.48	-2.86	WB
7560	3630279.71	217025.94	-2.83	WB
7561	3630279.51	217027.39	-2.81	WB
7562	3630279.31	217028.82	-2.79	WB
7563	3630279.14	217030.13	-2.77	WB
7564	3630278.96	217031.47	-2.76	WB
7565	3630278.82	217032.77	-2.75	WB
7566	3630278.71	217034.06	-2.74	WB
7567	3630278.60	217035.33	-2.73	WB
7568	3630278.55	217036.60	-2.73	WB
7569	3630278.51	217037.89	-2.73	WB
7570	3630278.51	217038.05	-2.73	WB
7571	3630278.50	217039.25	-2.73	WB
7572	3630278.51	217040.64	-2.73	WB
7573	3630278.52	217042.09	-2.72	WB
7574	3630278.52	217043.86	-2.72	WB
7575	3630278.52	217045.61	-2.72	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
7576	3630278.56	217047.58	-2.72	WB
7577	3630278.61	217049.56	-2.72	WB
7578	3630278.67	217051.65	-2.72	WB
7579	3630278.76	217053.80	-2.71	WB
7580	3630278.86	217055.91	-2.71	WB
7581	3630279.00	217058.01	-2.70	WB
7582	3630279.15	217060.05	-2.70	WB
7583	3630279.30	217061.95	-2.69	WB
7584	3630279.40	217063.32	-2.68	WB
7585	3630279.43	217063.76	-2.67	WB
7586	3630279.57	217065.59	-2.66	WB
7587	3630279.61	217067.16	-2.64	WB
7588	3630279.63	217068.77	-2.62	WB
7589	3630279.66	217070.29	-2.60	WB
7590	3630279.69	217071.68	-2.58	WB
7591	3630279.72	217073.15	-2.56	WB
7592	3629782.32	215653.37	-8.89	WB
7593	3629781.81	215655.90	-8.89	WB
7594	3629781.27	215658.51	-8.88	WB
7595	3629780.61	215661.20	-8.87	WB
7596	3629779.84	215663.99	-8.87	WB
7597	3629779.00	215666.93	-8.86	WB
7598	3629778.05	215670.06	-8.86	WB
7599	3629777.11	215673.16	-8.85	WB
7600	3629776.21	215676.50	-8.84	WB
7601	3629776.00	215677.36	-8.84	WB
7602	3629775.36	215679.93	-8.83	WB
7603	3629774.61	215683.27	-8.82	WB
7604	3629774.05	215686.73	-8.82	WB
7605	3629773.51	215690.22	-8.81	WB
7606	3629773.13	215693.63	-8.80	WB
7607	3629772.81	215697.14	-8.80	WB
7608	3629772.55	215700.54	-8.79	WB
7609	3629772.44	215703.00	-8.79	WB
7610	3629772.41	215703.79	-8.78	WB
7611	3629772.28	215707.10	-8.77	WB
7612	3629772.24	215710.18	-8.77	WB
7613	3629772.22	215713.20	-8.77	WB
7614	3629772.21	215716.15	-8.76	WB
7615	3629772.19	215719.06	-8.76	WB
7616	3629772.16	215721.97	-8.75	WB
7617	3629772.05	215724.88	-8.75	WB
7618	3629771.93	215727.46	-8.75	WB
7619	3629771.91	215727.86	-8.74	WB
7620	3629771.70	215730.80	-8.74	WB
7621	3629771.40	215733.84	-8.74	WB
7622	3629771.08	215736.94	-8.73	WB
7623	3629770.77	215740.04	-8.73	WB
7624	3629770.45	215743.21	-8.73	WB
7625	3629770.15	215746.38	-8.73	WB
7626	3629769.89	215749.52	-8.73	WB
7627	3629769.63	215752.76	-8.73	WB
7628	3629769.54	215755.95	-8.72	WB
7629	3629769.45	215759.13	-8.72	WB
7630	3629769.41	215762.30	-8.72	WB
7631	3629769.39	215765.49	-8.72	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
7632	3629769.38	215768.74	-8.72	WB
7633	3629769.40	215771.96	-8.72	WB
7634	3629769.43	215775.17	-8.72	WB
7635	3629769.50	215778.02	-8.72	WB
7636	3629769.51	215778.41	-8.72	WB
7637	3629769.62	215781.65	-8.72	WB
7638	3629769.75	215784.88	-8.72	WB
7639	3629769.89	215788.15	-8.72	WB
7640	3629770.03	215791.41	-8.71	WB
7641	3629770.10	215794.68	-8.71	WB
7642	3629770.15	215797.96	-8.71	WB
7643	3629770.18	215801.22	-8.71	WB
7644	3629770.19	215802.83	-8.70	WB
7645	3629770.19	215804.48	-8.70	WB
7646	3629770.19	215807.81	-8.69	WB
7647	3629770.06	215811.00	-8.69	WB
7648	3629769.91	215814.21	-8.68	WB
7649	3629769.72	215817.54	-8.67	WB
7650	3629769.50	215820.65	-8.66	WB
7651	3629769.27	215823.86	-8.66	WB
7652	3629768.94	215827.01	-8.65	WB
7653	3629768.90	215827.38	-8.64	WB
7654	3629768.59	215830.13	-8.63	WB
7655	3629768.18	215833.37	-8.62	WB
7656	3629767.73	215836.57	-8.61	WB
7657	3629767.27	215839.79	-8.60	WB
7658	3629766.81	215843.03	-8.58	WB
7659	3629766.33	215846.31	-8.57	WB
7660	3629765.89	215849.60	-8.56	WB
7661	3629765.46	215852.91	-8.55	WB
7662	3629765.08	215856.24	-8.53	WB
7663	3629764.87	215859.50	-8.52	WB
7664	3629764.67	215862.75	-8.51	WB
7665	3629764.65	215865.90	-8.50	WB
7666	3629764.70	215869.04	-8.49	WB
7667	3629764.83	215872.18	-8.47	WB
7668	3629765.11	215875.22	-8.46	WB
7669	3629765.41	215878.29	-8.45	WB
7670	3629765.50	215879.10	-8.44	WB
7671	3629765.87	215881.43	-8.43	WB
7672	3629766.35	215884.42	-8.42	WB
7673	3629766.90	215887.49	-8.41	WB
7674	3629767.52	215890.50	-8.40	WB
7675	3629768.15	215893.45	-8.40	WB
7676	3629768.85	215896.32	-8.39	WB
7677	3629769.56	215899.14	-8.38	WB
7678	3629770.26	215901.86	-8.38	WB
7679	3629770.70	215903.54	-8.37	WB
7680	3629770.96	215904.54	-8.37	WB
7681	3629771.67	215907.22	-8.37	WB
7682	3629772.26	215909.88	-8.36	WB
7683	3629772.85	215912.56	-8.36	WB
7684	3629773.36	215915.34	-8.36	WB
7685	3629773.78	215918.07	-8.35	WB
7686	3629774.18	215920.88	-8.35	WB
7687	3629774.44	215923.90	-8.35	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
7688	3629774.67	215926.85	-8.35	WB
7689	3629774.76	215928.02	-8.35	WB
7690	3629774.87	215930.13	-8.34	WB
7691	3629775.04	215933.37	-8.34	WB
7692	3629775.20	215936.66	-8.34	WB
7693	3629775.30	215940.25	-8.34	WB
7694	3629775.42	215943.77	-8.34	WB
7695	3629775.58	215947.27	-8.33	WB
7696	3629775.77	215950.79	-8.33	WB
7697	3629775.93	215953.39	-8.33	WB
7698	3629775.99	215954.24	-8.32	WB
7699	3629776.26	215957.52	-8.32	WB
7700	3629776.53	215960.78	-8.32	WB
7701	3629776.79	215963.89	-8.31	WB
7702	3629777.03	215966.93	-8.31	WB
7703	3629777.22	215969.94	-8.31	WB
7704	3629777.32	215972.85	-8.30	WB
7705	3629777.41	215975.78	-8.30	WB
7706	3629777.47	215977.52	-8.29	WB
7707	3629777.51	215978.60	-8.29	WB
7708	3629777.59	215981.33	-8.29	WB
7709	3629777.63	215984.12	-8.28	WB
7710	3629777.60	215986.90	-8.28	WB
7711	3629777.57	215989.61	-8.27	WB
7712	3629777.56	215992.45	-8.27	WB
7713	3629777.55	215995.25	-8.27	WB
7714	3629777.50	215998.14	-8.26	WB
7715	3629777.42	216001.20	-8.26	WB
7716	3629777.37	216003.10	-8.26	WB
7717	3629777.35	216004.24	-8.26	WB
7718	3629777.35	216007.48	-8.25	WB
7719	3629777.37	216010.68	-8.25	WB
7720	3629777.41	216014.00	-8.25	WB
7721	3629777.46	216017.39	-8.24	WB
7722	3629777.53	216020.91	-8.24	WB
7723	3629777.58	216024.56	-8.24	WB
7724	3629777.65	216028.14	-8.23	WB
7725	3629777.70	216031.82	-8.23	WB
7726	3629777.76	216035.58	-8.23	WB
7727	3629777.80	216039.21	-8.22	WB
7728	3629777.81	216042.92	-8.21	WB
7729	3629777.83	216046.56	-8.21	WB
7730	3629777.86	216050.02	-8.20	WB
7731	3629777.89	216052.68	-8.19	WB
7732	3629777.90	216053.56	-8.19	WB
7733	3629777.88	216057.03	-8.18	WB
7734	3629777.80	216060.35	-8.17	WB
7735	3629777.71	216063.68	-8.16	WB
7736	3629777.58	216066.80	-8.14	WB
7737	3629777.43	216069.91	-8.13	WB
7738	3629777.26	216072.94	-8.12	WB
7739	3629777.06	216075.86	-8.11	WB
7740	3629776.94	216077.34	-8.09	WB
7741	3629776.83	216078.79	-8.08	WB
7742	3629776.49	216081.68	-8.06	WB
7743	3629776.14	216084.58	-8.05	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
7744	3629775.77	216087.42	-8.03	WB
7745	3629775.38	216090.33	-8.02	WB
7746	3629775.01	216093.12	-8.00	WB
7747	3629774.61	216095.99	-7.99	WB
7748	3629774.20	216098.90	-7.97	WB
7749	3629773.79	216101.79	-7.95	WB
7750	3629773.68	216102.58	-7.94	WB
7751	3629773.37	216104.82	-7.92	WB
7752	3629772.95	216107.75	-7.91	WB
7753	3629772.51	216110.81	-7.89	WB
7754	3629772.04	216114.01	-7.88	WB
7755	3629771.63	216117.15	-7.86	WB
7756	3629771.24	216120.39	-7.85	WB
7757	3629770.87	216123.61	-7.83	WB
7758	3629770.56	216126.89	-7.82	WB
7759	3629770.48	216127.72	-7.80	WB
7760	3629770.26	216130.15	-7.79	WB
7761	3629770.08	216133.36	-7.78	WB
7762	3629769.94	216136.56	-7.76	WB
7763	3629769.82	216139.72	-7.75	WB
7764	3629769.71	216142.87	-7.74	WB
7765	3629769.59	216146.07	-7.73	WB
7766	3629769.47	216149.06	-7.72	WB
7767	3629769.33	216152.15	-7.71	WB
7768	3629769.30	216152.88	-7.70	WB
7769	3629769.20	216155.16	-7.69	WB
7770	3629769.09	216158.06	-7.68	WB
7771	3629768.98	216161.06	-7.67	WB
7772	3629768.90	216163.95	-7.66	WB
7773	3629768.82	216166.84	-7.66	WB
7774	3629768.76	216169.69	-7.65	WB
7775	3629768.71	216172.58	-7.64	WB
7776	3629768.66	216175.50	-7.64	WB
7777	3629768.65	216178.10	-7.63	WB
7778	3629768.65	216178.45	-7.63	WB
7779	3629768.64	216181.42	-7.62	WB
7780	3629768.64	216184.41	-7.62	WB
7781	3629768.68	216187.53	-7.61	WB
7782	3629768.73	216190.73	-7.60	WB
7783	3629768.87	216194.04	-7.60	WB
7784	3629769.03	216197.44	-7.59	WB
7785	3629769.21	216200.99	-7.59	WB
7786	3629769.36	216203.67	-7.58	WB
7787	3629769.41	216204.52	-7.57	WB
7788	3629769.64	216208.16	-7.57	WB
7789	3629769.93	216211.87	-7.56	WB
7790	3629770.23	216215.57	-7.55	WB
7791	3629770.54	216219.21	-7.54	WB
7792	3629770.86	216222.83	-7.53	WB
7793	3629771.18	216226.37	-7.52	WB
7794	3629771.32	216228.07	-7.51	WB
7795	3629771.47	216229.80	-7.50	WB
7796	3629771.76	216233.24	-7.49	WB
7797	3629771.94	216236.44	-7.47	WB
7798	3629772.09	216239.73	-7.46	WB
7799	3629772.24	216242.96	-7.44	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
7800	3629772.36	216245.95	-7.43	WB
7801	3629772.48	216249.06	-7.41	WB
7802	3629772.55	216251.95	-7.40	WB
7803	3629772.56	216252.64	-7.38	WB
7804	3629772.60	216254.79	-7.37	WB
7805	3629772.65	216257.68	-7.35	WB
7806	3629772.71	216260.48	-7.34	WB
7807	3629772.77	216263.29	-7.32	WB
7808	3629772.88	216266.05	-7.31	WB
7809	3629773.00	216268.79	-7.29	WB
7810	3629773.16	216271.54	-7.28	WB
7811	3629773.35	216274.33	-7.26	WB
7812	3629773.56	216277.16	-7.25	WB
7813	3629773.64	216278.25	-7.24	WB
7814	3629773.78	216280.07	-7.23	WB
7815	3629774.01	216282.98	-7.21	WB
7816	3629774.19	216286.04	-7.20	WB
7817	3629774.35	216289.19	-7.19	WB
7818	3629774.47	216292.45	-7.18	WB
7819	3629774.50	216295.78	-7.17	WB
7820	3629774.52	216299.17	-7.16	WB
7821	3629774.49	216302.76	-7.15	WB
7822	3629774.49	216303.19	-7.14	WB
7823	3629774.45	216306.34	-7.13	WB
7824	3629774.40	216310.03	-7.12	WB
7825	3629774.31	216313.67	-7.11	WB
7826	3629774.22	216317.24	-7.10	WB
7827	3629774.09	216320.85	-7.09	WB
7828	3629773.96	216324.39	-7.08	WB
7829	3629773.82	216327.45	-7.06	WB
7830	3629773.79	216327.84	-7.05	WB
7831	3629773.56	216331.15	-7.04	WB
7832	3629773.33	216334.48	-7.03	WB
7833	3629772.97	216337.56	-7.02	WB
7834	3629772.59	216340.64	-7.00	WB
7835	3629772.16	216343.67	-6.99	WB
7836	3629771.69	216346.55	-6.97	WB
7837	3629771.20	216349.44	-6.96	WB
7838	3629770.68	216352.24	-6.95	WB
7839	3629770.14	216355.05	-6.93	WB
7840	3629769.67	216357.84	-6.92	WB
7841	3629769.24	216360.56	-6.91	WB
7842	3629768.81	216363.37	-6.89	WB
7843	3629768.50	216366.22	-6.88	WB
7844	3629768.19	216369.00	-6.87	WB
7845	3629768.02	216371.86	-6.86	WB
7846	3629767.92	216374.78	-6.85	WB
7847	3629767.86	216377.57	-6.84	WB
7848	3629767.88	216378.34	-6.83	WB
7849	3629767.95	216380.46	-6.82	WB
7850	3629768.06	216383.29	-6.81	WB
7851	3629768.29	216386.08	-6.81	WB
7852	3629768.56	216388.85	-6.80	WB
7853	3629768.87	216391.63	-6.80	WB
7854	3629769.24	216394.41	-6.80	WB
7855	3629769.62	216397.22	-6.79	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
7856	3629770.05	216400.00	-6.79	WB
7857	3629770.50	216402.87	-6.80	WB
7858	3629770.61	216403.54	-6.80	WB
7859	3629770.96	216405.75	-6.80	WB
7860	3629771.45	216408.65	-6.80	WB
7861	3629771.93	216411.56	-6.81	WB
7862	3629772.46	216414.56	-6.81	WB
7863	3629773.01	216417.55	-6.81	WB
7864	3629773.57	216420.60	-6.82	WB
7865	3629774.16	216423.71	-6.82	WB
7866	3629774.75	216426.81	-6.83	WB
7867	3629775.10	216428.89	-6.83	WB
7868	3629775.32	216430.19	-6.84	WB
7869	3629775.88	216433.46	-6.84	WB
7870	3629776.36	216436.88	-6.84	WB
7871	3629776.78	216440.43	-6.84	WB
7872	3629777.19	216443.94	-6.84	WB
7873	3629777.51	216447.65	-6.84	WB
7874	3629777.82	216451.29	-6.84	WB
7875	3629777.93	216453.10	-6.83	WB
7876	3629777.96	216454.89	-6.83	WB
7877	3629778.03	216458.59	-6.82	WB
7878	3629778.06	216462.18	-6.81	WB
7879	3629777.99	216465.71	-6.80	WB
7880	3629777.91	216469.23	-6.79	WB
7881	3629777.79	216472.65	-6.78	WB
7882	3629777.64	216476.00	-6.76	WB
7883	3629777.58	216477.26	-6.75	WB
7884	3629777.46	216479.29	-6.73	WB
7885	3629777.22	216482.52	-6.71	WB
7886	3629776.96	216485.76	-6.70	WB
7887	3629776.73	216488.88	-6.68	WB
7888	3629776.49	216491.99	-6.66	WB
7889	3629776.24	216495.07	-6.64	WB
7890	3629775.98	216498.08	-6.62	WB
7891	3629775.73	216501.00	-6.60	WB
7892	3629775.62	216502.39	-6.58	WB
7893	3629775.50	216503.83	-6.56	WB
7894	3629775.28	216506.70	-6.54	WB
7895	3629775.07	216509.46	-6.52	WB
7896	3629774.86	216512.19	-6.50	WB
7897	3629774.67	216514.87	-6.49	WB
7898	3629774.48	216517.48	-6.47	WB
7899	3629774.29	216520.17	-6.45	WB
7900	3629774.08	216522.87	-6.44	WB
7901	3629773.84	216525.61	-6.43	WB
7902	3629773.66	216527.65	-6.41	WB
7903	3629773.60	216528.33	-6.40	WB
7904	3629773.28	216531.23	-6.39	WB
7905	3629772.97	216534.12	-6.38	WB
7906	3629772.64	216537.16	-6.37	WB
7907	3629772.31	216540.18	-6.37	WB
7908	3629771.96	216543.28	-6.36	WB
7909	3629771.57	216546.53	-6.35	WB
7910	3629771.19	216549.78	-6.35	WB
7911	3629770.83	216552.77	-6.34	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
7912	3629770.78	216553.18	-6.33	WB
7913	3629770.36	216556.69	-6.33	WB
7914	3629769.93	216560.16	-6.32	WB
7915	3629769.46	216563.70	-6.31	WB
7916	3629768.97	216567.30	-6.31	WB
7917	3629768.55	216570.84	-6.30	WB
7918	3629768.11	216574.52	-6.30	WB
7919	3629767.73	216578.13	-6.29	WB
7920	3629767.42	216581.66	-6.28	WB
7921	3629767.11	216585.26	-6.27	WB
7922	3629766.96	216588.65	-6.26	WB
7923	3629766.83	216591.99	-6.25	WB
7924	3629766.73	216595.14	-6.24	WB
7925	3629766.67	216598.20	-6.23	WB
7926	3629766.62	216601.22	-6.22	WB
7927	3629766.61	216602.92	-6.21	WB
7928	3629766.60	216604.00	-6.20	WB
7929	3629766.58	216606.78	-6.19	WB
7930	3629766.53	216609.48	-6.18	WB
7931	3629766.44	216612.19	-6.17	WB
7932	3629766.33	216614.91	-6.16	WB
7933	3629766.21	216617.65	-6.15	WB
7934	3629766.06	216620.46	-6.13	WB
7935	3629765.91	216623.26	-6.12	WB
7936	3629765.75	216626.15	-6.11	WB
7937	3629765.64	216628.01	-6.11	WB
7938	3629765.61	216629.09	-6.10	WB
7939	3629765.58	216632.00	-6.09	WB
7940	3629765.56	216634.99	-6.08	WB
7941	3629765.67	216637.97	-6.07	WB
7942	3629765.82	216640.90	-6.07	WB
7943	3629766.00	216643.85	-6.06	WB
7944	3629766.24	216646.81	-6.06	WB
7945	3629766.49	216649.75	-6.05	WB
7946	3629766.82	216652.77	-6.05	WB
7947	3629766.91	216653.54	-6.05	WB
7948	3629767.17	216655.79	-6.04	WB
7949	3629767.52	216658.85	-6.04	WB
7950	3629767.85	216661.96	-6.04	WB
7951	3629768.18	216665.18	-6.04	WB
7952	3629768.51	216668.59	-6.04	WB
7953	3629768.83	216671.96	-6.04	WB
7954	3629769.17	216675.53	-6.03	WB
7955	3629769.47	216678.70	-6.03	WB
7956	3629769.52	216679.19	-6.03	WB
7957	3629769.87	216682.85	-6.03	WB
7958	3629770.24	216686.68	-6.02	WB
7959	3629770.62	216690.51	-6.02	WB
7960	3629771.00	216694.30	-6.01	WB
7961	3629771.41	216698.11	-6.01	WB
7962	3629771.83	216701.89	-6.00	WB
7963	3629772.03	216703.71	-5.99	WB
7964	3629772.23	216705.47	-5.98	WB
7965	3629772.64	216709.02	-5.97	WB
7966	3629772.99	216712.40	-5.96	WB
7967	3629773.32	216715.69	-5.95	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
7968	3629773.62	216718.97	-5.94	WB
7969	3629773.78	216721.89	-5.92	WB
7970	3629773.95	216724.86	-5.91	WB
7971	3629774.01	216727.34	-5.89	WB
7972	3629774.01	216727.70	-5.87	WB
7973	3629774.01	216730.41	-5.86	WB
7974	3629773.99	216733.15	-5.84	WB
7975	3629773.87	216735.72	-5.82	WB
7976	3629773.73	216738.28	-5.80	WB
7977	3629773.49	216740.85	-5.78	WB
7978	3629773.21	216743.37	-5.76	WB
7979	3629772.92	216745.89	-5.74	WB
7980	3629772.60	216748.37	-5.72	WB
7981	3629772.27	216750.86	-5.70	WB
7982	3629772.06	216752.47	-5.69	WB
7983	3629771.93	216753.42	-5.67	WB
7984	3629771.60	216755.97	-5.65	WB
7985	3629771.27	216758.53	-5.63	WB
7986	3629770.95	216761.12	-5.62	WB
7987	3629770.62	216763.75	-5.60	WB
7988	3629770.40	216766.53	-5.58	WB
7989	3629770.18	216769.22	-5.57	WB
7990	3629770.02	216772.10	-5.56	WB
7991	3629769.91	216775.01	-5.54	WB
7992	3629769.82	216777.88	-5.53	WB
7993	3629769.82	216778.31	-5.52	WB
7994	3629769.82	216781.08	-5.50	WB
7995	3629769.83	216784.24	-5.49	WB
7996	3629769.90	216787.62	-5.48	WB
7997	3629770.01	216791.06	-5.47	WB
7998	3629770.13	216794.43	-5.46	WB
7999	3629770.32	216798.06	-5.45	WB
8000	3629770.51	216801.69	-5.43	WB
8001	3629770.62	216803.59	-5.42	WB
8002	3629770.73	216805.46	-5.41	WB
8003	3629770.96	216809.07	-5.40	WB
8004	3629771.18	216812.70	-5.39	WB
8005	3629771.36	216816.26	-5.37	WB
8006	3629771.54	216819.71	-5.36	WB
8007	3629771.69	216823.11	-5.35	WB
8008	3629771.83	216826.33	-5.33	WB
8009	3629771.90	216827.93	-5.32	WB
8010	3629771.95	216829.46	-5.30	WB
8011	3629772.02	216832.58	-5.29	WB
8012	3629772.08	216835.57	-5.27	WB
8013	3629772.11	216838.44	-5.26	WB
8014	3629772.12	216841.39	-5.24	WB
8015	3629772.06	216844.20	-5.23	WB
8016	3629771.90	216846.96	-5.21	WB
8017	3629771.73	216849.80	-5.20	WB
8018	3629771.54	216852.48	-5.18	WB
8019	3629771.34	216855.19	-5.17	WB
8020	3629771.13	216857.87	-5.15	WB
8021	3629770.92	216860.54	-5.14	WB
8022	3629770.72	216863.21	-5.12	WB
8023	3629770.57	216865.92	-5.11	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
8024	3629770.45	216868.52	-5.09	WB
8025	3629770.37	216871.17	-5.08	WB
8026	3629770.32	216873.87	-5.07	WB
8027	3629770.27	216876.54	-5.06	WB
8028	3629770.26	216877.91	-5.05	WB
8029	3629770.24	216879.38	-5.04	WB
8030	3629770.19	216882.19	-5.03	WB
8031	3629770.17	216885.14	-5.02	WB
8032	3629770.15	216888.26	-5.01	WB
8033	3629770.12	216891.40	-5.00	WB
8034	3629770.10	216894.64	-4.99	WB
8035	3629770.08	216897.98	-4.99	WB
8036	3629770.19	216901.40	-4.98	WB
8037	3629770.29	216903.56	-4.98	WB
8038	3629770.35	216904.84	-4.98	WB
8039	3629770.55	216908.29	-4.98	WB
8040	3629770.82	216911.81	-4.98	WB
8041	3629771.10	216915.30	-4.98	WB
8042	3629771.49	216918.75	-4.98	WB
8043	3629771.91	216922.21	-4.98	WB
8044	3629772.31	216925.60	-4.98	WB
8045	3629772.62	216928.21	-4.97	WB
8046	3629772.72	216929.13	-4.96	WB
8047	3629773.11	216932.50	-4.94	WB
8048	3629773.44	216935.79	-4.93	WB
8049	3629773.78	216939.23	-4.92	WB
8050	3629774.09	216942.45	-4.90	WB
8051	3629774.37	216945.67	-4.88	WB
8052	3629774.65	216948.90	-4.86	WB
8053	3629774.94	216952.03	-4.83	WB
8054	3629775.04	216953.20	-4.81	WB
8055	3629775.22	216955.17	-4.78	WB
8056	3629775.54	216958.30	-4.75	WB
8057	3629775.87	216961.38	-4.72	WB
8058	3629776.21	216964.46	-4.68	WB
8059	3629776.56	216967.61	-4.64	WB
8060	3629776.92	216970.75	-4.60	WB
8061	3629777.25	216974.03	-4.56	WB
8062	3629777.58	216977.31	-4.51	WB
8063	3629777.66	216978.14	-4.46	WB
8064	3629777.88	216980.60	-4.41	WB
8065	3629778.12	216983.94	-4.36	WB
8066	3629778.36	216987.27	-4.31	WB
8067	3629778.54	216990.59	-4.26	WB
8068	3629778.70	216993.96	-4.20	WB
8069	3629778.80	216997.22	-4.15	WB
8070	3629778.79	217000.49	-4.10	WB
8071	3629778.79	217002.59	-4.04	WB
8072	3629778.79	217003.81	-3.99	WB
8073	3629778.65	217006.88	-3.93	WB
8074	3629778.49	217010.06	-3.88	WB
8075	3629778.29	217013.06	-3.82	WB
8076	3629778.04	217015.85	-3.76	WB
8077	3629777.78	217018.78	-3.70	WB
8078	3629777.42	217021.32	-3.63	WB
8079	3629777.05	217023.90	-3.57	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
8080	3629776.64	217026.42	-3.51	WB
8081	3629776.50	217027.29	-3.45	WB
8082	3629776.23	217028.82	-3.39	WB
8083	3629775.79	217031.32	-3.34	WB
8084	3629775.41	217033.59	-3.29	WB
8085	3629775.02	217035.87	-3.23	WB
8086	3629774.74	217038.03	-3.17	WB
8087	3629774.78	217040.78	-3.11	WB
8088	3629774.83	217043.52	-3.05	WB
8089	3629774.87	217046.27	-2.98	WB
8090	3629774.92	217049.01	-2.92	WB
8091	3629774.96	217051.76	-2.88	WB
8092	3629775.00	217054.50	-2.86	WB
8093	3629775.05	217057.25	-2.85	WB
8094	3629775.09	217059.99	-2.83	WB
8095	3629775.14	217062.74	-2.83	WB
8096	3629775.18	217065.48	-2.83	WB
8097	3629775.23	217068.23	-2.84	WB
8098	3629775.27	217070.97	-2.84	WB
8099	3629775.31	217073.72	-2.85	WB
8100	3629775.36	217076.47	-2.86	WB
8101	3629775.40	217079.21	-2.86	WB
8102	3629775.45	217081.96	-2.85	WB
8103	3629775.49	217084.70	-2.86	WB
8104	3629775.53	217087.45	-2.86	WB
8105	3629775.58	217090.19	-2.87	WB
8106	3629775.68	217093.22	-2.87	WB
8107	3629775.77	217096.26	-2.88	WB
8108	3629775.87	217099.29	-2.89	WB
8109	3629775.96	217102.32	-2.90	WB
8110	3629776.06	217105.35	-2.91	WB
8111	3629776.16	217108.38	-2.92	WB
8112	3629776.25	217111.41	-2.95	WB
8113	3629776.35	217114.45	-2.98	WB
8114	3629776.49	217116.92	-3.02	WB
8115	3629776.67	217119.47	-3.05	WB
8116	3629776.89	217122.00	-3.08	WB
8117	3629777.11	217124.53	-3.12	WB
8118	3629777.28	217127.13	-3.15	WB
8119	3629777.47	217129.71	-3.18	WB
8120	3629777.49	217130.05	-3.23	WB
8121	3629777.58	217132.31	-3.27	WB
8122	3629777.69	217134.91	-3.31	WB
8123	3629777.77	217137.53	-3.35	WB
8124	3629777.78	217140.10	-3.39	WB
8125	3629777.80	217142.66	-3.43	WB
8126	3629777.66	217145.08	-3.47	WB
8127	3629777.49	217147.50	-3.51	WB
8128	3629777.27	217149.88	-3.56	WB
8129	3629776.99	217152.03	-3.60	WB
8130	3629776.81	217153.41	-3.64	WB
8131	3629281.81	215658.54	-9.03	WB
8132	3629280.74	215661.94	-9.02	WB
8133	3629279.68	215665.31	-9.01	WB
8134	3629278.70	215668.89	-8.99	WB
8135	3629277.81	215672.62	-8.98	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
8136	3629277.48	215673.98	-8.97	WB
8137	3629276.97	215676.22	-8.95	WB
8138	3629276.32	215679.92	-8.94	WB
8139	3629275.71	215683.53	-8.93	WB
8140	3629275.29	215686.87	-8.92	WB
8141	3629274.99	215690.20	-8.91	WB
8142	3629274.74	215693.39	-8.90	WB
8143	3629274.68	215696.30	-8.89	WB
8144	3629274.63	215699.20	-8.89	WB
8145	3629274.65	215701.98	-8.88	WB
8146	3629274.68	215704.75	-8.87	WB
8147	3629274.72	215707.53	-8.87	WB
8148	3629274.80	215710.33	-8.86	WB
8149	3629274.87	215713.14	-8.85	WB
8150	3629274.96	215716.02	-8.85	WB
8151	3629275.05	215718.93	-8.85	WB
8152	3629275.16	215721.88	-8.84	WB
8153	3629275.29	215724.47	-8.84	WB
8154	3629275.31	215724.86	-8.84	WB
8155	3629275.45	215727.74	-8.84	WB
8156	3629275.64	215730.69	-8.84	WB
8157	3629275.85	215733.66	-8.84	WB
8158	3629276.10	215736.60	-8.84	WB
8159	3629276.42	215739.65	-8.84	WB
8160	3629276.72	215742.66	-8.84	WB
8161	3629276.90	215745.96	-8.84	WB
8162	3629277.07	215749.38	-8.84	WB
8163	3629277.09	215749.79	-8.84	WB
8164	3629277.23	215752.98	-8.84	WB
8165	3629277.38	215756.69	-8.84	WB
8166	3629277.54	215760.46	-8.84	WB
8167	3629277.73	215764.42	-8.84	WB
8168	3629277.92	215768.23	-8.84	WB
8169	3629278.18	215771.96	-8.84	WB
8170	3629278.40	215774.66	-8.83	WB
8171	3629278.48	215775.62	-8.83	WB
8172	3629278.79	215779.06	-8.83	WB
8173	3629279.08	215782.20	-8.82	WB
8174	3629279.38	215785.39	-8.82	WB
8175	3629279.62	215788.27	-8.81	WB
8176	3629279.81	215791.19	-8.80	WB
8177	3629279.93	215794.10	-8.80	WB
8178	3629279.92	215796.99	-8.79	WB
8179	3629279.90	215798.89	-8.78	WB
8180	3629279.89	215800.00	-8.77	WB
8181	3629279.79	215803.15	-8.76	WB
8182	3629279.66	215806.30	-8.75	WB
8183	3629279.52	215809.47	-8.74	WB
8184	3629279.35	215812.74	-8.73	WB
8185	3629279.19	215816.01	-8.72	WB
8186	3629279.02	215819.29	-8.71	WB
8187	3629278.87	215822.47	-8.69	WB
8188	3629278.79	215824.09	-8.68	WB
8189	3629278.71	215825.58	-8.67	WB
8190	3629278.55	215828.64	-8.66	WB
8191	3629278.40	215831.60	-8.65	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
8192	3629277.94	215838.90	-8.64	WB
8193	3629277.66	215841.85	-8.63	WB
8194	3629277.36	215844.87	-8.62	WB
8195	3629277.02	215847.96	-8.61	WB
8196	3629276.93	215848.77	-8.60	WB
8197	3629276.65	215851.15	-8.59	WB
8198	3629276.27	215854.42	-8.58	WB
8199	3629275.94	215857.74	-8.58	WB
8200	3629275.60	215861.16	-8.57	WB
8201	3629275.35	215864.56	-8.56	WB
8202	3629275.14	215867.91	-8.56	WB
8203	3629274.99	215871.29	-8.55	WB
8204	3629275.00	215874.13	-8.55	WB
8205	3629275.01	215874.57	-8.54	WB
8206	3629275.04	215877.82	-8.54	WB
8207	3629275.16	215880.96	-8.53	WB
8208	3629275.29	215884.11	-8.53	WB
8209	3629275.41	215887.33	-8.52	WB
8210	3629275.50	215890.56	-8.52	WB
8211	3629275.57	215893.82	-8.51	WB
8212	3629275.65	215897.26	-8.51	WB
8213	3629275.70	215899.38	-8.50	WB
8214	3629275.73	215900.73	-8.50	WB
8215	3629275.84	215904.26	-8.49	WB
8216	3629275.99	215907.88	-8.49	WB
8217	3629276.14	215911.54	-8.48	WB
8218	3629276.42	215915.05	-8.48	WB
8219	3629276.72	215918.63	-8.47	WB
8220	3629277.06	215922.15	-8.46	WB
8221	3629277.34	215924.66	-8.45	WB
8222	3629277.43	215925.46	-8.45	WB
8223	3629277.83	215928.91	-8.44	WB
8224	3629278.27	215931.97	-8.43	WB
8225	3629278.71	215935.03	-8.42	WB
8226	3629279.16	215938.19	-8.41	WB
8227	3629279.58	215941.23	-8.40	WB
8228	3629280.02	215944.44	-8.39	WB
8229	3629280.43	215947.64	-8.38	WB
8230	3629280.68	215949.59	-8.36	WB
8231	3629280.83	215950.79	-8.35	WB
8232	3629281.25	215954.00	-8.34	WB
8233	3629281.68	215957.21	-8.33	WB
8234	3629282.12	215960.38	-8.31	WB
8235	3629282.56	215963.39	-8.30	WB
8236	3629283.00	215966.37	-8.29	WB
8237	3629283.40	215969.23	-8.27	WB
8238	3629283.78	215972.07	-8.26	WB
8239	3629284.01	215973.86	-8.25	WB
8240	3629284.11	215974.94	-8.24	WB
8241	3629284.33	215977.69	-8.23	WB
8242	3629284.54	215980.51	-8.22	WB
8243	3629284.64	215983.38	-8.21	WB
8244	3629284.71	215986.17	-8.20	WB
8245	3629284.77	215989.07	-8.19	WB
8246	3629284.80	215991.94	-8.18	WB
8247	3629284.83	215994.78	-8.17	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
8248	3629284.86	215997.80	-8.17	WB
8249	3629284.87	215998.92	-8.16	WB
8250	3629284.89	216000.80	-8.16	WB
8251	3629284.87	216003.81	-8.15	WB
8252	3629284.81	216007.03	-8.15	WB
8253	3629284.74	216010.21	-8.14	WB
8254	3629284.62	216013.50	-8.14	WB
8255	3629284.50	216016.82	-8.14	WB
8256	3629284.33	216020.30	-8.14	WB
8257	3629284.14	216023.69	-8.13	WB
8258	3629284.11	216024.16	-8.13	WB
8259	3629283.94	216027.11	-8.13	WB
8260	3629283.69	216030.62	-8.13	WB
8261	3629283.45	216034.02	-8.12	WB
8262	3629283.22	216037.56	-8.12	WB
8263	3629283.01	216041.00	-8.12	WB
8264	3629282.79	216044.43	-8.11	WB
8265	3629282.51	216047.99	-8.11	WB
8266	3629282.44	216048.82	-8.10	WB
8267	3629282.22	216051.51	-8.10	WB
8268	3629281.92	216055.12	-8.09	WB
8269	3629281.62	216058.75	-8.08	WB
8270	3629281.31	216062.41	-8.07	WB
8271	3629280.99	216066.07	-8.06	WB
8272	3629280.67	216069.79	-8.05	WB
8273	3629280.39	216073.34	-8.04	WB
8274	3629280.35	216073.82	-8.03	WB
8275	3629280.11	216076.97	-8.01	WB
8276	3629279.86	216080.58	-8.00	WB
8277	3629279.67	216083.97	-7.98	WB
8278	3629279.47	216087.46	-7.97	WB
8279	3629279.32	216090.64	-7.95	WB
8280	3629279.17	216093.79	-7.94	WB
8281	3629279.05	216096.98	-7.92	WB
8282	3629278.98	216098.88	-7.90	WB
8283	3629278.94	216100.01	-7.88	WB
8284	3629278.84	216102.99	-7.87	WB
8285	3629278.77	216105.98	-7.85	WB
8286	3629278.69	216108.95	-7.84	WB
8287	3629278.63	216111.87	-7.82	WB
8288	3629278.58	216114.85	-7.81	WB
8289	3629278.52	216117.81	-7.79	WB
8290	3629278.49	216120.77	-7.78	WB
8291	3629278.45	216123.77	-7.77	WB
8292	3629278.45	216124.12	-7.75	WB
8293	3629278.46	216126.64	-7.74	WB
8294	3629278.49	216129.54	-7.74	WB
8295	3629278.54	216132.43	-7.73	WB
8296	3629278.68	216135.31	-7.72	WB
8297	3629278.82	216138.19	-7.71	WB
8298	3629279.08	216141.10	-7.71	WB
8299	3629279.38	216144.02	-7.71	WB
8300	3629279.70	216146.92	-7.70	WB
8301	3629280.08	216149.71	-7.70	WB
8302	3629280.13	216150.08	-7.70	WB
8303	3629280.55	216153.18	-7.70	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
8304	3629281.01	216156.46	-7.69	WB
8305	3629281.49	216159.87	-7.69	WB
8306	3629281.95	216163.38	-7.69	WB
8307	3629282.39	216166.99	-7.69	WB
8308	3629282.83	216170.60	-7.69	WB
8309	3629283.20	216174.34	-7.69	WB
8310	3629283.57	216178.07	-7.68	WB
8311	3629283.92	216181.81	-7.68	WB
8312	3629284.24	216185.53	-7.68	WB
8313	3629284.57	216189.25	-7.67	WB
8314	3629284.74	216192.78	-7.67	WB
8315	3629284.91	216196.36	-7.66	WB
8316	3629285.01	216199.05	-7.66	WB
8317	3629285.03	216199.85	-7.65	WB
8318	3629285.11	216203.28	-7.64	WB
8319	3629285.18	216206.59	-7.63	WB
8320	3629285.15	216209.76	-7.62	WB
8321	3629285.11	216213.04	-7.61	WB
8322	3629285.05	216216.12	-7.60	WB
8323	3629284.98	216219.18	-7.59	WB
8324	3629284.93	216222.14	-7.58	WB
8325	3629284.91	216223.86	-7.56	WB
8326	3629284.89	216224.90	-7.55	WB
8327	3629284.86	216227.71	-7.54	WB
8328	3629284.82	216230.44	-7.52	WB
8329	3629284.77	216233.19	-7.51	WB
8330	3629284.71	216235.97	-7.50	WB
8331	3629284.61	216238.82	-7.49	WB
8332	3629284.51	216241.67	-7.48	WB
8333	3629284.42	216244.68	-7.46	WB
8334	3629284.32	216247.76	-7.45	WB
8335	3629284.28	216249.27	-7.44	WB
8336	3629284.22	216250.87	-7.43	WB
8337	3629284.11	216254.13	-7.42	WB
8338	3629284.00	216257.41	-7.42	WB
8339	3629283.96	216260.56	-7.41	WB
8340	3629283.94	216263.83	-7.40	WB
8341	3629283.91	216267.05	-7.39	WB
8342	3629283.86	216270.22	-7.39	WB
8343	3629283.82	216273.44	-7.38	WB
8344	3629283.82	216273.85	-7.38	WB
8345	3629283.78	216276.63	-7.37	WB
8346	3629283.75	216279.80	-7.37	WB
8347	3629283.69	216282.95	-7.36	WB
8348	3629283.60	216286.11	-7.36	WB
8349	3629283.51	216289.29	-7.36	WB
8350	3629283.37	216292.46	-7.36	WB
8351	3629283.23	216295.70	-7.35	WB
8352	3629283.06	216298.86	-7.35	WB
8353	3629282.86	216302.11	-7.35	WB
8354	3629282.66	216305.38	-7.34	WB
8355	3629282.14	216313.98	-7.34	WB
8356	3629281.95	216317.24	-7.33	WB
8357	3629281.77	216320.50	-7.33	WB
8358	3629281.56	216323.79	-7.32	WB
8359	3629281.35	216327.07	-7.32	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
8360	3629281.12	216330.43	-7.31	WB
8361	3629280.88	216333.79	-7.30	WB
8362	3629280.63	216337.21	-7.30	WB
8363	3629280.32	216340.64	-7.29	WB
8364	3629280.01	216344.05	-7.28	WB
8365	3629279.71	216347.56	-7.27	WB
8366	3629279.65	216348.39	-7.26	WB
8367	3629279.43	216351.06	-7.25	WB
8368	3629279.16	216354.56	-7.23	WB
8369	3629278.83	216357.99	-7.22	WB
8370	3629278.49	216361.44	-7.21	WB
8371	3629278.13	216364.79	-7.19	WB
8372	3629277.76	216368.07	-7.18	WB
8373	3629277.38	216371.35	-7.16	WB
8374	3629277.08	216373.30	-7.15	WB
8375	3629276.90	216374.46	-7.13	WB
8376	3629276.41	216377.59	-7.11	WB
8377	3629275.82	216380.62	-7.10	WB
8378	3629275.15	216383.61	-7.08	WB
8379	3629274.44	216386.66	-7.06	WB
8380	3629273.73	216389.56	-7.04	WB
8381	3629273.00	216392.51	-7.03	WB
8382	3629272.36	216395.51	-7.01	WB
8383	3629271.77	216398.45	-6.99	WB
8384	3629271.69	216398.84	-6.98	WB
8385	3629271.22	216401.50	-6.96	WB
8386	3629270.82	216404.57	-6.95	WB
8387	3629270.42	216407.59	-6.93	WB
8388	3629270.16	216410.79	-6.92	WB
8389	3629269.94	216413.88	-6.91	WB
8390	3629269.79	216417.06	-6.90	WB
8391	3629269.74	216420.20	-6.88	WB
8392	3629269.71	216423.27	-6.87	WB
8393	3629269.74	216424.51	-6.86	WB
8394	3629269.81	216426.45	-6.85	WB
8395	3629269.93	216429.52	-6.85	WB
8396	3629270.09	216432.58	-6.84	WB
8397	3629270.28	216435.61	-6.83	WB
8398	3629270.46	216438.64	-6.82	WB
8399	3629270.70	216441.64	-6.82	WB
8400	3629270.93	216444.65	-6.81	WB
8401	3629271.16	216447.77	-6.81	WB
8402	3629271.28	216449.32	-6.80	WB
8403	3629271.39	216450.92	-6.80	WB
8404	3629271.59	216454.13	-6.79	WB
8405	3629271.73	216457.50	-6.79	WB
8406	3629271.86	216460.88	-6.78	WB
8407	3629272.03	216464.35	-6.78	WB
8408	3629272.22	216467.81	-6.77	WB
8409	3629272.41	216471.32	-6.76	WB
8410	3629272.57	216474.46	-6.76	WB
8411	3629272.60	216474.93	-6.75	WB
8412	3629272.78	216478.43	-6.75	WB
8413	3629272.97	216482.03	-6.74	WB
8414	3629273.16	216485.56	-6.73	WB
8415	3629273.33	216489.03	-6.72	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
8416	3629273.49	216492.52	-6.72	WB
8417	3629273.65	216495.95	-6.71	WB
8418	3629273.77	216499.19	-6.70	WB
8419	3629273.90	216502.50	-6.69	WB
8420	3629274.04	216505.81	-6.68	WB
8421	3629274.21	216509.00	-6.67	WB
8422	3629274.38	216512.19	-6.66	WB
8423	3629274.57	216515.35	-6.65	WB
8424	3629274.76	216518.43	-6.64	WB
8425	3629274.96	216521.63	-6.63	WB
8426	3629275.13	216524.33	-6.62	WB
8427	3629275.16	216524.75	-6.61	WB
8428	3629275.36	216527.88	-6.60	WB
8429	3629275.57	216531.05	-6.59	WB
8430	3629275.78	216534.11	-6.58	WB
8431	3629276.02	216537.21	-6.57	WB
8432	3629276.30	216540.33	-6.56	WB
8433	3629276.57	216543.32	-6.55	WB
8434	3629276.91	216546.35	-6.54	WB
8435	3629277.25	216549.34	-6.53	WB
8436	3629277.59	216552.28	-6.52	WB
8437	3629277.93	216555.18	-6.52	WB
8438	3629278.26	216558.08	-6.51	WB
8439	3629278.54	216561.01	-6.50	WB
8440	3629278.83	216563.94	-6.50	WB
8441	3629279.00	216566.96	-6.49	WB
8442	3629279.13	216570.04	-6.49	WB
8443	3629279.21	216573.22	-6.48	WB
8444	3629279.21	216574.05	-6.48	WB
8445	3629279.20	216576.57	-6.47	WB
8446	3629279.17	216579.83	-6.47	WB
8447	3629279.04	216583.34	-6.46	WB
8448	3629278.89	216586.92	-6.46	WB
8449	3629278.71	216590.48	-6.46	WB
8450	3629278.50	216594.18	-6.45	WB
8451	3629278.29	216597.83	-6.45	WB
8452	3629278.22	216599.13	-6.44	WB
8453	3629278.10	216601.42	-6.44	WB
8454	3629277.92	216605.11	-6.43	WB
8455	3629277.77	216608.67	-6.42	WB
8456	3629277.64	216612.18	-6.42	WB
8457	3629277.52	216615.65	-6.41	WB
8458	3629277.42	216619.04	-6.40	WB
8459	3629277.33	216622.42	-6.40	WB
8460	3629277.29	216623.73	-6.39	WB
8461	3629277.17	216625.76	-6.38	WB
8462	3629276.97	216629.11	-6.37	WB
8463	3629276.76	216632.40	-6.36	WB
8464	3629276.49	216635.75	-6.35	WB
8465	3629276.21	216639.02	-6.34	WB
8466	3629275.93	216642.31	-6.33	WB
8467	3629275.64	216645.63	-6.32	WB
8468	3629275.38	216648.80	-6.31	WB
8469	3629275.15	216651.95	-6.29	WB
8470	3629274.93	216655.13	-6.28	WB
8471	3629274.82	216658.12	-6.27	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
8472	3629274.72	216661.17	-6.26	WB
8473	3629274.66	216664.19	-6.25	WB
8474	3629274.66	216667.09	-6.24	WB
8475	3629274.64	216670.14	-6.23	WB
8476	3629274.68	216673.10	-6.22	WB
8477	3629274.69	216674.24	-6.21	WB
8478	3629274.71	216676.18	-6.20	WB
8479	3629274.80	216679.27	-6.19	WB
8480	3629274.96	216682.34	-6.18	WB
8481	3629275.13	216685.51	-6.17	WB
8482	3629275.46	216688.71	-6.16	WB
8483	3629275.80	216691.91	-6.15	WB
8484	3629276.22	216695.07	-6.14	WB
8485	3629276.73	216698.28	-6.14	WB
8486	3629276.98	216699.85	-6.13	WB
8487	3629277.25	216701.47	-6.12	WB
8488	3629277.92	216704.68	-6.12	WB
8489	3629278.59	216707.88	-6.11	WB
8490	3629279.32	216711.08	-6.10	WB
8491	3629280.08	216714.35	-6.09	WB
8492	3629280.87	216717.59	-6.09	WB
8493	3629281.76	216720.85	-6.08	WB
8494	3629282.67	216724.11	-6.07	WB
8495	3629282.89	216724.88	-6.06	WB
8496	3629283.58	216727.25	-6.06	WB
8497	3629284.51	216730.35	-6.05	WB
8498	3629285.43	216733.46	-6.04	WB
8499	3629286.22	216736.43	-6.03	WB
8500	3629287.06	216739.48	-6.02	WB
8501	3629287.65	216742.46	-6.01	WB
8502	3629288.17	216745.35	-6.00	WB
8503	3629288.56	216748.32	-5.99	WB
8504	3629288.68	216751.18	-5.97	WB
8505	3629288.76	216754.10	-5.96	WB
8506	3629288.59	216756.87	-5.95	WB
8507	3629288.38	216759.64	-5.94	WB
8508	3629288.11	216762.36	-5.92	WB
8509	3629287.76	216765.03	-5.91	WB
8510	3629287.42	216767.69	-5.89	WB
8511	3629286.96	216770.35	-5.88	WB
8512	3629286.50	216773.01	-5.86	WB
8513	3629286.02	216775.66	-5.85	WB
8514	3629284.53	216782.92	-5.83	WB
8515	3629283.85	216785.70	-5.82	WB
8516	3629283.13	216788.58	-5.80	WB
8517	3629282.36	216791.47	-5.78	WB
8518	3629281.59	216794.32	-5.77	WB
8519	3629280.81	216797.32	-5.75	WB
8520	3629280.63	216798.04	-5.73	WB
8521	3629280.04	216800.30	-5.72	WB
8522	3629279.27	216803.36	-5.70	WB
8523	3629278.52	216806.46	-5.68	WB
8524	3629277.76	216809.56	-5.66	WB
8525	3629277.08	216812.80	-5.65	WB
8526	3629276.41	216816.06	-5.63	WB
8527	3629275.77	216819.43	-5.61	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
8528	3629275.20	216822.91	-5.59	WB
8529	3629275.06	216823.79	-5.57	WB
8530	3629274.63	216826.43	-5.55	WB
8531	3629274.20	216829.96	-5.54	WB
8532	3629273.77	216833.59	-5.52	WB
8533	3629273.44	216837.15	-5.50	WB
8534	3629273.18	216840.69	-5.48	WB
8535	3629272.94	216844.25	-5.46	WB
8536	3629272.82	216847.59	-5.44	WB
8537	3629272.76	216849.26	-5.41	WB
8538	3629272.70	216850.97	-5.39	WB
8539	3629272.64	216854.29	-5.37	WB
8540	3629272.61	216857.44	-5.35	WB
8541	3629272.59	216860.55	-5.33	WB
8542	3629272.62	216863.66	-5.30	WB
8543	3629272.64	216866.73	-5.28	WB
8544	3629272.69	216869.76	-5.25	WB
8545	3629272.74	216872.80	-5.23	WB
8546	3629272.76	216873.92	-5.21	WB
8547	3629272.81	216875.82	-5.18	WB
8548	3629272.94	216878.87	-5.16	WB
8549	3629273.07	216881.93	-5.13	WB
8550	3629273.28	216885.07	-5.11	WB
8551	3629273.52	216888.18	-5.08	WB
8552	3629273.78	216891.37	-5.05	WB
8553	3629274.09	216894.53	-5.04	WB
8554	3629274.41	216897.72	-5.02	WB
8555	3629274.66	216899.68	-5.01	WB
8556	3629274.83	216900.96	-5.00	WB
8557	3629275.26	216904.07	-4.99	WB
8558	3629275.72	216907.23	-4.97	WB
8559	3629276.21	216910.35	-4.96	WB
8560	3629276.70	216913.36	-4.94	WB
8561	3629277.19	216916.38	-4.93	WB
8562	3629277.68	216919.33	-4.91	WB
8563	3629278.15	216922.22	-4.90	WB
8564	3629278.49	216924.45	-4.88	WB
8565	3629278.59	216925.16	-4.86	WB
8566	3629279.03	216928.11	-4.84	WB
8567	3629279.34	216931.17	-4.82	WB
8568	3629279.65	216934.25	-4.80	WB
8569	3629279.91	216937.44	-4.78	WB
8570	3629280.14	216940.63	-4.75	WB
8571	3629280.34	216943.94	-4.73	WB
8572	3629280.41	216947.32	-4.70	WB
8573	3629280.45	216948.97	-4.67	WB
8574	3629280.48	216950.62	-4.64	WB
8575	3629280.58	216954.11	-4.60	WB
8576	3629280.68	216957.44	-4.56	WB
8577	3629280.78	216960.73	-4.52	WB
8578	3629280.85	216964.00	-4.48	WB
8579	3629280.92	216967.15	-4.44	WB
8580	3629280.96	216970.25	-4.39	WB
8581	3629280.99	216973.31	-4.34	WB
8582	3629280.99	216973.67	-4.28	WB
8583	3629280.99	216976.22	-4.22	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
8584	3629280.94	216979.08	-4.16	WB
8585	3629280.88	216981.92	-4.10	WB
8586	3629280.77	216984.58	-4.03	WB
8587	3629280.64	216987.32	-3.97	WB
8588	3629280.51	216990.00	-3.90	WB
8589	3629280.36	216992.63	-3.83	WB
8590	3629280.20	216995.28	-3.75	WB
8591	3629280.07	216997.97	-3.68	WB
8592	3629280.03	216998.69	-3.60	WB
8593	3629279.93	217000.65	-3.53	WB
8594	3629279.80	217003.34	-3.46	WB
8595	3629279.68	217005.97	-3.38	WB
8596	3629279.58	217008.69	-3.31	WB
8597	3629279.60	217011.75	-3.25	WB
8598	3629279.62	217014.79	-3.18	WB
8599	3629279.67	217017.80	-3.12	WB
8600	3629279.74	217020.80	-3.07	WB
8601	3629279.81	217023.80	-3.02	WB
8602	3629279.90	217026.85	-2.97	WB
8603	3629279.98	217029.81	-2.93	WB
8604	3629280.02	217032.74	-2.89	WB
8605	3629280.04	217035.75	-2.86	WB
8606	3629280.07	217038.72	-2.83	WB
8607	3629280.11	217041.63	-2.81	WB
8608	3629280.15	217044.45	-2.80	WB
8609	3629280.10	217047.27	-2.79	WB
8610	3629280.06	217048.74	-2.79	WB
8611	3629280.02	217050.13	-2.79	WB
8612	3629279.92	217052.90	-2.80	WB
8613	3629279.77	217055.69	-2.80	WB
8614	3629279.62	217058.53	-2.81	WB
8615	3629279.44	217061.30	-2.83	WB
8616	3629279.24	217064.18	-2.84	WB
8617	3629279.06	217066.90	-2.85	WB
8618	3629278.86	217069.69	-2.87	WB
8619	3629278.66	217072.52	-2.90	WB
8620	3629278.57	217073.85	-2.93	WB
8621	3629278.47	217075.22	-2.96	WB
8622	3629278.27	217078.07	-2.98	WB
8623	3629278.05	217080.78	-3.00	WB
8624	3629277.82	217083.47	-2.99	WB
8625	3629277.59	217086.19	-2.99	WB
8626	3629277.39	217088.77	-2.99	WB
8627	3629277.18	217091.40	-3.01	WB
8628	3629276.94	217093.97	-3.04	WB
8629	3629276.71	217096.41	-3.07	WB
8630	3629276.48	217098.85	-3.13	WB
8631	3629276.30	217101.12	-3.23	WB
8632	3629276.13	217103.37	-3.32	WB
8633	3629275.96	217105.45	-3.42	WB
8634	3629275.79	217107.45	-3.53	WB
8635	3629275.64	217109.40	-3.66	WB
8636	3629275.49	217111.19	-3.78	WB
8637	3629275.35	217113.00	-3.91	WB
8638	3629275.18	217114.81	-4.07	WB
8639	3629274.99	217116.65	-4.20	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
8640	3629274.80	217118.50	-4.30	WB
8641	3629274.60	217120.44	-4.41	WB
8642	3629274.38	217122.43	-4.52	WB
8643	3629274.21	217123.95	-4.61	WB
8644	3629274.15	217124.44	-4.69	WB
8645	3629273.92	217126.55	-4.73	WB
8646	3629273.73	217128.53	-4.76	WB
8647	3629273.58	217130.53	-4.76	WB
8648	3629273.42	217132.63	-4.73	WB
8649	3629273.32	217134.63	-4.70	WB
8650	3629273.22	217136.69	-4.66	WB
8651	3629273.16	217138.82	-4.59	WB
8652	3629273.12	217140.88	-4.52	WB
8653	3629273.09	217143.03	-4.46	WB
8654	3629273.09	217145.17	-4.39	WB
8655	3629273.10	217147.29	-4.30	WB
8656	3629273.13	217149.18	-4.20	WB
8657	3629273.13	217149.42	-4.11	WB
8658	3629273.20	217151.46	-4.01	WB
8659	3629273.28	217153.41	-3.91	WB
8660	3629273.41	217155.18	-3.81	WB
8661	3629273.54	217156.93	-3.71	WB
8662	3629273.67	217158.50	-3.61	WB
8663	3629273.80	217160.02	-3.51	WB
8664	3629273.92	217161.47	-3.47	WB
8665	3629274.04	217162.85	-3.40	WB
8666	3629274.16	217164.26	-3.32	WB
8667	3629274.29	217165.61	-3.26	WB
8668	3629274.42	217167.00	-3.21	WB
8669	3629274.54	217168.34	-3.16	WB
8670	3629274.68	217169.65	-3.12	WB
8671	3629274.81	217170.98	-3.07	WB
8672	3629275.09	217174.58	-3.02	WB
8673	3629275.09	217174.80	-2.98	WB
8674	3629275.10	217176.49	-2.93	WB
8675	3629275.10	217178.17	-2.89	WB
8676	3629275.06	217180.10	-2.85	WB
8677	3629275.00	217182.12	-2.80	WB
8678	3629274.95	217184.21	-2.76	WB
8679	3629274.88	217186.37	-2.72	WB
8680	3628778.83	215664.26	-9.19	WB
8681	3628778.72	215667.20	-9.20	WB
8682	3628778.61	215670.10	-9.22	WB
8683	3628778.45	215673.06	-9.20	WB
8684	3628778.25	215676.03	-9.20	WB
8685	3628778.12	215677.89	-9.21	WB
8686	3628778.04	215678.97	-9.20	WB
8687	3628777.78	215681.96	-9.20	WB
8688	3628777.52	215684.95	-9.18	WB
8689	3628777.25	215687.85	-9.17	WB
8690	3628776.95	215690.77	-9.16	WB
8691	3628776.65	215693.58	-9.14	WB
8692	3628776.28	215696.40	-9.14	WB
8693	3628775.91	215699.26	-9.13	WB
8694	3628775.51	215702.02	-9.13	WB
8695	3628775.45	215702.40	-9.13	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
8696	3628775.08	215704.84	-9.12	WB
8697	3628774.64	215707.62	-9.12	WB
8698	3628774.17	215710.40	-9.12	WB
8699	3628773.68	215713.30	-9.12	WB
8700	3628773.23	215716.28	-9.11	WB
8701	3628772.80	215719.24	-9.11	WB
8702	3628772.41	215722.36	-9.11	WB
8703	3628772.11	215725.58	-9.11	WB
8704	3628771.85	215728.43	-9.10	WB
8705	3628771.81	215728.80	-9.10	WB
8706	3628771.68	215732.11	-9.10	WB
8707	3628771.57	215735.48	-9.10	WB
8708	3628771.55	215738.76	-9.09	WB
8709	3628771.64	215742.07	-9.09	WB
8710	3628771.72	215745.48	-9.08	WB
8711	3628771.93	215748.79	-9.08	WB
8712	3628772.14	215752.10	-9.07	WB
8713	3628772.22	215753.38	-9.07	WB
8714	3628772.41	215755.33	-9.06	WB
8715	3628772.73	215758.55	-9.05	WB
8716	3628773.07	215761.73	-9.05	WB
8717	3628773.44	215764.86	-9.04	WB
8718	3628773.82	215768.00	-9.03	WB
8719	3628774.15	215771.12	-9.02	WB
8720	3628774.45	215774.25	-9.01	WB
8721	3628774.75	215777.38	-9.00	WB
8722	3628774.86	215778.50	-8.99	WB
8723	3628775.04	215780.39	-8.98	WB
8724	3628775.34	215783.44	-8.97	WB
8725	3628775.62	215786.25	-8.97	WB
8726	3628775.92	215788.98	-8.96	WB
8727	3628776.23	215791.75	-8.95	WB
8728	3628776.51	215794.34	-8.94	WB
8729	3628776.78	215796.94	-8.93	WB
8730	3628776.98	215799.52	-8.92	WB
8731	3628777.14	215802.06	-8.91	WB
8732	3628777.18	215802.68	-8.91	WB
8733	3628777.24	215804.72	-8.90	WB
8734	3628777.22	215807.44	-8.89	WB
8735	3628777.17	215810.14	-8.89	WB
8736	3628777.05	215812.95	-8.88	WB
8737	3628776.92	215815.78	-8.88	WB
8738	3628776.79	215818.64	-8.87	WB
8739	3628776.67	215821.53	-8.87	WB
8740	3628776.56	215824.46	-8.86	WB
8741	3628776.51	215827.37	-8.86	WB
8742	3628776.50	215827.76	-8.85	WB
8743	3628776.46	215830.33	-8.85	WB
8744	3628776.38	215833.39	-8.84	WB
8745	3628776.28	215836.49	-8.84	WB
8746	3628776.17	215839.71	-8.83	WB
8747	3628775.98	215843.10	-8.83	WB
8748	3628775.80	215846.45	-8.82	WB
8749	3628775.55	215850.03	-8.82	WB
8750	3628775.36	215852.62	-8.81	WB
8751	3628775.29	215853.58	-8.80	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
8752	3628775.03	215857.03	-8.80	WB
8753	3628774.72	215860.50	-8.79	WB
8754	3628774.42	215864.00	-8.78	WB
8755	3628774.13	215867.21	-8.77	WB
8756	3628773.86	215870.33	-8.76	WB
8757	3628773.60	215873.43	-8.75	WB
8758	3628773.34	215876.30	-8.74	WB
8759	3628773.21	215877.74	-8.73	WB
8760	3628773.08	215879.23	-8.72	WB
8761	3628772.83	215882.12	-8.71	WB
8762	3628772.60	215884.92	-8.70	WB
8763	3628772.35	215887.85	-8.69	WB
8764	3628772.14	215890.78	-8.67	WB
8765	3628771.92	215893.67	-8.66	WB
8766	3628771.73	215896.72	-8.65	WB
8767	3628771.55	215899.73	-8.64	WB
8768	3628771.40	215902.72	-8.63	WB
8769	3628771.38	215903.14	-8.62	WB
8770	3628771.28	215905.80	-8.61	WB
8771	3628771.16	215908.93	-8.60	WB
8772	3628771.06	215912.11	-8.59	WB
8773	3628770.96	215915.34	-8.58	WB
8774	3628770.92	215918.59	-8.57	WB
8775	3628770.93	215921.89	-8.56	WB
8776	3628770.96	215925.17	-8.56	WB
8777	3628771.15	215928.31	-8.55	WB
8778	3628771.18	215928.73	-8.54	WB
8779	3628771.35	215931.41	-8.53	WB
8780	3628771.64	215934.42	-8.53	WB
8781	3628771.97	215937.24	-8.52	WB
8782	3628772.31	215940.09	-8.51	WB
8783	3628772.66	215942.92	-8.51	WB
8784	3628772.97	215945.69	-8.50	WB
8785	3628773.21	215948.66	-8.49	WB
8786	3628773.40	215951.63	-8.49	WB
8787	3628773.51	215953.50	-8.48	WB
8788	3628773.56	215954.62	-8.48	WB
8789	3628773.70	215957.76	-8.47	WB
8790	3628773.83	215960.84	-8.47	WB
8791	3628774.00	215963.90	-8.46	WB
8792	3628774.17	215966.92	-8.45	WB
8793	3628774.37	215969.96	-8.45	WB
8794	3628774.56	215972.93	-8.44	WB
8795	3628774.76	215976.00	-8.44	WB
8796	3628774.94	215978.66	-8.43	WB
8797	3628774.97	215979.07	-8.42	WB
8798	3628775.18	215982.19	-8.42	WB
8799	3628775.41	215985.33	-8.41	WB
8800	3628775.67	215988.49	-8.40	WB
8801	3628775.93	215991.64	-8.39	WB
8802	3628776.23	215994.77	-8.39	WB
8803	3628776.53	215997.77	-8.38	WB
8804	3628776.83	216000.71	-8.37	WB
8805	3628777.10	216003.23	-8.36	WB
8806	3628777.15	216003.61	-8.35	WB
8807	3628777.45	216006.43	-8.35	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
8808	3628777.67	216009.11	-8.34	WB
8809	3628777.88	216011.81	-8.33	WB
8810	3628778.01	216014.54	-8.32	WB
8811	3628778.07	216017.25	-8.31	WB
8812	3628778.12	216019.99	-8.30	WB
8813	3628778.14	216022.80	-8.30	WB
8814	3628778.15	216025.61	-8.29	WB
8815	3628778.13	216027.77	-8.28	WB
8816	3628778.11	216028.52	-8.27	WB
8817	3628778.04	216031.43	-8.26	WB
8818	3628777.98	216034.36	-8.26	WB
8819	3628777.88	216037.41	-8.25	WB
8820	3628777.77	216040.39	-8.24	WB
8821	3628777.53	216043.50	-8.24	WB
8822	3628777.24	216046.68	-8.23	WB
8823	3628776.92	216049.72	-8.22	WB
8824	3628776.59	216052.52	-8.22	WB
8825	3628776.54	216052.94	-8.21	WB
8826	3628776.16	216056.00	-8.21	WB
8827	3628775.78	216059.00	-8.20	WB
8828	3628775.38	216062.11	-8.20	WB
8829	3628775.00	216065.08	-8.19	WB
8830	3628774.60	216068.07	-8.19	WB
8831	3628774.19	216071.10	-8.18	WB
8832	3628773.80	216074.15	-8.18	WB
8833	3628773.40	216077.31	-8.18	WB
8834	3628773.30	216078.06	-8.17	WB
8835	3628773.01	216080.50	-8.17	WB
8836	3628772.64	216083.79	-8.16	WB
8837	3628772.27	216087.09	-8.16	WB
8838	3628772.02	216090.49	-8.16	WB
8839	3628771.77	216093.87	-8.15	WB
8840	3628771.63	216097.23	-8.15	WB
8841	3628771.55	216100.53	-8.14	WB
8842	3628771.50	216103.41	-8.14	WB
8843	3628771.51	216103.79	-8.14	WB
8844	3628771.64	216106.90	-8.13	WB
8845	3628771.78	216110.00	-8.13	WB
8846	3628771.97	216113.10	-8.12	WB
8847	3628772.20	216116.21	-8.12	WB
8848	3628772.41	216119.24	-8.11	WB
8849	3628772.63	216122.39	-8.11	WB
8850	3628772.85	216125.59	-8.10	WB
8851	3628773.07	216128.75	-8.09	WB
8852	3628773.30	216131.99	-8.09	WB
8853	3628773.59	216135.13	-8.08	WB
8854	3628773.95	216138.16	-8.08	WB
8855	3628774.34	216141.27	-8.07	WB
8856	3628774.70	216144.32	-8.06	WB
8857	3628775.05	216147.44	-8.05	WB
8858	3628775.39	216150.57	-8.05	WB
8859	3628775.66	216153.30	-8.04	WB
8860	3628775.70	216153.72	-8.03	WB
8861	3628776.03	216156.86	-8.02	WB
8862	3628776.38	216159.83	-8.01	WB
8863	3628776.75	216162.79	-8.00	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
8864	3628777.14	216165.69	-7.99	WB
8865	3628777.55	216168.49	-7.98	WB
8866	3628777.94	216171.30	-7.97	WB
8867	3628778.17	216174.18	-7.96	WB
8868	3628778.39	216177.13	-7.95	WB
8869	3628778.44	216177.83	-7.94	WB
8870	3628778.45	216180.03	-7.94	WB
8871	3628778.41	216182.96	-7.93	WB
8872	3628778.35	216185.92	-7.92	WB
8873	3628778.20	216188.78	-7.91	WB
8874	3628778.06	216191.68	-7.90	WB
8875	3628777.85	216194.51	-7.89	WB
8876	3628777.63	216197.31	-7.88	WB
8877	3628777.40	216200.08	-7.88	WB
8878	3628777.17	216202.42	-7.87	WB
8879	3628777.13	216202.74	-7.86	WB
8880	3628776.86	216205.41	-7.85	WB
8881	3628776.51	216208.10	-7.85	WB
8882	3628776.13	216210.81	-7.84	WB
8883	3628775.71	216213.60	-7.84	WB
8884	3628775.23	216216.54	-7.83	WB
8885	3628774.74	216219.52	-7.82	WB
8886	3628774.24	216222.66	-7.82	WB
8887	3628773.72	216225.92	-7.81	WB
8888	3628773.44	216227.63	-7.81	WB
8889	3628773.19	216229.38	-7.80	WB
8890	3628772.70	216232.82	-7.80	WB
8891	3628772.18	216236.39	-7.79	WB
8892	3628771.73	216240.08	-7.78	WB
8893	3628771.29	216243.74	-7.78	WB
8894	3628770.91	216247.42	-7.77	WB
8895	3628770.59	216251.09	-7.76	WB
8896	3628770.39	216253.45	-7.75	WB
8897	3628770.29	216254.77	-7.74	WB
8898	3628770.16	216258.30	-7.74	WB
8899	3628770.03	216261.83	-7.73	WB
8900	3628770.01	216265.18	-7.71	WB
8901	3628770.07	216268.36	-7.70	WB
8902	3628770.16	216271.58	-7.69	WB
8903	3628770.37	216274.49	-7.68	WB
8904	3628770.59	216277.33	-7.67	WB
8905	3628770.69	216278.48	-7.65	WB
8906	3628770.88	216280.14	-7.64	WB
8907	3628771.20	216282.85	-7.63	WB
8908	3628771.49	216285.57	-7.61	WB
8909	3628771.75	216288.39	-7.60	WB
8910	3628772.00	216291.23	-7.59	WB
8911	3628772.24	216294.20	-7.57	WB
8912	3628772.47	216297.13	-7.56	WB
8913	3628772.68	216300.01	-7.55	WB
8914	3628772.90	216302.99	-7.53	WB
8915	3628773.11	216305.92	-7.52	WB
8916	3628773.28	216308.74	-7.51	WB
8917	3628773.43	216311.57	-7.50	WB
8918	3628773.60	216314.41	-7.49	WB
8919	3628773.76	216317.11	-7.48	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
8920	3628773.93	216319.86	-7.47	WB
8921	3628774.02	216322.61	-7.46	WB
8922	3628774.11	216325.28	-7.45	WB
8923	3628774.16	216327.78	-7.44	WB
8924	3628774.16	216328.12	-7.43	WB
8925	3628774.17	216330.95	-7.43	WB
8926	3628774.17	216333.74	-7.42	WB
8927	3628774.09	216336.83	-7.42	WB
8928	3628774.00	216339.88	-7.41	WB
8929	3628773.84	216343.10	-7.41	WB
8930	3628773.64	216346.42	-7.40	WB
8931	3628773.44	216349.76	-7.40	WB
8932	3628773.21	216353.17	-7.39	WB
8933	3628773.00	216356.57	-7.39	WB
8934	3628772.83	216359.96	-7.38	WB
8935	3628772.69	216363.29	-7.38	WB
8936	3628772.56	216366.61	-7.37	WB
8937	3628772.40	216370.03	-7.36	WB
8938	3628772.24	216373.36	-7.36	WB
8939	3628772.05	216376.83	-7.35	WB
8940	3628772.01	216377.62	-7.34	WB
8941	3628771.86	216380.09	-7.33	WB
8942	3628771.66	216383.34	-7.32	WB
8943	3628771.42	216386.70	-7.31	WB
8944	3628771.18	216390.03	-7.30	WB
8945	3628770.86	216393.36	-7.29	WB
8946	3628770.52	216396.64	-7.27	WB
8947	3628770.19	216399.87	-7.26	WB
8948	3628769.89	216402.64	-7.25	WB
8949	3628769.85	216403.02	-7.23	WB
8950	3628769.51	216406.17	-7.22	WB
8951	3628769.17	216409.21	-7.20	WB
8952	3628768.82	216412.24	-7.19	WB
8953	3628768.48	216415.20	-7.18	WB
8954	3628768.13	216418.14	-7.16	WB
8955	3628767.78	216421.10	-7.15	WB
8956	3628767.52	216424.13	-7.13	WB
8957	3628767.27	216427.04	-7.12	WB
8958	3628767.16	216428.19	-7.11	WB
8959	3628767.08	216429.96	-7.10	WB
8960	3628766.95	216432.95	-7.09	WB
8961	3628766.85	216435.85	-7.08	WB
8962	3628766.89	216438.86	-7.07	WB
8963	3628766.93	216441.83	-7.06	WB
8964	3628767.10	216444.76	-7.05	WB
8965	3628767.34	216447.78	-7.05	WB
8966	3628767.62	216450.81	-7.04	WB
8967	3628768.04	216453.93	-7.03	WB
8968	3628768.08	216454.30	-7.03	WB
8969	3628768.45	216457.06	-7.03	WB
8970	3628769.00	216460.24	-7.02	WB
8971	3628769.59	216463.38	-7.02	WB
8972	3628770.24	216466.48	-7.02	WB
8973	3628771.03	216469.62	-7.01	WB
8974	3628771.82	216472.68	-7.01	WB
8975	3628772.71	216475.98	-7.01	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
8976	3628773.60	216479.27	-7.00	WB
8977	3628773.72	216479.71	-7.00	WB
8978	3628774.48	216482.53	-7.00	WB
8979	3628775.41	216486.02	-6.99	WB
8980	3628776.32	216489.32	-6.99	WB
8981	3628777.22	216492.49	-6.98	WB
8982	3628778.15	216495.66	-6.98	WB
8983	3628779.07	216498.51	-6.97	WB
8984	3628779.99	216501.15	-6.96	WB
8985	3628780.83	216503.47	-6.95	WB
8986	3628780.94	216503.78	-6.95	WB
8987	3628781.71	216506.03	-6.94	WB
8988	3628782.48	216508.31	-6.93	WB
8989	3628783.11	216510.49	-6.92	WB
8990	3628783.63	216512.59	-6.91	WB
8991	3628784.13	216514.70	-6.91	WB
8992	3628784.44	216516.74	-6.90	WB
8993	3628784.74	216518.80	-6.89	WB
8994	3628784.89	216520.84	-6.88	WB
8995	3628784.94	216522.91	-6.88	WB
8996	3628784.94	216524.94	-6.87	WB
8997	3628784.76	216526.83	-6.87	WB
8998	3628784.74	216527.08	-6.86	WB
8999	3628784.52	216529.27	-6.86	WB
9000	3628784.14	216531.51	-6.86	WB
9001	3628783.69	216533.83	-6.85	WB
9002	3628783.18	216536.14	-6.85	WB
9003	3628782.51	216538.58	-6.85	WB
9004	3628781.81	216541.08	-6.85	WB
9005	3628780.96	216543.71	-6.85	WB
9006	3628780.03	216546.49	-6.85	WB
9007	3628779.03	216549.34	-6.85	WB
9008	3628778.05	216551.99	-6.85	WB
9009	3628777.91	216552.36	-6.85	WB
9010	3628776.76	216555.47	-6.85	WB
9011	3628775.45	216558.90	-6.85	WB
9012	3628774.12	216562.35	-6.85	WB
9013	3628772.77	216565.92	-6.85	WB
9014	3628771.37	216569.74	-6.85	WB
9015	3628769.98	216573.56	-6.84	WB
9016	3628768.84	216577.46	-6.84	WB
9017	3628768.71	216577.92	-6.83	WB
9018	3628767.70	216581.38	-6.83	WB
9019	3628766.75	216585.23	-6.82	WB
9020	3628765.98	216588.94	-6.81	WB
9021	3628765.24	216592.61	-6.80	WB
9022	3628764.75	216596.06	-6.79	WB
9023	3628764.27	216599.54	-6.77	WB
9024	3628764.00	216602.68	-6.76	WB
9025	3628763.95	216603.52	-6.74	WB
9026	3628763.83	216605.77	-6.73	WB
9027	3628763.70	216608.86	-6.71	WB
9028	3628763.74	216611.67	-6.70	WB
9029	3628763.77	216614.59	-6.68	WB
9030	3628763.91	216617.39	-6.67	WB
9031	3628764.09	216620.09	-6.65	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
9032	3628764.31	216622.84	-6.63	WB
9033	3628764.63	216625.46	-6.62	WB
9034	3628764.95	216628.06	-6.60	WB
9035	3628765.10	216629.04	-6.59	WB
9036	3628765.39	216630.60	-6.58	WB
9037	3628765.86	216633.09	-6.57	WB
9038	3628766.39	216635.51	-6.55	WB
9039	3628767.02	216637.93	-6.54	WB
9040	3628767.66	216640.35	-6.54	WB
9041	3628768.33	216642.87	-6.53	WB
9042	3628769.01	216645.40	-6.52	WB
9043	3628769.70	216647.99	-6.52	WB
9044	3628770.41	216650.61	-6.51	WB
9045	3628771.15	216653.25	-6.51	WB
9046	3628771.43	216654.22	-6.50	WB
9047	3628771.93	216655.90	-6.50	WB
9048	3628772.74	216658.58	-6.50	WB
9049	3628773.52	216661.43	-6.50	WB
9050	3628774.24	216664.26	-6.50	WB
9051	3628774.95	216667.21	-6.50	WB
9052	3628775.52	216670.42	-6.50	WB
9053	3628776.08	216673.60	-6.49	WB
9054	3628776.56	216676.97	-6.49	WB
9055	3628776.78	216678.69	-6.49	WB
9056	3628777.00	216680.36	-6.49	WB
9057	3628777.42	216683.78	-6.48	WB
9058	3628777.74	216687.16	-6.48	WB
9059	3628778.06	216690.53	-6.47	WB
9060	3628778.30	216693.76	-6.47	WB
9061	3628778.51	216697.01	-6.46	WB
9062	3628778.67	216700.13	-6.45	WB
9063	3628778.71	216702.88	-6.44	WB
9064	3628778.72	216703.25	-6.43	WB
9065	3628778.76	216706.34	-6.42	WB
9066	3628778.68	216709.29	-6.41	WB
9067	3628778.58	216712.23	-6.40	WB
9068	3628778.45	216715.14	-6.38	WB
9069	3628778.29	216717.95	-6.37	WB
9070	3628778.13	216720.79	-6.35	WB
9071	3628777.97	216723.52	-6.34	WB
9072	3628777.82	216726.24	-6.32	WB
9073	3628777.74	216727.63	-6.31	WB
9074	3628777.66	216729.08	-6.29	WB
9075	3628777.51	216731.72	-6.28	WB
9076	3628777.36	216734.35	-6.26	WB
9077	3628777.21	216737.05	-6.25	WB
9078	3628777.06	216739.66	-6.23	WB
9079	3628776.86	216742.41	-6.22	WB
9080	3628776.63	216745.11	-6.20	WB
9081	3628776.40	216747.78	-6.19	WB
9082	3628776.16	216750.61	-6.17	WB
9083	3628775.98	216752.71	-6.16	WB
9084	3628775.91	216753.42	-6.15	WB
9085	3628775.66	216756.27	-6.14	WB
9086	3628775.39	216759.14	-6.13	WB
9087	3628775.12	216762.07	-6.12	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
9088	3628774.91	216765.04	-6.11	WB
9089	3628774.71	216768.01	-6.10	WB
9090	3628774.59	216771.01	-6.09	WB
9091	3628774.50	216774.02	-6.08	WB
9092	3628774.45	216777.05	-6.07	WB
9093	3628774.46	216778.22	-6.06	WB
9094	3628774.48	216780.17	-6.06	WB
9095	3628774.51	216783.28	-6.05	WB
9096	3628774.59	216786.54	-6.04	WB
9097	3628774.67	216789.71	-6.03	WB
9098	3628774.75	216792.93	-6.02	WB
9099	3628774.81	216796.30	-6.01	WB
9100	3628774.87	216799.56	-6.00	WB
9101	3628774.88	216802.92	-5.99	WB
9102	3628774.88	216803.31	-5.98	WB
9103	3628774.89	216806.24	-5.97	WB
9104	3628774.86	216809.53	-5.96	WB
9105	3628774.78	216812.84	-5.95	WB
9106	3628774.69	216816.11	-5.93	WB
9107	3628774.55	216819.38	-5.92	WB
9108	3628774.40	216822.65	-5.90	WB
9109	3628774.21	216825.93	-5.88	WB
9110	3628774.08	216827.95	-5.86	WB
9111	3628774.00	216829.16	-5.84	WB
9112	3628773.78	216832.36	-5.82	WB
9113	3628773.54	216835.54	-5.79	WB
9114	3628773.30	216838.73	-5.77	WB
9115	3628773.09	216841.84	-5.75	WB
9116	3628772.91	216844.91	-5.73	WB
9117	3628772.73	216848.00	-5.70	WB
9118	3628772.59	216851.06	-5.68	WB
9119	3628772.49	216852.96	-5.65	WB
9120	3628772.44	216854.04	-5.63	WB
9121	3628772.34	216857.03	-5.60	WB
9122	3628772.25	216860.05	-5.58	WB
9123	3628772.18	216862.92	-5.56	WB
9124	3628772.13	216865.91	-5.53	WB
9125	3628772.08	216868.85	-5.51	WB
9126	3628772.09	216871.69	-5.48	WB
9127	3628772.12	216874.59	-5.46	WB
9128	3628772.17	216877.44	-5.44	WB
9129	3628772.20	216878.45	-5.41	WB
9130	3628772.26	216880.25	-5.39	WB
9131	3628772.35	216883.07	-5.37	WB
9132	3628772.45	216885.87	-5.35	WB
9133	3628772.57	216888.64	-5.33	WB
9134	3628772.71	216891.47	-5.31	WB
9135	3628772.89	216894.28	-5.29	WB
9136	3628773.07	216897.05	-5.27	WB
9137	3628773.21	216900.00	-5.26	WB
9138	3628773.35	216902.87	-5.25	WB
9139	3628773.37	216903.26	-5.23	WB
9140	3628773.50	216905.76	-5.22	WB
9141	3628773.66	216908.84	-5.20	WB
9142	3628773.81	216911.80	-5.19	WB
9143	3628773.90	216914.86	-5.17	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
9144	3628774.00	216918.06	-5.16	WB
9145	3628774.07	216921.21	-5.14	WB
9146	3628774.12	216924.45	-5.12	WB
9147	3628774.15	216927.77	-5.10	WB
9148	3628774.15	216928.17	-5.09	WB
9149	3628774.13	216931.07	-5.06	WB
9150	3628774.11	216934.41	-5.04	WB
9151	3628774.07	216937.78	-5.02	WB
9152	3628774.01	216941.06	-4.99	WB
9153	3628773.96	216944.40	-4.96	WB
9154	3628773.88	216947.75	-4.93	WB
9155	3628773.81	216950.98	-4.90	WB
9156	3628773.75	216953.04	-4.86	WB
9157	3628773.71	216954.26	-4.83	WB
9158	3628773.60	216957.58	-4.79	WB
9159	3628773.50	216960.73	-4.75	WB
9160	3628773.42	216963.92	-4.71	WB
9161	3628773.35	216967.14	-4.67	WB
9162	3628773.26	216970.26	-4.62	WB
9163	3628773.16	216973.50	-4.57	WB
9164	3628773.05	216976.61	-4.52	WB
9165	3628773.00	216977.79	-4.47	WB
9166	3628772.91	216979.78	-4.41	WB
9167	3628772.76	216983.02	-4.36	WB
9168	3628772.54	216986.16	-4.30	WB
9169	3628772.29	216989.42	-4.25	WB
9170	3628772.04	216992.59	-4.19	WB
9171	3628771.79	216995.69	-4.14	WB
9172	3628771.54	216998.84	-4.08	WB
9173	3628771.36	217001.87	-4.02	WB
9174	3628771.29	217002.95	-3.96	WB
9175	3628771.18	217004.88	-3.90	WB
9176	3628771.06	217007.78	-3.84	WB
9177	3628770.99	217010.59	-3.78	WB
9178	3628770.92	217013.36	-3.71	WB
9179	3628770.85	217016.02	-3.65	WB
9180	3628770.79	217018.68	-3.59	WB
9181	3628770.74	217021.24	-3.53	WB
9182	3628770.69	217023.77	-3.47	WB
9183	3628770.62	217026.31	-3.42	WB
9184	3628770.54	217027.87	-3.36	WB
9185	3628770.49	217028.80	-3.31	WB
9186	3628770.36	217031.35	-3.26	WB
9187	3628770.26	217033.73	-3.21	WB
9188	3628770.19	217036.11	-3.17	WB
9189	3628770.15	217038.45	-3.13	WB
9190	3628770.19	217040.69	-3.09	WB
9191	3628770.23	217042.99	-3.06	WB
9192	3628770.31	217045.14	-3.01	WB
9193	3628770.39	217047.25	-2.97	WB
9194	3628770.50	217049.53	-2.93	WB
9195	3628770.63	217051.77	-2.90	WB
9196	3628770.73	217053.52	-2.88	WB
9197	3628770.76	217054.12	-2.88	WB
9198	3628770.96	217056.80	-2.88	WB
9199	3628771.14	217059.48	-2.90	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
9200	3628771.37	217062.45	-2.90	WB
9201	3628771.63	217065.52	-2.94	WB
9202	3628771.91	217068.60	-2.97	WB
9203	3628772.35	217071.85	-2.94	WB
9204	3628772.79	217074.97	-2.98	WB
9205	3628773.30	217077.99	-3.00	WB
9206	3628773.69	217080.11	-3.01	WB
9207	3628773.84	217080.88	-3.10	WB
9208	3628774.40	217083.57	-3.20	WB
9209	3628774.95	217085.88	-3.30	WB
9210	3628775.55	217088.06	-3.41	WB
9211	3628776.10	217089.78	-3.54	WB
9212	3628776.66	217091.41	-3.68	WB
9213	3628777.21	217092.95	-3.79	WB
9214	3628777.63	217094.26	-3.91	WB
9215	3628778.03	217095.64	-4.01	WB
9216	3628778.21	217096.82	-4.09	WB
9217	3628778.32	217097.99	-4.17	WB
9218	3628778.39	217099.13	-4.24	WB
9219	3628778.40	217100.11	-4.31	WB
9220	3628778.41	217101.11	-4.40	WB
9221	3628778.37	217101.35	-4.50	WB
9222	3628778.21	217102.08	-4.60	WB
9223	3628777.97	217103.02	-4.69	WB
9224	3628777.57	217103.99	-4.79	WB
9225	3628777.02	217104.90	-4.89	WB
9226	3628776.46	217105.83	-4.99	WB
9227	3628775.72	217106.74	-5.08	WB
9228	3628774.98	217107.64	-5.18	WB
9229	3628774.17	217108.55	-5.27	WB
9230	3628773.29	217109.47	-5.34	WB
9231	3628772.39	217110.42	-5.42	WB
9232	3628771.39	217111.46	-5.50	WB
9233	3628770.38	217112.51	-5.56	WB
9234	3628769.29	217113.65	-5.58	WB
9235	3628768.14	217114.85	-5.60	WB
9236	3628766.93	217116.08	-5.63	WB
9237	3628765.66	217117.30	-5.64	WB
9238	3628764.39	217118.53	-5.64	WB
9239	3628763.20	217119.70	-5.64	WB
9240	3628762.09	217120.79	-5.64	WB
9241	3628761.01	217121.90	-5.66	WB
9242	3628760.06	217122.97	-5.67	WB
9243	3628759.12	217124.02	-5.70	WB
9244	3628758.16	217125.19	-5.72	WB
9245	3628757.24	217126.31	-5.71	WB
9246	3628756.66	217127.04	-5.70	WB
9247	3628756.32	217127.48	-5.67	WB
9248	3628755.40	217128.70	-5.64	WB
9249	3628754.50	217129.89	-5.62	WB
9250	3628753.61	217131.11	-5.59	WB
9251	3628752.73	217132.33	-5.56	WB
9252	3628751.89	217133.53	-5.53	WB
9253	3628751.06	217134.77	-5.50	WB
9254	3628750.25	217135.99	-5.46	WB
9255	3628749.56	217137.19	-5.42	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
9256	3628748.87	217138.43	-5.38	WB
9257	3628748.22	217139.67	-5.33	WB
9258	3628747.63	217140.89	-5.28	WB
9259	3628747.05	217142.12	-5.23	WB
9260	3628746.58	217143.31	-5.18	WB
9261	3628746.14	217144.45	-5.13	WB
9262	3628745.80	217145.54	-5.07	WB
9263	3628745.51	217146.61	-5.01	WB
9264	3628745.27	217147.65	-4.95	WB
9265	3628745.10	217148.70	-4.88	WB
9266	3628744.95	217149.73	-4.81	WB
9267	3628744.89	217150.91	-4.73	WB
9268	3628744.87	217152.19	-4.65	WB
9269	3628744.89	217153.51	-4.57	WB
9270	3628744.98	217154.87	-4.49	WB
9271	3628745.06	217156.02	-4.41	WB
9272	3628745.07	217156.18	-4.34	WB
9273	3628745.31	217157.12	-4.26	WB
9274	3628745.56	217157.97	-4.19	WB
9275	3628745.86	217158.81	-4.13	WB
9276	3628746.27	217159.68	-4.06	WB
9277	3628746.68	217160.57	-4.00	WB
9278	3628747.42	217161.72	-3.95	WB
9279	3628748.16	217162.82	-3.90	WB
9280	3628749.04	217163.87	-3.85	WB
9281	3628750.04	217164.81	-3.81	WB
9282	3628751.03	217165.69	-3.77	WB
9283	3628752.06	217166.45	-3.73	WB
9284	3628753.09	217167.20	-3.70	WB
9285	3628754.15	217167.94	-3.67	WB
9286	3628755.26	217168.69	-3.64	WB
9287	3628756.33	217169.45	-3.62	WB
9288	3628757.35	217170.26	-3.59	WB
9289	3628758.35	217171.03	-3.57	WB
9290	3628759.34	217171.76	-3.55	WB
9291	3628760.33	217172.47	-3.54	WB
9292	3628761.28	217173.22	-3.53	WB
9293	3628762.18	217174.19	-3.51	WB
9294	3628763.09	217175.19	-3.49	WB
9295	3628763.91	217176.23	-3.45	WB
9296	3628764.73	217177.28	-3.41	WB
9297	3628765.56	217178.33	-3.35	WB
9298	3628766.35	217179.35	-3.28	WB
9299	3628767.17	217180.40	-3.23	WB
9300	3628767.86	217181.37	-3.30	WB
9301	3628768.55	217182.35	-3.10	WB
9302	3628769.21	217183.23	-3.00	WB
9303	3628769.83	217183.99	-3.00	WB
9304	3628770.45	217184.78	-2.90	WB
9305	3628770.87	217185.50	-2.90	WB
9306	3628771.27	217186.25	-2.80	WB
9307	3628771.59	217186.97	-2.80	WB
9308	3628278.03	215680.01	-9.01	WB
9309	3628278.04	215682.77	-9.00	WB
9310	3628278.04	215684.86	-9.00	WB
9311	3628278.04	215685.52	-8.99	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
9312	3628278.08	215688.25	-8.99	WB
9313	3628278.13	215690.96	-8.98	WB
9314	3628278.20	215693.62	-8.97	WB
9315	3628278.33	215696.30	-8.97	WB
9316	3628278.45	215698.98	-8.96	WB
9317	3628278.62	215701.63	-8.95	WB
9318	3628278.81	215704.31	-8.95	WB
9319	3628279.00	215707.03	-8.94	WB
9320	3628279.21	215709.74	-8.94	WB
9321	3628279.43	215712.43	-8.93	WB
9322	3628279.63	215715.20	-8.93	WB
9323	3628279.85	215717.97	-8.92	WB
9324	3628280.02	215720.77	-8.92	WB
9325	3628280.09	215723.63	-8.91	WB
9326	3628280.16	215726.50	-8.90	WB
9327	3628280.09	215729.31	-8.90	WB
9328	3628279.97	215732.14	-8.90	WB
9329	3628279.87	215734.23	-8.89	WB
9330	3628279.82	215734.93	-8.89	WB
9331	3628279.62	215737.68	-8.88	WB
9332	3628279.41	215740.52	-8.88	WB
9333	3628279.18	215743.39	-8.88	WB
9334	3628278.95	215746.23	-8.87	WB
9335	3628278.75	215749.18	-8.87	WB
9336	3628278.59	215751.98	-8.87	WB
9337	3628278.44	215754.84	-8.86	WB
9338	3628278.34	215757.59	-8.86	WB
9339	3628278.29	215759.27	-8.86	WB
9340	3628278.25	215760.30	-8.85	WB
9341	3628278.13	215763.12	-8.85	WB
9342	3628278.01	215765.92	-8.85	WB
9343	3628277.87	215768.72	-8.84	WB
9344	3628277.64	215771.85	-8.84	WB
9345	3628277.40	215774.95	-8.84	WB
9346	3628277.09	215778.15	-8.83	WB
9347	3628276.72	215781.49	-8.83	WB
9348	3628276.44	215784.00	-8.82	WB
9349	3628276.32	215784.93	-8.82	WB
9350	3628275.88	215788.33	-8.81	WB
9351	3628275.44	215791.77	-8.81	WB
9352	3628275.03	215795.17	-8.80	WB
9353	3628274.65	215798.44	-8.80	WB
9354	3628274.27	215801.76	-8.79	WB
9355	3628273.89	215804.89	-8.79	WB
9356	3628273.51	215808.01	-8.78	WB
9357	3628273.40	215808.86	-8.77	WB
9358	3628273.08	215811.05	-8.77	WB
9359	3628272.63	215814.09	-8.76	WB
9360	3628272.17	215817.11	-8.75	WB
9361	3628271.72	215820.10	-8.75	WB
9362	3628271.25	215823.15	-8.74	WB
9363	3628270.85	215826.11	-8.73	WB
9364	3628270.45	215829.15	-8.73	WB
9365	3628270.13	215832.09	-8.72	WB
9366	3628269.93	215834.59	-8.72	WB
9367	3628269.90	215834.94	-8.71	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
9368	3628269.68	215837.80	-8.71	WB
9369	3628269.59	215840.69	-8.70	WB
9370	3628269.50	215843.50	-8.70	WB
9371	3628269.42	215846.47	-8.69	WB
9372	3628269.34	215849.49	-8.69	WB
9373	3628269.27	215852.45	-8.68	WB
9374	3628269.26	215855.78	-8.68	WB
9375	3628269.25	215858.96	-8.67	WB
9376	3628269.25	215859.78	-8.67	WB
9377	3628269.26	215862.37	-8.67	WB
9378	3628269.27	215865.74	-8.66	WB
9379	3628269.30	215869.05	-8.66	WB
9380	3628269.35	215872.49	-8.65	WB
9381	3628269.40	215875.88	-8.65	WB
9382	3628269.46	215879.19	-8.65	WB
9383	3628269.52	215882.55	-8.64	WB
9384	3628269.56	215884.66	-8.64	WB
9385	3628269.55	215885.90	-8.63	WB
9386	3628269.51	215889.20	-8.63	WB
9387	3628269.46	215892.50	-8.62	WB
9388	3628269.43	215895.77	-8.62	WB
9389	3628269.40	215898.92	-8.61	WB
9390	3628269.35	215902.12	-8.61	WB
9391	3628269.27	215905.33	-8.61	WB
9392	3628269.19	215908.46	-8.60	WB
9393	3628269.16	215909.65	-8.60	WB
9394	3628269.12	215911.61	-8.59	WB
9395	3628269.06	215914.58	-8.59	WB
9396	3628269.09	215917.45	-8.58	WB
9397	3628269.21	215920.29	-8.58	WB
9398	3628269.34	215923.08	-8.57	WB
9399	3628269.55	215925.81	-8.57	WB
9400	3628269.75	215928.54	-8.56	WB
9401	3628270.02	215931.34	-8.56	WB
9402	3628270.35	215934.17	-8.56	WB
9403	3628270.48	215935.27	-8.55	WB
9404	3628270.68	215936.99	-8.55	WB
9405	3628271.03	215940.01	-8.54	WB
9406	3628271.39	215943.02	-8.54	WB
9407	3628271.75	215946.18	-8.54	WB
9408	3628272.12	215949.34	-8.53	WB
9409	3628272.48	215952.53	-8.53	WB
9410	3628272.79	215955.87	-8.52	WB
9411	3628273.09	215959.10	-8.52	WB
9412	3628273.17	215959.93	-8.51	WB
9413	3628273.37	215962.42	-8.50	WB
9414	3628273.64	215965.80	-8.50	WB
9415	3628273.87	215969.08	-8.49	WB
9416	3628274.02	215972.44	-8.48	WB
9417	3628274.17	215975.74	-8.48	WB
9418	3628274.24	215978.87	-8.47	WB
9419	3628274.29	215982.07	-8.46	WB
9420	3628274.33	215984.05	-8.45	WB
9421	3628274.32	215985.12	-8.44	WB
9422	3628274.30	215988.09	-8.44	WB
9423	3628274.27	215991.08	-8.43	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
9424	3628274.18	215993.92	-8.42	WB
9425	3628274.07	215996.76	-8.41	WB
9426	3628273.78	216002.31	-8.40	WB
9427	3628273.61	216005.07	-8.39	WB
9428	3628273.41	216007.84	-8.38	WB
9429	3628273.31	216009.24	-8.37	WB
9430	3628273.22	216010.61	-8.37	WB
9431	3628273.02	216013.45	-8.36	WB
9432	3628272.83	216016.36	-8.35	WB
9433	3628272.63	216019.18	-8.34	WB
9434	3628272.42	216022.17	-8.34	WB
9435	3628272.20	216025.19	-8.33	WB
9436	3628271.99	216028.23	-8.32	WB
9437	3628271.77	216031.40	-8.32	WB
9438	3628271.58	216034.54	-8.31	WB
9439	3628271.43	216037.70	-8.31	WB
9440	3628271.28	216040.95	-8.30	WB
9441	3628271.16	216044.19	-8.30	WB
9442	3628271.04	216047.44	-8.29	WB
9443	3628270.94	216050.69	-8.28	WB
9444	3628270.87	216053.94	-8.28	WB
9445	3628270.80	216057.19	-8.27	WB
9446	3628270.73	216059.64	-8.27	WB
9447	3628270.70	216060.47	-8.26	WB
9448	3628270.59	216063.78	-8.26	WB
9449	3628270.48	216067.03	-8.25	WB
9450	3628270.38	216070.34	-8.24	WB
9451	3628270.28	216073.70	-8.23	WB
9452	3628270.18	216076.92	-8.23	WB
9453	3628270.09	216080.27	-8.22	WB
9454	3628270.01	216083.52	-8.21	WB
9455	3628270.00	216084.68	-8.20	WB
9456	3628269.97	216086.72	-8.19	WB
9457	3628269.92	216090.01	-8.18	WB
9458	3628269.90	216093.21	-8.17	WB
9459	3628269.87	216096.36	-8.16	WB
9460	3628269.86	216099.43	-8.15	WB
9461	3628269.88	216102.53	-8.14	WB
9462	3628269.89	216105.52	-8.13	WB
9463	3628269.92	216108.46	-8.12	WB
9464	3628269.93	216109.61	-8.11	WB
9465	3628269.95	216111.46	-8.10	WB
9466	3628269.96	216114.38	-8.09	WB
9467	3628269.96	216117.31	-8.08	WB
9468	3628269.96	216120.32	-8.07	WB
9469	3628269.97	216123.25	-8.06	WB
9470	3628269.98	216126.28	-8.05	WB
9471	3628270.06	216129.30	-8.04	WB
9472	3628270.16	216132.33	-8.03	WB
9473	3628270.27	216135.11	-8.02	WB
9474	3628270.29	216135.48	-8.01	WB
9475	3628270.49	216138.62	-8.01	WB
9476	3628270.68	216141.75	-8.00	WB
9477	3628270.95	216144.96	-7.99	WB
9478	3628271.24	216148.18	-7.99	WB
9479	3628271.54	216151.40	-7.98	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
9480	3628271.88	216154.78	-7.97	WB
9481	3628272.23	216158.11	-7.97	WB
9482	3628272.46	216160.17	-7.96	WB
9483	3628272.60	216161.37	-7.96	WB
9484	3628273.01	216164.77	-7.95	WB
9485	3628273.42	216168.14	-7.94	WB
9486	3628273.82	216171.40	-7.94	WB
9487	3628274.25	216174.81	-7.93	WB
9488	3628274.61	216178.04	-7.93	WB
9489	3628274.97	216181.29	-7.92	WB
9490	3628275.30	216184.64	-7.91	WB
9491	3628275.34	216185.03	-7.90	WB
9492	3628275.59	216187.81	-7.90	WB
9493	3628275.89	216191.07	-7.89	WB
9494	3628276.16	216194.18	-7.88	WB
9495	3628276.43	216197.25	-7.87	WB
9496	3628276.68	216200.30	-7.86	WB
9497	3628276.91	216203.31	-7.85	WB
9498	3628277.14	216206.26	-7.84	WB
9499	3628277.41	216209.14	-7.84	WB
9500	3628277.48	216209.87	-7.83	WB
9501	3628277.69	216212.06	-7.82	WB
9502	3628277.92	216214.91	-7.81	WB
9503	3628278.12	216217.77	-7.80	WB
9504	3628278.32	216220.67	-7.79	WB
9505	3628278.49	216223.56	-7.78	WB
9506	3628278.65	216226.50	-7.77	WB
9507	3628278.72	216229.54	-7.76	WB
9508	3628278.75	216232.51	-7.75	WB
9509	3628278.76	216234.05	-7.74	WB
9510	3628278.75	216235.61	-7.73	WB
9511	3628278.71	216238.65	-7.72	WB
9512	3628278.66	216241.65	-7.72	WB
9513	3628278.54	216244.78	-7.71	WB
9514	3628278.40	216247.78	-7.70	WB
9515	3628278.24	216250.84	-7.70	WB
9516	3628278.05	216253.93	-7.69	WB
9517	3628277.87	216256.93	-7.68	WB
9518	3628277.75	216259.19	-7.68	WB
9519	3628277.71	216259.90	-7.67	WB
9520	3628277.55	216262.90	-7.67	WB
9521	3628277.39	216265.81	-7.66	WB
9522	3628277.21	216268.78	-7.66	WB
9523	3628277.03	216271.81	-7.66	WB
9524	3628276.80	216274.87	-7.65	WB
9525	3628276.57	216277.96	-7.65	WB
9526	3628276.29	216281.20	-7.64	WB
9527	3628275.98	216284.46	-7.64	WB
9528	3628275.65	216287.81	-7.63	WB
9529	3628275.26	216291.39	-7.63	WB
9530	3628274.87	216294.89	-7.62	WB
9531	3628274.41	216298.64	-7.62	WB
9532	3628273.95	216302.31	-7.61	WB
9533	3628273.52	216305.91	-7.60	WB
9534	3628273.14	216309.64	-7.60	WB
9535	3628272.77	216313.31	-7.59	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
9536	3628272.47	216316.87	-7.58	WB
9537	3628272.20	216320.38	-7.57	WB
9538	3628271.98	216323.87	-7.56	WB
9539	3628271.87	216327.18	-7.55	WB
9540	3628271.75	216330.48	-7.54	WB
9541	3628271.70	216333.60	-7.53	WB
9542	3628271.69	216334.38	-7.52	WB
9543	3628271.66	216336.70	-7.51	WB
9544	3628271.65	216339.74	-7.50	WB
9545	3628271.68	216342.69	-7.49	WB
9546	3628271.70	216345.61	-7.48	WB
9547	3628271.75	216348.58	-7.47	WB
9548	3628271.80	216351.51	-7.46	WB
9549	3628271.87	216354.39	-7.45	WB
9550	3628271.97	216357.42	-7.45	WB
9551	3628272.06	216359.92	-7.44	WB
9552	3628272.08	216360.32	-7.43	WB
9553	3628272.24	216363.30	-7.42	WB
9554	3628272.41	216366.21	-7.42	WB
9555	3628272.64	216369.05	-7.41	WB
9556	3628272.91	216371.93	-7.40	WB
9557	3628273.19	216374.77	-7.40	WB
9558	3628273.50	216377.60	-7.39	WB
9559	3628273.82	216380.51	-7.39	WB
9560	3628274.15	216383.55	-7.38	WB
9561	3628274.32	216385.09	-7.38	WB
9562	3628274.50	216386.67	-7.37	WB
9563	3628274.83	216389.85	-7.37	WB
9564	3628275.13	216393.32	-7.36	WB
9565	3628275.43	216396.77	-7.36	WB
9566	3628275.69	216400.33	-7.35	WB
9567	3628275.95	216403.90	-7.35	WB
9568	3628276.20	216407.46	-7.34	WB
9569	3628276.32	216409.62	-7.34	WB
9570	3628276.40	216411.03	-7.33	WB
9571	3628276.61	216414.48	-7.32	WB
9572	3628276.71	216417.78	-7.31	WB
9573	3628276.79	216421.11	-7.31	WB
9574	3628276.81	216424.31	-7.30	WB
9575	3628276.73	216427.45	-7.29	WB
9576	3628276.63	216430.57	-7.28	WB
9577	3628276.38	216433.47	-7.27	WB
9578	3628276.35	216433.87	-7.26	WB
9579	3628276.11	216436.47	-7.25	WB
9580	3628275.76	216439.37	-7.23	WB
9581	3628275.34	216442.19	-7.22	WB
9582	3628274.90	216445.06	-7.21	WB
9583	3628274.37	216447.89	-7.20	WB
9584	3628273.84	216450.72	-7.19	WB
9585	3628273.28	216453.49	-7.18	WB
9586	3628272.69	216456.28	-7.16	WB
9587	3628272.11	216459.07	-7.15	WB
9588	3628271.59	216461.83	-7.14	WB
9589	3628271.08	216464.58	-7.13	WB
9590	3628270.59	216467.32	-7.12	WB
9591	3628270.08	216470.21	-7.11	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
9592	3628269.61	216472.97	-7.10	WB
9593	3628269.18	216475.81	-7.10	WB
9594	3628268.73	216478.73	-7.09	WB
9595	3628268.33	216481.70	-7.08	WB
9596	3628267.98	216484.33	-7.07	WB
9597	3628267.94	216484.69	-7.07	WB
9598	3628267.57	216487.78	-7.06	WB
9599	3628267.27	216490.99	-7.05	WB
9600	3628266.96	216494.21	-7.05	WB
9601	3628266.70	216497.65	-7.04	WB
9602	3628266.42	216501.19	-7.04	WB
9603	3628266.20	216504.81	-7.03	WB
9604	3628266.05	216508.55	-7.03	WB
9605	3628265.99	216509.95	-7.02	WB
9606	3628265.90	216512.30	-7.01	WB
9607	3628265.89	216516.05	-7.01	WB
9608	3628265.89	216519.86	-7.00	WB
9609	3628265.94	216523.49	-6.99	WB
9610	3628266.06	216527.10	-6.98	WB
9611	3628266.19	216530.74	-6.97	WB
9612	3628266.37	216534.05	-6.96	WB
9613	3628266.44	216535.30	-6.95	WB
9614	3628266.57	216537.46	-6.94	WB
9615	3628266.78	216540.68	-6.93	WB
9616	3628267.00	216543.74	-6.92	WB
9617	3628267.22	216546.90	-6.91	WB
9618	3628267.41	216549.97	-6.89	WB
9619	3628267.60	216553.05	-6.88	WB
9620	3628267.84	216556.06	-6.87	WB
9621	3628268.10	216559.08	-6.85	WB
9622	3628268.16	216559.80	-6.84	WB
9623	3628268.36	216562.13	-6.82	WB
9624	3628268.61	216565.08	-6.81	WB
9625	3628268.87	216568.04	-6.79	WB
9626	3628269.15	216570.98	-6.78	WB
9627	3628269.43	216573.91	-6.76	WB
9628	3628269.72	216576.80	-6.75	WB
9629	3628270.03	216579.71	-6.74	WB
9630	3628270.35	216582.66	-6.73	WB
9631	3628270.55	216584.43	-6.71	WB
9632	3628270.66	216585.43	-6.70	WB
9633	3628270.97	216588.23	-6.69	WB
9634	3628271.31	216591.04	-6.68	WB
9635	3628271.67	216593.72	-6.67	WB
9636	3628272.04	216596.50	-6.67	WB
9637	3628272.37	216599.23	-6.66	WB
9638	3628272.69	216601.93	-6.65	WB
9639	3628272.98	216604.80	-6.65	WB
9640	3628273.24	216607.69	-6.64	WB
9641	3628273.43	216609.88	-6.64	WB
9642	3628273.49	216610.55	-6.63	WB
9643	3628273.69	216613.66	-6.63	WB
9644	3628273.90	216616.78	-6.63	WB
9645	3628274.04	216620.08	-6.62	WB
9646	3628274.13	216623.59	-6.62	WB
9647	3628274.22	216627.08	-6.62	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
9648	3628274.21	216630.77	-6.61	WB
9649	3628274.20	216634.46	-6.61	WB
9650	3628274.13	216638.20	-6.61	WB
9651	3628274.04	216641.96	-6.60	WB
9652	3628273.91	216645.72	-6.59	WB
9653	3628273.70	216649.37	-6.59	WB
9654	3628273.47	216653.10	-6.58	WB
9655	3628273.21	216656.73	-6.57	WB
9656	3628273.01	216659.40	-6.57	WB
9657	3628272.95	216660.30	-6.56	WB
9658	3628272.69	216663.83	-6.55	WB
9659	3628272.43	216667.23	-6.53	WB
9660	3628272.17	216670.63	-6.52	WB
9661	3628271.90	216673.88	-6.51	WB
9662	3628271.63	216677.12	-6.50	WB
9663	3628271.37	216680.30	-6.48	WB
9664	3628271.15	216683.32	-6.47	WB
9665	3628271.09	216684.15	-6.45	WB
9666	3628270.91	216686.44	-6.44	WB
9667	3628270.73	216689.41	-6.42	WB
9668	3628270.56	216692.32	-6.40	WB
9669	3628270.41	216695.34	-6.39	WB
9670	3628270.31	216698.16	-6.37	WB
9671	3628270.22	216700.98	-6.36	WB
9672	3628270.20	216703.82	-6.34	WB
9673	3628270.19	216706.56	-6.32	WB
9674	3628270.20	216709.33	-6.31	WB
9675	3628270.23	216712.03	-6.29	WB
9676	3628270.27	216714.72	-6.28	WB
9677	3628270.34	216717.48	-6.27	WB
9678	3628270.40	216720.22	-6.26	WB
9679	3628270.45	216723.00	-6.24	WB
9680	3628270.48	216725.84	-6.23	WB
9681	3628270.49	216728.73	-6.22	WB
9682	3628270.48	216731.74	-6.22	WB
9683	3628270.47	216734.77	-6.21	WB
9684	3628270.55	216737.86	-6.20	WB
9685	3628270.66	216740.95	-6.19	WB
9686	3628270.81	216744.01	-6.19	WB
9687	3628271.07	216747.10	-6.18	WB
9688	3628271.34	216750.18	-6.18	WB
9689	3628271.69	216753.32	-6.18	WB
9690	3628272.03	216756.33	-6.17	WB
9691	3628272.41	216759.44	-6.17	WB
9692	3628272.51	216760.25	-6.16	WB
9693	3628272.80	216762.64	-6.16	WB
9694	3628273.19	216765.75	-6.16	WB
9695	3628273.57	216769.10	-6.15	WB
9696	3628273.94	216772.44	-6.15	WB
9697	3628274.33	216775.80	-6.14	WB
9698	3628274.73	216779.25	-6.13	WB
9699	3628275.13	216782.64	-6.13	WB
9700	3628275.40	216784.79	-6.12	WB
9701	3628275.56	216786.06	-6.11	WB
9702	3628275.99	216789.45	-6.09	WB
9703	3628276.41	216792.81	-6.08	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
9704	3628276.82	216796.14	-6.07	WB
9705	3628277.24	216799.51	-6.06	WB
9706	3628277.59	216802.78	-6.04	WB
9707	3628277.94	216806.10	-6.03	WB
9708	3628278.14	216809.04	-6.01	WB
9709	3628278.16	216809.49	-5.99	WB
9710	3628278.29	216812.79	-5.98	WB
9711	3628278.37	216816.20	-5.96	WB
9712	3628278.32	216819.52	-5.94	WB
9713	3628278.26	216822.81	-5.92	WB
9714	3628278.12	216826.04	-5.89	WB
9715	3628277.95	216829.23	-5.87	WB
9716	3628277.77	216832.30	-5.85	WB
9717	3628277.65	216833.80	-5.83	WB
9718	3628277.54	216835.32	-5.80	WB
9719	3628277.32	216838.29	-5.78	WB
9720	3628277.05	216841.03	-5.75	WB
9721	3628276.77	216843.82	-5.72	WB
9722	3628276.47	216846.53	-5.70	WB
9723	3628276.14	216849.11	-5.67	WB
9724	3628275.82	216851.69	-5.65	WB
9725	3628275.53	216854.17	-5.62	WB
9726	3628275.24	216856.64	-5.59	WB
9727	3628274.99	216858.82	-5.57	WB
9728	3628274.95	216859.11	-5.54	WB
9729	3628274.65	216861.57	-5.52	WB
9730	3628274.34	216864.01	-5.49	WB
9731	3628274.00	216866.57	-5.47	WB
9732	3628273.64	216869.18	-5.44	WB
9733	3628273.29	216871.75	-5.42	WB
9734	3628272.91	216874.51	-5.40	WB
9735	3628272.54	216877.25	-5.37	WB
9736	3628272.27	216880.10	-5.35	WB
9737	3628271.99	216883.03	-5.33	WB
9738	3628271.87	216884.53	-5.31	WB
9739	3628271.80	216886.07	-5.28	WB
9740	3628271.65	216889.19	-5.26	WB
9741	3628271.53	216892.37	-5.24	WB
9742	3628271.51	216895.81	-5.22	WB
9743	3628271.50	216899.27	-5.20	WB
9744	3628271.64	216902.97	-5.18	WB
9745	3628271.83	216906.71	-5.16	WB
9746	3628272.07	216910.50	-5.14	WB
9747	3628272.43	216914.42	-5.11	WB
9748	3628272.80	216918.32	-5.09	WB
9749	3628273.34	216922.24	-5.07	WB
9750	3628273.93	216926.15	-5.05	WB
9751	3628274.56	216929.83	-5.03	WB
9752	3628275.26	216933.44	-5.00	WB
9753	3628275.72	216935.73	-4.98	WB
9754	3628275.99	216937.05	-4.95	WB
9755	3628276.61	216940.28	-4.92	WB
9756	3628277.27	216943.60	-4.88	WB
9757	3628277.85	216946.71	-4.84	WB
9758	3628278.36	216949.60	-4.80	WB
9759	3628278.88	216952.59	-4.76	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
9760	3628279.18	216955.22	-4.71	WB
9761	3628279.47	216957.87	-4.66	WB
9762	3628279.61	216959.22	-4.61	WB
9763	3628279.70	216960.42	-4.55	WB
9764	3628279.85	216962.88	-4.50	WB
9765	3628279.98	216965.35	-4.44	WB
9766	3628280.00	216967.73	-4.39	WB
9767	3628280.01	216970.14	-4.33	WB
9768	3628279.95	216972.54	-4.27	WB
9769	3628279.86	216975.02	-4.21	WB
9770	3628279.78	216977.44	-4.15	WB
9771	3628279.70	216979.97	-4.09	WB
9772	3628279.62	216982.46	-4.03	WB
9773	3628279.55	216983.99	-3.97	WB
9774	3628279.50	216984.92	-3.92	WB
9775	3628279.36	216987.39	-3.86	WB
9776	3628279.24	216989.83	-3.81	WB
9777	3628279.12	216992.19	-3.76	WB
9778	3628279.02	216994.58	-3.71	WB
9779	3628278.87	216996.89	-3.67	WB
9780	3628278.71	216999.21	-3.62	WB
9781	3628278.53	217001.57	-3.58	WB
9782	3628278.35	217003.88	-3.54	WB
9783	3628278.16	217006.27	-3.50	WB
9784	3628277.92	217008.71	-3.47	WB
9785	3628277.67	217011.11	-3.43	WB
9786	3628277.40	217013.66	-3.40	WB
9787	3628277.10	217016.23	-3.36	WB
9788	3628276.79	217018.81	-3.32	WB
9789	3628276.41	217021.57	-3.29	WB
9790	3628276.03	217024.24	-3.26	WB
9791	3628275.64	217027.08	-3.23	WB
9792	3628275.24	217030.00	-3.21	WB
9793	3628274.84	217032.96	-3.20	WB
9794	3628274.69	217034.16	-3.19	WB
9795	3628274.43	217036.17	-3.19	WB
9796	3628274.01	217039.40	-3.19	WB
9797	3628273.65	217042.80	-3.20	WB
9798	3628273.32	217046.30	-3.22	WB
9799	3628273.02	217049.90	-3.23	WB
9800	3628272.84	217053.64	-3.26	WB
9801	3628272.65	217057.44	-3.28	WB
9802	3628272.63	217059.78	-3.32	WB
9803	3628272.64	217061.13	-3.38	WB
9804	3628272.67	217065.00	-3.48	WB
9805	3628272.79	217068.83	-3.61	WB
9806	3628273.08	217072.57	-3.75	WB
9807	3628273.38	217076.27	-3.90	WB
9808	3628273.79	217079.92	-4.11	WB
9809	3628274.22	217083.54	-4.36	WB
9810	3628274.45	217085.38	-4.64	WB
9811	3628274.66	217087.15	-4.96	WB
9812	3628275.10	217090.57	-5.24	WB
9813	3628275.55	217094.00	-5.56	WB
9814	3628275.98	217097.26	-5.97	WB
9815	3628276.42	217100.34	-6.30	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
9816	3628276.82	217103.35	-6.33	WB
9817	3628277.14	217106.17	-6.40	WB
9818	3628277.45	217108.95	-6.44	WB
9819	3628277.55	217111.57	-6.46	WB
9820	3628277.64	217114.19	-6.43	WB
9821	3628277.60	217116.68	-6.43	WB
9822	3628277.46	217119.13	-6.33	WB
9823	3628277.28	217121.58	-5.90	WB
9824	3628276.96	217123.94	-5.68	WB
9825	3628276.62	217126.32	-5.53	WB
9826	3628276.15	217128.75	-5.42	WB
9827	3628275.60	217131.21	-5.27	WB
9828	3628275.09	217133.41	-5.13	WB
9829	3628275.01	217133.70	-5.04	WB
9830	3628274.31	217136.16	-4.93	WB
9831	3628273.60	217138.63	-4.81	WB
9832	3628272.90	217141.04	-4.68	WB
9833	3628272.23	217143.36	-4.59	WB
9834	3628271.57	217145.69	-4.46	WB
9835	3628270.97	217147.92	-4.32	WB
9836	3628270.39	217150.07	-4.20	WB
9837	3628269.91	217152.20	-4.09	WB
9838	3628269.45	217154.28	-3.96	WB
9839	3628269.03	217156.33	-3.86	WB
9840	3628268.63	217158.49	-3.79	WB
9841	3628268.48	217159.29	-3.70	WB
9842	3628268.23	217160.64	-3.60	WB
9843	3628267.87	217162.82	-3.52	WB
9844	3628267.51	217165.02	-3.46	WB
9845	3628267.26	217167.20	-3.38	WB
9846	3628267.11	217169.34	-3.27	WB
9847	3628266.98	217171.50	-3.20	WB
9848	3628267.03	217173.54	-2.90	WB
9849	3628267.08	217175.59	-2.81	WB
9850	3627778.87	215681.83	-9.10	WB
9851	3627778.46	215685.06	-9.08	WB
9852	3627778.04	215688.34	-9.07	WB
9853	3627777.99	215688.73	-9.05	WB
9854	3627777.62	215691.49	-9.03	WB
9855	3627777.20	215694.62	-9.02	WB
9856	3627776.78	215697.73	-9.00	WB
9857	3627776.41	215700.71	-8.99	WB
9858	3627776.05	215703.69	-8.98	WB
9859	3627775.69	215706.63	-8.98	WB
9860	3627775.35	215709.55	-8.97	WB
9861	3627775.03	215712.46	-8.97	WB
9862	3627774.93	215713.90	-8.96	WB
9863	3627774.83	215715.33	-8.96	WB
9864	3627774.63	215718.28	-8.96	WB
9865	3627774.47	215721.21	-8.95	WB
9866	3627774.34	215724.12	-8.95	WB
9867	3627774.23	215727.12	-8.95	WB
9868	3627774.22	215730.06	-8.94	WB
9869	3627774.20	215733.01	-8.94	WB
9870	3627774.21	215736.06	-8.94	WB
9871	3627774.21	215739.04	-8.94	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
9872	3627774.21	215739.44	-8.94	WB
9873	3627774.25	215742.11	-8.94	WB
9874	3627774.35	215745.16	-8.94	WB
9875	3627774.47	215748.18	-8.94	WB
9876	3627774.58	215751.23	-8.94	WB
9877	3627774.71	215754.24	-8.94	WB
9878	3627774.83	215757.23	-8.94	WB
9879	3627774.94	215760.29	-8.94	WB
9880	3627775.04	215763.36	-8.94	WB
9881	3627775.03	215764.23	-8.94	WB
9882	3627774.96	215766.71	-8.93	WB
9883	3627774.88	215770.05	-8.93	WB
9884	3627774.78	215773.43	-8.93	WB
9885	3627774.67	215776.77	-8.93	WB
9886	3627774.57	215780.26	-8.93	WB
9887	3627774.45	215783.52	-8.92	WB
9888	3627774.33	215786.77	-8.92	WB
9889	3627774.23	215788.84	-8.92	WB
9890	3627774.16	215790.06	-8.91	WB
9891	3627773.96	215793.15	-8.91	WB
9892	3627773.74	215796.29	-8.90	WB
9893	3627773.51	215799.28	-8.90	WB
9894	3627773.26	215802.28	-8.89	WB
9895	3627772.99	215805.20	-8.89	WB
9896	3627772.69	215808.10	-8.88	WB
9897	3627772.36	215811.03	-8.87	WB
9898	3627772.02	215813.59	-8.86	WB
9899	3627771.98	215813.95	-8.86	WB
9900	3627771.56	215816.99	-8.85	WB
9901	3627771.12	215820.09	-8.84	WB
9902	3627770.66	215823.23	-8.84	WB
9903	3627770.20	215826.47	-8.83	WB
9904	3627769.77	215829.73	-8.82	WB
9905	3627769.35	215833.06	-8.82	WB
9906	3627769.13	215836.36	-8.81	WB
9907	3627768.95	215839.58	-8.80	WB
9908	3627768.85	215842.83	-8.80	WB
9909	3627768.84	215845.88	-8.79	WB
9910	3627768.84	215848.86	-8.78	WB
9911	3627769.01	215851.85	-8.78	WB
9912	3627769.19	215854.79	-8.77	WB
9913	3627769.35	215857.79	-8.77	WB
9914	3627769.49	215860.87	-8.77	WB
9915	3627769.64	215863.96	-8.76	WB
9916	3627769.70	215864.81	-8.76	WB
9917	3627769.86	215867.12	-8.75	WB
9918	3627770.09	215870.32	-8.75	WB
9919	3627770.32	215873.43	-8.75	WB
9920	3627770.57	215876.53	-8.74	WB
9921	3627770.82	215879.59	-8.74	WB
9922	3627771.12	215882.63	-8.74	WB
9923	3627771.42	215885.68	-8.74	WB
9924	3627771.71	215888.77	-8.73	WB
9925	3627771.78	215889.50	-8.73	WB
9926	3627771.99	215891.77	-8.73	WB
9927	3627772.28	215894.80	-8.72	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
9928	3627772.61	215897.84	-8.72	WB
9929	3627772.94	215900.76	-8.72	WB
9930	3627773.28	215903.74	-8.71	WB
9931	3627773.63	215906.69	-8.71	WB
9932	3627773.92	215909.68	-8.70	WB
9933	3627774.12	215912.75	-8.70	WB
9934	3627774.18	215913.88	-8.70	WB
9935	3627774.29	215915.79	-8.69	WB
9936	3627774.22	215918.95	-8.69	WB
9937	3627774.09	215922.18	-8.68	WB
9938	3627773.90	215925.36	-8.67	WB
9939	3627773.62	215928.65	-8.67	WB
9940	3627773.34	215931.91	-8.66	WB
9941	3627772.91	215935.17	-8.66	WB
9942	3627772.47	215938.48	-8.65	WB
9943	3627772.01	215941.84	-8.64	WB
9944	3627771.58	215945.07	-8.64	WB
9945	3627771.15	215948.31	-8.63	WB
9946	3627770.70	215951.52	-8.62	WB
9947	3627770.28	215954.62	-8.62	WB
9948	3627769.86	215957.76	-8.61	WB
9949	3627769.46	215960.79	-8.60	WB
9950	3627769.06	215963.82	-8.59	WB
9951	3627768.66	215966.87	-8.59	WB
9952	3627768.27	215969.82	-8.58	WB
9953	3627767.92	215972.84	-8.58	WB
9954	3627767.58	215975.90	-8.57	WB
9955	3627767.29	215978.84	-8.56	WB
9956	3627767.05	215981.89	-8.56	WB
9957	3627766.83	215984.89	-8.55	WB
9958	3627766.68	215987.85	-8.55	WB
9959	3627766.63	215989.02	-8.54	WB
9960	3627766.55	215990.91	-8.54	WB
9961	3627766.45	215994.00	-8.53	WB
9962	3627766.42	215997.12	-8.53	WB
9963	3627766.37	216000.31	-8.52	WB
9964	3627766.33	216003.66	-8.52	WB
9965	3627766.30	216007.03	-8.51	WB
9966	3627766.30	216010.46	-8.51	WB
9967	3627766.34	216013.94	-8.50	WB
9968	3627766.36	216014.75	-8.50	WB
9969	3627766.40	216017.27	-8.49	WB
9970	3627766.62	216020.56	-8.49	WB
9971	3627766.85	216023.86	-8.49	WB
9972	3627767.13	216027.00	-8.48	WB
9973	3627767.47	216030.17	-8.48	WB
9974	3627767.81	216033.29	-8.47	WB
9975	3627768.22	216036.34	-8.47	WB
9976	3627768.64	216039.48	-8.46	WB
9977	3627768.69	216039.86	-8.45	WB
9978	3627769.02	216042.69	-8.45	WB
9979	3627769.39	216045.98	-8.44	WB
9980	3627769.75	216049.26	-8.43	WB
9981	3627770.14	216052.59	-8.43	WB
9982	3627770.53	216055.90	-8.42	WB
9983	3627770.94	216059.11	-8.41	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
9984	3627771.37	216062.31	-8.41	WB
9985	3627771.64	216064.31	-8.40	WB
9986	3627771.81	216065.44	-8.39	WB
9987	3627772.29	216068.35	-8.38	WB
9988	3627772.77	216071.21	-8.38	WB
9989	3627773.24	216074.11	-8.37	WB
9990	3627773.70	216077.02	-8.36	WB
9991	3627774.06	216079.92	-8.35	WB
9992	3627774.27	216082.97	-8.35	WB
9993	3627774.47	216086.09	-8.34	WB
9994	3627774.59	216089.17	-8.33	WB
9995	3627774.71	216092.34	-8.33	WB
9996	3627774.82	216095.46	-8.32	WB
9997	3627774.90	216098.55	-8.31	WB
9998	3627774.99	216101.72	-8.31	WB
9999	3627775.05	216104.84	-8.30	WB
10000	3627775.12	216107.94	-8.29	WB
10001	3627775.21	216111.02	-8.29	WB
10002	3627775.33	216114.08	-8.28	WB
10003	3627775.45	216117.12	-8.28	WB
10004	3627775.49	216120.30	-8.27	WB
10005	3627775.54	216123.38	-8.27	WB
10006	3627775.55	216126.54	-8.26	WB
10007	3627775.54	216129.77	-8.25	WB
10008	3627775.50	216132.89	-8.25	WB
10009	3627775.35	216136.21	-8.24	WB
10010	3627775.23	216138.61	-8.23	WB
10011	3627775.19	216139.51	-8.23	WB
10012	3627774.95	216142.89	-8.22	WB
10013	3627774.68	216146.27	-8.21	WB
10014	3627774.39	216149.68	-8.21	WB
10015	3627774.09	216153.12	-8.20	WB
10016	3627773.77	216156.68	-8.19	WB
10017	3627773.48	216160.18	-8.18	WB
10018	3627773.20	216163.61	-8.17	WB
10019	3627773.16	216164.08	-8.17	WB
10020	3627772.95	216167.14	-8.16	WB
10021	3627772.77	216170.56	-8.15	WB
10022	3627772.59	216173.98	-8.14	WB
10023	3627772.50	216177.33	-8.13	WB
10024	3627772.42	216180.68	-8.12	WB
10025	3627772.34	216184.02	-8.11	WB
10026	3627772.28	216187.31	-8.10	WB
10027	3627772.24	216189.43	-8.09	WB
10028	3627772.22	216190.60	-8.07	WB
10029	3627772.30	216193.79	-8.06	WB
10030	3627772.38	216196.98	-8.05	WB
10031	3627772.49	216200.08	-8.04	WB
10032	3627772.61	216203.15	-8.03	WB
10033	3627772.76	216206.27	-8.02	WB
10034	3627772.99	216209.17	-8.01	WB
10035	3627773.23	216212.11	-8.00	WB
10036	3627773.40	216214.30	-7.99	WB
10037	3627773.47	216215.09	-7.98	WB
10038	3627773.69	216217.99	-7.97	WB
10039	3627773.93	216220.98	-7.96	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
10040	3627774.17	216223.93	-7.96	WB
10041	3627774.41	216226.84	-7.95	WB
10042	3627774.74	216229.79	-7.94	WB
10043	3627775.12	216232.67	-7.93	WB
10044	3627775.51	216235.56	-7.92	WB
10045	3627775.93	216238.50	-7.92	WB
10046	3627776.03	216239.20	-7.91	WB
10047	3627776.34	216241.46	-7.90	WB
10048	3627776.63	216244.55	-7.89	WB
10049	3627776.89	216247.67	-7.89	WB
10050	3627777.12	216250.85	-7.88	WB
10051	3627777.30	216254.12	-7.87	WB
10052	3627777.48	216257.38	-7.86	WB
10053	3627777.59	216260.78	-7.85	WB
10054	3627777.69	216264.14	-7.85	WB
10055	3627777.79	216267.65	-7.84	WB
10056	3627777.89	216271.19	-7.83	WB
10057	3627778.00	216274.67	-7.82	WB
10058	3627778.04	216278.27	-7.81	WB
10059	3627778.08	216281.82	-7.80	WB
10060	3627778.08	216285.38	-7.79	WB
10061	3627778.07	216288.89	-7.78	WB
10062	3627778.06	216292.39	-7.77	WB
10063	3627777.99	216295.78	-7.76	WB
10064	3627777.92	216299.17	-7.75	WB
10065	3627777.77	216302.42	-7.74	WB
10066	3627777.57	216305.64	-7.73	WB
10067	3627777.36	216308.84	-7.72	WB
10068	3627777.16	216311.84	-7.71	WB
10069	3627777.03	216313.72	-7.70	WB
10070	3627776.96	216314.84	-7.69	WB
10071	3627776.74	216317.82	-7.68	WB
10072	3627776.53	216320.63	-7.67	WB
10073	3627776.31	216323.47	-7.66	WB
10074	3627776.11	216326.25	-7.65	WB
10075	3627775.92	216328.94	-7.64	WB
10076	3627775.74	216331.64	-7.63	WB
10077	3627775.56	216334.31	-7.63	WB
10078	3627775.39	216336.97	-7.62	WB
10079	3627775.28	216338.67	-7.61	WB
10080	3627775.21	216339.68	-7.61	WB
10081	3627775.04	216342.40	-7.60	WB
10082	3627774.85	216345.24	-7.60	WB
10083	3627774.67	216348.08	-7.59	WB
10084	3627774.49	216351.10	-7.59	WB
10085	3627774.32	216354.23	-7.58	WB
10086	3627774.15	216357.42	-7.58	WB
10087	3627773.99	216361.07	-7.57	WB
10088	3627773.84	216364.66	-7.57	WB
10089	3627773.72	216368.47	-7.57	WB
10090	3627773.65	216372.41	-7.56	WB
10091	3627773.59	216376.24	-7.56	WB
10092	3627773.61	216380.17	-7.56	WB
10093	3627773.63	216384.02	-7.55	WB
10094	3627773.69	216387.69	-7.55	WB
10095	3627773.71	216389.14	-7.55	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
10096	3627773.76	216391.34	-7.54	WB
10097	3627773.83	216394.89	-7.54	WB
10098	3627773.87	216398.13	-7.53	WB
10099	3627773.90	216401.39	-7.53	WB
10100	3627773.90	216404.48	-7.52	WB
10101	3627773.87	216407.50	-7.51	WB
10102	3627773.83	216410.52	-7.51	WB
10103	3627773.75	216413.44	-7.50	WB
10104	3627773.74	216413.83	-7.49	WB
10105	3627773.66	216416.38	-7.49	WB
10106	3627773.52	216419.28	-7.48	WB
10107	3627773.37	216422.23	-7.47	WB
10108	3627773.22	216425.16	-7.46	WB
10109	3627773.10	216428.12	-7.46	WB
10110	3627773.00	216430.98	-7.45	WB
10111	3627772.91	216433.86	-7.44	WB
10112	3627772.84	216436.76	-7.43	WB
10113	3627772.77	216439.23	-7.42	WB
10114	3627772.76	216439.63	-7.42	WB
10115	3627772.67	216442.59	-7.41	WB
10116	3627772.58	216445.52	-7.40	WB
10117	3627772.48	216448.59	-7.39	WB
10118	3627772.37	216451.77	-7.38	WB
10119	3627772.29	216455.08	-7.38	WB
10120	3627772.23	216458.46	-7.37	WB
10121	3627772.19	216461.82	-7.36	WB
10122	3627772.20	216464.37	-7.35	WB
10123	3627772.21	216465.32	-7.34	WB
10124	3627772.23	216468.76	-7.34	WB
10125	3627772.29	216472.32	-7.33	WB
10126	3627772.37	216475.76	-7.32	WB
10127	3627772.45	216479.10	-7.32	WB
10128	3627772.56	216482.45	-7.31	WB
10129	3627772.66	216485.73	-7.30	WB
10130	3627772.78	216488.86	-7.29	WB
10131	3627772.79	216489.28	-7.29	WB
10132	3627772.90	216492.04	-7.28	WB
10133	3627773.01	216495.14	-7.27	WB
10134	3627773.10	216498.13	-7.27	WB
10135	3627773.19	216501.21	-7.26	WB
10136	3627773.29	216504.21	-7.25	WB
10137	3627773.39	216507.22	-7.25	WB
10138	3627773.48	216510.21	-7.24	WB
10139	3627773.56	216513.19	-7.23	WB
10140	3627773.59	216514.35	-7.23	WB
10141	3627773.64	216516.18	-7.22	WB
10142	3627773.75	216519.19	-7.22	WB
10143	3627773.85	216522.23	-7.21	WB
10144	3627773.96	216525.31	-7.20	WB
10145	3627774.07	216528.46	-7.20	WB
10146	3627774.18	216531.52	-7.19	WB
10147	3627774.24	216534.70	-7.19	WB
10148	3627774.29	216537.95	-7.18	WB
10149	3627774.31	216539.52	-7.18	WB
10150	3627774.33	216541.11	-7.17	WB
10151	3627774.38	216544.36	-7.17	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
10152	3627774.43	216547.55	-7.16	WB
10153	3627774.50	216550.65	-7.16	WB
10154	3627774.59	216553.88	-7.15	WB
10155	3627774.67	216556.97	-7.14	WB
10156	3627774.75	216560.11	-7.14	WB
10157	3627774.82	216563.29	-7.13	WB
10158	3627774.84	216564.46	-7.13	WB
10159	3627774.86	216566.51	-7.12	WB
10160	3627774.89	216569.84	-7.11	WB
10161	3627774.94	216573.23	-7.10	WB
10162	3627774.99	216576.65	-7.10	WB
10163	3627775.04	216580.23	-7.09	WB
10164	3627775.10	216583.80	-7.08	WB
10165	3627775.17	216587.37	-7.07	WB
10166	3627775.20	216589.09	-7.06	WB
10167	3627775.24	216590.90	-7.05	WB
10168	3627775.31	216594.45	-7.04	WB
10169	3627775.37	216597.98	-7.03	WB
10170	3627775.41	216601.35	-7.02	WB
10171	3627775.45	216604.72	-7.01	WB
10172	3627775.46	216607.88	-7.00	WB
10173	3627775.45	216610.99	-6.99	WB
10174	3627775.46	216613.66	-6.98	WB
10175	3627775.46	216614.00	-6.97	WB
10176	3627775.47	216616.84	-6.96	WB
10177	3627775.47	216619.73	-6.95	WB
10178	3627775.41	216622.25	-6.94	WB
10179	3627775.33	216624.85	-6.93	WB
10180	3627775.24	216627.45	-6.92	WB
10181	3627775.16	216629.95	-6.92	WB
10182	3627775.07	216632.54	-6.91	WB
10183	3627775.02	216635.17	-6.90	WB
10184	3627774.96	216637.77	-6.89	WB
10185	3627774.94	216639.12	-6.89	WB
10186	3627774.93	216640.58	-6.88	WB
10187	3627774.92	216643.46	-6.88	WB
10188	3627774.93	216646.36	-6.87	WB
10189	3627775.01	216649.51	-6.87	WB
10190	3627775.09	216652.65	-6.86	WB
10191	3627775.22	216656.03	-6.86	WB
10192	3627775.36	216659.53	-6.86	WB
10193	3627775.52	216663.09	-6.85	WB
10194	3627775.62	216664.93	-6.85	WB
10195	3627775.73	216666.84	-6.85	WB
10196	3627775.94	216670.59	-6.84	WB
10197	3627776.20	216674.45	-6.84	WB
10198	3627776.48	216678.32	-6.84	WB
10199	3627776.77	216682.22	-6.83	WB
10200	3627777.05	216685.99	-6.83	WB
10201	3627777.35	216689.79	-6.82	WB
10202	3627777.63	216693.52	-6.82	WB
10203	3627777.90	216697.06	-6.81	WB
10204	3627778.15	216700.55	-6.80	WB
10205	3627778.34	216703.78	-6.80	WB
10206	3627778.54	216706.96	-6.79	WB
10207	3627778.74	216709.89	-6.78	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
10208	3627778.92	216712.78	-6.77	WB
10209	3627778.99	216713.81	-6.76	WB
10210	3627779.08	216715.59	-6.75	WB
10211	3627779.19	216718.32	-6.73	WB
10212	3627779.29	216721.09	-6.72	WB
10213	3627779.30	216723.85	-6.71	WB
10214	3627779.31	216726.63	-6.69	WB
10215	3627779.31	216729.48	-6.68	WB
10216	3627779.30	216732.38	-6.66	WB
10217	3627779.29	216735.28	-6.65	WB
10218	3627779.30	216738.29	-6.63	WB
10219	3627779.30	216739.10	-6.62	WB
10220	3627779.31	216741.30	-6.60	WB
10221	3627779.35	216744.38	-6.58	WB
10222	3627779.41	216747.38	-6.57	WB
10223	3627779.48	216750.41	-6.55	WB
10224	3627779.54	216753.49	-6.54	WB
10225	3627779.59	216756.50	-6.52	WB
10226	3627779.62	216759.74	-6.50	WB
10227	3627779.63	216762.81	-6.49	WB
10228	3627779.63	216763.98	-6.47	WB
10229	3627779.65	216765.90	-6.46	WB
10230	3627779.69	216769.10	-6.44	WB
10231	3627779.72	216772.25	-6.43	WB
10232	3627779.74	216775.43	-6.41	WB
10233	3627779.75	216778.60	-6.40	WB
10234	3627779.78	216781.75	-6.38	WB
10235	3627779.84	216784.87	-6.37	WB
10236	3627779.91	216787.97	-6.35	WB
10237	3627779.94	216789.15	-6.34	WB
10238	3627779.98	216791.10	-6.33	WB
10239	3627780.06	216794.22	-6.32	WB
10240	3627780.11	216797.35	-6.30	WB
10241	3627780.13	216800.55	-6.29	WB
10242	3627780.15	216803.76	-6.28	WB
10243	3627780.15	216807.12	-6.27	WB
10244	3627780.16	216810.37	-6.26	WB
10245	3627780.16	216813.72	-6.24	WB
10246	3627780.16	216814.12	-6.23	WB
10247	3627780.14	216817.14	-6.22	WB
10248	3627780.12	216820.49	-6.21	WB
10249	3627780.07	216824.01	-6.20	WB
10250	3627780.03	216827.49	-6.19	WB
10251	3627779.98	216830.95	-6.18	WB
10252	3627779.95	216834.48	-6.16	WB
10253	3627779.91	216837.95	-6.14	WB
10254	3627779.89	216838.78	-6.12	WB
10255	3627779.85	216841.43	-6.10	WB
10256	3627779.79	216844.92	-6.08	WB
10257	3627779.76	216848.37	-6.05	WB
10258	3627779.73	216851.81	-6.02	WB
10259	3627779.71	216855.26	-5.99	WB
10260	3627779.70	216858.68	-5.96	WB
10261	3627779.68	216862.10	-5.92	WB
10262	3627779.66	216863.86	-5.88	WB
10263	3627779.64	216865.54	-5.84	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
10264	3627779.59	216868.96	-5.79	WB
10265	3627779.52	216872.35	-5.74	WB
10266	3627779.39	216875.73	-5.69	WB
10267	3627779.27	216879.00	-5.64	WB
10268	3627779.16	216882.18	-5.58	WB
10269	3627779.06	216885.40	-5.52	WB
10270	3627778.92	216888.41	-5.46	WB
10271	3627778.90	216888.80	-5.40	WB
10272	3627778.76	216891.39	-5.33	WB
10273	3627778.61	216894.27	-5.27	WB
10274	3627778.55	216896.93	-5.21	WB
10275	3627778.49	216899.66	-5.15	WB
10276	3627778.38	216902.28	-5.08	WB
10277	3627778.24	216904.79	-5.02	WB
10278	3627778.08	216907.37	-4.95	WB
10279	3627777.91	216909.85	-4.89	WB
10280	3627777.75	216912.29	-4.83	WB
10281	3627777.67	216913.55	-4.78	WB
10282	3627777.60	216914.75	-4.72	WB
10283	3627777.44	216917.25	-4.67	WB
10284	3627777.28	216919.72	-4.62	WB
10285	3627777.14	216922.22	-4.59	WB
10286	3627776.99	216924.72	-4.54	WB
10287	3627776.90	216927.30	-4.50	WB
10288	3627776.84	216929.94	-4.44	WB
10289	3627776.77	216932.60	-4.41	WB
10290	3627776.71	216935.48	-4.40	WB
10291	3627776.63	216938.42	-4.38	WB
10292	3627776.62	216939.15	-4.37	WB
10293	3627776.57	216941.59	-4.36	WB
10294	3627776.51	216944.92	-4.34	WB
10295	3627776.47	216948.36	-4.34	WB
10296	3627776.44	216951.98	-4.32	WB
10297	3627776.41	216955.73	-4.31	WB
10298	3627776.47	216959.74	-4.29	WB
10299	3627776.54	216963.77	-4.24	WB
10300	3627776.57	216965.28	-4.20	WB
10301	3627776.72	216967.92	-4.13	WB
10302	3627777.03	216972.21	-4.08	WB
10303	3627777.35	216976.44	-4.01	WB
10304	3627777.84	216980.69	-3.94	WB
10305	3627778.34	216984.91	-3.90	WB
10306	3627778.88	216988.91	-3.86	WB
10307	3627779.10	216990.44	-3.83	WB
10308	3627779.46	216992.85	-3.82	WB
10309	3627780.04	216996.77	-3.81	WB
10310	3627780.53	217000.51	-3.81	WB
10311	3627781.01	217004.19	-3.82	WB
10312	3627781.36	217007.70	-3.83	WB
10313	3627781.63	217011.08	-3.85	WB
10314	3627781.86	217014.03	-3.87	WB
10315	3627781.87	217014.39	-3.88	WB
10316	3627781.95	217017.42	-3.89	WB
10317	3627782.04	217020.45	-3.91	WB
10318	3627781.96	217023.11	-3.94	WB
10319	3627781.82	217025.78	-3.96	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
10320	3627781.61	217028.38	-4.00	WB
10321	3627781.29	217030.69	-4.04	WB
10322	3627780.93	217033.10	-4.08	WB
10323	3627780.53	217035.38	-4.13	WB
10324	3627780.10	217037.62	-4.18	WB
10325	3627779.98	217038.24	-4.24	WB
10326	3627779.60	217039.99	-4.31	WB
10327	3627779.07	217042.30	-4.37	WB
10328	3627778.49	217044.71	-4.44	WB
10329	3627777.98	217047.19	-4.51	WB
10330	3627777.48	217049.67	-4.58	WB
10331	3627777.03	217052.22	-4.65	WB
10332	3627776.67	217054.66	-4.73	WB
10333	3627776.34	217057.05	-4.81	WB
10334	3627776.22	217059.36	-4.90	WB
10335	3627776.12	217061.65	-5.00	WB
10336	3627776.06	217063.83	-5.10	WB
10337	3627776.06	217064.09	-5.18	WB
10338	3627776.04	217065.98	-5.26	WB
10339	3627776.03	217068.14	-5.32	WB
10340	3627776.02	217070.27	-5.37	WB
10341	3627776.01	217072.44	-5.39	WB
10342	3627776.01	217074.73	-5.40	WB
10343	3627776.01	217077.00	-5.39	WB
10344	3627775.99	217079.38	-5.40	WB
10345	3627775.91	217081.89	-5.41	WB
10346	3627775.83	217084.38	-5.42	WB
10347	3627775.76	217087.19	-5.39	WB
10348	3627775.70	217089.27	-5.35	WB
10349	3627775.68	217090.04	-5.31	WB
10350	3627775.61	217092.93	-5.26	WB
10351	3627775.51	217096.11	-5.22	WB
10352	3627775.42	217099.32	-5.17	WB
10353	3627775.35	217102.56	-5.14	WB
10354	3627775.30	217105.86	-5.10	WB
10355	3627775.27	217109.18	-5.06	WB
10356	3627775.29	217112.33	-5.02	WB
10357	3627775.31	217114.35	-4.98	WB
10358	3627775.32	217115.55	-4.94	WB
10359	3627775.35	217118.56	-4.89	WB
10360	3627775.38	217121.49	-4.85	WB
10361	3627775.42	217124.36	-4.81	WB
10362	3627775.48	217126.99	-4.76	WB
10363	3627775.52	217129.61	-4.72	WB
10364	3627775.55	217131.88	-4.67	WB
10365	3627775.57	217134.15	-4.63	WB
10366	3627775.58	217136.23	-4.58	WB
10367	3627775.56	217138.19	-4.53	WB
10368	3627775.56	217138.92	-4.48	WB
10369	3627775.55	217140.14	-4.43	WB
10370	3627775.55	217142.01	-4.38	WB
10371	3627775.55	217143.88	-4.32	WB
10372	3627775.54	217145.73	-4.26	WB
10373	3627775.52	217147.59	-4.20	WB
10374	3627775.52	217149.42	-4.14	WB
10375	3627775.59	217151.19	-4.08	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
10376	3627775.67	217152.94	-4.02	WB
10377	3627775.78	217154.55	-3.97	WB
10378	3627775.90	217156.05	-3.91	WB
10379	3627776.03	217157.53	-3.85	WB
10380	3627776.16	217158.91	-3.79	WB
10381	3627776.29	217160.25	-3.74	WB
10382	3627776.45	217161.52	-3.68	WB
10383	3627776.61	217162.76	-3.62	WB
10384	3627776.78	217163.99	-3.56	WB
10385	3627776.82	217164.29	-3.51	WB
10386	3627776.94	217165.19	-3.45	WB
10387	3627777.09	217166.36	-3.40	WB
10388	3627777.28	217167.50	-3.35	WB
10389	3627777.47	217168.66	-3.29	WB
10390	3627777.65	217169.81	-3.25	WB
10391	3627777.83	217171.02	-3.20	WB
10392	3627777.99	217172.23	-3.15	WB
10393	3627778.10	217173.67	-3.10	WB
10394	3627778.19	217175.13	-3.05	WB
10395	3627778.25	217176.83	-3.00	WB
10396	3627778.28	217178.65	-2.95	WB
10397	3627778.31	217180.46	-2.88	WB
10398	3627778.36	217182.39	-2.82	WB
10399	3627778.43	217184.27	-2.76	WB
10400	3627778.52	217185.91	-2.70	WB
10401	3627778.65	217187.43	-2.63	WB
10402	3627281.10	215694.88	-8.80	WB
10403	3627280.34	215697.75	-8.80	WB
10404	3627279.79	215699.89	-8.82	WB
10405	3627279.60	215700.62	-8.83	WB
10406	3627278.98	215703.54	-8.84	WB
10407	3627278.46	215706.47	-8.85	WB
10408	3627277.98	215709.42	-8.86	WB
10409	3627277.68	215712.36	-8.87	WB
10410	3627277.40	215715.24	-8.87	WB
10411	3627277.19	215718.16	-8.87	WB
10412	3627277.01	215721.12	-8.88	WB
10413	3627276.85	215724.10	-8.88	WB
10414	3627276.79	215725.60	-8.89	WB
10415	3627276.74	215727.10	-8.89	WB
10416	3627276.62	215730.15	-8.89	WB
10417	3627276.59	215733.32	-8.89	WB
10418	3627276.59	215736.40	-8.89	WB
10419	3627276.64	215739.57	-8.89	WB
10420	3627276.77	215742.67	-8.88	WB
10421	3627276.91	215745.71	-8.88	WB
10422	3627277.16	215748.66	-8.87	WB
10423	3627277.34	215750.49	-8.86	WB
10424	3627277.45	215751.63	-8.85	WB
10425	3627277.74	215754.46	-8.84	WB
10426	3627278.06	215757.32	-8.83	WB
10427	3627278.37	215760.19	-8.83	WB
10428	3627278.58	215763.05	-8.82	WB
10429	3627278.78	215765.91	-8.81	WB
10430	3627278.97	215768.78	-8.80	WB
10431	3627279.14	215771.53	-8.79	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
10432	3627279.33	215774.30	-8.79	WB
10433	3627279.42	215775.35	-8.78	WB
10434	3627279.57	215777.02	-8.77	WB
10435	3627279.82	215779.63	-8.76	WB
10436	3627280.11	215782.31	-8.76	WB
10437	3627280.39	215784.87	-8.75	WB
10438	3627280.68	215787.46	-8.75	WB
10439	3627280.92	215790.26	-8.74	WB
10440	3627281.15	215792.94	-8.74	WB
10441	3627281.36	215795.77	-8.73	WB
10442	3627281.58	215798.56	-8.73	WB
10443	3627281.71	215800.30	-8.72	WB
10444	3627281.77	215801.35	-8.72	WB
10445	3627281.89	215804.28	-8.71	WB
10446	3627282.01	215807.16	-8.71	WB
10447	3627282.09	215810.09	-8.71	WB
10448	3627282.16	215813.04	-8.70	WB
10449	3627282.19	215816.00	-8.70	WB
10450	3627282.13	215818.92	-8.70	WB
10451	3627282.06	215821.90	-8.69	WB
10452	3627281.92	215824.94	-8.69	WB
10453	3627281.75	215827.90	-8.68	WB
10454	3627281.51	215831.03	-8.68	WB
10455	3627281.20	215834.21	-8.67	WB
10456	3627280.87	215837.40	-8.67	WB
10457	3627280.56	215840.69	-8.67	WB
10458	3627280.27	215843.93	-8.66	WB
10459	3627280.00	215847.24	-8.65	WB
10460	3627279.75	215850.62	-8.65	WB
10461	3627279.51	215853.89	-8.64	WB
10462	3627279.38	215857.04	-8.64	WB
10463	3627279.26	215860.18	-8.63	WB
10464	3627279.21	215863.11	-8.63	WB
10465	3627279.22	215865.93	-8.62	WB
10466	3627279.25	215868.72	-8.61	WB
10467	3627279.41	215871.25	-8.61	WB
10468	3627279.56	215873.82	-8.60	WB
10469	3627279.66	215875.38	-8.60	WB
10470	3627279.72	215876.37	-8.59	WB
10471	3627279.88	215878.93	-8.59	WB
10472	3627280.04	215881.55	-8.58	WB
10473	3627280.25	215884.26	-8.58	WB
10474	3627280.45	215886.94	-8.57	WB
10475	3627280.74	215889.81	-8.57	WB
10476	3627281.05	215892.68	-8.57	WB
10477	3627281.38	215895.52	-8.57	WB
10478	3627281.78	215898.61	-8.56	WB
10479	3627282.08	215900.89	-8.56	WB
10480	3627282.18	215901.66	-8.56	WB
10481	3627282.61	215904.76	-8.56	WB
10482	3627283.06	215907.98	-8.55	WB
10483	3627283.51	215911.20	-8.55	WB
10484	3627283.99	215914.45	-8.55	WB
10485	3627284.47	215917.67	-8.55	WB
10486	3627285.02	215920.79	-8.55	WB
10487	3627285.59	215923.85	-8.55	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
10488	3627286.02	215926.13	-8.55	WB
10489	3627286.17	215926.92	-8.54	WB
10490	3627286.72	215929.82	-8.54	WB
10491	3627287.28	215932.71	-8.54	WB
10492	3627287.73	215935.52	-8.54	WB
10493	3627288.18	215938.29	-8.54	WB
10494	3627288.57	215941.02	-8.53	WB
10495	3627288.93	215943.67	-8.53	WB
10496	3627289.27	215946.32	-8.53	WB
10497	3627289.53	215948.87	-8.52	WB
10498	3627289.62	215949.83	-8.52	WB
10499	3627289.76	215951.45	-8.51	WB
10500	3627289.83	215954.07	-8.51	WB
10501	3627289.81	215956.78	-8.50	WB
10502	3627289.75	215959.44	-8.50	WB
10503	3627289.59	215962.19	-8.49	WB
10504	3627289.42	215965.02	-8.49	WB
10505	3627289.19	215967.87	-8.48	WB
10506	3627288.94	215970.79	-8.47	WB
10507	3627288.65	215973.75	-8.47	WB
10508	3627288.51	215974.87	-8.46	WB
10509	3627288.28	215976.77	-8.45	WB
10510	3627287.90	215979.80	-8.45	WB
10511	3627287.46	215982.91	-8.44	WB
10512	3627287.00	215985.99	-8.43	WB
10513	3627286.55	215989.09	-8.42	WB
10514	3627286.11	215992.19	-8.41	WB
10515	3627285.66	215995.30	-8.40	WB
10516	3627285.14	215998.37	-8.39	WB
10517	3627284.94	215999.52	-8.38	WB
10518	3627284.59	216001.50	-8.37	WB
10519	3627284.08	216004.54	-8.36	WB
10520	3627283.57	216007.61	-8.35	WB
10521	3627283.05	216010.74	-8.34	WB
10522	3627282.63	216013.79	-8.33	WB
10523	3627282.19	216016.96	-8.32	WB
10524	3627281.81	216020.11	-8.31	WB
10525	3627281.49	216023.27	-8.30	WB
10526	3627281.28	216025.28	-8.29	WB
10527	3627281.18	216026.48	-8.27	WB
10528	3627281.06	216029.83	-8.26	WB
10529	3627280.94	216033.10	-8.25	WB
10530	3627280.91	216036.43	-8.24	WB
10531	3627280.95	216039.77	-8.22	WB
10532	3627281.05	216042.96	-8.21	WB
10533	3627281.37	216046.09	-8.20	WB
10534	3627281.70	216049.15	-8.19	WB
10535	3627281.94	216050.98	-8.18	WB
10536	3627282.10	216052.04	-8.17	WB
10537	3627282.54	216055.03	-8.15	WB
10538	3627283.01	216057.90	-8.14	WB
10539	3627283.57	216060.73	-8.13	WB
10540	3627284.14	216063.60	-8.12	WB
10541	3627284.66	216066.33	-8.11	WB
10542	3627285.19	216069.08	-8.10	WB
10543	3627285.70	216071.82	-8.09	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
10544	3627286.16	216074.41	-8.09	WB
10545	3627286.34	216075.40	-8.08	WB
10546	3627286.64	216077.09	-8.07	WB
10547	3627287.00	216079.69	-8.06	WB
10548	3627287.35	216082.26	-8.06	WB
10549	3627287.69	216084.96	-8.05	WB
10550	3627288.02	216087.67	-8.04	WB
10551	3627288.36	216090.36	-8.04	WB
10552	3627288.68	216093.29	-8.03	WB
10553	3627289.01	216096.17	-8.03	WB
10554	3627289.30	216099.13	-8.02	WB
10555	3627289.41	216100.33	-8.02	WB
10556	3627289.58	216102.22	-8.01	WB
10557	3627289.87	216105.35	-8.01	WB
10558	3627290.10	216108.46	-8.00	WB
10559	3627290.33	216111.62	-8.00	WB
10560	3627290.43	216114.86	-7.99	WB
10561	3627290.44	216118.02	-7.99	WB
10562	3627290.43	216121.30	-7.98	WB
10563	3627290.34	216124.54	-7.98	WB
10564	3627290.32	216124.98	-7.97	WB
10565	3627290.23	216127.75	-7.97	WB
10566	3627290.01	216131.06	-7.96	WB
10567	3627289.75	216134.33	-7.96	WB
10568	3627289.51	216137.57	-7.95	WB
10569	3627289.34	216140.69	-7.95	WB
10570	3627289.17	216143.76	-7.94	WB
10571	3627289.00	216146.78	-7.94	WB
10572	3627288.83	216149.70	-7.94	WB
10573	3627288.66	216152.54	-7.93	WB
10574	3627288.48	216155.43	-7.93	WB
10575	3627288.31	216158.28	-7.92	WB
10576	3627288.13	216161.11	-7.92	WB
10577	3627287.96	216163.95	-7.92	WB
10578	3627287.80	216166.78	-7.91	WB
10579	3627287.67	216169.58	-7.91	WB
10580	3627287.54	216172.37	-7.91	WB
10581	3627287.51	216174.75	-7.91	WB
10582	3627287.51	216175.12	-7.91	WB
10583	3627287.48	216177.86	-7.91	WB
10584	3627287.45	216180.68	-7.91	WB
10585	3627287.41	216183.44	-7.90	WB
10586	3627287.36	216186.27	-7.90	WB
10587	3627287.21	216189.39	-7.90	WB
10588	3627287.06	216192.42	-7.90	WB
10589	3627286.80	216195.78	-7.90	WB
10590	3627286.50	216199.19	-7.90	WB
10591	3627286.42	216200.01	-7.90	WB
10592	3627286.18	216202.60	-7.90	WB
10593	3627285.80	216206.24	-7.90	WB
10594	3627285.43	216209.82	-7.90	WB
10595	3627285.02	216213.31	-7.90	WB
10596	3627284.60	216216.90	-7.90	WB
10597	3627284.17	216220.41	-7.90	WB
10598	3627283.72	216223.82	-7.89	WB
10599	3627283.61	216224.69	-7.89	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
10600	3627283.27	216227.23	-7.89	WB
10601	3627282.83	216230.46	-7.88	WB
10602	3627282.38	216233.65	-7.88	WB
10603	3627281.93	216236.82	-7.87	WB
10604	3627281.50	216239.86	-7.86	WB
10605	3627281.05	216242.92	-7.86	WB
10606	3627280.65	216245.95	-7.85	WB
10607	3627280.27	216248.89	-7.84	WB
10608	3627280.12	216250.01	-7.83	WB
10609	3627279.91	216251.87	-7.82	WB
10610	3627279.57	216254.97	-7.81	WB
10611	3627279.24	216257.99	-7.80	WB
10612	3627279.02	216261.21	-7.79	WB
10613	3627278.81	216264.41	-7.78	WB
10614	3627278.72	216267.58	-7.77	WB
10615	3627278.72	216270.82	-7.76	WB
10616	3627278.75	216274.00	-7.75	WB
10617	3627278.85	216275.61	-7.74	WB
10618	3627278.94	216277.26	-7.73	WB
10619	3627279.14	216280.52	-7.71	WB
10620	3627279.38	216283.76	-7.70	WB
10621	3627279.65	216287.00	-7.69	WB
10622	3627279.94	216290.26	-7.68	WB
10623	3627280.31	216293.39	-7.67	WB
10624	3627280.68	216296.51	-7.66	WB
10625	3627281.07	216299.52	-7.64	WB
10626	3627281.22	216300.62	-7.63	WB
10627	3627281.48	216302.46	-7.62	WB
10628	3627281.92	216305.34	-7.61	WB
10629	3627282.43	216308.08	-7.60	WB
10630	3627282.94	216310.74	-7.59	WB
10631	3627283.45	216313.33	-7.58	WB
10632	3627283.97	216315.98	-7.57	WB
10633	3627284.46	216318.55	-7.56	WB
10634	3627284.96	216321.21	-7.55	WB
10635	3627285.45	216323.83	-7.54	WB
10636	3627285.68	216325.50	-7.53	WB
10637	3627285.81	216326.53	-7.52	WB
10638	3627286.17	216329.32	-7.51	WB
10639	3627286.44	216332.15	-7.50	WB
10640	3627286.63	216335.02	-7.49	WB
10641	3627286.84	216337.94	-7.49	WB
10642	3627286.94	216340.91	-7.48	WB
10643	3627287.05	216343.82	-7.47	WB
10644	3627287.09	216346.78	-7.47	WB
10645	3627287.07	216349.79	-7.46	WB
10646	3627287.04	216352.68	-7.46	WB
10647	3627286.98	216355.60	-7.45	WB
10648	3627286.90	216358.58	-7.45	WB
10649	3627286.74	216361.47	-7.44	WB
10650	3627286.52	216364.48	-7.44	WB
10651	3627286.26	216367.49	-7.43	WB
10652	3627285.91	216370.45	-7.43	WB
10653	3627285.52	216373.58	-7.42	WB
10654	3627285.38	216374.68	-7.42	WB
10655	3627285.12	216376.60	-7.41	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
10656	3627284.71	216379.68	-7.40	WB
10657	3627284.31	216382.76	-7.40	WB
10658	3627283.93	216385.87	-7.39	WB
10659	3627283.57	216388.95	-7.39	WB
10660	3627283.27	216391.96	-7.38	WB
10661	3627282.99	216394.98	-7.38	WB
10662	3627282.75	216397.99	-7.37	WB
10663	3627282.61	216399.88	-7.36	WB
10664	3627282.54	216401.00	-7.36	WB
10665	3627282.33	216404.01	-7.35	WB
10666	3627282.10	216407.04	-7.35	WB
10667	3627281.87	216410.11	-7.34	WB
10668	3627281.65	216413.11	-7.34	WB
10669	3627281.43	216416.20	-7.33	WB
10670	3627281.21	216419.33	-7.32	WB
10671	3627280.99	216422.41	-7.32	WB
10672	3627280.79	216425.22	-7.31	WB
10673	3627280.77	216425.58	-7.30	WB
10674	3627280.57	216428.76	-7.30	WB
10675	3627280.40	216431.95	-7.29	WB
10676	3627280.23	216435.23	-7.28	WB
10677	3627280.10	216438.54	-7.27	WB
10678	3627279.96	216441.82	-7.27	WB
10679	3627279.82	216445.17	-7.26	WB
10680	3627279.68	216448.52	-7.25	WB
10681	3627279.61	216450.22	-7.24	WB
10682	3627279.55	216451.86	-7.23	WB
10683	3627279.43	216455.09	-7.22	WB
10684	3627279.30	216458.36	-7.21	WB
10685	3627279.19	216461.40	-7.20	WB
10686	3627279.08	216464.45	-7.18	WB
10687	3627279.00	216467.51	-7.17	WB
10688	3627278.96	216470.38	-7.16	WB
10689	3627278.93	216473.33	-7.15	WB
10690	3627278.92	216475.45	-7.14	WB
10691	3627278.92	216476.23	-7.13	WB
10692	3627278.91	216479.09	-7.12	WB
10693	3627278.91	216482.05	-7.11	WB
10694	3627278.94	216484.96	-7.10	WB
10695	3627278.98	216487.82	-7.09	WB
10696	3627279.16	216490.76	-7.08	WB
10697	3627279.37	216493.61	-7.07	WB
10698	3627279.61	216496.45	-7.06	WB
10699	3627279.89	216499.43	-7.05	WB
10700	3627279.99	216500.53	-7.04	WB
10701	3627280.17	216502.38	-7.03	WB
10702	3627280.53	216505.36	-7.02	WB
10703	3627280.89	216508.45	-7.02	WB
10704	3627281.25	216511.65	-7.01	WB
10705	3627281.59	216514.83	-7.00	WB
10706	3627281.94	216518.14	-6.99	WB
10707	3627282.26	216521.38	-6.98	WB
10708	3627282.58	216524.61	-6.98	WB
10709	3627282.67	216525.49	-6.97	WB
10710	3627282.91	216528.00	-6.96	WB
10711	3627283.23	216531.21	-6.95	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
10712	3627283.56	216534.49	-6.94	WB
10713	3627283.87	216537.58	-6.93	WB
10714	3627284.18	216540.61	-6.93	WB
10715	3627284.50	216543.52	-6.92	WB
10716	3627284.83	216546.37	-6.91	WB
10717	3627285.16	216549.20	-6.90	WB
10718	3627285.26	216550.21	-6.89	WB
10719	3627285.44	216551.91	-6.88	WB
10720	3627285.73	216554.62	-6.88	WB
10721	3627285.94	216557.29	-6.87	WB
10722	3627286.13	216559.99	-6.86	WB
10723	3627286.29	216562.73	-6.86	WB
10724	3627286.37	216565.42	-6.85	WB
10725	3627286.46	216568.17	-6.85	WB
10726	3627286.51	216570.98	-6.84	WB
10727	3627286.56	216573.67	-6.84	WB
10728	3627286.58	216574.73	-6.84	WB
10729	3627286.60	216576.44	-6.83	WB
10730	3627286.60	216579.18	-6.83	WB
10731	3627286.61	216581.89	-6.83	WB
10732	3627286.52	216584.76	-6.83	WB
10733	3627286.42	216587.57	-6.83	WB
10734	3627286.28	216590.39	-6.82	WB
10735	3627286.08	216593.26	-6.82	WB
10736	3627285.87	216596.18	-6.82	WB
10737	3627285.58	216599.24	-6.82	WB
10738	3627285.54	216599.60	-6.82	WB
10739	3627285.28	216602.36	-6.82	WB
10740	3627284.96	216605.51	-6.82	WB
10741	3627284.63	216608.79	-6.81	WB
10742	3627284.27	216612.12	-6.81	WB
10743	3627283.87	216615.61	-6.81	WB
10744	3627283.48	216619.10	-6.80	WB
10745	3627283.13	216622.64	-6.80	WB
10746	3627282.89	216625.18	-6.79	WB
10747	3627282.81	216626.06	-6.79	WB
10748	3627282.53	216629.41	-6.78	WB
10749	3627282.32	216632.72	-6.77	WB
10750	3627282.12	216635.96	-6.76	WB
10751	3627281.98	216639.06	-6.75	WB
10752	3627281.85	216642.10	-6.74	WB
10753	3627281.73	216645.09	-6.73	WB
10754	3627281.60	216647.99	-6.72	WB
10755	3627281.51	216649.78	-6.71	WB
10756	3627281.46	216650.91	-6.70	WB
10757	3627281.34	216653.82	-6.69	WB
10758	3627281.22	216656.71	-6.68	WB
10759	3627281.08	216659.62	-6.67	WB
10760	3627280.91	216662.53	-6.66	WB
10761	3627280.74	216665.45	-6.65	WB
10762	3627280.66	216668.50	-6.63	WB
10763	3627280.59	216671.43	-6.62	WB
10764	3627280.52	216674.49	-6.61	WB
10765	3627280.51	216675.27	-6.60	WB
10766	3627280.45	216677.63	-6.59	WB
10767	3627280.40	216680.70	-6.58	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
10768	3627280.42	216683.97	-6.57	WB
10769	3627280.44	216687.09	-6.55	WB
10770	3627280.52	216690.21	-6.54	WB
10771	3627280.64	216693.47	-6.53	WB
10772	3627280.75	216696.56	-6.52	WB
10773	3627280.87	216699.65	-6.51	WB
10774	3627280.88	216700.01	-6.50	WB
10775	3627281.00	216702.68	-6.49	WB
10776	3627281.16	216705.56	-6.48	WB
10777	3627281.33	216708.48	-6.46	WB
10778	3627281.47	216711.36	-6.45	WB
10779	3627281.54	216714.20	-6.44	WB
10780	3627281.59	216717.06	-6.43	WB
10781	3627281.60	216719.90	-6.42	WB
10782	3627281.59	216722.79	-6.41	WB
10783	3627281.58	216724.94	-6.39	WB
10784	3627281.58	216725.68	-6.38	WB
10785	3627281.56	216728.59	-6.37	WB
10786	3627281.55	216731.50	-6.36	WB
10787	3627281.57	216734.48	-6.34	WB
10788	3627281.59	216737.43	-6.33	WB
10789	3627281.66	216740.38	-6.32	WB
10790	3627281.78	216743.42	-6.30	WB
10791	3627281.89	216746.36	-6.29	WB
10792	3627282.00	216749.36	-6.28	WB
10793	3627282.02	216750.12	-6.26	WB
10794	3627282.11	216752.40	-6.25	WB
10795	3627282.22	216755.35	-6.24	WB
10796	3627282.35	216758.39	-6.22	WB
10797	3627282.48	216761.37	-6.21	WB
10798	3627282.59	216764.27	-6.20	WB
10799	3627282.72	216767.26	-6.18	WB
10800	3627282.85	216770.16	-6.17	WB
10801	3627282.99	216773.03	-6.15	WB
10802	3627283.09	216775.19	-6.14	WB
10803	3627283.12	216775.92	-6.13	WB
10804	3627283.22	216778.79	-6.11	WB
10805	3627283.31	216781.67	-6.10	WB
10806	3627283.38	216784.53	-6.09	WB
10807	3627283.43	216787.39	-6.07	WB
10808	3627283.49	216790.25	-6.06	WB
10809	3627283.53	216793.07	-6.05	WB
10810	3627283.57	216795.89	-6.04	WB
10811	3627283.55	216798.73	-6.02	WB
10812	3627283.54	216799.84	-6.01	WB
10813	3627283.52	216801.62	-6.00	WB
10814	3627283.46	216804.47	-5.99	WB
10815	3627283.35	216807.44	-5.98	WB
10816	3627283.23	216810.47	-5.97	WB
10817	3627283.04	216813.62	-5.96	WB
10818	3627282.84	216816.86	-5.96	WB
10819	3627282.63	216820.19	-5.95	WB
10820	3627282.41	216823.63	-5.94	WB
10821	3627282.31	216825.33	-5.92	WB
10822	3627282.21	216827.06	-5.91	WB
10823	3627282.06	216830.50	-5.90	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
10824	3627281.94	216833.91	-5.88	WB
10825	3627281.84	216837.23	-5.86	WB
10826	3627281.77	216840.47	-5.84	WB
10827	3627281.70	216843.69	-5.81	WB
10828	3627281.61	216846.74	-5.78	WB
10829	3627281.53	216849.52	-5.75	WB
10830	3627281.52	216849.88	-5.72	WB
10831	3627281.38	216852.90	-5.68	WB
10832	3627281.19	216855.87	-5.64	WB
10833	3627280.97	216858.96	-5.60	WB
10834	3627280.72	216861.97	-5.56	WB
10835	3627280.44	216865.00	-5.52	WB
10836	3627280.13	216868.10	-5.47	WB
10837	3627279.81	216871.19	-5.42	WB
10838	3627279.50	216874.28	-5.37	WB
10839	3627279.47	216874.66	-5.32	WB
10840	3627279.22	216877.43	-5.27	WB
10841	3627278.94	216880.59	-5.21	WB
10842	3627278.72	216883.72	-5.16	WB
10843	3627278.51	216886.85	-5.10	WB
10844	3627278.33	216889.95	-5.05	WB
10845	3627278.21	216893.00	-5.00	WB
10846	3627278.09	216896.08	-4.94	WB
10847	3627278.01	216899.00	-4.89	WB
10848	3627277.98	216900.10	-4.84	WB
10849	3627277.94	216901.94	-4.78	WB
10850	3627277.89	216904.88	-4.73	WB
10851	3627277.88	216907.69	-4.68	WB
10852	3627277.87	216910.57	-4.63	WB
10853	3627277.90	216913.31	-4.58	WB
10854	3627277.94	216916.06	-4.53	WB
10855	3627277.98	216918.83	-4.47	WB
10856	3627278.03	216921.52	-4.42	WB
10857	3627278.08	216924.20	-4.37	WB
10858	3627278.10	216925.19	-4.32	WB
10859	3627278.12	216926.84	-4.27	WB
10860	3627278.16	216929.49	-4.22	WB
10861	3627278.23	216932.14	-4.17	WB
10862	3627278.31	216934.78	-4.12	WB
10863	3627278.39	216937.44	-4.08	WB
10864	3627278.47	216940.23	-4.03	WB
10865	3627278.54	216942.99	-3.99	WB
10866	3627278.68	216945.86	-3.94	WB
10867	3627278.84	216948.74	-3.90	WB
10868	3627279.01	216951.62	-3.87	WB
10869	3627279.19	216954.59	-3.83	WB
10870	3627279.36	216957.61	-3.80	WB
10871	3627279.63	216960.74	-3.76	WB
10872	3627279.92	216963.78	-3.73	WB
10873	3627280.25	216967.00	-3.71	WB
10874	3627280.60	216970.11	-3.68	WB
10875	3627280.96	216973.25	-3.66	WB
10876	3627281.28	216975.58	-3.63	WB
10877	3627281.39	216976.42	-3.61	WB
10878	3627281.83	216979.46	-3.59	WB
10879	3627282.28	216982.54	-3.57	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
10880	3627282.74	216985.51	-3.56	WB
10881	3627283.19	216988.41	-3.56	WB
10882	3627283.57	216991.30	-3.56	WB
10883	3627283.96	216994.15	-3.57	WB
10884	3627284.29	216996.92	-3.59	WB
10885	3627284.59	216999.78	-3.60	WB
10886	3627284.63	217000.11	-3.61	WB
10887	3627284.87	217002.61	-3.66	WB
10888	3627284.99	217005.39	-3.67	WB
10889	3627285.10	217008.18	-3.72	WB
10890	3627285.21	217011.00	-3.78	WB
10891	3627285.31	217013.80	-3.84	WB
10892	3627285.41	217016.65	-3.94	WB
10893	3627285.45	217019.48	-4.08	WB
10894	3627285.50	217022.34	-4.26	WB
10895	3627285.52	217025.39	-4.46	WB
10896	3627285.53	217028.39	-4.64	WB
10897	3627285.53	217031.53	-4.81	WB
10898	3627285.49	217034.78	-4.99	WB
10899	3627285.44	217037.97	-5.17	WB
10900	3627285.29	217041.36	-5.33	WB
10901	3627285.12	217044.69	-5.46	WB
10902	3627284.97	217047.90	-5.54	WB
10903	3627284.86	217049.92	-5.60	WB
10904	3627284.80	217051.09	-5.64	WB
10905	3627284.63	217054.22	-5.69	WB
10906	3627284.35	217057.09	-5.77	WB
10907	3627284.05	217059.92	-5.80	WB
10908	3627283.78	217062.62	-5.82	WB
10909	3627283.51	217065.19	-5.83	WB
10910	3627283.24	217067.79	-5.84	WB
10911	3627282.95	217070.29	-5.84	WB
10912	3627282.63	217072.81	-5.83	WB
10913	3627282.41	217074.40	-5.80	WB
10914	3627282.26	217075.36	-5.76	WB
10915	3627281.85	217077.94	-5.69	WB
10916	3627281.43	217080.54	-5.63	WB
10917	3627281.05	217083.24	-5.57	WB
10918	3627280.67	217085.86	-5.50	WB
10919	3627280.36	217088.49	-5.42	WB
10920	3627280.10	217091.12	-5.37	WB
10921	3627279.88	217093.62	-5.32	WB
10922	3627279.78	217096.05	-5.29	WB
10923	3627279.69	217098.42	-5.27	WB
10924	3627279.66	217100.13	-5.24	WB
10925	3627279.66	217100.65	-5.23	WB
10926	3627279.64	217102.87	-5.23	WB
10927	3627279.63	217105.06	-5.23	WB
10928	3627279.60	217107.28	-5.22	WB
10929	3627279.55	217109.51	-5.19	WB
10930	3627279.49	217111.94	-5.15	WB
10931	3627279.41	217114.42	-5.10	WB
10932	3627279.33	217117.00	-5.05	WB
10933	3627279.26	217119.69	-5.00	WB
10934	3627279.20	217122.37	-4.94	WB
10935	3627279.24	217125.04	-4.89	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
10936	3627279.25	217125.67	-4.84	WB
10937	3627279.30	217127.68	-4.78	WB
10938	3627279.40	217130.20	-4.73	WB
10939	3627279.55	217132.69	-4.67	WB
10940	3627279.69	217135.11	-4.60	WB
10941	3627279.77	217137.46	-4.54	WB
10942	3627279.85	217139.89	-4.48	WB
10943	3627279.88	217142.26	-4.42	WB
10944	3627279.88	217144.67	-4.35	WB
10945	3627279.88	217147.04	-4.29	WB
10946	3627279.89	217149.33	-4.22	WB
10947	3627279.89	217150.26	-4.15	WB
10948	3627279.90	217151.71	-4.09	WB
10949	3627279.93	217153.86	-4.02	WB
10950	3627279.99	217155.97	-3.95	WB
10951	3627280.06	217158.00	-3.89	WB
10952	3627280.14	217159.82	-3.82	WB
10953	3627280.23	217161.67	-3.75	WB
10954	3627280.31	217163.43	-3.69	WB
10955	3627280.39	217165.16	-3.61	WB
10956	3627280.44	217166.90	-3.54	WB
10957	3627280.46	217168.64	-3.47	WB
10958	3627280.48	217170.40	-3.41	WB
10959	3627280.53	217172.14	-3.30	WB
10960	3627280.58	217173.89	-3.24	WB
10961	3627280.60	217174.77	-3.14	WB
10962	3627280.62	217175.62	-3.12	WB
10963	3627280.65	217177.38	-3.03	WB
10964	3627280.67	217179.08	-3.03	WB
10965	3626789.72	215699.63	-8.97	WB
10966	3626788.78	215702.92	-8.96	WB
10967	3626787.94	215705.83	-8.95	WB
10968	3626787.82	215706.22	-8.94	WB
10969	3626786.88	215709.51	-8.93	WB
10970	3626785.95	215712.77	-8.92	WB
10971	3626785.04	215716.03	-8.91	WB
10972	3626784.24	215719.16	-8.89	WB
10973	3626783.42	215722.29	-8.89	WB
10974	3626782.63	215725.49	-8.88	WB
10975	3626781.87	215728.53	-8.88	WB
10976	3626781.16	215731.56	-8.87	WB
10977	3626780.57	215734.69	-8.87	WB
10978	3626780.00	215737.76	-8.87	WB
10979	3626779.52	215740.78	-8.87	WB
10980	3626779.06	215743.84	-8.87	WB
10981	3626778.69	215746.82	-8.86	WB
10982	3626778.45	215749.78	-8.86	WB
10983	3626778.23	215752.75	-8.86	WB
10984	3626778.17	215755.60	-8.86	WB
10985	3626778.15	215756.72	-8.86	WB
10986	3626778.12	215758.48	-8.86	WB
10987	3626778.07	215761.46	-8.86	WB
10988	3626778.00	215764.39	-8.85	WB
10989	3626777.93	215767.40	-8.85	WB
10990	3626777.84	215770.53	-8.85	WB
10991	3626777.75	215773.60	-8.85	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
10992	3626777.65	215776.66	-8.85	WB
10993	3626777.53	215779.81	-8.85	WB
10994	3626777.45	215782.11	-8.85	WB
10995	3626777.43	215782.89	-8.85	WB
10996	3626777.45	215785.87	-8.85	WB
10997	3626777.48	215788.87	-8.84	WB
10998	3626777.55	215791.78	-8.84	WB
10999	3626777.64	215794.76	-8.84	WB
11000	3626777.74	215797.77	-8.84	WB
11001	3626777.88	215800.81	-8.84	WB
11002	3626778.04	215803.82	-8.84	WB
11003	3626778.22	215806.95	-8.83	WB
11004	3626778.41	215810.02	-8.83	WB
11005	3626778.59	215813.09	-8.83	WB
11006	3626778.76	215816.39	-8.82	WB
11007	3626778.94	215819.64	-8.82	WB
11008	3626779.08	215822.90	-8.81	WB
11009	3626779.21	215826.30	-8.81	WB
11010	3626779.30	215829.70	-8.80	WB
11011	3626779.32	215831.84	-8.80	WB
11012	3626779.34	215833.07	-8.79	WB
11013	3626779.37	215836.54	-8.79	WB
11014	3626779.36	215839.90	-8.78	WB
11015	3626779.34	215843.20	-8.77	WB
11016	3626779.34	215846.48	-8.76	WB
11017	3626779.34	215849.68	-8.76	WB
11018	3626779.36	215852.76	-8.75	WB
11019	3626779.35	215855.64	-8.74	WB
11020	3626779.35	215856.82	-8.74	WB
11021	3626779.35	215858.59	-8.73	WB
11022	3626779.38	215861.41	-8.72	WB
11023	3626779.46	215864.16	-8.71	WB
11024	3626779.53	215866.89	-8.71	WB
11025	3626779.58	215869.59	-8.70	WB
11026	3626779.62	215872.40	-8.69	WB
11027	3626779.64	215875.20	-8.69	WB
11028	3626779.62	215878.02	-8.68	WB
11029	3626779.60	215880.97	-8.67	WB
11030	3626779.59	215881.67	-8.67	WB
11031	3626779.55	215883.91	-8.66	WB
11032	3626779.49	215886.86	-8.66	WB
11033	3626779.43	215889.78	-8.66	WB
11034	3626779.36	215892.75	-8.65	WB
11035	3626779.31	215895.76	-8.65	WB
11036	3626779.34	215898.80	-8.65	WB
11037	3626779.36	215901.74	-8.64	WB
11038	3626779.39	215904.76	-8.64	WB
11039	3626779.42	215906.73	-8.64	WB
11040	3626779.43	215907.88	-8.64	WB
11041	3626779.45	215910.94	-8.63	WB
11042	3626779.47	215914.20	-8.63	WB
11043	3626779.49	215917.42	-8.63	WB
11044	3626779.50	215920.79	-8.63	WB
11045	3626779.52	215924.31	-8.63	WB
11046	3626779.52	215927.84	-8.62	WB
11047	3626779.54	215931.44	-8.62	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
11048	3626779.54	215932.41	-8.62	WB
11049	3626779.56	215935.13	-8.61	WB
11050	3626779.69	215938.78	-8.61	WB
11051	3626779.85	215942.39	-8.61	WB
11052	3626780.03	215945.96	-8.60	WB
11053	3626780.22	215949.47	-8.60	WB
11054	3626780.44	215952.90	-8.59	WB
11055	3626780.75	215956.15	-8.59	WB
11056	3626780.88	215957.41	-8.58	WB
11057	3626781.09	215959.42	-8.58	WB
11058	3626781.47	215962.41	-8.57	WB
11059	3626781.91	215965.40	-8.57	WB
11060	3626782.33	215968.37	-8.56	WB
11061	3626782.69	215971.13	-8.55	WB
11062	3626783.05	215974.01	-8.55	WB
11063	3626783.36	215976.75	-8.54	WB
11064	3626783.65	215979.45	-8.54	WB
11065	3626783.88	215981.53	-8.53	WB
11066	3626783.95	215982.26	-8.53	WB
11067	3626784.19	215984.99	-8.53	WB
11068	3626784.43	215987.74	-8.52	WB
11069	3626784.65	215990.48	-8.52	WB
11070	3626784.87	215993.24	-8.52	WB
11071	3626785.11	215995.98	-8.52	WB
11072	3626785.40	215998.71	-8.52	WB
11073	3626785.69	216001.43	-8.52	WB
11074	3626785.88	216004.23	-8.52	WB
11075	3626786.02	216006.70	-8.52	WB
11076	3626786.04	216007.07	-8.52	WB
11077	3626786.19	216009.85	-8.53	WB
11078	3626786.31	216012.83	-8.53	WB
11079	3626786.44	216015.83	-8.53	WB
11080	3626786.32	216018.93	-8.54	WB
11081	3626786.18	216022.14	-8.54	WB
11082	3626785.98	216025.38	-8.55	WB
11083	3626785.72	216028.64	-8.55	WB
11084	3626785.53	216031.16	-8.55	WB
11085	3626785.46	216031.96	-8.56	WB
11086	3626784.96	216035.37	-8.56	WB
11087	3626784.45	216038.75	-8.56	WB
11088	3626783.81	216042.33	-8.57	WB
11089	3626783.11	216045.85	-8.57	WB
11090	3626782.40	216049.30	-8.57	WB
11091	3626781.55	216052.82	-8.57	WB
11092	3626780.79	216055.94	-8.57	WB
11093	3626780.68	216056.41	-8.57	WB
11094	3626779.84	216059.81	-8.56	WB
11095	3626778.99	216063.22	-8.56	WB
11096	3626778.09	216066.67	-8.56	WB
11097	3626777.17	216069.84	-8.55	WB
11098	3626776.20	216073.13	-8.55	WB
11099	3626775.37	216076.30	-8.54	WB
11100	3626774.61	216079.34	-8.53	WB
11101	3626774.11	216081.28	-8.52	WB
11102	3626773.87	216082.44	-8.51	WB
11103	3626773.28	216085.49	-8.50	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
11104	3626772.70	216088.50	-8.50	WB
11105	3626772.33	216091.58	-8.49	WB
11106	3626772.02	216094.60	-8.47	WB
11107	3626771.81	216097.66	-8.46	WB
11108	3626771.74	216100.74	-8.45	WB
11109	3626771.68	216103.83	-8.44	WB
11110	3626771.82	216106.89	-8.43	WB
11111	3626771.86	216107.67	-8.42	WB
11112	3626771.98	216109.96	-8.41	WB
11113	3626772.25	216112.97	-8.40	WB
11114	3626772.63	216115.88	-8.39	WB
11115	3626773.03	216118.82	-8.38	WB
11116	3626773.51	216121.62	-8.37	WB
11117	3626774.00	216124.44	-8.37	WB
11118	3626774.58	216127.28	-8.36	WB
11119	3626775.20	216129.96	-8.35	WB
11120	3626775.84	216132.69	-8.34	WB
11121	3626776.49	216135.41	-8.33	WB
11122	3626777.14	216138.09	-8.33	WB
11123	3626777.79	216140.89	-8.32	WB
11124	3626778.42	216143.67	-8.31	WB
11125	3626779.03	216146.47	-8.31	WB
11126	3626779.54	216149.46	-8.30	WB
11127	3626780.06	216152.39	-8.29	WB
11128	3626780.57	216155.32	-8.29	WB
11129	3626780.98	216157.53	-8.28	WB
11130	3626781.12	216158.28	-8.27	WB
11131	3626781.68	216161.18	-8.27	WB
11132	3626782.28	216164.01	-8.26	WB
11133	3626782.88	216166.85	-8.25	WB
11134	3626783.38	216169.70	-8.25	WB
11135	3626783.83	216172.57	-8.24	WB
11136	3626784.22	216175.51	-8.23	WB
11137	3626784.48	216178.36	-8.23	WB
11138	3626784.74	216181.26	-8.22	WB
11139	3626784.77	216181.61	-8.21	WB
11140	3626784.87	216184.17	-8.21	WB
11141	3626784.98	216186.98	-8.20	WB
11142	3626785.09	216189.79	-8.19	WB
11143	3626785.17	216192.46	-8.19	WB
11144	3626785.26	216195.10	-8.18	WB
11145	3626785.16	216197.78	-8.17	WB
11146	3626785.04	216200.44	-8.17	WB
11147	3626784.82	216203.15	-8.16	WB
11148	3626784.51	216206.00	-8.16	WB
11149	3626784.48	216206.34	-8.15	WB
11150	3626784.19	216208.85	-8.14	WB
11151	3626783.79	216211.82	-8.14	WB
11152	3626783.40	216214.79	-8.13	WB
11153	3626783.01	216217.83	-8.13	WB
11154	3626782.64	216220.84	-8.12	WB
11155	3626782.27	216223.93	-8.12	WB
11156	3626781.95	216226.95	-8.11	WB
11157	3626781.64	216229.97	-8.11	WB
11158	3626781.52	216231.09	-8.10	WB
11159	3626781.30	216233.02	-8.10	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
11160	3626780.97	216235.98	-8.09	WB
11161	3626780.61	216239.02	-8.08	WB
11162	3626780.20	216242.23	-8.08	WB
11163	3626779.77	216245.37	-8.07	WB
11164	3626779.20	216248.80	-8.07	WB
11165	3626778.60	216252.26	-8.06	WB
11166	3626778.01	216255.76	-8.06	WB
11167	3626777.87	216256.70	-8.05	WB
11168	3626777.45	216259.51	-8.04	WB
11169	3626776.91	216263.20	-8.03	WB
11170	3626776.40	216266.85	-8.03	WB
11171	3626775.91	216270.54	-8.02	WB
11172	3626775.55	216273.98	-8.01	WB
11173	3626775.33	216277.29	-8.00	WB
11174	3626775.13	216280.56	-7.99	WB
11175	3626775.10	216281.68	-7.98	WB
11176	3626775.05	216283.55	-7.97	WB
11177	3626774.97	216286.53	-7.96	WB
11178	3626774.94	216289.45	-7.95	WB
11179	3626774.95	216292.31	-7.94	WB
11180	3626774.94	216295.18	-7.93	WB
11181	3626774.97	216298.13	-7.92	WB
11182	3626775.00	216301.01	-7.91	WB
11183	3626775.11	216303.98	-7.90	WB
11184	3626775.28	216307.03	-7.89	WB
11185	3626775.47	216310.05	-7.88	WB
11186	3626775.76	216313.21	-7.87	WB
11187	3626776.05	216316.32	-7.86	WB
11188	3626776.38	216319.40	-7.85	WB
11189	3626776.74	216322.60	-7.84	WB
11190	3626777.11	216325.73	-7.83	WB
11191	3626777.47	216328.81	-7.82	WB
11192	3626777.84	216331.98	-7.81	WB
11193	3626777.89	216332.35	-7.80	WB
11194	3626778.28	216335.11	-7.80	WB
11195	3626778.72	216338.19	-7.79	WB
11196	3626779.17	216341.22	-7.78	WB
11197	3626779.62	216344.18	-7.77	WB
11198	3626780.06	216347.13	-7.77	WB
11199	3626780.49	216350.07	-7.76	WB
11200	3626780.92	216353.02	-7.75	WB
11201	3626781.32	216355.96	-7.75	WB
11202	3626781.46	216357.04	-7.74	WB
11203	3626781.71	216358.92	-7.73	WB
11204	3626782.09	216361.80	-7.73	WB
11205	3626782.52	216364.66	-7.72	WB
11206	3626782.96	216367.56	-7.72	WB
11207	3626783.38	216370.39	-7.71	WB
11208	3626783.80	216373.30	-7.70	WB
11209	3626784.21	216376.18	-7.70	WB
11210	3626784.53	216379.10	-7.69	WB
11211	3626784.86	216382.09	-7.68	WB
11212	3626785.16	216385.07	-7.68	WB
11213	3626785.43	216388.06	-7.67	WB
11214	3626785.70	216391.13	-7.67	WB
11215	3626785.85	216394.18	-7.66	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
11216	3626786.01	216397.21	-7.65	WB
11217	3626786.11	216400.14	-7.64	WB
11218	3626786.20	216403.07	-7.64	WB
11219	3626786.23	216405.97	-7.63	WB
11220	3626786.21	216406.35	-7.62	WB
11221	3626786.10	216408.83	-7.61	WB
11222	3626785.96	216411.76	-7.60	WB
11223	3626785.76	216414.64	-7.60	WB
11224	3626785.52	216417.63	-7.59	WB
11225	3626785.18	216420.63	-7.58	WB
11226	3626784.71	216423.64	-7.57	WB
11227	3626784.19	216426.79	-7.56	WB
11228	3626783.63	216429.93	-7.55	WB
11229	3626783.43	216431.09	-7.54	WB
11230	3626783.09	216432.98	-7.53	WB
11231	3626782.55	216436.05	-7.53	WB
11232	3626782.05	216439.03	-7.52	WB
11233	3626781.55	216442.00	-7.51	WB
11234	3626781.17	216444.78	-7.50	WB
11235	3626780.80	216447.55	-7.49	WB
11236	3626780.43	216450.28	-7.48	WB
11237	3626780.05	216453.09	-7.48	WB
11238	3626779.67	216455.87	-7.47	WB
11239	3626779.56	216456.60	-7.46	WB
11240	3626779.26	216458.74	-7.46	WB
11241	3626778.81	216461.76	-7.45	WB
11242	3626778.41	216464.78	-7.44	WB
11243	3626778.03	216467.86	-7.43	WB
11244	3626777.67	216471.11	-7.43	WB
11245	3626777.46	216474.28	-7.42	WB
11246	3626777.25	216477.45	-7.41	WB
11247	3626777.14	216480.86	-7.41	WB
11248	3626777.11	216482.49	-7.40	WB
11249	3626777.07	216484.11	-7.39	WB
11250	3626777.03	216487.42	-7.38	WB
11251	3626777.07	216490.78	-7.37	WB
11252	3626777.11	216494.04	-7.37	WB
11253	3626777.23	216497.34	-7.36	WB
11254	3626777.38	216500.68	-7.35	WB
11255	3626777.57	216503.92	-7.34	WB
11256	3626777.87	216507.27	-7.33	WB
11257	3626778.15	216510.56	-7.32	WB
11258	3626778.46	216513.77	-7.31	WB
11259	3626778.78	216517.06	-7.30	WB
11260	3626779.14	216520.22	-7.29	WB
11261	3626779.57	216523.29	-7.27	WB
11262	3626780.01	216526.44	-7.26	WB
11263	3626780.45	216529.43	-7.25	WB
11264	3626780.83	216532.01	-7.24	WB
11265	3626780.89	216532.36	-7.22	WB
11266	3626781.31	216535.33	-7.21	WB
11267	3626781.73	216538.22	-7.20	WB
11268	3626782.13	216541.10	-7.19	WB
11269	3626782.47	216543.88	-7.17	WB
11270	3626782.80	216546.61	-7.16	WB
11271	3626783.11	216549.27	-7.15	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
11272	3626783.42	216551.89	-7.14	WB
11273	3626783.71	216554.50	-7.13	WB
11274	3626783.91	216556.77	-7.12	WB
11275	3626783.93	216557.08	-7.11	WB
11276	3626784.15	216559.67	-7.10	WB
11277	3626784.27	216562.32	-7.09	WB
11278	3626784.35	216564.99	-7.08	WB
11279	3626784.41	216567.71	-7.07	WB
11280	3626784.43	216570.41	-7.06	WB
11281	3626784.44	216573.15	-7.06	WB
11282	3626784.37	216576.02	-7.05	WB
11283	3626784.28	216578.80	-7.04	WB
11284	3626784.19	216581.63	-7.04	WB
11285	3626784.07	216584.66	-7.03	WB
11286	3626783.95	216587.65	-7.03	WB
11287	3626783.78	216590.76	-7.02	WB
11288	3626783.61	216593.89	-7.02	WB
11289	3626783.41	216597.09	-7.01	WB
11290	3626783.19	216600.37	-7.01	WB
11291	3626782.99	216603.63	-7.00	WB
11292	3626782.85	216606.45	-7.00	WB
11293	3626782.83	216606.89	-6.99	WB
11294	3626782.68	216610.19	-6.99	WB
11295	3626782.52	216613.56	-6.98	WB
11296	3626782.36	216616.78	-6.98	WB
11297	3626782.20	216620.05	-6.97	WB
11298	3626782.02	216623.44	-6.96	WB
11299	3626781.84	216626.75	-6.96	WB
11300	3626781.55	216630.15	-6.95	WB
11301	3626781.43	216631.42	-6.94	WB
11302	3626781.21	216633.54	-6.93	WB
11303	3626780.85	216636.93	-6.92	WB
11304	3626780.47	216640.42	-6.91	WB
11305	3626780.09	216643.86	-6.90	WB
11306	3626779.69	216647.24	-6.89	WB
11307	3626779.27	216650.71	-6.88	WB
11308	3626778.87	216654.10	-6.87	WB
11309	3626778.62	216656.59	-6.86	WB
11310	3626778.54	216657.37	-6.85	WB
11311	3626778.22	216660.63	-6.84	WB
11312	3626777.97	216663.67	-6.83	WB
11313	3626777.76	216666.62	-6.81	WB
11314	3626777.61	216669.48	-6.80	WB
11315	3626777.58	216672.28	-6.79	WB
11316	3626777.55	216675.07	-6.78	WB
11317	3626777.51	216677.83	-6.77	WB
11318	3626777.46	216680.50	-6.76	WB
11319	3626777.44	216681.88	-6.75	WB
11320	3626777.43	216683.22	-6.74	WB
11321	3626777.43	216685.97	-6.73	WB
11322	3626777.42	216688.62	-6.72	WB
11323	3626777.39	216691.47	-6.72	WB
11324	3626777.35	216694.19	-6.71	WB
11325	3626777.32	216696.93	-6.70	WB
11326	3626777.30	216699.81	-6.70	WB
11327	3626777.29	216702.54	-6.69	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
11328	3626777.34	216705.43	-6.69	WB
11329	3626777.37	216706.84	-6.68	WB
11330	3626777.40	216708.28	-6.68	WB
11331	3626777.44	216711.18	-6.68	WB
11332	3626777.49	216714.25	-6.67	WB
11333	3626777.53	216717.28	-6.67	WB
11334	3626777.57	216720.40	-6.67	WB
11335	3626777.63	216723.60	-6.67	WB
11336	3626777.67	216726.83	-6.67	WB
11337	3626777.70	216730.08	-6.67	WB
11338	3626777.72	216731.73	-6.67	WB
11339	3626777.71	216733.37	-6.67	WB
11340	3626777.67	216736.67	-6.67	WB
11341	3626777.62	216740.00	-6.67	WB
11342	3626777.60	216743.37	-6.67	WB
11343	3626777.60	216746.66	-6.67	WB
11344	3626777.55	216750.05	-6.66	WB
11345	3626777.41	216753.39	-6.64	WB
11346	3626777.28	216756.34	-6.63	WB
11347	3626777.26	216756.74	-6.60	WB
11348	3626777.10	216760.16	-6.58	WB
11349	3626776.92	216763.56	-6.55	WB
11350	3626776.71	216766.95	-6.52	WB
11351	3626776.43	216770.48	-6.50	WB
11352	3626776.16	216773.90	-6.47	WB
11353	3626775.91	216777.36	-6.44	WB
11354	3626775.65	216780.84	-6.41	WB
11355	3626775.59	216781.65	-6.38	WB
11356	3626775.41	216784.11	-6.34	WB
11357	3626775.18	216787.39	-6.31	WB
11358	3626774.97	216790.59	-6.27	WB
11359	3626774.82	216793.49	-6.24	WB
11360	3626774.68	216796.46	-6.20	WB
11361	3626774.62	216799.27	-6.16	WB
11362	3626774.61	216801.97	-6.13	WB
11363	3626774.58	216804.78	-6.09	WB
11364	3626774.56	216806.82	-6.06	WB
11365	3626774.55	216807.51	-6.03	WB
11366	3626774.50	216810.26	-5.99	WB
11367	3626774.54	216813.04	-5.96	WB
11368	3626774.63	216815.83	-5.93	WB
11369	3626774.73	216818.64	-5.91	WB
11370	3626774.91	216821.53	-5.88	WB
11371	3626775.09	216824.42	-5.85	WB
11372	3626775.35	216827.37	-5.83	WB
11373	3626775.65	216830.41	-5.80	WB
11374	3626775.88	216832.67	-5.78	WB
11375	3626775.97	216833.41	-5.75	WB
11376	3626776.34	216836.53	-5.73	WB
11377	3626776.72	216839.69	-5.70	WB
11378	3626777.11	216842.87	-5.68	WB
11379	3626777.53	216846.23	-5.65	WB
11380	3626777.96	216849.51	-5.62	WB
11381	3626778.41	216852.79	-5.59	WB
11382	3626778.88	216856.21	-5.56	WB
11383	3626779.03	216857.40	-5.53	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
11384	3626779.30	216859.48	-5.49	WB
11385	3626779.72	216862.74	-5.45	WB
11386	3626780.17	216866.02	-5.41	WB
11387	3626780.62	216869.14	-5.37	WB
11388	3626781.06	216872.39	-5.32	WB
11389	3626781.39	216875.50	-5.28	WB
11390	3626781.69	216878.58	-5.23	WB
11391	3626781.99	216881.65	-5.19	WB
11392	3626782.02	216882.01	-5.14	WB
11393	3626782.27	216884.67	-5.09	WB
11394	3626782.54	216887.65	-5.04	WB
11395	3626782.75	216890.65	-4.99	WB
11396	3626782.95	216893.71	-4.95	WB
11397	3626783.08	216896.67	-4.90	WB
11398	3626783.19	216899.69	-4.86	WB
11399	3626783.31	216902.76	-4.82	WB
11400	3626783.41	216905.78	-4.77	WB
11401	3626783.45	216906.97	-4.72	WB
11402	3626783.53	216908.93	-4.68	WB
11403	3626783.53	216912.06	-4.64	WB
11404	3626783.52	216915.26	-4.60	WB
11405	3626783.49	216918.51	-4.57	WB
11406	3626783.43	216921.69	-4.54	WB
11407	3626783.38	216924.94	-4.52	WB
11408	3626783.26	216928.04	-4.50	WB
11409	3626783.14	216931.10	-4.47	WB
11410	3626783.12	216931.52	-4.43	WB
11411	3626782.93	216934.21	-4.40	WB
11412	3626782.62	216937.22	-4.36	WB
11413	3626782.30	216940.20	-4.30	WB
11414	3626781.95	216943.14	-4.26	WB
11415	3626781.59	216946.00	-4.19	WB
11416	3626781.20	216948.88	-4.12	WB
11417	3626780.78	216951.75	-4.07	WB
11418	3626780.36	216954.55	-4.02	WB
11419	3626780.12	216956.30	-3.99	WB
11420	3626779.96	216957.35	-3.94	WB
11421	3626779.55	216960.17	-3.90	WB
11422	3626779.22	216962.96	-3.87	WB
11423	3626778.95	216965.78	-3.86	WB
11424	3626778.70	216968.64	-3.83	WB
11425	3626778.56	216971.36	-3.81	WB
11426	3626778.43	216974.10	-3.80	WB
11427	3626778.47	216976.80	-3.79	WB
11428	3626778.59	216979.35	-3.78	WB
11429	3626778.73	216981.97	-3.79	WB
11430	3626778.91	216984.49	-3.80	WB
11431	3626779.10	216986.98	-3.88	WB
11432	3626779.28	216989.49	-3.89	WB
11433	3626779.46	216991.90	-3.93	WB
11434	3626779.65	216994.31	-3.99	WB
11435	3626779.83	216996.70	-4.04	WB
11436	3626780.02	216999.04	-4.10	WB
11437	3626780.12	217001.38	-4.17	WB
11438	3626780.20	217003.76	-4.22	WB
11439	3626780.20	217006.15	-4.31	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
11440	3626780.19	217006.48	-4.33	WB
11441	3626780.10	217008.68	-4.44	WB
11442	3626779.99	217011.20	-4.54	WB
11443	3626779.77	217013.99	-4.67	WB
11444	3626779.54	217016.79	-4.82	WB
11445	3626779.25	217019.78	-5.00	WB
11446	3626778.92	217022.95	-5.19	WB
11447	3626778.59	217026.10	-5.39	WB
11448	3626778.23	217029.58	-5.57	WB
11449	3626778.01	217031.75	-5.73	WB
11450	3626777.87	217033.04	-5.86	WB
11451	3626777.51	217036.68	-6.00	WB
11452	3626777.17	217040.26	-6.11	WB
11453	3626776.84	217043.89	-6.17	WB
11454	3626776.52	217047.60	-6.20	WB
11455	3626776.22	217051.17	-6.21	WB
11456	3626775.95	217054.82	-6.20	WB
11457	3626775.82	217056.64	-6.16	WB
11458	3626775.69	217058.39	-6.11	WB
11459	3626775.44	217061.85	-6.04	WB
11460	3626775.15	217065.45	-5.94	WB
11461	3626774.87	217068.89	-5.87	WB
11462	3626774.50	217072.41	-5.80	WB
11463	3626774.11	217075.83	-5.77	WB
11464	3626773.74	217079.15	-5.73	WB
11465	3626773.46	217081.69	-5.71	WB
11466	3626773.36	217082.53	-5.71	WB
11467	3626772.98	217085.87	-5.70	WB
11468	3626772.66	217089.07	-5.69	WB
11469	3626772.32	217092.36	-5.68	WB
11470	3626772.04	217095.60	-5.63	WB
11471	3626771.83	217098.76	-5.57	WB
11472	3626771.62	217101.92	-5.46	WB
11473	3626771.57	217104.93	-5.34	WB
11474	3626771.52	217107.25	-5.23	WB
11475	3626771.51	217107.98	-5.12	WB
11476	3626771.55	217110.94	-5.03	WB
11477	3626771.68	217113.85	-4.94	WB
11478	3626771.84	217116.70	-4.86	WB
11479	3626772.10	217119.41	-4.78	WB
11480	3626772.37	217122.08	-4.71	WB
11481	3626772.72	217124.66	-4.62	WB
11482	3626773.11	217127.21	-4.54	WB
11483	3626773.51	217129.75	-4.47	WB
11484	3626773.98	217132.35	-4.40	WB
11485	3626774.44	217134.86	-4.33	WB
11486	3626774.94	217137.53	-4.27	WB
11487	3626775.46	217140.27	-4.21	WB
11488	3626775.97	217142.95	-4.15	WB
11489	3626776.50	217145.83	-4.10	WB
11490	3626777.00	217148.57	-4.05	WB
11491	3626777.55	217151.44	-3.99	WB
11492	3626778.11	217154.38	-3.94	WB
11493	3626778.64	217157.27	-3.89	WB
11494	3626778.72	217157.67	-3.83	WB
11495	3626779.19	217160.30	-3.78	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
11496	3626779.72	217163.28	-3.72	WB
11497	3626780.20	217166.27	-3.68	WB
11498	3626780.69	217169.34	-3.63	WB
11499	3626781.13	217172.40	-3.58	WB
11500	3626781.55	217175.51	-3.54	WB
11501	3626781.99	217178.73	-3.48	WB
11502	3626782.28	217181.87	-3.41	WB
11503	3626782.36	217182.68	-3.33	WB
11504	3626782.60	217185.08	-3.26	WB
11505	3626782.86	217188.16	-3.20	WB
11506	3626783.10	217191.15	-3.14	WB
11507	3626283.55	215711.83	-9.04	WB
11508	3626283.68	215714.21	-9.03	WB
11509	3626283.73	215715.11	-9.02	WB
11510	3626283.83	215716.65	-9.01	WB
11511	3626283.93	215719.04	-9.00	WB
11512	3626284.00	215721.40	-8.99	WB
11513	3626284.06	215723.83	-8.98	WB
11514	3626284.06	215726.34	-8.98	WB
11515	3626284.05	215728.81	-8.97	WB
11516	3626283.92	215731.41	-8.97	WB
11517	3626283.73	215734.09	-8.96	WB
11518	3626283.53	215736.73	-8.95	WB
11519	3626283.29	215739.45	-8.95	WB
11520	3626283.04	215742.21	-8.94	WB
11521	3626282.76	215744.87	-8.94	WB
11522	3626282.47	215747.52	-8.93	WB
11523	3626282.17	215750.27	-8.93	WB
11524	3626281.85	215753.04	-8.93	WB
11525	3626281.55	215755.80	-8.92	WB
11526	3626281.30	215758.52	-8.92	WB
11527	3626281.06	215761.25	-8.92	WB
11528	3626280.84	215764.01	-8.92	WB
11529	3626280.79	215764.72	-8.92	WB
11530	3626280.63	215766.81	-8.91	WB
11531	3626280.41	215769.61	-8.91	WB
11532	3626280.04	215772.57	-8.91	WB
11533	3626279.65	215775.58	-8.91	WB
11534	3626279.27	215778.62	-8.91	WB
11535	3626278.88	215781.76	-8.90	WB
11536	3626278.47	215784.94	-8.90	WB
11537	3626277.96	215788.14	-8.90	WB
11538	3626277.70	215789.75	-8.89	WB
11539	3626277.44	215791.34	-8.89	WB
11540	3626276.98	215794.65	-8.89	WB
11541	3626276.58	215797.92	-8.88	WB
11542	3626276.18	215801.18	-8.87	WB
11543	3626275.76	215804.37	-8.87	WB
11544	3626275.36	215807.52	-8.86	WB
11545	3626275.09	215810.53	-8.85	WB
11546	3626274.88	215813.46	-8.84	WB
11547	3626274.78	215814.95	-8.84	WB
11548	3626274.69	215816.34	-8.83	WB
11549	3626274.52	215819.19	-8.82	WB
11550	3626274.34	215822.09	-8.81	WB
11551	3626274.19	215824.92	-8.80	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
11552	3626274.04	215827.77	-8.79	WB
11553	3626273.91	215830.67	-8.79	WB
11554	3626273.83	215833.53	-8.78	WB
11555	3626273.73	215836.49	-8.77	WB
11556	3626273.70	215839.40	-8.76	WB
11557	3626273.70	215840.10	-8.76	WB
11558	3626273.69	215842.28	-8.75	WB
11559	3626273.70	215845.25	-8.74	WB
11560	3626273.74	215848.11	-8.74	WB
11561	3626273.79	215850.92	-8.74	WB
11562	3626274.00	215853.66	-8.73	WB
11563	3626274.22	215856.36	-8.73	WB
11564	3626274.44	215859.15	-8.73	WB
11565	3626274.66	215861.96	-8.72	WB
11566	3626274.88	215864.78	-8.72	WB
11567	3626274.93	215865.53	-8.72	WB
11568	3626275.08	215867.74	-8.72	WB
11569	3626275.28	215870.69	-8.72	WB
11570	3626275.51	215873.74	-8.72	WB
11571	3626275.75	215876.83	-8.72	WB
11572	3626276.01	215879.98	-8.71	WB
11573	3626276.28	215883.14	-8.71	WB
11574	3626276.55	215886.31	-8.71	WB
11575	3626276.83	215889.63	-8.71	WB
11576	3626276.90	215890.43	-8.70	WB
11577	3626277.12	215892.96	-8.70	WB
11578	3626277.43	215896.22	-8.69	WB
11579	3626277.78	215899.47	-8.69	WB
11580	3626278.14	215902.65	-8.68	WB
11581	3626278.47	215905.61	-8.67	WB
11582	3626278.80	215908.53	-8.67	WB
11583	3626279.13	215911.40	-8.66	WB
11584	3626279.45	215914.00	-8.65	WB
11585	3626279.53	215914.72	-8.64	WB
11586	3626279.76	215916.68	-8.64	WB
11587	3626279.93	215919.32	-8.63	WB
11588	3626280.08	215921.91	-8.62	WB
11589	3626280.22	215924.63	-8.61	WB
11590	3626280.34	215927.25	-8.60	WB
11591	3626280.46	215929.88	-8.60	WB
11592	3626280.50	215932.61	-8.59	WB
11593	3626280.55	215935.29	-8.58	WB
11594	3626280.64	215937.92	-8.57	WB
11595	3626280.75	215939.94	-8.57	WB
11596	3626280.79	215940.62	-8.56	WB
11597	3626280.93	215943.28	-8.56	WB
11598	3626281.05	215946.06	-8.55	WB
11599	3626281.16	215948.85	-8.55	WB
11600	3626281.18	215951.78	-8.54	WB
11601	3626281.14	215954.75	-8.54	WB
11602	3626281.08	215957.75	-8.54	WB
11603	3626280.93	215960.93	-8.53	WB
11604	3626280.79	215964.11	-8.53	WB
11605	3626280.75	215964.91	-8.53	WB
11606	3626280.56	215967.37	-8.52	WB
11607	3626280.30	215970.60	-8.52	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
11608	3626280.03	215973.87	-8.52	WB
11609	3626279.73	215977.15	-8.51	WB
11610	3626279.45	215980.31	-8.51	WB
11611	3626279.17	215983.52	-8.51	WB
11612	3626278.88	215986.65	-8.50	WB
11613	3626278.59	215989.38	-8.50	WB
11614	3626278.54	215989.75	-8.49	WB
11615	3626278.07	215992.94	-8.48	WB
11616	3626277.60	215996.09	-8.48	WB
11617	3626277.14	215999.12	-8.47	WB
11618	3626276.67	216002.24	-8.47	WB
11619	3626276.22	216005.27	-8.46	WB
11620	3626275.77	216008.24	-8.45	WB
11621	3626275.32	216011.21	-8.45	WB
11622	3626274.84	216014.07	-8.44	WB
11623	3626274.37	216016.92	-8.43	WB
11624	3626273.89	216019.74	-8.43	WB
11625	3626273.40	216022.54	-8.42	WB
11626	3626272.92	216025.34	-8.41	WB
11627	3626272.28	216028.15	-8.41	WB
11628	3626271.65	216030.91	-8.40	WB
11629	3626271.00	216033.75	-8.40	WB
11630	3626270.34	216036.66	-8.39	WB
11631	3626269.67	216039.50	-8.39	WB
11632	3626268.93	216042.45	-8.39	WB
11633	3626268.16	216045.50	-8.38	WB
11634	3626267.49	216048.58	-8.38	WB
11635	3626266.87	216051.72	-8.38	WB
11636	3626266.29	216054.89	-8.37	WB
11637	3626265.87	216058.12	-8.37	WB
11638	3626265.46	216061.34	-8.37	WB
11639	3626265.19	216064.66	-8.37	WB
11640	3626265.14	216065.45	-8.36	WB
11641	3626264.98	216067.97	-8.36	WB
11642	3626264.85	216071.27	-8.36	WB
11643	3626264.88	216074.67	-8.35	WB
11644	3626264.92	216077.97	-8.35	WB
11645	3626265.16	216081.27	-8.34	WB
11646	3626265.45	216084.60	-8.34	WB
11647	3626265.87	216087.77	-8.33	WB
11648	3626266.52	216090.95	-8.32	WB
11649	3626266.68	216091.69	-8.32	WB
11650	3626267.16	216094.06	-8.31	WB
11651	3626268.04	216097.02	-8.30	WB
11652	3626268.96	216100.08	-8.29	WB
11653	3626269.93	216103.06	-8.28	WB
11654	3626270.95	216105.94	-8.27	WB
11655	3626272.02	216108.87	-8.26	WB
11656	3626273.20	216111.45	-8.26	WB
11657	3626274.37	216113.97	-8.25	WB
11658	3626275.60	216116.26	-8.24	WB
11659	3626275.90	216116.77	-8.23	WB
11660	3626276.86	216118.39	-8.22	WB
11661	3626278.12	216120.49	-8.21	WB
11662	3626279.33	216122.40	-8.21	WB
11663	3626280.55	216124.29	-8.20	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
11664	3626281.76	216126.15	-8.20	WB
11665	3626282.95	216128.02	-8.19	WB
11666	3626284.04	216129.88	-8.19	WB
11667	3626284.94	216131.89	-8.18	WB
11668	3626285.86	216133.98	-8.18	WB
11669	3626286.65	216136.14	-8.17	WB
11670	3626287.39	216138.30	-8.17	WB
11671	3626288.03	216140.35	-8.17	WB
11672	3626288.09	216140.65	-8.17	WB
11673	3626288.62	216143.23	-8.16	WB
11674	3626289.13	216145.85	-8.16	WB
11675	3626289.46	216148.89	-8.16	WB
11676	3626289.75	216152.03	-8.15	WB
11677	3626290.01	216155.23	-8.15	WB
11678	3626290.21	216158.57	-8.15	WB
11679	3626290.43	216161.90	-8.14	WB
11680	3626290.54	216165.19	-8.14	WB
11681	3626290.65	216168.67	-8.13	WB
11682	3626290.75	216171.94	-8.12	WB
11683	3626290.83	216175.18	-8.11	WB
11684	3626290.90	216178.48	-8.11	WB
11685	3626290.86	216181.45	-8.10	WB
11686	3626290.81	216184.52	-8.09	WB
11687	3626290.81	216187.34	-8.08	WB
11688	3626290.84	216189.38	-8.07	WB
11689	3626290.84	216190.03	-8.06	WB
11690	3626290.86	216192.83	-8.05	WB
11691	3626290.84	216195.41	-8.04	WB
11692	3626290.81	216197.99	-8.02	WB
11693	3626290.75	216200.62	-8.01	WB
11694	3626290.69	216203.22	-8.00	WB
11695	3626290.64	216205.80	-8.00	WB
11696	3626290.61	216208.36	-7.99	WB
11697	3626290.57	216210.91	-7.98	WB
11698	3626290.58	216213.50	-7.97	WB
11699	3626290.60	216214.79	-7.96	WB
11700	3626290.61	216216.12	-7.96	WB
11701	3626290.64	216218.75	-7.95	WB
11702	3626290.65	216221.51	-7.95	WB
11703	3626290.67	216224.31	-7.94	WB
11704	3626290.67	216227.25	-7.94	WB
11705	3626290.66	216230.27	-7.94	WB
11706	3626290.67	216233.43	-7.93	WB
11707	3626290.70	216236.63	-7.93	WB
11708	3626290.74	216239.94	-7.93	WB
11709	3626290.72	216243.40	-7.92	WB
11710	3626290.70	216246.81	-7.92	WB
11711	3626290.66	216250.36	-7.92	WB
11712	3626290.59	216253.87	-7.91	WB
11713	3626290.53	216257.31	-7.90	WB
11714	3626290.29	216260.71	-7.90	WB
11715	3626290.05	216264.03	-7.89	WB
11716	3626290.02	216264.43	-7.88	WB
11717	3626289.76	216267.14	-7.87	WB
11718	3626289.42	216270.28	-7.86	WB
11719	3626289.07	216273.39	-7.85	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
11720	3626288.62	216276.19	-7.84	WB
11721	3626288.15	216279.08	-7.83	WB
11722	3626287.69	216281.79	-7.82	WB
11723	3626287.25	216284.40	-7.81	WB
11724	3626286.78	216287.04	-7.79	WB
11725	3626286.42	216288.89	-7.78	WB
11726	3626286.30	216289.51	-7.77	WB
11727	3626285.81	216291.96	-7.76	WB
11728	3626285.29	216294.49	-7.75	WB
11729	3626284.76	216296.95	-7.74	WB
11730	3626284.24	216299.42	-7.73	WB
11731	3626283.70	216302.02	-7.72	WB
11732	3626283.17	216304.60	-7.71	WB
11733	3626282.69	216307.33	-7.70	WB
11734	3626282.23	216310.09	-7.69	WB
11735	3626281.84	216312.84	-7.69	WB
11736	3626281.65	216314.63	-7.68	WB
11737	3626281.54	216315.68	-7.68	WB
11738	3626281.26	216318.50	-7.67	WB
11739	3626281.11	216321.52	-7.67	WB
11740	3626280.96	216324.58	-7.67	WB
11741	3626280.74	216327.91	-7.67	WB
11742	3626280.47	216331.31	-7.66	WB
11743	3626280.19	216334.77	-7.66	WB
11744	3626279.91	216338.58	-7.66	WB
11745	3626279.78	216340.43	-7.66	WB
11746	3626279.64	216342.27	-7.65	WB
11747	3626279.40	216346.04	-7.65	WB
11748	3626279.20	216349.67	-7.64	WB
11749	3626279.02	216353.23	-7.64	WB
11750	3626278.96	216356.61	-7.63	WB
11751	3626278.92	216359.92	-7.62	WB
11752	3626278.90	216362.99	-7.61	WB
11753	3626278.89	216364.53	-7.60	WB
11754	3626278.88	216366.08	-7.59	WB
11755	3626278.85	216369.12	-7.58	WB
11756	3626278.84	216372.00	-7.57	WB
11757	3626278.81	216374.95	-7.56	WB
11758	3626278.75	216377.91	-7.54	WB
11759	3626278.68	216380.78	-7.53	WB
11760	3626278.58	216383.73	-7.52	WB
11761	3626278.44	216386.59	-7.50	WB
11762	3626278.31	216389.41	-7.49	WB
11763	3626278.29	216389.80	-7.47	WB
11764	3626278.22	216392.21	-7.46	WB
11765	3626278.15	216394.98	-7.45	WB
11766	3626278.13	216397.70	-7.44	WB
11767	3626278.19	216400.44	-7.43	WB
11768	3626278.25	216403.11	-7.42	WB
11769	3626278.41	216405.65	-7.41	WB
11770	3626278.60	216408.23	-7.40	WB
11771	3626278.79	216410.76	-7.39	WB
11772	3626278.98	216413.28	-7.39	WB
11773	3626279.12	216415.18	-7.38	WB
11774	3626279.17	216415.87	-7.38	WB
11775	3626279.35	216418.56	-7.38	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
11776	3626279.53	216421.29	-7.38	WB
11777	3626279.75	216424.19	-7.38	WB
11778	3626279.98	216427.09	-7.38	WB
11779	3626280.22	216430.05	-7.38	WB
11780	3626280.43	216433.27	-7.38	WB
11781	3626280.62	216436.40	-7.38	WB
11782	3626280.80	216439.78	-7.38	WB
11783	3626280.82	216440.20	-7.38	WB
11784	3626280.98	216443.31	-7.38	WB
11785	3626281.14	216446.77	-7.38	WB
11786	3626281.29	216450.46	-7.38	WB
11787	3626281.46	216454.06	-7.38	WB
11788	3626281.60	216457.46	-7.38	WB
11789	3626281.75	216460.96	-7.37	WB
11790	3626281.93	216464.28	-7.37	WB
11791	3626281.98	216465.03	-7.36	WB
11792	3626282.17	216467.39	-7.36	WB
11793	3626282.41	216470.61	-7.35	WB
11794	3626282.53	216473.67	-7.34	WB
11795	3626282.61	216476.69	-7.33	WB
11796	3626282.65	216479.64	-7.32	WB
11797	3626282.64	216482.50	-7.31	WB
11798	3626282.63	216485.37	-7.30	WB
11799	3626282.49	216488.07	-7.29	WB
11800	3626282.43	216489.08	-7.27	WB
11801	3626282.33	216490.78	-7.26	WB
11802	3626282.09	216493.50	-7.25	WB
11803	3626281.77	216496.22	-7.23	WB
11804	3626281.45	216498.84	-7.22	WB
11805	3626281.03	216501.46	-7.20	WB
11806	3626280.60	216504.16	-7.19	WB
11807	3626280.16	216506.78	-7.18	WB
11808	3626279.67	216509.52	-7.17	WB
11809	3626279.19	216512.22	-7.16	WB
11810	3626278.83	216514.22	-7.15	WB
11811	3626278.71	216514.86	-7.14	WB
11812	3626278.20	216517.60	-7.13	WB
11813	3626277.74	216520.34	-7.12	WB
11814	3626277.30	216523.06	-7.11	WB
11815	3626276.86	216525.83	-7.11	WB
11816	3626276.42	216528.64	-7.10	WB
11817	3626275.99	216531.44	-7.10	WB
11818	3626275.65	216534.28	-7.09	WB
11819	3626275.36	216537.18	-7.09	WB
11820	3626275.10	216540.03	-7.09	WB
11821	3626274.88	216543.04	-7.08	WB
11822	3626274.65	216546.10	-7.08	WB
11823	3626274.49	216549.33	-7.08	WB
11824	3626274.33	216552.70	-7.07	WB
11825	3626274.18	216556.09	-7.07	WB
11826	3626274.05	216559.59	-7.07	WB
11827	3626273.91	216563.26	-7.06	WB
11828	3626273.83	216565.49	-7.06	WB
11829	3626273.78	216566.85	-7.05	WB
11830	3626273.66	216570.43	-7.05	WB
11831	3626273.60	216574.09	-7.04	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
11832	3626273.59	216577.48	-7.03	WB
11833	3626273.60	216580.90	-7.03	WB
11834	3626273.63	216584.12	-7.02	WB
11835	3626273.66	216587.25	-7.00	WB
11836	3626273.70	216589.99	-6.99	WB
11837	3626273.71	216590.34	-6.98	WB
11838	3626273.78	216593.30	-6.97	WB
11839	3626273.84	216596.23	-6.95	WB
11840	3626273.92	216599.18	-6.93	WB
11841	3626273.99	216602.11	-6.92	WB
11842	3626274.02	216605.00	-6.90	WB
11843	3626274.04	216607.94	-6.88	WB
11844	3626274.06	216610.94	-6.87	WB
11845	3626274.16	216613.88	-6.85	WB
11846	3626274.20	216615.04	-6.83	WB
11847	3626274.26	216616.95	-6.81	WB
11848	3626274.38	216619.85	-6.79	WB
11849	3626274.52	216622.77	-6.77	WB
11850	3626274.70	216625.81	-6.76	WB
11851	3626274.96	216628.58	-6.74	WB
11852	3626275.24	216631.43	-6.72	WB
11853	3626275.60	216634.14	-6.71	WB
11854	3626275.97	216636.79	-6.69	WB
11855	3626276.36	216639.51	-6.68	WB
11856	3626276.44	216640.14	-6.66	WB
11857	3626276.72	216642.15	-6.65	WB
11858	3626277.08	216644.75	-6.64	WB
11859	3626277.52	216647.39	-6.63	WB
11860	3626277.96	216649.96	-6.62	WB
11861	3626278.38	216652.55	-6.61	WB
11862	3626278.77	216655.13	-6.61	WB
11863	3626279.17	216657.72	-6.60	WB
11864	3626279.53	216660.35	-6.60	WB
11865	3626279.91	216662.98	-6.59	WB
11866	3626280.17	216665.01	-6.59	WB
11867	3626280.24	216665.67	-6.58	WB
11868	3626280.53	216668.41	-6.58	WB
11869	3626280.82	216671.21	-6.58	WB
11870	3626281.03	216674.07	-6.58	WB
11871	3626281.25	216676.93	-6.58	WB
11872	3626281.42	216680.03	-6.57	WB
11873	3626281.54	216683.08	-6.57	WB
11874	3626281.64	216686.12	-6.57	WB
11875	3626281.57	216689.47	-6.56	WB
11876	3626281.50	216692.67	-6.56	WB
11877	3626281.34	216696.07	-6.56	WB
11878	3626281.16	216699.41	-6.55	WB
11879	3626280.93	216702.69	-6.54	WB
11880	3626280.54	216705.98	-6.54	WB
11881	3626280.14	216709.34	-6.53	WB
11882	3626279.69	216712.48	-6.52	WB
11883	3626279.46	216714.10	-6.51	WB
11884	3626279.21	216715.71	-6.50	WB
11885	3626278.71	216718.85	-6.49	WB
11886	3626278.15	216721.88	-6.48	WB
11887	3626277.58	216724.92	-6.46	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
11888	3626277.03	216727.80	-6.45	WB
11889	3626276.47	216730.67	-6.44	WB
11890	3626275.94	216733.52	-6.42	WB
11891	3626275.46	216736.22	-6.41	WB
11892	3626274.97	216738.93	-6.39	WB
11893	3626274.90	216739.29	-6.37	WB
11894	3626274.46	216741.67	-6.36	WB
11895	3626273.96	216744.38	-6.34	WB
11896	3626273.51	216747.03	-6.33	WB
11897	3626273.07	216749.80	-6.31	WB
11898	3626272.66	216752.44	-6.29	WB
11899	3626272.28	216755.20	-6.28	WB
11900	3626271.92	216757.92	-6.26	WB
11901	3626271.62	216760.61	-6.25	WB
11902	3626271.36	216763.43	-6.24	WB
11903	3626271.23	216764.80	-6.22	WB
11904	3626271.10	216766.24	-6.21	WB
11905	3626270.90	216769.01	-6.20	WB
11906	3626270.69	216771.77	-6.18	WB
11907	3626270.54	216774.60	-6.17	WB
11908	3626270.42	216777.46	-6.16	WB
11909	3626270.32	216780.33	-6.15	WB
11910	3626270.29	216783.22	-6.14	WB
11911	3626270.26	216786.13	-6.13	WB
11912	3626270.31	216789.13	-6.12	WB
11913	3626270.33	216790.19	-6.11	WB
11914	3626270.37	216792.04	-6.10	WB
11915	3626270.48	216795.01	-6.09	WB
11916	3626270.66	216798.06	-6.08	WB
11917	3626270.83	216801.02	-6.07	WB
11918	3626271.05	216804.15	-6.06	WB
11919	3626271.28	216807.27	-6.05	WB
11920	3626271.52	216810.39	-6.04	WB
11921	3626271.78	216813.69	-6.03	WB
11922	3626271.95	216815.72	-6.02	WB
11923	3626272.05	216816.93	-6.01	WB
11924	3626272.34	216820.18	-6.00	WB
11925	3626272.66	216823.52	-5.98	WB
11926	3626272.98	216826.84	-5.97	WB
11927	3626273.30	216830.15	-5.96	WB
11928	3626273.62	216833.46	-5.94	WB
11929	3626273.90	216836.83	-5.93	WB
11930	3626274.18	216840.20	-5.91	WB
11931	3626274.21	216840.59	-5.89	WB
11932	3626274.43	216843.59	-5.85	WB
11933	3626274.68	216846.82	-5.81	WB
11934	3626274.93	216850.07	-5.76	WB
11935	3626275.22	216853.16	-5.71	WB
11936	3626275.50	216856.17	-5.66	WB
11937	3626275.76	216859.11	-5.62	WB
11938	3626276.00	216862.06	-5.57	WB
11939	3626276.23	216864.89	-5.52	WB
11940	3626276.46	216867.69	-5.46	WB
11941	3626276.68	216870.45	-5.41	WB
11942	3626276.88	216873.05	-5.35	WB
11943	3626277.07	216875.70	-5.29	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
11944	3626277.23	216878.31	-5.23	WB
11945	3626277.34	216880.87	-5.17	WB
11946	3626277.46	216883.50	-5.10	WB
11947	3626277.63	216886.19	-5.04	WB
11948	3626277.80	216888.87	-4.98	WB
11949	3626277.87	216889.93	-4.93	WB
11950	3626277.95	216891.60	-4.87	WB
11951	3626278.07	216894.48	-4.82	WB
11952	3626278.19	216897.27	-4.77	WB
11953	3626278.38	216900.25	-4.72	WB
11954	3626278.56	216903.19	-4.67	WB
11955	3626278.73	216906.18	-4.62	WB
11956	3626278.89	216909.24	-4.58	WB
11957	3626279.04	216912.22	-4.54	WB
11958	3626279.23	216915.38	-4.50	WB
11959	3626279.43	216918.59	-4.46	WB
11960	3626279.59	216921.81	-4.42	WB
11961	3626279.74	216925.17	-4.38	WB
11962	3626279.88	216928.48	-4.35	WB
11963	3626280.00	216931.84	-4.32	WB
11964	3626280.14	216935.30	-4.29	WB
11965	3626280.23	216938.72	-4.26	WB
11966	3626280.25	216939.94	-4.23	WB
11967	3626280.30	216942.09	-4.20	WB
11968	3626280.36	216945.56	-4.18	WB
11969	3626280.38	216948.96	-4.15	WB
11970	3626280.39	216952.36	-4.13	WB
11971	3626280.30	216955.71	-4.12	WB
11972	3626280.19	216958.94	-4.10	WB
11973	3626280.04	216962.21	-4.08	WB
11974	3626279.88	216964.51	-4.06	WB
11975	3626279.83	216965.36	-4.05	WB
11976	3626279.62	216968.46	-4.04	WB
11977	3626279.33	216971.50	-4.03	WB
11978	3626279.03	216974.52	-4.03	WB
11979	3626278.72	216977.41	-4.04	WB
11980	3626278.38	216980.23	-4.07	WB
11981	3626278.04	216983.10	-4.11	WB
11982	3626277.69	216985.74	-4.14	WB
11983	3626277.31	216988.53	-4.18	WB
11984	3626277.22	216989.18	-4.21	WB
11985	3626276.92	216991.18	-4.23	WB
11986	3626276.51	216993.80	-4.28	WB
11987	3626276.07	216996.47	-4.33	WB
11988	3626275.59	216999.06	-4.40	WB
11989	3626275.07	217001.76	-4.48	WB
11990	3626274.60	217004.40	-4.53	WB
11991	3626274.18	217006.99	-4.60	WB
11992	3626273.75	217009.65	-4.69	WB
11993	3626273.34	217012.21	-4.79	WB
11994	3626272.98	217014.44	-4.92	WB
11995	3626272.93	217014.74	-5.06	WB
11996	3626272.60	217017.27	-5.19	WB
11997	3626272.30	217019.77	-5.34	WB
11998	3626272.02	217022.26	-5.49	WB
11999	3626271.77	217024.86	-5.61	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
12000	3626271.51	217027.43	-5.74	WB
12001	3626271.31	217030.19	-5.87	WB
12002	3626271.13	217032.97	-5.97	WB
12003	3626271.03	217035.85	-6.04	WB
12004	3626271.06	217038.81	-6.09	WB
12005	3626271.08	217040.62	-6.12	WB
12006	3626271.10	217041.80	-6.10	WB
12007	3626271.26	217044.93	-6.08	WB
12008	3626271.44	217048.11	-6.06	WB
12009	3626271.67	217051.41	-6.04	WB
12010	3626271.98	217054.69	-6.01	WB
12011	3626272.30	217058.05	-5.99	WB
12012	3626272.71	217061.41	-5.97	WB
12013	3626273.11	217064.69	-5.94	WB
12014	3626273.27	217065.92	-5.92	WB
12015	3626273.52	217067.86	-5.94	WB
12016	3626273.92	217070.93	-5.97	WB
12017	3626274.34	217073.94	-5.96	WB
12018	3626274.77	217076.63	-5.90	WB
12019	3626275.20	217079.31	-5.84	WB
12020	3626275.57	217081.84	-5.78	WB
12021	3626275.89	217084.30	-5.70	WB
12022	3626276.18	217086.79	-5.61	WB
12023	3626276.38	217089.21	-5.50	WB
12024	3626276.43	217089.84	-5.37	WB
12025	3626276.56	217091.70	-5.22	WB
12026	3626276.70	217094.21	-5.13	WB
12027	3626276.81	217096.63	-5.09	WB
12028	3626276.92	217099.07	-5.03	WB
12029	3626277.03	217101.62	-4.99	WB
12030	3626277.14	217104.05	-4.94	WB
12031	3626277.28	217106.67	-4.91	WB
12032	3626277.41	217109.26	-4.89	WB
12033	3626277.55	217111.86	-4.85	WB
12034	3626277.69	217114.59	-4.81	WB
12035	3626277.71	217114.91	-4.77	WB
12036	3626277.84	217117.34	-4.74	WB
12037	3626277.97	217120.16	-4.71	WB
12038	3626278.11	217123.04	-4.68	WB
12039	3626278.22	217125.88	-4.65	WB
12040	3626278.31	217128.79	-4.62	WB
12041	3626278.40	217131.69	-4.59	WB
12042	3626278.36	217134.67	-4.56	WB
12043	3626278.33	217137.60	-4.53	WB
12044	3626278.28	217139.84	-4.50	WB
12045	3626278.25	217140.67	-4.46	WB
12046	3626278.14	217143.71	-4.43	WB
12047	3626278.01	217146.77	-4.40	WB
12048	3626277.80	217150.13	-4.36	WB
12049	3626277.58	217153.40	-4.32	WB
12050	3626277.29	217156.88	-4.28	WB
12051	3626276.97	217160.38	-4.24	WB
12052	3626276.64	217163.85	-4.19	WB
12053	3626276.55	217164.76	-4.14	WB
12054	3626276.28	217167.45	-4.09	WB
12055	3626275.92	217171.01	-4.03	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
12056	3626275.57	217174.51	-3.97	WB
12057	3626275.22	217178.07	-3.90	WB
12058	3626274.89	217181.48	-3.84	WB
12059	3626274.57	217184.81	-3.77	WB
12060	3626274.26	217188.15	-3.71	WB
12061	3626274.14	217189.73	-3.64	WB
12062	3626274.04	217191.22	-3.56	WB
12063	3626273.84	217194.28	-3.48	WB
12064	3626273.63	217197.09	-3.39	WB
12065	3626273.35	217199.66	-3.31	WB
12066	3626273.09	217202.22	-3.24	WB
12067	3626272.82	217204.44	-3.17	WB
12068	3626272.55	217206.60	-3.11	WB
12069	3626272.22	217208.60	-3.03	WB
12070	3626271.82	217210.40	-2.95	WB
12071	3626271.40	217212.22	-2.87	WB
12072	3626270.92	217213.77	-2.78	WB
12073	3626270.43	217215.31	-2.70	WB
12074	3625770.05	215719.20	-8.95	WB
12075	3625769.86	215721.57	-8.94	WB
12076	3625769.79	215722.34	-8.94	WB
12077	3625769.52	215725.59	-8.93	WB
12078	3625769.25	215728.83	-8.92	WB
12079	3625768.99	215732.03	-8.91	WB
12080	3625768.75	215735.36	-8.90	WB
12081	3625768.64	215738.60	-8.90	WB
12082	3625768.54	215741.77	-8.89	WB
12083	3625768.64	215745.01	-8.88	WB
12084	3625768.75	215746.93	-8.88	WB
12085	3625768.81	215748.14	-8.87	WB
12086	3625769.00	215751.22	-8.87	WB
12087	3625769.24	215754.29	-8.86	WB
12088	3625769.48	215757.41	-8.86	WB
12089	3625769.85	215760.32	-8.85	WB
12090	3625770.27	215763.25	-8.85	WB
12091	3625770.72	215766.09	-8.85	WB
12092	3625771.19	215768.80	-8.84	WB
12093	3625771.69	215771.57	-8.84	WB
12094	3625771.81	215772.20	-8.84	WB
12095	3625772.24	215774.12	-8.84	WB
12096	3625772.79	215776.60	-8.84	WB
12097	3625773.41	215779.11	-8.84	WB
12098	3625774.08	215781.54	-8.84	WB
12099	3625774.76	215783.96	-8.85	WB
12100	3625775.29	215786.44	-8.85	WB
12101	3625775.84	215788.94	-8.85	WB
12102	3625776.30	215791.55	-8.85	WB
12103	3625776.70	215794.24	-8.85	WB
12104	3625776.99	215796.29	-8.86	WB
12105	3625777.07	215796.94	-8.86	WB
12106	3625777.18	215799.87	-8.86	WB
12107	3625777.28	215802.85	-8.86	WB
12108	3625777.21	215805.88	-8.87	WB
12109	3625777.02	215809.03	-8.87	WB
12110	3625776.77	215812.29	-8.87	WB
12111	3625776.33	215815.47	-8.87	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
12112	3625775.88	215818.65	-8.87	WB
12113	3625775.58	215820.73	-8.86	WB
12114	3625775.41	215822.00	-8.86	WB
12115	3625774.95	215825.21	-8.86	WB
12116	3625774.48	215828.46	-8.85	WB
12117	3625774.00	215831.67	-8.85	WB
12118	3625773.53	215834.88	-8.84	WB
12119	3625773.10	215837.93	-8.84	WB
12120	3625772.69	215840.91	-8.83	WB
12121	3625772.34	215843.81	-8.82	WB
12122	3625772.11	215846.27	-8.82	WB
12123	3625772.07	215846.60	-8.81	WB
12124	3625771.81	215849.44	-8.80	WB
12125	3625771.52	215852.10	-8.79	WB
12126	3625771.23	215854.78	-8.79	WB
12127	3625770.96	215857.51	-8.78	WB
12128	3625770.73	215860.12	-8.77	WB
12129	3625770.49	215862.82	-8.76	WB
12130	3625770.22	215865.49	-8.76	WB
12131	3625769.94	215868.13	-8.75	WB
12132	3625769.67	215870.87	-8.74	WB
12133	3625769.64	215871.21	-8.74	WB
12134	3625769.42	215873.65	-8.73	WB
12135	3625769.17	215876.45	-8.73	WB
12136	3625768.97	215879.49	-8.72	WB
12137	3625768.77	215882.42	-8.72	WB
12138	3625768.62	215885.53	-8.72	WB
12139	3625768.52	215888.64	-8.71	WB
12140	3625768.41	215891.74	-8.71	WB
12141	3625768.33	215895.00	-8.71	WB
12142	3625768.28	215896.96	-8.71	WB
12143	3625768.25	215898.20	-8.71	WB
12144	3625768.24	215901.41	-8.71	WB
12145	3625768.28	215904.60	-8.70	WB
12146	3625768.34	215907.77	-8.70	WB
12147	3625768.49	215910.90	-8.70	WB
12148	3625768.64	215914.01	-8.70	WB
12149	3625768.83	215917.18	-8.69	WB
12150	3625769.04	215920.36	-8.69	WB
12151	3625769.17	215922.30	-8.69	WB
12152	3625769.26	215923.59	-8.68	WB
12153	3625769.49	215926.74	-8.68	WB
12154	3625769.72	215929.92	-8.67	WB
12155	3625770.10	215933.08	-8.66	WB
12156	3625770.48	215936.13	-8.66	WB
12157	3625770.89	215939.12	-8.65	WB
12158	3625771.38	215942.10	-8.64	WB
12159	3625771.85	215945.05	-8.63	WB
12160	3625772.17	215946.84	-8.63	WB
12161	3625772.35	215947.89	-8.62	WB
12162	3625772.86	215950.71	-8.61	WB
12163	3625773.33	215953.44	-8.60	WB
12164	3625773.78	215956.13	-8.59	WB
12165	3625774.23	215958.83	-8.59	WB
12166	3625774.63	215961.51	-8.58	WB
12167	3625775.04	215964.19	-8.57	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
12168	3625775.48	215966.87	-8.57	WB
12169	3625775.93	215969.45	-8.57	WB
12170	3625776.33	215971.76	-8.56	WB
12171	3625776.38	215972.07	-8.56	WB
12172	3625776.74	215974.73	-8.56	WB
12173	3625777.09	215977.30	-8.56	WB
12174	3625777.46	215979.82	-8.56	WB
12175	3625777.85	215982.43	-8.56	WB
12176	3625778.20	215984.90	-8.56	WB
12177	3625778.43	215987.40	-8.57	WB
12178	3625778.66	215989.91	-8.57	WB
12179	3625778.77	215992.46	-8.57	WB
12180	3625778.84	215995.03	-8.58	WB
12181	3625778.86	215996.03	-8.59	WB
12182	3625778.85	215997.71	-8.59	WB
12183	3625778.72	216000.56	-8.60	WB
12184	3625778.58	216003.41	-8.60	WB
12185	3625778.30	216006.68	-8.61	WB
12186	3625777.99	216009.91	-8.61	WB
12187	3625777.62	216013.30	-8.61	WB
12188	3625777.16	216016.98	-8.62	WB
12189	3625776.71	216020.55	-8.62	WB
12190	3625776.63	216021.10	-8.62	WB
12191	3625776.14	216024.37	-8.62	WB
12192	3625775.58	216028.11	-8.62	WB
12193	3625775.02	216031.71	-8.62	WB
12194	3625774.42	216035.28	-8.61	WB
12195	3625773.82	216038.89	-8.61	WB
12196	3625773.23	216042.06	-8.60	WB
12197	3625772.64	216045.26	-8.59	WB
12198	3625772.57	216045.65	-8.59	WB
12199	3625772.07	216048.29	-8.58	WB
12200	3625771.51	216051.13	-8.57	WB
12201	3625770.95	216053.94	-8.56	WB
12202	3625770.34	216056.60	-8.55	WB
12203	3625769.75	216059.20	-8.54	WB
12204	3625769.22	216061.80	-8.53	WB
12205	3625768.72	216064.41	-8.52	WB
12206	3625768.25	216066.97	-8.51	WB
12207	3625767.82	216069.67	-8.49	WB
12208	3625767.54	216071.34	-8.49	WB
12209	3625767.38	216072.33	-8.48	WB
12210	3625767.06	216075.00	-8.47	WB
12211	3625766.77	216077.78	-8.46	WB
12212	3625766.55	216080.51	-8.45	WB
12213	3625766.46	216083.24	-8.45	WB
12214	3625766.37	216086.06	-8.44	WB
12215	3625766.44	216088.90	-8.44	WB
12216	3625766.53	216091.75	-8.43	WB
12217	3625766.61	216094.66	-8.43	WB
12218	3625766.66	216096.85	-8.42	WB
12219	3625766.68	216097.66	-8.42	WB
12220	3625766.74	216100.66	-8.42	WB
12221	3625766.86	216103.82	-8.42	WB
12222	3625766.99	216106.97	-8.41	WB
12223	3625767.10	216110.10	-8.41	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
12224	3625767.19	216113.47	-8.41	WB
12225	3625767.29	216116.68	-8.41	WB
12226	3625767.52	216119.85	-8.40	WB
12227	3625767.73	216122.71	-8.40	WB
12228	3625767.76	216123.14	-8.40	WB
12229	3625768.04	216126.26	-8.39	WB
12230	3625768.38	216129.46	-8.39	WB
12231	3625768.72	216132.61	-8.38	WB
12232	3625769.13	216135.67	-8.38	WB
12233	3625769.55	216138.82	-8.37	WB
12234	3625770.05	216141.78	-8.36	WB
12235	3625770.60	216144.68	-8.35	WB
12236	3625771.12	216147.28	-8.34	WB
12237	3625771.20	216147.60	-8.34	WB
12238	3625771.90	216150.30	-8.33	WB
12239	3625772.61	216153.01	-8.32	WB
12240	3625773.36	216155.59	-8.31	WB
12241	3625774.11	216158.12	-8.30	WB
12242	3625774.82	216160.64	-8.29	WB
12243	3625775.48	216163.18	-8.28	WB
12244	3625776.14	216165.73	-8.27	WB
12245	3625776.76	216168.37	-8.27	WB
12246	3625777.37	216171.04	-8.26	WB
12247	3625777.58	216171.99	-8.25	WB
12248	3625777.92	216173.67	-8.24	WB
12249	3625778.43	216176.39	-8.24	WB
12250	3625778.96	216179.15	-8.23	WB
12251	3625779.44	216181.80	-8.23	WB
12252	3625779.94	216184.52	-8.22	WB
12253	3625780.37	216187.26	-8.22	WB
12254	3625780.69	216190.03	-8.21	WB
12255	3625781.01	216192.93	-8.21	WB
12256	3625781.02	216195.97	-8.20	WB
12257	3625781.02	216196.33	-8.20	WB
12258	3625781.03	216198.98	-8.20	WB
12259	3625780.98	216202.10	-8.19	WB
12260	3625780.88	216205.19	-8.19	WB
12261	3625780.77	216208.29	-8.18	WB
12262	3625780.58	216211.41	-8.18	WB
12263	3625780.40	216214.53	-8.18	WB
12264	3625780.16	216217.60	-8.17	WB
12265	3625779.89	216220.74	-8.17	WB
12266	3625779.86	216221.12	-8.16	WB
12267	3625779.61	216223.91	-8.16	WB
12268	3625779.29	216226.98	-8.15	WB
12269	3625778.95	216230.15	-8.14	WB
12270	3625778.62	216233.22	-8.14	WB
12271	3625778.30	216236.21	-8.13	WB
12272	3625778.00	216239.27	-8.12	WB
12273	3625777.76	216242.20	-8.11	WB
12274	3625777.52	216245.09	-8.11	WB
12275	3625777.42	216246.24	-8.10	WB
12276	3625777.29	216247.98	-8.09	WB
12277	3625777.06	216250.80	-8.08	WB
12278	3625776.83	216253.72	-8.07	WB
12279	3625776.61	216256.65	-8.06	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
12280	3625776.39	216259.59	-8.06	WB
12281	3625776.13	216262.55	-8.05	WB
12282	3625775.86	216265.56	-8.04	WB
12283	3625775.62	216268.70	-8.03	WB
12284	3625775.42	216271.82	-8.02	WB
12285	3625775.21	216275.02	-8.01	WB
12286	3625775.08	216278.19	-8.00	WB
12287	3625774.95	216281.30	-8.00	WB
12288	3625774.89	216284.50	-7.99	WB
12289	3625774.90	216287.52	-7.98	WB
12290	3625774.90	216290.54	-7.97	WB
12291	3625774.87	216293.69	-7.96	WB
12292	3625774.84	216296.30	-7.95	WB
12293	3625774.84	216296.70	-7.95	WB
12294	3625774.72	216299.71	-7.94	WB
12295	3625774.57	216302.63	-7.93	WB
12296	3625774.42	216305.51	-7.92	WB
12297	3625774.20	216308.26	-7.91	WB
12298	3625773.98	216311.01	-7.91	WB
12299	3625773.68	216313.72	-7.90	WB
12300	3625773.33	216316.40	-7.89	WB
12301	3625772.95	216319.18	-7.88	WB
12302	3625772.70	216320.90	-7.87	WB
12303	3625772.54	216321.89	-7.87	WB
12304	3625772.12	216324.64	-7.86	WB
12305	3625771.64	216327.53	-7.85	WB
12306	3625771.15	216330.35	-7.84	WB
12307	3625770.61	216333.33	-7.83	WB
12308	3625770.01	216336.39	-7.83	WB
12309	3625769.41	216339.40	-7.82	WB
12310	3625768.88	216342.56	-7.81	WB
12311	3625768.37	216345.69	-7.80	WB
12312	3625768.30	216346.06	-7.80	WB
12313	3625767.84	216348.75	-7.79	WB
12314	3625767.26	216351.94	-7.78	WB
12315	3625766.66	216355.18	-7.78	WB
12316	3625766.17	216358.30	-7.77	WB
12317	3625765.68	216361.46	-7.77	WB
12318	3625765.22	216364.60	-7.76	WB
12319	3625764.82	216367.59	-7.75	WB
12320	3625764.42	216370.60	-7.75	WB
12321	3625764.30	216371.71	-7.74	WB
12322	3625764.11	216373.48	-7.74	WB
12323	3625763.82	216376.25	-7.73	WB
12324	3625763.64	216379.10	-7.73	WB
12325	3625763.54	216381.81	-7.72	WB
12326	3625763.44	216384.57	-7.71	WB
12327	3625763.38	216387.63	-7.71	WB
12328	3625763.32	216390.59	-7.70	WB
12329	3625763.29	216393.73	-7.69	WB
12330	3625763.29	216397.11	-7.69	WB
12331	3625763.33	216400.40	-7.68	WB
12332	3625763.47	216403.87	-7.67	WB
12333	3625763.61	216407.29	-7.66	WB
12334	3625763.81	216410.70	-7.65	WB
12335	3625764.03	216414.19	-7.64	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
12336	3625764.28	216417.65	-7.63	WB
12337	3625764.59	216421.03	-7.62	WB
12338	3625764.71	216422.28	-7.61	WB
12339	3625764.91	216424.37	-7.60	WB
12340	3625765.30	216427.54	-7.59	WB
12341	3625765.68	216430.57	-7.57	WB
12342	3625766.11	216433.46	-7.56	WB
12343	3625766.60	216436.36	-7.55	WB
12344	3625767.06	216439.13	-7.54	WB
12345	3625767.52	216441.87	-7.52	WB
12346	3625767.97	216444.53	-7.51	WB
12347	3625768.36	216446.76	-7.50	WB
12348	3625768.43	216447.11	-7.49	WB
12349	3625768.91	216449.65	-7.48	WB
12350	3625769.39	216452.22	-7.47	WB
12351	3625769.78	216454.73	-7.46	WB
12352	3625770.18	216457.29	-7.45	WB
12353	3625770.53	216459.89	-7.44	WB
12354	3625770.83	216462.42	-7.44	WB
12355	3625771.14	216465.03	-7.43	WB
12356	3625771.42	216467.61	-7.43	WB
12357	3625771.71	216470.13	-7.42	WB
12358	3625771.84	216471.47	-7.42	WB
12359	3625771.95	216472.82	-7.42	WB
12360	3625772.16	216475.50	-7.42	WB
12361	3625772.36	216478.18	-7.42	WB
12362	3625772.55	216481.14	-7.42	WB
12363	3625772.74	216483.96	-7.42	WB
12364	3625772.85	216486.95	-7.42	WB
12365	3625772.95	216490.13	-7.42	WB
12366	3625772.94	216493.23	-7.42	WB
12367	3625772.69	216496.30	-7.42	WB
12368	3625772.45	216499.45	-7.42	WB
12369	3625772.48	216503.04	-7.42	WB
12370	3625772.55	216506.65	-7.42	WB
12371	3625772.47	216510.19	-7.42	WB
12372	3625772.20	216513.68	-7.42	WB
12373	3625771.92	216517.20	-7.41	WB
12374	3625771.55	216520.58	-7.41	WB
12375	3625771.51	216520.99	-7.40	WB
12376	3625771.18	216523.98	-7.40	WB
12377	3625770.78	216527.27	-7.39	WB
12378	3625770.37	216530.53	-7.38	WB
12379	3625769.97	216533.69	-7.37	WB
12380	3625769.59	216536.63	-7.36	WB
12381	3625769.21	216539.63	-7.35	WB
12382	3625768.84	216542.48	-7.34	WB
12383	3625768.47	216545.38	-7.33	WB
12384	3625768.38	216546.06	-7.31	WB
12385	3625768.10	216548.22	-7.30	WB
12386	3625767.75	216551.12	-7.29	WB
12387	3625767.38	216554.11	-7.27	WB
12388	3625766.98	216557.16	-7.25	WB
12389	3625766.56	216560.21	-7.24	WB
12390	3625766.16	216563.39	-7.22	WB
12391	3625765.86	216566.62	-7.20	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
12392	3625765.55	216569.87	-7.19	WB
12393	3625765.43	216571.89	-7.17	WB
12394	3625765.37	216573.09	-7.15	WB
12395	3625765.23	216576.32	-7.14	WB
12396	3625765.18	216579.53	-7.12	WB
12397	3625765.28	216582.62	-7.10	WB
12398	3625765.39	216585.70	-7.09	WB
12399	3625765.63	216588.74	-7.07	WB
12400	3625765.89	216591.80	-7.06	WB
12401	3625766.20	216594.69	-7.04	WB
12402	3625766.49	216596.89	-7.03	WB
12403	3625766.59	216597.58	-7.02	WB
12404	3625766.98	216600.50	-7.01	WB
12405	3625767.45	216603.23	-7.00	WB
12406	3625767.94	216606.04	-6.99	WB
12407	3625768.43	216608.80	-6.98	WB
12408	3625768.93	216611.47	-6.97	WB
12409	3625769.46	216614.19	-6.96	WB
12410	3625770.09	216616.82	-6.96	WB
12411	3625770.71	216619.42	-6.95	WB
12412	3625771.34	216622.13	-6.95	WB
12413	3625771.97	216624.84	-6.94	WB
12414	3625772.59	216627.53	-6.94	WB
12415	3625773.21	216630.39	-6.93	WB
12416	3625773.84	216633.25	-6.93	WB
12417	3625774.39	216636.28	-6.92	WB
12418	3625774.90	216639.39	-6.92	WB
12419	3625775.40	216642.49	-6.91	WB
12420	3625775.84	216645.70	-6.91	WB
12421	3625776.01	216646.89	-6.90	WB
12422	3625776.30	216648.94	-6.90	WB
12423	3625776.64	216652.10	-6.89	WB
12424	3625776.95	216655.25	-6.88	WB
12425	3625777.25	216658.37	-6.88	WB
12426	3625777.50	216661.30	-6.87	WB
12427	3625777.76	216664.32	-6.86	WB
12428	3625777.89	216667.18	-6.85	WB
12429	3625778.00	216670.02	-6.83	WB
12430	3625778.02	216670.76	-6.82	WB
12431	3625777.99	216672.98	-6.81	WB
12432	3625777.84	216675.81	-6.79	WB
12433	3625777.69	216678.62	-6.78	WB
12434	3625777.38	216681.47	-6.76	WB
12435	3625777.06	216684.30	-6.74	WB
12436	3625776.65	216687.08	-6.73	WB
12437	3625776.14	216689.82	-6.71	WB
12438	3625775.62	216692.61	-6.69	WB
12439	3625775.04	216695.19	-6.67	WB
12440	3625774.96	216695.55	-6.65	WB
12441	3625774.43	216697.86	-6.64	WB
12442	3625773.83	216700.41	-6.62	WB
12443	3625773.21	216702.97	-6.60	WB
12444	3625772.58	216705.56	-6.59	WB
12445	3625772.04	216708.00	-6.57	WB
12446	3625771.50	216710.44	-6.56	WB
12447	3625771.00	216713.02	-6.54	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
12448	3625770.53	216715.53	-6.53	WB
12449	3625770.10	216718.07	-6.52	WB
12450	3625769.76	216720.87	-6.51	WB
12451	3625769.68	216721.52	-6.49	WB
12452	3625769.43	216723.56	-6.48	WB
12453	3625769.13	216726.51	-6.48	WB
12454	3625768.86	216729.44	-6.47	WB
12455	3625768.64	216732.34	-6.46	WB
12456	3625768.48	216735.40	-6.45	WB
12457	3625768.34	216738.41	-6.45	WB
12458	3625768.28	216741.53	-6.44	WB
12459	3625768.23	216744.73	-6.43	WB
12460	3625768.21	216746.66	-6.43	WB
12461	3625768.22	216747.95	-6.42	WB
12462	3625768.24	216751.21	-6.41	WB
12463	3625768.27	216754.57	-6.40	WB
12464	3625768.36	216758.02	-6.40	WB
12465	3625768.45	216761.46	-6.39	WB
12466	3625768.53	216765.00	-6.38	WB
12467	3625768.59	216768.47	-6.37	WB
12468	3625768.65	216771.57	-6.35	WB
12469	3625768.66	216772.00	-6.34	WB
12470	3625768.78	216775.55	-6.33	WB
12471	3625768.89	216778.99	-6.31	WB
12472	3625769.00	216782.46	-6.29	WB
12473	3625769.09	216785.80	-6.28	WB
12474	3625769.18	216789.06	-6.26	WB
12475	3625769.29	216792.28	-6.24	WB
12476	3625769.40	216795.45	-6.21	WB
12477	3625769.44	216796.55	-6.19	WB
12478	3625769.50	216798.39	-6.17	WB
12479	3625769.61	216801.34	-6.14	WB
12480	3625769.72	216804.16	-6.12	WB
12481	3625769.87	216806.81	-6.09	WB
12482	3625770.01	216809.53	-6.07	WB
12483	3625770.14	216812.17	-6.04	WB
12484	3625770.24	216814.78	-6.01	WB
12485	3625770.33	216817.37	-5.99	WB
12486	3625770.41	216819.98	-5.96	WB
12487	3625770.44	216821.27	-5.93	WB
12488	3625770.48	216822.56	-5.90	WB
12489	3625770.56	216825.31	-5.88	WB
12490	3625770.63	216827.94	-5.85	WB
12491	3625770.67	216830.69	-5.82	WB
12492	3625770.68	216833.42	-5.79	WB
12493	3625770.70	216836.11	-5.77	WB
12494	3625770.75	216838.90	-5.74	WB
12495	3625770.82	216841.59	-5.71	WB
12496	3625770.88	216844.29	-5.68	WB
12497	3625770.94	216846.39	-5.66	WB
12498	3625770.95	216847.13	-5.63	WB
12499	3625771.02	216849.85	-5.60	WB
12500	3625771.08	216852.88	-5.57	WB
12501	3625771.14	216855.85	-5.54	WB
12502	3625771.19	216858.92	-5.51	WB
12503	3625771.25	216862.18	-5.48	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
12504	3625771.29	216865.45	-5.45	WB
12505	3625771.29	216868.82	-5.42	WB
12506	3625771.29	216871.88	-5.39	WB
12507	3625771.29	216872.29	-5.35	WB
12508	3625771.32	216875.78	-5.32	WB
12509	3625771.36	216879.24	-5.28	WB
12510	3625771.42	216882.69	-5.24	WB
12511	3625771.51	216886.06	-5.20	WB
12512	3625771.60	216889.41	-5.16	WB
12513	3625771.73	216892.52	-5.12	WB
12514	3625771.86	216895.64	-5.08	WB
12515	3625771.90	216896.42	-5.04	WB
12516	3625771.99	216898.73	-4.99	WB
12517	3625772.09	216901.74	-4.95	WB
12518	3625772.19	216904.66	-4.90	WB
12519	3625772.27	216907.56	-4.86	WB
12520	3625772.34	216910.49	-4.81	WB
12521	3625772.37	216913.29	-4.76	WB
12522	3625772.36	216916.19	-4.71	WB
12523	3625772.35	216919.05	-4.66	WB
12524	3625772.30	216921.15	-4.60	WB
12525	3625772.29	216921.82	-4.54	WB
12526	3625772.23	216924.66	-4.49	WB
12527	3625772.15	216927.48	-4.46	WB
12528	3625772.04	216930.28	-4.41	WB
12529	3625771.92	216933.21	-4.39	WB
12530	3625771.70	216936.15	-4.37	WB
12531	3625771.47	216939.21	-4.34	WB
12532	3625771.32	216942.28	-4.29	WB
12533	3625771.22	216945.36	-4.21	WB
12534	3625771.19	216946.20	-4.14	WB
12535	3625771.10	216948.56	-4.11	WB
12536	3625770.93	216951.77	-4.09	WB
12537	3625770.76	216954.97	-4.06	WB
12538	3625770.73	216958.15	-4.01	WB
12539	3625770.76	216961.19	-3.97	WB
12540	3625770.78	216964.28	-3.93	WB
12541	3625770.78	216967.38	-3.93	WB
12542	3625770.77	216970.38	-3.94	WB
12543	3625770.77	216971.19	-3.97	WB
12544	3625770.80	216973.31	-3.98	WB
12545	3625770.86	216976.25	-3.98	WB
12546	3625770.90	216979.10	-4.00	WB
12547	3625770.92	216981.98	-4.02	WB
12548	3625770.93	216984.89	-4.06	WB
12549	3625770.84	216987.79	-4.09	WB
12550	3625770.75	216990.74	-4.13	WB
12551	3625770.65	216993.64	-4.17	WB
12552	3625770.57	216996.26	-4.19	WB
12553	3625770.56	216996.62	-4.21	WB
12554	3625770.45	216999.67	-4.27	WB
12555	3625770.26	217002.70	-4.32	WB
12556	3625770.05	217005.84	-4.39	WB
12557	3625769.90	217008.91	-4.44	WB
12558	3625769.79	217011.94	-4.51	WB
12559	3625769.68	217015.08	-4.56	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
12560	3625769.62	217018.05	-4.62	WB
12561	3625769.57	217020.99	-4.70	WB
12562	3625769.56	217021.38	-4.80	WB
12563	3625769.56	217023.93	-4.90	WB
12564	3625769.57	217026.71	-5.02	WB
12565	3625769.59	217029.56	-5.13	WB
12566	3625769.64	217032.42	-5.26	WB
12567	3625769.68	217035.20	-5.38	WB
12568	3625769.68	217038.04	-5.50	WB
12569	3625769.66	217040.93	-5.62	WB
12570	3625769.67	217043.74	-5.72	WB
12571	3625769.71	217046.57	-5.79	WB
12572	3625769.77	217049.42	-5.82	WB
12573	3625769.87	217052.16	-5.82	WB
12574	3625769.98	217054.94	-5.83	WB
12575	3625770.12	217057.75	-5.83	WB
12576	3625770.29	217060.48	-5.82	WB
12577	3625770.47	217063.30	-5.81	WB
12578	3625770.65	217066.16	-5.78	WB
12579	3625770.83	217069.00	-5.74	WB
12580	3625770.98	217071.68	-5.73	WB
12581	3625771.00	217072.06	-5.74	WB
12582	3625771.15	217075.21	-5.78	WB
12583	3625771.29	217078.34	-5.80	WB
12584	3625771.35	217081.84	-5.83	WB
12585	3625771.40	217085.30	-5.87	WB
12586	3625771.44	217088.89	-5.89	WB
12587	3625771.48	217092.62	-5.92	WB
12588	3625771.53	217096.26	-5.96	WB
12589	3625771.54	217096.75	-5.97	WB
12590	3625771.61	217099.98	-5.97	WB
12591	3625771.71	217103.63	-5.93	WB
12592	3625771.80	217107.10	-5.90	WB
12593	3625771.90	217110.57	-5.86	WB
12594	3625771.98	217114.04	-5.80	WB
12595	3625772.00	217117.17	-5.76	WB
12596	3625772.02	217120.35	-5.69	WB
12597	3625772.03	217121.16	-5.63	WB
12598	3625771.96	217123.42	-5.57	WB
12599	3625771.87	217126.30	-5.49	WB
12600	3625771.77	217129.25	-5.41	WB
12601	3625771.66	217131.94	-5.32	WB
12602	3625771.55	217134.64	-5.22	WB
12603	3625771.37	217137.32	-5.13	WB
12604	3625771.19	217139.90	-5.04	WB
12605	3625770.99	217142.55	-4.96	WB
12606	3625770.79	217145.14	-4.88	WB
12607	3625770.72	217146.07	-4.81	WB
12608	3625770.59	217147.70	-4.75	WB
12609	3625770.41	217150.41	-4.69	WB
12610	3625770.22	217153.11	-4.64	WB
12611	3625770.03	217155.85	-4.57	WB
12612	3625769.85	217158.81	-4.51	WB
12613	3625769.68	217161.64	-4.45	WB
12614	3625769.56	217164.60	-4.39	WB
12615	3625769.45	217167.52	-4.33	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
12616	3625769.38	217170.43	-4.28	WB
12617	3625769.37	217171.55	-4.23	WB
12618	3625769.36	217173.31	-4.17	WB
12619	3625769.35	217176.24	-4.13	WB
12620	3625769.41	217179.02	-4.08	WB
12621	3625769.48	217181.88	-4.03	WB
12622	3625769.55	217184.61	-3.98	WB
12623	3625769.62	217187.29	-3.93	WB
12624	3625769.69	217190.06	-3.88	WB
12625	3625769.77	217192.77	-3.83	WB
12626	3625769.85	217195.49	-3.78	WB
12627	3625769.87	217196.56	-3.73	WB
12628	3625769.88	217198.29	-3.67	WB
12629	3625769.90	217201.02	-3.60	WB
12630	3625769.91	217203.78	-3.55	WB
12631	3625769.90	217206.56	-3.50	WB
12632	3625769.89	217209.30	-3.44	WB
12633	3625769.91	217212.11	-3.39	WB
12634	3625769.94	217214.84	-3.32	WB
12635	3625769.99	217217.64	-3.25	WB
12636	3625770.06	217220.41	-3.16	WB
12637	3625770.08	217221.44	-3.08	WB
12638	3625770.13	217223.18	-2.99	WB
12639	3625770.23	217225.90	-2.92	WB
12640	3625770.33	217228.53	-2.83	WB
12641	3625770.53	217233.68	-2.66	WB
12642	3625770.69	217238.57	-2.41	WB
12643	3625770.74	217240.89	-2.29	WB
12644	3625283.34	215722.29	-8.84	WB
12645	3625282.85	215725.27	-8.85	WB
12646	3625282.37	215728.22	-8.86	WB
12647	3625282.19	215729.32	-8.86	WB
12648	3625282.11	215731.09	-8.87	WB
12649	3625282.02	215733.88	-8.88	WB
12650	3625281.97	215736.62	-8.88	WB
12651	3625282.09	215739.24	-8.89	WB
12652	3625282.22	215741.86	-8.89	WB
12653	3625282.47	215744.47	-8.89	WB
12654	3625282.77	215746.99	-8.90	WB
12655	3625283.08	215749.58	-8.90	WB
12656	3625283.38	215752.28	-8.91	WB
12657	3625283.56	215753.95	-8.91	WB
12658	3625283.66	215754.91	-8.91	WB
12659	3625283.93	215757.80	-8.92	WB
12660	3625284.18	215760.76	-8.92	WB
12661	3625284.37	215763.77	-8.92	WB
12662	3625284.42	215767.08	-8.92	WB
12663	3625284.46	215770.36	-8.92	WB
12664	3625284.37	215773.87	-8.92	WB
12665	3625284.26	215777.44	-8.92	WB
12666	3625284.20	215779.19	-8.92	WB
12667	3625284.13	215781.05	-8.92	WB
12668	3625283.99	215784.68	-8.92	WB
12669	3625283.87	215788.34	-8.91	WB
12670	3625283.78	215792.07	-8.91	WB
12671	3625283.70	215795.64	-8.91	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
12672	3625283.66	215799.15	-8.90	WB
12673	3625283.66	215802.63	-8.90	WB
12674	3625283.66	215803.85	-8.89	WB
12675	3625283.67	215805.98	-8.88	WB
12676	3625283.69	215809.30	-8.88	WB
12677	3625283.71	215812.57	-8.87	WB
12678	3625283.69	215815.74	-8.86	WB
12679	3625283.64	215818.98	-8.86	WB
12680	3625283.58	215822.20	-8.85	WB
12681	3625283.47	215825.37	-8.84	WB
12682	3625283.35	215828.28	-8.83	WB
12683	3625283.33	215828.67	-8.82	WB
12684	3625283.11	215832.03	-8.82	WB
12685	3625282.85	215835.34	-8.81	WB
12686	3625282.59	215838.79	-8.80	WB
12687	3625282.39	215842.25	-8.79	WB
12688	3625282.19	215845.71	-8.78	WB
12689	3625282.07	215849.15	-8.77	WB
12690	3625281.99	215852.58	-8.77	WB
12691	3625281.95	215853.91	-8.76	WB
12692	3625281.95	215855.97	-8.75	WB
12693	3625282.05	215859.35	-8.74	WB
12694	3625282.15	215862.61	-8.74	WB
12695	3625282.39	215865.82	-8.73	WB
12696	3625282.66	215869.06	-8.72	WB
12697	3625282.97	215872.19	-8.72	WB
12698	3625283.37	215875.46	-8.71	WB
12699	3625283.76	215878.58	-8.71	WB
12700	3625283.88	215879.43	-8.70	WB
12701	3625284.22	215881.82	-8.70	WB
12702	3625284.69	215885.06	-8.69	WB
12703	3625285.15	215888.24	-8.69	WB
12704	3625285.63	215891.49	-8.68	WB
12705	3625286.12	215894.68	-8.68	WB
12706	3625286.56	215897.83	-8.68	WB
12707	3625287.03	215901.07	-8.67	WB
12708	3625287.42	215904.32	-8.67	WB
12709	3625287.77	215907.64	-8.67	WB
12710	3625288.09	215910.96	-8.67	WB
12711	3625288.28	215914.30	-8.66	WB
12712	3625288.47	215917.64	-8.66	WB
12713	3625288.57	215920.93	-8.66	WB
12714	3625288.62	215924.20	-8.66	WB
12715	3625288.67	215927.34	-8.65	WB
12716	3625288.68	215928.55	-8.65	WB
12717	3625288.68	215930.50	-8.65	WB
12718	3625288.69	215933.61	-8.65	WB
12719	3625288.66	215936.63	-8.64	WB
12720	3625288.62	215939.70	-8.64	WB
12721	3625288.54	215942.69	-8.64	WB
12722	3625288.37	215945.75	-8.64	WB
12723	3625288.19	215948.88	-8.63	WB
12724	3625288.00	215952.05	-8.63	WB
12725	3625287.93	215953.25	-8.63	WB
12726	3625287.80	215955.26	-8.62	WB
12727	3625287.48	215958.62	-8.62	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
12728	3625287.02	215962.02	-8.61	WB
12729	3625286.54	215965.53	-8.61	WB
12730	3625286.14	215969.12	-8.60	WB
12731	3625285.75	215972.70	-8.60	WB
12732	3625285.30	215976.25	-8.59	WB
12733	3625284.97	215978.46	-8.59	WB
12734	3625284.76	215979.87	-8.58	WB
12735	3625284.22	215983.43	-8.57	WB
12736	3625283.68	215987.04	-8.57	WB
12737	3625283.15	215990.58	-8.56	WB
12738	3625282.63	215994.07	-8.55	WB
12739	3625282.10	215997.64	-8.55	WB
12740	3625281.56	216001.16	-8.54	WB
12741	3625281.18	216003.31	-8.53	WB
12742	3625280.97	216004.55	-8.52	WB
12743	3625280.35	216008.10	-8.51	WB
12744	3625279.82	216011.39	-8.51	WB
12745	3625279.30	216014.73	-8.50	WB
12746	3625278.75	216018.15	-8.49	WB
12747	3625278.23	216021.32	-8.48	WB
12748	3625277.70	216024.55	-8.47	WB
12749	3625277.26	216027.82	-8.46	WB
12750	3625277.22	216028.20	-8.45	WB
12751	3625276.87	216030.97	-8.45	WB
12752	3625276.49	216034.14	-8.44	WB
12753	3625276.14	216037.35	-8.43	WB
12754	3625275.79	216040.56	-8.42	WB
12755	3625275.52	216043.88	-8.42	WB
12756	3625275.26	216047.21	-8.41	WB
12757	3625275.00	216050.59	-8.40	WB
12758	3625274.79	216053.63	-8.40	WB
12759	3625274.76	216054.05	-8.39	WB
12760	3625274.52	216057.56	-8.39	WB
12761	3625274.38	216061.01	-8.38	WB
12762	3625274.24	216064.51	-8.37	WB
12763	3625274.12	216068.00	-8.37	WB
12764	3625274.04	216071.33	-8.36	WB
12765	3625273.96	216074.76	-8.36	WB
12766	3625273.99	216077.93	-8.36	WB
12767	3625274.00	216079.05	-8.35	WB
12768	3625274.02	216081.04	-8.35	WB
12769	3625274.07	216084.12	-8.34	WB
12770	3625274.13	216087.14	-8.34	WB
12771	3625274.18	216090.18	-8.33	WB
12772	3625274.25	216093.27	-8.33	WB
12773	3625274.31	216096.38	-8.32	WB
12774	3625274.33	216099.70	-8.32	WB
12775	3625274.34	216103.15	-8.31	WB
12776	3625274.34	216104.44	-8.31	WB
12777	3625274.36	216106.68	-8.30	WB
12778	3625274.42	216110.56	-8.29	WB
12779	3625274.50	216114.43	-8.28	WB
12780	3625274.40	216118.49	-8.28	WB
12781	3625274.25	216122.60	-8.27	WB
12782	3625274.27	216126.70	-8.26	WB
12783	3625274.55	216129.61	-8.25	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
12784	3625274.64	216130.54	-8.24	WB
12785	3625275.02	216134.41	-8.23	WB
12786	3625275.43	216138.00	-8.22	WB
12787	3625275.83	216141.41	-8.21	WB
12788	3625276.37	216144.74	-8.20	WB
12789	3625277.06	216147.72	-8.19	WB
12790	3625277.75	216150.66	-8.18	WB
12791	3625278.13	216153.56	-8.17	WB
12792	3625278.47	216156.43	-8.16	WB
12793	3625278.76	216159.25	-8.14	WB
12794	3625278.97	216161.99	-8.13	WB
12795	3625279.16	216164.78	-8.12	WB
12796	3625279.28	216167.48	-8.11	WB
12797	3625279.39	216170.30	-8.10	WB
12798	3625279.48	216173.08	-8.09	WB
12799	3625279.55	216175.85	-8.09	WB
12800	3625279.63	216178.71	-8.08	WB
12801	3625279.64	216179.05	-8.07	WB
12802	3625279.72	216181.62	-8.06	WB
12803	3625279.81	216184.51	-8.06	WB
12804	3625279.90	216187.50	-8.05	WB
12805	3625279.98	216190.44	-8.05	WB
12806	3625280.08	216193.45	-8.04	WB
12807	3625280.20	216196.65	-8.04	WB
12808	3625280.32	216199.75	-8.03	WB
12809	3625280.39	216203.09	-8.03	WB
12810	3625280.41	216204.42	-8.03	WB
12811	3625280.44	216206.55	-8.03	WB
12812	3625280.50	216209.99	-8.03	WB
12813	3625280.61	216213.45	-8.03	WB
12814	3625280.72	216216.94	-8.02	WB
12815	3625280.85	216220.42	-8.02	WB
12816	3625280.98	216223.79	-8.02	WB
12817	3625281.11	216227.18	-8.02	WB
12818	3625281.15	216228.48	-8.02	WB
12819	3625281.22	216230.59	-8.02	WB
12820	3625281.32	216233.91	-8.02	WB
12821	3625281.27	216237.41	-8.02	WB
12822	3625281.19	216240.78	-8.02	WB
12823	3625281.03	216244.27	-8.02	WB
12824	3625280.79	216247.87	-8.01	WB
12825	3625280.54	216251.36	-8.01	WB
12826	3625280.33	216253.67	-8.01	WB
12827	3625280.20	216255.10	-8.00	WB
12828	3625279.86	216258.78	-8.00	WB
12829	3625279.48	216262.42	-7.99	WB
12830	3625279.03	216266.22	-7.99	WB
12831	3625278.60	216269.95	-7.98	WB
12832	3625278.20	216273.55	-7.98	WB
12833	3625277.81	216277.15	-7.97	WB
12834	3625277.67	216278.48	-7.96	WB
12835	3625277.42	216280.60	-7.95	WB
12836	3625277.02	216283.98	-7.94	WB
12837	3625276.64	216287.30	-7.94	WB
12838	3625276.33	216290.36	-7.93	WB
12839	3625276.02	216293.41	-7.92	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
12840	3625275.73	216296.34	-7.91	WB
12841	3625275.43	216299.18	-7.90	WB
12842	3625275.15	216301.97	-7.89	WB
12843	3625275.02	216303.39	-7.88	WB
12844	3625274.88	216304.85	-7.87	WB
12845	3625274.60	216307.62	-7.86	WB
12846	3625274.33	216310.45	-7.85	WB
12847	3625274.02	216313.48	-7.84	WB
12848	3625273.73	216316.45	-7.83	WB
12849	3625273.45	216319.61	-7.82	WB
12850	3625273.16	216322.74	-7.81	WB
12851	3625273.02	216325.95	-7.81	WB
12852	3625272.89	216329.28	-7.80	WB
12853	3625272.85	216332.59	-7.79	WB
12854	3625272.92	216335.95	-7.78	WB
12855	3625272.99	216339.31	-7.78	WB
12856	3625273.21	216342.70	-7.77	WB
12857	3625273.44	216346.10	-7.76	WB
12858	3625273.78	216349.46	-7.76	WB
12859	3625274.22	216352.78	-7.75	WB
12860	3625274.50	216354.85	-7.74	WB
12861	3625274.68	216356.10	-7.74	WB
12862	3625275.30	216359.36	-7.73	WB
12863	3625275.92	216362.62	-7.73	WB
12864	3625276.62	216365.86	-7.72	WB
12865	3625277.38	216369.13	-7.72	WB
12866	3625278.14	216372.24	-7.71	WB
12867	3625278.99	216375.33	-7.70	WB
12868	3625279.87	216378.43	-7.70	WB
12869	3625280.18	216379.51	-7.69	WB
12870	3625280.74	216381.41	-7.68	WB
12871	3625281.64	216384.48	-7.68	WB
12872	3625282.47	216387.49	-7.67	WB
12873	3625283.16	216390.53	-7.66	WB
12874	3625283.87	216393.64	-7.65	WB
12875	3625284.42	216396.72	-7.65	WB
12876	3625284.93	216399.81	-7.64	WB
12877	3625285.33	216402.87	-7.63	WB
12878	3625285.39	216403.59	-7.62	WB
12879	3625285.55	216405.88	-7.61	WB
12880	3625285.76	216408.86	-7.60	WB
12881	3625285.80	216411.81	-7.59	WB
12882	3625285.81	216414.71	-7.58	WB
12883	3625285.76	216417.61	-7.57	WB
12884	3625285.64	216420.44	-7.56	WB
12885	3625285.51	216423.28	-7.55	WB
12886	3625285.28	216426.08	-7.54	WB
12887	3625285.10	216428.20	-7.53	WB
12888	3625285.03	216428.96	-7.52	WB
12889	3625284.78	216431.77	-7.51	WB
12890	3625284.50	216434.64	-7.51	WB
12891	3625284.22	216437.52	-7.50	WB
12892	3625283.93	216440.31	-7.49	WB
12893	3625283.63	216443.16	-7.48	WB
12894	3625283.31	216446.05	-7.47	WB
12895	3625282.97	216448.93	-7.46	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
12896	3625282.64	216451.83	-7.45	WB
12897	3625282.49	216453.34	-7.45	WB
12898	3625282.33	216454.82	-7.44	WB
12899	3625282.02	216457.82	-7.43	WB
12900	3625281.69	216460.91	-7.43	WB
12901	3625281.35	216464.03	-7.42	WB
12902	3625281.01	216467.24	-7.42	WB
12903	3625280.66	216470.63	-7.41	WB
12904	3625280.32	216474.06	-7.40	WB
12905	3625280.03	216477.54	-7.40	WB
12906	3625279.93	216478.92	-7.39	WB
12907	3625279.77	216481.10	-7.39	WB
12908	3625279.52	216484.71	-7.38	WB
12909	3625279.31	216488.34	-7.38	WB
12910	3625279.10	216492.07	-7.37	WB
12911	3625278.94	216495.74	-7.37	WB
12912	3625278.80	216499.37	-7.36	WB
12913	3625278.65	216503.12	-7.36	WB
12914	3625278.61	216503.99	-7.35	WB
12915	3625278.49	216506.76	-7.34	WB
12916	3625278.34	216510.40	-7.34	WB
12917	3625278.17	216513.92	-7.33	WB
12918	3625278.02	216517.46	-7.32	WB
12919	3625277.85	216520.89	-7.32	WB
12920	3625277.67	216524.24	-7.31	WB
12921	3625277.48	216527.59	-7.30	WB
12922	3625277.44	216528.40	-7.29	WB
12923	3625277.34	216530.80	-7.28	WB
12924	3625277.18	216534.03	-7.27	WB
12925	3625277.02	216537.23	-7.26	WB
12926	3625276.86	216540.38	-7.25	WB
12927	3625276.69	216543.73	-7.24	WB
12928	3625276.57	216546.94	-7.23	WB
12929	3625276.44	216550.18	-7.22	WB
12930	3625276.39	216553.55	-7.21	WB
12931	3625276.39	216553.93	-7.20	WB
12932	3625276.39	216556.76	-7.19	WB
12933	3625276.43	216560.00	-7.18	WB
12934	3625276.61	216563.18	-7.17	WB
12935	3625276.79	216566.28	-7.16	WB
12936	3625277.15	216569.36	-7.15	WB
12937	3625277.55	216572.29	-7.14	WB
12938	3625278.02	216575.26	-7.13	WB
12939	3625278.60	216578.25	-7.12	WB
12940	3625278.90	216579.77	-7.11	WB
12941	3625279.18	216581.25	-7.10	WB
12942	3625279.82	216584.41	-7.10	WB
12943	3625280.46	216587.57	-7.09	WB
12944	3625281.17	216590.87	-7.08	WB
12945	3625281.93	216594.12	-7.07	WB
12946	3625282.70	216597.37	-7.06	WB
12947	3625283.49	216600.72	-7.06	WB
12948	3625284.28	216603.93	-7.05	WB
12949	3625284.48	216604.75	-7.04	WB
12950	3625285.11	216607.20	-7.04	WB
12951	3625285.94	216610.35	-7.03	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
12952	3625286.76	216613.46	-7.02	WB
12953	3625287.46	216616.55	-7.02	WB
12954	3625288.14	216619.64	-7.01	WB
12955	3625288.70	216622.66	-7.00	WB
12956	3625289.17	216625.64	-6.99	WB
12957	3625289.61	216628.62	-6.99	WB
12958	3625289.85	216631.55	-6.98	WB
12959	3625290.09	216634.49	-6.97	WB
12960	3625290.22	216637.42	-6.96	WB
12961	3625290.30	216640.34	-6.95	WB
12962	3625290.37	216643.28	-6.95	WB
12963	3625290.36	216646.30	-6.94	WB
12964	3625290.36	216649.32	-6.93	WB
12965	3625290.31	216652.52	-6.92	WB
12966	3625290.29	216653.28	-6.91	WB
12967	3625290.24	216655.65	-6.90	WB
12968	3625290.11	216658.90	-6.88	WB
12969	3625289.89	216662.32	-6.87	WB
12970	3625289.68	216665.64	-6.86	WB
12971	3625289.34	216669.16	-6.85	WB
12972	3625288.99	216672.65	-6.83	WB
12973	3625288.56	216676.13	-6.82	WB
12974	3625288.30	216677.90	-6.81	WB
12975	3625288.03	216679.69	-6.79	WB
12976	3625287.49	216683.21	-6.78	WB
12977	3625286.85	216686.55	-6.76	WB
12978	3625286.20	216689.90	-6.75	WB
12979	3625285.53	216693.15	-6.73	WB
12980	3625284.87	216696.25	-6.72	WB
12981	3625284.19	216699.36	-6.70	WB
12982	3625283.47	216702.38	-6.68	WB
12983	3625283.37	216702.79	-6.67	WB
12984	3625282.76	216705.33	-6.65	WB
12985	3625282.03	216708.30	-6.64	WB
12986	3625281.32	216711.19	-6.62	WB
12987	3625280.61	216714.04	-6.60	WB
12988	3625279.92	216717.02	-6.59	WB
12989	3625279.24	216719.95	-6.57	WB
12990	3625278.63	216722.97	-6.56	WB
12991	3625278.05	216726.06	-6.54	WB
12992	3625277.57	216728.71	-6.52	WB
12993	3625277.51	216729.13	-6.51	WB
12994	3625277.06	216732.32	-6.49	WB
12995	3625276.61	216735.48	-6.48	WB
12996	3625276.37	216738.69	-6.46	WB
12997	3625276.18	216741.90	-6.45	WB
12998	3625276.04	216745.17	-6.43	WB
12999	3625275.98	216748.56	-6.42	WB
13000	3625275.92	216751.89	-6.40	WB
13001	3625275.94	216754.08	-6.39	WB
13002	3625275.96	216755.40	-6.38	WB
13003	3625276.02	216758.99	-6.36	WB
13004	3625276.10	216762.51	-6.35	WB
13005	3625276.23	216766.16	-6.33	WB
13006	3625276.36	216769.75	-6.32	WB
13007	3625276.59	216773.22	-6.30	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
13008	3625276.84	216776.69	-6.29	WB
13009	3625277.04	216779.22	-6.27	WB
13010	3625277.13	216780.08	-6.26	WB
13011	3625277.46	216783.47	-6.24	WB
13012	3625277.79	216786.85	-6.23	WB
13013	3625278.09	216790.03	-6.21	WB
13014	3625278.39	216793.18	-6.20	WB
13015	3625278.71	216796.25	-6.18	WB
13016	3625279.04	216799.30	-6.17	WB
13017	3625279.37	216802.27	-6.15	WB
13018	3625279.52	216803.77	-6.13	WB
13019	3625279.67	216805.23	-6.11	WB
13020	3625279.96	216808.25	-6.10	WB
13021	3625280.19	216811.28	-6.08	WB
13022	3625280.39	216814.50	-6.06	WB
13023	3625280.56	216817.59	-6.04	WB
13024	3625280.68	216820.81	-6.02	WB
13025	3625280.81	216824.17	-6.00	WB
13026	3625280.96	216827.54	-5.99	WB
13027	3625281.03	216829.22	-5.97	WB
13028	3625281.12	216830.99	-5.95	WB
13029	3625281.29	216834.39	-5.93	WB
13030	3625281.47	216837.74	-5.91	WB
13031	3625281.66	216841.13	-5.88	WB
13032	3625281.90	216844.51	-5.86	WB
13033	3625282.15	216847.88	-5.83	WB
13034	3625282.41	216851.26	-5.81	WB
13035	3625282.63	216854.21	-5.78	WB
13036	3625282.66	216854.60	-5.76	WB
13037	3625282.91	216857.93	-5.73	WB
13038	3625283.19	216861.11	-5.70	WB
13039	3625283.50	216864.41	-5.67	WB
13040	3625283.79	216867.51	-5.63	WB
13041	3625284.08	216870.68	-5.60	WB
13042	3625284.38	216873.87	-5.57	WB
13043	3625284.55	216876.88	-5.53	WB
13044	3625284.67	216878.80	-5.49	WB
13045	3625284.74	216879.93	-5.45	WB
13046	3625284.88	216882.96	-5.41	WB
13047	3625284.98	216885.99	-5.37	WB
13048	3625285.05	216889.04	-5.33	WB
13049	3625285.03	216892.04	-5.29	WB
13050	3625284.99	216895.07	-5.24	WB
13051	3625284.95	216898.09	-5.20	WB
13052	3625284.91	216901.15	-5.16	WB
13053	3625284.88	216903.48	-5.12	WB
13054	3625284.85	216904.17	-5.07	WB
13055	3625284.74	216907.24	-5.02	WB
13056	3625284.62	216910.35	-4.98	WB
13057	3625284.51	216913.42	-4.93	WB
13058	3625284.40	216916.56	-4.88	WB
13059	3625284.25	216919.79	-4.83	WB
13060	3625284.05	216922.98	-4.77	WB
13061	3625283.83	216926.23	-4.72	WB
13062	3625283.69	216928.69	-4.67	WB
13063	3625283.64	216929.57	-4.62	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
13064	3625283.45	216932.82	-4.57	WB
13065	3625283.30	216936.19	-4.52	WB
13066	3625283.20	216939.53	-4.46	WB
13067	3625283.10	216942.88	-4.41	WB
13068	3625283.07	216946.23	-4.35	WB
13069	3625283.04	216949.60	-4.29	WB
13070	3625283.05	216953.00	-4.23	WB
13071	3625283.05	216953.88	-4.18	WB
13072	3625283.07	216956.45	-4.13	WB
13073	3625283.11	216959.89	-4.10	WB
13074	3625283.18	216963.44	-4.08	WB
13075	3625283.26	216966.95	-4.04	WB
13076	3625283.33	216970.45	-4.01	WB
13077	3625283.39	216974.01	-4.00	WB
13078	3625283.45	216977.62	-4.02	WB
13079	3625283.48	216978.95	-4.00	WB
13080	3625283.51	216981.12	-4.00	WB
13081	3625283.59	216984.66	-4.00	WB
13082	3625283.63	216988.29	-3.99	WB
13083	3625283.64	216991.77	-4.00	WB
13084	3625283.64	216995.43	-4.02	WB
13085	3625283.56	216998.91	-4.07	WB
13086	3625283.48	217002.39	-4.11	WB
13087	3625283.46	217003.33	-4.14	WB
13088	3625283.34	217005.94	-4.22	WB
13089	3625283.17	217009.43	-4.29	WB
13090	3625282.97	217012.98	-4.37	WB
13091	3625282.68	217016.47	-4.46	WB
13092	3625282.38	217019.93	-4.54	WB
13093	3625282.00	217023.46	-4.66	WB
13094	3625281.60	217026.95	-4.78	WB
13095	3625281.46	217028.21	-4.93	WB
13096	3625281.18	217030.40	-5.10	WB
13097	3625280.72	217033.88	-5.28	WB
13098	3625280.26	217037.36	-5.47	WB
13099	3625279.84	217040.65	-5.64	WB
13100	3625279.41	217043.98	-5.81	WB
13101	3625278.96	217047.34	-5.96	WB
13102	3625278.53	217050.54	-6.07	WB
13103	3625278.13	217053.46	-6.17	WB
13104	3625278.08	217053.85	-6.19	WB
13105	3625277.69	217057.06	-6.17	WB
13106	3625277.30	217060.22	-6.12	WB
13107	3625276.92	217063.45	-6.07	WB
13108	3625276.57	217066.55	-6.00	WB
13109	3625276.23	217069.70	-5.93	WB
13110	3625276.05	217072.80	-5.87	WB
13111	3625275.87	217075.76	-5.79	WB
13112	3625275.87	217078.74	-5.68	WB
13113	3625275.88	217079.09	-5.60	WB
13114	3625275.96	217081.73	-5.53	WB
13115	3625276.11	217084.62	-5.47	WB
13116	3625276.44	217087.53	-5.41	WB
13117	3625276.79	217090.43	-5.37	WB
13118	3625277.29	217093.30	-5.33	WB
13119	3625277.85	217096.15	-5.30	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
13120	3625278.46	217099.05	-5.30	WB
13121	3625279.15	217101.99	-5.32	WB
13122	3625279.77	217104.64	-5.37	WB
13123	3625279.85	217104.99	-5.41	WB
13124	3625280.60	217108.22	-5.47	WB
13125	3625281.34	217111.37	-5.51	WB
13126	3625282.11	217114.67	-5.56	WB
13127	3625282.93	217118.14	-5.59	WB
13128	3625283.74	217121.48	-5.63	WB
13129	3625284.60	217125.01	-5.67	WB
13130	3625285.46	217128.43	-5.69	WB
13131	3625285.76	217129.64	-5.68	WB
13132	3625286.24	217131.77	-5.67	WB
13133	3625287.01	217135.27	-5.64	WB
13134	3625287.75	217138.72	-5.61	WB
13135	3625288.31	217142.17	-5.58	WB
13136	3625288.87	217145.63	-5.53	WB
13137	3625289.31	217149.05	-5.48	WB
13138	3625289.67	217152.46	-5.41	WB
13139	3625289.80	217153.74	-5.33	WB
13140	3625290.00	217155.91	-5.26	WB
13141	3625290.19	217159.25	-5.18	WB
13142	3625290.38	217162.58	-5.10	WB
13143	3625290.52	217165.76	-5.02	WB
13144	3625290.65	217168.92	-4.94	WB
13145	3625290.76	217171.96	-4.87	WB
13146	3625290.86	217174.88	-4.80	WB
13147	3625290.94	217177.68	-4.73	WB
13148	3625290.97	217178.41	-4.68	WB
13149	3625290.95	217180.39	-4.62	WB
13150	3625290.92	217183.07	-4.58	WB
13151	3625290.86	217185.66	-4.52	WB
13152	3625290.72	217188.29	-4.47	WB
13153	3625290.57	217190.88	-4.41	WB
13154	3625290.30	217193.47	-4.34	WB
13155	3625290.00	217196.16	-4.29	WB
13156	3625289.71	217198.86	-4.23	WB
13157	3625289.44	217201.59	-4.17	WB
13158	3625289.24	217203.63	-4.12	WB
13159	3625289.18	217204.31	-4.07	WB
13160	3625288.96	217207.12	-4.02	WB
13161	3625288.75	217209.89	-3.98	WB
13162	3625288.58	217212.69	-3.93	WB
13163	3625288.44	217215.51	-3.91	WB
13164	3625288.32	217218.31	-3.88	WB
13165	3625288.17	217221.12	-3.84	WB
13166	3625288.03	217223.92	-3.83	WB
13167	3625287.88	217226.73	-3.79	WB
13168	3625287.80	217228.16	-3.74	WB
13169	3625287.71	217229.59	-3.70	WB
13170	3625287.52	217232.42	-3.66	WB
13171	3625287.25	217235.26	-3.60	WB
13172	3625286.97	217238.11	-3.59	WB
13173	3625286.66	217241.00	-3.53	WB
13174	3625286.33	217243.97	-3.46	WB
13175	3625286.01	217246.88	-3.39	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
13176	3625285.69	217249.91	-3.32	WB
13177	3625285.37	217252.98	-3.24	WB
13178	3625285.33	217253.34	-3.17	WB
13179	3625285.08	217255.92	-3.06	WB
13180	3625284.79	217258.95	-2.86	WB
13181	3625284.52	217261.94	-2.67	WB
13182	3625284.29	217264.90	-2.54	WB
13183	3625284.05	217268.01	-2.43	WB
13184	3625283.83	217271.06	-2.40	WB
13185	3624779.65	215731.90	-8.68	WB
13186	3624779.19	215734.56	-8.67	WB
13187	3624778.74	215737.17	-8.66	WB
13188	3624778.38	215739.75	-8.66	WB
13189	3624778.06	215742.38	-8.65	WB
13190	3624777.77	215744.95	-8.65	WB
13191	3624777.53	215747.65	-8.65	WB
13192	3624777.28	215750.41	-8.65	WB
13193	3624777.13	215753.23	-8.65	WB
13194	3624777.02	215756.20	-8.65	WB
13195	3624776.92	215759.17	-8.65	WB
13196	3624776.87	215762.23	-8.65	WB
13197	3624776.83	215765.01	-8.65	WB
13198	3624776.83	215765.38	-8.65	WB
13199	3624776.86	215768.54	-8.64	WB
13200	3624776.93	215771.72	-8.64	WB
13201	3624777.02	215774.88	-8.64	WB
13202	3624777.17	215777.99	-8.64	WB
13203	3624777.34	215781.09	-8.64	WB
13204	3624777.47	215784.19	-8.64	WB
13205	3624777.60	215787.30	-8.64	WB
13206	3624777.68	215789.67	-8.64	WB
13207	3624777.69	215790.41	-8.64	WB
13208	3624777.73	215793.56	-8.63	WB
13209	3624777.77	215796.62	-8.63	WB
13210	3624777.80	215799.80	-8.63	WB
13211	3624777.82	215802.96	-8.63	WB
13212	3624777.76	215806.21	-8.63	WB
13213	3624777.65	215809.49	-8.62	WB
13214	3624777.54	215812.77	-8.62	WB
13215	3624777.49	215814.83	-8.62	WB
13216	3624777.46	215816.06	-8.62	WB
13217	3624777.37	215819.40	-8.61	WB
13218	3624777.27	215822.64	-8.61	WB
13219	3624777.18	215825.92	-8.61	WB
13220	3624777.08	215829.27	-8.60	WB
13221	3624777.03	215832.53	-8.60	WB
13222	3624776.99	215835.88	-8.59	WB
13223	3624776.99	215839.18	-8.59	WB
13224	3624777.00	215840.02	-8.59	WB
13225	3624777.02	215842.42	-8.58	WB
13226	3624777.07	215845.79	-8.58	WB
13227	3624777.14	215849.05	-8.57	WB
13228	3624777.20	215852.42	-8.57	WB
13229	3624777.25	215855.72	-8.56	WB
13230	3624777.30	215858.97	-8.55	WB
13231	3624777.30	215862.38	-8.55	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
13232	3624777.28	215864.80	-8.54	WB
13233	3624777.27	215865.69	-8.54	WB
13234	3624777.24	215868.99	-8.53	WB
13235	3624777.27	215872.17	-8.53	WB
13236	3624777.30	215875.36	-8.52	WB
13237	3624777.31	215878.46	-8.51	WB
13238	3624777.31	215881.49	-8.51	WB
13239	3624777.30	215884.56	-8.50	WB
13240	3624777.47	215887.54	-8.50	WB
13241	3624777.58	215889.78	-8.49	WB
13242	3624777.61	215890.55	-8.49	WB
13243	3624777.76	215893.61	-8.48	WB
13244	3624777.91	215896.73	-8.48	WB
13245	3624778.06	215899.92	-8.47	WB
13246	3624778.22	215903.10	-8.47	WB
13247	3624778.39	215906.30	-8.46	WB
13248	3624778.57	215909.50	-8.46	WB
13249	3624778.76	215912.60	-8.45	WB
13250	3624778.91	215914.99	-8.45	WB
13251	3624778.97	215915.79	-8.45	WB
13252	3624779.18	215918.91	-8.44	WB
13253	3624779.39	215922.01	-8.44	WB
13254	3624779.56	215925.27	-8.43	WB
13255	3624779.70	215928.52	-8.43	WB
13256	3624779.82	215931.76	-8.43	WB
13257	3624779.89	215935.17	-8.42	WB
13258	3624779.96	215938.52	-8.42	WB
13259	3624779.99	215939.77	-8.41	WB
13260	3624780.02	215941.86	-8.41	WB
13261	3624780.07	215945.16	-8.40	WB
13262	3624780.12	215948.39	-8.40	WB
13263	3624780.16	215951.50	-8.39	WB
13264	3624780.21	215954.62	-8.39	WB
13265	3624780.21	215957.64	-8.38	WB
13266	3624780.19	215960.61	-8.38	WB
13267	3624780.10	215963.63	-8.37	WB
13268	3624780.07	215963.98	-8.37	WB
13269	3624779.92	215966.56	-8.36	WB
13270	3624779.72	215969.56	-8.36	WB
13271	3624779.33	215972.65	-8.35	WB
13272	3624778.93	215975.71	-8.35	WB
13273	3624778.52	215978.80	-8.34	WB
13274	3624778.11	215981.91	-8.34	WB
13275	3624777.68	215985.05	-8.33	WB
13276	3624777.24	215988.32	-8.33	WB
13277	3624777.06	215989.59	-8.32	WB
13278	3624776.78	215991.65	-8.32	WB
13279	3624776.42	215994.90	-8.31	WB
13280	3624776.10	215998.19	-8.31	WB
13281	3624775.80	216001.49	-8.30	WB
13282	3624775.55	216004.74	-8.30	WB
13283	3624775.30	216008.04	-8.30	WB
13284	3624775.12	216011.36	-8.29	WB
13285	3624774.97	216014.61	-8.29	WB
13286	3624774.95	216015.00	-8.29	WB
13287	3624774.86	216017.87	-8.28	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
13288	3624774.84	216021.10	-8.28	WB
13289	3624774.82	216024.32	-8.28	WB
13290	3624774.89	216027.59	-8.28	WB
13291	3624774.98	216030.74	-8.27	WB
13292	3624775.12	216033.93	-8.27	WB
13293	3624775.32	216037.13	-8.27	WB
13294	3624775.50	216039.81	-8.27	WB
13295	3624775.52	216040.23	-8.26	WB
13296	3624775.75	216043.47	-8.26	WB
13297	3624775.98	216046.67	-8.26	WB
13298	3624776.20	216049.85	-8.26	WB
13299	3624776.43	216053.17	-8.25	WB
13300	3624776.65	216056.44	-8.25	WB
13301	3624776.81	216059.78	-8.25	WB
13302	3624776.96	216063.11	-8.24	WB
13303	3624777.04	216064.75	-8.24	WB
13304	3624777.13	216066.43	-8.24	WB
13305	3624777.31	216069.73	-8.23	WB
13306	3624777.49	216073.01	-8.23	WB
13307	3624777.64	216076.24	-8.22	WB
13308	3624777.78	216079.45	-8.22	WB
13309	3624777.90	216082.65	-8.21	WB
13310	3624778.02	216085.92	-8.21	WB
13311	3624778.14	216089.08	-8.21	WB
13312	3624778.17	216089.94	-8.20	WB
13313	3624778.24	216092.33	-8.19	WB
13314	3624778.35	216095.52	-8.19	WB
13315	3624778.49	216098.64	-8.18	WB
13316	3624778.65	216101.87	-8.18	WB
13317	3624778.81	216104.91	-8.17	WB
13318	3624779.00	216108.06	-8.17	WB
13319	3624779.19	216111.24	-8.16	WB
13320	3624779.44	216114.41	-8.16	WB
13321	3624779.47	216114.83	-8.15	WB
13322	3624779.70	216117.64	-8.14	WB
13323	3624779.94	216120.82	-8.14	WB
13324	3624780.17	216123.98	-8.13	WB
13325	3624780.40	216127.15	-8.13	WB
13326	3624780.60	216130.26	-8.12	WB
13327	3624780.81	216133.35	-8.12	WB
13328	3624781.02	216136.41	-8.11	WB
13329	3624781.23	216139.47	-8.10	WB
13330	3624781.43	216142.54	-8.10	WB
13331	3624781.46	216145.66	-8.09	WB
13332	3624781.48	216148.79	-8.09	WB
13333	3624781.49	216151.95	-8.08	WB
13334	3624781.48	216155.27	-8.07	WB
13335	3624781.48	216158.49	-8.07	WB
13336	3624781.44	216161.83	-8.06	WB
13337	3624781.41	216164.76	-8.06	WB
13338	3624781.40	216165.21	-8.05	WB
13339	3624781.36	216168.53	-8.04	WB
13340	3624781.31	216171.96	-8.04	WB
13341	3624781.29	216175.35	-8.03	WB
13342	3624781.32	216178.61	-8.03	WB
13343	3624781.36	216181.94	-8.02	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
13344	3624781.37	216185.11	-8.01	WB
13345	3624781.36	216188.25	-8.01	WB
13346	3624781.36	216189.41	-8.00	WB
13347	3624781.35	216191.35	-7.99	WB
13348	3624781.34	216194.40	-7.98	WB
13349	3624781.32	216197.45	-7.98	WB
13350	3624781.23	216200.58	-7.97	WB
13351	3624781.13	216203.73	-7.96	WB
13352	3624781.00	216206.92	-7.95	WB
13353	3624780.83	216210.14	-7.95	WB
13354	3624780.65	216213.37	-7.94	WB
13355	3624780.58	216214.59	-7.93	WB
13356	3624780.48	216216.63	-7.92	WB
13357	3624780.30	216219.96	-7.91	WB
13358	3624780.12	216223.19	-7.91	WB
13359	3624779.93	216226.48	-7.90	WB
13360	3624779.74	216229.78	-7.89	WB
13361	3624779.55	216233.04	-7.88	WB
13362	3624779.36	216236.34	-7.88	WB
13363	3624779.18	216239.59	-7.87	WB
13364	3624779.02	216242.84	-7.86	WB
13365	3624778.86	216246.09	-7.85	WB
13366	3624778.73	216249.27	-7.85	WB
13367	3624778.61	216252.44	-7.84	WB
13368	3624778.55	216255.56	-7.83	WB
13369	3624778.54	216258.59	-7.83	WB
13370	3624778.51	216261.64	-7.82	WB
13371	3624778.41	216264.72	-7.81	WB
13372	3624778.30	216267.87	-7.81	WB
13373	3624778.23	216270.91	-7.80	WB
13374	3624778.17	216273.99	-7.80	WB
13375	3624778.07	216277.15	-7.79	WB
13376	3624777.89	216280.28	-7.78	WB
13377	3624777.70	216283.52	-7.78	WB
13378	3624777.59	216286.79	-7.77	WB
13379	3624777.51	216289.64	-7.77	WB
13380	3624777.50	216290.02	-7.76	WB
13381	3624777.39	216293.42	-7.75	WB
13382	3624777.26	216296.86	-7.74	WB
13383	3624777.12	216300.31	-7.74	WB
13384	3624777.10	216303.85	-7.73	WB
13385	3624777.10	216307.43	-7.72	WB
13386	3624777.18	216310.97	-7.71	WB
13387	3624777.33	216314.48	-7.70	WB
13388	3624777.37	216315.32	-7.70	WB
13389	3624777.49	216317.99	-7.69	WB
13390	3624777.71	216321.39	-7.68	WB
13391	3624777.93	216324.88	-7.67	WB
13392	3624778.23	216328.23	-7.66	WB
13393	3624778.61	216331.58	-7.65	WB
13394	3624779.00	216335.01	-7.64	WB
13395	3624779.31	216338.22	-7.63	WB
13396	3624779.51	216340.26	-7.62	WB
13397	3624779.64	216341.47	-7.61	WB
13398	3624780.05	216344.63	-7.60	WB
13399	3624780.49	216347.62	-7.59	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
13400	3624780.96	216350.65	-7.58	WB
13401	3624781.40	216353.56	-7.57	WB
13402	3624781.84	216356.43	-7.56	WB
13403	3624782.16	216359.34	-7.55	WB
13404	3624782.44	216362.18	-7.55	WB
13405	3624782.67	216364.61	-7.54	WB
13406	3624782.69	216364.93	-7.53	WB
13407	3624782.88	216367.59	-7.53	WB
13408	3624783.07	216370.25	-7.52	WB
13409	3624783.16	216372.84	-7.52	WB
13410	3624783.23	216375.46	-7.51	WB
13411	3624783.20	216378.24	-7.51	WB
13412	3624783.03	216381.03	-7.50	WB
13413	3624782.84	216383.83	-7.50	WB
13414	3624782.46	216386.86	-7.50	WB
13415	3624782.15	216389.11	-7.50	WB
13416	3624782.05	216389.87	-7.49	WB
13417	3624781.58	216392.93	-7.49	WB
13418	3624781.02	216396.08	-7.49	WB
13419	3624780.47	216399.23	-7.49	WB
13420	3624779.84	216402.37	-7.49	WB
13421	3624779.18	216405.58	-7.49	WB
13422	3624778.48	216408.93	-7.49	WB
13423	3624777.77	216412.24	-7.49	WB
13424	3624777.41	216413.96	-7.49	WB
13425	3624777.05	216415.63	-7.48	WB
13426	3624776.34	216419.17	-7.48	WB
13427	3624775.63	216422.63	-7.48	WB
13428	3624774.89	216426.30	-7.48	WB
13429	3624774.15	216429.92	-7.47	WB
13430	3624773.44	216433.51	-7.47	WB
13431	3624772.78	216437.28	-7.46	WB
13432	3624772.38	216439.61	-7.46	WB
13433	3624772.14	216441.00	-7.45	WB
13434	3624771.59	216444.67	-7.44	WB
13435	3624771.09	216448.31	-7.44	WB
13436	3624770.66	216451.91	-7.43	WB
13437	3624770.37	216455.43	-7.42	WB
13438	3624770.09	216458.99	-7.41	WB
13439	3624770.00	216462.34	-7.40	WB
13440	3624769.95	216465.32	-7.38	WB
13441	3624769.94	216465.72	-7.37	WB
13442	3624769.93	216469.08	-7.36	WB
13443	3624769.99	216472.36	-7.34	WB
13444	3624770.05	216475.64	-7.33	WB
13445	3624770.26	216478.89	-7.31	WB
13446	3624770.50	216482.02	-7.30	WB
13447	3624770.79	216485.19	-7.28	WB
13448	3624771.17	216488.39	-7.27	WB
13449	3624771.41	216490.32	-7.25	WB
13450	3624771.55	216491.49	-7.24	WB
13451	3624772.00	216494.53	-7.22	WB
13452	3624772.47	216497.66	-7.21	WB
13453	3624772.97	216500.73	-7.19	WB
13454	3624773.49	216503.85	-7.18	WB
13455	3624774.01	216506.90	-7.16	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
13456	3624774.54	216509.89	-7.15	WB
13457	3624775.08	216512.86	-7.14	WB
13458	3624775.56	216515.41	-7.12	WB
13459	3624775.63	216515.81	-7.11	WB
13460	3624776.20	216518.69	-7.10	WB
13461	3624776.77	216521.59	-7.09	WB
13462	3624777.36	216524.53	-7.08	WB
13463	3624777.93	216527.37	-7.07	WB
13464	3624778.48	216530.28	-7.07	WB
13465	3624779.02	216533.25	-7.06	WB
13466	3624779.54	216536.18	-7.05	WB
13467	3624779.99	216539.21	-7.05	WB
13468	3624780.16	216540.32	-7.04	WB
13469	3624780.44	216542.18	-7.04	WB
13470	3624780.84	216545.20	-7.03	WB
13471	3624781.26	216548.34	-7.03	WB
13472	3624781.63	216551.45	-7.02	WB
13473	3624781.93	216554.73	-7.02	WB
13474	3624782.22	216558.03	-7.01	WB
13475	3624782.43	216561.51	-7.01	WB
13476	3624782.62	216564.97	-7.00	WB
13477	3624782.79	216568.53	-7.00	WB
13478	3624782.93	216572.25	-6.99	WB
13479	3624783.06	216575.96	-6.99	WB
13480	3624783.10	216579.69	-6.98	WB
13481	3624783.15	216583.45	-6.98	WB
13482	3624783.19	216587.18	-6.97	WB
13483	3624783.21	216589.50	-6.96	WB
13484	3624783.22	216590.93	-6.95	WB
13485	3624783.25	216594.54	-6.94	WB
13486	3624783.21	216598.04	-6.93	WB
13487	3624783.17	216601.60	-6.92	WB
13488	3624783.10	216605.01	-6.91	WB
13489	3624783.00	216608.45	-6.90	WB
13490	3624782.92	216611.81	-6.89	WB
13491	3624782.85	216614.63	-6.87	WB
13492	3624782.84	216615.02	-6.86	WB
13493	3624782.76	216618.33	-6.85	WB
13494	3624782.67	216621.52	-6.83	WB
13495	3624782.57	216624.63	-6.82	WB
13496	3624782.47	216627.78	-6.81	WB
13497	3624782.38	216630.91	-6.79	WB
13498	3624782.29	216633.95	-6.78	WB
13499	3624782.20	216636.96	-6.77	WB
13500	3624782.12	216639.62	-6.75	WB
13501	3624782.11	216640.03	-6.74	WB
13502	3624782.01	216643.00	-6.73	WB
13503	3624781.89	216645.95	-6.72	WB
13504	3624781.78	216648.89	-6.71	WB
13505	3624781.66	216651.91	-6.70	WB
13506	3624781.53	216654.97	-6.69	WB
13507	3624781.39	216657.91	-6.68	WB
13508	3624781.20	216660.96	-6.67	WB
13509	3624781.02	216664.05	-6.66	WB
13510	3624780.98	216664.84	-6.65	WB
13511	3624780.86	216667.22	-6.65	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
13512	3624780.71	216670.46	-6.64	WB
13513	3624780.56	216673.71	-6.63	WB
13514	3624780.42	216676.98	-6.63	WB
13515	3624780.28	216680.30	-6.62	WB
13516	3624780.20	216683.75	-6.62	WB
13517	3624780.11	216687.19	-6.61	WB
13518	3624780.03	216689.81	-6.60	WB
13519	3624779.99	216690.77	-6.60	WB
13520	3624779.85	216694.30	-6.59	WB
13521	3624779.69	216697.98	-6.58	WB
13522	3624779.49	216701.70	-6.58	WB
13523	3624779.29	216705.43	-6.57	WB
13524	3624779.06	216709.21	-6.56	WB
13525	3624778.84	216713.03	-6.55	WB
13526	3624778.72	216714.90	-6.54	WB
13527	3624778.59	216716.83	-6.53	WB
13528	3624778.30	216720.62	-6.52	WB
13529	3624778.01	216724.41	-6.51	WB
13530	3624777.79	216728.19	-6.50	WB
13531	3624777.61	216731.90	-6.48	WB
13532	3624777.44	216735.50	-6.47	WB
13533	3624777.31	216739.06	-6.46	WB
13534	3624777.28	216739.95	-6.44	WB
13535	3624777.18	216742.67	-6.43	WB
13536	3624777.16	216745.99	-6.41	WB
13537	3624777.17	216749.74	-6.39	WB
13538	3624777.22	216753.07	-6.38	WB
13539	3624777.32	216756.17	-6.36	WB
13540	3624777.42	216759.36	-6.34	WB
13541	3624777.61	216762.46	-6.32	WB
13542	3624777.75	216764.79	-6.31	WB
13543	3624777.80	216765.58	-6.29	WB
13544	3624778.02	216768.69	-6.27	WB
13545	3624778.27	216771.84	-6.26	WB
13546	3624778.52	216774.87	-6.24	WB
13547	3624778.82	216777.93	-6.22	WB
13548	3624779.13	216781.04	-6.21	WB
13549	3624779.45	216784.03	-6.19	WB
13550	3624779.79	216787.10	-6.17	WB
13551	3624780.13	216790.11	-6.16	WB
13552	3624780.48	216793.06	-6.15	WB
13553	3624780.84	216796.06	-6.13	WB
13554	3624781.24	216799.14	-6.12	WB
13555	3624781.64	216802.14	-6.10	WB
13556	3624782.02	216805.35	-6.09	WB
13557	3624782.34	216808.48	-6.08	WB
13558	3624782.66	216811.60	-6.07	WB
13559	3624782.92	216814.91	-6.06	WB
13560	3624782.95	216815.31	-6.05	WB
13561	3624783.18	216818.20	-6.04	WB
13562	3624783.41	216821.57	-6.03	WB
13563	3624783.58	216824.92	-6.02	WB
13564	3624783.76	216828.25	-6.01	WB
13565	3624783.86	216831.55	-6.00	WB
13566	3624783.97	216834.84	-5.99	WB
13567	3624784.01	216838.06	-5.98	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
13568	3624783.99	216839.30	-5.97	WB
13569	3624783.97	216841.25	-5.96	WB
13570	3624783.90	216844.51	-5.95	WB
13571	3624783.65	216847.67	-5.94	WB
13572	3624783.38	216850.91	-5.93	WB
13573	3624782.99	216854.22	-5.92	WB
13574	3624782.53	216857.49	-5.91	WB
13575	3624782.02	216860.85	-5.89	WB
13576	3624781.45	216863.85	-5.88	WB
13577	3624781.37	216864.31	-5.86	WB
13578	3624780.73	216867.67	-5.85	WB
13579	3624780.00	216871.16	-5.83	WB
13580	3624779.26	216874.59	-5.81	WB
13581	3624778.54	216878.00	-5.79	WB
13582	3624777.83	216881.46	-5.76	WB
13583	3624777.13	216884.86	-5.73	WB
13584	3624776.44	216888.18	-5.70	WB
13585	3624776.26	216889.02	-5.67	WB
13586	3624775.75	216891.50	-5.64	WB
13587	3624775.07	216894.77	-5.60	WB
13588	3624774.43	216897.99	-5.55	WB
13589	3624773.79	216901.21	-5.51	WB
13590	3624773.20	216904.36	-5.46	WB
13591	3624772.62	216907.46	-5.41	WB
13592	3624772.04	216910.61	-5.35	WB
13593	3624771.50	216913.64	-5.30	WB
13594	3624771.36	216914.43	-5.24	WB
13595	3624770.95	216916.72	-5.18	WB
13596	3624770.60	216919.84	-5.12	WB
13597	3624770.26	216922.87	-5.06	WB
13598	3624769.99	216925.94	-5.00	WB
13599	3624769.76	216929.03	-4.94	WB
13600	3624769.56	216932.03	-4.88	WB
13601	3624769.51	216935.08	-4.82	WB
13602	3624769.46	216938.08	-4.77	WB
13603	3624769.49	216940.29	-4.71	WB
13604	3624769.52	216941.00	-4.66	WB
13605	3624769.64	216944.02	-4.60	WB
13606	3624769.77	216946.98	-4.55	WB
13607	3624769.98	216950.02	-4.51	WB
13608	3624770.19	216953.07	-4.46	WB
13609	3624770.49	216956.19	-4.42	WB
13610	3624770.82	216959.33	-4.37	WB
13611	3624771.19	216962.55	-4.33	WB
13612	3624771.66	216965.91	-4.29	WB
13613	3624772.12	216969.25	-4.25	WB
13614	3624772.73	216972.79	-4.22	WB
13615	3624773.36	216976.25	-4.19	WB
13616	3624774.05	216979.82	-4.16	WB
13617	3624774.79	216983.41	-4.12	WB
13618	3624775.53	216986.85	-4.09	WB
13619	3624776.32	216990.20	-4.06	WB
13620	3624776.63	216991.48	-4.03	WB
13621	3624777.13	216993.53	-4.00	WB
13622	3624777.94	216996.57	-3.97	WB
13623	3624778.81	216999.54	-3.95	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
13624	3624779.66	217002.34	-3.94	WB
13625	3624780.39	217004.94	-3.91	WB
13626	3624781.13	217007.64	-3.92	WB
13627	3624781.72	217010.25	-3.91	WB
13628	3624782.18	217012.87	-3.91	WB
13629	3624782.52	217014.84	-3.91	WB
13630	3624782.61	217015.52	-3.91	WB
13631	3624782.89	217018.23	-3.93	WB
13632	3624783.15	217020.97	-3.93	WB
13633	3624783.29	217023.74	-3.94	WB
13634	3624783.37	217026.60	-3.98	WB
13635	3624783.43	217029.43	-3.99	WB
13636	3624783.41	217032.33	-4.01	WB
13637	3624783.38	217035.28	-4.03	WB
13638	3624783.30	217038.13	-4.07	WB
13639	3624783.26	217039.23	-4.11	WB
13640	3624783.20	217041.06	-4.16	WB
13641	3624783.10	217043.85	-4.23	WB
13642	3624783.02	217046.61	-4.32	WB
13643	3624782.93	217049.41	-4.39	WB
13644	3624782.82	217052.00	-4.48	WB
13645	3624782.70	217054.71	-4.58	WB
13646	3624782.54	217057.35	-4.70	WB
13647	3624782.34	217059.94	-4.82	WB
13648	3624782.12	217062.60	-4.94	WB
13649	3624781.96	217064.27	-5.07	WB
13650	3624781.86	217065.26	-5.19	WB
13651	3624781.59	217067.92	-5.32	WB
13652	3624781.25	217070.66	-5.47	WB
13653	3624780.85	217073.49	-5.60	WB
13654	3624780.44	217076.32	-5.72	WB
13655	3624780.02	217079.36	-5.82	WB
13656	3624779.58	217082.43	-5.91	WB
13657	3624779.11	217085.64	-6.00	WB
13658	3624778.60	217089.07	-6.04	WB
13659	3624778.48	217089.88	-6.06	WB
13660	3624778.11	217092.48	-6.02	WB
13661	3624777.72	217096.10	-5.97	WB
13662	3624777.33	217099.79	-5.88	WB
13663	3624777.01	217103.49	-5.78	WB
13664	3624776.73	217107.30	-5.69	WB
13665	3624776.47	217111.16	-5.61	WB
13666	3624776.29	217114.94	-5.54	WB
13667	3624776.12	217118.82	-5.53	WB
13668	3624776.01	217122.53	-5.57	WB
13669	3624775.92	217126.09	-5.60	WB
13670	3624775.85	217129.67	-5.61	WB
13671	3624775.83	217133.05	-5.63	WB
13672	3624775.80	217136.44	-5.66	WB
13673	3624775.80	217139.68	-5.67	WB
13674	3624775.81	217142.91	-5.67	WB
13675	3624775.79	217146.14	-5.64	WB
13676	3624775.76	217149.37	-5.58	WB
13677	3624775.71	217152.62	-5.49	WB
13678	3624775.70	217155.88	-5.41	WB
13679	3624775.68	217159.22	-5.37	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
13680	3624775.70	217162.59	-5.33	WB
13681	3624775.74	217165.12	-5.31	WB
13682	3624775.75	217165.93	-5.29	WB
13683	3624775.81	217169.38	-5.25	WB
13684	3624776.02	217172.77	-5.22	WB
13685	3624776.23	217176.10	-5.18	WB
13686	3624776.53	217179.46	-5.14	WB
13687	3624776.89	217182.76	-5.09	WB
13688	3624777.28	217186.07	-5.04	WB
13689	3624777.70	217189.31	-4.99	WB
13690	3624777.85	217190.51	-4.93	WB
13691	3624778.12	217192.53	-4.88	WB
13692	3624778.60	217195.62	-4.83	WB
13693	3624779.11	217198.74	-4.78	WB
13694	3624779.62	217201.85	-4.73	WB
13695	3624780.10	217204.86	-4.68	WB
13696	3624780.58	217207.93	-4.63	WB
13697	3624781.02	217210.79	-4.58	WB
13698	3624781.47	217213.66	-4.53	WB
13699	3624781.70	217215.16	-4.48	WB
13700	3624781.91	217216.55	-4.43	WB
13701	3624782.30	217219.30	-4.39	WB
13702	3624782.69	217222.11	-4.34	WB
13703	3624783.04	217224.94	-4.30	WB
13704	3624783.36	217227.70	-4.27	WB
13705	3624783.68	217230.53	-4.23	WB
13706	3624784.00	217233.30	-4.20	WB
13707	3624784.32	217236.00	-4.17	WB
13708	3624784.59	217238.74	-4.13	WB
13709	3624784.73	217240.05	-4.11	WB
13710	3624784.87	217241.35	-4.08	WB
13711	3624785.13	217244.09	-4.06	WB
13712	3624785.37	217246.75	-4.05	WB
13713	3624785.60	217249.38	-4.04	WB
13714	3624785.66	217252.18	-4.03	WB
13715	3624785.71	217254.97	-4.02	WB
13716	3624785.67	217257.95	-3.99	WB
13717	3624785.57	217261.00	-3.96	WB
13718	3624785.46	217264.08	-3.92	WB
13719	3624785.44	217264.51	-3.87	WB
13720	3624785.28	217267.32	-3.81	WB
13721	3624785.10	217270.57	-3.75	WB
13722	3624784.86	217273.84	-3.68	WB
13723	3624784.57	217277.15	-3.62	WB
13724	3624784.28	217280.49	-3.56	WB
13725	3624783.96	217283.67	-3.50	WB
13726	3624783.64	217286.89	-3.43	WB
13727	3624783.32	217289.31	-3.36	WB
13728	3624783.20	217290.09	-3.28	WB
13729	3624782.75	217293.14	-3.21	WB
13730	3624782.27	217296.17	-3.13	WB
13731	3624781.74	217299.13	-3.05	WB
13732	3624781.21	217302.01	-2.97	WB
13733	3624780.54	217304.86	-2.88	WB
13734	3624779.86	217307.53	-2.80	WB
13735	3624779.17	217310.12	-2.71	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
13736	3624778.39	217312.73	-2.62	WB
13737	3624777.63	217315.25	-2.50	WB
13738	3624295.69	215739.99	-8.85	WB
13739	3624295.32	215741.50	-8.85	WB
13740	3624295.10	215742.40	-8.84	WB
13741	3624294.53	215744.78	-8.84	WB
13742	3624293.92	215747.16	-8.84	WB
13743	3624293.27	215749.52	-8.83	WB
13744	3624292.64	215751.83	-8.83	WB
13745	3624291.94	215754.23	-8.82	WB
13746	3624291.23	215756.62	-8.82	WB
13747	3624290.47	215758.95	-8.82	WB
13748	3624289.62	215761.39	-8.81	WB
13749	3624288.78	215763.72	-8.81	WB
13750	3624287.90	215766.05	-8.81	WB
13751	3624286.97	215768.47	-8.80	WB
13752	3624286.09	215770.94	-8.80	WB
13753	3624285.22	215773.41	-8.80	WB
13754	3624284.34	215776.02	-8.79	WB
13755	3624283.56	215778.59	-8.79	WB
13756	3624282.77	215781.24	-8.79	WB
13757	3624282.18	215783.95	-8.78	WB
13758	3624281.64	215786.62	-8.78	WB
13759	3624281.16	215789.39	-8.78	WB
13760	3624280.79	215792.16	-8.78	WB
13761	3624280.70	215792.82	-8.77	WB
13762	3624280.44	215794.90	-8.77	WB
13763	3624280.20	215797.72	-8.77	WB
13764	3624279.97	215800.56	-8.77	WB
13765	3624279.83	215803.38	-8.76	WB
13766	3624279.78	215806.20	-8.76	WB
13767	3624279.75	215809.00	-8.76	WB
13768	3624279.89	215811.59	-8.76	WB
13769	3624280.02	215814.27	-8.75	WB
13770	3624280.26	215816.81	-8.75	WB
13771	3624280.33	215817.40	-8.75	WB
13772	3624280.56	215819.21	-8.75	WB
13773	3624280.88	215821.69	-8.75	WB
13774	3624281.32	215824.01	-8.74	WB
13775	3624281.75	215826.29	-8.74	WB
13776	3624282.22	215828.64	-8.74	WB
13777	3624282.70	215830.96	-8.74	WB
13778	3624283.17	215833.38	-8.74	WB
13779	3624283.67	215835.95	-8.73	WB
13780	3624284.17	215838.53	-8.73	WB
13781	3624284.61	215841.38	-8.73	WB
13782	3624284.86	215843.19	-8.73	WB
13783	3624285.02	215844.35	-8.73	WB
13784	3624285.46	215847.34	-8.73	WB
13785	3624285.98	215850.42	-8.72	WB
13786	3624286.50	215853.53	-8.72	WB
13787	3624287.11	215856.50	-8.72	WB
13788	3624287.75	215859.44	-8.72	WB
13789	3624288.45	215862.33	-8.72	WB
13790	3624289.20	215864.93	-8.72	WB
13791	3624289.96	215867.45	-8.72	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
13792	3624290.07	215867.79	-8.71	WB
13793	3624290.91	215869.71	-8.71	WB
13794	3624291.89	215871.87	-8.71	WB
13795	3624292.77	215874.00	-8.71	WB
13796	3624293.53	215876.17	-8.71	WB
13797	3624294.26	215878.30	-8.71	WB
13798	3624294.83	215880.51	-8.71	WB
13799	3624295.42	215882.75	-8.71	WB
13800	3624295.85	215885.00	-8.71	WB
13801	3624296.15	215887.37	-8.71	WB
13802	3624296.42	215889.70	-8.70	WB
13803	3624296.45	215891.22	-8.70	WB
13804	3624296.46	215892.13	-8.70	WB
13805	3624296.48	215894.58	-8.70	WB
13806	3624296.33	215897.24	-8.70	WB
13807	3624296.08	215899.97	-8.70	WB
13808	3624295.78	215902.77	-8.70	WB
13809	3624295.29	215905.63	-8.70	WB
13810	3624294.78	215908.55	-8.70	WB
13811	3624294.17	215911.54	-8.69	WB
13812	3624293.53	215914.48	-8.69	WB
13813	3624293.21	215915.95	-8.69	WB
13814	3624292.85	215917.42	-8.69	WB
13815	3624292.04	215920.44	-8.69	WB
13816	3624291.23	215923.43	-8.69	WB
13817	3624290.32	215926.36	-8.68	WB
13818	3624289.38	215929.28	-8.68	WB
13819	3624288.43	215932.20	-8.68	WB
13820	3624287.47	215935.11	-8.68	WB
13821	3624286.50	215938.03	-8.68	WB
13822	3624285.54	215940.95	-8.67	WB
13823	3624285.41	215941.35	-8.67	WB
13824	3624284.58	215943.88	-8.67	WB
13825	3624283.69	215946.82	-8.67	WB
13826	3624282.92	215949.70	-8.66	WB
13827	3624282.14	215952.62	-8.66	WB
13828	3624281.45	215955.75	-8.66	WB
13829	3624280.79	215958.75	-8.65	WB
13830	3624280.18	215961.94	-8.65	WB
13831	3624279.65	215965.17	-8.64	WB
13832	3624279.31	215967.18	-8.64	WB
13833	3624279.13	215968.37	-8.63	WB
13834	3624278.66	215971.87	-8.62	WB
13835	3624278.22	215975.22	-8.62	WB
13836	3624277.85	215978.61	-8.61	WB
13837	3624277.52	215982.18	-8.60	WB
13838	3624277.21	215985.58	-8.59	WB
13839	3624276.94	215988.97	-8.59	WB
13840	3624276.70	215991.95	-8.58	WB
13841	3624276.67	215992.35	-8.57	WB
13842	3624276.46	215995.61	-8.56	WB
13843	3624276.28	215998.77	-8.55	WB
13844	3624276.09	216001.94	-8.54	WB
13845	3624275.89	216005.00	-8.53	WB
13846	3624275.68	216007.97	-8.51	WB
13847	3624275.48	216010.92	-8.50	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
13848	3624275.25	216013.81	-8.49	WB
13849	3624274.99	216016.69	-8.48	WB
13850	3624274.64	216019.69	-8.47	WB
13851	3624274.30	216022.66	-8.46	WB
13852	3624274.10	216025.53	-8.45	WB
13853	3624273.93	216028.44	-8.44	WB
13854	3624273.85	216031.26	-8.43	WB
13855	3624273.87	216034.06	-8.42	WB
13856	3624273.91	216036.86	-8.41	WB
13857	3624274.08	216039.79	-8.41	WB
13858	3624274.27	216042.68	-8.40	WB
13859	3624274.29	216043.03	-8.39	WB
13860	3624274.55	216045.61	-8.38	WB
13861	3624274.91	216048.57	-8.38	WB
13862	3624275.29	216051.51	-8.37	WB
13863	3624275.81	216054.50	-8.37	WB
13864	3624276.30	216057.42	-8.36	WB
13865	3624276.79	216060.46	-8.36	WB
13866	3624277.27	216063.58	-8.36	WB
13867	3624277.75	216066.59	-8.35	WB
13868	3624278.04	216068.08	-8.35	WB
13869	3624278.35	216069.65	-8.35	WB
13870	3624278.94	216072.65	-8.34	WB
13871	3624279.51	216075.60	-8.34	WB
13872	3624280.09	216078.65	-8.33	WB
13873	3624280.65	216081.59	-8.33	WB
13874	3624281.21	216084.45	-8.33	WB
13875	3624281.80	216087.39	-8.32	WB
13876	3624282.37	216090.30	-8.32	WB
13877	3624282.79	216092.48	-8.31	WB
13878	3624282.92	216093.17	-8.31	WB
13879	3624283.43	216096.11	-8.30	WB
13880	3624283.83	216099.20	-8.29	WB
13881	3624284.23	216102.19	-8.29	WB
13882	3624284.58	216105.21	-8.28	WB
13883	3624284.94	216108.28	-8.27	WB
13884	3624285.22	216111.21	-8.27	WB
13885	3624285.41	216114.17	-8.26	WB
13886	3624285.56	216116.71	-8.25	WB
13887	3624285.58	216117.10	-8.24	WB
13888	3624285.70	216119.87	-8.23	WB
13889	3624285.82	216122.68	-8.22	WB
13890	3624285.87	216125.51	-8.22	WB
13891	3624285.86	216128.27	-8.21	WB
13892	3624285.84	216131.05	-8.20	WB
13893	3624285.79	216133.72	-8.20	WB
13894	3624285.73	216136.40	-8.19	WB
13895	3624285.67	216139.02	-8.18	WB
13896	3624285.61	216141.70	-8.18	WB
13897	3624285.53	216144.31	-8.18	WB
13898	3624285.43	216146.91	-8.17	WB
13899	3624285.33	216149.53	-8.17	WB
13900	3624285.28	216152.02	-8.17	WB
13901	3624285.26	216154.55	-8.17	WB
13902	3624285.27	216157.03	-8.17	WB
13903	3624285.30	216159.57	-8.17	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
13904	3624285.32	216162.22	-8.17	WB
13905	3624285.26	216165.09	-8.17	WB
13906	3624285.21	216166.90	-8.17	WB
13907	3624285.17	216168.00	-8.17	WB
13908	3624285.07	216171.07	-8.17	WB
13909	3624284.92	216174.49	-8.17	WB
13910	3624284.77	216177.82	-8.18	WB
13911	3624284.56	216181.43	-8.18	WB
13912	3624284.34	216185.10	-8.18	WB
13913	3624284.14	216188.66	-8.18	WB
13914	3624283.96	216191.85	-8.18	WB
13915	3624283.93	216192.29	-8.18	WB
13916	3624283.73	216195.96	-8.18	WB
13917	3624283.57	216199.40	-8.18	WB
13918	3624283.40	216202.98	-8.18	WB
13919	3624283.22	216206.28	-8.18	WB
13920	3624283.02	216209.44	-8.18	WB
13921	3624282.80	216212.76	-8.17	WB
13922	3624282.63	216215.69	-8.17	WB
13923	3624282.58	216216.45	-8.16	WB
13924	3624282.44	216218.64	-8.16	WB
13925	3624282.17	216221.54	-8.15	WB
13926	3624281.84	216224.34	-8.14	WB
13927	3624281.49	216227.14	-8.14	WB
13928	3624281.18	216229.83	-8.13	WB
13929	3624280.85	216232.53	-8.12	WB
13930	3624280.47	216235.30	-8.11	WB
13931	3624280.07	216238.07	-8.10	WB
13932	3624279.68	216240.87	-8.10	WB
13933	3624279.55	216241.96	-8.09	WB
13934	3624279.35	216243.78	-8.08	WB
13935	3624279.02	216246.73	-8.07	WB
13936	3624278.79	216249.72	-8.06	WB
13937	3624278.60	216252.78	-8.05	WB
13938	3624278.47	216255.91	-8.05	WB
13939	3624278.46	216259.02	-8.04	WB
13940	3624278.46	216262.21	-8.03	WB
13941	3624278.54	216265.40	-8.03	WB
13942	3624278.61	216267.71	-8.02	WB
13943	3624278.64	216268.51	-8.02	WB
13944	3624278.83	216271.66	-8.01	WB
13945	3624279.13	216274.69	-8.01	WB
13946	3624279.45	216277.66	-8.00	WB
13947	3624279.75	216280.66	-8.00	WB
13948	3624280.04	216283.61	-8.00	WB
13949	3624280.38	216286.49	-7.99	WB
13950	3624280.79	216289.34	-7.99	WB
13951	3624281.20	216292.19	-7.99	WB
13952	3624281.47	216295.04	-7.98	WB
13953	3624281.72	216297.89	-7.98	WB
13954	3624281.91	216300.83	-7.98	WB
13955	3624282.05	216303.78	-7.97	WB
13956	3624282.17	216306.81	-7.97	WB
13957	3624282.17	216309.90	-7.97	WB
13958	3624282.15	216312.95	-7.96	WB
13959	3624282.10	216316.14	-7.96	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
13960	3624282.08	216317.29	-7.96	WB
13961	3624282.05	216319.22	-7.95	WB
13962	3624282.02	216322.22	-7.95	WB
13963	3624282.02	216325.31	-7.94	WB
13964	3624282.04	216328.35	-7.94	WB
13965	3624282.04	216331.41	-7.93	WB
13966	3624282.04	216334.46	-7.92	WB
13967	3624282.03	216337.53	-7.92	WB
13968	3624281.96	216340.61	-7.91	WB
13969	3624281.94	216341.82	-7.90	WB
13970	3624281.89	216343.71	-7.89	WB
13971	3624281.81	216346.82	-7.88	WB
13972	3624281.70	216350.32	-7.87	WB
13973	3624281.55	216353.58	-7.86	WB
13974	3624281.35	216356.77	-7.85	WB
13975	3624281.14	216359.93	-7.84	WB
13976	3624280.89	216363.12	-7.83	WB
13977	3624280.64	216366.32	-7.82	WB
13978	3624280.61	216366.70	-7.81	WB
13979	3624280.39	216369.50	-7.80	WB
13980	3624280.16	216372.64	-7.79	WB
13981	3624279.94	216375.75	-7.77	WB
13982	3624279.78	216378.79	-7.76	WB
13983	3624279.63	216381.82	-7.75	WB
13984	3624279.57	216384.74	-7.74	WB
13985	3624279.56	216387.54	-7.74	WB
13986	3624279.55	216390.41	-7.73	WB
13987	3624279.57	216391.82	-7.72	WB
13988	3624279.58	216393.22	-7.71	WB
13989	3624279.61	216395.94	-7.71	WB
13990	3624279.69	216398.72	-7.70	WB
13991	3624279.79	216401.50	-7.70	WB
13992	3624279.87	216404.31	-7.69	WB
13993	3624279.92	216407.19	-7.69	WB
13994	3624279.96	216410.08	-7.69	WB
13995	3624280.05	216413.04	-7.69	WB
13996	3624280.15	216415.96	-7.68	WB
13997	3624280.20	216417.39	-7.68	WB
13998	3624280.30	216418.86	-7.69	WB
13999	3624280.53	216421.73	-7.69	WB
14000	3624280.77	216424.54	-7.69	WB
14001	3624281.02	216427.54	-7.69	WB
14002	3624281.26	216430.42	-7.69	WB
14003	3624281.54	216433.35	-7.69	WB
14004	3624281.89	216436.48	-7.70	WB
14005	3624282.23	216439.47	-7.70	WB
14006	3624282.39	216442.40	-7.70	WB
14007	3624282.41	216442.80	-7.70	WB
14008	3624282.59	216446.11	-7.70	WB
14009	3624282.73	216449.45	-7.70	WB
14010	3624282.86	216452.94	-7.70	WB
14011	3624282.99	216456.40	-7.70	WB
14012	3624282.99	216459.69	-7.70	WB
14013	3624282.99	216463.08	-7.69	WB
14014	3624282.97	216466.25	-7.69	WB
14015	3624282.97	216466.63	-7.68	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
14016	3624282.94	216469.40	-7.68	WB
14017	3624282.89	216472.50	-7.67	WB
14018	3624282.76	216475.45	-7.66	WB
14019	3624282.62	216478.37	-7.66	WB
14020	3624282.37	216481.21	-7.65	WB
14021	3624282.05	216484.06	-7.64	WB
14022	3624281.70	216486.82	-7.63	WB
14023	3624281.26	216489.62	-7.62	WB
14024	3624280.97	216491.37	-7.61	WB
14025	3624280.79	216492.40	-7.60	WB
14026	3624280.26	216495.20	-7.58	WB
14027	3624279.70	216498.08	-7.57	WB
14028	3624279.16	216500.92	-7.56	WB
14029	3624278.67	216503.72	-7.55	WB
14030	3624278.19	216506.54	-7.54	WB
14031	3624277.76	216509.37	-7.53	WB
14032	3624277.36	216512.13	-7.52	WB
14033	3624277.00	216514.99	-7.51	WB
14034	3624276.78	216517.07	-7.50	WB
14035	3624276.70	216517.84	-7.49	WB
14036	3624276.40	216520.65	-7.48	WB
14037	3624276.16	216523.66	-7.47	WB
14038	3624275.91	216526.73	-7.46	WB
14039	3624275.76	216529.72	-7.46	WB
14040	3624275.67	216532.87	-7.45	WB
14041	3624275.61	216535.99	-7.44	WB
14042	3624275.65	216539.07	-7.44	WB
14043	3624275.70	216542.18	-7.43	WB
14044	3624275.71	216542.55	-7.43	WB
14045	3624275.82	216545.24	-7.42	WB
14046	3624275.99	216548.31	-7.42	WB
14047	3624276.18	216551.35	-7.41	WB
14048	3624276.43	216554.30	-7.41	WB
14049	3624276.69	216557.25	-7.40	WB
14050	3624276.99	216560.23	-7.40	WB
14051	3624277.31	216563.22	-7.39	WB
14052	3624277.62	216566.16	-7.39	WB
14053	3624277.72	216567.30	-7.38	WB
14054	3624277.89	216569.17	-7.37	WB
14055	3624278.16	216572.30	-7.36	WB
14056	3624278.41	216575.52	-7.36	WB
14057	3624278.66	216578.77	-7.35	WB
14058	3624278.89	216582.06	-7.34	WB
14059	3624279.07	216585.44	-7.33	WB
14060	3624279.25	216588.82	-7.32	WB
14061	3624279.35	216592.24	-7.30	WB
14062	3624279.45	216595.74	-7.29	WB
14063	3624279.53	216599.20	-7.28	WB
14064	3624279.61	216602.57	-7.26	WB
14065	3624279.70	216605.91	-7.25	WB
14066	3624279.80	216608.99	-7.23	WB
14067	3624279.91	216612.16	-7.22	WB
14068	3624279.99	216615.11	-7.20	WB
14069	3624280.01	216616.58	-7.19	WB
14070	3624280.03	216618.02	-7.17	WB
14071	3624280.07	216621.01	-7.15	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
14072	3624280.09	216623.70	-7.14	WB
14073	3624280.10	216626.48	-7.12	WB
14074	3624280.13	216629.14	-7.11	WB
14075	3624280.17	216631.73	-7.09	WB
14076	3624280.21	216634.37	-7.08	WB
14077	3624280.25	216636.88	-7.06	WB
14078	3624280.28	216639.39	-7.05	WB
14079	3624280.29	216641.88	-7.04	WB
14080	3624280.29	216644.36	-7.02	WB
14081	3624280.29	216646.88	-7.01	WB
14082	3624280.30	216649.49	-7.00	WB
14083	3624280.31	216652.10	-6.99	WB
14084	3624280.30	216654.87	-6.98	WB
14085	3624280.28	216657.73	-6.98	WB
14086	3624280.29	216660.57	-6.97	WB
14087	3624280.33	216663.64	-6.96	WB
14088	3624280.39	216666.66	-6.95	WB
14089	3624280.41	216667.46	-6.95	WB
14090	3624280.46	216669.83	-6.94	WB
14091	3624280.54	216673.07	-6.94	WB
14092	3624280.63	216676.47	-6.93	WB
14093	3624280.73	216679.87	-6.92	WB
14094	3624280.84	216683.36	-6.92	WB
14095	3624280.90	216686.97	-6.91	WB
14096	3624280.96	216690.58	-6.91	WB
14097	3624280.98	216692.05	-6.90	WB
14098	3624280.96	216694.34	-6.89	WB
14099	3624280.92	216698.02	-6.88	WB
14100	3624280.88	216701.66	-6.88	WB
14101	3624280.84	216705.20	-6.87	WB
14102	3624280.81	216708.73	-6.86	WB
14103	3624280.71	216712.15	-6.84	WB
14104	3624280.54	216715.50	-6.83	WB
14105	3624280.48	216716.75	-6.82	WB
14106	3624280.36	216718.82	-6.81	WB
14107	3624280.11	216721.96	-6.79	WB
14108	3624279.86	216725.11	-6.78	WB
14109	3624279.62	216728.03	-6.76	WB
14110	3624279.38	216730.87	-6.75	WB
14111	3624279.16	216733.67	-6.73	WB
14112	3624278.99	216736.18	-6.71	WB
14113	3624278.82	216738.75	-6.70	WB
14114	3624278.65	216741.27	-6.68	WB
14115	3624278.63	216741.56	-6.67	WB
14116	3624278.48	216743.71	-6.65	WB
14117	3624278.29	216746.25	-6.63	WB
14118	3624278.07	216748.80	-6.62	WB
14119	3624277.84	216751.33	-6.60	WB
14120	3624277.58	216754.09	-6.59	WB
14121	3624277.31	216756.80	-6.57	WB
14122	3624277.04	216759.55	-6.56	WB
14123	3624276.77	216762.41	-6.55	WB
14124	3624276.51	216765.29	-6.53	WB
14125	3624276.41	216767.18	-6.52	WB
14126	3624276.35	216768.25	-6.51	WB
14127	3624276.20	216771.22	-6.50	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
14128	3624276.10	216774.24	-6.49	WB
14129	3624276.08	216777.14	-6.48	WB
14130	3624276.06	216780.04	-6.47	WB
14131	3624276.18	216783.05	-6.46	WB
14132	3624276.31	216786.00	-6.46	WB
14133	3624276.48	216789.02	-6.45	WB
14134	3624276.68	216792.06	-6.44	WB
14135	3624276.73	216792.79	-6.43	WB
14136	3624276.89	216795.12	-6.43	WB
14137	3624277.15	216798.30	-6.42	WB
14138	3624277.42	216801.47	-6.41	WB
14139	3624277.71	216804.71	-6.40	WB
14140	3624278.01	216808.03	-6.40	WB
14141	3624278.33	216811.35	-6.39	WB
14142	3624278.69	216814.65	-6.38	WB
14143	3624279.00	216817.55	-6.37	WB
14144	3624279.05	216817.94	-6.36	WB
14145	3624279.42	216821.20	-6.36	WB
14146	3624279.79	216824.32	-6.35	WB
14147	3624280.16	216827.45	-6.33	WB
14148	3624280.54	216830.53	-6.32	WB
14149	3624280.92	216833.51	-6.31	WB
14150	3624281.30	216836.47	-6.30	WB
14151	3624281.68	216839.36	-6.29	WB
14152	3624281.95	216841.80	-6.28	WB
14153	3624281.98	216842.18	-6.26	WB
14154	3624282.21	216845.05	-6.25	WB
14155	3624282.42	216847.90	-6.23	WB
14156	3624282.56	216850.66	-6.22	WB
14157	3624282.70	216853.51	-6.21	WB
14158	3624282.77	216856.34	-6.19	WB
14159	3624282.76	216859.18	-6.17	WB
14160	3624282.74	216862.04	-6.16	WB
14161	3624282.64	216864.96	-6.14	WB
14162	3624282.57	216866.79	-6.13	WB
14163	3624282.52	216867.88	-6.11	WB
14164	3624282.36	216870.81	-6.10	WB
14165	3624282.15	216873.74	-6.08	WB
14166	3624281.95	216876.68	-6.07	WB
14167	3624281.75	216879.72	-6.05	WB
14168	3624281.56	216882.67	-6.04	WB
14169	3624281.37	216885.71	-6.02	WB
14170	3624281.16	216888.85	-6.01	WB
14171	3624280.98	216891.91	-5.99	WB
14172	3624280.86	216895.14	-5.98	WB
14173	3624280.74	216898.33	-5.96	WB
14174	3624280.63	216901.48	-5.95	WB
14175	3624280.52	216904.69	-5.93	WB
14176	3624280.44	216907.84	-5.91	WB
14177	3624280.41	216910.93	-5.90	WB
14178	3624280.38	216914.10	-5.88	WB
14179	3624280.32	216916.76	-5.86	WB
14180	3624280.31	216917.18	-5.83	WB
14181	3624280.23	216920.23	-5.81	WB
14182	3624280.14	216923.34	-5.78	WB
14183	3624280.05	216926.49	-5.75	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
14184	3624279.95	216929.56	-5.71	WB
14185	3624279.84	216932.70	-5.68	WB
14186	3624279.71	216935.84	-5.64	WB
14187	3624279.63	216938.88	-5.60	WB
14188	3624279.57	216941.99	-5.56	WB
14189	3624279.51	216945.05	-5.52	WB
14190	3624279.47	216948.00	-5.47	WB
14191	3624279.42	216951.12	-5.43	WB
14192	3624279.43	216954.08	-5.38	WB
14193	3624279.49	216957.05	-5.34	WB
14194	3624279.55	216960.01	-5.29	WB
14195	3624279.65	216962.93	-5.25	WB
14196	3624279.75	216965.84	-5.20	WB
14197	3624279.80	216967.33	-5.16	WB
14198	3624279.87	216968.74	-5.11	WB
14199	3624280.00	216971.63	-5.07	WB
14200	3624280.15	216974.53	-5.03	WB
14201	3624280.32	216977.41	-4.99	WB
14202	3624280.50	216980.28	-4.95	WB
14203	3624280.64	216983.22	-4.91	WB
14204	3624280.75	216986.25	-4.87	WB
14205	3624280.86	216989.19	-4.84	WB
14206	3624280.98	216992.29	-4.80	WB
14207	3624281.11	216995.44	-4.77	WB
14208	3624281.17	216998.64	-4.73	WB
14209	3624281.22	217001.97	-4.70	WB
14210	3624281.28	217005.32	-4.67	WB
14211	3624281.37	217008.70	-4.64	WB
14212	3624281.47	217012.18	-4.60	WB
14213	3624281.60	217015.68	-4.57	WB
14214	3624281.67	217017.42	-4.55	WB
14215	3624281.75	217019.20	-4.52	WB
14216	3624281.90	217022.68	-4.49	WB
14217	3624282.07	217025.97	-4.47	WB
14218	3624282.26	217029.27	-4.44	WB
14219	3624282.54	217032.41	-4.42	WB
14220	3624282.82	217035.44	-4.40	WB
14221	3624282.99	217038.35	-4.38	WB
14222	3624283.08	217041.22	-4.36	WB
14223	3624283.10	217041.90	-4.34	WB
14224	3624283.16	217044.10	-4.32	WB
14225	3624283.19	217046.79	-4.32	WB
14226	3624283.22	217049.52	-4.31	WB
14227	3624283.19	217052.08	-4.30	WB
14228	3624283.10	217054.68	-4.29	WB
14229	3624282.98	217057.33	-4.31	WB
14230	3624282.77	217059.82	-4.30	WB
14231	3624282.55	217062.37	-4.31	WB
14232	3624282.35	217064.84	-4.30	WB
14233	3624282.22	217066.40	-4.29	WB
14234	3624282.15	217067.33	-4.30	WB
14235	3624281.90	217069.86	-4.33	WB
14236	3624281.57	217072.32	-4.37	WB
14237	3624281.22	217074.87	-4.39	WB
14238	3624280.92	217077.41	-4.43	WB
14239	3624280.62	217079.92	-4.49	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
14240	3624280.29	217082.52	-4.57	WB
14241	3624279.90	217085.23	-4.66	WB
14242	3624279.50	217087.95	-4.78	WB
14243	3624279.15	217090.90	-4.90	WB
14244	3624279.02	217092.00	-5.03	WB
14245	3624278.81	217093.86	-5.18	WB
14246	3624278.49	217096.95	-5.32	WB
14247	3624278.21	217100.20	-5.47	WB
14248	3624277.93	217103.44	-5.62	WB
14249	3624277.78	217106.87	-5.77	WB
14250	3624277.64	217110.28	-5.91	WB
14251	3624277.56	217113.76	-6.04	WB
14252	3624277.51	217117.28	-6.19	WB
14253	3624277.47	217120.85	-6.30	WB
14254	3624277.45	217124.23	-6.38	WB
14255	3624277.44	217127.64	-6.43	WB
14256	3624277.48	217130.95	-6.47	WB
14257	3624277.56	217134.08	-6.47	WB
14258	3624277.65	217137.27	-6.44	WB
14259	3624277.77	217140.22	-6.39	WB
14260	3624277.84	217142.07	-6.32	WB
14261	3624277.88	217143.13	-6.22	WB
14262	3624278.00	217146.06	-6.12	WB
14263	3624278.11	217148.93	-6.04	WB
14264	3624278.20	217151.82	-5.98	WB
14265	3624278.27	217154.71	-5.90	WB
14266	3624278.34	217157.62	-5.83	WB
14267	3624278.39	217160.55	-5.79	WB
14268	3624278.44	217163.51	-5.78	WB
14269	3624278.52	217166.47	-5.77	WB
14270	3624278.55	217167.23	-5.77	WB
14271	3624278.64	217169.44	-5.76	WB
14272	3624278.76	217172.41	-5.73	WB
14273	3624278.86	217175.42	-5.72	WB
14274	3624278.97	217178.42	-5.71	WB
14275	3624279.11	217181.47	-5.69	WB
14276	3624279.29	217184.36	-5.67	WB
14277	3624279.47	217187.29	-5.63	WB
14278	3624279.68	217190.18	-5.58	WB
14279	3624279.82	217191.96	-5.52	WB
14280	3624279.89	217192.98	-5.48	WB
14281	3624280.10	217195.85	-5.44	WB
14282	3624280.30	217198.69	-5.39	WB
14283	3624280.48	217201.54	-5.36	WB
14284	3624280.57	217204.49	-5.33	WB
14285	3624280.66	217207.40	-5.30	WB
14286	3624280.74	217210.31	-5.27	WB
14287	3624280.82	217213.30	-5.24	WB
14288	3624280.89	217216.36	-5.22	WB
14289	3624280.90	217217.09	-5.20	WB
14290	3624280.93	217219.36	-5.18	WB
14291	3624280.98	217222.44	-5.17	WB
14292	3624281.04	217225.56	-5.14	WB
14293	3624281.10	217228.66	-5.11	WB
14294	3624281.15	217231.90	-5.10	WB
14295	3624281.18	217235.21	-5.08	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
14296	3624281.21	217238.48	-5.08	WB
14297	3624281.23	217242.01	-5.08	WB
14298	3624281.23	217242.43	-5.07	WB
14299	3624281.26	217245.41	-5.06	WB
14300	3624281.28	217248.82	-5.06	WB
14301	3624281.29	217252.33	-5.04	WB
14302	3624281.30	217255.73	-5.02	WB
14303	3624281.28	217259.12	-4.99	WB
14304	3624281.26	217262.44	-4.95	WB
14305	3624281.23	217265.67	-4.91	WB
14306	3624281.21	217266.90	-4.87	WB
14307	3624281.19	217268.82	-4.83	WB
14308	3624281.16	217271.96	-4.80	WB
14309	3624281.07	217274.95	-4.76	WB
14310	3624280.98	217277.97	-4.72	WB
14311	3624280.89	217280.95	-4.68	WB
14312	3624280.79	217283.87	-4.63	WB
14313	3624280.69	217286.79	-4.59	WB
14314	3624280.53	217289.69	-4.54	WB
14315	3624280.41	217291.82	-4.48	WB
14316	3624280.37	217292.50	-4.43	WB
14317	3624280.24	217295.31	-4.37	WB
14318	3624280.12	217298.14	-4.31	WB
14319	3624280.00	217300.89	-4.26	WB
14320	3624279.89	217303.68	-4.20	WB
14321	3624279.78	217306.43	-4.14	WB
14322	3624279.73	217309.08	-4.08	WB
14323	3624279.71	217311.83	-4.03	WB
14324	3624279.71	217314.42	-3.97	WB
14325	3624279.77	217316.96	-3.91	WB
14326	3624279.78	217317.27	-3.86	WB
14327	3624279.83	217319.50	-3.80	WB
14328	3624279.93	217321.95	-3.75	WB
14329	3624280.05	217324.37	-3.70	WB
14330	3624280.18	217326.82	-3.64	WB
14331	3624280.32	217329.13	-3.58	WB
14332	3624280.47	217331.51	-3.52	WB
14333	3624280.57	217333.95	-3.47	WB
14334	3624280.67	217336.42	-3.42	WB
14335	3624280.74	217338.97	-3.37	WB
14336	3624280.78	217341.64	-3.32	WB
14337	3624280.79	217342.00	-3.28	WB
14338	3624280.82	217344.33	-3.24	WB
14339	3624280.78	217347.28	-3.18	WB
14340	3624280.74	217350.23	-3.09	WB
14341	3624280.68	217353.27	-2.99	WB
14342	3624280.61	217356.41	-2.90	WB
14343	3624280.54	217359.43	-2.80	WB
14344	3624280.45	217362.42	-2.75	WB
14345	3623792.95	215747.98	-8.67	WB
14346	3623792.24	215751.33	-8.66	WB
14347	3623792.08	215752.11	-8.65	WB
14348	3623791.57	215754.56	-8.64	WB
14349	3623790.90	215757.79	-8.63	WB
14350	3623790.23	215761.04	-8.61	WB
14351	3623789.57	215764.18	-8.60	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
14352	3623788.88	215767.17	-8.59	WB
14353	3623788.20	215770.22	-8.58	WB
14354	3623787.57	215773.13	-8.57	WB
14355	3623786.98	215775.92	-8.56	WB
14356	3623786.75	215777.00	-8.56	WB
14357	3623786.38	215778.68	-8.55	WB
14358	3623785.74	215781.30	-8.54	WB
14359	3623785.05	215783.95	-8.54	WB
14360	3623784.38	215786.60	-8.53	WB
14361	3623783.72	215789.25	-8.53	WB
14362	3623783.00	215791.98	-8.52	WB
14363	3623782.17	215794.90	-8.52	WB
14364	3623781.34	215797.76	-8.52	WB
14365	3623780.62	215800.74	-8.51	WB
14366	3623780.10	215803.06	-8.51	WB
14367	3623779.92	215803.83	-8.51	WB
14368	3623779.35	215806.77	-8.51	WB
14369	3623778.93	215809.73	-8.51	WB
14370	3623778.56	215812.59	-8.51	WB
14371	3623778.53	215815.28	-8.50	WB
14372	3623778.56	215817.97	-8.50	WB
14373	3623778.64	215820.74	-8.50	WB
14374	3623778.77	215823.63	-8.50	WB
14375	3623778.91	215826.62	-8.50	WB
14376	3623779.03	215828.67	-8.50	WB
14377	3623779.12	215829.98	-8.50	WB
14378	3623779.33	215833.30	-8.50	WB
14379	3623779.53	215836.91	-8.50	WB
14380	3623779.72	215840.59	-8.50	WB
14381	3623779.93	215844.23	-8.49	WB
14382	3623780.19	215847.68	-8.49	WB
14383	3623780.50	215851.12	-8.49	WB
14384	3623780.66	215852.69	-8.48	WB
14385	3623780.83	215854.12	-8.48	WB
14386	3623781.19	215857.09	-8.48	WB
14387	3623781.51	215859.99	-8.47	WB
14388	3623781.67	215862.62	-8.47	WB
14389	3623781.81	215865.37	-8.46	WB
14390	3623781.76	215868.05	-8.46	WB
14391	3623781.63	215870.68	-8.45	WB
14392	3623781.44	215873.40	-8.44	WB
14393	3623781.14	215876.05	-8.44	WB
14394	3623780.99	215877.36	-8.43	WB
14395	3623780.84	215878.71	-8.43	WB
14396	3623780.58	215881.34	-8.42	WB
14397	3623780.34	215883.96	-8.41	WB
14398	3623780.15	215886.52	-8.41	WB
14399	3623780.02	215889.13	-8.40	WB
14400	3623779.88	215891.75	-8.40	WB
14401	3623779.69	215894.60	-8.39	WB
14402	3623779.49	215897.51	-8.38	WB
14403	3623779.34	215900.45	-8.38	WB
14404	3623779.25	215903.15	-8.38	WB
14405	3623779.23	215903.52	-8.37	WB
14406	3623779.14	215906.62	-8.37	WB
14407	3623779.20	215909.67	-8.36	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
14408	3623779.27	215912.75	-8.36	WB
14409	3623779.41	215915.93	-8.36	WB
14410	3623779.61	215919.09	-8.36	WB
14411	3623779.83	215922.26	-8.35	WB
14412	3623780.21	215925.43	-8.35	WB
14413	3623780.60	215928.57	-8.35	WB
14414	3623780.96	215931.70	-8.35	WB
14415	3623781.29	215934.83	-8.34	WB
14416	3623781.66	215937.85	-8.34	WB
14417	3623782.20	215940.66	-8.34	WB
14418	3623782.77	215943.47	-8.34	WB
14419	3623783.30	215946.09	-8.34	WB
14420	3623783.82	215948.72	-8.33	WB
14421	3623784.31	215951.45	-8.33	WB
14422	3623784.48	215952.81	-8.33	WB
14423	3623784.65	215954.18	-8.32	WB
14424	3623784.98	215957.02	-8.32	WB
14425	3623785.01	215960.01	-8.32	WB
14426	3623784.96	215962.96	-8.31	WB
14427	3623784.84	215966.01	-8.31	WB
14428	3623784.62	215969.03	-8.30	WB
14429	3623784.39	215972.01	-8.30	WB
14430	3623784.07	215974.88	-8.29	WB
14431	3623783.83	215976.97	-8.29	WB
14432	3623783.74	215977.68	-8.28	WB
14433	3623783.41	215980.39	-8.28	WB
14434	3623783.05	215983.02	-8.27	WB
14435	3623782.69	215985.68	-8.27	WB
14436	3623782.18	215988.32	-8.26	WB
14437	3623781.64	215990.98	-8.26	WB
14438	3623781.01	215993.70	-8.25	WB
14439	3623780.31	215996.45	-8.25	WB
14440	3623779.57	215999.30	-8.24	WB
14441	3623778.81	216002.10	-8.24	WB
14442	3623778.01	216004.98	-8.23	WB
14443	3623777.25	216007.93	-8.23	WB
14444	3623776.53	216010.81	-8.22	WB
14445	3623775.84	216013.77	-8.22	WB
14446	3623775.42	216016.79	-8.22	WB
14447	3623775.01	216019.76	-8.21	WB
14448	3623774.71	216022.98	-8.21	WB
14449	3623774.46	216026.21	-8.21	WB
14450	3623774.28	216028.63	-8.20	WB
14451	3623774.27	216029.48	-8.20	WB
14452	3623774.23	216033.00	-8.20	WB
14453	3623774.21	216036.44	-8.19	WB
14454	3623774.31	216039.87	-8.19	WB
14455	3623774.46	216043.28	-8.19	WB
14456	3623774.71	216046.64	-8.18	WB
14457	3623775.14	216049.77	-8.18	WB
14458	3623775.59	216052.97	-8.18	WB
14459	3623775.72	216053.71	-8.17	WB
14460	3623776.16	216055.97	-8.17	WB
14461	3623776.75	216058.89	-8.17	WB
14462	3623777.37	216061.90	-8.16	WB
14463	3623777.99	216064.84	-8.16	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
14464	3623778.60	216067.74	-8.15	WB
14465	3623778.99	216070.69	-8.15	WB
14466	3623779.36	216073.60	-8.14	WB
14467	3623779.72	216076.41	-8.14	WB
14468	3623779.91	216077.84	-8.14	WB
14469	3623780.09	216079.20	-8.13	WB
14470	3623780.45	216081.96	-8.13	WB
14471	3623780.65	216084.55	-8.12	WB
14472	3623780.86	216087.14	-8.12	WB
14473	3623781.07	216089.71	-8.11	WB
14474	3623781.29	216092.27	-8.11	WB
14475	3623781.50	216094.88	-8.10	WB
14476	3623781.62	216097.52	-8.10	WB
14477	3623781.74	216100.20	-8.10	WB
14478	3623781.93	216103.02	-8.09	WB
14479	3623782.15	216105.83	-8.09	WB
14480	3623782.33	216108.74	-8.08	WB
14481	3623782.44	216111.90	-8.08	WB
14482	3623782.53	216114.99	-8.08	WB
14483	3623782.62	216118.44	-8.07	WB
14484	3623782.72	216121.93	-8.07	WB
14485	3623782.80	216125.41	-8.07	WB
14486	3623782.87	216128.68	-8.07	WB
14487	3623782.88	216129.11	-8.06	WB
14488	3623782.97	216132.72	-8.06	WB
14489	3623783.15	216136.13	-8.06	WB
14490	3623783.37	216139.57	-8.06	WB
14491	3623783.67	216142.76	-8.05	WB
14492	3623784.09	216145.70	-8.05	WB
14493	3623784.51	216148.68	-8.05	WB
14494	3623784.95	216151.54	-8.05	WB
14495	3623785.16	216152.92	-8.04	WB
14496	3623785.37	216154.31	-8.04	WB
14497	3623785.73	216157.17	-8.04	WB
14498	3623786.04	216160.11	-8.03	WB
14499	3623786.31	216162.99	-8.03	WB
14500	3623786.43	216166.00	-8.03	WB
14501	3623786.54	216169.01	-8.02	WB
14502	3623786.60	216171.96	-8.02	WB
14503	3623786.60	216174.93	-8.02	WB
14504	3623786.61	216177.47	-8.01	WB
14505	3623786.61	216177.85	-8.01	WB
14506	3623786.60	216180.69	-8.00	WB
14507	3623786.58	216183.61	-8.00	WB
14508	3623786.53	216186.50	-7.99	WB
14509	3623786.47	216189.42	-7.99	WB
14510	3623786.37	216192.44	-7.98	WB
14511	3623786.19	216195.54	-7.98	WB
14512	3623786.02	216198.64	-7.97	WB
14513	3623785.85	216201.87	-7.96	WB
14514	3623785.81	216202.66	-7.96	WB
14515	3623785.68	216205.14	-7.95	WB
14516	3623785.49	216208.40	-7.94	WB
14517	3623785.23	216211.91	-7.94	WB
14518	3623784.98	216215.26	-7.93	WB
14519	3623784.74	216218.61	-7.92	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
14520	3623784.50	216222.02	-7.92	WB
14521	3623784.26	216225.32	-7.91	WB
14522	3623784.10	216227.40	-7.90	WB
14523	3623783.99	216228.69	-7.89	WB
14524	3623783.70	216232.03	-7.88	WB
14525	3623783.42	216235.14	-7.88	WB
14526	3623783.13	216238.38	-7.87	WB
14527	3623782.88	216241.40	-7.86	WB
14528	3623782.68	216244.29	-7.85	WB
14529	3623782.47	216247.26	-7.85	WB
14530	3623782.18	216250.01	-7.84	WB
14531	3623781.92	216252.40	-7.83	WB
14532	3623781.88	216252.73	-7.83	WB
14533	3623781.57	216255.54	-7.82	WB
14534	3623781.26	216258.25	-7.82	WB
14535	3623780.93	216260.96	-7.81	WB
14536	3623780.50	216263.73	-7.81	WB
14537	3623780.05	216266.57	-7.80	WB
14538	3623779.65	216269.43	-7.80	WB
14539	3623779.28	216272.40	-7.79	WB
14540	3623778.92	216275.34	-7.79	WB
14541	3623778.64	216278.03	-7.79	WB
14542	3623778.61	216278.40	-7.79	WB
14543	3623778.30	216281.54	-7.78	WB
14544	3623778.14	216284.77	-7.78	WB
14545	3623778.04	216287.99	-7.78	WB
14546	3623777.97	216291.46	-7.78	WB
14547	3623777.92	216294.92	-7.77	WB
14548	3623777.88	216298.44	-7.77	WB
14549	3623777.88	216302.16	-7.77	WB
14550	3623777.89	216303.58	-7.77	WB
14551	3623777.90	216305.96	-7.76	WB
14552	3623777.94	216309.75	-7.76	WB
14553	3623778.00	216313.49	-7.76	WB
14554	3623778.09	216317.21	-7.75	WB
14555	3623778.29	216320.68	-7.75	WB
14556	3623778.51	216324.17	-7.74	WB
14557	3623778.70	216327.39	-7.74	WB
14558	3623778.72	216327.81	-7.73	WB
14559	3623778.86	216330.54	-7.73	WB
14560	3623779.01	216333.78	-7.72	WB
14561	3623779.04	216336.65	-7.71	WB
14562	3623779.08	216339.60	-7.71	WB
14563	3623779.05	216342.48	-7.70	WB
14564	3623778.97	216345.27	-7.69	WB
14565	3623778.89	216348.13	-7.68	WB
14566	3623778.75	216350.91	-7.68	WB
14567	3623778.67	216352.66	-7.67	WB
14568	3623778.62	216353.66	-7.66	WB
14569	3623778.47	216356.54	-7.65	WB
14570	3623778.33	216359.35	-7.64	WB
14571	3623778.18	216362.18	-7.64	WB
14572	3623778.04	216365.15	-7.63	WB
14573	3623777.90	216368.13	-7.62	WB
14574	3623777.77	216371.15	-7.62	WB
14575	3623777.64	216374.18	-7.61	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
14576	3623777.56	216377.22	-7.60	WB
14577	3623777.57	216377.98	-7.60	WB
14578	3623777.58	216380.23	-7.59	WB
14579	3623777.59	216383.28	-7.59	WB
14580	3623777.64	216386.21	-7.58	WB
14581	3623777.69	216389.12	-7.58	WB
14582	3623777.76	216392.11	-7.57	WB
14583	3623777.85	216395.15	-7.57	WB
14584	3623777.93	216398.16	-7.57	WB
14585	3623777.93	216401.47	-7.57	WB
14586	3623777.92	216403.07	-7.56	WB
14587	3623777.91	216404.72	-7.56	WB
14588	3623777.87	216408.00	-7.56	WB
14589	3623777.81	216411.43	-7.56	WB
14590	3623777.76	216414.89	-7.55	WB
14591	3623777.83	216418.27	-7.55	WB
14592	3623777.90	216421.67	-7.55	WB
14593	3623778.00	216425.15	-7.55	WB
14594	3623778.12	216428.60	-7.55	WB
14595	3623778.24	216432.06	-7.54	WB
14596	3623778.42	216435.41	-7.54	WB
14597	3623778.62	216438.79	-7.54	WB
14598	3623778.84	216442.10	-7.53	WB
14599	3623779.07	216445.25	-7.53	WB
14600	3623779.32	216448.47	-7.53	WB
14601	3623779.60	216451.49	-7.52	WB
14602	3623779.74	216452.98	-7.52	WB
14603	3623779.87	216454.48	-7.51	WB
14604	3623780.10	216457.54	-7.51	WB
14605	3623780.30	216460.54	-7.50	WB
14606	3623780.48	216463.53	-7.50	WB
14607	3623780.64	216466.72	-7.49	WB
14608	3623780.78	216469.78	-7.48	WB
14609	3623780.82	216473.00	-7.48	WB
14610	3623780.85	216476.19	-7.47	WB
14611	3623780.86	216477.76	-7.47	WB
14612	3623780.86	216479.29	-7.46	WB
14613	3623780.85	216482.47	-7.45	WB
14614	3623780.84	216485.60	-7.45	WB
14615	3623780.72	216488.64	-7.44	WB
14616	3623780.60	216491.68	-7.43	WB
14617	3623780.45	216494.62	-7.43	WB
14618	3623780.26	216497.46	-7.42	WB
14619	3623780.08	216500.34	-7.42	WB
14620	3623779.88	216502.87	-7.41	WB
14621	3623779.86	216503.25	-7.41	WB
14622	3623779.64	216506.03	-7.40	WB
14623	3623779.42	216508.92	-7.40	WB
14624	3623779.19	216511.78	-7.40	WB
14625	3623778.97	216514.59	-7.39	WB
14626	3623778.78	216517.45	-7.39	WB
14627	3623778.60	216520.26	-7.39	WB
14628	3623778.46	216523.12	-7.39	WB
14629	3623778.35	216525.92	-7.39	WB
14630	3623778.27	216527.65	-7.38	WB
14631	3623778.23	216528.72	-7.38	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
14632	3623778.12	216531.68	-7.38	WB
14633	3623778.01	216534.61	-7.38	WB
14634	3623777.94	216537.65	-7.38	WB
14635	3623777.86	216540.83	-7.38	WB
14636	3623777.79	216544.03	-7.38	WB
14637	3623777.69	216547.46	-7.38	WB
14638	3623777.59	216550.99	-7.38	WB
14639	3623777.56	216553.62	-7.37	WB
14640	3623777.55	216554.59	-7.37	WB
14641	3623777.53	216558.14	-7.37	WB
14642	3623777.55	216561.74	-7.37	WB
14643	3623777.60	216565.37	-7.36	WB
14644	3623777.68	216568.85	-7.36	WB
14645	3623777.81	216572.37	-7.35	WB
14646	3623777.96	216575.84	-7.35	WB
14647	3623778.06	216578.43	-7.34	WB
14648	3623778.09	216579.24	-7.33	WB
14649	3623778.21	216582.71	-7.33	WB
14650	3623778.34	216586.11	-7.32	WB
14651	3623778.48	216589.23	-7.31	WB
14652	3623778.64	216592.45	-7.30	WB
14653	3623778.86	216595.35	-7.29	WB
14654	3623779.14	216598.20	-7.28	WB
14655	3623779.40	216601.00	-7.27	WB
14656	3623779.56	216602.92	-7.26	WB
14657	3623779.61	216603.59	-7.25	WB
14658	3623779.83	216606.22	-7.24	WB
14659	3623780.08	216608.77	-7.23	WB
14660	3623780.33	216611.21	-7.22	WB
14661	3623780.57	216613.68	-7.21	WB
14662	3623780.72	216616.17	-7.20	WB
14663	3623780.85	216618.61	-7.19	WB
14664	3623780.83	216621.10	-7.18	WB
14665	3623780.76	216623.64	-7.17	WB
14666	3623780.68	216626.18	-7.17	WB
14667	3623780.62	216627.42	-7.16	WB
14668	3623780.56	216628.73	-7.15	WB
14669	3623780.45	216631.20	-7.14	WB
14670	3623780.18	216633.82	-7.14	WB
14671	3623779.87	216636.53	-7.13	WB
14672	3623779.51	216639.27	-7.13	WB
14673	3623779.08	216642.16	-7.12	WB
14674	3623778.63	216645.14	-7.11	WB
14675	3623778.04	216648.40	-7.11	WB
14676	3623777.44	216651.68	-7.11	WB
14677	3623777.29	216652.51	-7.10	WB
14678	3623776.76	216655.12	-7.10	WB
14679	3623776.01	216658.61	-7.09	WB
14680	3623775.25	216662.17	-7.09	WB
14681	3623774.52	216665.90	-7.08	WB
14682	3623773.78	216669.65	-7.07	WB
14683	3623773.04	216673.39	-7.07	WB
14684	3623772.26	216677.25	-7.06	WB
14685	3623772.17	216677.71	-7.05	WB
14686	3623771.54	216681.01	-7.05	WB
14687	3623770.99	216684.79	-7.04	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
14688	3623770.45	216688.53	-7.03	WB
14689	3623770.00	216692.14	-7.02	WB
14690	3623769.55	216695.88	-7.01	WB
14691	3623769.18	216699.40	-7.00	WB
14692	3623769.01	216702.79	-6.99	WB
14693	3623768.98	216703.26	-6.97	WB
14694	3623768.83	216706.32	-6.96	WB
14695	3623768.78	216709.55	-6.95	WB
14696	3623768.76	216712.77	-6.93	WB
14697	3623768.83	216715.88	-6.92	WB
14698	3623769.08	216718.82	-6.90	WB
14699	3623769.34	216721.87	-6.88	WB
14700	3623769.71	216724.92	-6.87	WB
14701	3623770.08	216727.92	-6.85	WB
14702	3623770.18	216728.74	-6.83	WB
14703	3623770.50	216731.04	-6.82	WB
14704	3623770.96	216734.16	-6.80	WB
14705	3623771.44	216737.26	-6.78	WB
14706	3623772.08	216740.30	-6.77	WB
14707	3623772.76	216743.29	-6.75	WB
14708	3623773.47	216746.15	-6.73	WB
14709	3623774.23	216748.95	-6.72	WB
14710	3623775.00	216751.69	-6.70	WB
14711	3623775.79	216753.88	-6.69	WB
14712	3623775.89	216754.18	-6.67	WB
14713	3623776.79	216756.67	-6.66	WB
14714	3623777.68	216759.10	-6.65	WB
14715	3623778.56	216761.49	-6.64	WB
14716	3623779.43	216763.86	-6.62	WB
14717	3623780.27	216766.30	-6.61	WB
14718	3623781.13	216768.78	-6.60	WB
14719	3623781.87	216771.21	-6.59	WB
14720	3623782.56	216773.67	-6.58	WB
14721	3623783.27	216776.32	-6.57	WB
14722	3623783.71	216778.35	-6.56	WB
14723	3623783.86	216779.00	-6.55	WB
14724	3623784.46	216781.79	-6.54	WB
14725	3623784.93	216784.77	-6.53	WB
14726	3623785.34	216787.76	-6.52	WB
14727	3623785.76	216790.88	-6.51	WB
14728	3623786.13	216794.10	-6.50	WB
14729	3623786.51	216797.26	-6.49	WB
14730	3623786.81	216800.56	-6.48	WB
14731	3623787.03	216802.98	-6.47	WB
14732	3623787.10	216803.80	-6.46	WB
14733	3623787.37	216807.04	-6.45	WB
14734	3623787.59	216810.27	-6.44	WB
14735	3623787.82	216813.52	-6.43	WB
14736	3623787.82	216816.72	-6.41	WB
14737	3623787.80	216819.94	-6.40	WB
14738	3623787.71	216823.14	-6.39	WB
14739	3623787.55	216826.29	-6.37	WB
14740	3623787.51	216827.09	-6.36	WB
14741	3623787.38	216829.49	-6.34	WB
14742	3623787.11	216832.38	-6.33	WB
14743	3623786.85	216835.30	-6.31	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
14744	3623786.59	216838.16	-6.30	WB
14745	3623786.33	216840.87	-6.28	WB
14746	3623786.05	216843.65	-6.27	WB
14747	3623785.70	216846.26	-6.25	WB
14748	3623785.34	216848.86	-6.23	WB
14749	3623784.93	216851.56	-6.22	WB
14750	3623784.84	216852.18	-6.20	WB
14751	3623784.53	216854.11	-6.18	WB
14752	3623784.12	216856.69	-6.17	WB
14753	3623783.66	216859.44	-6.15	WB
14754	3623783.22	216862.07	-6.14	WB
14755	3623782.79	216864.87	-6.12	WB
14756	3623782.38	216867.60	-6.11	WB
14757	3623782.01	216870.31	-6.09	WB
14758	3623781.70	216873.14	-6.08	WB
14759	3623781.42	216875.91	-6.07	WB
14760	3623781.29	216877.67	-6.05	WB
14761	3623781.23	216878.70	-6.04	WB
14762	3623781.05	216881.50	-6.03	WB
14763	3623780.90	216884.34	-6.02	WB
14764	3623780.78	216887.25	-6.01	WB
14765	3623780.65	216890.17	-6.00	WB
14766	3623780.47	216893.32	-5.99	WB
14767	3623780.28	216896.46	-5.98	WB
14768	3623780.07	216899.89	-5.98	WB
14769	3623779.89	216902.82	-5.97	WB
14770	3623779.86	216903.28	-5.96	WB
14771	3623779.65	216906.68	-5.95	WB
14772	3623779.48	216910.39	-5.94	WB
14773	3623779.32	216913.93	-5.94	WB
14774	3623779.23	216917.49	-5.93	WB
14775	3623779.21	216920.98	-5.92	WB
14776	3623779.20	216924.38	-5.91	WB
14777	3623779.30	216927.77	-5.90	WB
14778	3623779.31	216928.17	-5.89	WB
14779	3623779.39	216931.10	-5.87	WB
14780	3623779.48	216934.37	-5.86	WB
14781	3623779.55	216937.69	-5.85	WB
14782	3623779.61	216941.01	-5.83	WB
14783	3623779.60	216944.33	-5.81	WB
14784	3623779.59	216947.63	-5.79	WB
14785	3623779.61	216950.90	-5.77	WB
14786	3623779.64	216952.89	-5.75	WB
14787	3623779.65	216954.03	-5.72	WB
14788	3623779.70	216957.13	-5.69	WB
14789	3623779.73	216960.16	-5.66	WB
14790	3623779.76	216963.10	-5.63	WB
14791	3623779.74	216965.99	-5.59	WB
14792	3623779.69	216968.81	-5.56	WB
14793	3623779.64	216971.56	-5.52	WB
14794	3623779.56	216974.33	-5.49	WB
14795	3623779.47	216977.08	-5.45	WB
14796	3623779.23	216979.81	-5.41	WB
14797	3623778.95	216982.63	-5.37	WB
14798	3623778.64	216985.45	-5.34	WB
14799	3623778.28	216988.37	-5.30	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
14800	3623777.90	216991.33	-5.26	WB
14801	3623777.40	216994.38	-5.22	WB
14802	3623776.89	216997.42	-5.17	WB
14803	3623776.43	217000.53	-5.13	WB
14804	3623776.10	217002.92	-5.09	WB
14805	3623776.00	217003.66	-5.06	WB
14806	3623775.58	217006.78	-5.02	WB
14807	3623775.19	217009.92	-4.98	WB
14808	3623774.82	217012.95	-4.94	WB
14809	3623774.56	217015.95	-4.90	WB
14810	3623774.35	217018.99	-4.86	WB
14811	3623774.14	217021.92	-4.82	WB
14812	3623773.93	217024.82	-4.78	WB
14813	3623773.71	217027.85	-4.74	WB
14814	3623773.69	217028.21	-4.70	WB
14815	3623773.57	217030.79	-4.66	WB
14816	3623773.46	217033.76	-4.62	WB
14817	3623773.38	217036.68	-4.58	WB
14818	3623773.33	217039.53	-4.54	WB
14819	3623773.29	217042.44	-4.51	WB
14820	3623773.31	217045.28	-4.47	WB
14821	3623773.35	217048.11	-4.44	WB
14822	3623773.41	217050.90	-4.41	WB
14823	3623773.48	217053.02	-4.38	WB
14824	3623773.50	217053.74	-4.35	WB
14825	3623773.59	217056.58	-4.32	WB
14826	3623773.71	217059.54	-4.29	WB
14827	3623773.82	217062.44	-4.26	WB
14828	3623773.94	217065.55	-4.24	WB
14829	3623774.05	217068.73	-4.23	WB
14830	3623774.15	217071.98	-4.23	WB
14831	3623774.30	217075.47	-4.22	WB
14832	3623774.40	217078.13	-4.22	WB
14833	3623774.43	217078.97	-4.21	WB
14834	3623774.65	217082.64	-4.21	WB
14835	3623774.92	217086.41	-4.22	WB
14836	3623775.20	217090.04	-4.23	WB
14837	3623775.62	217093.81	-4.24	WB
14838	3623776.05	217097.62	-4.27	WB
14839	3623776.52	217101.24	-4.29	WB
14840	3623776.91	217104.01	-4.33	WB
14841	3623777.05	217104.98	-4.39	WB
14842	3623777.55	217108.47	-4.47	WB
14843	3623778.05	217111.77	-4.54	WB
14844	3623778.57	217115.19	-4.62	WB
14845	3623779.05	217118.30	-4.71	WB
14846	3623779.53	217121.35	-4.80	WB
14847	3623779.99	217124.47	-4.90	WB
14848	3623780.35	217127.48	-5.00	WB
14849	3623780.44	217128.25	-5.11	WB
14850	3623780.71	217130.49	-5.22	WB
14851	3623780.96	217133.48	-5.30	WB
14852	3623781.19	217136.47	-5.37	WB
14853	3623781.40	217139.42	-5.44	WB
14854	3623781.56	217142.37	-5.51	WB
14855	3623781.73	217145.32	-5.61	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
14856	3623781.88	217148.22	-5.69	WB
14857	3623782.03	217151.17	-5.78	WB
14858	3623782.11	217152.60	-5.84	WB
14859	3623782.17	217154.03	-5.90	WB
14860	3623782.30	217156.94	-5.97	WB
14861	3623782.41	217159.95	-6.01	WB
14862	3623782.38	217162.94	-6.03	WB
14863	3623782.34	217166.03	-6.07	WB
14864	3623782.28	217169.18	-6.01	WB
14865	3623782.21	217172.30	-5.98	WB
14866	3623782.14	217175.47	-5.93	WB
14867	3623782.11	217177.81	-5.88	WB
14868	3623782.09	217178.61	-5.80	WB
14869	3623782.04	217181.70	-5.71	WB
14870	3623782.03	217184.86	-5.64	WB
14871	3623782.03	217187.92	-5.59	WB
14872	3623782.05	217190.95	-5.52	WB
14873	3623782.10	217193.88	-5.51	WB
14874	3623782.17	217196.81	-5.47	WB
14875	3623782.27	217199.69	-5.43	WB
14876	3623782.40	217202.59	-5.39	WB
14877	3623782.41	217202.94	-5.38	WB
14878	3623782.53	217205.52	-5.37	WB
14879	3623782.69	217208.40	-5.36	WB
14880	3623782.86	217211.38	-5.33	WB
14881	3623782.99	217214.29	-5.32	WB
14882	3623783.13	217217.19	-5.31	WB
14883	3623783.31	217220.18	-5.31	WB
14884	3623783.53	217223.07	-5.31	WB
14885	3623783.75	217225.92	-5.31	WB
14886	3623783.89	217227.74	-5.30	WB
14887	3623783.98	217228.87	-5.30	WB
14888	3623784.19	217231.81	-5.30	WB
14889	3623784.36	217234.88	-5.31	WB
14890	3623784.49	217237.99	-5.32	WB
14891	3623784.60	217241.10	-5.32	WB
14892	3623784.65	217244.51	-5.32	WB
14893	3623784.69	217247.92	-5.31	WB
14894	3623784.64	217251.53	-5.31	WB
14895	3623784.60	217252.90	-5.31	WB
14896	3623784.53	217255.17	-5.32	WB
14897	3623784.43	217258.91	-5.32	WB
14898	3623784.34	217262.66	-5.33	WB
14899	3623784.27	217266.32	-5.33	WB
14900	3623784.17	217270.02	-5.33	WB
14901	3623784.06	217273.55	-5.33	WB
14902	3623783.96	217277.02	-5.33	WB
14903	3623783.94	217277.47	-5.33	WB
14904	3623783.81	217280.39	-5.33	WB
14905	3623783.66	217283.69	-5.32	WB
14906	3623783.43	217286.80	-5.31	WB
14907	3623783.16	217289.85	-5.27	WB
14908	3623782.83	217292.87	-5.22	WB
14909	3623782.37	217295.74	-5.17	WB
14910	3623781.88	217298.64	-5.12	WB
14911	3623781.28	217301.39	-5.07	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
14912	3623781.19	217301.75	-5.01	WB
14913	3623780.63	217304.13	-4.94	WB
14914	3623779.96	217306.91	-4.87	WB
14915	3623779.32	217309.54	-4.79	WB
14916	3623778.67	217312.22	-4.73	WB
14917	3623777.96	217314.98	-4.69	WB
14918	3623777.26	217317.65	-4.67	WB
14919	3623776.60	217320.38	-4.63	WB
14920	3623776.00	217323.10	-4.59	WB
14921	3623775.40	217325.78	-4.55	WB
14922	3623775.11	217327.22	-4.52	WB
14923	3623774.84	217328.58	-4.48	WB
14924	3623774.27	217331.35	-4.44	WB
14925	3623773.75	217334.12	-4.40	WB
14926	3623773.25	217337.06	-4.36	WB
14927	3623772.79	217339.88	-4.33	WB
14928	3623772.47	217342.82	-4.29	WB
14929	3623772.14	217345.81	-4.25	WB
14930	3623771.93	217348.78	-4.21	WB
14931	3623771.77	217351.88	-4.17	WB
14932	3623771.72	217353.02	-4.13	WB
14933	3623771.67	217354.91	-4.09	WB
14934	3623771.75	217357.93	-4.05	WB
14935	3623771.85	217361.02	-4.01	WB
14936	3623772.04	217364.06	-3.97	WB
14937	3623772.27	217367.06	-3.93	WB
14938	3623772.55	217370.09	-3.89	WB
14939	3623772.92	217373.12	-3.85	WB
14940	3623773.29	217376.09	-3.81	WB
14941	3623773.67	217378.84	-3.76	WB
14942	3623773.73	217379.26	-3.71	WB
14943	3623774.16	217382.33	-3.66	WB
14944	3623774.60	217385.48	-3.61	WB
14945	3623774.79	217388.46	-3.56	WB
14946	3623774.98	217391.45	-3.51	WB
14947	3623775.17	217394.43	-3.46	WB
14948	3623775.35	217397.42	-3.40	WB
14949	3623775.54	217400.40	-3.35	WB
14950	3623775.73	217403.39	-3.29	WB
14951	3623775.92	217406.37	-3.24	WB
14952	3623776.11	217409.36	-3.18	WB
14953	3623776.30	217412.34	-3.12	WB
14954	3623776.49	217415.33	-3.06	WB
14955	3623776.67	217418.31	-3.00	WB
14956	3623776.86	217421.30	-2.94	WB
14957	3623777.05	217424.28	-2.88	WB
14958	3623777.24	217427.27	-2.83	WB
14959	3623777.43	217430.25	-2.78	WB
14960	3623777.45	217433.21	-2.74	WB
14961	3623777.47	217436.17	-2.71	WB
14962	3623777.50	217439.12	-2.69	WB
14963	3623777.52	217442.08	-2.67	WB
14964	3623777.54	217445.04	-2.66	WB
14965	3623777.57	217447.99	-2.63	WB
14966	3623777.59	217450.95	-2.61	WB
14967	3623777.61	217453.91	-2.60	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
14968	3623777.64	217456.86	-2.61	WB
14969	3623777.66	217459.82	-2.61	WB
14970	3623777.68	217462.78	-2.62	WB
14971	3623777.71	217465.74	-2.63	WB
14972	3623777.73	217468.69	-2.64	WB
14973	3623777.75	217471.65	-2.65	WB
14974	3623777.73	217473.58	-2.66	WB
14975	3623777.70	217475.52	-2.69	WB
14976	3623777.67	217477.45	-2.72	WB
14977	3623777.65	217479.38	-2.73	WB
14978	3623777.62	217481.31	-2.76	WB
14979	3623777.60	217483.25	-2.79	WB
14980	3623777.57	217485.18	-2.81	WB
14981	3623777.54	217487.11	-2.83	WB
14982	3623777.52	217489.05	-2.83	WB
14983	3623777.49	217490.98	-2.87	WB
14984	3623777.46	217492.91	-2.88	WB
14985	3623777.44	217494.84	-2.90	WB
14986	3623777.41	217496.78	-2.91	WB
14987	3623777.38	217498.71	-2.90	WB
14988	3623777.36	217500.64	-2.92	WB
14989	3623777.33	217502.58	-2.93	WB
14990	3623777.31	217504.51	-2.96	WB
14991	3623777.26	217505.58	-2.97	WB
14992	3623777.24	217506.70	-2.99	WB
14993	3623777.21	217507.59	-3.00	WB
14994	3623777.20	217507.89	-3.01	WB
14995	3623777.14	217509.13	-3.01	WB
14996	3623777.08	217510.38	-3.01	WB
14997	3623777.05	217511.60	-3.01	WB
14998	3623777.10	217512.69	-3.01	WB
14999	3623777.16	217513.75	-3.00	WB
15000	3623777.26	217514.57	-3.00	WB
15001	3623777.36	217515.37	-3.00	WB
15002	3623777.48	217516.03	-3.01	WB
15003	3623777.64	217516.54	-3.01	WB
15004	3623777.78	217517.04	-3.02	WB
15005	3623777.92	217517.33	-3.02	WB
15006	3623778.06	217517.63	-3.03	WB
15007	3623778.20	217517.79	-3.03	WB
15008	3623778.33	217517.84	-3.04	WB
15009	3623778.46	217517.87	-3.04	WB
15010	3623778.57	217517.78	-3.02	WB
15011	3623778.68	217517.70	-3.01	WB
15012	3623778.76	217517.62	-3.00	WB
15013	3623778.82	217517.54	-2.98	WB
15014	3623778.86	217517.49	-3.00	WB
15015	3623287.11	215754.88	-8.50	WB
15016	3623286.65	215757.55	-8.51	WB
15017	3623286.15	215760.29	-8.51	WB
15018	3623286.03	215760.94	-8.51	WB
15019	3623285.62	215763.05	-8.50	WB
15020	3623285.06	215765.94	-8.49	WB
15021	3623284.49	215768.83	-8.47	WB
15022	3623283.84	215771.85	-8.46	WB
15023	3623283.16	215774.98	-8.45	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
15024	3623282.55	215778.08	-8.44	WB
15025	3623281.98	215781.13	-8.44	WB
15026	3623281.45	215784.18	-8.43	WB
15027	3623281.13	215786.45	-8.42	WB
15028	3623281.03	215787.20	-8.41	WB
15029	3623280.64	215790.12	-8.40	WB
15030	3623280.31	215792.99	-8.39	WB
15031	3623280.01	215795.80	-8.39	WB
15032	3623279.73	215798.53	-8.38	WB
15033	3623279.50	215801.25	-8.37	WB
15034	3623279.28	215803.93	-8.36	WB
15035	3623279.07	215806.69	-8.36	WB
15036	3623278.85	215809.42	-8.35	WB
15037	3623278.66	215811.48	-8.34	WB
15038	3623278.59	215812.26	-8.34	WB
15039	3623278.33	215815.17	-8.33	WB
15040	3623278.07	215818.08	-8.33	WB
15041	3623277.82	215821.03	-8.32	WB
15042	3623277.58	215823.98	-8.32	WB
15043	3623277.32	215827.05	-8.31	WB
15044	3623277.06	215830.05	-8.31	WB
15045	3623276.82	215833.06	-8.30	WB
15046	3623276.64	215836.13	-8.30	WB
15047	3623276.60	215836.85	-8.29	WB
15048	3623276.48	215839.10	-8.29	WB
15049	3623276.37	215842.04	-8.28	WB
15050	3623276.28	215845.09	-8.28	WB
15051	3623276.22	215848.03	-8.27	WB
15052	3623276.18	215851.16	-8.27	WB
15053	3623276.15	215854.25	-8.26	WB
15054	3623276.10	215857.37	-8.26	WB
15055	3623276.05	215860.66	-8.25	WB
15056	3623276.05	215861.43	-8.25	WB
15057	3623275.99	215863.88	-8.24	WB
15058	3623275.83	215867.03	-8.24	WB
15059	3623275.66	215870.24	-8.23	WB
15060	3623275.47	215873.49	-8.23	WB
15061	3623275.30	215876.64	-8.22	WB
15062	3623275.08	215879.89	-8.22	WB
15063	3623274.79	215883.12	-8.21	WB
15064	3623274.51	215886.30	-8.20	WB
15065	3623274.19	215889.47	-8.20	WB
15066	3623273.87	215892.63	-8.19	WB
15067	3623273.57	215895.60	-8.19	WB
15068	3623273.30	215898.60	-8.18	WB
15069	3623273.03	215901.49	-8.18	WB
15070	3623272.77	215904.39	-8.17	WB
15071	3623272.50	215907.29	-8.17	WB
15072	3623272.21	215910.12	-8.16	WB
15073	3623272.08	215911.20	-8.16	WB
15074	3623271.88	215913.01	-8.15	WB
15075	3623271.52	215915.96	-8.15	WB
15076	3623271.10	215918.83	-8.15	WB
15077	3623270.66	215921.75	-8.14	WB
15078	3623270.25	215924.74	-8.14	WB
15079	3623269.87	215927.75	-8.14	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
15080	3623269.52	215930.78	-8.13	WB
15081	3623269.29	215933.90	-8.13	WB
15082	3623269.08	215936.90	-8.13	WB
15083	3623268.98	215939.97	-8.12	WB
15084	3623268.90	215943.15	-8.12	WB
15085	3623268.85	215946.28	-8.12	WB
15086	3623268.85	215949.48	-8.12	WB
15087	3623268.86	215952.82	-8.12	WB
15088	3623268.87	215956.13	-8.11	WB
15089	3623268.89	215959.50	-8.11	WB
15090	3623268.90	215962.07	-8.11	WB
15091	3623268.89	215962.98	-8.11	WB
15092	3623268.87	215966.37	-8.10	WB
15093	3623268.85	215969.85	-8.10	WB
15094	3623268.86	215973.24	-8.10	WB
15095	3623268.87	215976.58	-8.09	WB
15096	3623268.85	215979.91	-8.09	WB
15097	3623268.79	215983.30	-8.09	WB
15098	3623268.70	215986.62	-8.08	WB
15099	3623268.63	215990.02	-8.08	WB
15100	3623268.56	215993.47	-8.08	WB
15101	3623268.49	215996.82	-8.07	WB
15102	3623268.42	216000.22	-8.07	WB
15103	3623268.35	216003.69	-8.07	WB
15104	3623268.40	216006.93	-8.06	WB
15105	3623268.45	216010.25	-8.06	WB
15106	3623268.52	216012.26	-8.05	WB
15107	3623268.58	216013.42	-8.05	WB
15108	3623268.76	216016.48	-8.05	WB
15109	3623268.95	216019.56	-8.04	WB
15110	3623269.27	216022.49	-8.04	WB
15111	3623269.58	216025.41	-8.03	WB
15112	3623270.00	216028.23	-8.03	WB
15113	3623270.47	216030.99	-8.03	WB
15114	3623270.96	216033.72	-8.03	WB
15115	3623271.49	216036.45	-8.02	WB
15116	3623271.62	216037.11	-8.02	WB
15117	3623272.01	216039.21	-8.02	WB
15118	3623272.42	216042.06	-8.02	WB
15119	3623272.82	216044.97	-8.02	WB
15120	3623273.19	216047.77	-8.02	WB
15121	3623273.56	216050.59	-8.01	WB
15122	3623273.95	216053.42	-8.01	WB
15123	3623274.31	216056.24	-8.01	WB
15124	3623274.67	216059.07	-8.01	WB
15125	3623274.99	216062.02	-8.01	WB
15126	3623275.22	216064.97	-8.01	WB
15127	3623275.45	216067.98	-8.01	WB
15128	3623275.56	216071.28	-8.01	WB
15129	3623275.65	216074.49	-8.01	WB
15130	3623275.62	216077.98	-8.01	WB
15131	3623275.50	216081.54	-8.00	WB
15132	3623275.39	216085.02	-8.00	WB
15133	3623275.32	216086.86	-8.00	WB
15134	3623275.25	216088.62	-8.00	WB
15135	3623275.12	216092.27	-7.99	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
15136	3623274.95	216095.70	-7.99	WB
15137	3623274.74	216099.20	-7.99	WB
15138	3623274.52	216102.71	-7.98	WB
15139	3623274.30	216105.96	-7.98	WB
15140	3623274.07	216109.27	-7.97	WB
15141	3623273.95	216111.28	-7.97	WB
15142	3623273.89	216112.41	-7.96	WB
15143	3623273.73	216115.41	-7.95	WB
15144	3623273.55	216118.45	-7.95	WB
15145	3623273.32	216121.27	-7.94	WB
15146	3623273.05	216124.10	-7.94	WB
15147	3623272.71	216126.95	-7.93	WB
15148	3623272.33	216129.72	-7.92	WB
15149	3623271.93	216132.50	-7.92	WB
15150	3623271.52	216135.25	-7.91	WB
15151	3623271.32	216136.60	-7.90	WB
15152	3623271.11	216138.01	-7.90	WB
15153	3623270.85	216140.82	-7.89	WB
15154	3623270.62	216143.62	-7.89	WB
15155	3623270.49	216146.51	-7.88	WB
15156	3623270.47	216149.50	-7.88	WB
15157	3623270.45	216152.54	-7.87	WB
15158	3623270.60	216155.60	-7.87	WB
15159	3623270.75	216158.77	-7.86	WB
15160	3623271.05	216161.99	-7.86	WB
15161	3623271.16	216162.76	-7.86	WB
15162	3623271.50	216165.14	-7.85	WB
15163	3623271.96	216168.26	-7.85	WB
15164	3623272.52	216171.57	-7.85	WB
15165	3623273.06	216174.70	-7.85	WB
15166	3623273.64	216177.89	-7.84	WB
15167	3623274.23	216181.05	-7.84	WB
15168	3623274.81	216184.15	-7.84	WB
15169	3623275.34	216187.24	-7.84	WB
15170	3623275.40	216187.61	-7.83	WB
15171	3623275.88	216190.31	-7.83	WB
15172	3623276.40	216193.28	-7.83	WB
15173	3623276.90	216196.22	-7.83	WB
15174	3623277.38	216199.21	-7.83	WB
15175	3623277.70	216202.04	-7.82	WB
15176	3623278.01	216204.94	-7.82	WB
15177	3623278.24	216207.86	-7.82	WB
15178	3623278.42	216210.71	-7.81	WB
15179	3623278.47	216211.45	-7.81	WB
15180	3623278.56	216213.62	-7.81	WB
15181	3623278.61	216216.61	-7.80	WB
15182	3623278.64	216219.49	-7.80	WB
15183	3623278.58	216222.50	-7.80	WB
15184	3623278.49	216225.50	-7.79	WB
15185	3623278.38	216228.55	-7.79	WB
15186	3623278.22	216231.66	-7.78	WB
15187	3623278.05	216234.77	-7.78	WB
15188	3623277.94	216236.76	-7.77	WB
15189	3623277.88	216237.87	-7.77	WB
15190	3623277.73	216240.99	-7.76	WB
15191	3623277.60	216244.04	-7.76	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
15192	3623277.49	216247.02	-7.75	WB
15193	3623277.37	216250.13	-7.75	WB
15194	3623277.23	216253.30	-7.74	WB
15195	3623277.09	216256.43	-7.74	WB
15196	3623276.95	216259.73	-7.73	WB
15197	3623276.86	216261.71	-7.73	WB
15198	3623276.81	216262.92	-7.73	WB
15199	3623276.69	216266.12	-7.72	WB
15200	3623276.68	216269.35	-7.72	WB
15201	3623276.68	216272.48	-7.71	WB
15202	3623276.75	216275.63	-7.71	WB
15203	3623276.83	216278.77	-7.70	WB
15204	3623276.92	216281.82	-7.70	WB
15205	3623276.98	216285.02	-7.70	WB
15206	3623277.01	216287.02	-7.69	WB
15207	3623277.02	216288.21	-7.69	WB
15208	3623277.08	216291.41	-7.68	WB
15209	3623277.15	216294.70	-7.68	WB
15210	3623277.22	216297.96	-7.68	WB
15211	3623277.29	216301.25	-7.67	WB
15212	3623277.38	216304.52	-7.67	WB
15213	3623277.50	216307.76	-7.66	WB
15214	3623277.63	216311.02	-7.66	WB
15215	3623277.69	216312.28	-7.66	WB
15216	3623277.82	216314.24	-7.65	WB
15217	3623278.07	216317.45	-7.65	WB
15218	3623278.33	216320.65	-7.64	WB
15219	3623278.55	216323.91	-7.64	WB
15220	3623278.77	216327.06	-7.63	WB
15221	3623278.96	216330.28	-7.63	WB
15222	3623279.11	216333.54	-7.62	WB
15223	3623279.23	216336.71	-7.62	WB
15224	3623279.16	216339.95	-7.61	WB
15225	3623279.09	216343.23	-7.60	WB
15226	3623278.94	216346.40	-7.60	WB
15227	3623278.73	216349.60	-7.59	WB
15228	3623278.50	216352.75	-7.59	WB
15229	3623278.16	216355.86	-7.58	WB
15230	3623277.80	216359.07	-7.57	WB
15231	3623277.50	216361.43	-7.57	WB
15232	3623277.39	216362.22	-7.56	WB
15233	3623276.97	216365.35	-7.55	WB
15234	3623276.57	216368.46	-7.55	WB
15235	3623276.23	216371.51	-7.54	WB
15236	3623275.90	216374.56	-7.53	WB
15237	3623275.57	216377.55	-7.53	WB
15238	3623275.24	216380.52	-7.52	WB
15239	3623274.98	216383.44	-7.51	WB
15240	3623274.85	216386.47	-7.51	WB
15241	3623274.71	216389.40	-7.50	WB
15242	3623274.51	216392.50	-7.50	WB
15243	3623274.27	216395.71	-7.49	WB
15244	3623274.09	216398.82	-7.48	WB
15245	3623273.95	216402.01	-7.48	WB
15246	3623273.81	216405.25	-7.48	WB
15247	3623273.65	216408.46	-7.47	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
15248	3623273.49	216411.73	-7.47	WB
15249	3623273.40	216414.86	-7.46	WB
15250	3623273.38	216417.95	-7.46	WB
15251	3623273.36	216421.12	-7.46	WB
15252	3623273.42	216424.19	-7.45	WB
15253	3623273.47	216427.26	-7.45	WB
15254	3623273.48	216430.36	-7.45	WB
15255	3623273.46	216433.42	-7.44	WB
15256	3623273.45	216436.47	-7.44	WB
15257	3623273.45	216436.84	-7.44	WB
15258	3623273.47	216439.53	-7.43	WB
15259	3623273.49	216442.59	-7.43	WB
15260	3623273.40	216445.70	-7.43	WB
15261	3623273.26	216448.93	-7.42	WB
15262	3623273.11	216452.18	-7.42	WB
15263	3623272.94	216455.49	-7.42	WB
15264	3623272.78	216458.90	-7.41	WB
15265	3623272.60	216461.85	-7.41	WB
15266	3623272.58	216462.30	-7.40	WB
15267	3623272.37	216465.68	-7.40	WB
15268	3623272.15	216469.17	-7.39	WB
15269	3623271.95	216472.64	-7.39	WB
15270	3623271.75	216476.10	-7.38	WB
15271	3623271.58	216479.57	-7.37	WB
15272	3623271.43	216483.02	-7.37	WB
15273	3623271.26	216486.39	-7.36	WB
15274	3623271.24	216486.79	-7.35	WB
15275	3623271.08	216489.73	-7.34	WB
15276	3623270.89	216493.08	-7.34	WB
15277	3623270.72	216496.32	-7.33	WB
15278	3623270.54	216499.60	-7.32	WB
15279	3623270.38	216502.74	-7.31	WB
15280	3623270.22	216505.83	-7.30	WB
15281	3623270.03	216509.06	-7.29	WB
15282	3623269.90	216511.70	-7.28	WB
15283	3623269.88	216512.11	-7.28	WB
15284	3623269.73	216515.13	-7.27	WB
15285	3623269.67	216518.17	-7.26	WB
15286	3623269.66	216521.13	-7.25	WB
15287	3623269.67	216524.11	-7.25	WB
15288	3623269.75	216526.98	-7.24	WB
15289	3623269.82	216529.86	-7.23	WB
15290	3623270.02	216532.68	-7.22	WB
15291	3623270.30	216535.50	-7.22	WB
15292	3623270.47	216537.30	-7.21	WB
15293	3623270.57	216538.30	-7.21	WB
15294	3623270.82	216541.15	-7.20	WB
15295	3623271.09	216544.06	-7.20	WB
15296	3623271.41	216546.95	-7.19	WB
15297	3623271.75	216549.79	-7.19	WB
15298	3623272.14	216552.78	-7.18	WB
15299	3623272.56	216555.84	-7.18	WB
15300	3623272.98	216558.87	-7.17	WB
15301	3623273.37	216562.20	-7.17	WB
15302	3623273.42	216562.60	-7.16	WB
15303	3623273.76	216565.57	-7.16	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
15304	3623274.18	216569.06	-7.16	WB
15305	3623274.64	216572.63	-7.15	WB
15306	3623275.12	216576.19	-7.15	WB
15307	3623275.53	216579.77	-7.14	WB
15308	3623275.95	216583.35	-7.14	WB
15309	3623276.35	216586.82	-7.13	WB
15310	3623276.41	216587.28	-7.13	WB
15311	3623276.74	216590.16	-7.12	WB
15312	3623277.15	216593.52	-7.11	WB
15313	3623277.45	216596.51	-7.11	WB
15314	3623277.74	216599.56	-7.10	WB
15315	3623277.96	216602.54	-7.10	WB
15316	3623278.12	216605.36	-7.09	WB
15317	3623278.24	216608.21	-7.08	WB
15318	3623278.21	216611.10	-7.07	WB
15319	3623278.20	216611.44	-7.07	WB
15320	3623278.16	216613.90	-7.06	WB
15321	3623278.04	216616.76	-7.05	WB
15322	3623277.88	216619.60	-7.04	WB
15323	3623277.71	216622.38	-7.04	WB
15324	3623277.55	216625.16	-7.03	WB
15325	3623277.39	216627.89	-7.02	WB
15326	3623277.30	216630.50	-7.02	WB
15327	3623277.22	216633.13	-7.01	WB
15328	3623277.12	216635.82	-7.00	WB
15329	3623277.09	216636.45	-7.00	WB
15330	3623277.00	216638.41	-6.99	WB
15331	3623276.86	216641.05	-6.99	WB
15332	3623276.80	216643.79	-6.98	WB
15333	3623276.76	216646.47	-6.98	WB
15334	3623276.70	216649.25	-6.97	WB
15335	3623276.61	216652.17	-6.97	WB
15336	3623276.53	216655.01	-6.97	WB
15337	3623276.48	216658.17	-6.96	WB
15338	3623276.44	216661.22	-6.96	WB
15339	3623276.42	216662.00	-6.96	WB
15340	3623276.36	216664.45	-6.95	WB
15341	3623276.26	216667.87	-6.95	WB
15342	3623276.16	216671.19	-6.95	WB
15343	3623276.10	216674.76	-6.94	WB
15344	3623276.05	216678.37	-6.94	WB
15345	3623276.01	216682.01	-6.94	WB
15346	3623275.99	216685.68	-6.93	WB
15347	3623275.98	216687.10	-6.93	WB
15348	3623275.98	216689.37	-6.92	WB
15349	3623275.98	216692.91	-6.92	WB
15350	3623276.00	216696.48	-6.91	WB
15351	3623276.00	216700.00	-6.91	WB
15352	3623276.00	216703.34	-6.90	WB
15353	3623276.00	216706.72	-6.90	WB
15354	3623275.97	216709.86	-6.89	WB
15355	3623275.96	216711.41	-6.88	WB
15356	3623275.94	216713.01	-6.87	WB
15357	3623275.87	216716.04	-6.87	WB
15358	3623275.79	216718.88	-6.86	WB
15359	3623275.71	216721.73	-6.85	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
15360	3623275.63	216724.54	-6.84	WB
15361	3623275.55	216727.33	-6.83	WB
15362	3623275.37	216730.03	-6.82	WB
15363	3623275.15	216732.82	-6.81	WB
15364	3623274.91	216735.55	-6.80	WB
15365	3623274.88	216735.87	-6.79	WB
15366	3623274.65	216738.27	-6.78	WB
15367	3623274.38	216741.00	-6.77	WB
15368	3623273.99	216743.69	-6.76	WB
15369	3623273.58	216746.40	-6.75	WB
15370	3623273.17	216749.13	-6.74	WB
15371	3623272.76	216751.78	-6.73	WB
15372	3623272.35	216754.48	-6.73	WB
15373	3623271.92	216757.24	-6.72	WB
15374	3623271.50	216759.91	-6.71	WB
15375	3623271.24	216761.60	-6.70	WB
15376	3623271.10	216762.67	-6.69	WB
15377	3623270.70	216765.57	-6.69	WB
15378	3623270.33	216768.40	-6.68	WB
15379	3623270.03	216771.46	-6.67	WB
15380	3623269.72	216774.58	-6.66	WB
15381	3623269.45	216777.80	-6.66	WB
15382	3623269.18	216781.24	-6.65	WB
15383	3623268.96	216784.74	-6.64	WB
15384	3623268.91	216787.51	-6.64	WB
15385	3623268.90	216788.40	-6.63	WB
15386	3623268.85	216792.14	-6.62	WB
15387	3623268.86	216795.87	-6.61	WB
15388	3623268.90	216799.69	-6.61	WB
15389	3623269.00	216803.49	-6.60	WB
15390	3623269.25	216807.19	-6.59	WB
15391	3623269.52	216810.84	-6.58	WB
15392	3623269.63	216812.15	-6.57	WB
15393	3623269.84	216814.23	-6.56	WB
15394	3623270.20	216817.66	-6.55	WB
15395	3623270.55	216820.89	-6.54	WB
15396	3623270.87	216823.96	-6.53	WB
15397	3623271.21	216827.18	-6.52	WB
15398	3623271.47	216830.13	-6.50	WB
15399	3623271.72	216833.19	-6.49	WB
15400	3623271.92	216836.17	-6.48	WB
15401	3623271.94	216836.52	-6.46	WB
15402	3623272.08	216839.08	-6.45	WB
15403	3623272.24	216842.07	-6.43	WB
15404	3623272.39	216844.93	-6.42	WB
15405	3623272.52	216847.83	-6.41	WB
15406	3623272.57	216850.67	-6.39	WB
15407	3623272.57	216853.48	-6.38	WB
15408	3623272.55	216856.29	-6.36	WB
15409	3623272.54	216859.03	-6.35	WB
15410	3623272.53	216861.76	-6.33	WB
15411	3623272.52	216864.50	-6.32	WB
15412	3623272.52	216867.27	-6.31	WB
15413	3623272.51	216869.92	-6.29	WB
15414	3623272.53	216872.64	-6.28	WB
15415	3623272.55	216875.39	-6.27	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
15416	3623272.65	216878.08	-6.25	WB
15417	3623272.77	216880.74	-6.24	WB
15418	3623272.88	216883.57	-6.23	WB
15419	3623272.99	216886.36	-6.22	WB
15420	3623273.01	216887.07	-6.21	WB
15421	3623273.09	216889.19	-6.20	WB
15422	3623273.23	216892.15	-6.18	WB
15423	3623273.38	216895.14	-6.17	WB
15424	3623273.52	216898.22	-6.16	WB
15425	3623273.66	216901.48	-6.15	WB
15426	3623273.80	216904.74	-6.14	WB
15427	3623274.02	216908.28	-6.13	WB
15428	3623274.26	216911.96	-6.12	WB
15429	3623274.29	216912.40	-6.10	WB
15430	3623274.49	216915.63	-6.09	WB
15431	3623274.72	216919.51	-6.08	WB
15432	3623274.96	216923.45	-6.06	WB
15433	3623275.27	216927.35	-6.05	WB
15434	3623275.60	216931.26	-6.03	WB
15435	3623275.92	216935.09	-6.02	WB
15436	3623276.12	216937.45	-6.00	WB
15437	3623276.23	216938.78	-5.98	WB
15438	3623276.57	216942.57	-5.96	WB
15439	3623276.90	216945.92	-5.94	WB
15440	3623277.24	216949.22	-5.92	WB
15441	3623277.53	216952.42	-5.90	WB
15442	3623277.77	216955.46	-5.88	WB
15443	3623277.97	216958.45	-5.86	WB
15444	3623278.09	216961.33	-5.83	WB
15445	3623278.19	216964.18	-5.81	WB
15446	3623278.27	216966.88	-5.78	WB
15447	3623278.35	216969.57	-5.76	WB
15448	3623278.39	216972.29	-5.73	WB
15449	3623278.31	216974.87	-5.70	WB
15450	3623278.22	216977.59	-5.67	WB
15451	3623278.20	216980.16	-5.64	WB
15452	3623278.20	216982.80	-5.61	WB
15453	3623278.14	216985.51	-5.58	WB
15454	3623278.09	216986.48	-5.55	WB
15455	3623278.00	216988.19	-5.52	WB
15456	3623277.85	216990.92	-5.50	WB
15457	3623277.79	216993.74	-5.47	WB
15458	3623277.75	216996.47	-5.45	WB
15459	3623277.73	216999.26	-5.43	WB
15460	3623277.72	217002.09	-5.41	WB
15461	3623277.71	217004.93	-5.38	WB
15462	3623277.75	217007.77	-5.36	WB
15463	3623277.80	217010.60	-5.33	WB
15464	3623277.82	217011.66	-5.31	WB
15465	3623277.88	217013.48	-5.29	WB
15466	3623277.98	217016.34	-5.27	WB
15467	3623278.09	217019.22	-5.25	WB
15468	3623278.22	217022.03	-5.23	WB
15469	3623278.35	217024.88	-5.21	WB
15470	3623278.53	217027.88	-5.19	WB
15471	3623278.73	217030.86	-5.18	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
15472	3623278.91	217033.93	-5.16	WB
15473	3623279.03	217037.33	-5.15	WB
15474	3623279.15	217040.64	-5.13	WB
15475	3623279.30	217044.26	-5.11	WB
15476	3623279.47	217047.90	-5.10	WB
15477	3623279.65	217051.51	-5.08	WB
15478	3623279.89	217055.34	-5.06	WB
15479	3623280.14	217059.08	-5.04	WB
15480	3623280.32	217062.35	-5.02	WB
15481	3623280.34	217062.79	-5.01	WB
15482	3623280.54	217066.49	-4.99	WB
15483	3623280.75	217070.11	-4.97	WB
15484	3623280.93	217073.53	-4.94	WB
15485	3623281.14	217077.04	-4.92	WB
15486	3623281.21	217080.27	-4.89	WB
15487	3623281.27	217083.49	-4.87	WB
15488	3623281.31	217086.23	-4.85	WB
15489	3623281.31	217086.61	-4.83	WB
15490	3623281.30	217089.44	-4.80	WB
15491	3623281.29	217092.33	-4.76	WB
15492	3623281.08	217095.02	-4.73	WB
15493	3623280.85	217097.66	-4.68	WB
15494	3623280.54	217100.31	-4.63	WB
15495	3623280.16	217102.96	-4.59	WB
15496	3623279.77	217105.55	-4.56	WB
15497	3623279.21	217108.21	-4.49	WB
15498	3623278.71	217110.50	-4.43	WB
15499	3623278.63	217110.86	-4.36	WB
15500	3623277.95	217113.53	-4.31	WB
15501	3623277.17	217116.29	-4.28	WB
15502	3623276.41	217118.99	-4.28	WB
15503	3623275.66	217121.75	-4.29	WB
15504	3623274.93	217124.49	-4.27	WB
15505	3623274.18	217127.27	-4.23	WB
15506	3623273.44	217130.06	-4.22	WB
15507	3623272.71	217132.92	-4.23	WB
15508	3623272.02	217135.77	-4.23	WB
15509	3623271.93	217136.16	-4.24	WB
15510	3623271.33	217138.66	-4.26	WB
15511	3623270.68	217141.64	-4.28	WB
15512	3623270.06	217144.56	-4.28	WB
15513	3623269.47	217147.52	-4.31	WB
15514	3623268.96	217150.46	-4.34	WB
15515	3623268.47	217153.39	-4.39	WB
15516	3623268.09	217156.33	-4.43	WB
15517	3623267.75	217159.20	-4.48	WB
15518	3623267.48	217161.77	-4.52	WB
15519	3623267.45	217162.11	-4.58	WB
15520	3623267.23	217165.04	-4.62	WB
15521	3623267.02	217167.87	-4.68	WB
15522	3623266.98	217170.73	-4.74	WB
15523	3623266.94	217173.63	-4.81	WB
15524	3623266.99	217176.46	-4.89	WB
15525	3623267.12	217179.46	-4.94	WB
15526	3623267.24	217182.38	-5.01	WB
15527	3623267.45	217185.42	-5.08	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
15528	3623267.58	217187.40	-5.16	WB
15529	3623267.66	217188.60	-5.24	WB
15530	3623267.96	217191.73	-5.33	WB
15531	3623268.33	217194.95	-5.42	WB
15532	3623268.74	217198.12	-5.52	WB
15533	3623269.29	217201.43	-5.62	WB
15534	3623269.85	217204.73	-5.74	WB
15535	3623270.46	217208.10	-5.87	WB
15536	3623271.10	217211.48	-5.98	WB
15537	3623271.42	217213.12	-6.06	WB
15538	3623271.76	217214.79	-6.12	WB
15539	3623272.47	217218.05	-6.16	WB
15540	3623273.18	217221.15	-6.17	WB
15541	3623273.93	217224.06	-6.17	WB
15542	3623274.71	217226.93	-6.14	WB
15543	3623275.42	217229.63	-6.11	WB
15544	3623276.04	217232.28	-6.07	WB
15545	3623276.67	217235.00	-6.03	WB
15546	3623276.95	217236.65	-6.00	WB
15547	3623277.10	217237.58	-5.97	WB
15548	3623277.51	217240.26	-5.96	WB
15549	3623277.83	217242.93	-5.96	WB
15550	3623278.03	217245.54	-5.96	WB
15551	3623278.21	217248.20	-5.96	WB
15552	3623278.21	217251.03	-5.96	WB
15553	3623278.19	217253.81	-5.96	WB
15554	3623278.12	217256.69	-5.94	WB
15555	3623278.01	217259.69	-5.93	WB
15556	3623277.94	217261.54	-5.90	WB
15557	3623277.90	217262.62	-5.87	WB
15558	3623277.73	217265.61	-5.83	WB
15559	3623277.55	217268.64	-5.78	WB
15560	3623277.36	217271.59	-5.72	WB
15561	3623277.16	217274.57	-5.68	WB
15562	3623276.95	217277.55	-5.62	WB
15563	3623276.68	217280.48	-5.56	WB
15564	3623276.41	217283.50	-5.49	WB
15565	3623276.13	217286.48	-5.42	WB
15566	3623275.83	217289.42	-5.34	WB
15567	3623275.52	217292.42	-5.27	WB
15568	3623275.19	217295.45	-5.20	WB
15569	3623274.85	217298.48	-5.14	WB
15570	3623274.51	217301.61	-5.07	WB
15571	3623274.16	217304.80	-5.00	WB
15572	3623273.82	217307.92	-4.96	WB
15573	3623273.51	217311.13	-4.90	WB
15574	3623273.47	217311.51	-4.86	WB
15575	3623273.19	217314.37	-4.82	WB
15576	3623272.98	217317.55	-4.79	WB
15577	3623272.77	217320.78	-4.78	WB
15578	3623272.58	217324.06	-4.77	WB
15579	3623272.41	217327.26	-4.77	WB
15580	3623272.24	217330.56	-4.77	WB
15581	3623272.13	217333.81	-4.76	WB
15582	3623272.03	217336.67	-4.76	WB
15583	3623272.02	217337.05	-4.78	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
15584	3623271.91	217340.42	-4.79	WB
15585	3623271.80	217343.74	-4.80	WB
15586	3623271.68	217347.17	-4.80	WB
15587	3623271.58	217350.66	-4.79	WB
15588	3623271.47	217354.11	-4.79	WB
15589	3623271.36	217357.78	-4.78	WB
15590	3623271.23	217361.46	-4.77	WB
15591	3623271.22	217361.96	-4.78	WB
15592	3623271.11	217365.21	-4.77	WB
15593	3623271.01	217369.00	-4.76	WB
15594	3623270.90	217372.74	-4.74	WB
15595	3623270.79	217376.57	-4.72	WB
15596	3623270.68	217380.42	-4.72	WB
15597	3623270.57	217384.30	-4.69	WB
15598	3623270.51	217386.70	-4.67	WB
15599	3623270.48	217388.13	-4.64	WB
15600	3623270.39	217391.95	-4.60	WB
15601	3623270.29	217395.67	-4.56	WB
15602	3623270.19	217399.44	-4.52	WB
15603	3623270.09	217403.02	-4.49	WB
15604	3623269.99	217406.49	-4.48	WB
15605	3623269.91	217410.00	-4.43	WB
15606	3623269.86	217411.61	-4.40	WB
15607	3623269.82	217413.16	-4.36	WB
15608	3623269.74	217416.32	-4.30	WB
15609	3623269.63	217419.41	-4.24	WB
15610	3623269.50	217422.23	-4.18	WB
15611	3623269.36	217425.12	-4.11	WB
15612	3623269.22	217427.81	-4.04	WB
15613	3623269.08	217430.42	-3.97	WB
15614	3623268.96	217433.02	-3.90	WB
15615	3623268.87	217435.55	-3.83	WB
15616	3623268.84	217436.50	-3.77	WB
15617	3623268.78	217438.06	-3.70	WB
15618	3623268.70	217440.62	-3.63	WB
15619	3623268.61	217443.10	-3.59	WB
15620	3623268.58	217445.60	-3.53	WB
15621	3623268.59	217448.04	-3.46	WB
15622	3623268.63	217450.48	-3.37	WB
15623	3623268.83	217452.84	-3.28	WB
15624	3623269.04	217455.22	-3.20	WB
15625	3623269.35	217457.48	-3.14	WB
15626	3623269.71	217459.82	-3.09	WB
15627	3623270.11	217462.15	-3.05	WB
15628	3623270.18	217462.46	-3.01	WB
15629	3623270.60	217464.43	-2.98	WB
15630	3623271.10	217466.76	-2.96	WB
15631	3623271.65	217469.25	-2.93	WB
15632	3623272.20	217471.71	-2.90	WB
15633	3623272.79	217474.38	-2.88	WB
15634	3623273.41	217477.09	-2.86	WB
15635	3623274.04	217479.84	-2.85	WB
15636	3623274.75	217482.85	-2.83	WB
15637	3623277.22	217491.74	-2.82	WB
15638	3623279.06	217497.59	-2.81	WB
15639	3623282.58	217508.47	-2.82	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
15640	3623284.34	217518.46	-2.84	WB
15641	3623284.54	217520.92	-2.86	WB
15642	3623284.42	217523.32	-2.89	WB
15643	3623284.29	217525.81	-2.92	WB
15644	3623284.06	217528.24	-2.95	WB
15645	3623283.79	217530.67	-2.99	WB
15646	3623283.48	217533.20	-3.03	WB
15647	3623283.12	217535.72	-3.05	WB
15648	3623283.07	217536.06	-3.08	WB
15649	3623282.73	217538.27	-3.10	WB
15650	3623282.31	217540.96	-3.11	WB
15651	3623281.45	217546.35	-3.11	WB
15652	3623281.09	217549.15	-3.11	WB
15653	3623280.74	217551.88	-3.11	WB
15654	3623280.57	217554.60	-3.11	WB
15655	3623280.44	217557.33	-3.11	WB
15656	3623280.40	217559.87	-3.11	WB
15657	3623280.47	217562.04	-3.11	WB
15658	3623280.48	217562.33	-3.10	WB
15659	3623280.58	217564.69	-3.10	WB
15660	3623280.78	217566.78	-3.09	WB
15661	3623280.99	217568.96	-3.09	WB
15662	3623281.22	217570.93	-3.08	WB
15663	3623281.44	217572.85	-3.08	WB
15664	3623281.65	217574.72	-3.07	WB
15665	3623281.78	217576.47	-3.07	WB
15666	3623281.89	217578.29	-3.07	WB
15667	3623281.98	217580.09	-3.07	WB
15668	3623282.05	217581.90	-3.07	WB
15669	3623282.10	217583.70	-3.07	WB
15670	3623282.09	217585.48	-3.07	WB
15671	3623282.08	217586.59	-3.07	WB
15672	3623282.08	217587.25	-3.05	WB
15673	3623282.08	217588.96	-3.04	WB
15674	3623282.09	217590.66	-3.02	WB
15675	3623282.07	217592.38	-2.99	WB
15676	3623281.97	217594.13	-2.95	WB
15677	3623281.87	217595.83	-2.90	WB
15678	3623281.77	217597.61	-2.86	WB
15679	3623281.67	217599.41	-2.81	WB
15680	3623281.58	217601.24	-2.76	WB
15681	3623281.48	217603.23	-2.72	WB
15682	3623281.38	217605.25	-2.67	WB
15683	3623281.21	217607.47	-2.63	WB
15684	3623281.01	217609.80	-2.59	WB
15685	3623280.88	217611.26	-2.55	WB
15686	3623280.78	217612.14	-2.51	WB
15687	3623280.51	217614.47	-2.46	WB
15688	3623280.27	217616.59	-2.41	WB
15689	3622817.01	215772.76	-8.36	WB
15690	3622815.90	215775.19	-8.36	WB
15691	3622814.77	215777.60	-8.35	WB
15692	3622813.56	215780.08	-8.34	WB
15693	3622812.27	215782.65	-8.33	WB
15694	3622810.93	215785.26	-8.33	WB
15695	3622809.47	215788.00	-8.32	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
15696	3622808.38	215790.08	-8.31	WB
15697	3622808.03	215790.73	-8.31	WB
15698	3622806.62	215793.57	-8.30	WB
15699	3622805.26	215796.38	-8.30	WB
15700	3622803.97	215799.18	-8.29	WB
15701	3622802.79	215802.02	-8.28	WB
15702	3622801.67	215804.75	-8.28	WB
15703	3622800.85	215807.38	-8.27	WB
15704	3622800.07	215810.09	-8.27	WB
15705	3622799.40	215812.66	-8.26	WB
15706	3622798.87	215815.26	-8.26	WB
15707	3622798.73	215815.91	-8.25	WB
15708	3622798.33	215817.88	-8.25	WB
15709	3622798.01	215820.53	-8.25	WB
15710	3622797.70	215823.22	-8.24	WB
15711	3622797.41	215826.01	-8.24	WB
15712	3622797.17	215828.78	-8.24	WB
15713	3622796.91	215831.64	-8.23	WB
15714	3622796.73	215834.51	-8.23	WB
15715	3622796.57	215837.34	-8.23	WB
15716	3622796.48	215840.06	-8.23	WB
15717	3622796.46	215841.41	-8.23	WB
15718	3622796.45	215842.72	-8.23	WB
15719	3622796.44	215845.33	-8.22	WB
15720	3622796.40	215847.90	-8.22	WB
15721	3622796.37	215850.37	-8.22	WB
15722	3622796.36	215852.86	-8.22	WB
15723	3622796.37	215855.35	-8.22	WB
15724	3622796.35	215857.78	-8.22	WB
15725	3622796.26	215860.24	-8.21	WB
15726	3622796.14	215862.78	-8.21	WB
15727	3622796.00	215865.34	-8.21	WB
15728	3622795.98	215865.68	-8.21	WB
15729	3622795.85	215867.96	-8.21	WB
15730	3622795.67	215870.60	-8.20	WB
15731	3622795.48	215873.27	-8.20	WB
15732	3622795.27	215876.02	-8.20	WB
15733	3622795.07	215878.70	-8.19	WB
15734	3622794.87	215881.41	-8.19	WB
15735	3622794.69	215884.15	-8.18	WB
15736	3622794.57	215886.91	-8.18	WB
15737	3622794.46	215889.65	-8.17	WB
15738	3622794.41	215891.09	-8.17	WB
15739	3622794.37	215892.57	-8.16	WB
15740	3622794.28	215895.47	-8.16	WB
15741	3622794.28	215898.41	-8.15	WB
15742	3622794.38	215901.46	-8.15	WB
15743	3622794.48	215904.40	-8.14	WB
15744	3622794.57	215907.38	-8.13	WB
15745	3622794.64	215910.42	-8.13	WB
15746	3622794.76	215913.25	-8.12	WB
15747	3622794.92	215916.05	-8.12	WB
15748	3622794.94	215916.38	-8.11	WB
15749	3622795.10	215918.84	-8.11	WB
15750	3622795.36	215921.29	-8.10	WB
15751	3622795.65	215923.79	-8.10	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
15752	3622795.87	215926.14	-8.09	WB
15753	3622796.04	215928.42	-8.09	WB
15754	3622796.21	215930.73	-8.09	WB
15755	3622796.34	215932.92	-8.09	WB
15756	3622796.49	215935.11	-8.08	WB
15757	3622796.57	215937.36	-8.08	WB
15758	3622796.64	215939.63	-8.08	WB
15759	3622796.67	215940.75	-8.08	WB
15760	3622796.65	215941.94	-8.08	WB
15761	3622796.52	215944.34	-8.08	WB
15762	3622796.40	215946.74	-8.08	WB
15763	3622796.27	215949.09	-8.08	WB
15764	3622796.12	215951.53	-8.08	WB
15765	3622795.89	215954.06	-8.08	WB
15766	3622795.56	215956.61	-8.08	WB
15767	3622795.19	215959.32	-8.08	WB
15768	3622794.75	215962.21	-8.08	WB
15769	3622794.30	215965.09	-8.08	WB
15770	3622794.24	215965.49	-8.08	WB
15771	3622793.76	215968.18	-8.08	WB
15772	3622793.15	215971.32	-8.07	WB
15773	3622792.52	215974.52	-8.07	WB
15774	3622791.81	215977.87	-8.07	WB
15775	3622791.11	215981.23	-8.06	WB
15776	3622790.49	215984.55	-8.06	WB
15777	3622789.96	215987.81	-8.05	WB
15778	3622789.45	215991.04	-8.05	WB
15779	3622789.10	215994.02	-8.04	WB
15780	3622788.75	215997.02	-8.03	WB
15781	3622788.50	215999.73	-8.03	WB
15782	3622788.31	216002.34	-8.02	WB
15783	3622788.14	216004.95	-8.01	WB
15784	3622788.13	216007.33	-8.01	WB
15785	3622788.12	216009.67	-8.00	WB
15786	3622788.14	216012.02	-8.00	WB
15787	3622788.17	216014.27	-7.99	WB
15788	3622788.22	216016.23	-7.99	WB
15789	3622788.24	216016.48	-7.98	WB
15790	3622788.40	216018.67	-7.98	WB
15791	3622788.56	216020.87	-7.98	WB
15792	3622788.68	216023.15	-7.97	WB
15793	3622788.77	216025.48	-7.97	WB
15794	3622788.86	216027.89	-7.97	WB
15795	3622788.96	216030.46	-7.97	WB
15796	3622789.06	216033.07	-7.97	WB
15797	3622789.12	216035.90	-7.97	WB
15798	3622789.19	216038.83	-7.97	WB
15799	3622789.25	216041.56	-7.97	WB
15800	3622789.26	216042.00	-7.97	WB
15801	3622789.36	216045.19	-7.97	WB
15802	3622789.47	216048.40	-7.97	WB
15803	3622789.69	216051.70	-7.97	WB
15804	3622789.92	216054.87	-7.97	WB
15805	3622790.15	216057.97	-7.97	WB
15806	3622790.38	216060.98	-7.97	WB
15807	3622790.62	216063.95	-7.97	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
15808	3622790.78	216065.95	-7.97	WB
15809	3622790.83	216066.62	-7.96	WB
15810	3622791.04	216069.27	-7.96	WB
15811	3622791.20	216071.68	-7.96	WB
15812	3622791.32	216073.98	-7.96	WB
15813	3622791.41	216076.26	-7.96	WB
15814	3622791.40	216078.36	-7.95	WB
15815	3622791.38	216080.46	-7.95	WB
15816	3622791.31	216082.51	-7.95	WB
15817	3622791.22	216084.55	-7.94	WB
15818	3622791.03	216086.69	-7.94	WB
15819	3622790.67	216088.83	-7.94	WB
15820	3622790.43	216090.21	-7.94	WB
15821	3622790.28	216091.03	-7.93	WB
15822	3622789.76	216093.47	-7.93	WB
15823	3622789.21	216095.88	-7.93	WB
15824	3622788.61	216098.39	-7.93	WB
15825	3622787.90	216101.09	-7.93	WB
15826	3622787.20	216103.72	-7.92	WB
15827	3622786.51	216106.54	-7.92	WB
15828	3622785.82	216109.37	-7.92	WB
15829	3622785.15	216112.18	-7.92	WB
15830	3622784.48	216115.12	-7.92	WB
15831	3622784.32	216115.81	-7.91	WB
15832	3622783.82	216118.02	-7.91	WB
15833	3622783.30	216120.92	-7.91	WB
15834	3622782.77	216123.80	-7.91	WB
15835	3622782.30	216126.66	-7.91	WB
15836	3622781.87	216129.57	-7.90	WB
15837	3622781.44	216132.53	-7.90	WB
15838	3622781.15	216135.42	-7.90	WB
15839	3622780.89	216138.25	-7.89	WB
15840	3622780.75	216141.18	-7.89	WB
15841	3622780.74	216141.51	-7.88	WB
15842	3622780.69	216143.94	-7.88	WB
15843	3622780.65	216146.70	-7.87	WB
15844	3622780.63	216149.57	-7.86	WB
15845	3622780.62	216152.38	-7.86	WB
15846	3622780.70	216155.14	-7.85	WB
15847	3622780.82	216157.98	-7.84	WB
15848	3622780.94	216160.80	-7.83	WB
15849	3622781.05	216163.62	-7.83	WB
15850	3622781.15	216166.45	-7.82	WB
15851	3622781.16	216166.78	-7.81	WB
15852	3622781.36	216169.16	-7.80	WB
15853	3622781.61	216171.83	-7.80	WB
15854	3622781.92	216174.39	-7.79	WB
15855	3622782.36	216176.71	-7.78	WB
15856	3622782.82	216178.99	-7.78	WB
15857	3622783.27	216181.21	-7.77	WB
15858	3622783.70	216183.37	-7.77	WB
15859	3622784.11	216185.52	-7.76	WB
15860	3622784.51	216187.74	-7.76	WB
15861	3622784.88	216189.88	-7.76	WB
15862	3622785.00	216190.99	-7.76	WB
15863	3622785.12	216192.12	-7.75	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
15864	3622785.35	216194.38	-7.75	WB
15865	3622785.52	216196.59	-7.75	WB
15866	3622785.65	216198.87	-7.75	WB
15867	3622785.76	216201.17	-7.75	WB
15868	3622785.73	216203.66	-7.75	WB
15869	3622785.69	216206.17	-7.75	WB
15870	3622785.54	216208.92	-7.75	WB
15871	3622785.32	216211.83	-7.75	WB
15872	3622785.09	216214.77	-7.75	WB
15873	3622784.98	216216.01	-7.75	WB
15874	3622784.80	216218.01	-7.75	WB
15875	3622784.53	216221.15	-7.75	WB
15876	3622784.20	216224.42	-7.75	WB
15877	3622783.86	216227.78	-7.75	WB
15878	3622783.55	216231.04	-7.75	WB
15879	3622783.30	216234.32	-7.74	WB
15880	3622783.05	216237.65	-7.74	WB
15881	3622782.76	216240.74	-7.73	WB
15882	3622782.72	216241.16	-7.73	WB
15883	3622782.45	216243.94	-7.72	WB
15884	3622782.17	216246.87	-7.71	WB
15885	3622781.93	216249.64	-7.70	WB
15886	3622781.68	216252.49	-7.70	WB
15887	3622781.57	216255.04	-7.69	WB
15888	3622781.48	216257.54	-7.68	WB
15889	3622781.39	216260.03	-7.67	WB
15890	3622781.34	216262.44	-7.66	WB
15891	3622781.27	216264.87	-7.65	WB
15892	3622781.32	216266.36	-7.64	WB
15893	3622781.35	216267.25	-7.64	WB
15894	3622781.45	216269.68	-7.63	WB
15895	3622781.54	216272.18	-7.62	WB
15896	3622781.62	216274.75	-7.62	WB
15897	3622781.71	216277.27	-7.61	WB
15898	3622781.92	216279.89	-7.61	WB
15899	3622782.15	216282.53	-7.60	WB
15900	3622782.41	216285.13	-7.60	WB
15901	3622782.70	216287.71	-7.60	WB
15902	3622783.00	216290.37	-7.60	WB
15903	3622783.22	216292.04	-7.60	WB
15904	3622783.35	216293.04	-7.60	WB
15905	3622783.70	216295.70	-7.60	WB
15906	3622784.02	216298.43	-7.60	WB
15907	3622784.32	216301.24	-7.60	WB
15908	3622784.65	216304.02	-7.60	WB
15909	3622785.02	216306.81	-7.61	WB
15910	3622785.41	216309.57	-7.61	WB
15911	3622785.77	216312.31	-7.61	WB
15912	3622786.14	216315.10	-7.61	WB
15913	3622786.32	216316.45	-7.61	WB
15914	3622786.50	216317.79	-7.61	WB
15915	3622786.87	216320.50	-7.61	WB
15916	3622787.26	216323.23	-7.61	WB
15917	3622787.54	216325.82	-7.61	WB
15918	3622787.82	216328.44	-7.61	WB
15919	3622788.06	216331.13	-7.60	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
15920	3622788.22	216333.68	-7.60	WB
15921	3622788.37	216336.34	-7.60	WB
15922	3622788.39	216338.86	-7.59	WB
15923	3622788.40	216340.46	-7.59	WB
15924	3622788.39	216341.38	-7.58	WB
15925	3622788.31	216343.98	-7.58	WB
15926	3622788.14	216346.55	-7.57	WB
15927	3622787.96	216349.14	-7.56	WB
15928	3622787.69	216351.78	-7.56	WB
15929	3622787.42	216354.40	-7.55	WB
15930	3622787.10	216357.00	-7.55	WB
15931	3622786.73	216359.65	-7.54	WB
15932	3622786.37	216362.28	-7.53	WB
15933	3622786.09	216364.82	-7.53	WB
15934	3622785.97	216365.82	-7.52	WB
15935	3622785.77	216367.50	-7.52	WB
15936	3622785.50	216370.03	-7.51	WB
15937	3622785.23	216372.54	-7.51	WB
15938	3622784.99	216375.15	-7.50	WB
15939	3622784.86	216377.66	-7.50	WB
15940	3622784.73	216380.17	-7.49	WB
15941	3622784.66	216382.84	-7.49	WB
15942	3622784.61	216385.47	-7.49	WB
15943	3622784.57	216388.16	-7.49	WB
15944	3622784.57	216391.00	-7.48	WB
15945	3622784.57	216391.34	-7.48	WB
15946	3622784.57	216393.84	-7.48	WB
15947	3622784.64	216396.75	-7.48	WB
15948	3622784.74	216399.66	-7.47	WB
15949	3622784.84	216402.63	-7.47	WB
15950	3622784.94	216405.63	-7.47	WB
15951	3622785.04	216408.69	-7.47	WB
15952	3622785.20	216411.61	-7.46	WB
15953	3622785.38	216414.60	-7.46	WB
15954	3622785.48	216416.54	-7.46	WB
15955	3622785.52	216417.65	-7.45	WB
15956	3622785.64	216420.57	-7.45	WB
15957	3622785.75	216423.54	-7.44	WB
15958	3622785.93	216426.41	-7.44	WB
15959	3622786.11	216429.18	-7.43	WB
15960	3622786.25	216431.95	-7.43	WB
15961	3622786.35	216434.63	-7.42	WB
15962	3622786.43	216437.25	-7.42	WB
15963	3622786.44	216439.91	-7.41	WB
15964	3622786.45	216440.90	-7.40	WB
15965	3622786.45	216442.56	-7.40	WB
15966	3622786.38	216445.19	-7.39	WB
15967	3622786.28	216447.80	-7.39	WB
15968	3622786.18	216450.38	-7.38	WB
15969	3622786.04	216452.97	-7.38	WB
15970	3622785.92	216455.54	-7.37	WB
15971	3622785.80	216458.09	-7.37	WB
15972	3622785.69	216460.64	-7.37	WB
15973	3622785.54	216463.26	-7.36	WB
15974	3622785.34	216465.82	-7.36	WB
15975	3622785.13	216468.43	-7.36	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
15976	3622784.88	216471.10	-7.35	WB
15977	3622784.61	216473.75	-7.35	WB
15978	3622784.35	216476.48	-7.35	WB
15979	3622784.07	216479.34	-7.35	WB
15980	3622783.81	216482.11	-7.34	WB
15981	3622783.56	216485.19	-7.34	WB
15982	3622783.32	216488.20	-7.34	WB
15983	3622783.11	216491.22	-7.34	WB
15984	3622782.91	216494.40	-7.33	WB
15985	3622782.72	216497.54	-7.33	WB
15986	3622782.61	216500.62	-7.33	WB
15987	3622782.49	216503.74	-7.32	WB
15988	3622782.44	216506.89	-7.32	WB
15989	3622782.42	216509.95	-7.31	WB
15990	3622782.41	216513.00	-7.31	WB
15991	3622782.36	216516.16	-7.30	WB
15992	3622782.35	216516.53	-7.30	WB
15993	3622782.31	216519.21	-7.29	WB
15994	3622782.33	216522.22	-7.28	WB
15995	3622782.40	216525.22	-7.28	WB
15996	3622782.48	216528.10	-7.27	WB
15997	3622782.58	216530.98	-7.26	WB
15998	3622782.70	216533.80	-7.25	WB
15999	3622782.84	216536.41	-7.24	WB
16000	3622782.99	216539.05	-7.23	WB
16001	3622783.10	216540.96	-7.23	WB
16002	3622783.16	216541.62	-7.22	WB
16003	3622783.35	216544.06	-7.21	WB
16004	3622783.55	216546.58	-7.20	WB
16005	3622783.69	216549.05	-7.20	WB
16006	3622783.83	216551.49	-7.19	WB
16007	3622783.94	216553.95	-7.18	WB
16008	3622784.01	216556.44	-7.18	WB
16009	3622784.08	216558.91	-7.17	WB
16010	3622784.12	216561.48	-7.17	WB
16011	3622784.15	216564.07	-7.17	WB
16012	3622784.18	216566.28	-7.17	WB
16013	3622784.19	216566.59	-7.16	WB
16014	3622784.24	216569.27	-7.16	WB
16015	3622784.30	216571.90	-7.16	WB
16016	3622784.33	216574.65	-7.16	WB
16017	3622784.36	216577.46	-7.16	WB
16018	3622784.40	216580.35	-7.16	WB
16019	3622784.47	216583.33	-7.16	WB
16020	3622784.54	216586.33	-7.16	WB
16021	3622784.58	216589.48	-7.16	WB
16022	3622784.62	216591.44	-7.16	WB
16023	3622784.64	216592.61	-7.16	WB
16024	3622784.71	216595.74	-7.16	WB
16025	3622784.80	216598.88	-7.16	WB
16026	3622784.88	216601.95	-7.15	WB
16027	3622784.92	216605.00	-7.15	WB
16028	3622784.96	216608.08	-7.15	WB
16029	3622784.94	216610.99	-7.15	WB
16030	3622784.90	216613.94	-7.14	WB
16031	3622784.88	216616.03	-7.14	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
16032	3622784.86	216616.71	-7.13	WB
16033	3622784.80	216619.33	-7.13	WB
16034	3622784.73	216622.07	-7.12	WB
16035	3622784.56	216624.62	-7.11	WB
16036	3622784.35	216627.21	-7.11	WB
16037	3622784.09	216629.79	-7.10	WB
16038	3622783.78	216632.29	-7.09	WB
16039	3622783.46	216634.83	-7.09	WB
16040	3622783.15	216637.38	-7.08	WB
16041	3622782.86	216639.87	-7.07	WB
16042	3622782.78	216640.54	-7.06	WB
16043	3622782.54	216642.40	-7.06	WB
16044	3622782.19	216644.94	-7.05	WB
16045	3622781.84	216647.42	-7.04	WB
16046	3622781.55	216649.96	-7.04	WB
16047	3622781.26	216652.56	-7.03	WB
16048	3622780.95	216655.13	-7.02	WB
16049	3622780.63	216657.78	-7.02	WB
16050	3622780.29	216660.52	-7.01	WB
16051	3622779.97	216663.26	-7.01	WB
16052	3622779.65	216666.10	-7.00	WB
16053	3622779.38	216668.97	-7.00	WB
16054	3622779.14	216671.86	-6.99	WB
16055	3622778.90	216674.85	-6.99	WB
16056	3622778.64	216677.92	-6.98	WB
16057	3622778.39	216681.01	-6.98	WB
16058	3622778.23	216684.13	-6.97	WB
16059	3622778.12	216687.35	-6.97	WB
16060	3622778.05	216690.45	-6.96	WB
16061	3622778.07	216692.06	-6.95	WB
16062	3622778.08	216693.61	-6.95	WB
16063	3622778.12	216696.81	-6.94	WB
16064	3622778.30	216699.83	-6.93	WB
16065	3622778.54	216702.96	-6.93	WB
16066	3622778.83	216705.87	-6.92	WB
16067	3622779.21	216708.68	-6.91	WB
16068	3622779.61	216711.58	-6.90	WB
16069	3622780.13	216714.18	-6.89	WB
16070	3622780.67	216716.75	-6.88	WB
16071	3622780.74	216717.10	-6.87	WB
16072	3622781.26	216719.38	-6.86	WB
16073	3622781.86	216721.85	-6.85	WB
16074	3622782.46	216724.37	-6.84	WB
16075	3622783.04	216726.78	-6.83	WB
16076	3622783.62	216729.21	-6.82	WB
16077	3622784.21	216731.57	-6.81	WB
16078	3622784.81	216733.88	-6.80	WB
16079	3622785.41	216736.23	-6.79	WB
16080	3622785.92	216738.54	-6.78	WB
16081	3622786.44	216740.88	-6.77	WB
16082	3622786.56	216741.42	-6.76	WB
16083	3622786.97	216743.11	-6.76	WB
16084	3622787.54	216745.37	-6.75	WB
16085	3622788.11	216747.66	-6.74	WB
16086	3622788.60	216749.89	-6.74	WB
16087	3622789.10	216752.16	-6.73	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
16088	3622789.55	216754.55	-6.73	WB
16089	3622789.96	216756.91	-6.72	WB
16090	3622790.32	216759.44	-6.72	WB
16091	3622790.48	216762.19	-6.71	WB
16092	3622790.62	216764.92	-6.71	WB
16093	3622790.64	216766.44	-6.70	WB
16094	3622790.61	216768.04	-6.70	WB
16095	3622790.55	216771.19	-6.69	WB
16096	3622790.45	216774.38	-6.69	WB
16097	3622790.23	216777.69	-6.68	WB
16098	3622790.02	216780.99	-6.68	WB
16099	3622789.72	216784.22	-6.67	WB
16100	3622789.42	216787.41	-6.66	WB
16101	3622789.08	216790.48	-6.66	WB
16102	3622788.68	216793.43	-6.65	WB
16103	3622788.26	216796.42	-6.64	WB
16104	3622787.79	216799.02	-6.63	WB
16105	3622787.30	216801.61	-6.62	WB
16106	3622786.80	216804.21	-6.61	WB
16107	3622786.32	216806.56	-6.60	WB
16108	3622785.82	216808.94	-6.59	WB
16109	3622785.22	216811.27	-6.58	WB
16110	3622784.63	216813.54	-6.57	WB
16111	3622784.16	216815.34	-6.56	WB
16112	3622784.02	216815.92	-6.54	WB
16113	3622783.39	216818.37	-6.53	WB
16114	3622782.78	216820.79	-6.52	WB
16115	3622782.13	216823.46	-6.51	WB
16116	3622781.48	216826.14	-6.50	WB
16117	3622780.89	216829.01	-6.48	WB
16118	3622780.33	216831.94	-6.47	WB
16119	3622779.75	216835.06	-6.46	WB
16120	3622779.20	216838.18	-6.45	WB
16121	3622778.70	216840.99	-6.44	WB
16122	3622778.63	216841.37	-6.43	WB
16123	3622778.19	216844.57	-6.42	WB
16124	3622777.80	216847.66	-6.41	WB
16125	3622777.51	216850.66	-6.40	WB
16126	3622777.38	216853.59	-6.39	WB
16127	3622777.25	216856.44	-6.38	WB
16128	3622777.24	216859.22	-6.37	WB
16129	3622777.25	216861.92	-6.37	WB
16130	3622777.34	216864.53	-6.36	WB
16131	3622777.56	216867.06	-6.35	WB
16132	3622777.78	216869.54	-6.35	WB
16133	3622778.10	216872.03	-6.34	WB
16134	3622778.44	216874.51	-6.33	WB
16135	3622778.83	216877.06	-6.32	WB
16136	3622779.27	216879.67	-6.32	WB
16137	3622779.72	216882.28	-6.31	WB
16138	3622780.23	216885.08	-6.30	WB
16139	3622780.73	216887.86	-6.30	WB
16140	3622781.31	216890.73	-6.29	WB
16141	3622781.70	216892.52	-6.28	WB
16142	3622781.92	216893.52	-6.27	WB
16143	3622782.56	216896.30	-6.26	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
16144	3622783.35	216899.18	-6.25	WB
16145	3622784.11	216901.95	-6.24	WB
16146	3622784.95	216904.71	-6.23	WB
16147	3622785.81	216907.49	-6.22	WB
16148	3622786.67	216910.20	-6.21	WB
16149	3622787.57	216912.90	-6.20	WB
16150	3622788.46	216915.56	-6.18	WB
16151	3622788.87	216916.86	-6.17	WB
16152	3622789.25	216918.13	-6.16	WB
16153	3622790.02	216920.74	-6.15	WB
16154	3622790.74	216923.26	-6.13	WB
16155	3622791.40	216925.76	-6.12	WB
16156	3622792.06	216928.26	-6.11	WB
16157	3622792.63	216930.67	-6.09	WB
16158	3622793.18	216933.07	-6.08	WB
16159	3622793.71	216935.46	-6.07	WB
16160	3622794.19	216937.77	-6.06	WB
16161	3622794.67	216940.09	-6.05	WB
16162	3622794.88	216941.22	-6.04	WB
16163	3622795.09	216942.41	-6.03	WB
16164	3622795.50	216944.67	-6.02	WB
16165	3622795.80	216946.98	-6.01	WB
16166	3622796.01	216949.39	-6.00	WB
16167	3622796.21	216951.78	-5.99	WB
16168	3622796.38	216954.28	-5.99	WB
16169	3622796.55	216956.84	-5.98	WB
16170	3622796.64	216959.43	-5.98	WB
16171	3622796.67	216962.09	-5.97	WB
16172	3622796.69	216964.71	-5.97	WB
16173	3622796.66	216966.07	-5.96	WB
16174	3622796.63	216967.47	-5.96	WB
16175	3622796.58	216970.17	-5.96	WB
16176	3622796.47	216972.98	-5.95	WB
16177	3622796.31	216975.89	-5.95	WB
16178	3622796.13	216978.76	-5.94	WB
16179	3622795.85	216981.82	-5.94	WB
16180	3622795.55	216984.93	-5.93	WB
16181	3622795.22	216988.12	-5.93	WB
16182	3622794.96	216990.60	-5.92	WB
16183	3622794.87	216991.42	-5.91	WB
16184	3622794.51	216994.66	-5.90	WB
16185	3622794.13	216997.92	-5.90	WB
16186	3622793.73	217001.30	-5.89	WB
16187	3622793.35	217004.64	-5.88	WB
16188	3622792.97	217007.95	-5.87	WB
16189	3622792.64	217011.21	-5.85	WB
16190	3622792.38	217014.40	-5.84	WB
16191	3622792.26	217016.00	-5.83	WB
16192	3622792.13	217017.57	-5.82	WB
16193	3622791.91	217020.64	-5.80	WB
16194	3622791.70	217023.64	-5.79	WB
16195	3622791.53	217026.62	-5.77	WB
16196	3622791.39	217029.44	-5.76	WB
16197	3622791.28	217032.20	-5.74	WB
16198	3622791.24	217034.85	-5.73	WB
16199	3622791.21	217037.45	-5.71	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
16200	3622791.14	217040.00	-5.70	WB
16201	3622791.11	217040.94	-5.68	WB
16202	3622791.05	217042.56	-5.67	WB
16203	3622790.96	217045.02	-5.66	WB
16204	3622790.84	217047.43	-5.64	WB
16205	3622790.73	217049.90	-5.63	WB
16206	3622790.58	217052.44	-5.62	WB
16207	3622790.41	217054.96	-5.61	WB
16208	3622790.20	217057.62	-5.59	WB
16209	3622789.89	217060.48	-5.58	WB
16210	3622789.55	217063.37	-5.57	WB
16211	3622789.30	217065.66	-5.56	WB
16212	3622789.21	217066.46	-5.55	WB
16213	3622788.86	217069.63	-5.53	WB
16214	3622788.52	217072.84	-5.51	WB
16215	3622788.19	217076.21	-5.49	WB
16216	3622787.88	217079.49	-5.46	WB
16217	3622787.60	217082.83	-5.44	WB
16218	3622787.33	217086.23	-5.41	WB
16219	3622787.10	217089.46	-5.38	WB
16220	3622786.99	217091.10	-5.34	WB
16221	3622786.89	217092.68	-5.31	WB
16222	3622786.69	217095.95	-5.27	WB
16223	3622786.56	217098.90	-5.23	WB
16224	3622786.45	217101.89	-5.20	WB
16225	3622786.37	217104.78	-5.16	WB
16226	3622786.34	217107.41	-5.12	WB
16227	3622786.32	217110.13	-5.08	WB
16228	3622786.32	217112.64	-5.04	WB
16229	3622786.32	217115.13	-5.01	WB
16230	3622786.32	217115.81	-4.97	WB
16231	3622786.30	217117.65	-4.94	WB
16232	3622786.26	217120.09	-4.92	WB
16233	3622786.22	217122.52	-4.89	WB
16234	3622786.16	217124.98	-4.87	WB
16235	3622786.10	217127.38	-4.86	WB
16236	3622786.00	217129.98	-4.84	WB
16237	3622785.87	217132.62	-4.83	WB
16238	3622785.74	217135.37	-4.83	WB
16239	3622785.59	217138.42	-4.82	WB
16240	3622785.46	217141.07	-4.82	WB
16241	3622785.44	217141.48	-4.82	WB
16242	3622785.25	217144.88	-4.82	WB
16243	3622785.04	217148.38	-4.82	WB
16244	3622784.85	217151.96	-4.82	WB
16245	3622784.68	217155.74	-4.83	WB
16246	3622784.52	217159.57	-4.82	WB
16247	3622784.36	217163.38	-4.82	WB
16248	3622784.25	217166.27	-4.82	WB
16249	3622784.21	217167.20	-4.81	WB
16250	3622784.05	217171.11	-4.79	WB
16251	3622783.90	217174.92	-4.78	WB
16252	3622783.75	217178.68	-4.76	WB
16253	3622783.58	217182.35	-4.74	WB
16254	3622783.42	217185.94	-4.72	WB
16255	3622783.25	217189.40	-4.70	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
16256	3622783.19	217190.68	-4.67	WB
16257	3622783.09	217192.74	-4.65	WB
16258	3622782.92	217196.01	-4.63	WB
16259	3622782.79	217199.00	-4.61	WB
16260	3622782.66	217201.95	-4.60	WB
16261	3622782.52	217204.69	-4.58	WB
16262	3622782.38	217207.30	-4.57	WB
16263	3622782.25	217209.84	-4.56	WB
16264	3622782.22	217212.14	-4.55	WB
16265	3622782.19	217214.45	-4.55	WB
16266	3622782.15	217215.64	-4.55	WB
16267	3622782.06	217216.74	-4.55	WB
16268	3622781.88	217218.98	-4.56	WB
16269	3622781.73	217221.25	-4.56	WB
16270	3622781.69	217223.44	-4.58	WB
16271	3622781.65	217225.66	-4.60	WB
16272	3622781.52	217227.98	-4.62	WB
16273	3622781.35	217230.27	-4.64	WB
16274	3622781.20	217232.62	-4.67	WB
16275	3622781.09	217235.08	-4.71	WB
16276	3622780.99	217237.48	-4.75	WB
16277	3622780.86	217240.09	-4.79	WB
16278	3622780.81	217241.01	-4.84	WB
16279	3622780.72	217242.63	-4.89	WB
16280	3622780.60	217245.23	-4.94	WB
16281	3622780.53	217247.95	-4.99	WB
16282	3622780.47	217250.61	-5.04	WB
16283	3622780.51	217253.47	-5.09	WB
16284	3622780.57	217256.32	-5.14	WB
16285	3622780.62	217259.30	-5.19	WB
16286	3622780.66	217262.47	-5.23	WB
16287	3622780.70	217265.68	-5.28	WB
16288	3622780.72	217266.52	-5.32	WB
16289	3622780.79	217269.19	-5.36	WB
16290	3622780.89	217272.68	-5.40	WB
16291	3622781.01	217276.30	-5.45	WB
16292	3622781.16	217279.85	-5.50	WB
16293	3622781.32	217283.44	-5.55	WB
16294	3622781.48	217287.00	-5.58	WB
16295	3622781.66	217290.42	-5.60	WB
16296	3622781.71	217291.30	-5.61	WB
16297	3622781.81	217293.70	-5.63	WB
16298	3622781.95	217296.94	-5.65	WB
16299	3622782.08	217300.00	-5.68	WB
16300	3622782.11	217302.86	-5.68	WB
16301	3622782.13	217305.68	-5.69	WB
16302	3622782.08	217308.16	-5.70	WB
16303	3622781.98	217310.68	-5.68	WB
16304	3622781.87	217313.10	-5.64	WB
16305	3622781.73	217315.36	-5.61	WB
16306	3622781.57	217317.67	-5.57	WB
16307	3622781.25	217320.05	-5.53	WB
16308	3622780.89	217322.48	-5.49	WB
16309	3622780.49	217325.04	-5.46	WB
16310	3622780.08	217327.69	-5.43	WB
16311	3622779.67	217330.35	-5.41	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
16312	3622779.29	217333.20	-5.40	WB
16313	3622778.95	217335.95	-5.40	WB
16314	3622778.69	217338.74	-5.37	WB
16315	3622778.54	217341.31	-5.36	WB
16316	3622778.52	217341.65	-5.33	WB
16317	3622778.37	217344.49	-5.31	WB
16318	3622778.36	217347.24	-5.30	WB
16319	3622778.35	217350.06	-5.28	WB
16320	3622778.40	217352.82	-5.26	WB
16321	3622778.49	217355.49	-5.23	WB
16322	3622778.60	217358.15	-5.21	WB
16323	3622778.77	217360.76	-5.20	WB
16324	3622778.93	217363.36	-5.18	WB
16325	3622779.10	217366.03	-5.17	WB
16326	3622779.12	217366.35	-5.16	WB
16327	3622779.27	217368.75	-5.14	WB
16328	3622779.44	217371.53	-5.13	WB
16329	3622779.64	217374.59	-5.12	WB
16330	3622779.83	217377.56	-5.13	WB
16331	3622780.00	217380.84	-5.13	WB
16332	3622780.17	217384.30	-5.14	WB
16333	3622780.36	217387.68	-5.16	WB
16334	3622780.62	217391.30	-5.17	WB
16335	3622780.69	217392.22	-5.17	WB
16336	3622780.90	217394.95	-5.18	WB
16337	3622781.22	217398.53	-5.19	WB
16338	3622781.58	217402.14	-5.19	WB
16339	3622781.95	217405.62	-5.17	WB
16340	3622782.33	217408.94	-5.16	WB
16341	3622782.73	217412.34	-5.14	WB
16342	3622783.03	217415.36	-5.12	WB
16343	3622783.10	217416.08	-5.09	WB
16344	3622783.33	217418.36	-5.04	WB
16345	3622783.22	217422.29	-4.99	WB
16346	3622783.11	217426.23	-4.92	WB
16347	3622782.99	217430.16	-4.84	WB
16348	3622782.88	217434.09	-4.78	WB
16349	3622782.77	217438.02	-4.69	WB
16350	3622782.66	217441.96	-4.60	WB
16351	3622782.54	217445.89	-4.52	WB
16352	3622782.43	217449.82	-4.44	WB
16353	3622782.32	217453.75	-4.38	WB
16354	3622782.21	217457.69	-4.32	WB
16355	3622782.09	217461.62	-4.28	WB
16356	3622781.98	217465.55	-4.24	WB
16357	3622781.87	217469.48	-4.21	WB
16358	3622781.76	217473.42	-4.19	WB
16359	3622781.64	217477.35	-4.16	WB
16360	3622781.53	217481.28	-4.14	WB
16361	3622781.42	217485.22	-4.12	WB
16362	3622781.31	217489.15	-4.09	WB
16363	3622781.19	217493.08	-4.07	WB
16364	3622781.08	217497.01	-4.04	WB
16365	3622780.97	217500.95	-4.02	WB
16366	3622780.86	217504.88	-4.00	WB
16367	3622780.74	217508.81	-3.98	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
16368	3622780.63	217512.74	-3.95	WB
16369	3622780.52	217516.68	-3.93	WB
16370	3622780.41	217520.61	-3.90	WB
16371	3622780.29	217524.54	-3.88	WB
16372	3622780.18	217528.47	-3.85	WB
16373	3622780.07	217532.41	-3.82	WB
16374	3622779.96	217536.34	-3.79	WB
16375	3622779.84	217540.27	-3.75	WB
16376	3622779.73	217544.21	-3.72	WB
16377	3622779.62	217548.14	-3.68	WB
16378	3622779.51	217552.07	-3.64	WB
16379	3622779.39	217556.00	-3.61	WB
16380	3622779.28	217559.94	-3.57	WB
16381	3622779.17	217563.87	-3.53	WB
16382	3622779.06	217567.80	-3.49	WB
16383	3622778.94	217571.73	-3.45	WB
16384	3622779.04	217573.92	-3.40	WB
16385	3622779.14	217576.11	-3.36	WB
16386	3622779.23	217578.30	-3.32	WB
16387	3622779.33	217580.48	-3.28	WB
16388	3622779.42	217582.67	-3.25	WB
16389	3622779.52	217584.86	-3.21	WB
16390	3622779.62	217587.05	-3.18	WB
16391	3622779.71	217589.23	-3.15	WB
16392	3622779.81	217591.42	-3.11	WB
16393	3622779.90	217593.61	-3.08	WB
16394	3622780.00	217595.80	-3.05	WB
16395	3622780.10	217597.99	-3.02	WB
16396	3622780.19	217600.17	-3.00	WB
16397	3622780.29	217602.36	-2.98	WB
16398	3622780.38	217604.55	-2.95	WB
16399	3622780.48	217606.74	-2.93	WB
16400	3622780.48	217608.08	-2.91	WB
16401	3622780.49	217609.41	-2.89	WB
16402	3622780.49	217610.75	-2.87	WB
16403	3622780.49	217612.04	-2.86	WB
16404	3622780.49	217613.38	-2.84	WB
16405	3622780.39	217614.71	-2.82	WB
16406	3622780.29	217616.06	-2.81	WB
16407	3622780.13	217617.47	-2.79	WB
16408	3622779.95	217618.82	-2.77	WB
16409	3622779.75	217620.20	-2.76	WB
16410	3622779.53	217621.60	-2.75	WB
16411	3622779.35	217622.64	-2.74	WB
16412	3622779.30	217622.97	-2.73	WB
16413	3622778.98	217624.35	-2.72	WB
16414	3622778.63	217625.65	-2.72	WB
16415	3622778.27	217626.93	-2.72	WB
16416	3622777.86	217628.10	-2.72	WB
16417	3622777.48	217629.23	-2.72	WB
16418	3622777.09	217630.27	-2.73	WB
16419	3622776.69	217631.29	-2.74	WB
16420	3622776.29	217632.32	-2.75	WB
16421	3622775.83	217633.46	-2.76	WB
16422	3622775.39	217634.56	-2.77	WB
16423	3622774.90	217635.96	-2.79	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
16424	3622774.39	217637.42	-2.81	WB
16425	3622773.79	217638.98	-2.82	WB
16426	3622773.07	217640.71	-2.84	WB
16427	3622772.33	217642.47	-2.86	WB
16428	3622771.62	217644.39	-2.88	WB
16429	3622770.91	217646.32	-2.90	WB
16430	3622770.38	217647.74	-2.93	WB
16431	3622770.19	217648.22	-2.95	WB
16432	3622769.52	217650.01	-2.97	WB
16433	3622768.83	217651.82	-2.99	WB
16434	3622768.32	217653.38	-3.00	WB
16435	3622767.83	217654.90	-3.01	WB
16436	3622767.39	217656.27	-3.02	WB
16437	3622766.99	217657.50	-3.04	WB
16438	3622766.59	217658.72	-3.06	WB
16439	3622766.21	217659.78	-3.07	WB
16440	3622765.84	217660.81	-3.09	WB
16441	3622765.55	217661.67	-3.11	WB
16442	3622765.29	217662.48	-3.13	WB
16443	3622765.05	217663.20	-3.15	WB
16444	3622764.85	217663.81	-3.15	WB
16445	3622764.65	217664.37	-3.18	WB
16446	3622764.63	217664.45	-3.18	WB
16447	3622297.22	215767.22	-8.59	WB
16448	3622296.19	215770.36	-8.55	WB
16449	3622295.80	215771.53	-8.51	WB
16450	3622295.14	215773.50	-8.48	WB
16451	3622294.15	215776.51	-8.46	WB
16452	3622293.16	215779.55	-8.43	WB
16453	3622292.19	215782.53	-8.41	WB
16454	3622291.39	215785.41	-8.39	WB
16455	3622290.57	215788.35	-8.37	WB
16456	3622289.89	215791.14	-8.36	WB
16457	3622289.25	215793.98	-8.34	WB
16458	3622288.68	215796.76	-8.32	WB
16459	3622288.59	215797.39	-8.31	WB
16460	3622288.32	215799.38	-8.29	WB
16461	3622287.95	215802.09	-8.28	WB
16462	3622287.68	215804.82	-8.27	WB
16463	3622287.45	215807.52	-8.26	WB
16464	3622287.28	215810.26	-8.25	WB
16465	3622287.27	215813.07	-8.25	WB
16466	3622287.26	215815.85	-8.24	WB
16467	3622287.35	215818.67	-8.24	WB
16468	3622287.46	215821.55	-8.23	WB
16469	3622287.53	215823.32	-8.23	WB
16470	3622287.64	215824.37	-8.23	WB
16471	3622287.96	215827.27	-8.23	WB
16472	3622288.28	215830.23	-8.23	WB
16473	3622288.65	215833.33	-8.23	WB
16474	3622289.03	215836.54	-8.23	WB
16475	3622289.41	215839.76	-8.23	WB
16476	3622289.79	215843.06	-8.23	WB
16477	3622290.18	215846.44	-8.23	WB
16478	3622290.37	215848.16	-8.23	WB
16479	3622290.55	215849.87	-8.23	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
16480	3622290.92	215853.26	-8.22	WB
16481	3622291.25	215856.62	-8.22	WB
16482	3622291.56	215859.95	-8.22	WB
16483	3622291.86	215863.24	-8.22	WB
16484	3622292.07	215866.33	-8.22	WB
16485	3622292.29	215869.43	-8.21	WB
16486	3622292.43	215872.06	-8.21	WB
16487	3622292.44	215872.40	-8.20	WB
16488	3622292.56	215875.28	-8.20	WB
16489	3622292.64	215878.13	-8.19	WB
16490	3622292.62	215880.82	-8.19	WB
16491	3622292.59	215883.57	-8.18	WB
16492	3622292.58	215886.19	-8.17	WB
16493	3622292.57	215888.85	-8.17	WB
16494	3622292.52	215891.57	-8.16	WB
16495	3622292.38	215894.25	-8.15	WB
16496	3622292.25	215897.02	-8.15	WB
16497	3622292.11	215899.78	-8.14	WB
16498	3622291.98	215902.48	-8.13	WB
16499	3622291.83	215905.30	-8.13	WB
16500	3622291.65	215908.13	-8.12	WB
16501	3622291.47	215910.92	-8.12	WB
16502	3622291.25	215913.85	-8.11	WB
16503	3622291.03	215916.85	-8.11	WB
16504	3622290.83	215919.81	-8.11	WB
16505	3622290.66	215922.48	-8.10	WB
16506	3622290.63	215922.84	-8.10	WB
16507	3622290.45	215925.82	-8.10	WB
16508	3622290.18	215928.86	-8.10	WB
16509	3622289.91	215931.99	-8.10	WB
16510	3622289.70	215935.06	-8.10	WB
16511	3622289.54	215938.11	-8.10	WB
16512	3622289.38	215941.28	-8.10	WB
16513	3622289.18	215944.32	-8.10	WB
16514	3622289.02	215947.00	-8.10	WB
16515	3622288.99	215947.37	-8.10	WB
16516	3622288.72	215950.53	-8.10	WB
16517	3622288.41	215953.54	-8.10	WB
16518	3622288.06	215956.70	-8.10	WB
16519	3622287.63	215959.80	-8.10	WB
16520	3622287.21	215962.87	-8.10	WB
16521	3622286.72	215966.05	-8.10	WB
16522	3622286.20	215969.21	-8.10	WB
16523	3622285.74	215972.01	-8.10	WB
16524	3622285.68	215972.39	-8.10	WB
16525	3622285.13	215975.63	-8.09	WB
16526	3622284.56	215978.90	-8.09	WB
16527	3622284.02	215982.24	-8.09	WB
16528	3622283.49	215985.60	-8.08	WB
16529	3622282.97	215988.97	-8.07	WB
16530	3622282.50	215992.43	-8.07	WB
16531	3622282.03	215995.89	-8.06	WB
16532	3622281.86	215997.63	-8.05	WB
16533	3622281.71	215999.33	-8.04	WB
16534	3622281.43	216002.74	-8.03	WB
16535	3622281.21	216006.16	-8.02	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
16536	3622281.08	216009.39	-8.01	WB
16537	3622280.95	216012.68	-8.00	WB
16538	3622280.96	216015.85	-7.99	WB
16539	3622280.98	216018.93	-7.98	WB
16540	3622281.01	216021.95	-7.97	WB
16541	3622281.02	216022.64	-7.96	WB
16542	3622281.04	216024.86	-7.95	WB
16543	3622281.08	216027.69	-7.94	WB
16544	3622281.13	216030.41	-7.93	WB
16545	3622281.18	216033.09	-7.92	WB
16546	3622281.25	216035.69	-7.91	WB
16547	3622281.34	216038.24	-7.90	WB
16548	3622281.45	216040.80	-7.90	WB
16549	3622281.64	216043.38	-7.89	WB
16550	3622281.83	216045.98	-7.88	WB
16551	3622281.93	216047.67	-7.88	WB
16552	3622281.98	216048.65	-7.87	WB
16553	3622282.12	216051.41	-7.87	WB
16554	3622282.26	216054.27	-7.87	WB
16555	3622282.40	216057.33	-7.87	WB
16556	3622282.54	216060.39	-7.86	WB
16557	3622282.69	216063.66	-7.86	WB
16558	3622282.85	216066.87	-7.86	WB
16559	3622283.01	216070.23	-7.86	WB
16560	3622283.13	216072.83	-7.86	WB
16561	3622283.17	216073.71	-7.86	WB
16562	3622283.33	216077.10	-7.86	WB
16563	3622283.39	216080.84	-7.86	WB
16564	3622283.44	216084.50	-7.86	WB
16565	3622283.48	216088.08	-7.86	WB
16566	3622283.53	216091.75	-7.86	WB
16567	3622283.60	216095.32	-7.86	WB
16568	3622283.70	216097.85	-7.85	WB
16569	3622283.73	216098.63	-7.85	WB
16570	3622283.87	216101.93	-7.85	WB
16571	3622283.98	216105.11	-7.85	WB
16572	3622284.07	216108.18	-7.84	WB
16573	3622284.16	216111.22	-7.84	WB
16574	3622284.29	216114.07	-7.83	WB
16575	3622284.43	216116.90	-7.83	WB
16576	3622284.53	216119.68	-7.82	WB
16577	3622284.59	216122.42	-7.82	WB
16578	3622284.65	216125.17	-7.81	WB
16579	3622284.73	216127.94	-7.81	WB
16580	3622284.80	216130.62	-7.80	WB
16581	3622284.80	216133.34	-7.79	WB
16582	3622284.77	216136.11	-7.79	WB
16583	3622284.73	216138.86	-7.78	WB
16584	3622284.64	216141.85	-7.77	WB
16585	3622284.55	216144.81	-7.77	WB
16586	3622284.47	216147.46	-7.76	WB
16587	3622284.45	216147.83	-7.76	WB
16588	3622284.36	216150.95	-7.75	WB
16589	3622284.30	216154.06	-7.75	WB
16590	3622284.28	216157.20	-7.74	WB
16591	3622284.25	216160.34	-7.74	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
16592	3622284.23	216163.47	-7.73	WB
16593	3622284.21	216166.63	-7.73	WB
16594	3622284.23	216169.78	-7.73	WB
16595	3622284.30	216172.51	-7.73	WB
16596	3622284.31	216172.88	-7.72	WB
16597	3622284.40	216175.96	-7.72	WB
16598	3622284.41	216179.02	-7.72	WB
16599	3622284.42	216182.09	-7.72	WB
16600	3622284.40	216185.18	-7.72	WB
16601	3622284.38	216188.33	-7.72	WB
16602	3622284.36	216191.37	-7.72	WB
16603	3622284.37	216194.48	-7.72	WB
16604	3622284.39	216197.62	-7.72	WB
16605	3622284.36	216200.66	-7.72	WB
16606	3622284.30	216203.86	-7.72	WB
16607	3622284.27	216207.00	-7.72	WB
16608	3622284.31	216210.13	-7.72	WB
16609	3622284.36	216213.34	-7.71	WB
16610	3622284.36	216216.53	-7.71	WB
16611	3622284.33	216219.72	-7.71	WB
16612	3622284.30	216222.16	-7.71	WB
16613	3622284.28	216222.94	-7.71	WB
16614	3622284.18	216226.22	-7.71	WB
16615	3622284.07	216229.53	-7.70	WB
16616	3622283.83	216232.83	-7.70	WB
16617	3622283.54	216236.14	-7.70	WB
16618	3622283.25	216239.37	-7.69	WB
16619	3622282.93	216242.58	-7.69	WB
16620	3622282.61	216245.85	-7.69	WB
16621	3622282.43	216247.34	-7.68	WB
16622	3622282.24	216248.86	-7.68	WB
16623	3622281.84	216252.01	-7.67	WB
16624	3622281.49	216255.04	-7.67	WB
16625	3622281.19	216257.97	-7.67	WB
16626	3622280.90	216260.97	-7.66	WB
16627	3622280.70	216263.91	-7.66	WB
16628	3622280.52	216266.85	-7.66	WB
16629	3622280.41	216269.78	-7.65	WB
16630	3622280.36	216272.78	-7.65	WB
16631	3622280.32	216275.77	-7.65	WB
16632	3622280.41	216278.80	-7.65	WB
16633	3622280.50	216281.83	-7.64	WB
16634	3622280.62	216284.90	-7.64	WB
16635	3622280.74	216288.06	-7.64	WB
16636	3622280.89	216291.12	-7.64	WB
16637	3622281.09	216294.21	-7.64	WB
16638	3622281.31	216297.46	-7.64	WB
16639	3622281.33	216297.84	-7.64	WB
16640	3622281.47	216300.63	-7.64	WB
16641	3622281.61	216303.80	-7.64	WB
16642	3622281.74	216307.12	-7.64	WB
16643	3622281.84	216310.32	-7.64	WB
16644	3622281.95	216313.56	-7.65	WB
16645	3622282.01	216316.87	-7.65	WB
16646	3622282.07	216320.05	-7.65	WB
16647	3622282.12	216322.48	-7.65	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
16648	3622282.12	216323.27	-7.65	WB
16649	3622282.13	216326.40	-7.65	WB
16650	3622282.14	216329.56	-7.65	WB
16651	3622282.11	216332.64	-7.65	WB
16652	3622282.09	216335.71	-7.65	WB
16653	3622282.07	216338.74	-7.65	WB
16654	3622282.04	216341.79	-7.65	WB
16655	3622282.02	216344.84	-7.65	WB
16656	3622281.97	216347.53	-7.65	WB
16657	3622281.97	216347.90	-7.65	WB
16658	3622281.91	216350.98	-7.65	WB
16659	3622281.85	216354.11	-7.64	WB
16660	3622281.79	216357.28	-7.64	WB
16661	3622281.74	216360.51	-7.64	WB
16662	3622281.65	216363.72	-7.63	WB
16663	3622281.56	216367.00	-7.63	WB
16664	3622281.53	216370.38	-7.62	WB
16665	3622281.53	216372.86	-7.62	WB
16666	3622281.53	216373.65	-7.61	WB
16667	3622281.55	216377.07	-7.60	WB
16668	3622281.66	216380.43	-7.60	WB
16669	3622281.76	216383.73	-7.59	WB
16670	3622281.89	216387.15	-7.58	WB
16671	3622282.02	216390.55	-7.58	WB
16672	3622282.18	216393.91	-7.57	WB
16673	3622282.42	216397.19	-7.56	WB
16674	3622282.48	216397.98	-7.55	WB
16675	3622282.67	216400.47	-7.54	WB
16676	3622282.93	216403.59	-7.54	WB
16677	3622283.19	216406.66	-7.53	WB
16678	3622283.47	216409.68	-7.52	WB
16679	3622283.79	216412.53	-7.51	WB
16680	3622284.11	216415.38	-7.51	WB
16681	3622284.47	216418.04	-7.50	WB
16682	3622284.84	216420.71	-7.49	WB
16683	3622285.11	216422.69	-7.49	WB
16684	3622285.19	216423.38	-7.48	WB
16685	3622285.51	216425.93	-7.48	WB
16686	3622285.83	216428.52	-7.48	WB
16687	3622286.00	216431.22	-7.47	WB
16688	3622286.17	216433.83	-7.47	WB
16689	3622286.29	216436.59	-7.47	WB
16690	3622286.39	216439.35	-7.47	WB
16691	3622286.50	216442.04	-7.47	WB
16692	3622286.54	216444.90	-7.47	WB
16693	3622286.57	216447.33	-7.47	WB
16694	3622286.58	216447.71	-7.47	WB
16695	3622286.59	216450.62	-7.47	WB
16696	3622286.59	216453.64	-7.47	WB
16697	3622286.57	216456.71	-7.46	WB
16698	3622286.48	216459.98	-7.46	WB
16699	3622286.38	216463.24	-7.46	WB
16700	3622286.21	216466.75	-7.46	WB
16701	3622286.00	216470.22	-7.46	WB
16702	3622285.87	216472.44	-7.46	WB
16703	3622285.77	216473.81	-7.45	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
16704	3622285.47	216477.58	-7.45	WB
16705	3622285.16	216481.26	-7.44	WB
16706	3622284.73	216485.22	-7.44	WB
16707	3622284.30	216489.10	-7.43	WB
16708	3622283.88	216492.90	-7.42	WB
16709	3622283.49	216496.68	-7.41	WB
16710	3622283.40	216497.57	-7.40	WB
16711	3622283.12	216500.38	-7.39	WB
16712	3622282.87	216503.73	-7.38	WB
16713	3622282.64	216507.06	-7.37	WB
16714	3622282.48	216510.21	-7.36	WB
16715	3622282.41	216513.17	-7.34	WB
16716	3622282.34	216516.13	-7.33	WB
16717	3622282.31	216518.91	-7.32	WB
16718	3622282.29	216521.71	-7.30	WB
16719	3622282.28	216522.42	-7.29	WB
16720	3622282.30	216524.49	-7.28	WB
16721	3622282.35	216527.24	-7.27	WB
16722	3622282.39	216530.03	-7.25	WB
16723	3622282.39	216532.84	-7.24	WB
16724	3622282.38	216535.58	-7.23	WB
16725	3622282.36	216538.34	-7.22	WB
16726	3622282.34	216541.18	-7.21	WB
16727	3622282.33	216543.98	-7.20	WB
16728	3622282.38	216546.81	-7.19	WB
16729	3622282.40	216547.85	-7.18	WB
16730	3622282.44	216549.59	-7.17	WB
16731	3622282.59	216552.39	-7.16	WB
16732	3622282.78	216555.31	-7.16	WB
16733	3622282.98	216558.17	-7.15	WB
16734	3622283.18	216561.20	-7.15	WB
16735	3622283.38	216564.22	-7.14	WB
16736	3622283.65	216567.35	-7.14	WB
16737	3622283.93	216570.50	-7.14	WB
16738	3622284.20	216573.30	-7.13	WB
16739	3622284.25	216573.69	-7.13	WB
16740	3622284.61	216576.95	-7.13	WB
16741	3622284.97	216580.20	-7.12	WB
16742	3622285.36	216583.57	-7.12	WB
16743	3622285.74	216586.93	-7.12	WB
16744	3622286.14	216590.31	-7.12	WB
16745	3622286.55	216593.76	-7.12	WB
16746	3622286.96	216597.10	-7.11	WB
16747	3622287.11	216598.41	-7.11	WB
16748	3622287.35	216600.50	-7.11	WB
16749	3622287.75	216603.96	-7.10	WB
16750	3622288.11	216607.26	-7.10	WB
16751	3622288.47	216610.60	-7.09	WB
16752	3622288.82	216613.87	-7.09	WB
16753	3622289.18	216616.92	-7.08	WB
16754	3622289.54	216620.06	-7.07	WB
16755	3622289.81	216622.64	-7.07	WB
16756	3622289.85	216623.04	-7.06	WB
16757	3622290.11	216625.96	-7.05	WB
16758	3622290.38	216628.89	-7.05	WB
16759	3622290.64	216631.63	-7.04	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
16760	3622290.89	216634.39	-7.03	WB
16761	3622291.09	216637.14	-7.02	WB
16762	3622291.26	216639.87	-7.02	WB
16763	3622291.41	216642.65	-7.01	WB
16764	3622291.55	216645.50	-7.00	WB
16765	3622291.65	216647.67	-6.99	WB
16766	3622291.68	216648.35	-6.99	WB
16767	3622291.80	216651.30	-6.98	WB
16768	3622291.92	216654.32	-6.97	WB
16769	3622292.05	216657.22	-6.97	WB
16770	3622292.22	216660.16	-6.96	WB
16771	3622292.40	216663.18	-6.96	WB
16772	3622292.64	216666.10	-6.95	WB
16773	3622292.89	216669.00	-6.95	WB
16774	3622293.18	216671.91	-6.95	WB
16775	3622293.30	216673.01	-6.95	WB
16776	3622293.51	216674.86	-6.94	WB
16777	3622293.85	216677.81	-6.94	WB
16778	3622294.09	216680.83	-6.94	WB
16779	3622294.33	216683.79	-6.94	WB
16780	3622294.57	216686.91	-6.94	WB
16781	3622294.80	216690.00	-6.94	WB
16782	3622295.03	216693.04	-6.94	WB
16783	3622295.12	216696.24	-6.94	WB
16784	3622295.17	216697.87	-6.95	WB
16785	3622295.22	216699.48	-6.95	WB
16786	3622295.26	216702.71	-6.95	WB
16787	3622295.27	216705.99	-6.95	WB
16788	3622295.28	216709.28	-6.95	WB
16789	3622295.17	216712.48	-6.95	WB
16790	3622295.06	216715.83	-6.95	WB
16791	3622294.89	216718.94	-6.95	WB
16792	3622294.69	216722.01	-6.95	WB
16793	3622294.46	216725.15	-6.95	WB
16794	3622294.17	216728.10	-6.95	WB
16795	3622293.85	216731.11	-6.94	WB
16796	3622293.42	216734.08	-6.94	WB
16797	3622292.96	216736.91	-6.94	WB
16798	3622292.48	216739.75	-6.94	WB
16799	3622291.97	216742.61	-6.93	WB
16800	3622291.46	216745.39	-6.93	WB
16801	3622291.22	216746.50	-6.93	WB
16802	3622290.83	216748.17	-6.92	WB
16803	3622290.18	216750.91	-6.92	WB
16804	3622289.52	216753.64	-6.91	WB
16805	3622288.85	216756.38	-6.91	WB
16806	3622288.17	216759.17	-6.90	WB
16807	3622287.39	216761.87	-6.90	WB
16808	3622286.57	216764.69	-6.89	WB
16809	3622285.72	216767.55	-6.89	WB
16810	3622284.84	216770.43	-6.88	WB
16811	3622284.41	216771.85	-6.88	WB
16812	3622283.95	216773.37	-6.87	WB
16813	3622283.06	216776.33	-6.86	WB
16814	3622282.17	216779.34	-6.86	WB
16815	3622281.30	216782.50	-6.85	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
16816	3622280.48	216785.64	-6.84	WB
16817	3622279.65	216788.87	-6.84	WB
16818	3622278.90	216792.26	-6.83	WB
16819	3622278.16	216795.64	-6.82	WB
16820	3622277.84	216797.33	-6.82	WB
16821	3622277.58	216799.09	-6.81	WB
16822	3622277.07	216802.56	-6.80	WB
16823	3622276.61	216806.00	-6.79	WB
16824	3622276.30	216809.35	-6.78	WB
16825	3622276.00	216812.74	-6.78	WB
16826	3622275.86	216816.09	-6.77	WB
16827	3622275.76	216819.32	-6.76	WB
16828	3622275.70	216822.62	-6.75	WB
16829	3622275.68	216825.84	-6.74	WB
16830	3622275.67	216829.02	-6.73	WB
16831	3622275.68	216832.16	-6.72	WB
16832	3622275.71	216835.28	-6.71	WB
16833	3622275.76	216838.36	-6.70	WB
16834	3622275.86	216841.35	-6.69	WB
16835	3622275.96	216844.34	-6.68	WB
16836	3622276.15	216847.27	-6.67	WB
16837	3622276.17	216847.62	-6.66	WB
16838	3622276.33	216850.20	-6.65	WB
16839	3622276.53	216853.12	-6.64	WB
16840	3622276.75	216856.03	-6.63	WB
16841	3622276.98	216858.96	-6.62	WB
16842	3622277.23	216861.85	-6.62	WB
16843	3622277.49	216864.72	-6.61	WB
16844	3622277.74	216867.61	-6.60	WB
16845	3622277.98	216870.40	-6.59	WB
16846	3622278.20	216872.89	-6.59	WB
16847	3622278.24	216873.23	-6.58	WB
16848	3622278.55	216876.15	-6.57	WB
16849	3622278.86	216878.97	-6.56	WB
16850	3622279.15	216881.93	-6.56	WB
16851	3622279.43	216884.88	-6.55	WB
16852	3622279.72	216887.80	-6.54	WB
16853	3622280.03	216890.82	-6.54	WB
16854	3622280.34	216893.78	-6.53	WB
16855	3622280.62	216896.82	-6.52	WB
16856	3622280.70	216897.59	-6.51	WB
16857	3622280.90	216899.86	-6.51	WB
16858	3622281.14	216902.89	-6.50	WB
16859	3622281.31	216906.03	-6.49	WB
16860	3622281.46	216909.19	-6.48	WB
16861	3622281.51	216912.52	-6.47	WB
16862	3622281.53	216915.85	-6.46	WB
16863	3622281.48	216919.26	-6.44	WB
16864	3622281.37	216922.31	-6.43	WB
16865	3622281.35	216922.73	-6.42	WB
16866	3622281.22	216926.22	-6.40	WB
16867	3622281.08	216929.77	-6.39	WB
16868	3622280.94	216933.22	-6.37	WB
16869	3622280.79	216936.65	-6.36	WB
16870	3622280.65	216940.04	-6.34	WB
16871	3622280.51	216943.37	-6.33	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
16872	3622280.43	216946.48	-6.31	WB
16873	3622280.41	216947.21	-6.29	WB
16874	3622280.35	216949.49	-6.28	WB
16875	3622280.29	216952.34	-6.26	WB
16876	3622280.23	216955.16	-6.24	WB
16877	3622280.19	216957.86	-6.23	WB
16878	3622280.26	216960.49	-6.21	WB
16879	3622280.32	216963.08	-6.19	WB
16880	3622280.37	216965.67	-6.18	WB
16881	3622280.40	216968.35	-6.16	WB
16882	3622280.45	216971.03	-6.15	WB
16883	3622280.50	216972.79	-6.13	WB
16884	3622280.53	216973.79	-6.12	WB
16885	3622280.61	216976.65	-6.11	WB
16886	3622280.71	216979.56	-6.09	WB
16887	3622280.83	216982.45	-6.08	WB
16888	3622281.01	216985.48	-6.07	WB
16889	3622281.29	216988.63	-6.06	WB
16890	3622281.61	216992.10	-6.05	WB
16891	3622281.95	216995.35	-6.04	WB
16892	3622282.26	216998.30	-6.03	WB
16893	3622282.30	216998.70	-6.02	WB
16894	3622282.72	217002.09	-6.01	WB
16895	3622283.22	217005.55	-6.00	WB
16896	3622283.73	217009.01	-5.99	WB
16897	3622284.30	217012.62	-5.98	WB
16898	3622284.87	217016.23	-5.98	WB
16899	3622285.47	217019.88	-5.97	WB
16900	3622286.02	217023.11	-5.96	WB
16901	3622286.10	217023.55	-5.95	WB
16902	3622286.71	217027.17	-5.93	WB
16903	3622287.25	217030.73	-5.92	WB
16904	3622287.78	217034.16	-5.91	WB
16905	3622288.28	217037.41	-5.90	WB
16906	3622288.77	217040.64	-5.89	WB
16907	3622289.22	217043.70	-5.87	WB
16908	3622289.56	217046.69	-5.86	WB
16909	3622289.60	217047.03	-5.84	WB
16910	3622289.88	217049.56	-5.83	WB
16911	3622290.09	217052.32	-5.81	WB
16912	3622290.25	217055.09	-5.80	WB
16913	3622290.34	217057.75	-5.78	WB
16914	3622290.35	217060.43	-5.76	WB
16915	3622290.34	217063.17	-5.74	WB
16916	3622290.19	217065.81	-5.73	WB
16917	3622290.02	217068.54	-5.71	WB
16918	3622289.84	217071.26	-5.69	WB
16919	3622289.80	217071.91	-5.67	WB
16920	3622289.65	217073.95	-5.66	WB
16921	3622289.45	217076.73	-5.64	WB
16922	3622289.15	217079.48	-5.62	WB
16923	3622288.84	217082.23	-5.60	WB
16924	3622288.57	217084.99	-5.59	WB
16925	3622288.35	217087.74	-5.57	WB
16926	3622288.13	217090.42	-5.56	WB
16927	3622287.87	217093.23	-5.54	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
16928	3622287.60	217096.07	-5.53	WB
16929	3622287.50	217097.12	-5.51	WB
16930	3622287.36	217098.90	-5.50	WB
16931	3622287.13	217101.80	-5.48	WB
16932	3622286.91	217104.79	-5.47	WB
16933	3622286.73	217107.79	-5.46	WB
16934	3622286.53	217110.88	-5.44	WB
16935	3622286.35	217113.99	-5.43	WB
16936	3622286.17	217117.09	-5.42	WB
16937	3622286.01	217120.35	-5.41	WB
16938	3622285.96	217122.32	-5.39	WB
16939	3622285.92	217123.57	-5.38	WB
16940	3622285.84	217126.73	-5.37	WB
16941	3622285.80	217130.03	-5.36	WB
16942	3622285.77	217133.41	-5.34	WB
16943	3622285.74	217136.77	-5.33	WB
16944	3622285.75	217140.28	-5.32	WB
16945	3622285.75	217143.86	-5.30	WB
16946	3622285.84	217147.44	-5.29	WB
16947	3622285.86	217147.93	-5.27	WB
16948	3622285.95	217151.05	-5.26	WB
16949	3622286.11	217154.77	-5.24	WB
16950	3622286.34	217158.46	-5.22	WB
16951	3622286.58	217162.13	-5.21	WB
16952	3622286.96	217165.63	-5.19	WB
16953	3622287.36	217169.11	-5.17	WB
16954	3622287.79	217172.40	-5.15	WB
16955	3622287.90	217173.21	-5.13	WB
16956	3622288.26	217175.59	-5.11	WB
16957	3622288.74	217178.74	-5.09	WB
16958	3622289.22	217181.56	-5.07	WB
16959	3622289.72	217184.41	-5.05	WB
16960	3622290.16	217187.05	-5.03	WB
16961	3622290.56	217189.65	-5.01	WB
16962	3622290.95	217192.30	-4.98	WB
16963	3622291.21	217194.77	-4.96	WB
16964	3622291.44	217196.99	-4.94	WB
16965	3622291.47	217197.28	-4.92	WB
16966	3622291.70	217199.79	-4.90	WB
16967	3622291.89	217202.21	-4.88	WB
16968	3622292.07	217204.67	-4.86	WB
16969	3622292.12	217207.09	-4.83	WB
16970	3622292.17	217209.50	-4.81	WB
16971	3622292.19	217211.98	-4.79	WB
16972	3622292.19	217214.43	-4.77	WB
16973	3622292.14	217216.95	-4.76	WB
16974	3622291.96	217219.52	-4.74	WB
16975	3622291.80	217221.75	-4.72	WB
16976	3622291.78	217222.10	-4.70	WB
16977	3622291.59	217224.83	-4.68	WB
16978	3622291.39	217227.59	-4.66	WB
16979	3622291.11	217230.46	-4.65	WB
16980	3622290.70	217233.51	-4.63	WB
16981	3622290.29	217236.54	-4.62	WB
16982	3622289.89	217239.73	-4.61	WB
16983	3622289.50	217242.98	-4.60	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
16984	3622289.06	217246.28	-4.60	WB
16985	3622288.93	217247.14	-4.59	WB
16986	3622288.57	217249.68	-4.60	WB
16987	3622288.07	217253.15	-4.61	WB
16988	3622287.69	217256.60	-4.60	WB
16989	3622287.32	217260.08	-4.58	WB
16990	3622287.01	217263.61	-4.58	WB
16991	3622286.75	217267.01	-4.57	WB
16992	3622286.50	217270.58	-4.57	WB
16993	3622286.39	217272.63	-4.56	WB
16994	3622286.33	217273.87	-4.56	WB
16995	3622286.17	217277.20	-4.56	WB
16996	3622286.04	217280.44	-4.57	WB
16997	3622285.94	217283.53	-4.60	WB
16998	3622285.84	217286.61	-4.61	WB
16999	3622285.75	217289.57	-4.62	WB
17000	3622285.67	217292.44	-4.66	WB
17001	3622285.57	217295.33	-4.68	WB
17002	3622285.51	217297.02	-4.70	WB
17003	3622285.47	217298.05	-4.74	WB
17004	3622285.35	217300.78	-4.79	WB
17005	3622285.22	217303.51	-4.84	WB
17006	3622285.07	217306.18	-4.89	WB
17007	3622284.84	217309.02	-4.96	WB
17008	3622284.60	217311.84	-5.02	WB
17009	3622284.32	217314.69	-5.09	WB
17010	3622283.99	217317.74	-5.18	WB
17011	3622283.66	217320.77	-5.29	WB
17012	3622283.55	217321.90	-5.38	WB
17013	3622283.35	217323.96	-5.47	WB
17014	3622283.03	217327.17	-5.56	WB
17015	3622282.67	217330.46	-5.64	WB
17016	3622282.29	217333.77	-5.74	WB
17017	3622281.90	217337.12	-5.83	WB
17018	3622281.58	217340.52	-5.90	WB
17019	3622281.27	217343.93	-5.93	WB
17020	3622280.95	217347.32	-5.94	WB
17021	3622280.64	217350.65	-5.96	WB
17022	3622280.34	217354.01	-5.98	WB
17023	3622280.16	217357.36	-5.98	WB
17024	3622280.00	217360.60	-5.98	WB
17025	3622279.94	217363.78	-5.96	WB
17026	3622279.94	217367.00	-5.92	WB
17027	3622279.95	217370.16	-5.89	WB
17028	3622280.04	217372.89	-5.87	WB
17029	3622280.06	217373.26	-5.84	WB
17030	3622280.16	217376.35	-5.82	WB
17031	3622280.39	217379.34	-5.79	WB
17032	3622280.65	217382.28	-5.76	WB
17033	3622280.96	217385.16	-5.70	WB
17034	3622281.36	217387.98	-5.66	WB
17035	3622281.77	217390.78	-5.61	WB
17036	3622282.26	217393.53	-5.59	WB
17037	3622282.77	217396.20	-5.56	WB
17038	3622283.18	217398.27	-5.52	WB
17039	3622283.32	217398.91	-5.50	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
17040	3622283.92	217401.64	-5.49	WB
17041	3622284.51	217404.28	-5.47	WB
17042	3622285.10	217407.08	-5.47	WB
17043	3622285.69	217409.93	-5.48	WB
17044	3622286.24	217412.91	-5.50	WB
17045	3622286.77	217416.12	-5.52	WB
17046	3622287.28	217419.28	-5.54	WB
17047	3622287.72	217422.72	-5.57	WB
17048	3622287.78	217423.19	-5.57	WB
17049	3622288.18	217426.25	-5.56	WB
17050	3622288.60	217429.80	-5.56	WB
17051	3622289.02	217433.32	-5.54	WB
17052	3622289.46	217436.89	-5.52	WB
17053	3622289.91	217440.30	-5.50	WB
17054	3622290.37	217443.64	-5.47	WB
17055	3622290.76	217446.92	-5.44	WB
17056	3622290.80	217447.29	-5.41	WB
17057	3622291.12	217450.10	-5.38	WB
17058	3622291.41	217453.19	-5.34	WB
17059	3622291.52	217456.21	-5.30	WB
17060	3622291.62	217459.29	-5.26	WB
17061	3622291.58	217462.11	-5.21	WB
17062	3622291.49	217465.01	-5.16	WB
17063	3622291.39	217467.82	-5.09	WB
17064	3622291.29	217470.49	-5.01	WB
17065	3622291.25	217471.58	-4.93	WB
17066	3622291.19	217473.24	-4.85	WB
17067	3622291.05	217475.80	-4.78	WB
17068	3622290.90	217478.34	-4.71	WB
17069	3622290.76	217480.83	-4.65	WB
17070	3622290.64	217483.26	-4.59	WB
17071	3622290.52	217485.67	-4.55	WB
17072	3622290.38	217488.07	-4.51	WB
17073	3622290.24	217490.46	-4.48	WB
17074	3622290.07	217492.89	-4.44	WB
17075	3622289.88	217495.43	-4.40	WB
17076	3622289.75	217497.01	-4.36	WB
17077	3622289.68	217497.95	-4.33	WB
17078	3622289.45	217500.64	-4.30	WB
17079	3622289.22	217503.37	-4.27	WB
17080	3622289.01	217506.12	-4.25	WB
17081	3622288.77	217509.06	-4.23	WB
17082	3622288.56	217511.90	-4.21	WB
17083	3622288.30	217514.92	-4.19	WB
17084	3622288.04	217517.99	-4.17	WB
17085	3622287.77	217521.10	-4.16	WB
17086	3622287.70	217521.91	-4.14	WB
17087	3622287.49	217524.30	-4.12	WB
17088	3622287.18	217527.57	-4.11	WB
17089	3622286.81	217530.89	-4.09	WB
17090	3622286.43	217534.31	-4.08	WB
17091	3622286.03	217537.76	-4.06	WB
17092	3622285.61	217541.18	-4.05	WB
17093	3622285.18	217544.73	-4.03	WB
17094	3622284.91	217546.80	-4.01	WB
17095	3622284.75	217548.06	-3.99	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
17096	3622284.30	217551.53	-3.97	WB
17097	3622283.84	217554.99	-3.95	WB
17098	3622283.38	217558.36	-3.92	WB
17099	3622282.95	217561.73	-3.90	WB
17100	3622282.53	217565.11	-3.87	WB
17101	3622282.10	217568.50	-3.84	WB
17102	3622281.76	217571.87	-3.81	WB
17103	3622281.72	217572.27	-3.78	WB
17104	3622281.42	217575.24	-3.74	WB
17105	3622281.15	217578.43	-3.71	WB
17106	3622280.90	217581.70	-3.67	WB
17107	3622280.67	217584.91	-3.64	WB
17108	3622280.50	217587.99	-3.60	WB
17109	3622280.33	217591.10	-3.56	WB
17110	3622280.20	217594.00	-3.52	WB
17111	3622280.09	217596.86	-3.47	WB
17112	3622280.08	217597.20	-3.43	WB
17113	3622280.00	217599.70	-3.38	WB
17114	3622279.96	217602.30	-3.34	WB
17115	3622279.91	217604.94	-3.30	WB
17116	3622279.89	217607.43	-3.26	WB
17117	3622279.87	217609.78	-3.22	WB
17118	3622279.83	217612.16	-3.19	WB
17119	3622279.80	217614.34	-3.16	WB
17120	3622279.75	217616.50	-3.13	WB
17121	3622279.72	217618.58	-3.09	WB
17122	3622279.70	217620.51	-3.06	WB
17123	3622279.69	217622.19	-3.03	WB
17124	3622279.70	217622.40	-3.01	WB
17125	3622279.74	217624.17	-2.98	WB
17126	3622279.78	217625.89	-2.96	WB
17127	3622279.84	217627.53	-2.93	WB
17128	3622279.89	217629.10	-2.91	WB
17129	3622280.00	217630.63	-2.90	WB
17130	3622280.16	217632.11	-2.89	WB
17131	3622280.32	217633.62	-2.88	WB
17132	3622280.48	217635.07	-2.87	WB
17133	3622280.64	217636.52	-2.86	WB
17134	3622280.83	217637.97	-2.85	WB
17135	3622281.03	217639.42	-2.85	WB
17136	3622281.24	217640.89	-2.85	WB
17137	3622281.46	217642.34	-2.85	WB
17138	3622281.68	217643.77	-2.85	WB
17139	3622281.93	217645.34	-2.85	WB
17140	3622282.19	217646.97	-2.86	WB
17141	3622282.39	217648.19	-2.87	WB
17142	3622282.46	217648.66	-2.89	WB
17143	3622282.73	217650.55	-2.91	WB
17144	3622283.00	217652.46	-2.93	WB
17145	3622283.33	217654.54	-2.95	WB
17146	3622283.67	217656.59	-2.97	WB
17147	3622284.05	217658.67	-2.99	WB
17148	3622284.50	217660.84	-3.01	WB
17149	3622284.94	217662.92	-3.03	WB
17150	3622285.37	217664.98	-3.05	WB
17151	3622285.82	217666.94	-3.07	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
17152	3622286.27	217668.82	-3.09	WB
17153	3622286.74	217670.66	-3.11	WB
17154	3622287.19	217672.50	-3.14	WB
17155	3622287.52	217674.24	-3.16	WB
17156	3622287.82	217675.97	-3.18	WB
17157	3622288.07	217677.63	-3.20	WB
17158	3622288.26	217679.19	-3.21	WB
17159	3622288.45	217680.77	-3.23	WB
17160	3622288.53	217682.11	-3.24	WB
17161	3622288.62	217683.49	-3.25	WB
17162	3622288.66	217684.79	-3.25	WB
17163	3622288.66	217686.02	-3.26	WB
17164	3622288.66	217687.28	-3.27	WB
17165	3622288.63	217688.53	-3.28	WB
17166	3622288.60	217689.79	-3.29	WB
17167	3622288.56	217691.06	-3.30	WB
17168	3622288.52	217692.28	-3.30	WB
17169	3622288.50	217693.52	-3.31	WB
17170	3622288.51	217694.77	-3.31	WB
17171	3622288.52	217695.98	-3.31	WB
17172	3622288.50	217696.76	-3.32	WB
17173	3622288.48	217697.22	-3.34	WB
17174	3622288.43	217698.48	-3.38	WB
17175	3622288.36	217699.73	-3.42	WB
17176	3622288.27	217701.08	-3.47	WB
17177	3622288.17	217702.39	-3.53	WB
17178	3622287.92	217703.83	-3.60	WB
17179	3622287.63	217705.38	-3.68	WB
17180	3622287.31	217706.96	-3.77	WB
17181	3622286.92	217708.73	-3.84	WB
17182	3622286.55	217710.47	-3.93	WB
17183	3622286.16	217712.27	-4.03	WB
17184	3622285.76	217714.12	-4.13	WB
17185	3622285.42	217715.91	-4.21	WB
17186	3622285.10	217717.68	-4.27	WB
17187	3622284.79	217719.44	-4.31	WB
17188	3622284.54	217721.13	-4.32	WB
17189	3622284.45	217721.77	-4.30	WB
17190	3622284.28	217722.84	-4.27	WB
17191	3622284.01	217724.49	-4.20	WB
17192	3622283.74	217726.11	-4.11	WB
17193	3622283.46	217727.72	-3.99	WB
17194	3622283.20	217729.24	-3.88	WB
17195	3622282.95	217730.71	-3.77	WB
17196	3622282.69	217732.11	-3.68	WB
17197	3622282.43	217733.49	-3.62	WB
17198	3622282.19	217734.80	-3.56	WB
17199	3622282.00	217736.04	-3.52	WB
17200	3622281.82	217737.28	-3.48	WB
17201	3622281.68	217738.48	-3.46	WB
17202	3622281.55	217739.71	-3.43	WB
17203	3622281.43	217740.94	-3.40	WB
17204	3622281.32	217742.15	-3.36	WB
17205	3622281.21	217743.39	-3.32	WB
17206	3622281.15	217744.62	-3.28	WB
17207	3622281.08	217745.85	-3.25	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
17208	3622281.02	217747.11	-3.22	WB
17209	3622281.00	217747.43	-3.20	WB
17210	3622280.95	217748.45	-3.17	WB
17211	3622280.88	217749.78	-3.15	WB
17212	3622280.82	217751.44	-3.12	WB
17213	3622280.75	217753.12	-3.08	WB
17214	3622280.71	217754.99	-3.03	WB
17215	3622280.68	217757.08	-2.98	WB
17216	3622280.66	217758.84	-2.96	WB
17217	3621781.97	215777.06	-8.39	WB
17218	3621781.75	215780.28	-8.38	WB
17219	3621781.53	215783.55	-8.38	WB
17220	3621781.37	215786.74	-8.37	WB
17221	3621781.33	215787.83	-8.37	WB
17222	3621781.26	215789.74	-8.36	WB
17223	3621781.16	215792.77	-8.36	WB
17224	3621781.10	215795.54	-8.36	WB
17225	3621781.04	215798.27	-8.35	WB
17226	3621780.95	215800.93	-8.35	WB
17227	3621780.83	215803.49	-8.35	WB
17228	3621780.70	215806.04	-8.34	WB
17229	3621780.55	215808.53	-8.34	WB
17230	3621780.39	215811.02	-8.34	WB
17231	3621780.28	215812.62	-8.33	WB
17232	3621780.22	215813.57	-8.33	WB
17233	3621780.04	215816.13	-8.33	WB
17234	3621779.86	215818.69	-8.33	WB
17235	3621779.69	215821.32	-8.32	WB
17236	3621779.52	215823.96	-8.32	WB
17237	3621779.40	215826.74	-8.32	WB
17238	3621779.31	215829.51	-8.32	WB
17239	3621779.24	215832.37	-8.32	WB
17240	3621779.22	215835.26	-8.31	WB
17241	3621779.20	215838.20	-8.31	WB
17242	3621779.31	215841.37	-8.31	WB
17243	3621779.44	215844.44	-8.31	WB
17244	3621779.60	215847.63	-8.31	WB
17245	3621779.80	215850.77	-8.30	WB
17246	3621780.01	215853.84	-8.30	WB
17247	3621780.34	215857.02	-8.30	WB
17248	3621780.66	215860.11	-8.30	WB
17249	3621781.00	215863.13	-8.30	WB
17250	3621781.34	215866.23	-8.29	WB
17251	3621781.68	215869.29	-8.29	WB
17252	3621782.08	215872.26	-8.29	WB
17253	3621782.48	215875.24	-8.29	WB
17254	3621782.83	215878.17	-8.28	WB
17255	3621783.16	215881.12	-8.28	WB
17256	3621783.48	215884.08	-8.28	WB
17257	3621783.77	215887.09	-8.27	WB
17258	3621783.85	215887.85	-8.27	WB
17259	3621784.07	215890.10	-8.27	WB
17260	3621784.31	215893.21	-8.27	WB
17261	3621784.52	215896.21	-8.26	WB
17262	3621784.75	215899.16	-8.26	WB
17263	3621785.05	215902.10	-8.26	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
17264	3621785.35	215904.92	-8.26	WB
17265	3621785.63	215907.68	-8.25	WB
17266	3621785.89	215910.42	-8.25	WB
17267	3621786.12	215912.75	-8.25	WB
17268	3621786.16	215913.10	-8.25	WB
17269	3621786.47	215915.71	-8.24	WB
17270	3621786.77	215918.32	-8.24	WB
17271	3621787.06	215920.95	-8.24	WB
17272	3621787.34	215923.57	-8.24	WB
17273	3621787.58	215926.22	-8.24	WB
17274	3621787.76	215928.93	-8.23	WB
17275	3621787.95	215931.59	-8.23	WB
17276	3621788.24	215934.50	-8.23	WB
17277	3621788.52	215937.37	-8.23	WB
17278	3621788.59	215938.05	-8.23	WB
17279	3621788.72	215940.26	-8.23	WB
17280	3621788.83	215943.39	-8.22	WB
17281	3621788.95	215946.50	-8.22	WB
17282	3621789.13	215949.78	-8.22	WB
17283	3621789.32	215953.05	-8.22	WB
17284	3621789.41	215956.41	-8.22	WB
17285	3621789.43	215959.86	-8.22	WB
17286	3621789.44	215962.95	-8.22	WB
17287	3621789.44	215963.35	-8.22	WB
17288	3621789.48	215966.77	-8.22	WB
17289	3621789.52	215970.16	-8.21	WB
17290	3621789.54	215973.44	-8.21	WB
17291	3621789.56	215976.55	-8.21	WB
17292	3621789.58	215979.69	-8.21	WB
17293	3621789.61	215982.55	-8.21	WB
17294	3621789.64	215985.38	-8.21	WB
17295	3621789.61	215987.07	-8.21	WB
17296	3621789.59	215988.05	-8.20	WB
17297	3621789.49	215990.71	-8.20	WB
17298	3621789.35	215993.30	-8.20	WB
17299	3621789.10	215995.98	-8.20	WB
17300	3621788.84	215998.56	-8.20	WB
17301	3621788.46	216001.18	-8.20	WB
17302	3621788.05	216003.87	-8.19	WB
17303	3621787.70	216006.50	-8.19	WB
17304	3621787.38	216009.18	-8.19	WB
17305	3621787.08	216011.84	-8.19	WB
17306	3621787.03	216012.18	-8.19	WB
17307	3621786.71	216014.66	-8.19	WB
17308	3621786.35	216017.49	-8.18	WB
17309	3621785.98	216020.43	-8.18	WB
17310	3621785.61	216023.51	-8.18	WB
17311	3621785.23	216026.65	-8.18	WB
17312	3621784.85	216029.94	-8.17	WB
17313	3621784.47	216033.24	-8.17	WB
17314	3621784.08	216036.51	-8.17	WB
17315	3621783.98	216037.37	-8.17	WB
17316	3621783.67	216039.93	-8.16	WB
17317	3621783.28	216043.26	-8.16	WB
17318	3621783.01	216046.53	-8.16	WB
17319	3621782.74	216049.83	-8.15	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
17320	3621782.50	216052.95	-8.15	WB
17321	3621782.27	216056.14	-8.15	WB
17322	3621782.06	216059.24	-8.14	WB
17323	3621781.93	216062.22	-8.14	WB
17324	3621781.91	216062.63	-8.14	WB
17325	3621781.78	216065.30	-8.13	WB
17326	3621781.63	216068.40	-8.13	WB
17327	3621781.48	216071.49	-8.12	WB
17328	3621781.31	216074.66	-8.12	WB
17329	3621781.10	216077.97	-8.12	WB
17330	3621780.90	216081.25	-8.11	WB
17331	3621780.74	216084.57	-8.11	WB
17332	3621780.59	216087.51	-8.10	WB
17333	3621780.57	216087.97	-8.10	WB
17334	3621780.38	216091.37	-8.09	WB
17335	3621780.20	216094.73	-8.09	WB
17336	3621780.02	216098.09	-8.08	WB
17337	3621779.94	216101.27	-8.08	WB
17338	3621779.88	216104.47	-8.07	WB
17339	3621779.88	216107.41	-8.07	WB
17340	3621779.92	216110.25	-8.06	WB
17341	3621779.95	216112.42	-8.06	WB
17342	3621779.96	216113.15	-8.05	WB
17343	3621780.05	216115.78	-8.05	WB
17344	3621780.13	216118.51	-8.05	WB
17345	3621780.19	216121.24	-8.04	WB
17346	3621780.23	216123.96	-8.04	WB
17347	3621780.28	216126.77	-8.03	WB
17348	3621780.31	216129.64	-8.03	WB
17349	3621780.33	216132.52	-8.03	WB
17350	3621780.33	216135.51	-8.02	WB
17351	3621780.34	216138.14	-8.02	WB
17352	3621780.34	216138.55	-8.01	WB
17353	3621780.39	216141.62	-8.01	WB
17354	3621780.54	216144.79	-8.01	WB
17355	3621780.71	216147.93	-8.00	WB
17356	3621780.86	216151.20	-8.00	WB
17357	3621781.02	216154.50	-8.00	WB
17358	3621781.19	216157.79	-7.99	WB
17359	3621781.38	216161.11	-7.99	WB
17360	3621781.49	216162.78	-7.99	WB
17361	3621781.60	216164.45	-7.98	WB
17362	3621781.77	216167.61	-7.98	WB
17363	3621781.94	216170.88	-7.98	WB
17364	3621782.03	216174.18	-7.97	WB
17365	3621782.01	216177.38	-7.97	WB
17366	3621781.99	216180.70	-7.96	WB
17367	3621781.91	216183.86	-7.96	WB
17368	3621781.82	216187.00	-7.95	WB
17369	3621781.80	216187.42	-7.95	WB
17370	3621781.61	216190.23	-7.94	WB
17371	3621781.31	216193.38	-7.94	WB
17372	3621780.99	216196.49	-7.93	WB
17373	3621780.62	216199.52	-7.93	WB
17374	3621780.26	216202.54	-7.92	WB
17375	3621779.88	216205.54	-7.92	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
17376	3621779.48	216208.47	-7.91	WB
17377	3621779.08	216211.38	-7.91	WB
17378	3621778.97	216212.09	-7.90	WB
17379	3621778.65	216214.17	-7.89	WB
17380	3621778.22	216217.01	-7.89	WB
17381	3621777.86	216219.81	-7.88	WB
17382	3621777.54	216222.51	-7.88	WB
17383	3621777.19	216225.36	-7.87	WB
17384	3621776.86	216228.09	-7.86	WB
17385	3621776.52	216230.83	-7.86	WB
17386	3621776.24	216233.70	-7.85	WB
17387	3621775.99	216236.49	-7.85	WB
17388	3621775.89	216237.54	-7.84	WB
17389	3621775.74	216239.36	-7.84	WB
17390	3621775.50	216242.26	-7.83	WB
17391	3621775.25	216245.14	-7.83	WB
17392	3621775.03	216248.21	-7.82	WB
17393	3621774.83	216251.21	-7.82	WB
17394	3621774.62	216254.30	-7.81	WB
17395	3621774.42	216257.62	-7.81	WB
17396	3621774.23	216260.89	-7.80	WB
17397	3621774.20	216263.58	-7.80	WB
17398	3621774.20	216264.42	-7.79	WB
17399	3621774.18	216267.93	-7.79	WB
17400	3621774.26	216271.50	-7.78	WB
17401	3621774.44	216275.06	-7.78	WB
17402	3621774.65	216278.66	-7.77	WB
17403	3621775.05	216282.25	-7.77	WB
17404	3621775.45	216285.71	-7.77	WB
17405	3621775.82	216288.78	-7.76	WB
17406	3621775.87	216289.19	-7.76	WB
17407	3621776.30	216292.54	-7.75	WB
17408	3621776.76	216295.80	-7.75	WB
17409	3621777.40	216298.84	-7.74	WB
17410	3621778.03	216301.81	-7.74	WB
17411	3621778.60	216304.64	-7.73	WB
17412	3621779.12	216307.41	-7.73	WB
17413	3621779.66	216310.14	-7.73	WB
17414	3621780.28	216312.71	-7.72	WB
17415	3621780.90	216315.30	-7.72	WB
17416	3621781.38	216317.87	-7.71	WB
17417	3621781.82	216320.48	-7.71	WB
17418	3621782.20	216323.15	-7.70	WB
17419	3621782.47	216325.78	-7.70	WB
17420	3621782.73	216328.46	-7.70	WB
17421	3621782.93	216331.24	-7.69	WB
17422	3621783.11	216333.96	-7.69	WB
17423	3621783.26	216336.74	-7.69	WB
17424	3621783.29	216337.83	-7.68	WB
17425	3621783.35	216339.58	-7.68	WB
17426	3621783.45	216342.34	-7.68	WB
17427	3621783.57	216345.14	-7.68	WB
17428	3621783.69	216347.90	-7.67	WB
17429	3621783.78	216350.66	-7.67	WB
17430	3621783.85	216353.47	-7.67	WB
17431	3621783.92	216356.35	-7.67	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
17432	3621783.95	216359.28	-7.66	WB
17433	3621783.97	216362.28	-7.66	WB
17434	3621783.97	216363.04	-7.66	WB
17435	3621783.95	216365.45	-7.66	WB
17436	3621783.90	216368.83	-7.65	WB
17437	3621783.83	216372.29	-7.65	WB
17438	3621783.69	216376.16	-7.65	WB
17439	3621783.56	216379.90	-7.65	WB
17440	3621783.49	216383.87	-7.64	WB
17441	3621783.45	216387.94	-7.64	WB
17442	3621783.44	216388.41	-7.64	WB
17443	3621783.43	216391.87	-7.63	WB
17444	3621783.44	216395.92	-7.63	WB
17445	3621783.46	216399.88	-7.62	WB
17446	3621783.56	216403.56	-7.62	WB
17447	3621783.70	216407.29	-7.62	WB
17448	3621783.84	216410.86	-7.61	WB
17449	3621783.92	216412.92	-7.61	WB
17450	3621783.97	216414.15	-7.60	WB
17451	3621784.11	216417.44	-7.60	WB
17452	3621784.26	216420.39	-7.59	WB
17453	3621784.42	216423.26	-7.59	WB
17454	3621784.56	216426.06	-7.58	WB
17455	3621784.68	216428.69	-7.58	WB
17456	3621784.79	216431.33	-7.57	WB
17457	3621784.79	216433.78	-7.57	WB
17458	3621784.78	216436.22	-7.56	WB
17459	3621784.78	216437.43	-7.56	WB
17460	3621784.78	216438.63	-7.56	WB
17461	3621784.77	216441.02	-7.55	WB
17462	3621784.77	216443.34	-7.55	WB
17463	3621784.65	216445.71	-7.55	WB
17464	3621784.53	216448.13	-7.54	WB
17465	3621784.42	216450.55	-7.54	WB
17466	3621784.33	216453.10	-7.54	WB
17467	3621784.22	216455.65	-7.53	WB
17468	3621784.04	216458.33	-7.53	WB
17469	3621783.84	216461.11	-7.53	WB
17470	3621783.73	216462.55	-7.53	WB
17471	3621783.61	216464.08	-7.53	WB
17472	3621783.35	216467.21	-7.52	WB
17473	3621783.07	216470.44	-7.52	WB
17474	3621782.79	216473.92	-7.52	WB
17475	3621782.50	216477.40	-7.52	WB
17476	3621782.15	216481.09	-7.52	WB
17477	3621781.78	216484.91	-7.52	WB
17478	3621781.49	216487.80	-7.52	WB
17479	3621781.40	216488.76	-7.51	WB
17480	3621781.02	216492.81	-7.51	WB
17481	3621780.65	216496.86	-7.51	WB
17482	3621780.30	216500.84	-7.51	WB
17483	3621779.95	216504.97	-7.51	WB
17484	3621779.65	216508.83	-7.50	WB
17485	3621779.38	216512.68	-7.50	WB
17486	3621779.13	216516.42	-7.50	WB
17487	3621778.95	216519.71	-7.50	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
17488	3621778.78	216523.08	-7.49	WB
17489	3621778.66	216526.18	-7.49	WB
17490	3621778.61	216529.08	-7.49	WB
17491	3621778.55	216532.04	-7.49	WB
17492	3621778.55	216534.71	-7.48	WB
17493	3621778.54	216537.40	-7.48	WB
17494	3621778.50	216540.07	-7.47	WB
17495	3621778.42	216542.76	-7.47	WB
17496	3621778.32	216545.47	-7.47	WB
17497	3621778.23	216548.21	-7.46	WB
17498	3621778.13	216550.96	-7.46	WB
17499	3621778.09	216553.76	-7.46	WB
17500	3621778.06	216556.55	-7.45	WB
17501	3621778.06	216559.31	-7.45	WB
17502	3621778.16	216562.15	-7.44	WB
17503	3621778.20	216563.25	-7.44	WB
17504	3621778.26	216565.03	-7.44	WB
17505	3621778.47	216567.95	-7.43	WB
17506	3621778.73	216570.91	-7.43	WB
17507	3621779.01	216573.95	-7.43	WB
17508	3621779.31	216577.03	-7.42	WB
17509	3621779.62	216580.20	-7.42	WB
17510	3621779.96	216583.41	-7.42	WB
17511	3621780.30	216586.55	-7.41	WB
17512	3621780.53	216588.54	-7.41	WB
17513	3621780.71	216589.72	-7.41	WB
17514	3621781.18	216592.76	-7.40	WB
17515	3621781.65	216595.73	-7.40	WB
17516	3621782.14	216598.69	-7.40	WB
17517	3621782.63	216601.61	-7.39	WB
17518	3621783.09	216604.53	-7.39	WB
17519	3621783.56	216607.51	-7.39	WB
17520	3621784.02	216610.56	-7.38	WB
17521	3621784.35	216613.27	-7.38	WB
17522	3621784.39	216613.65	-7.38	WB
17523	3621784.77	216616.79	-7.37	WB
17524	3621785.11	216619.98	-7.37	WB
17525	3621785.41	216623.10	-7.37	WB
17526	3621785.73	216626.28	-7.36	WB
17527	3621785.98	216629.33	-7.36	WB
17528	3621786.24	216632.31	-7.35	WB
17529	3621786.53	216635.25	-7.35	WB
17530	3621786.80	216637.74	-7.35	WB
17531	3621786.84	216638.08	-7.34	WB
17532	3621787.12	216640.89	-7.34	WB
17533	3621787.33	216643.67	-7.33	WB
17534	3621787.53	216646.48	-7.33	WB
17535	3621787.68	216649.31	-7.32	WB
17536	3621787.81	216652.14	-7.32	WB
17537	3621787.93	216655.02	-7.31	WB
17538	3621787.99	216657.82	-7.31	WB
17539	3621788.03	216660.68	-7.30	WB
17540	3621788.03	216662.18	-7.29	WB
17541	3621788.02	216663.66	-7.29	WB
17542	3621787.99	216666.53	-7.28	WB
17543	3621787.95	216669.49	-7.28	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
17544	3621787.91	216672.38	-7.27	WB
17545	3621787.87	216675.23	-7.27	WB
17546	3621787.79	216678.11	-7.26	WB
17547	3621787.70	216680.95	-7.26	WB
17548	3621787.59	216683.79	-7.26	WB
17549	3621787.44	216686.68	-7.25	WB
17550	3621787.41	216687.38	-7.25	WB
17551	3621787.30	216689.59	-7.24	WB
17552	3621787.13	216692.59	-7.24	WB
17553	3621786.96	216695.55	-7.23	WB
17554	3621786.79	216698.54	-7.23	WB
17555	3621786.62	216701.59	-7.23	WB
17556	3621786.45	216704.69	-7.22	WB
17557	3621786.28	216707.86	-7.22	WB
17558	3621786.12	216711.01	-7.22	WB
17559	3621786.02	216712.96	-7.21	WB
17560	3621785.95	216714.25	-7.21	WB
17561	3621785.80	216717.39	-7.21	WB
17562	3621785.66	216720.56	-7.20	WB
17563	3621785.60	216723.81	-7.20	WB
17564	3621785.56	216726.93	-7.19	WB
17565	3621785.50	216730.09	-7.19	WB
17566	3621785.44	216733.17	-7.19	WB
17567	3621785.39	216736.17	-7.18	WB
17568	3621785.38	216737.35	-7.18	WB
17569	3621785.36	216739.21	-7.17	WB
17570	3621785.33	216742.31	-7.17	WB
17571	3621785.18	216745.27	-7.17	WB
17572	3621785.00	216748.31	-7.16	WB
17573	3621784.78	216751.41	-7.16	WB
17574	3621784.51	216754.41	-7.15	WB
17575	3621784.23	216757.51	-7.14	WB
17576	3621783.86	216760.58	-7.14	WB
17577	3621783.67	216762.09	-7.13	WB
17578	3621783.48	216763.60	-7.13	WB
17579	3621783.02	216766.76	-7.12	WB
17580	3621782.53	216769.82	-7.12	WB
17581	3621782.02	216772.89	-7.11	WB
17582	3621781.51	216775.98	-7.10	WB
17583	3621781.01	216778.97	-7.10	WB
17584	3621780.49	216782.02	-7.09	WB
17585	3621779.94	216785.10	-7.08	WB
17586	3621779.61	216786.97	-7.08	WB
17587	3621779.41	216788.10	-7.07	WB
17588	3621778.85	216791.18	-7.06	WB
17589	3621778.29	216794.22	-7.05	WB
17590	3621777.80	216797.21	-7.05	WB
17591	3621777.32	216800.27	-7.04	WB
17592	3621776.85	216803.31	-7.03	WB
17593	3621776.43	216806.33	-7.02	WB
17594	3621776.01	216809.36	-7.02	WB
17595	3621775.67	216812.38	-7.01	WB
17596	3621775.38	216815.36	-7.00	WB
17597	3621775.08	216818.39	-6.99	WB
17598	3621774.80	216821.53	-6.99	WB
17599	3621774.52	216824.57	-6.98	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
17600	3621774.28	216827.74	-6.97	WB
17601	3621774.05	216830.98	-6.96	WB
17602	3621773.84	216834.16	-6.95	WB
17603	3621773.62	216837.63	-6.95	WB
17604	3621773.60	216838.04	-6.94	WB
17605	3621773.41	216841.06	-6.93	WB
17606	3621773.32	216844.64	-6.92	WB
17607	3621773.25	216848.29	-6.91	WB
17608	3621773.20	216851.96	-6.90	WB
17609	3621773.17	216855.66	-6.90	WB
17610	3621773.15	216859.46	-6.89	WB
17611	3621773.27	216863.14	-6.88	WB
17612	3621773.41	216866.80	-6.87	WB
17613	3621773.56	216870.33	-6.86	WB
17614	3621773.72	216873.78	-6.85	WB
17615	3621773.89	216877.19	-6.84	WB
17616	3621774.07	216880.33	-6.83	WB
17617	3621774.27	216883.45	-6.82	WB
17618	3621774.44	216886.38	-6.81	WB
17619	3621774.50	216887.44	-6.80	WB
17620	3621774.60	216889.26	-6.79	WB
17621	3621774.74	216892.02	-6.78	WB
17622	3621774.82	216894.64	-6.78	WB
17623	3621774.88	216897.40	-6.77	WB
17624	3621774.94	216899.97	-6.76	WB
17625	3621774.98	216902.68	-6.75	WB
17626	3621775.00	216905.33	-6.74	WB
17627	3621774.99	216907.94	-6.73	WB
17628	3621774.97	216910.62	-6.72	WB
17629	3621774.98	216912.59	-6.72	WB
17630	3621774.98	216913.32	-6.71	WB
17631	3621775.00	216916.01	-6.70	WB
17632	3621775.00	216918.81	-6.69	WB
17633	3621774.96	216921.75	-6.68	WB
17634	3621774.92	216924.61	-6.68	WB
17635	3621774.85	216927.76	-6.67	WB
17636	3621774.77	216930.89	-6.66	WB
17637	3621774.73	216934.12	-6.66	WB
17638	3621774.72	216937.51	-6.65	WB
17639	3621774.72	216938.31	-6.65	WB
17640	3621774.71	216940.85	-6.64	WB
17641	3621774.83	216944.29	-6.63	WB
17642	3621774.96	216947.79	-6.63	WB
17643	3621775.16	216951.22	-6.62	WB
17644	3621775.42	216954.76	-6.62	WB
17645	3621775.68	216958.34	-6.61	WB
17646	3621775.94	216961.81	-6.61	WB
17647	3621776.08	216963.59	-6.60	WB
17648	3621776.22	216965.36	-6.60	WB
17649	3621776.58	216968.75	-6.59	WB
17650	3621776.99	216972.01	-6.59	WB
17651	3621777.41	216975.32	-6.58	WB
17652	3621777.76	216978.42	-6.58	WB
17653	3621778.11	216981.51	-6.57	WB
17654	3621778.52	216984.44	-6.57	WB
17655	3621778.94	216987.26	-6.56	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
17656	3621779.00	216987.64	-6.56	WB
17657	3621779.32	216990.05	-6.55	WB
17658	3621779.57	216992.83	-6.55	WB
17659	3621779.81	216995.54	-6.54	WB
17660	3621779.99	216998.35	-6.53	WB
17661	3621780.15	217001.10	-6.53	WB
17662	3621780.25	217003.82	-6.52	WB
17663	3621780.26	217006.60	-6.52	WB
17664	3621780.26	217009.44	-6.51	WB
17665	3621780.24	217012.26	-6.51	WB
17666	3621780.23	217012.64	-6.50	WB
17667	3621780.21	217015.12	-6.49	WB
17668	3621780.17	217018.06	-6.49	WB
17669	3621780.12	217020.97	-6.48	WB
17670	3621780.06	217023.97	-6.47	WB
17671	3621780.00	217027.06	-6.47	WB
17672	3621779.93	217030.12	-6.46	WB
17673	3621779.87	217033.31	-6.45	WB
17674	3621779.79	217036.65	-6.45	WB
17675	3621779.76	217037.83	-6.44	WB
17676	3621779.71	217039.90	-6.43	WB
17677	3621779.60	217043.44	-6.42	WB
17678	3621779.49	217046.95	-6.42	WB
17679	3621779.40	217050.49	-6.41	WB
17680	3621779.32	217054.06	-6.40	WB
17681	3621779.25	217057.66	-6.39	WB
17682	3621779.24	217061.07	-6.39	WB
17683	3621779.24	217062.82	-6.38	WB
17684	3621779.25	217064.58	-6.37	WB
17685	3621779.27	217067.94	-6.36	WB
17686	3621779.29	217071.21	-6.35	WB
17687	3621779.32	217074.59	-6.35	WB
17688	3621779.35	217077.66	-6.34	WB
17689	3621779.37	217080.78	-6.33	WB
17690	3621779.43	217083.73	-6.32	WB
17691	3621779.49	217086.60	-6.31	WB
17692	3621779.51	217087.69	-6.30	WB
17693	3621779.55	217089.49	-6.30	WB
17694	3621779.60	217092.23	-6.29	WB
17695	3621779.65	217094.98	-6.28	WB
17696	3621779.69	217097.65	-6.27	WB
17697	3621779.73	217100.35	-6.26	WB
17698	3621779.77	217103.05	-6.25	WB
17699	3621779.78	217105.70	-6.24	WB
17700	3621779.80	217108.36	-6.23	WB
17701	3621779.81	217111.07	-6.23	WB
17702	3621779.82	217112.43	-6.22	WB
17703	3621779.83	217113.76	-6.21	WB
17704	3621779.85	217116.55	-6.20	WB
17705	3621779.89	217119.36	-6.19	WB
17706	3621779.91	217122.24	-6.18	WB
17707	3621779.88	217125.43	-6.17	WB
17708	3621779.85	217128.52	-6.16	WB
17709	3621779.80	217131.91	-6.15	WB
17710	3621779.75	217135.41	-6.14	WB
17711	3621779.71	217138.03	-6.13	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
17712	3621779.69	217138.95	-6.11	WB
17713	3621779.59	217142.85	-6.10	WB
17714	3621779.49	217146.70	-6.09	WB
17715	3621779.43	217150.69	-6.08	WB
17716	3621779.39	217154.69	-6.07	WB
17717	3621779.39	217158.63	-6.05	WB
17718	3621779.46	217162.51	-6.04	WB
17719	3621779.47	217162.97	-6.02	WB
17720	3621779.54	217166.36	-6.01	WB
17721	3621779.58	217170.02	-5.99	WB
17722	3621779.60	217173.63	-5.98	WB
17723	3621779.63	217177.12	-5.96	WB
17724	3621779.66	217180.42	-5.95	WB
17725	3621779.70	217183.71	-5.93	WB
17726	3621779.64	217186.83	-5.91	WB
17727	3621779.63	217187.56	-5.90	WB
17728	3621779.58	217189.84	-5.88	WB
17729	3621779.50	217192.81	-5.86	WB
17730	3621779.41	217195.71	-5.84	WB
17731	3621779.33	217198.53	-5.82	WB
17732	3621779.16	217201.29	-5.81	WB
17733	3621778.98	217204.05	-5.79	WB
17734	3621778.79	217206.74	-5.77	WB
17735	3621778.59	217209.47	-5.75	WB
17736	3621778.38	217212.16	-5.73	WB
17737	3621778.36	217212.47	-5.71	WB
17738	3621778.16	217214.75	-5.70	WB
17739	3621777.95	217217.33	-5.68	WB
17740	3621777.79	217219.79	-5.66	WB
17741	3621777.66	217222.19	-5.64	WB
17742	3621777.54	217224.67	-5.62	WB
17743	3621777.44	217227.18	-5.61	WB
17744	3621777.34	217229.64	-5.59	WB
17745	3621777.26	217232.22	-5.57	WB
17746	3621777.20	217234.91	-5.56	WB
17747	3621777.15	217237.54	-5.54	WB
17748	3621777.13	217240.37	-5.52	WB
17749	3621777.11	217243.15	-5.51	WB
17750	3621777.11	217246.07	-5.49	WB
17751	3621777.12	217249.12	-5.47	WB
17752	3621777.13	217252.24	-5.46	WB
17753	3621777.14	217255.61	-5.44	WB
17754	3621777.14	217258.97	-5.43	WB
17755	3621777.15	217262.79	-5.41	WB
17756	3621777.15	217263.24	-5.39	WB
17757	3621777.15	217266.62	-5.38	WB
17758	3621777.19	217270.58	-5.36	WB
17759	3621777.27	217274.81	-5.35	WB
17760	3621777.36	217279.04	-5.33	WB
17761	3621777.55	217283.30	-5.31	WB
17762	3621777.75	217287.55	-5.29	WB
17763	3621777.81	217288.62	-5.27	WB
17764	3621778.03	217291.73	-5.26	WB
17765	3621778.39	217295.89	-5.24	WB
17766	3621778.74	217299.89	-5.22	WB
17767	3621779.08	217303.67	-5.20	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
17768	3621779.44	217307.55	-5.18	WB
17769	3621779.78	217311.13	-5.16	WB
17770	3621779.98	217313.21	-5.13	WB
17771	3621780.10	217314.47	-5.11	WB
17772	3621780.43	217317.82	-5.09	WB
17773	3621780.63	217320.86	-5.07	WB
17774	3621780.83	217323.90	-5.04	WB
17775	3621780.96	217326.65	-5.02	WB
17776	3621781.06	217329.37	-4.99	WB
17777	3621781.12	217331.97	-4.97	WB
17778	3621781.07	217334.45	-4.94	WB
17779	3621781.00	217336.97	-4.91	WB
17780	3621780.99	217337.27	-4.88	WB
17781	3621780.96	217339.37	-4.84	WB
17782	3621780.92	217341.77	-4.80	WB
17783	3621780.87	217344.10	-4.76	WB
17784	3621780.79	217346.40	-4.72	WB
17785	3621780.71	217348.78	-4.70	WB
17786	3621780.63	217351.14	-4.68	WB
17787	3621780.56	217353.49	-4.66	WB
17788	3621780.49	217355.87	-4.63	WB
17789	3621780.41	217358.29	-4.62	WB
17790	3621780.33	217360.71	-4.62	WB
17791	3621780.30	217362.57	-4.61	WB
17792	3621780.29	217363.21	-4.62	WB
17793	3621780.25	217365.70	-4.64	WB
17794	3621780.20	217368.29	-4.68	WB
17795	3621780.16	217370.89	-4.71	WB
17796	3621780.13	217373.50	-4.76	WB
17797	3621780.12	217376.31	-4.81	WB
17798	3621780.11	217379.11	-4.88	WB
17799	3621780.07	217382.11	-4.93	WB
17800	3621779.99	217385.26	-5.01	WB
17801	3621779.92	217387.62	-5.08	WB
17802	3621779.89	217388.48	-5.14	WB
17803	3621779.75	217391.97	-5.21	WB
17804	3621779.58	217395.64	-5.29	WB
17805	3621779.42	217399.42	-5.36	WB
17806	3621779.25	217403.28	-5.41	WB
17807	3621779.09	217407.30	-5.47	WB
17808	3621778.97	217411.40	-5.52	WB
17809	3621778.92	217413.42	-5.58	WB
17810	3621778.87	217415.50	-5.64	WB
17811	3621778.86	217419.58	-5.70	WB
17812	3621778.90	217423.56	-5.76	WB
17813	3621778.97	217427.51	-5.80	WB
17814	3621779.12	217431.22	-5.82	WB
17815	3621779.28	217434.84	-5.83	WB
17816	3621779.51	217438.11	-5.82	WB
17817	3621779.78	217441.35	-5.82	WB
17818	3621780.01	217444.33	-5.80	WB
17819	3621780.20	217447.07	-5.77	WB
17820	3621780.39	217449.85	-5.73	WB
17821	3621780.62	217452.20	-5.69	WB
17822	3621780.86	217454.56	-5.64	WB
17823	3621781.03	217456.94	-5.61	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
17824	3621781.12	217459.26	-5.59	WB
17825	3621781.18	217461.66	-5.58	WB
17826	3621781.18	217462.27	-5.56	WB
17827	3621781.15	217464.22	-5.54	WB
17828	3621781.11	217466.76	-5.53	WB
17829	3621781.02	217469.52	-5.53	WB
17830	3621780.89	217472.33	-5.53	WB
17831	3621780.76	217475.21	-5.53	WB
17832	3621780.61	217478.31	-5.54	WB
17833	3621780.45	217481.42	-5.57	WB
17834	3621780.36	217484.66	-5.57	WB
17835	3621780.29	217487.56	-5.57	WB
17836	3621780.29	217487.95	-5.58	WB
17837	3621780.22	217491.27	-5.59	WB
17838	3621780.17	217494.65	-5.59	WB
17839	3621780.12	217498.06	-5.60	WB
17840	3621780.12	217501.33	-5.61	WB
17841	3621780.13	217504.69	-5.61	WB
17842	3621780.14	217508.07	-5.59	WB
17843	3621780.13	217511.31	-5.59	WB
17844	3621780.13	217512.59	-5.57	WB
17845	3621780.11	217514.67	-5.54	WB
17846	3621780.07	217517.92	-5.50	WB
17847	3621780.02	217521.17	-5.46	WB
17848	3621779.95	217524.46	-5.42	WB
17849	3621779.86	217527.60	-5.37	WB
17850	3621779.77	217530.76	-5.33	WB
17851	3621779.65	217533.95	-5.30	WB
17852	3621779.53	217537.09	-5.26	WB
17853	3621779.51	217537.51	-5.22	WB
17854	3621779.42	217540.20	-5.18	WB
17855	3621779.33	217543.24	-5.15	WB
17856	3621779.25	217546.31	-5.11	WB
17857	3621779.15	217549.29	-5.08	WB
17858	3621779.06	217552.27	-5.04	WB
17859	3621779.01	217555.17	-5.01	WB
17860	3621779.01	217558.07	-4.98	WB
17861	3621779.01	217560.96	-4.95	WB
17862	3621779.04	217562.74	-4.92	WB
17863	3621779.05	217563.80	-4.89	WB
17864	3621779.09	217566.59	-4.86	WB
17865	3621779.16	217569.54	-4.84	WB
17866	3621779.24	217572.36	-4.81	WB
17867	3621779.31	217575.22	-4.79	WB
17868	3621779.40	217578.24	-4.77	WB
17869	3621779.47	217581.18	-4.74	WB
17870	3621779.54	217584.39	-4.72	WB
17871	3621779.61	217587.61	-4.70	WB
17872	3621779.62	217587.99	-4.68	WB
17873	3621779.68	217590.82	-4.65	WB
17874	3621779.78	217594.23	-4.63	WB
17875	3621779.89	217597.58	-4.61	WB
17876	3621780.04	217601.01	-4.58	WB
17877	3621780.20	217604.46	-4.56	WB
17878	3621780.37	217607.82	-4.53	WB
17879	3621780.55	217611.28	-4.51	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
17880	3621780.62	217612.55	-4.48	WB
17881	3621780.74	217614.69	-4.45	WB
17882	3621780.94	217618.13	-4.42	WB
17883	3621781.13	217621.55	-4.39	WB
17884	3621781.33	217624.92	-4.36	WB
17885	3621781.53	217628.29	-4.32	WB
17886	3621781.73	217631.67	-4.29	WB
17887	3621781.83	217635.07	-4.25	WB
17888	3621781.90	217637.65	-4.22	WB
17889	3621781.93	217638.46	-4.18	WB
17890	3621782.01	217641.85	-4.14	WB
17891	3621782.07	217645.23	-4.10	WB
17892	3621782.12	217648.60	-4.06	WB
17893	3621782.08	217652.04	-4.02	WB
17894	3621782.03	217655.38	-3.98	WB
17895	3621781.95	217658.75	-3.93	WB
17896	3621781.85	217662.15	-3.89	WB
17897	3621781.84	217662.55	-3.85	WB
17898	3621781.75	217665.44	-3.80	WB
17899	3621781.62	217668.77	-3.75	WB
17900	3621781.50	217672.06	-3.71	WB
17901	3621781.39	217675.17	-3.66	WB
17902	3621781.30	217678.40	-3.62	WB
17903	3621781.23	217681.44	-3.57	WB
17904	3621781.22	217684.37	-3.52	WB
17905	3621781.21	217687.24	-3.47	WB
17906	3621781.21	217687.59	-3.42	WB
17907	3621781.18	217689.86	-3.36	WB
17908	3621781.15	217692.46	-3.31	WB
17909	3621781.11	217694.92	-3.27	WB
17910	3621781.03	217697.15	-3.19	WB
17911	3621780.96	217699.42	-3.13	WB
17912	3621780.85	217701.50	-3.09	WB
17913	3621780.74	217703.58	-3.03	WB
17914	3621780.58	217705.61	-3.00	WB
17915	3621780.36	217707.60	-2.97	WB
17916	3621780.13	217709.63	-2.94	WB
17917	3621779.81	217711.61	-2.91	WB
17918	3621779.77	217711.85	-2.89	WB
17919	3621779.47	217713.61	-2.87	WB
17920	3621779.09	217715.63	-2.87	WB
17921	3621778.67	217717.77	-2.87	WB
17922	3621778.25	217719.87	-2.91	WB
17923	3621777.83	217722.26	-2.93	WB
17924	3621777.41	217724.66	-2.96	WB
17925	3621777.04	217727.34	-2.99	WB
17926	3621776.67	217730.25	-3.01	WB
17927	3621776.31	217733.23	-3.07	WB
17928	3621775.97	217736.52	-3.14	WB
17929	3621775.87	217737.42	-3.22	WB
17930	3621775.60	217740.00	-3.30	WB
17931	3621775.10	217744.76	-3.35	WB
17932	3621774.50	217750.30	-3.44	WB
17933	3621773.87	217755.95	-3.54	WB
17934	3621773.24	217761.67	-3.63	WB
17935	3621773.16	217762.39	-3.71	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
17936	3621772.63	217767.47	-3.80	WB
17937	3621772.31	217773.05	-3.88	WB
17938	3621772.09	217778.55	-3.97	WB
17939	3621772.01	217783.90	-4.06	WB
17940	3621772.01	217788.56	-4.13	WB
17941	3621772.02	217789.21	-4.21	WB
17942	3621772.10	217793.46	-4.27	WB
17943	3621772.28	217796.95	-4.33	WB
17944	3621772.52	217800.36	-4.36	WB
17945	3621772.79	217803.87	-4.38	WB
17946	3621773.17	217807.15	-4.37	WB
17947	3621773.55	217810.37	-4.36	WB
17948	3621774.00	217813.29	-4.33	WB
17949	3621774.12	217813.94	-4.28	WB
17950	3621774.49	217815.97	-4.21	WB
17951	3621774.99	217818.48	-4.16	WB
17952	3621775.51	217820.50	-4.05	WB
17953	3621776.02	217822.46	-3.95	WB
17954	3621776.54	217824.13	-3.84	WB
17955	3621777.05	217825.73	-3.74	WB
17956	3621777.56	217827.26	-3.66	WB
17957	3621778.12	217828.78	-3.57	WB
17958	3621778.66	217830.30	-3.50	WB
17959	3621779.17	217831.83	-3.45	WB
17960	3621779.67	217833.35	-3.37	WB
17961	3621780.17	217834.86	-3.33	WB
17962	3621780.67	217836.34	-3.31	WB
17963	3621781.18	217837.80	-3.29	WB
17964	3621781.47	217838.67	-3.27	WB
17965	3621781.63	217839.15	-3.24	WB
17966	3621782.09	217840.47	-3.22	WB
17967	3621782.55	217841.78	-3.20	WB
17968	3621782.97	217843.03	-3.18	WB
17969	3621783.39	217844.34	-3.17	WB
17970	3621783.75	217845.73	-3.16	WB
17971	3621784.12	217847.14	-3.14	WB
17972	3621784.47	217848.78	-3.09	WB
17973	3621784.79	217850.50	-3.06	WB
17974	3621785.11	217852.32	-3.03	WB
17975	3621785.41	217854.49	-2.99	WB
17976	3621785.71	217856.58	-2.96	WB
17977	3621786.01	217858.84	-2.91	WB
17978	3621786.31	217861.14	-2.86	WB
17979	3621786.55	217863.14	-2.81	WB
17980	3621786.57	217863.40	-2.76	WB
17981	3621786.72	217865.66	-2.71	WB
17982	3621786.87	217867.81	-2.64	WB
17983	3621786.96	217869.67	-2.62	WB
17984	3621787.04	217871.48	-2.61	WB
17985	3621787.07	217873.11	-2.54	WB
17986	3621275.67	215787.54	-8.51	WB
17987	3621275.45	215790.56	-8.51	WB
17988	3621275.24	215793.54	-8.51	WB
17989	3621275.17	215796.44	-8.52	WB
17990	3621275.18	215799.34	-8.52	WB
17991	3621275.19	215802.14	-8.52	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
17992	3621275.16	215805.01	-8.53	WB
17993	3621275.12	215807.86	-8.53	WB
17994	3621275.09	215810.73	-8.53	WB
17995	3621275.06	215813.71	-8.53	WB
17996	3621274.97	215816.67	-8.54	WB
17997	3621274.71	215819.66	-8.54	WB
17998	3621274.61	215820.89	-8.54	WB
17999	3621274.44	215822.76	-8.54	WB
18000	3621274.11	215825.85	-8.54	WB
18001	3621273.79	215828.95	-8.55	WB
18002	3621273.40	215832.03	-8.55	WB
18003	3621272.88	215835.08	-8.55	WB
18004	3621272.35	215838.14	-8.55	WB
18005	3621271.75	215841.22	-8.55	WB
18006	3621271.16	215844.21	-8.55	WB
18007	3621270.84	215845.75	-8.55	WB
18008	3621270.45	215847.33	-8.55	WB
18009	3621269.66	215850.46	-8.55	WB
18010	3621268.85	215853.61	-8.55	WB
18011	3621268.05	215856.93	-8.55	WB
18012	3621267.24	215860.28	-8.54	WB
18013	3621266.42	215863.78	-8.54	WB
18014	3621265.60	215867.35	-8.54	WB
18015	3621264.81	215870.93	-8.53	WB
18016	3621264.65	215871.84	-8.53	WB
18017	3621264.20	215874.54	-8.52	WB
18018	3621263.61	215878.18	-8.52	WB
18019	3621263.33	215881.58	-8.51	WB
18020	3621263.22	215885.00	-8.51	WB
18021	3621263.16	215888.39	-8.50	WB
18022	3621263.29	215891.57	-8.50	WB
18023	3621263.43	215894.82	-8.49	WB
18024	3621263.68	215897.13	-8.49	WB
18025	3621263.79	215897.90	-8.48	WB
18026	3621264.21	215900.90	-8.47	WB
18027	3621264.67	215903.99	-8.47	WB
18028	3621265.18	215907.00	-8.46	WB
18029	3621265.69	215910.01	-8.45	WB
18030	3621266.23	215912.95	-8.45	WB
18031	3621266.77	215915.89	-8.44	WB
18032	3621267.40	215918.80	-8.44	WB
18033	3621268.13	215921.57	-8.43	WB
18034	3621268.31	215922.24	-8.43	WB
18035	3621268.87	215924.35	-8.42	WB
18036	3621269.55	215927.20	-8.42	WB
18037	3621270.21	215930.08	-8.41	WB
18038	3621270.87	215933.02	-8.41	WB
18039	3621271.55	215936.07	-8.41	WB
18040	3621272.23	215939.17	-8.40	WB
18041	3621272.94	215942.28	-8.40	WB
18042	3621273.68	215945.42	-8.40	WB
18043	3621274.14	215947.39	-8.39	WB
18044	3621274.42	215948.60	-8.39	WB
18045	3621275.14	215951.64	-8.39	WB
18046	3621275.90	215954.73	-8.39	WB
18047	3621276.63	215957.61	-8.38	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
18048	3621277.36	215960.43	-8.38	WB
18049	3621278.01	215963.25	-8.38	WB
18050	3621278.61	215966.11	-8.38	WB
18051	3621279.17	215968.87	-8.38	WB
18052	3621279.64	215971.70	-8.37	WB
18053	3621280.12	215974.54	-8.37	WB
18054	3621280.48	215977.30	-8.37	WB
18055	3621280.80	215980.04	-8.37	WB
18056	3621281.08	215982.84	-8.36	WB
18057	3621281.25	215985.56	-8.36	WB
18058	3621281.42	215988.34	-8.36	WB
18059	3621281.38	215991.27	-8.35	WB
18060	3621281.26	215994.16	-8.35	WB
18061	3621281.18	215996.01	-8.35	WB
18062	3621281.07	215997.18	-8.34	WB
18063	3621280.78	216000.24	-8.34	WB
18064	3621280.50	216003.26	-8.34	WB
18065	3621280.15	216006.48	-8.33	WB
18066	3621279.80	216009.73	-8.33	WB
18067	3621279.45	216012.89	-8.32	WB
18068	3621279.11	216016.08	-8.32	WB
18069	3621278.78	216019.26	-8.31	WB
18070	3621278.63	216021.22	-8.31	WB
18071	3621278.55	216022.31	-8.30	WB
18072	3621278.33	216025.35	-8.30	WB
18073	3621278.14	216028.46	-8.29	WB
18074	3621277.96	216031.47	-8.29	WB
18075	3621277.79	216034.49	-8.29	WB
18076	3621277.63	216037.72	-8.28	WB
18077	3621277.46	216040.88	-8.28	WB
18078	3621277.30	216044.18	-8.27	WB
18079	3621277.19	216046.62	-8.27	WB
18080	3621277.15	216047.52	-8.27	WB
18081	3621277.03	216050.84	-8.26	WB
18082	3621277.02	216054.15	-8.26	WB
18083	3621277.03	216057.40	-8.26	WB
18084	3621277.16	216060.57	-8.26	WB
18085	3621277.34	216063.65	-8.25	WB
18086	3621277.57	216066.65	-8.25	WB
18087	3621277.91	216069.58	-8.25	WB
18088	3621278.16	216071.76	-8.25	WB
18089	3621278.25	216072.50	-8.25	WB
18090	3621278.53	216075.47	-8.24	WB
18091	3621278.78	216078.47	-8.24	WB
18092	3621279.04	216081.54	-8.24	WB
18093	3621279.29	216084.65	-8.24	WB
18094	3621279.55	216087.76	-8.24	WB
18095	3621279.64	216090.92	-8.24	WB
18096	3621279.70	216094.00	-8.24	WB
18097	3621279.77	216096.33	-8.23	WB
18098	3621279.81	216097.04	-8.23	WB
18099	3621279.97	216100.03	-8.23	WB
18100	3621280.13	216102.92	-8.23	WB
18101	3621280.18	216105.88	-8.23	WB
18102	3621280.19	216108.82	-8.22	WB
18103	3621280.15	216111.85	-8.22	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
18104	3621280.06	216115.09	-8.22	WB
18105	3621279.97	216118.29	-8.22	WB
18106	3621279.76	216121.28	-8.21	WB
18107	3621279.73	216121.68	-8.21	WB
18108	3621279.49	216125.07	-8.21	WB
18109	3621279.20	216128.53	-8.20	WB
18110	3621278.89	216131.98	-8.20	WB
18111	3621278.58	216135.39	-8.19	WB
18112	3621278.33	216138.70	-8.19	WB
18113	3621278.10	216141.98	-8.19	WB
18114	3621277.95	216145.16	-8.18	WB
18115	3621277.91	216146.32	-8.18	WB
18116	3621277.85	216148.24	-8.17	WB
18117	3621277.76	216151.29	-8.17	WB
18118	3621277.68	216154.37	-8.17	WB
18119	3621277.60	216157.37	-8.16	WB
18120	3621277.48	216160.43	-8.16	WB
18121	3621277.35	216163.53	-8.16	WB
18122	3621277.27	216166.52	-8.15	WB
18123	3621277.25	216169.49	-8.15	WB
18124	3621277.24	216171.71	-8.15	WB
18125	3621277.24	216172.50	-8.15	WB
18126	3621277.29	216175.34	-8.15	WB
18127	3621277.35	216178.22	-8.14	WB
18128	3621277.46	216181.08	-8.14	WB
18129	3621277.62	216183.95	-8.14	WB
18130	3621277.78	216186.83	-8.14	WB
18131	3621277.97	216189.92	-8.14	WB
18132	3621278.14	216193.04	-8.14	WB
18133	3621278.26	216196.35	-8.14	WB
18134	3621278.28	216197.22	-8.14	WB
18135	3621278.34	216199.87	-8.14	WB
18136	3621278.43	216203.24	-8.14	WB
18137	3621278.62	216206.81	-8.13	WB
18138	3621278.82	216210.41	-8.13	WB
18139	3621279.04	216213.86	-8.13	WB
18140	3621279.28	216217.38	-8.13	WB
18141	3621279.54	216220.86	-8.13	WB
18142	3621279.61	216221.65	-8.12	WB
18143	3621279.84	216224.14	-8.12	WB
18144	3621280.15	216227.47	-8.12	WB
18145	3621280.45	216230.73	-8.11	WB
18146	3621280.73	216233.96	-8.11	WB
18147	3621280.96	216237.23	-8.11	WB
18148	3621281.04	216240.43	-8.10	WB
18149	3621281.11	216243.64	-8.10	WB
18150	3621281.23	216246.61	-8.10	WB
18151	3621281.37	216249.58	-8.09	WB
18152	3621281.51	216252.39	-8.09	WB
18153	3621281.66	216255.11	-8.09	WB
18154	3621281.82	216257.86	-8.08	WB
18155	3621282.01	216260.44	-8.08	WB
18156	3621282.19	216263.10	-8.08	WB
18157	3621282.37	216265.77	-8.08	WB
18158	3621282.54	216268.47	-8.08	WB
18159	3621282.72	216271.26	-8.07	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
18160	3621282.77	216271.97	-8.07	WB
18161	3621282.94	216274.23	-8.07	WB
18162	3621283.17	216277.21	-8.07	WB
18163	3621283.48	216280.29	-8.07	WB
18164	3621283.86	216283.43	-8.06	WB
18165	3621284.24	216286.51	-8.06	WB
18166	3621284.73	216289.99	-8.06	WB
18167	3621285.20	216293.43	-8.06	WB
18168	3621285.64	216296.92	-8.06	WB
18169	3621285.70	216297.42	-8.05	WB
18170	3621286.07	216300.61	-8.05	WB
18171	3621286.49	216304.22	-8.05	WB
18172	3621286.94	216307.77	-8.04	WB
18173	3621287.41	216311.41	-8.04	WB
18174	3621287.82	216314.85	-8.03	WB
18175	3621288.19	216318.17	-8.03	WB
18176	3621288.54	216321.53	-8.02	WB
18177	3621288.75	216324.59	-8.02	WB
18178	3621288.96	216327.65	-8.01	WB
18179	3621289.14	216330.45	-8.01	WB
18180	3621289.31	216333.20	-8.00	WB
18181	3621289.42	216335.90	-7.99	WB
18182	3621289.42	216338.46	-7.98	WB
18183	3621289.41	216341.04	-7.98	WB
18184	3621289.38	216343.57	-7.97	WB
18185	3621289.33	216346.10	-7.96	WB
18186	3621289.33	216346.40	-7.96	WB
18187	3621289.26	216348.66	-7.95	WB
18188	3621289.15	216351.22	-7.94	WB
18189	3621289.05	216353.81	-7.94	WB
18190	3621288.87	216356.47	-7.93	WB
18191	3621288.69	216359.16	-7.93	WB
18192	3621288.50	216361.90	-7.92	WB
18193	3621288.28	216364.61	-7.92	WB
18194	3621288.07	216367.41	-7.91	WB
18195	3621287.79	216370.32	-7.91	WB
18196	3621287.71	216371.06	-7.91	WB
18197	3621287.51	216373.20	-7.90	WB
18198	3621287.15	216376.25	-7.90	WB
18199	3621286.75	216379.32	-7.90	WB
18200	3621286.33	216382.41	-7.90	WB
18201	3621285.86	216385.58	-7.90	WB
18202	3621285.37	216388.77	-7.89	WB
18203	3621284.81	216392.00	-7.89	WB
18204	3621284.18	216395.33	-7.89	WB
18205	3621284.10	216395.73	-7.89	WB
18206	3621283.53	216398.69	-7.88	WB
18207	3621282.84	216402.09	-7.88	WB
18208	3621282.16	216405.49	-7.88	WB
18209	3621281.48	216408.83	-7.88	WB
18210	3621280.81	216412.13	-7.87	WB
18211	3621280.15	216415.46	-7.87	WB
18212	3621279.54	216418.61	-7.86	WB
18213	3621279.07	216421.00	-7.86	WB
18214	3621278.92	216421.76	-7.85	WB
18215	3621278.33	216425.02	-7.85	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
18216	3621277.77	216428.14	-7.84	WB
18217	3621277.20	216431.38	-7.84	WB
18218	3621276.64	216434.58	-7.83	WB
18219	3621276.10	216437.73	-7.83	WB
18220	3621275.68	216440.95	-7.82	WB
18221	3621275.28	216444.14	-7.81	WB
18222	3621275.01	216446.54	-7.80	WB
18223	3621274.94	216447.29	-7.80	WB
18224	3621274.63	216450.43	-7.79	WB
18225	3621274.33	216453.58	-7.78	WB
18226	3621274.23	216456.73	-7.78	WB
18227	3621274.12	216459.87	-7.77	WB
18228	3621274.01	216463.09	-7.76	WB
18229	3621273.90	216466.32	-7.75	WB
18230	3621273.80	216469.56	-7.75	WB
18231	3621273.82	216471.62	-7.74	WB
18232	3621273.83	216472.78	-7.73	WB
18233	3621273.87	216475.98	-7.73	WB
18234	3621273.92	216479.22	-7.72	WB
18235	3621273.97	216482.32	-7.72	WB
18236	3621274.05	216485.45	-7.71	WB
18237	3621274.29	216488.53	-7.71	WB
18238	3621274.52	216491.50	-7.70	WB
18239	3621274.77	216494.51	-7.70	WB
18240	3621274.94	216496.76	-7.69	WB
18241	3621275.00	216497.52	-7.69	WB
18242	3621275.26	216500.51	-7.69	WB
18243	3621275.58	216503.68	-7.68	WB
18244	3621275.89	216506.80	-7.68	WB
18245	3621276.15	216510.01	-7.68	WB
18246	3621276.39	216513.22	-7.68	WB
18247	3621276.71	216516.43	-7.68	WB
18248	3621277.13	216519.58	-7.67	WB
18249	3621277.44	216521.92	-7.67	WB
18250	3621277.55	216522.71	-7.67	WB
18251	3621277.98	216525.70	-7.67	WB
18252	3621278.41	216528.72	-7.67	WB
18253	3621278.81	216531.72	-7.67	WB
18254	3621279.19	216534.73	-7.67	WB
18255	3621279.56	216537.77	-7.67	WB
18256	3621279.86	216540.90	-7.67	WB
18257	3621280.14	216543.93	-7.67	WB
18258	3621280.39	216547.03	-7.66	WB
18259	3621280.61	216550.19	-7.66	WB
18260	3621280.84	216553.23	-7.66	WB
18261	3621281.08	216556.30	-7.66	WB
18262	3621281.33	216559.32	-7.66	WB
18263	3621281.54	216562.26	-7.65	WB
18264	3621281.72	216565.32	-7.65	WB
18265	3621281.90	216568.33	-7.64	WB
18266	3621282.03	216571.34	-7.64	WB
18267	3621282.15	216574.35	-7.64	WB
18268	3621282.22	216577.42	-7.63	WB
18269	3621282.26	216580.51	-7.63	WB
18270	3621282.24	216583.61	-7.62	WB
18271	3621282.11	216586.69	-7.62	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
18272	3621281.97	216589.77	-7.61	WB
18273	3621281.86	216592.79	-7.60	WB
18274	3621281.76	216595.79	-7.60	WB
18275	3621281.75	216596.20	-7.59	WB
18276	3621281.63	216598.78	-7.59	WB
18277	3621281.45	216601.77	-7.58	WB
18278	3621281.27	216604.68	-7.58	WB
18279	3621281.10	216607.57	-7.57	WB
18280	3621280.92	216610.50	-7.57	WB
18281	3621280.72	216613.38	-7.56	WB
18282	3621280.48	216616.36	-7.56	WB
18283	3621280.24	216619.32	-7.55	WB
18284	3621280.06	216621.51	-7.55	WB
18285	3621279.99	216622.28	-7.55	WB
18286	3621279.74	216625.34	-7.55	WB
18287	3621279.54	216628.36	-7.55	WB
18288	3621279.37	216631.36	-7.54	WB
18289	3621279.21	216634.40	-7.54	WB
18290	3621279.11	216637.41	-7.54	WB
18291	3621279.02	216640.40	-7.54	WB
18292	3621279.08	216643.33	-7.54	WB
18293	3621279.24	216646.29	-7.54	WB
18294	3621279.28	216646.99	-7.55	WB
18295	3621279.41	216649.17	-7.55	WB
18296	3621279.62	216652.16	-7.55	WB
18297	3621279.84	216655.19	-7.55	WB
18298	3621280.20	216658.36	-7.55	WB
18299	3621280.60	216661.60	-7.55	WB
18300	3621280.99	216665.00	-7.55	WB
18301	3621281.33	216668.53	-7.55	WB
18302	3621281.68	216672.11	-7.54	WB
18303	3621282.01	216675.84	-7.54	WB
18304	3621282.34	216679.46	-7.54	WB
18305	3621282.67	216683.06	-7.54	WB
18306	3621282.99	216686.57	-7.54	WB
18307	3621283.31	216690.04	-7.53	WB
18308	3621283.57	216693.26	-7.53	WB
18309	3621283.82	216696.53	-7.53	WB
18310	3621284.00	216699.57	-7.52	WB
18311	3621284.12	216702.54	-7.52	WB
18312	3621284.22	216705.56	-7.51	WB
18313	3621284.21	216708.33	-7.51	WB
18314	3621284.19	216711.23	-7.51	WB
18315	3621284.13	216714.03	-7.50	WB
18316	3621284.04	216716.75	-7.50	WB
18317	3621283.95	216719.54	-7.49	WB
18318	3621283.91	216721.45	-7.49	WB
18319	3621283.89	216722.16	-7.49	WB
18320	3621283.84	216724.74	-7.49	WB
18321	3621283.81	216727.36	-7.48	WB
18322	3621283.79	216729.90	-7.48	WB
18323	3621283.76	216732.43	-7.48	WB
18324	3621283.67	216735.20	-7.48	WB
18325	3621283.58	216737.94	-7.48	WB
18326	3621283.38	216740.89	-7.48	WB
18327	3621283.16	216743.99	-7.48	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
18328	3621282.96	216746.71	-7.48	WB
18329	3621282.93	216747.12	-7.48	WB
18330	3621282.69	216750.51	-7.47	WB
18331	3621282.45	216753.96	-7.47	WB
18332	3621282.21	216757.52	-7.47	WB
18333	3621281.96	216761.18	-7.47	WB
18334	3621281.74	216764.96	-7.47	WB
18335	3621281.58	216768.76	-7.47	WB
18336	3621281.46	216771.69	-7.46	WB
18337	3621281.42	216772.66	-7.46	WB
18338	3621281.25	216776.56	-7.45	WB
18339	3621281.07	216780.41	-7.45	WB
18340	3621280.90	216784.34	-7.44	WB
18341	3621280.74	216788.26	-7.43	WB
18342	3621280.59	216792.18	-7.42	WB
18343	3621280.45	216795.88	-7.41	WB
18344	3621280.41	216796.77	-7.40	WB
18345	3621280.31	216799.59	-7.39	WB
18346	3621280.21	216803.09	-7.38	WB
18347	3621280.13	216806.43	-7.36	WB
18348	3621280.08	216809.73	-7.35	WB
18349	3621280.15	216812.67	-7.34	WB
18350	3621280.22	216815.62	-7.32	WB
18351	3621280.27	216818.42	-7.31	WB
18352	3621280.29	216821.15	-7.30	WB
18353	3621280.30	216821.47	-7.28	WB
18354	3621280.32	216823.93	-7.27	WB
18355	3621280.39	216826.56	-7.26	WB
18356	3621280.45	216829.23	-7.25	WB
18357	3621280.44	216832.01	-7.24	WB
18358	3621280.40	216834.73	-7.23	WB
18359	3621280.39	216837.50	-7.22	WB
18360	3621280.45	216840.37	-7.21	WB
18361	3621280.52	216843.15	-7.20	WB
18362	3621280.62	216846.02	-7.20	WB
18363	3621280.65	216846.75	-7.19	WB
18364	3621280.73	216848.92	-7.19	WB
18365	3621280.87	216851.83	-7.18	WB
18366	3621281.07	216854.86	-7.18	WB
18367	3621281.26	216857.90	-7.18	WB
18368	3621281.49	216861.10	-7.18	WB
18369	3621281.71	216864.32	-7.17	WB
18370	3621281.95	216867.74	-7.17	WB
18371	3621282.17	216871.19	-7.17	WB
18372	3621282.23	216872.12	-7.17	WB
18373	3621282.40	216874.68	-7.17	WB
18374	3621282.76	216878.48	-7.17	WB
18375	3621283.11	216882.19	-7.17	WB
18376	3621283.55	216886.12	-7.17	WB
18377	3621284.05	216890.02	-7.17	WB
18378	3621284.55	216893.83	-7.17	WB
18379	3621285.06	216897.30	-7.16	WB
18380	3621285.12	216897.75	-7.16	WB
18381	3621285.70	216901.60	-7.15	WB
18382	3621286.27	216905.18	-7.15	WB
18383	3621286.85	216908.74	-7.14	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
18384	3621287.44	216912.21	-7.13	WB
18385	3621287.97	216915.40	-7.12	WB
18386	3621288.49	216918.60	-7.12	WB
18387	3621288.82	216921.32	-7.11	WB
18388	3621288.86	216921.71	-7.10	WB
18389	3621289.15	216924.65	-7.08	WB
18390	3621289.40	216927.65	-7.07	WB
18391	3621289.56	216930.60	-7.06	WB
18392	3621289.71	216933.47	-7.05	WB
18393	3621289.69	216936.33	-7.04	WB
18394	3621289.63	216939.12	-7.03	WB
18395	3621289.61	216941.79	-7.02	WB
18396	3621289.67	216944.41	-7.01	WB
18397	3621289.70	216945.99	-7.00	WB
18398	3621289.72	216947.00	-6.99	WB
18399	3621289.66	216949.46	-6.98	WB
18400	3621289.55	216951.99	-6.97	WB
18401	3621289.50	216954.50	-6.96	WB
18402	3621289.51	216956.98	-6.96	WB
18403	3621289.53	216959.53	-6.95	WB
18404	3621289.44	216962.16	-6.95	WB
18405	3621289.34	216964.79	-6.95	WB
18406	3621289.25	216967.52	-6.94	WB
18407	3621289.17	216970.30	-6.94	WB
18408	3621289.13	216971.67	-6.94	WB
18409	3621289.10	216973.03	-6.94	WB
18410	3621289.08	216976.08	-6.94	WB
18411	3621289.06	216978.97	-6.94	WB
18412	3621289.05	216982.08	-6.95	WB
18413	3621289.03	216985.48	-6.95	WB
18414	3621289.02	216988.85	-6.95	WB
18415	3621289.05	216992.68	-6.95	WB
18416	3621289.07	216996.57	-6.95	WB
18417	3621289.07	216997.03	-6.95	WB
18418	3621289.08	217000.66	-6.95	WB
18419	3621289.08	217004.94	-6.95	WB
18420	3621289.10	217009.32	-6.95	WB
18421	3621289.13	217013.66	-6.95	WB
18422	3621289.19	217018.04	-6.95	WB
18423	3621289.34	217022.20	-6.94	WB
18424	3621289.55	217026.30	-6.94	WB
18425	3621289.77	217030.21	-6.93	WB
18426	3621289.99	217033.82	-6.92	WB
18427	3621290.21	217037.33	-6.91	WB
18428	3621290.42	217040.49	-6.91	WB
18429	3621290.62	217043.65	-6.90	WB
18430	3621290.72	217046.21	-6.89	WB
18431	3621290.72	217046.53	-6.87	WB
18432	3621290.70	217049.34	-6.86	WB
18433	3621290.67	217052.12	-6.85	WB
18434	3621290.61	217054.68	-6.84	WB
18435	3621290.55	217057.28	-6.83	WB
18436	3621290.46	217059.76	-6.82	WB
18437	3621290.34	217062.17	-6.80	WB
18438	3621290.21	217064.55	-6.79	WB
18439	3621290.05	217066.83	-6.78	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
18440	3621289.88	217069.11	-6.77	WB
18441	3621289.70	217071.17	-6.76	WB
18442	3621289.67	217071.45	-6.75	WB
18443	3621289.44	217073.81	-6.75	WB
18444	3621289.19	217076.19	-6.74	WB
18445	3621288.83	217078.70	-6.73	WB
18446	3621288.47	217081.22	-6.73	WB
18447	3621288.07	217083.87	-6.73	WB
18448	3621287.65	217086.65	-6.72	WB
18449	3621287.23	217089.46	-6.72	WB
18450	3621286.77	217092.44	-6.72	WB
18451	3621286.30	217095.55	-6.72	WB
18452	3621286.19	217096.28	-6.72	WB
18453	3621285.90	217098.70	-6.72	WB
18454	3621285.50	217102.01	-6.71	WB
18455	3621285.06	217105.39	-6.71	WB
18456	3621284.57	217108.87	-6.71	WB
18457	3621284.07	217112.35	-6.71	WB
18458	3621283.62	217115.95	-6.71	WB
18459	3621283.17	217119.62	-6.70	WB
18460	3621282.94	217121.43	-6.70	WB
18461	3621282.72	217123.32	-6.69	WB
18462	3621282.28	217127.12	-6.68	WB
18463	3621281.82	217130.94	-6.67	WB
18464	3621281.43	217134.88	-6.66	WB
18465	3621281.04	217138.84	-6.65	WB
18466	3621280.76	217142.66	-6.63	WB
18467	3621280.58	217146.52	-6.62	WB
18468	3621280.56	217146.99	-6.61	WB
18469	3621280.40	217150.43	-6.60	WB
18470	3621280.33	217154.10	-6.59	WB
18471	3621280.27	217157.81	-6.58	WB
18472	3621280.28	217161.45	-6.56	WB
18473	3621280.34	217164.89	-6.55	WB
18474	3621280.43	217168.34	-6.54	WB
18475	3621280.69	217171.50	-6.52	WB
18476	3621280.75	217172.26	-6.51	WB
18477	3621280.95	217174.66	-6.50	WB
18478	3621281.27	217177.61	-6.48	WB
18479	3621281.60	217180.52	-6.47	WB
18480	3621281.97	217183.39	-6.45	WB
18481	3621282.44	217186.14	-6.44	WB
18482	3621282.92	217188.89	-6.43	WB
18483	3621283.40	217191.64	-6.41	WB
18484	3621283.88	217194.36	-6.40	WB
18485	3621284.37	217197.05	-6.38	WB
18486	3621284.90	217199.77	-6.37	WB
18487	3621285.44	217202.52	-6.36	WB
18488	3621286.00	217205.19	-6.34	WB
18489	3621286.58	217207.87	-6.33	WB
18490	3621287.14	217210.58	-6.32	WB
18491	3621287.64	217213.22	-6.31	WB
18492	3621288.15	217215.94	-6.29	WB
18493	3621288.65	217218.65	-6.28	WB
18494	3621289.13	217221.28	-6.27	WB
18495	3621289.20	217221.64	-6.26	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
18496	3621289.58	217224.00	-6.25	WB
18497	3621289.96	217226.70	-6.24	WB
18498	3621290.33	217229.38	-6.23	WB
18499	3621290.54	217232.21	-6.22	WB
18500	3621290.75	217235.06	-6.22	WB
18501	3621290.86	217238.01	-6.21	WB
18502	3621290.92	217241.08	-6.20	WB
18503	3621290.95	217244.04	-6.19	WB
18504	3621290.87	217246.42	-6.18	WB
18505	3621290.85	217247.16	-6.17	WB
18506	3621290.74	217250.34	-6.16	WB
18507	3621290.58	217253.44	-6.15	WB
18508	3621290.40	217256.59	-6.14	WB
18509	3621290.18	217259.81	-6.13	WB
18510	3621289.89	217262.95	-6.12	WB
18511	3621289.57	217266.20	-6.11	WB
18512	3621289.22	217269.40	-6.10	WB
18513	3621289.03	217270.99	-6.09	WB
18514	3621288.85	217272.58	-6.08	WB
18515	3621288.42	217275.98	-6.06	WB
18516	3621287.95	217279.23	-6.05	WB
18517	3621287.48	217282.49	-6.03	WB
18518	3621286.95	217285.96	-6.02	WB
18519	3621286.44	217289.29	-6.00	WB
18520	3621285.91	217292.74	-5.99	WB
18521	3621285.41	217296.13	-5.97	WB
18522	3621284.91	217299.46	-5.95	WB
18523	3621284.41	217302.81	-5.93	WB
18524	3621283.93	217306.09	-5.91	WB
18525	3621283.49	217309.25	-5.89	WB
18526	3621283.09	217312.41	-5.87	WB
18527	3621282.68	217315.54	-5.85	WB
18528	3621282.26	217318.54	-5.83	WB
18529	3621281.95	217320.77	-5.81	WB
18530	3621281.85	217321.53	-5.78	WB
18531	3621281.46	217324.50	-5.76	WB
18532	3621281.10	217327.40	-5.74	WB
18533	3621280.71	217330.35	-5.72	WB
18534	3621280.25	217333.35	-5.69	WB
18535	3621279.79	217336.29	-5.67	WB
18536	3621279.40	217339.30	-5.65	WB
18537	3621279.06	217342.28	-5.63	WB
18538	3621278.77	217345.23	-5.61	WB
18539	3621278.70	217346.76	-5.59	WB
18540	3621278.64	217348.24	-5.57	WB
18541	3621278.54	217351.10	-5.55	WB
18542	3621278.65	217353.91	-5.53	WB
18543	3621278.83	217356.65	-5.52	WB
18544	3621279.09	217359.33	-5.50	WB
18545	3621279.48	217361.89	-5.49	WB
18546	3621279.89	217364.44	-5.48	WB
18547	3621280.44	217366.89	-5.46	WB
18548	3621281.03	217369.34	-5.45	WB
18549	3621281.62	217371.84	-5.45	WB
18550	3621281.76	217372.44	-5.44	WB
18551	3621282.19	217374.39	-5.43	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
18552	3621282.76	217376.95	-5.43	WB
18553	3621283.41	217379.75	-5.42	WB
18554	3621284.04	217382.47	-5.42	WB
18555	3621284.64	217385.51	-5.41	WB
18556	3621285.21	217388.88	-5.41	WB
18557	3621285.79	217392.15	-5.41	WB
18558	3621286.55	217395.50	-5.41	WB
18559	3621287.02	217397.50	-5.41	WB
18560	3621287.32	217398.76	-5.41	WB
18561	3621288.00	217402.07	-5.41	WB
18562	3621288.65	217405.60	-5.40	WB
18563	3621289.30	217409.11	-5.40	WB
18564	3621289.90	217412.57	-5.40	WB
18565	3621290.53	217416.16	-5.40	WB
18566	3621291.03	217419.32	-5.40	WB
18567	3621291.38	217421.69	-5.39	WB
18568	3621291.49	217422.47	-5.39	WB
18569	3621291.89	217425.60	-5.39	WB
18570	3621292.08	217428.78	-5.38	WB
18571	3621292.28	217432.07	-5.38	WB
18572	3621292.34	217435.12	-5.37	WB
18573	3621292.34	217438.10	-5.36	WB
18574	3621292.25	217441.11	-5.36	WB
18575	3621291.98	217443.93	-5.35	WB
18576	3621291.81	217445.70	-5.34	WB
18577	3621291.71	217446.72	-5.33	WB
18578	3621291.36	217449.36	-5.32	WB
18579	3621291.00	217452.02	-5.31	WB
18580	3621290.60	217454.53	-5.31	WB
18581	3621290.12	217456.99	-5.30	WB
18582	3621289.65	217459.43	-5.29	WB
18583	3621289.14	217461.73	-5.28	WB
18584	3621288.62	217464.11	-5.26	WB
18585	3621288.08	217466.40	-5.25	WB
18586	3621287.50	217468.66	-5.24	WB
18587	3621286.99	217470.65	-5.23	WB
18588	3621286.92	217470.93	-5.23	WB
18589	3621286.30	217473.19	-5.22	WB
18590	3621285.68	217475.44	-5.22	WB
18591	3621285.01	217477.73	-5.23	WB
18592	3621284.29	217480.07	-5.22	WB
18593	3621283.56	217482.41	-5.22	WB
18594	3621282.73	217484.93	-5.22	WB
18595	3621281.90	217487.42	-5.23	WB
18596	3621281.06	217490.06	-5.23	WB
18597	3621280.18	217492.91	-5.25	WB
18598	3621279.32	217495.76	-5.27	WB
18599	3621279.20	217496.18	-5.30	WB
18600	3621278.43	217498.83	-5.34	WB
18601	3621277.50	217502.04	-5.41	WB
18602	3621276.66	217505.38	-5.48	WB
18603	3621275.82	217508.87	-5.54	WB
18604	3621275.02	217512.42	-5.62	WB
18605	3621274.25	217516.18	-5.69	WB
18606	3621273.49	217519.92	-5.74	WB
18607	3621273.23	217521.43	-5.79	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
18608	3621272.85	217523.81	-5.83	WB
18609	3621272.24	217527.70	-5.88	WB
18610	3621271.66	217531.54	-5.92	WB
18611	3621271.10	217535.45	-5.97	WB
18612	3621270.54	217539.35	-6.00	WB
18613	3621270.11	217543.06	-6.03	WB
18614	3621269.72	217546.42	-6.04	WB
18615	3621269.66	217546.92	-6.04	WB
18616	3621269.20	217550.60	-6.04	WB
18617	3621268.73	217554.18	-6.04	WB
18618	3621268.26	217557.74	-6.01	WB
18619	3621267.90	217561.03	-5.98	WB
18620	3621267.53	217564.43	-5.93	WB
18621	3621267.12	217567.67	-5.88	WB
18622	3621266.68	217570.73	-5.80	WB
18623	3621266.62	217571.15	-5.73	WB
18624	3621266.25	217573.83	-5.69	WB
18625	3621265.91	217576.72	-5.63	WB
18626	3621265.58	217579.62	-5.56	WB
18627	3621265.25	217582.40	-5.51	WB
18628	3621264.92	217585.12	-5.49	WB
18629	3621264.59	217587.80	-5.47	WB
18630	3621264.31	217590.39	-5.46	WB
18631	3621264.02	217592.99	-5.43	WB
18632	3621263.86	217595.61	-5.41	WB
18633	3621263.82	217596.33	-5.38	WB
18634	3621263.71	217598.30	-5.36	WB
18635	3621263.56	217601.09	-5.36	WB
18636	3621263.43	217603.90	-5.33	WB
18637	3621263.28	217606.82	-5.30	WB
18638	3621263.29	217609.88	-5.26	WB
18639	3621263.32	217612.95	-5.20	WB
18640	3621263.41	217616.16	-5.18	WB
18641	3621263.59	217619.44	-5.17	WB
18642	3621263.80	217622.72	-5.17	WB
18643	3621264.31	217625.91	-5.16	WB
18644	3621264.85	217629.06	-5.13	WB
18645	3621265.54	217632.05	-5.13	WB
18646	3621266.38	217634.94	-5.12	WB
18647	3621267.24	217637.81	-5.13	WB
18648	3621268.26	217640.62	-5.16	WB
18649	3621269.29	217643.45	-5.18	WB
18650	3621270.42	217646.27	-5.20	WB
18651	3621271.47	217648.78	-5.20	WB
18652	3621271.62	217649.13	-5.21	WB
18653	3621272.83	217652.03	-5.23	WB
18654	3621274.07	217655.00	-5.24	WB
18655	3621275.32	217657.99	-5.26	WB
18656	3621276.73	217660.96	-5.27	WB
18657	3621278.15	217663.79	-5.28	WB
18658	3621279.64	217666.62	-5.28	WB
18659	3621281.13	217669.26	-5.27	WB
18660	3621282.63	217671.84	-5.27	WB
18661	3621283.21	217672.87	-5.27	WB
18662	3621284.02	217674.42	-5.24	WB
18663	3621285.35	217676.97	-5.21	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
18664	3621286.58	217679.56	-5.18	WB
18665	3621287.58	217682.12	-5.14	WB
18666	3621288.58	217684.72	-5.10	WB
18667	3621289.38	217687.24	-5.04	WB
18668	3621290.14	217689.77	-4.99	WB
18669	3621290.81	217692.34	-4.93	WB
18670	3621291.36	217694.83	-4.87	WB
18671	3621291.75	217696.71	-4.80	WB
18672	3621291.89	217697.35	-4.76	WB
18673	3621292.33	217699.83	-4.69	WB
18674	3621292.76	217702.34	-4.62	WB
18675	3621293.18	217704.85	-4.57	WB
18676	3621293.58	217707.24	-4.52	WB
18677	3621293.98	217709.66	-4.48	WB
18678	3621294.41	217712.08	-4.43	WB
18679	3621294.82	217714.43	-4.39	WB
18680	3621295.25	217716.85	-4.36	WB
18681	3621295.68	217719.21	-4.30	WB
18682	3621296.10	217721.52	-4.27	WB
18683	3621296.22	217722.15	-4.23	WB
18684	3621296.54	217723.89	-4.20	WB
18685	3621296.99	217726.20	-4.16	WB
18686	3621297.49	217728.54	-4.13	WB
18687	3621298.02	217730.85	-4.11	WB
18688	3621298.55	217733.18	-4.11	WB
18689	3621299.04	217735.59	-4.11	WB
18690	3621299.54	217737.97	-4.11	WB
18691	3621300.00	217740.49	-4.11	WB
18692	3621300.45	217743.08	-4.12	WB
18693	3621300.82	217745.87	-4.13	WB
18694	3621300.85	217746.27	-4.17	WB
18695	3621301.01	217748.80	-4.18	WB
18696	3621301.20	217751.82	-4.20	WB
18697	3621301.13	217755.14	-4.20	WB
18698	3621301.00	217758.55	-4.19	WB
18699	3621300.76	217762.12	-4.19	WB
18700	3621300.34	217765.89	-4.19	WB
18701	3621299.92	217769.68	-4.17	WB
18702	3621299.68	217771.28	-4.14	WB
18703	3621299.29	217773.80	-4.09	WB
18704	3621298.67	217777.76	-4.05	WB
18705	3621298.03	217781.78	-3.98	WB
18706	3621297.38	217785.90	-3.93	WB
18707	3621296.73	217789.96	-3.87	WB
18708	3621296.08	217794.07	-3.81	WB
18709	3621295.75	217796.12	-3.74	WB
18710	3621295.44	217798.11	-3.68	WB
18711	3621294.92	217801.99	-3.62	WB
18712	3621294.45	217805.99	-3.56	WB
18713	3621294.02	217809.73	-3.50	WB
18714	3621293.68	217813.52	-3.46	WB
18715	3621293.35	217817.24	-3.41	WB
18716	3621293.07	217820.72	-3.38	WB
18717	3621293.03	217821.19	-3.36	WB
18718	3621292.78	217824.24	-3.33	WB
18719	3621292.51	217827.63	-3.31	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
18720	3621292.23	217830.92	-3.31	WB
18721	3621291.97	217834.20	-3.31	WB
18722	3621291.67	217837.25	-3.33	WB
18723	3621291.39	217840.20	-3.33	WB
18724	3621291.12	217843.12	-3.33	WB
18725	3621290.91	217845.74	-3.33	WB
18726	3621290.89	217846.09	-3.33	WB
18727	3621290.73	217848.34	-3.33	WB
18728	3621290.50	217850.60	-3.33	WB
18729	3621290.27	217852.79	-3.32	WB
18730	3621290.02	217854.85	-3.33	WB
18731	3621289.72	217856.81	-3.32	WB
18732	3621289.42	217858.73	-3.33	WB
18733	3621288.98	217860.50	-3.34	WB
18734	3621288.51	217862.33	-3.34	WB
18735	3621288.01	217864.13	-3.35	WB
18736	3621287.46	217866.00	-3.36	WB
18737	3621286.88	217867.90	-3.36	WB
18738	3621286.27	217869.89	-3.36	WB
18739	3621286.10	217870.44	-3.36	WB
18740	3621285.62	217871.96	-3.36	WB
18741	3621284.99	217874.07	-3.35	WB
18742	3621284.37	217876.24	-3.36	WB
18743	3621283.77	217878.41	-3.36	WB
18744	3621283.29	217880.66	-3.36	WB
18745	3621282.81	217882.91	-3.34	WB
18746	3621282.41	217885.14	-3.34	WB
18747	3621282.05	217887.40	-3.36	WB
18748	3621281.74	217889.63	-3.36	WB
18749	3621281.56	217891.83	-3.37	WB
18750	3621281.39	217894.01	-3.41	WB
18751	3621281.30	217896.26	-3.44	WB
18752	3621281.29	217896.52	-3.48	WB
18753	3621281.22	217898.46	-3.55	WB
18754	3621281.16	217900.63	-3.62	WB
18755	3621281.12	217902.99	-3.69	WB
18756	3621281.07	217905.30	-3.77	WB
18757	3621281.03	217907.82	-3.84	WB
18758	3621280.99	217910.40	-3.91	WB
18759	3621280.93	217913.04	-3.97	WB
18760	3621280.83	217915.87	-4.00	WB
18761	3621280.73	217918.73	-4.03	WB
18762	3621280.60	217921.75	-4.04	WB
18763	3621280.48	217924.85	-4.06	WB
18764	3621280.34	217927.95	-4.06	WB
18765	3621280.19	217931.06	-4.04	WB
18766	3621280.05	217934.23	-4.03	WB
18767	3621279.91	217937.41	-4.01	WB
18768	3621279.78	217940.59	-3.96	WB
18769	3621279.61	217943.80	-3.92	WB
18770	3621279.46	217946.49	-3.87	WB
18771	3621279.43	217946.91	-3.82	WB
18772	3621279.25	217950.07	-3.77	WB
18773	3621279.04	217953.11	-3.73	WB
18774	3621278.83	217956.17	-3.68	WB
18775	3621278.56	217959.10	-3.63	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
18776	3621278.25	217962.06	-3.59	WB
18777	3621277.94	217964.85	-3.53	WB
18778	3621277.63	217967.60	-3.48	WB
18779	3621277.31	217970.31	-3.42	WB
18780	3621277.20	217971.31	-3.37	WB
18781	3621277.02	217972.88	-3.32	WB
18782	3621276.72	217975.41	-3.26	WB
18783	3621276.45	217977.88	-3.22	WB
18784	3621276.22	217980.23	-3.18	WB
18785	3621275.99	217982.62	-3.14	WB
18786	3621275.85	217984.68	-3.09	WB
18787	3621275.72	217986.75	-3.05	WB
18788	3621275.63	217988.69	-3.01	WB
18789	3621275.57	217990.42	-2.96	WB
18790	3621275.53	217992.17	-2.92	WB
18791	3621275.63	217993.58	-2.88	WB
18792	3621275.73	217994.96	-2.84	WB
18793	3621275.86	217996.28	-2.79	WB
18794	3621276.01	217997.43	-2.75	WB
18795	3621276.13	217998.48	-2.71	WB
18796	3620796.05	215792.94	-8.86	WB
18797	3620795.92	215793.37	-8.85	WB
18798	3620795.06	215796.16	-8.85	WB
18799	3620794.81	215796.98	-8.84	WB
18800	3620794.09	215799.34	-8.84	WB
18801	3620793.20	215802.53	-8.83	WB
18802	3620792.42	215805.56	-8.83	WB
18803	3620791.65	215808.68	-8.82	WB
18804	3620791.07	215811.57	-8.82	WB
18805	3620790.53	215814.38	-8.82	WB
18806	3620790.14	215817.18	-8.81	WB
18807	3620789.83	215819.93	-8.81	WB
18808	3620789.57	215822.34	-8.80	WB
18809	3620789.54	215822.69	-8.80	WB
18810	3620789.29	215825.54	-8.80	WB
18811	3620789.01	215828.43	-8.79	WB
18812	3620788.73	215831.48	-8.79	WB
18813	3620788.46	215834.57	-8.79	WB
18814	3620788.20	215837.74	-8.79	WB
18815	3620787.96	215840.99	-8.78	WB
18816	3620787.72	215844.24	-8.78	WB
18817	3620787.56	215847.11	-8.78	WB
18818	3620787.54	215847.49	-8.77	WB
18819	3620787.37	215850.73	-8.77	WB
18820	3620787.23	215853.99	-8.77	WB
18821	3620787.13	215857.11	-8.77	WB
18822	3620787.04	215860.22	-8.77	WB
18823	3620786.93	215863.40	-8.76	WB
18824	3620786.84	215866.44	-8.76	WB
18825	3620786.67	215869.52	-8.76	WB
18826	3620786.44	215872.16	-8.76	WB
18827	3620786.41	215872.58	-8.75	WB
18828	3620786.13	215875.60	-8.75	WB
18829	3620785.73	215878.72	-8.75	WB
18830	3620785.28	215882.16	-8.75	WB
18831	3620784.83	215885.28	-8.74	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
18832	3620784.35	215888.42	-8.74	WB
18833	3620783.87	215891.61	-8.74	WB
18834	3620783.40	215894.87	-8.73	WB
18835	3620783.03	215897.36	-8.73	WB
18836	3620782.92	215898.14	-8.73	WB
18837	3620782.50	215901.51	-8.73	WB
18838	3620782.10	215904.82	-8.72	WB
18839	3620781.70	215908.26	-8.72	WB
18840	3620781.30	215911.76	-8.72	WB
18841	3620780.91	215915.16	-8.71	WB
18842	3620780.54	215918.65	-8.71	WB
18843	3620780.19	215922.09	-8.71	WB
18844	3620780.15	215922.54	-8.70	WB
18845	3620779.97	215925.37	-8.70	WB
18846	3620779.89	215928.60	-8.69	WB
18847	3620779.82	215931.77	-8.69	WB
18848	3620779.89	215934.82	-8.69	WB
18849	3620779.95	215937.87	-8.68	WB
18850	3620780.10	215940.85	-8.68	WB
18851	3620780.33	215943.81	-8.68	WB
18852	3620780.58	215946.69	-8.67	WB
18853	3620780.71	215947.74	-8.67	WB
18854	3620780.93	215949.58	-8.66	WB
18855	3620781.27	215952.56	-8.66	WB
18856	3620781.58	215955.56	-8.66	WB
18857	3620781.85	215958.64	-8.65	WB
18858	3620782.12	215961.72	-8.65	WB
18859	3620782.32	215964.83	-8.65	WB
18860	3620782.51	215967.97	-8.64	WB
18861	3620782.61	215971.14	-8.64	WB
18862	3620782.63	215972.33	-8.64	WB
18863	3620782.66	215974.33	-8.63	WB
18864	3620782.73	215977.55	-8.63	WB
18865	3620782.84	215980.78	-8.63	WB
18866	3620782.96	215983.93	-8.62	WB
18867	3620782.98	215987.04	-8.62	WB
18868	3620782.97	215990.16	-8.62	WB
18869	3620782.98	215993.25	-8.62	WB
18870	3620783.00	215996.36	-8.61	WB
18871	3620783.01	215997.49	-8.61	WB
18872	3620783.02	215999.36	-8.61	WB
18873	3620783.04	216002.37	-8.61	WB
18874	3620783.05	216005.42	-8.61	WB
18875	3620783.05	216008.38	-8.60	WB
18876	3620783.04	216011.55	-8.60	WB
18877	3620783.03	216015.00	-8.60	WB
18878	3620783.05	216018.00	-8.60	WB
18879	3620783.07	216021.09	-8.60	WB
18880	3620783.14	216022.93	-8.59	WB
18881	3620783.22	216024.09	-8.59	WB
18882	3620783.42	216027.07	-8.59	WB
18883	3620783.62	216030.05	-8.59	WB
18884	3620783.80	216033.08	-8.59	WB
18885	3620783.99	216036.09	-8.59	WB
18886	3620784.22	216039.16	-8.58	WB
18887	3620784.47	216042.22	-8.58	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
18888	3620784.67	216045.27	-8.58	WB
18889	3620784.72	216047.17	-8.58	WB
18890	3620784.76	216048.43	-8.57	WB
18891	3620784.83	216051.50	-8.57	WB
18892	3620784.80	216054.62	-8.57	WB
18893	3620784.76	216057.77	-8.57	WB
18894	3620784.65	216060.77	-8.56	WB
18895	3620784.46	216063.81	-8.56	WB
18896	3620784.24	216066.92	-8.56	WB
18897	3620783.89	216069.87	-8.55	WB
18898	3620783.67	216071.74	-8.55	WB
18899	3620783.52	216072.90	-8.55	WB
18900	3620783.14	216075.90	-8.54	WB
18901	3620782.77	216078.80	-8.54	WB
18902	3620782.36	216081.83	-8.54	WB
18903	3620781.82	216084.69	-8.53	WB
18904	3620781.26	216087.62	-8.53	WB
18905	3620780.74	216090.64	-8.52	WB
18906	3620780.27	216093.60	-8.52	WB
18907	3620779.79	216096.65	-8.52	WB
18908	3620779.68	216097.38	-8.51	WB
18909	3620779.33	216099.73	-8.51	WB
18910	3620778.88	216102.77	-8.50	WB
18911	3620778.51	216105.89	-8.50	WB
18912	3620778.18	216109.08	-8.50	WB
18913	3620777.91	216112.13	-8.49	WB
18914	3620777.72	216115.19	-8.49	WB
18915	3620777.53	216118.30	-8.48	WB
18916	3620777.51	216121.29	-8.48	WB
18917	3620777.52	216122.76	-8.48	WB
18918	3620777.54	216124.31	-8.47	WB
18919	3620777.62	216127.21	-8.47	WB
18920	3620777.78	216130.08	-8.46	WB
18921	3620777.94	216133.04	-8.46	WB
18922	3620778.19	216136.04	-8.46	WB
18923	3620778.45	216138.95	-8.45	WB
18924	3620778.74	216141.96	-8.45	WB
18925	3620779.04	216144.96	-8.45	WB
18926	3620779.31	216147.62	-8.44	WB
18927	3620779.34	216147.98	-8.44	WB
18928	3620779.58	216151.08	-8.44	WB
18929	3620779.82	216154.18	-8.43	WB
18930	3620780.08	216157.27	-8.43	WB
18931	3620780.39	216160.42	-8.43	WB
18932	3620780.68	216163.65	-8.42	WB
18933	3620780.77	216166.97	-8.42	WB
18934	3620780.86	216170.35	-8.42	WB
18935	3620780.94	216172.75	-8.41	WB
18936	3620780.98	216173.58	-8.41	WB
18937	3620781.13	216176.79	-8.40	WB
18938	3620781.27	216180.13	-8.40	WB
18939	3620781.32	216183.32	-8.40	WB
18940	3620781.35	216186.52	-8.39	WB
18941	3620781.39	216189.88	-8.39	WB
18942	3620781.42	216193.13	-8.38	WB
18943	3620781.41	216196.47	-8.38	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
18944	3620781.35	216197.75	-8.38	WB
18945	3620781.26	216199.78	-8.37	WB
18946	3620781.12	216203.08	-8.37	WB
18947	3620781.06	216206.33	-8.37	WB
18948	3620781.03	216209.53	-8.36	WB
18949	3620781.04	216212.64	-8.36	WB
18950	3620781.11	216215.52	-8.35	WB
18951	3620781.19	216218.44	-8.35	WB
18952	3620781.30	216221.26	-8.35	WB
18953	3620781.34	216222.30	-8.35	WB
18954	3620781.41	216224.01	-8.34	WB
18955	3620781.50	216226.88	-8.34	WB
18956	3620781.58	216229.73	-8.34	WB
18957	3620781.63	216232.57	-8.33	WB
18958	3620781.57	216235.65	-8.33	WB
18959	3620781.51	216238.60	-8.33	WB
18960	3620781.50	216241.63	-8.33	WB
18961	3620781.55	216244.70	-8.32	WB
18962	3620781.60	216247.36	-8.32	WB
18963	3620781.61	216247.78	-8.32	WB
18964	3620781.66	216250.93	-8.32	WB
18965	3620781.71	216254.09	-8.32	WB
18966	3620781.78	216257.35	-8.31	WB
18967	3620781.85	216260.65	-8.31	WB
18968	3620781.91	216264.01	-8.31	WB
18969	3620781.99	216267.54	-8.31	WB
18970	3620782.07	216271.05	-8.30	WB
18971	3620782.11	216272.87	-8.30	WB
18972	3620782.14	216274.65	-8.30	WB
18973	3620782.22	216278.18	-8.30	WB
18974	3620782.32	216281.76	-8.29	WB
18975	3620782.45	216285.31	-8.29	WB
18976	3620782.59	216288.78	-8.29	WB
18977	3620782.71	216292.14	-8.29	WB
18978	3620782.82	216295.35	-8.28	WB
18979	3620782.89	216297.39	-8.28	WB
18980	3620782.93	216298.56	-8.27	WB
18981	3620783.04	216301.69	-8.27	WB
18982	3620783.15	216304.72	-8.27	WB
18983	3620783.19	216307.73	-8.26	WB
18984	3620783.20	216310.74	-8.26	WB
18985	3620783.16	216313.67	-8.25	WB
18986	3620783.04	216316.66	-8.25	WB
18987	3620782.92	216319.53	-8.25	WB
18988	3620782.78	216322.06	-8.24	WB
18989	3620782.76	216322.40	-8.24	WB
18990	3620782.61	216325.30	-8.23	WB
18991	3620782.42	216328.12	-8.23	WB
18992	3620782.18	216330.96	-8.22	WB
18993	3620781.91	216333.88	-8.22	WB
18994	3620781.60	216336.81	-8.21	WB
18995	3620781.27	216339.77	-8.21	WB
18996	3620780.96	216342.82	-8.20	WB
18997	3620780.66	216345.81	-8.20	WB
18998	3620780.54	216346.99	-8.20	WB
18999	3620780.35	216348.84	-8.19	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
19000	3620779.96	216351.98	-8.19	WB
19001	3620779.57	216355.04	-8.18	WB
19002	3620779.24	216358.17	-8.18	WB
19003	3620778.95	216361.31	-8.18	WB
19004	3620778.68	216364.37	-8.17	WB
19005	3620778.43	216367.58	-8.17	WB
19006	3620778.18	216370.74	-8.17	WB
19007	3620778.02	216372.77	-8.16	WB
19008	3620777.92	216373.96	-8.16	WB
19009	3620777.65	216377.30	-8.15	WB
19010	3620777.43	216380.62	-8.15	WB
19011	3620777.34	216383.93	-8.15	WB
19012	3620777.26	216387.34	-8.14	WB
19013	3620777.12	216390.77	-8.14	WB
19014	3620776.98	216394.19	-8.14	WB
19015	3620776.93	216397.67	-8.13	WB
19016	3620777.03	216401.20	-8.13	WB
19017	3620777.13	216404.61	-8.12	WB
19018	3620777.23	216408.12	-8.12	WB
19019	3620777.32	216411.69	-8.12	WB
19020	3620777.45	216415.06	-8.11	WB
19021	3620777.62	216418.54	-8.11	WB
19022	3620777.81	216421.98	-8.10	WB
19023	3620777.86	216422.73	-8.10	WB
19024	3620778.04	216425.10	-8.09	WB
19025	3620778.28	216428.33	-8.09	WB
19026	3620778.48	216431.42	-8.08	WB
19027	3620778.67	216434.45	-8.08	WB
19028	3620778.88	216437.47	-8.07	WB
19029	3620779.22	216440.33	-8.07	WB
19030	3620779.55	216443.19	-8.06	WB
19031	3620779.83	216446.06	-8.06	WB
19032	3620779.98	216447.86	-8.05	WB
19033	3620780.07	216448.93	-8.05	WB
19034	3620780.35	216451.82	-8.04	WB
19035	3620780.71	216454.81	-8.04	WB
19036	3620781.06	216457.69	-8.03	WB
19037	3620781.37	216460.66	-8.03	WB
19038	3620781.67	216463.82	-8.02	WB
19039	3620781.96	216466.84	-8.02	WB
19040	3620782.28	216470.03	-8.01	WB
19041	3620782.57	216472.81	-8.01	WB
19042	3620782.61	216473.24	-8.00	WB
19043	3620782.99	216476.37	-8.00	WB
19044	3620783.38	216479.55	-8.00	WB
19045	3620783.74	216482.80	-7.99	WB
19046	3620784.05	216485.99	-7.99	WB
19047	3620784.37	216489.22	-7.98	WB
19048	3620784.75	216492.31	-7.98	WB
19049	3620785.16	216495.36	-7.98	WB
19050	3620785.46	216497.69	-7.97	WB
19051	3620785.53	216498.40	-7.97	WB
19052	3620785.82	216501.40	-7.97	WB
19053	3620786.09	216504.34	-7.97	WB
19054	3620786.32	216507.29	-7.96	WB
19055	3620786.56	216510.25	-7.96	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
19056	3620786.69	216513.13	-7.96	WB
19057	3620786.73	216516.05	-7.95	WB
19058	3620786.77	216519.01	-7.95	WB
19059	3620786.77	216521.94	-7.95	WB
19060	3620786.77	216522.35	-7.94	WB
19061	3620786.77	216524.93	-7.94	WB
19062	3620786.74	216527.95	-7.94	WB
19063	3620786.69	216530.98	-7.93	WB
19064	3620786.64	216534.08	-7.93	WB
19065	3620786.52	216537.44	-7.93	WB
19066	3620786.41	216540.79	-7.92	WB
19067	3620786.29	216544.06	-7.92	WB
19068	3620786.16	216547.42	-7.92	WB
19069	3620786.06	216550.80	-7.91	WB
19070	3620785.99	216554.01	-7.91	WB
19071	3620785.93	216557.31	-7.90	WB
19072	3620785.84	216560.51	-7.90	WB
19073	3620785.74	216563.66	-7.89	WB
19074	3620785.65	216566.89	-7.89	WB
19075	3620785.57	216570.04	-7.88	WB
19076	3620785.50	216572.76	-7.88	WB
19077	3620785.49	216573.13	-7.87	WB
19078	3620785.45	216576.28	-7.87	WB
19079	3620785.41	216579.44	-7.86	WB
19080	3620785.40	216582.52	-7.86	WB
19081	3620785.41	216585.63	-7.85	WB
19082	3620785.43	216588.79	-7.85	WB
19083	3620785.43	216591.80	-7.84	WB
19084	3620785.43	216594.88	-7.84	WB
19085	3620785.47	216597.55	-7.83	WB
19086	3620785.48	216597.95	-7.83	WB
19087	3620785.56	216600.93	-7.82	WB
19088	3620785.64	216603.95	-7.82	WB
19089	3620785.63	216606.97	-7.81	WB
19090	3620785.61	216609.90	-7.81	WB
19091	3620785.64	216612.82	-7.80	WB
19092	3620785.72	216615.73	-7.80	WB
19093	3620785.77	216618.52	-7.79	WB
19094	3620785.73	216621.36	-7.79	WB
19095	3620785.71	216622.08	-7.79	WB
19096	3620785.66	216624.25	-7.78	WB
19097	3620785.64	216627.10	-7.78	WB
19098	3620785.65	216629.98	-7.78	WB
19099	3620785.63	216632.96	-7.77	WB
19100	3620785.54	216635.97	-7.77	WB
19101	3620785.45	216639.04	-7.77	WB
19102	3620785.34	216642.35	-7.76	WB
19103	3620785.23	216645.55	-7.76	WB
19104	3620785.17	216647.59	-7.76	WB
19105	3620785.15	216648.91	-7.76	WB
19106	3620785.10	216652.33	-7.75	WB
19107	3620785.07	216655.69	-7.75	WB
19108	3620784.97	216659.22	-7.75	WB
19109	3620784.86	216662.73	-7.74	WB
19110	3620784.78	216666.26	-7.74	WB
19111	3620784.72	216669.77	-7.74	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
19112	3620784.68	216672.40	-7.73	WB
19113	3620784.67	216673.29	-7.73	WB
19114	3620784.50	216676.79	-7.73	WB
19115	3620784.31	216680.28	-7.72	WB
19116	3620784.13	216683.67	-7.72	WB
19117	3620783.96	216686.96	-7.71	WB
19118	3620783.79	216690.27	-7.71	WB
19119	3620783.60	216693.28	-7.70	WB
19120	3620783.40	216696.33	-7.70	WB
19121	3620783.35	216697.11	-7.69	WB
19122	3620783.18	216699.31	-7.69	WB
19123	3620782.96	216702.14	-7.68	WB
19124	3620782.73	216705.01	-7.68	WB
19125	3620782.50	216707.87	-7.67	WB
19126	3620782.27	216710.65	-7.67	WB
19127	3620782.02	216713.54	-7.66	WB
19128	3620781.77	216716.40	-7.66	WB
19129	3620781.51	216719.27	-7.65	WB
19130	3620781.26	216721.93	-7.64	WB
19131	3620781.22	216722.29	-7.64	WB
19132	3620780.93	216725.28	-7.63	WB
19133	3620780.61	216728.45	-7.63	WB
19134	3620780.28	216731.61	-7.62	WB
19135	3620779.97	216734.80	-7.62	WB
19136	3620779.67	216738.10	-7.61	WB
19137	3620779.38	216741.41	-7.61	WB
19138	3620779.11	216744.77	-7.61	WB
19139	3620778.92	216747.31	-7.60	WB
19140	3620778.86	216748.11	-7.60	WB
19141	3620778.65	216751.47	-7.60	WB
19142	3620778.50	216754.64	-7.59	WB
19143	3620778.37	216757.84	-7.59	WB
19144	3620778.41	216760.92	-7.59	WB
19145	3620778.46	216763.89	-7.58	WB
19146	3620778.49	216766.92	-7.58	WB
19147	3620778.46	216769.96	-7.58	WB
19148	3620778.45	216772.56	-7.58	WB
19149	3620778.45	216772.92	-7.58	WB
19150	3620778.55	216776.00	-7.57	WB
19151	3620778.64	216779.04	-7.57	WB
19152	3620778.68	216782.12	-7.57	WB
19153	3620778.67	216785.38	-7.57	WB
19154	3620778.67	216788.58	-7.57	WB
19155	3620778.77	216791.89	-7.57	WB
19156	3620778.89	216795.27	-7.56	WB
19157	3620778.98	216797.74	-7.56	WB
19158	3620779.01	216798.66	-7.56	WB
19159	3620779.14	216802.03	-7.56	WB
19160	3620779.30	216805.38	-7.55	WB
19161	3620779.53	216808.79	-7.55	WB
19162	3620779.76	216812.19	-7.55	WB
19163	3620779.92	216815.67	-7.54	WB
19164	3620780.07	216819.10	-7.54	WB
19165	3620780.23	216822.62	-7.54	WB
19166	3620780.39	216826.14	-7.53	WB
19167	3620780.57	216829.54	-7.53	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
19168	3620780.73	216832.91	-7.52	WB
19169	3620780.90	216836.32	-7.52	WB
19170	3620781.05	216839.57	-7.51	WB
19171	3620781.20	216842.84	-7.51	WB
19172	3620781.35	216846.06	-7.50	WB
19173	3620781.37	216847.57	-7.50	WB
19174	3620781.38	216849.13	-7.49	WB
19175	3620781.41	216852.33	-7.49	WB
19176	3620781.41	216855.41	-7.48	WB
19177	3620781.40	216858.41	-7.47	WB
19178	3620781.38	216861.41	-7.47	WB
19179	3620781.31	216864.30	-7.46	WB
19180	3620781.23	216867.20	-7.46	WB
19181	3620781.14	216870.07	-7.45	WB
19182	3620781.06	216872.23	-7.44	WB
19183	3620781.04	216872.91	-7.44	WB
19184	3620780.93	216875.78	-7.43	WB
19185	3620780.84	216878.62	-7.43	WB
19186	3620780.76	216881.38	-7.42	WB
19187	3620780.66	216884.17	-7.42	WB
19188	3620780.56	216887.07	-7.41	WB
19189	3620780.48	216889.87	-7.41	WB
19190	3620780.47	216892.79	-7.41	WB
19191	3620780.46	216895.75	-7.40	WB
19192	3620780.45	216897.63	-7.40	WB
19193	3620780.46	216898.73	-7.40	WB
19194	3620780.46	216901.85	-7.39	WB
19195	3620780.51	216904.98	-7.39	WB
19196	3620780.65	216908.20	-7.39	WB
19197	3620780.79	216911.50	-7.38	WB
19198	3620781.03	216914.91	-7.38	WB
19199	3620781.28	216918.36	-7.38	WB
19200	3620781.56	216921.90	-7.37	WB
19201	3620781.68	216923.27	-7.37	WB
19202	3620781.88	216925.57	-7.37	WB
19203	3620782.19	216929.18	-7.37	WB
19204	3620782.64	216932.90	-7.36	WB
19205	3620783.10	216936.55	-7.36	WB
19206	3620783.58	216940.08	-7.36	WB
19207	3620784.07	216943.59	-7.35	WB
19208	3620784.56	216946.97	-7.35	WB
19209	3620784.76	216948.14	-7.34	WB
19210	3620785.09	216950.12	-7.34	WB
19211	3620785.62	216953.32	-7.34	WB
19212	3620786.09	216956.35	-7.33	WB
19213	3620786.51	216959.32	-7.33	WB
19214	3620786.92	216962.33	-7.32	WB
19215	3620787.21	216965.14	-7.32	WB
19216	3620787.50	216968.05	-7.31	WB
19217	3620787.74	216970.87	-7.30	WB
19218	3620787.85	216972.24	-7.30	WB
19219	3620787.96	216973.60	-7.29	WB
19220	3620788.13	216976.38	-7.29	WB
19221	3620788.17	216979.12	-7.28	WB
19222	3620788.20	216981.88	-7.27	WB
19223	3620788.17	216984.66	-7.27	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
19224	3620788.12	216987.46	-7.26	WB
19225	3620788.07	216990.30	-7.25	WB
19226	3620788.04	216993.22	-7.25	WB
19227	3620788.00	216996.14	-7.24	WB
19228	3620787.98	216997.64	-7.23	WB
19229	3620787.95	216999.21	-7.23	WB
19230	3620787.90	217002.34	-7.22	WB
19231	3620787.88	217005.45	-7.21	WB
19232	3620787.90	217008.72	-7.20	WB
19233	3620787.93	217012.04	-7.20	WB
19234	3620787.92	217015.38	-7.19	WB
19235	3620787.91	217018.78	-7.18	WB
19236	3620787.94	217022.23	-7.18	WB
19237	3620787.94	217022.64	-7.17	WB
19238	3620787.99	217025.56	-7.16	WB
19239	3620788.05	217028.99	-7.16	WB
19240	3620788.09	217032.29	-7.15	WB
19241	3620788.13	217035.56	-7.14	WB
19242	3620788.19	217038.85	-7.13	WB
19243	3620788.27	217042.06	-7.13	WB
19244	3620788.34	217045.23	-7.12	WB
19245	3620788.32	217047.54	-7.11	WB
19246	3620788.32	217048.32	-7.11	WB
19247	3620788.30	217051.40	-7.10	WB
19248	3620788.32	217054.46	-7.10	WB
19249	3620788.35	217057.44	-7.09	WB
19250	3620788.38	217060.41	-7.08	WB
19251	3620788.35	217063.35	-7.08	WB
19252	3620788.31	217066.36	-7.07	WB
19253	3620788.26	217069.30	-7.06	WB
19254	3620788.21	217072.29	-7.06	WB
19255	3620788.13	217075.33	-7.05	WB
19256	3620788.00	217078.34	-7.05	WB
19257	3620787.87	217081.41	-7.04	WB
19258	3620787.70	217084.54	-7.03	WB
19259	3620787.54	217087.58	-7.03	WB
19260	3620787.37	217090.64	-7.02	WB
19261	3620787.21	217093.72	-7.02	WB
19262	3620787.06	217096.70	-7.01	WB
19263	3620787.04	217097.09	-7.00	WB
19264	3620786.92	217099.64	-7.00	WB
19265	3620786.77	217102.64	-6.99	WB
19266	3620786.66	217105.56	-6.99	WB
19267	3620786.58	217108.51	-6.98	WB
19268	3620786.49	217111.50	-6.98	WB
19269	3620786.38	217114.52	-6.97	WB
19270	3620786.26	217117.61	-6.96	WB
19271	3620786.10	217120.88	-6.96	WB
19272	3620786.01	217122.52	-6.95	WB
19273	3620785.92	217124.16	-6.95	WB
19274	3620785.73	217127.53	-6.94	WB
19275	3620785.51	217131.16	-6.93	WB
19276	3620785.29	217134.68	-6.93	WB
19277	3620785.05	217138.37	-6.92	WB
19278	3620784.80	217142.14	-6.91	WB
19279	3620784.55	217145.81	-6.91	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
19280	3620784.45	217147.24	-6.90	WB
19281	3620784.29	217149.51	-6.89	WB
19282	3620784.04	217153.27	-6.88	WB
19283	3620783.80	217156.73	-6.88	WB
19284	3620783.55	217160.23	-6.87	WB
19285	3620783.32	217163.67	-6.86	WB
19286	3620783.13	217166.81	-6.85	WB
19287	3620782.94	217169.99	-6.84	WB
19288	3620782.81	217171.90	-6.84	WB
19289	3620782.73	217172.99	-6.83	WB
19290	3620782.50	217175.88	-6.82	WB
19291	3620782.26	217178.77	-6.81	WB
19292	3620782.00	217181.58	-6.81	WB
19293	3620781.73	217184.32	-6.80	WB
19294	3620781.46	217187.13	-6.79	WB
19295	3620781.18	217189.84	-6.78	WB
19296	3620780.89	217192.60	-6.78	WB
19297	3620780.59	217195.40	-6.77	WB
19298	3620780.40	217197.14	-6.76	WB
19299	3620780.29	217198.14	-6.76	WB
19300	3620780.05	217201.07	-6.75	WB
19301	3620779.82	217203.95	-6.74	WB
19302	3620779.65	217206.92	-6.74	WB
19303	3620779.54	217210.06	-6.73	WB
19304	3620779.44	217213.22	-6.73	WB
19305	3620779.43	217216.55	-6.72	WB
19306	3620779.44	217219.86	-6.71	WB
19307	3620779.57	217223.30	-6.71	WB
19308	3620779.77	217226.80	-6.70	WB
19309	3620780.00	217230.32	-6.70	WB
19310	3620780.32	217233.87	-6.69	WB
19311	3620780.65	217237.51	-6.68	WB
19312	3620781.07	217241.06	-6.68	WB
19313	3620781.52	217244.59	-6.67	WB
19314	3620781.97	217248.07	-6.67	WB
19315	3620782.41	217251.50	-6.66	WB
19316	3620782.86	217254.87	-6.65	WB
19317	3620783.37	217258.25	-6.64	WB
19318	3620783.88	217261.45	-6.64	WB
19319	3620784.37	217264.60	-6.63	WB
19320	3620784.83	217267.80	-6.62	WB
19321	3620785.26	217270.86	-6.61	WB
19322	3620785.42	217272.33	-6.60	WB
19323	3620785.59	217273.83	-6.59	WB
19324	3620785.93	217276.97	-6.58	WB
19325	3620786.20	217280.01	-6.57	WB
19326	3620786.43	217283.16	-6.56	WB
19327	3620786.65	217286.28	-6.55	WB
19328	3620786.81	217289.43	-6.54	WB
19329	3620786.96	217292.69	-6.53	WB
19330	3620787.08	217295.92	-6.52	WB
19331	3620787.13	217297.53	-6.51	WB
19332	3620787.18	217299.19	-6.50	WB
19333	3620787.30	217302.41	-6.49	WB
19334	3620787.52	217305.48	-6.48	WB
19335	3620787.75	217308.46	-6.47	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
19336	3620788.05	217311.35	-6.45	WB
19337	3620788.38	217314.25	-6.44	WB
19338	3620788.68	217317.06	-6.43	WB
19339	3620788.91	217319.86	-6.42	WB
19340	3620789.10	217322.34	-6.41	WB
19341	3620789.13	217322.72	-6.40	WB
19342	3620789.33	217325.49	-6.39	WB
19343	3620789.55	217328.37	-6.38	WB
19344	3620789.74	217331.11	-6.37	WB
19345	3620789.88	217333.88	-6.36	WB
19346	3620790.03	217336.77	-6.35	WB
19347	3620790.16	217339.54	-6.34	WB
19348	3620790.30	217342.41	-6.33	WB
19349	3620790.39	217345.26	-6.32	WB
19350	3620790.41	217347.02	-6.31	WB
19351	3620790.42	217348.10	-6.30	WB
19352	3620790.45	217351.02	-6.29	WB
19353	3620790.45	217354.02	-6.28	WB
19354	3620790.44	217357.03	-6.27	WB
19355	3620790.34	217360.16	-6.26	WB
19356	3620790.14	217363.44	-6.25	WB
19357	3620789.93	217366.77	-6.24	WB
19358	3620789.61	217370.43	-6.23	WB
19359	3620789.45	217372.29	-6.22	WB
19360	3620789.30	217374.09	-6.21	WB
19361	3620788.93	217377.86	-6.19	WB
19362	3620788.52	217381.79	-6.18	WB
19363	3620788.11	217385.78	-6.17	WB
19364	3620787.72	217389.69	-6.16	WB
19365	3620787.35	217393.70	-6.14	WB
19366	3620787.04	217397.51	-6.13	WB
19367	3620786.76	217401.24	-6.11	WB
19368	3620786.48	217405.04	-6.10	WB
19369	3620786.19	217408.50	-6.08	WB
19370	3620785.92	217411.90	-6.06	WB
19371	3620785.65	217415.24	-6.05	WB
19372	3620785.39	217418.49	-6.03	WB
19373	3620785.09	217421.62	-6.01	WB
19374	3620784.68	217424.73	-5.99	WB
19375	3620784.25	217427.82	-5.97	WB
19376	3620783.83	217430.76	-5.95	WB
19377	3620783.41	217433.71	-5.92	WB
19378	3620782.97	217436.63	-5.90	WB
19379	3620782.50	217439.44	-5.88	WB
19380	3620782.01	217442.35	-5.86	WB
19381	3620781.50	217445.15	-5.84	WB
19382	3620781.17	217446.89	-5.82	WB
19383	3620780.99	217447.89	-5.79	WB
19384	3620780.49	217450.73	-5.77	WB
19385	3620780.04	217453.48	-5.75	WB
19386	3620779.58	217456.24	-5.72	WB
19387	3620779.11	217458.99	-5.70	WB
19388	3620778.65	217461.74	-5.68	WB
19389	3620778.22	217464.50	-5.65	WB
19390	3620777.81	217467.28	-5.63	WB
19391	3620777.41	217470.05	-5.61	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
19392	3620777.13	217471.83	-5.58	WB
19393	3620776.96	217472.89	-5.56	WB
19394	3620776.51	217475.79	-5.54	WB
19395	3620776.09	217478.64	-5.52	WB
19396	3620775.67	217481.55	-5.50	WB
19397	3620775.23	217484.54	-5.49	WB
19398	3620774.77	217487.51	-5.47	WB
19399	3620774.29	217490.54	-5.45	WB
19400	3620773.83	217493.70	-5.44	WB
19401	3620773.40	217496.82	-5.42	WB
19402	3620773.34	217497.25	-5.41	WB
19403	3620772.97	217500.07	-5.40	WB
19404	3620772.59	217503.34	-5.39	WB
19405	3620772.20	217506.57	-5.38	WB
19406	3620771.96	217509.97	-5.37	WB
19407	3620771.74	217513.33	-5.37	WB
19408	3620771.60	217516.73	-5.37	WB
19409	3620771.56	217520.20	-5.36	WB
19410	3620771.52	217523.23	-5.36	WB
19411	3620771.52	217523.70	-5.36	WB
19412	3620771.64	217527.31	-5.36	WB
19413	3620771.79	217531.00	-5.36	WB
19414	3620772.02	217534.76	-5.36	WB
19415	3620772.36	217538.59	-5.36	WB
19416	3620772.73	217542.47	-5.36	WB
19417	3620773.39	217546.31	-5.36	WB
19418	3620773.88	217549.10	-5.37	WB
19419	3620774.04	217549.99	-5.38	WB
19420	3620774.80	217553.66	-5.38	WB
19421	3620775.60	217557.17	-5.38	WB
19422	3620776.42	217560.60	-5.38	WB
19423	3620777.34	217563.81	-5.37	WB
19424	3620778.26	217566.93	-5.34	WB
19425	3620779.12	217569.84	-5.30	WB
19426	3620779.97	217572.67	-5.29	WB
19427	3620780.07	217573.00	-5.28	WB
19428	3620780.81	217575.49	-5.24	WB
19429	3620781.53	217578.16	-5.22	WB
19430	3620782.26	217580.84	-5.18	WB
19431	3620782.83	217583.43	-5.13	WB
19432	3620783.34	217586.04	-5.09	WB
19433	3620783.78	217588.70	-5.03	WB
19434	3620784.03	217591.23	-5.01	WB
19435	3620784.26	217593.83	-4.98	WB
19436	3620784.43	217596.47	-4.92	WB
19437	3620784.45	217596.78	-4.88	WB
19438	3620784.58	217599.00	-4.82	WB
19439	3620784.66	217601.52	-4.79	WB
19440	3620784.62	217604.07	-4.77	WB
19441	3620784.57	217606.59	-4.74	WB
19442	3620784.49	217609.09	-4.72	WB
19443	3620784.40	217611.60	-4.69	WB
19444	3620784.27	217614.03	-4.66	WB
19445	3620784.08	217616.55	-4.64	WB
19446	3620783.89	217619.05	-4.64	WB
19447	3620783.69	217621.63	-4.66	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
19448	3620783.67	217621.94	-4.66	WB
19449	3620783.51	217624.20	-4.66	WB
19450	3620783.30	217626.85	-4.67	WB
19451	3620783.07	217629.58	-4.70	WB
19452	3620782.83	217632.32	-4.74	WB
19453	3620782.56	217635.30	-4.80	WB
19454	3620782.29	217638.26	-4.86	WB
19455	3620782.00	217641.52	-4.91	WB
19456	3620781.72	217644.77	-4.98	WB
19457	3620781.50	217647.27	-5.06	WB
19458	3620781.43	217648.13	-5.14	WB
19459	3620781.09	217651.84	-5.23	WB
19460	3620780.76	217655.46	-5.31	WB
19461	3620780.48	217659.37	-5.38	WB
19462	3620780.20	217663.41	-5.42	WB
19463	3620779.95	217667.38	-5.47	WB
19464	3620779.71	217671.63	-5.50	WB
19465	3620779.66	217672.62	-5.53	WB
19466	3620779.49	217675.80	-5.54	WB
19467	3620779.36	217679.84	-5.56	WB
19468	3620779.24	217684.04	-5.54	WB
19469	3620779.16	217688.12	-5.53	WB
19470	3620779.14	217692.12	-5.51	WB
19471	3620779.11	217696.18	-5.51	WB
19472	3620779.12	217697.58	-5.50	WB
19473	3620779.15	217700.00	-5.50	WB
19474	3620779.20	217703.87	-5.50	WB
19475	3620779.26	217707.66	-5.50	WB
19476	3620779.35	217711.30	-5.49	WB
19477	3620779.43	217714.95	-5.48	WB
19478	3620779.55	217718.42	-5.47	WB
19479	3620779.67	217721.82	-5.48	WB
19480	3620779.70	217722.70	-5.49	WB
19481	3620779.83	217725.16	-5.49	WB
19482	3620780.04	217728.40	-5.48	WB
19483	3620780.24	217731.52	-5.49	WB
19484	3620780.49	217734.52	-5.51	WB
19485	3620780.75	217737.56	-5.53	WB
19486	3620781.05	217740.46	-5.57	WB
19487	3620781.39	217743.35	-5.59	WB
19488	3620781.73	217746.26	-5.61	WB
19489	3620781.90	217747.67	-5.62	WB
19490	3620782.08	217749.08	-5.64	WB
19491	3620782.42	217751.99	-5.68	WB
19492	3620782.81	217754.84	-5.67	WB
19493	3620783.21	217757.63	-5.67	WB
19494	3620783.64	217760.50	-5.66	WB
19495	3620784.10	217763.37	-5.63	WB
19496	3620784.57	217766.24	-5.61	WB
19497	3620785.04	217769.13	-5.59	WB
19498	3620785.53	217772.02	-5.57	WB
19499	3620785.65	217772.74	-5.53	WB
19500	3620786.00	217774.88	-5.49	WB
19501	3620786.48	217777.77	-5.46	WB
19502	3620786.96	217780.55	-5.42	WB
19503	3620787.40	217783.41	-5.40	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
19504	3620787.85	217786.29	-5.39	WB
19505	3620788.22	217789.06	-5.39	WB
19506	3620788.53	217791.87	-5.39	WB
19507	3620788.85	217794.75	-5.39	WB
19508	3620789.01	217797.24	-5.41	WB
19509	3620789.04	217797.63	-5.44	WB
19510	3620789.23	217800.53	-5.48	WB
19511	3620789.35	217803.47	-5.51	WB
19512	3620789.40	217806.43	-5.54	WB
19513	3620789.43	217809.73	-5.58	WB
19514	3620789.37	217812.71	-5.60	WB
19515	3620789.29	217815.74	-5.62	WB
19516	3620789.16	217818.70	-5.64	WB
19517	3620789.00	217821.77	-5.64	WB
19518	3620788.81	217824.84	-5.64	WB
19519	3620788.57	217827.92	-5.63	WB
19520	3620788.32	217831.10	-5.60	WB
19521	3620787.98	217834.40	-5.57	WB
19522	3620787.61	217837.69	-5.53	WB
19523	3620787.18	217841.19	-5.51	WB
19524	3620786.67	217844.80	-5.47	WB
19525	3620786.42	217846.58	-5.42	WB
19526	3620786.15	217848.42	-5.40	WB
19527	3620785.58	217852.25	-5.36	WB
19528	3620784.99	217856.10	-5.33	WB
19529	3620784.44	217859.98	-5.31	WB
19530	3620783.92	217863.89	-5.29	WB
19531	3620783.41	217867.81	-5.27	WB
19532	3620783.03	217871.65	-5.26	WB
19533	3620782.99	217872.12	-5.23	WB
19534	3620782.64	217875.60	-5.21	WB
19535	3620782.37	217879.30	-5.18	WB
19536	3620782.15	217882.96	-5.14	WB
19537	3620781.92	217886.70	-5.09	WB
19538	3620781.71	217890.04	-5.02	WB
19539	3620781.50	217893.49	-4.95	WB
19540	3620781.32	217896.64	-4.86	WB
19541	3620781.30	217897.01	-4.76	WB
19542	3620781.17	217899.62	-4.66	WB
19543	3620781.05	217902.60	-4.56	WB
19544	3620781.01	217905.25	-4.47	WB
19545	3620780.97	217907.85	-4.38	WB
19546	3620780.94	217910.32	-4.29	WB
19547	3620780.91	217912.73	-4.22	WB
19548	3620780.88	217915.12	-4.14	WB
19549	3620780.89	217917.41	-4.06	WB
19550	3620780.89	217919.70	-3.99	WB
19551	3620780.90	217922.02	-3.92	WB
19552	3620780.91	217924.33	-3.85	WB
19553	3620780.90	217926.65	-3.79	WB
19554	3620780.85	217929.05	-3.73	WB
19555	3620780.81	217931.48	-3.67	WB
19556	3620780.76	217934.01	-3.61	WB
19557	3620780.72	217936.57	-3.56	WB
19558	3620780.61	217939.29	-3.51	WB
19559	3620780.44	217942.02	-3.47	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
19560	3620780.25	217944.88	-3.43	WB
19561	3620780.12	217946.76	-3.39	WB
19562	3620780.04	217947.88	-3.35	WB
19563	3620779.82	217950.84	-3.33	WB
19564	3620779.51	217953.92	-3.31	WB
19565	3620779.14	217957.03	-3.27	WB
19566	3620778.76	217960.10	-3.24	WB
19567	3620778.36	217963.33	-3.21	WB
19568	3620777.96	217966.52	-3.18	WB
19569	3620777.51	217969.72	-3.16	WB
19570	3620777.21	217971.73	-3.15	WB
19571	3620777.02	217972.97	-3.15	WB
19572	3620776.55	217976.15	-3.18	WB
19573	3620776.12	217979.37	-3.22	WB
19574	3620775.68	217982.65	-3.24	WB
19575	3620775.33	217985.86	-3.23	WB
19576	3620774.99	217989.07	-3.26	WB
19577	3620774.71	217992.26	-3.29	WB
19578	3620774.54	217995.44	-3.31	WB
19579	3620774.44	217997.43	-3.32	WB
19580	3620774.38	217998.62	-3.35	WB
19581	3620774.40	218001.74	-3.39	WB
19582	3620774.45	218004.81	-3.44	WB
19583	3620774.59	218007.90	-3.50	WB
19584	3620774.84	218010.84	-3.56	WB
19585	3620775.11	218013.86	-3.62	WB
19586	3620775.48	218016.78	-3.67	WB
19587	3620775.85	218019.61	-3.72	WB
19588	3620776.30	218022.56	-3.78	WB
19589	3620776.35	218022.90	-3.83	WB
19590	3620776.77	218025.36	-3.90	WB
19591	3620777.25	218028.23	-3.97	WB
19592	3620777.74	218031.18	-4.04	WB
19593	3620778.20	218034.04	-4.12	WB
19594	3620778.69	218037.05	-4.20	WB
19595	3620779.17	218040.07	-4.27	WB
19596	3620779.66	218043.06	-4.33	WB
19597	3620780.23	218046.32	-4.38	WB
19598	3620780.51	218047.89	-4.47	WB
19599	3620780.79	218049.52	-4.52	WB
19600	3620781.37	218052.87	-4.56	WB
19601	3620781.96	218056.38	-4.56	WB
19602	3620782.55	218059.90	-4.53	WB
19603	3620783.19	218063.52	-4.51	WB
19604	3620783.83	218067.20	-4.48	WB
19605	3620784.48	218070.97	-4.41	WB
19606	3620784.88	218073.29	-4.31	WB
19607	3620785.11	218074.61	-4.18	WB
19608	3620785.78	218078.22	-4.03	WB
19609	3620786.51	218081.78	-3.93	WB
19610	3620787.23	218085.20	-3.83	WB
19611	3620787.87	218088.61	-3.76	WB
19612	3620788.48	218091.81	-3.71	WB
19613	3620789.02	218094.94	-3.66	WB
19614	3620789.33	218097.21	-3.62	WB
19615	3620789.45	218098.04	-3.60	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
19616	3620789.86	218101.04	-3.61	WB
19617	3620790.04	218103.93	-3.60	WB
19618	3620790.19	218106.79	-3.56	WB
19619	3620790.20	218109.57	-3.57	WB
19620	3620790.07	218112.34	-3.57	WB
19621	3620789.90	218115.10	-3.53	WB
19622	3620789.55	218117.64	-3.49	WB
19623	3620789.17	218120.31	-3.43	WB
19624	3620788.98	218121.55	-3.37	WB
19625	3620788.75	218122.71	-3.33	WB
19626	3620788.27	218125.13	-3.28	WB
19627	3620787.80	218127.45	-3.25	WB
19628	3620787.37	218129.51	-3.19	WB
19629	3620786.94	218131.61	-3.12	WB
19630	3620786.49	218133.51	-3.04	WB
19631	3620786.04	218135.36	-3.00	WB
19632	3620785.59	218137.16	-2.98	WB
19633	3620785.14	218138.85	-2.94	WB
19634	3620784.71	218140.50	-2.90	WB
19635	3620784.23	218142.12	-2.86	WB
19636	3620783.74	218143.70	-2.84	WB
19637	3620783.44	218144.69	-2.81	WB
19638	3620288.22	215795.46	-8.96	WB
19639	3620288.16	215798.55	-8.97	WB
19640	3620288.11	215801.66	-8.97	WB
19641	3620288.15	215804.71	-8.98	WB
19642	3620288.25	215807.72	-8.98	WB
19643	3620288.34	215810.72	-8.99	WB
19644	3620288.35	215813.76	-8.99	WB
19645	3620288.35	215816.71	-9.00	WB
19646	3620288.34	215819.66	-9.00	WB
19647	3620288.32	215822.74	-9.00	WB
19648	3620288.26	215825.80	-9.01	WB
19649	3620288.04	215828.87	-9.01	WB
19650	3620287.79	215832.07	-9.02	WB
19651	3620287.41	215835.31	-9.02	WB
19652	3620287.00	215838.50	-9.02	WB
19653	3620286.63	215841.35	-9.02	WB
19654	3620286.58	215841.75	-9.03	WB
19655	3620286.15	215845.16	-9.03	WB
19656	3620285.74	215848.48	-9.03	WB
19657	3620285.32	215851.88	-9.03	WB
19658	3620284.88	215855.38	-9.03	WB
19659	3620284.49	215858.84	-9.03	WB
19660	3620284.16	215862.43	-9.04	WB
19661	3620283.83	215865.95	-9.04	WB
19662	3620283.77	215866.80	-9.04	WB
19663	3620283.59	215869.48	-9.03	WB
19664	3620283.35	215873.13	-9.03	WB
19665	3620283.14	215876.79	-9.03	WB
19666	3620282.96	215880.44	-9.03	WB
19667	3620282.80	215884.16	-9.03	WB
19668	3620282.75	215887.85	-9.03	WB
19669	3620282.72	215891.47	-9.02	WB
19670	3620282.72	215891.96	-9.02	WB
19671	3620282.73	215895.02	-9.02	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
19672	3620282.79	215898.58	-9.01	WB
19673	3620282.87	215901.99	-9.01	WB
19674	3620283.06	215905.24	-9.01	WB
19675	3620283.25	215908.55	-9.00	WB
19676	3620283.34	215911.72	-9.00	WB
19677	3620283.38	215914.97	-8.99	WB
19678	3620283.40	215916.61	-8.99	WB
19679	3620283.40	215918.19	-8.98	WB
19680	3620283.33	215921.34	-8.98	WB
19681	3620283.28	215924.57	-8.97	WB
19682	3620283.13	215927.72	-8.97	WB
19683	3620282.94	215930.76	-8.96	WB
19684	3620282.72	215933.81	-8.95	WB
19685	3620282.45	215936.81	-8.95	WB
19686	3620282.16	215939.82	-8.94	WB
19687	3620282.02	215941.28	-8.94	WB
19688	3620281.88	215942.76	-8.93	WB
19689	3620281.57	215945.73	-8.93	WB
19690	3620281.30	215948.62	-8.92	WB
19691	3620281.05	215951.56	-8.92	WB
19692	3620280.78	215954.56	-8.91	WB
19693	3620280.53	215957.56	-8.91	WB
19694	3620280.28	215960.65	-8.90	WB
19695	3620280.05	215963.79	-8.90	WB
19696	3620279.86	215966.56	-8.90	WB
19697	3620279.84	215966.94	-8.89	WB
19698	3620279.63	215970.19	-8.89	WB
19699	3620279.39	215973.52	-8.89	WB
19700	3620279.17	215976.80	-8.88	WB
19701	3620279.00	215980.17	-8.88	WB
19702	3620278.88	215983.49	-8.88	WB
19703	3620278.77	215986.80	-8.88	WB
19704	3620278.75	215990.03	-8.87	WB
19705	3620278.74	215992.07	-8.87	WB
19706	3620278.73	215993.29	-8.87	WB
19707	3620278.78	215996.51	-8.87	WB
19708	3620278.90	215999.70	-8.87	WB
19709	3620278.99	216002.97	-8.87	WB
19710	3620279.07	216006.28	-8.87	WB
19711	3620279.15	216009.65	-8.87	WB
19712	3620279.23	216012.93	-8.86	WB
19713	3620279.31	216016.31	-8.86	WB
19714	3620279.33	216017.17	-8.86	WB
19715	3620279.40	216019.76	-8.86	WB
19716	3620279.48	216023.14	-8.86	WB
19717	3620279.56	216026.50	-8.86	WB
19718	3620279.68	216030.04	-8.86	WB
19719	3620279.80	216033.38	-8.86	WB
19720	3620279.96	216036.78	-8.86	WB
19721	3620280.20	216040.15	-8.86	WB
19722	3620280.32	216041.86	-8.86	WB
19723	3620280.43	216043.53	-8.86	WB
19724	3620280.63	216046.85	-8.86	WB
19725	3620280.81	216050.21	-8.85	WB
19726	3620280.98	216053.55	-8.85	WB
19727	3620281.14	216056.80	-8.85	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
19728	3620281.29	216060.16	-8.85	WB
19729	3620281.29	216063.45	-8.85	WB
19730	3620281.25	216066.72	-8.84	WB
19731	3620281.16	216070.11	-8.84	WB
19732	3620281.03	216073.39	-8.84	WB
19733	3620280.91	216076.61	-8.84	WB
19734	3620280.81	216079.80	-8.83	WB
19735	3620280.71	216082.97	-8.83	WB
19736	3620280.59	216086.13	-8.83	WB
19737	3620280.46	216089.29	-8.82	WB
19738	3620280.37	216091.66	-8.82	WB
19739	3620280.33	216092.53	-8.81	WB
19740	3620280.26	216095.72	-8.81	WB
19741	3620280.18	216098.95	-8.81	WB
19742	3620280.11	216102.26	-8.80	WB
19743	3620280.04	216105.53	-8.80	WB
19744	3620279.99	216108.95	-8.79	WB
19745	3620279.97	216112.36	-8.79	WB
19746	3620279.96	216115.71	-8.78	WB
19747	3620279.96	216117.10	-8.78	WB
19748	3620280.00	216119.24	-8.77	WB
19749	3620280.07	216122.73	-8.77	WB
19750	3620280.15	216126.14	-8.76	WB
19751	3620280.26	216129.68	-8.75	WB
19752	3620280.38	216133.16	-8.75	WB
19753	3620280.59	216136.53	-8.74	WB
19754	3620280.82	216139.94	-8.74	WB
19755	3620280.96	216142.03	-8.74	WB
19756	3620281.04	216143.38	-8.73	WB
19757	3620281.24	216146.67	-8.73	WB
19758	3620281.45	216149.96	-8.72	WB
19759	3620281.70	216153.22	-8.72	WB
19760	3620281.95	216156.33	-8.71	WB
19761	3620282.17	216159.36	-8.71	WB
19762	3620282.38	216162.40	-8.71	WB
19763	3620282.57	216165.32	-8.70	WB
19764	3620282.71	216167.13	-8.70	WB
19765	3620282.81	216168.24	-8.70	WB
19766	3620283.04	216171.10	-8.69	WB
19767	3620283.27	216173.94	-8.69	WB
19768	3620283.48	216176.86	-8.69	WB
19769	3620283.70	216179.92	-8.69	WB
19770	3620283.88	216183.01	-8.68	WB
19771	3620284.06	216186.08	-8.68	WB
19772	3620284.29	216189.22	-8.68	WB
19773	3620284.52	216192.01	-8.68	WB
19774	3620284.55	216192.38	-8.68	WB
19775	3620284.82	216195.51	-8.67	WB
19776	3620285.12	216198.74	-8.67	WB
19777	3620285.41	216201.97	-8.67	WB
19778	3620285.72	216205.30	-8.67	WB
19779	3620286.02	216208.57	-8.67	WB
19780	3620286.31	216211.89	-8.67	WB
19781	3620286.55	216215.30	-8.67	WB
19782	3620286.67	216216.96	-8.66	WB
19783	3620286.79	216218.61	-8.66	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
19784	3620286.98	216222.03	-8.66	WB
19785	3620287.15	216225.43	-8.66	WB
19786	3620287.26	216228.79	-8.65	WB
19787	3620287.27	216232.35	-8.65	WB
19788	3620287.26	216235.89	-8.65	WB
19789	3620287.19	216239.46	-8.65	WB
19790	3620287.13	216241.74	-8.64	WB
19791	3620287.10	216243.15	-8.64	WB
19792	3620287.01	216246.84	-8.63	WB
19793	3620286.91	216250.48	-8.63	WB
19794	3620286.81	216254.18	-8.62	WB
19795	3620286.70	216257.92	-8.62	WB
19796	3620286.58	216261.54	-8.61	WB
19797	3620286.49	216265.17	-8.61	WB
19798	3620286.45	216267.01	-8.60	WB
19799	3620286.41	216268.73	-8.60	WB
19800	3620286.34	216272.16	-8.59	WB
19801	3620286.34	216275.36	-8.58	WB
19802	3620286.33	216278.71	-8.58	WB
19803	3620286.39	216281.81	-8.57	WB
19804	3620286.50	216284.94	-8.56	WB
19805	3620286.63	216288.00	-8.56	WB
19806	3620286.80	216290.91	-8.55	WB
19807	3620286.85	216291.71	-8.54	WB
19808	3620286.97	216293.93	-8.54	WB
19809	3620287.16	216296.88	-8.53	WB
19810	3620287.35	216299.80	-8.52	WB
19811	3620287.56	216302.75	-8.52	WB
19812	3620287.82	216305.71	-8.51	WB
19813	3620288.08	216308.59	-8.50	WB
19814	3620288.28	216311.51	-8.50	WB
19815	3620288.47	216314.48	-8.49	WB
19816	3620288.61	216316.69	-8.49	WB
19817	3620288.65	216317.40	-8.48	WB
19818	3620288.84	216320.45	-8.48	WB
19819	3620289.02	216323.36	-8.48	WB
19820	3620289.13	216326.36	-8.47	WB
19821	3620289.24	216329.47	-8.47	WB
19822	3620289.32	216332.45	-8.47	WB
19823	3620289.38	216335.47	-8.46	WB
19824	3620289.44	216338.62	-8.46	WB
19825	3620289.45	216341.64	-8.46	WB
19826	3620289.47	216344.76	-8.46	WB
19827	3620289.49	216347.84	-8.46	WB
19828	3620289.53	216350.86	-8.45	WB
19829	3620289.57	216353.96	-8.45	WB
19830	3620289.55	216356.98	-8.45	WB
19831	3620289.53	216359.98	-8.45	WB
19832	3620289.51	216363.07	-8.45	WB
19833	3620289.50	216366.24	-8.45	WB
19834	3620289.50	216366.66	-8.45	WB
19835	3620289.47	216369.33	-8.45	WB
19836	3620289.32	216372.76	-8.45	WB
19837	3620289.16	216376.25	-8.44	WB
19838	3620288.95	216379.90	-8.44	WB
19839	3620288.72	216383.76	-8.44	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
19840	3620288.44	216387.63	-8.44	WB
19841	3620288.06	216391.62	-8.44	WB
19842	3620287.67	216395.71	-8.44	WB
19843	3620287.30	216399.79	-8.43	WB
19844	3620286.95	216403.74	-8.43	WB
19845	3620286.60	216407.66	-8.43	WB
19846	3620286.23	216411.39	-8.43	WB
19847	3620285.86	216415.12	-8.42	WB
19848	3620285.77	216416.04	-8.42	WB
19849	3620285.53	216418.51	-8.42	WB
19850	3620285.22	216421.80	-8.41	WB
19851	3620284.88	216424.91	-8.41	WB
19852	3620284.49	216427.86	-8.40	WB
19853	3620284.07	216430.83	-8.40	WB
19854	3620283.60	216433.62	-8.40	WB
19855	3620283.11	216436.43	-8.39	WB
19856	3620282.63	216439.09	-8.39	WB
19857	3620282.25	216441.11	-8.38	WB
19858	3620282.12	216441.74	-8.38	WB
19859	3620281.59	216444.46	-8.37	WB
19860	3620281.03	216447.08	-8.37	WB
19861	3620280.45	216449.78	-8.36	WB
19862	3620279.90	216452.47	-8.36	WB
19863	3620279.37	216455.14	-8.35	WB
19864	3620278.84	216457.89	-8.35	WB
19865	3620278.30	216460.75	-8.34	WB
19866	3620277.76	216463.59	-8.34	WB
19867	3620277.32	216466.27	-8.33	WB
19868	3620277.27	216466.63	-8.33	WB
19869	3620276.79	216469.70	-8.33	WB
19870	3620276.33	216472.85	-8.32	WB
19871	3620275.95	216476.16	-8.32	WB
19872	3620275.56	216479.49	-8.31	WB
19873	3620275.24	216482.94	-8.31	WB
19874	3620274.94	216486.41	-8.31	WB
19875	3620274.70	216489.93	-8.30	WB
19876	3620274.65	216491.68	-8.30	WB
19877	3620274.60	216493.50	-8.30	WB
19878	3620274.51	216497.10	-8.30	WB
19879	3620274.47	216500.61	-8.29	WB
19880	3620274.44	216504.18	-8.29	WB
19881	3620274.43	216507.83	-8.29	WB
19882	3620274.45	216511.32	-8.29	WB
19883	3620274.46	216514.83	-8.29	WB
19884	3620274.51	216517.11	-8.28	WB
19885	3620274.55	216518.48	-8.28	WB
19886	3620274.66	216521.94	-8.28	WB
19887	3620274.82	216525.35	-8.28	WB
19888	3620275.04	216528.67	-8.28	WB
19889	3620275.29	216531.85	-8.28	WB
19890	3620275.51	216534.86	-8.27	WB
19891	3620275.75	216537.92	-8.27	WB
19892	3620276.03	216540.79	-8.27	WB
19893	3620276.16	216541.89	-8.27	WB
19894	3620276.37	216543.61	-8.27	WB
19895	3620276.71	216546.42	-8.27	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
19896	3620277.00	216549.11	-8.26	WB
19897	3620277.29	216551.85	-8.26	WB
19898	3620277.54	216554.66	-8.26	WB
19899	3620277.75	216557.45	-8.26	WB
19900	3620277.93	216560.49	-8.25	WB
19901	3620278.02	216563.53	-8.25	WB
19902	3620278.11	216566.59	-8.25	WB
19903	3620278.12	216567.01	-8.25	WB
19904	3620278.13	216569.96	-8.24	WB
19905	3620278.12	216573.27	-8.24	WB
19906	3620278.11	216576.66	-8.24	WB
19907	3620278.10	216580.37	-8.23	WB
19908	3620278.08	216583.90	-8.23	WB
19909	3620278.07	216587.64	-8.23	WB
19910	3620278.07	216591.36	-8.22	WB
19911	3620278.06	216592.25	-8.22	WB
19912	3620278.10	216595.09	-8.21	WB
19913	3620278.18	216598.82	-8.21	WB
19914	3620278.26	216602.61	-8.20	WB
19915	3620278.40	216606.33	-8.20	WB
19916	3620278.55	216610.11	-8.19	WB
19917	3620278.72	216613.85	-8.19	WB
19918	3620278.90	216617.40	-8.19	WB
19919	3620279.12	216620.96	-8.18	WB
19920	3620279.56	216624.13	-8.18	WB
19921	3620279.99	216627.24	-8.17	WB
19922	3620280.39	216630.34	-8.16	WB
19923	3620280.75	216633.27	-8.16	WB
19924	3620281.11	216636.16	-8.15	WB
19925	3620281.56	216638.99	-8.15	WB
19926	3620281.99	216641.80	-8.15	WB
19927	3620282.25	216644.61	-8.14	WB
19928	3620282.45	216647.56	-8.14	WB
19929	3620282.63	216650.43	-8.13	WB
19930	3620282.78	216653.39	-8.13	WB
19931	3620282.95	216656.34	-8.12	WB
19932	3620283.06	216659.33	-8.12	WB
19933	3620283.17	216662.35	-8.11	WB
19934	3620283.25	216665.36	-8.11	WB
19935	3620283.29	216666.88	-8.11	WB
19936	3620283.32	216668.34	-8.10	WB
19937	3620283.41	216671.30	-8.10	WB
19938	3620283.63	216674.22	-8.09	WB
19939	3620283.86	216677.01	-8.09	WB
19940	3620284.05	216679.78	-8.09	WB
19941	3620284.18	216682.74	-8.08	WB
19942	3620284.29	216685.59	-8.08	WB
19943	3620284.38	216688.59	-8.08	WB
19944	3620284.46	216691.72	-8.08	WB
19945	3620284.51	216694.86	-8.07	WB
19946	3620284.51	216698.16	-8.07	WB
19947	3620284.50	216701.51	-8.07	WB
19948	3620284.38	216705.04	-8.06	WB
19949	3620284.25	216708.69	-8.06	WB
19950	3620284.14	216712.41	-8.06	WB
19951	3620284.06	216716.13	-8.05	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
19952	3620284.04	216717.14	-8.05	WB
19953	3620283.99	216719.91	-8.05	WB
19954	3620283.94	216723.63	-8.04	WB
19955	3620283.91	216727.28	-8.04	WB
19956	3620283.89	216730.98	-8.04	WB
19957	3620283.89	216734.66	-8.03	WB
19958	3620283.92	216738.17	-8.03	WB
19959	3620284.03	216741.64	-8.02	WB
19960	3620284.14	216745.06	-8.02	WB
19961	3620284.17	216748.26	-8.02	WB
19962	3620284.19	216751.52	-8.01	WB
19963	3620284.20	216754.68	-8.01	WB
19964	3620284.22	216757.71	-8.00	WB
19965	3620284.24	216760.84	-8.00	WB
19966	3620284.10	216763.82	-7.99	WB
19967	3620283.94	216766.48	-7.99	WB
19968	3620283.92	216766.84	-7.98	WB
19969	3620283.72	216769.86	-7.97	WB
19970	3620283.53	216772.86	-7.97	WB
19971	3620283.34	216775.81	-7.96	WB
19972	3620283.09	216778.82	-7.96	WB
19973	3620282.85	216781.87	-7.95	WB
19974	3620282.65	216784.80	-7.95	WB
19975	3620282.48	216787.83	-7.94	WB
19976	3620282.32	216790.79	-7.94	WB
19977	3620282.28	216791.52	-7.93	WB
19978	3620282.18	216793.66	-7.93	WB
19979	3620282.04	216796.62	-7.92	WB
19980	3620281.95	216799.60	-7.92	WB
19981	3620281.90	216802.57	-7.91	WB
19982	3620281.84	216805.71	-7.91	WB
19983	3620281.76	216808.84	-7.91	WB
19984	3620281.67	216812.07	-7.90	WB
19985	3620281.65	216815.30	-7.90	WB
19986	3620281.66	216816.90	-7.90	WB
19987	3620281.66	216818.51	-7.89	WB
19988	3620281.65	216821.87	-7.89	WB
19989	3620281.59	216825.17	-7.89	WB
19990	3620281.53	216828.43	-7.88	WB
19991	3620281.59	216831.63	-7.88	WB
19992	3620281.69	216834.83	-7.88	WB
19993	3620281.79	216837.88	-7.88	WB
19994	3620281.87	216840.92	-7.88	WB
19995	3620281.89	216841.69	-7.87	WB
19996	3620281.94	216844.00	-7.87	WB
19997	3620282.04	216846.99	-7.87	WB
19998	3620282.13	216850.07	-7.87	WB
19999	3620282.19	216853.12	-7.87	WB
20000	3620282.20	216856.24	-7.87	WB
20001	3620282.20	216859.45	-7.86	WB
20002	3620282.13	216862.78	-7.86	WB
20003	3620282.06	216866.05	-7.86	WB
20004	3620282.04	216866.93	-7.86	WB
20005	3620281.99	216869.40	-7.86	WB
20006	3620281.91	216872.77	-7.85	WB
20007	3620281.84	216876.17	-7.85	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
20008	3620281.76	216879.51	-7.85	WB
20009	3620281.68	216882.83	-7.85	WB
20010	3620281.62	216886.15	-7.84	WB
20011	3620281.56	216889.46	-7.84	WB
20012	3620281.52	216891.60	-7.84	WB
20013	3620281.48	216892.81	-7.83	WB
20014	3620281.34	216896.20	-7.83	WB
20015	3620281.18	216899.65	-7.83	WB
20016	3620281.00	216903.03	-7.82	WB
20017	3620280.81	216906.48	-7.82	WB
20018	3620280.60	216910.01	-7.81	WB
20019	3620280.36	216913.43	-7.81	WB
20020	3620280.14	216916.54	-7.80	WB
20021	3620280.11	216916.96	-7.80	WB
20022	3620279.83	216920.40	-7.79	WB
20023	3620279.55	216923.76	-7.79	WB
20024	3620279.26	216927.19	-7.78	WB
20025	3620278.99	216930.44	-7.78	WB
20026	3620278.72	216933.65	-7.77	WB
20027	3620278.46	216936.68	-7.77	WB
20028	3620278.21	216939.70	-7.76	WB
20029	3620278.08	216941.23	-7.75	WB
20030	3620278.00	216942.63	-7.75	WB
20031	3620277.85	216945.41	-7.74	WB
20032	3620277.70	216948.23	-7.74	WB
20033	3620277.51	216951.03	-7.73	WB
20034	3620277.31	216953.89	-7.73	WB
20035	3620277.09	216956.76	-7.72	WB
20036	3620276.85	216959.69	-7.72	WB
20037	3620276.60	216962.70	-7.71	WB
20038	3620276.39	216965.77	-7.71	WB
20039	3620276.32	216966.86	-7.70	WB
20040	3620276.19	216968.78	-7.70	WB
20041	3620276.02	216971.92	-7.69	WB
20042	3620275.87	216975.05	-7.69	WB
20043	3620275.74	216978.15	-7.68	WB
20044	3620275.71	216981.41	-7.68	WB
20045	3620275.68	216984.61	-7.68	WB
20046	3620275.68	216987.87	-7.67	WB
20047	3620275.70	216991.22	-7.67	WB
20048	3620275.71	216992.00	-7.67	WB
20049	3620275.73	216994.45	-7.66	WB
20050	3620275.78	216997.75	-7.66	WB
20051	3620275.83	217001.09	-7.66	WB
20052	3620275.96	217004.26	-7.66	WB
20053	3620276.13	217007.43	-7.65	WB
20054	3620276.30	217010.62	-7.65	WB
20055	3620276.48	217013.68	-7.65	WB
20056	3620276.66	217016.77	-7.64	WB
20057	3620276.69	217017.14	-7.64	WB
20058	3620276.86	217019.93	-7.64	WB
20059	3620277.05	217022.95	-7.64	WB
20060	3620277.23	217026.19	-7.63	WB
20061	3620277.37	217029.37	-7.63	WB
20062	3620277.50	217032.56	-7.63	WB
20063	3620277.60	217036.09	-7.62	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
20064	3620277.68	217039.48	-7.62	WB
20065	3620277.74	217042.05	-7.61	WB
20066	3620277.75	217042.90	-7.61	WB
20067	3620277.78	217046.57	-7.61	WB
20068	3620277.82	217050.08	-7.60	WB
20069	3620277.84	217053.72	-7.60	WB
20070	3620277.85	217057.31	-7.59	WB
20071	3620277.83	217060.81	-7.58	WB
20072	3620277.77	217064.29	-7.58	WB
20073	3620277.74	217066.88	-7.57	WB
20074	3620277.73	217067.73	-7.57	WB
20075	3620277.71	217070.94	-7.56	WB
20076	3620277.71	217074.12	-7.55	WB
20077	3620277.73	217077.19	-7.54	WB
20078	3620277.75	217080.10	-7.54	WB
20079	3620277.76	217083.05	-7.53	WB
20080	3620277.73	217086.07	-7.52	WB
20081	3620277.68	217089.02	-7.51	WB
20082	3620277.62	217091.74	-7.51	WB
20083	3620277.61	217092.11	-7.50	WB
20084	3620277.53	217095.21	-7.49	WB
20085	3620277.43	217098.31	-7.48	WB
20086	3620277.27	217101.48	-7.47	WB
20087	3620277.13	217104.60	-7.46	WB
20088	3620277.05	217107.59	-7.45	WB
20089	3620276.99	217110.70	-7.45	WB
20090	3620276.89	217113.74	-7.44	WB
20091	3620276.74	217116.36	-7.43	WB
20092	3620276.72	217116.71	-7.42	WB
20093	3620276.54	217119.78	-7.41	WB
20094	3620276.41	217122.74	-7.41	WB
20095	3620276.29	217125.64	-7.40	WB
20096	3620276.14	217128.58	-7.39	WB
20097	3620275.94	217131.58	-7.38	WB
20098	3620275.74	217134.49	-7.38	WB
20099	3620275.62	217137.57	-7.37	WB
20100	3620275.49	217140.53	-7.36	WB
20101	3620275.44	217141.66	-7.36	WB
20102	3620275.35	217143.55	-7.35	WB
20103	3620275.20	217146.76	-7.35	WB
20104	3620275.05	217149.85	-7.34	WB
20105	3620274.96	217153.06	-7.33	WB
20106	3620274.87	217156.41	-7.33	WB
20107	3620274.81	217159.73	-7.32	WB
20108	3620274.77	217163.23	-7.32	WB
20109	3620274.75	217166.72	-7.31	WB
20110	3620274.76	217167.14	-7.31	WB
20111	3620274.84	217170.16	-7.31	WB
20112	3620274.94	217173.68	-7.30	WB
20113	3620275.18	217177.11	-7.30	WB
20114	3620275.47	217180.53	-7.29	WB
20115	3620275.80	217183.91	-7.29	WB
20116	3620276.16	217187.26	-7.28	WB
20117	3620276.52	217190.53	-7.28	WB
20118	3620276.72	217192.22	-7.28	WB
20119	3620276.93	217193.85	-7.27	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
20120	3620277.37	217197.22	-7.27	WB
20121	3620277.80	217200.48	-7.26	WB
20122	3620278.24	217203.83	-7.26	WB
20123	3620278.68	217207.11	-7.25	WB
20124	3620279.07	217210.40	-7.25	WB
20125	3620279.48	217213.82	-7.24	WB
20126	3620279.89	217217.19	-7.24	WB
20127	3620280.32	217220.52	-7.23	WB
20128	3620280.75	217223.89	-7.23	WB
20129	3620281.15	217227.21	-7.22	WB
20130	3620281.55	217230.52	-7.22	WB
20131	3620281.98	217233.72	-7.21	WB
20132	3620282.45	217236.94	-7.21	WB
20133	3620282.90	217240.05	-7.20	WB
20134	3620283.14	217241.99	-7.20	WB
20135	3620283.29	217243.15	-7.19	WB
20136	3620283.68	217246.31	-7.18	WB
20137	3620284.00	217249.34	-7.18	WB
20138	3620284.29	217252.43	-7.17	WB
20139	3620284.57	217255.51	-7.17	WB
20140	3620284.81	217258.54	-7.16	WB
20141	3620285.05	217261.68	-7.15	WB
20142	3620285.18	217264.78	-7.15	WB
20143	3620285.24	217266.74	-7.14	WB
20144	3620285.28	217267.85	-7.13	WB
20145	3620285.38	217271.02	-7.13	WB
20146	3620285.50	217274.10	-7.12	WB
20147	3620285.61	217277.18	-7.12	WB
20148	3620285.59	217280.25	-7.11	WB
20149	3620285.55	217283.30	-7.10	WB
20150	3620285.51	217286.33	-7.10	WB
20151	3620285.47	217289.31	-7.09	WB
20152	3620285.45	217291.52	-7.09	WB
20153	3620285.44	217292.27	-7.08	WB
20154	3620285.32	217295.13	-7.08	WB
20155	3620285.19	217298.06	-7.07	WB
20156	3620285.03	217300.87	-7.07	WB
20157	3620284.85	217303.69	-7.06	WB
20158	3620284.65	217306.55	-7.06	WB
20159	3620284.46	217309.32	-7.06	WB
20160	3620284.25	217312.18	-7.05	WB
20161	3620283.94	217315.05	-7.05	WB
20162	3620283.81	217316.09	-7.04	WB
20163	3620283.56	217317.93	-7.04	WB
20164	3620283.16	217320.95	-7.03	WB
20165	3620282.82	217324.07	-7.03	WB
20166	3620282.49	217327.15	-7.03	WB
20167	3620282.11	217330.47	-7.02	WB
20168	3620281.69	217333.83	-7.02	WB
20169	3620281.28	217337.24	-7.01	WB
20170	3620280.87	217340.83	-7.01	WB
20171	3620280.78	217341.68	-7.00	WB
20172	3620280.48	217344.41	-7.00	WB
20173	3620280.18	217347.99	-6.99	WB
20174	3620279.93	217351.67	-6.99	WB
20175	3620279.70	217355.25	-6.98	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
20176	3620279.52	217358.74	-6.98	WB
20177	3620279.35	217362.39	-6.97	WB
20178	3620279.29	217365.83	-6.96	WB
20179	3620279.28	217367.11	-6.95	WB
20180	3620279.26	217369.23	-6.95	WB
20181	3620279.24	217372.80	-6.94	WB
20182	3620279.24	217376.19	-6.93	WB
20183	3620279.23	217379.68	-6.92	WB
20184	3620279.27	217383.10	-6.91	WB
20185	3620279.31	217386.49	-6.90	WB
20186	3620279.40	217389.95	-6.89	WB
20187	3620279.47	217392.01	-6.88	WB
20188	3620279.51	217393.32	-6.87	WB
20189	3620279.63	217396.64	-6.86	WB
20190	3620279.76	217400.07	-6.85	WB
20191	3620279.88	217403.44	-6.83	WB
20192	3620279.97	217406.78	-6.82	WB
20193	3620280.05	217410.10	-6.81	WB
20194	3620280.12	217413.42	-6.79	WB
20195	3620280.18	217416.63	-6.78	WB
20196	3620280.22	217419.86	-6.77	WB
20197	3620280.23	217423.07	-6.75	WB
20198	3620280.22	217426.19	-6.74	WB
20199	3620280.19	217429.41	-6.72	WB
20200	3620280.15	217432.47	-6.71	WB
20201	3620280.10	217435.49	-6.69	WB
20202	3620280.08	217438.57	-6.68	WB
20203	3620280.06	217441.47	-6.67	WB
20204	3620280.05	217444.34	-6.65	WB
20205	3620280.02	217447.25	-6.64	WB
20206	3620280.00	217450.04	-6.62	WB
20207	3620279.98	217452.82	-6.61	WB
20208	3620279.97	217455.62	-6.59	WB
20209	3620279.95	217458.41	-6.58	WB
20210	3620279.92	217461.20	-6.57	WB
20211	3620279.89	217464.00	-6.56	WB
20212	3620279.89	217466.46	-6.54	WB
20213	3620279.89	217466.80	-6.53	WB
20214	3620279.88	217469.60	-6.52	WB
20215	3620279.87	217472.52	-6.51	WB
20216	3620279.85	217475.37	-6.50	WB
20217	3620279.83	217478.26	-6.48	WB
20218	3620279.84	217481.22	-6.47	WB
20219	3620279.85	217484.13	-6.46	WB
20220	3620279.86	217487.22	-6.45	WB
20221	3620279.88	217490.29	-6.44	WB
20222	3620279.89	217491.80	-6.44	WB
20223	3620279.90	217493.31	-6.43	WB
20224	3620279.93	217496.56	-6.42	WB
20225	3620279.95	217499.77	-6.41	WB
20226	3620279.95	217503.09	-6.40	WB
20227	3620279.95	217506.59	-6.39	WB
20228	3620279.97	217510.06	-6.38	WB
20229	3620280.06	217513.69	-6.37	WB
20230	3620280.16	217517.30	-6.37	WB
20231	3620280.24	217520.99	-6.36	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
20232	3620280.32	217524.71	-6.35	WB
20233	3620280.43	217528.44	-6.34	WB
20234	3620280.60	217532.20	-6.33	WB
20235	3620280.77	217535.95	-6.32	WB
20236	3620280.85	217539.76	-6.31	WB
20237	3620280.88	217542.10	-6.30	WB
20238	3620280.90	217543.45	-6.29	WB
20239	3620280.94	217547.11	-6.28	WB
20240	3620280.98	217550.82	-6.27	WB
20241	3620281.03	217554.42	-6.26	WB
20242	3620281.01	217557.99	-6.25	WB
20243	3620280.99	217561.40	-6.24	WB
20244	3620280.95	217564.78	-6.23	WB
20245	3620280.92	217566.50	-6.21	WB
20246	3620280.89	217568.16	-6.20	WB
20247	3620280.83	217571.40	-6.19	WB
20248	3620280.78	217574.52	-6.17	WB
20249	3620280.72	217577.75	-6.16	WB
20250	3620280.64	217580.93	-6.15	WB
20251	3620280.54	217584.07	-6.13	WB
20252	3620280.44	217587.22	-6.12	WB
20253	3620280.43	217590.35	-6.10	WB
20254	3620280.43	217591.95	-6.09	WB
20255	3620280.43	217593.49	-6.07	WB
20256	3620280.45	217596.61	-6.06	WB
20257	3620280.48	217599.74	-6.04	WB
20258	3620280.54	217602.83	-6.02	WB
20259	3620280.73	217605.88	-6.01	WB
20260	3620280.92	217608.80	-5.99	WB
20261	3620281.18	217611.71	-5.98	WB
20262	3620281.48	217614.63	-5.96	WB
20263	3620281.72	217617.03	-5.94	WB
20264	3620281.76	217617.40	-5.93	WB
20265	3620282.05	217620.21	-5.91	WB
20266	3620282.36	217623.13	-5.90	WB
20267	3620282.67	217625.91	-5.88	WB
20268	3620282.97	217628.77	-5.87	WB
20269	3620283.25	217631.62	-5.85	WB
20270	3620283.50	217634.41	-5.84	WB
20271	3620283.76	217637.30	-5.82	WB
20272	3620283.99	217640.20	-5.81	WB
20273	3620284.13	217642.02	-5.80	WB
20274	3620284.22	217643.10	-5.78	WB
20275	3620284.44	217646.03	-5.77	WB
20276	3620284.66	217648.99	-5.76	WB
20277	3620284.89	217651.93	-5.74	WB
20278	3620285.08	217654.87	-5.73	WB
20279	3620285.27	217657.84	-5.72	WB
20280	3620285.46	217660.85	-5.71	WB
20281	3620285.63	217663.94	-5.70	WB
20282	3620285.78	217666.58	-5.69	WB
20283	3620285.80	217666.98	-5.68	WB
20284	3620285.88	217670.25	-5.67	WB
20285	3620285.95	217673.57	-5.66	WB
20286	3620285.98	217676.95	-5.65	WB
20287	3620285.98	217680.55	-5.64	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
20288	3620285.95	217684.14	-5.63	WB
20289	3620285.82	217687.89	-5.62	WB
20290	3620285.69	217691.75	-5.61	WB
20291	3620285.51	217695.62	-5.60	WB
20292	3620285.32	217699.52	-5.59	WB
20293	3620285.13	217703.57	-5.58	WB
20294	3620284.94	217707.44	-5.57	WB
20295	3620284.75	217711.41	-5.56	WB
20296	3620284.62	217715.21	-5.55	WB
20297	3620284.56	217717.05	-5.54	WB
20298	3620284.51	217718.90	-5.53	WB
20299	3620284.43	217722.63	-5.52	WB
20300	3620284.36	217726.15	-5.51	WB
20301	3620284.29	217729.67	-5.50	WB
20302	3620284.17	217732.97	-5.48	WB
20303	3620284.05	217736.25	-5.47	WB
20304	3620283.90	217739.44	-5.46	WB
20305	3620283.78	217741.32	-5.45	WB
20306	3620283.71	217742.52	-5.43	WB
20307	3620283.51	217745.62	-5.42	WB
20308	3620283.17	217748.59	-5.41	WB
20309	3620282.81	217751.61	-5.40	WB
20310	3620282.42	217754.50	-5.38	WB
20311	3620282.02	217757.35	-5.37	WB
20312	3620281.58	217760.31	-5.36	WB
20313	3620281.10	217763.14	-5.35	WB
20314	3620280.62	217765.93	-5.34	WB
20315	3620280.13	217768.78	-5.33	WB
20316	3620279.65	217771.56	-5.32	WB
20317	3620279.17	217774.30	-5.31	WB
20318	3620278.64	217777.06	-5.30	WB
20319	3620278.11	217779.81	-5.29	WB
20320	3620277.63	217782.55	-5.28	WB
20321	3620277.18	217785.29	-5.27	WB
20322	3620276.73	217788.04	-5.26	WB
20323	3620276.27	217790.70	-5.26	WB
20324	3620276.21	217791.06	-5.25	WB
20325	3620275.81	217793.47	-5.25	WB
20326	3620275.36	217796.14	-5.24	WB
20327	3620274.92	217798.78	-5.24	WB
20328	3620274.46	217801.56	-5.23	WB
20329	3620274.03	217804.25	-5.23	WB
20330	3620273.58	217806.96	-5.23	WB
20331	3620273.07	217809.80	-5.22	WB
20332	3620272.53	217812.67	-5.22	WB
20333	3620271.97	217815.69	-5.22	WB
20334	3620271.90	217816.06	-5.22	WB
20335	3620271.40	217818.82	-5.21	WB
20336	3620270.81	217821.97	-5.21	WB
20337	3620270.27	217825.41	-5.21	WB
20338	3620269.74	217828.87	-5.21	WB
20339	3620269.25	217832.39	-5.21	WB
20340	3620268.80	217836.07	-5.20	WB
20341	3620268.37	217839.80	-5.20	WB
20342	3620268.25	217842.15	-5.19	WB
20343	3620268.19	217843.49	-5.19	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
20344	3620268.02	217847.22	-5.18	WB
20345	3620267.97	217850.95	-5.18	WB
20346	3620268.01	217854.50	-5.17	WB
20347	3620268.08	217858.11	-5.16	WB
20348	3620268.29	217861.48	-5.15	WB
20349	3620268.51	217864.76	-5.14	WB
20350	3620268.72	217867.19	-5.13	WB
20351	3620268.80	217867.98	-5.12	WB
20352	3620269.11	217871.08	-5.11	WB
20353	3620269.41	217874.10	-5.09	WB
20354	3620269.69	217877.02	-5.08	WB
20355	3620269.97	217879.96	-5.06	WB
20356	3620270.21	217882.89	-5.04	WB
20357	3620270.43	217885.84	-5.02	WB
20358	3620270.62	217888.93	-5.00	WB
20359	3620270.74	217892.00	-4.98	WB
20360	3620270.84	217895.13	-4.96	WB
20361	3620270.96	217898.51	-4.93	WB
20362	3620271.07	217901.82	-4.91	WB
20363	3620271.20	217905.30	-4.89	WB
20364	3620271.36	217908.79	-4.86	WB
20365	3620271.52	217912.24	-4.83	WB
20366	3620271.84	217915.87	-4.81	WB
20367	3620272.01	217917.69	-4.78	WB
20368	3620272.17	217919.45	-4.75	WB
20369	3620272.57	217923.02	-4.72	WB
20370	3620273.05	217926.72	-4.70	WB
20371	3620273.54	217930.34	-4.72	WB
20372	3620274.19	217933.92	-4.74	WB
20373	3620274.86	217937.52	-4.80	WB
20374	3620275.56	217940.85	-4.84	WB
20375	3620276.04	217942.93	-4.90	WB
20376	3620276.33	217944.17	-5.00	WB
20377	3620277.12	217947.52	-5.09	WB
20378	3620277.94	217950.63	-5.18	WB
20379	3620278.77	217953.77	-5.27	WB
20380	3620279.60	217956.85	-5.34	WB
20381	3620280.41	217959.85	-5.41	WB
20382	3620281.21	217962.91	-5.44	WB
20383	3620281.96	217965.93	-5.47	WB
20384	3620282.33	217967.40	-5.47	WB
20385	3620282.69	217968.86	-5.43	WB
20386	3620283.43	217971.85	-5.40	WB
20387	3620284.14	217974.72	-5.37	WB
20388	3620284.83	217977.48	-5.34	WB
20389	3620285.52	217980.23	-5.33	WB
20390	3620286.20	217982.93	-5.33	WB
20391	3620286.82	217985.49	-5.36	WB
20392	3620287.44	217988.17	-5.39	WB
20393	3620288.01	217990.83	-5.41	WB
20394	3620288.19	217991.79	-5.44	WB
20395	3620288.52	217993.51	-5.48	WB
20396	3620289.01	217996.22	-5.51	WB
20397	3620289.35	217999.00	-5.52	WB
20398	3620289.69	218001.78	-5.52	WB
20399	3620290.03	218004.57	-5.51	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
20400	3620290.38	218007.37	-5.49	WB
20401	3620290.74	218010.17	-5.47	WB
20402	3620290.96	218013.08	-5.47	WB
20403	3620291.18	218015.90	-5.47	WB
20404	3620291.24	218016.62	-5.46	WB
20405	3620291.35	218018.78	-5.42	WB
20406	3620291.48	218021.73	-5.40	WB
20407	3620291.58	218024.61	-5.37	WB
20408	3620291.48	218027.51	-5.34	WB
20409	3620291.38	218030.49	-5.32	WB
20410	3620291.13	218033.42	-5.30	WB
20411	3620290.81	218036.38	-5.28	WB
20412	3620290.45	218039.33	-5.23	WB
20413	3620290.17	218040.84	-5.20	WB
20414	3620289.91	218042.32	-5.18	WB
20415	3620289.36	218045.32	-5.13	WB
20416	3620288.67	218048.36	-5.10	WB
20417	3620287.91	218051.43	-5.06	WB
20418	3620287.10	218054.53	-5.01	WB
20419	3620286.15	218057.74	-4.97	WB
20420	3620285.23	218060.86	-4.92	WB
20421	3620284.29	218064.12	-4.88	WB
20422	3620283.79	218065.85	-4.81	WB
20423	3620283.33	218067.48	-4.72	WB
20424	3620282.38	218070.82	-4.63	WB
20425	3620281.37	218074.37	-4.54	WB
20426	3620280.38	218077.87	-4.46	WB
20427	3620279.49	218081.45	-4.37	WB
20428	3620278.57	218085.16	-4.26	WB
20429	3620277.73	218088.85	-4.14	WB
20430	3620277.25	218091.19	-4.02	WB
20431	3620276.98	218092.53	-3.92	WB
20432	3620276.17	218096.41	-3.88	WB
20433	3620275.51	218100.15	-3.82	WB
20434	3620274.83	218104.00	-3.76	WB
20435	3620274.29	218107.79	-3.70	WB
20436	3620273.85	218111.52	-3.63	WB
20437	3620273.42	218115.34	-3.60	WB
20438	3620273.29	218116.72	-3.58	WB
20439	3620273.09	218119.03	-3.57	WB
20440	3620272.76	218122.73	-3.54	WB
20441	3620272.57	218126.36	-3.50	WB
20442	3620272.45	218129.96	-3.48	WB
20443	3620272.35	218133.55	-3.47	WB
20444	3620272.31	218137.06	-3.47	WB
20445	3620272.28	218140.54	-3.48	WB
20446	3620272.29	218141.82	-3.48	WB
20447	3620272.36	218143.90	-3.48	WB
20448	3620272.49	218147.27	-3.50	WB
20449	3620272.60	218150.46	-3.56	WB
20450	3620272.70	218153.58	-3.62	WB
20451	3620272.81	218156.76	-3.69	WB
20452	3620272.87	218159.71	-3.74	WB
20453	3620272.92	218162.78	-3.80	WB
20454	3620272.95	218165.64	-3.87	WB
20455	3620272.95	218166.33	-3.94	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
20456	3620272.95	218168.35	-4.00	WB
20457	3620272.95	218171.15	-4.04	WB
20458	3620272.98	218173.73	-4.11	WB
20459	3620273.02	218176.23	-4.12	WB
20460	3620273.05	218178.81	-4.16	WB
20461	3620273.07	218181.24	-4.21	WB
20462	3620273.10	218183.72	-4.26	WB
20463	3620273.12	218186.25	-4.28	WB
20464	3620273.13	218188.77	-4.31	WB
20465	3620273.12	218191.32	-4.36	WB
20466	3620273.11	218191.62	-4.40	WB
20467	3620273.09	218193.84	-4.41	WB
20468	3620273.06	218196.38	-4.44	WB
20469	3620273.07	218198.96	-4.44	WB
20470	3620273.09	218201.50	-4.46	WB
20471	3620273.11	218203.97	-4.46	WB
20472	3620273.12	218206.42	-4.47	WB
20473	3620273.16	218208.79	-4.44	WB
20474	3620273.28	218211.08	-4.41	WB
20475	3620273.40	218213.40	-4.39	WB
20476	3620273.50	218215.53	-4.36	WB
20477	3620273.56	218216.87	-4.31	WB
20478	3620273.59	218217.67	-4.29	WB
20479	3620273.69	218219.86	-4.29	WB
20480	3620273.80	218221.98	-4.26	WB
20481	3620273.92	218224.16	-4.23	WB
20482	3620274.06	218226.42	-4.23	WB
20483	3620274.20	218228.65	-4.24	WB
20484	3620274.34	218231.09	-4.23	WB
20485	3620274.47	218233.63	-4.22	WB
20486	3620274.59	218236.12	-4.23	WB
20487	3620274.67	218238.99	-4.23	WB
20488	3620274.73	218241.75	-4.18	WB
20489	3620274.78	218244.74	-4.18	WB
20490	3620274.81	218247.86	-4.16	WB
20491	3620274.82	218250.96	-4.13	WB
20492	3620274.77	218254.32	-4.11	WB
20493	3620274.73	218257.64	-4.10	WB
20494	3620274.68	218260.96	-4.08	WB
20495	3620274.63	218264.22	-4.04	WB
20496	3620274.60	218266.64	-4.01	WB
20497	3620274.59	218267.42	-3.94	WB
20498	3620274.58	218270.36	-3.86	WB
20499	3620274.57	218273.29	-3.78	WB
20500	3620274.53	218275.93	-3.69	WB
20501	3620274.49	218278.43	-3.59	WB
20502	3620274.45	218280.86	-3.52	WB
20503	3620274.42	218282.89	-3.46	WB
20504	3620274.38	218284.95	-3.36	WB
20505	3620274.33	218286.73	-3.28	WB
20506	3620274.29	218288.38	-3.19	WB
20507	3620274.24	218289.99	-3.13	WB
20508	3620274.20	218291.00	-3.06	WB
20509	3620274.19	218291.34	-3.01	WB
20510	3620274.15	218292.69	-2.98	WB
20511	3620274.07	218293.99	-2.93	WB

West Belle Pass Headland Restoration - Hydro Survey

RTK Pt No	Northing	Easting	Elevation	Description
20512	3620273.98	218295.21	-2.84	WB
20513	3620273.88	218296.41	-2.82	WB
20514	3620273.73	218297.64	-2.77	WB
20515	3620273.59	218298.82	-2.75	WB
20516	3620273.36	218299.95	-2.71	WB
20517	3620273.11	218301.07	-2.67	WB
20518	3620272.85	218302.12	-2.62	WB
20519	3620272.27	218304.14	-2.58	WB

SECTION F

Fieldnotes

TAS013_140587 1/13/15

0680 E/R to Dock
0700 Arrive @ Dock
0815 E/R to Survey Area
0848 RTK WATER SURFACE SHOT PT. #2000 ELEVATION: -0.295'
0901 SOUND VELOCITY 4916, CAST #2 Bar Check
0906 HYPACK TIDE +0.260' QC CHECK
0913 SOL 100 Breakers @ Beach 1' to 2'
0918 SOL 101
0923 SOL 102
0930 SOL 103
0938 SOL 104
0946 SOL 105
0953 SOL 106
1000 SOL 107
1008 SOL 108
1016 SOL 109
1024 SOL 110
1030 SOL 111
1037 SOL 112
1044 SOL 113
1052 SOL 114
1059 SOL 115
1107 SOL 116
1115 SOL 117


TAS013_140587 1/13/15

Tim Sonnier
Terence Hebert

CPRA
Bathy Survey
West Bell Pass
Lafourche Parish

NAD 83
LA South
GEOID 2012





5.91
-1.10
-4.81

Hydro Draft
1.10
-4.81' Hypack offset

JCLS BOOK NO. 1541

TAS013-140587 11/3/15

1123	SOL18
1131	SOL19
1140	SOL20
1149	SOL21
1158	SOL22
1207	SOL23
1217	SOL24
1227	SOL25
1300	RTK
1336	RTK WATER SURFACE PT. #2001 ELEVATION: -0.03'
1340	HELPING ROCKY WITH HIS RTK BASE
1600	BACK AT BOAT LAUNCH

73

JCLS BOOK NO. 1541

0600	Meet Crew
0735	Start Base @ TE23-SM-01
	Staff Edge @ Bridge Disturbed - unusable
	Survey transects @ water Edge
1512	End Survey

Static	8994013.T02
Base Pt	TE23-SM-01
N	224296.37
E	3645688.81
Z	7.30

R McKelvier
D Hebert
W Collins

2014-0587
CPRA
West Belle Pass Restoration Project
Lafourche Parish, LA

NAD 83 Louisiana South Zone
Geoid 12A

RPA-013-2015-20140587

500 - 539	MANG		649	SP-8
540	WES		650 - 653	NG
541 - 542	WB		654	WES
543	WES		655 - 664	WB
544 - 553	MANG		665 - 669	NG
554	WES		670	WES
555	WB		671 - 676	WB
556	WES		677 - 680	NG
557 - 572	MANG		681	WES
573 - 579	NG		682 - 687	WB
580	WES		688 - 691	NG
581 - 596	WB		692	WES
597 - 599	NG		693 - 699	WB
600	WES		700	NG
601 - 611	WB		701	SP-6
612 - 613	NG		702 - 705	NG
614	WES		706	WES
615 - 622	WB		707 - 713	WB
623 - 626	NG		714 - 719	NG
627	WES		720	WES
628 - 633	WB		721 - 728	WB
634 - 640	NG		729 - 732	NG
641	WES		733	WES
642 - 648	WB		734 - 742	WB

72

JCLS BOOK NO. 1533

743 - 747	NG
748	WES
749 - 758	WB
759	NG
760	SP - 3
761 - 764	NG
765	WES
766 - 777	WB
778 - 781	NG
782	WES
783 - 792	WB
793 - 796	NG
797	WES
798 - 807	WB
808 - 811	NG
812	WES
813 - 823	WB
824	NG
825	SP - 1
826 - 830	NG
831	WES
832 - 841	WB
842 - 844	NG
845	WES
846 - 850	WB
851 - 854	NG
855	WES
856 - 861	WB
862 - 865	NG
866	WES
867 - 871	WB
872 - 876	NG
877 -	WES
878 - 883	WB
884 - 888	NG
889	WES
890 - 895	WB
896 - 901	NG
902 -	WES
903 - 909	WB
910 - 912	NG
913	WES
914 - 924	WB
925 - 928	NG
929 -	WES
930 - 941	WB
942	CHK

73

JCLS BOOK NO. 1533

0600	Meet Crew
0745	Start Base @ TE23-SM01
	Topo Transects
	Base Powered off
1512	End Survey
1600	E/R
1700	@ Hotel

Static	84940140.T02
Base ft	TE23-SM-01
N	224296.37
E	3645688.81
Z	7.30

Wednesday January 14, 2015

(014)

R McKeivier
D Hebert
W Collins

2014-0587
CPRA
West Belle Pass Restoration Project
Lafourche Parish, LA

NAD 83 Louisiana South Zone
Geoid 12A

RPM-014-2015-20140587

943	CHK		1154-1176	NG
944-981	MANG		1177	SP
982-983	WB		1178-1182	NG
984-1007	NG		1183	SP-10
1008-1018	MANG		1184	SP-9
1019	WES		1185-1186	NG
1020	WB		1187	WES
1021	WES		1188-1285	NG
1022-1024	MANG		1286	WES
1025-1032	NG			
1033-1034	WES			
1035-	WB			
1036-1037	NG			
1038-1048	MANG			
1049-1060	NG			
1061	WES			
1062	WB			
1063	WES			
1064-1138	NG			
1139	WES			
1140	WB			
1141	WES			
1142-1152	NG			
1153	WB			

75

JCLS BOOK NO. 1533

0500	Meet Crew	
0530	E/R	
0830	Wreck on LA1	Standby
0945	E/R	
1025	Start Base @	TE23-SM-01
1654	End Survey	
1720	E/R	
1800	@ Hotel	

Static 81750190.T02
Base Pt TE23-SM-01
N 224296.329
E 3645688.772
Z 7.304

Monday January 19, 2015
(019)

R McKeivier
D Hebert
W Collins

2014-0587
CPRA
West Belle Pass Restoration Project
Lafourche Parish, LA

NAD 83 Louisiana South Zone
Geoid 12A

RPM-019-2015-20140587

1287	CHK	Δ H: 0.049 Δ V: 0.194	1419 - 1420	WES
1288	WES		1421 - 1432	NG
1289 - 1302	NG		1433 - 1434	WES
1303 - 1304	WES		1435 - 1439	NG
1305 - 1315	NG		1440 - 1441	WES
1316 - 1317	WES		1442 - 1450	WB
1318 - 1326	NG		1451 - 1464	NG
1327 - 1328	WES		1465	WES
1329 - 1337	NG		1466 - 1472	WB
1338 - 1339	WES		1473 -	WES
1340 - 1353	NG		1474 - 1524	NG
1354	WES		1525	WES
1355 - 1362	NG		1526 - 1537	WB
1363 - 1364	WES		1538	WES
1365 - 1377	NG		1539 - 1572	NG
1378	WES			
1379	NG			
1380	SP - 5			
1381	WES			
1382 - 1394	NG			
1395	WES			
1396 - 1406	NG			
1407 - 1408	WES			
1409 - 1418	NG			

77

JCLS BOOK NO. 1533

0600	Meet Crew
0700	C/R
0734	Start Base @ TE23-SM-01
	Base Powered off
1200	change Cable
1604	End Survey
1630	C/R
1730	@ Hotel

Static	81750200.T02
Base Pt	TE23-SM-01
N	224296.329
E	3645688.772
Z	7.304

Tuesday January 20, 2015
(020)

R McKeiver
D Hebert
W Collins

2014-0587
CPRA
West Belle Pass Restoration Project
Lafourche Parish, LA

NAD 83 Louisiana South Zone
Geoid 12A

RPM-020-2015-20140587

1573	CHK
1574-1587	WB
1588	WES
1589-1634	NG
1635	WES
1636-1637	WB
1638	WES
1639-1737	NG
1738	WES
1739-1799	WB
1800	WES
1801-1923	NG
1924	WES
1925-1978	WB
1979-2002	NG
2003-	WES
2004	WB
2005	WES
2006-2023	NG
2024-2248	WB
2249	NG
2250	SP-2

79

JCLS BOOK NO. 1533

0600	Meet Crew
0700	E/R
0730	Start Base @ TE23-SM-01
1626	End Survey
1700	C/R
1800	@ Hotel

Static	81750210.T02
Base Pt	TE23-SM-01
N	224296.37
E	3645688.81
Z	7.30

(021)

R McKeivier
D Hebert
L Evans

2014-0587
CPRA
West Belle Pass Restoration Project
Lafourche Parish, LA

NAD 83 Louisiana South Zone
Geoid 12A

RPM-021-2015-20140587

2

2251	CHK
2252-2253	WB
2254	WES
2255-2422	NG
2423	WES
2424-2438	WB
2439	WES
2440-2454	NG
2455	WES
2456-2460	WB
2461-2628	NG
2629-2630	WES
2631-2702	NG
2703	WES
2704-2705	WB
2706	WES
2707-2816	NG
2817	WES
2818	NG
2819	SP-4
2820-2902	NG
2903	WES
2904-2914	WB

2

0600	Meet Crew
0700	E/R
0745	Start Base @ TE23-SM-01
1523	End Survey
1600	E/R
	Clean Equipment
Static	81750220.702
Base Pt	TE23-SM-01
N	224296.37
E	3645688.81
Z	7.30

(0221)

R McKelvier
D Hebert
L Evans

2014-0587
CPRA
West Belle Pass Restoration Project
Lafourche Parish, LA

NAD 83 Louisiana South Zone
Geoid 12A

RPM-002-2015-20140587

2915	CHK
2916	WES
2917 - 3081	NG
3082 - 3098	WS
3099 - 3100	WES
3101 - 3229	NG
3230	SP - 7
3231 - 3265	NG
3266 - 3267	WES
3268 - 3497	NG
3498	WES

SECTION G

Photos



gauge_bridge.JPG



RPM_013_SP-1.jpg



RPM_013_SP-3.jpg



RPM_013_SP-6.jpg



RPM_013_SP-8.jpg



RPM_013_STAFFGAGE.jpg



RPM_013_TBM.jpg



RPM_013_TE23SM01_CLOSEUP.jpg



RPM_013_TE23SM01_EYELEVEL.jpg



RPM_013_TE23SM01_HORIZON.jpg



RPM_014_SP-9.jpg



RPM_014_SP-10.jpg



RPM_014_TE23SM01_CLOSEUP.jpg




RPM_014_TE23SM01_EYELEVEL.jpg



RPM_014_TE23SM01_HORIZON.jpg



RPM_020_SP2.jpg




RPM_020_SP-2.jpg




RPM_020_TE23SM01_CLOSEUP.jpg



RPM_020_TE23SM01_EYELEVEL.jpg



RPM_020_TE23SM01_HORIZON.jpg




RPM_021_SP-4.jpg




RPM_021_TE23SM01_CLOSEUP.jpg



RPM_021_TE23SM01_EYELEVEL.jpg



RPM_021_TE23SM01_HORIZON.jpg



RPM_022_SP-7.jpg



RPM_022_TE23SM01_CLOSEUP.jpg




RPM_022_TE23SM01_EYELEVEL.jpg



RPM_022_TE23SM01_HORIZON.jpg

SECTION H

Maps



VICINITY MAP

NOT TO SCALE

T23S-R22E

SEC. 019 | SEC. 020 | SEC. 021 | SEC. 022

TIMBALIER BAY

SP-1 SP-2 SP-3 SP-4 SP-5 SP-6 SP-7 SP-8 SP-9 SP-10

TRANSECT 1 TRANSECT 2 TRANSECT 3 TRANSECT 4 TRANSECT 5 TRANSECT 6 TRANSECT 7 TRANSECT 8 TRANSECT 9 TRANSECT 10 TRANSECT 11 TRANSECT 12 TRANSECT 13 TRANSECT 14 TRANSECT 15 TRANSECT 16 TRANSECT 17 TRANSECT 18 TRANSECT 19 TRANSECT 20 TRANSECT 21 TRANSECT 22 TRANSECT 23 TRANSECT 24 TRANSECT 25 TRANSECT 26

GRID NORTH

SEC. 027

SEC. 030 | GULF OF MEXICO | SEC. 029 | SEC. 028

- 2015 DATA
- DENOTES CONTOURS
- DENOTES SETTLEMENT PLATES
- PIPELINES

STATE OF LOUISIANA
Ricardo M. Johnson
REG No. 4767
REGISTERED PROFESSIONAL LAND SURVEYOR

RICARDO M. JOHNSON
PROFESSIONAL LAND SURVEYOR
LOUISIANA REGISTRATION NO. 4767

NOTE: GPS observations at elevations based on reference Monument TE23 SM-01 using vertical datum of NAVD88 adjusted with Geoid12A.

Aerial Image taken in January 2015.

Proj. Mgr.: RMJ
Revised:
Printed: 3/6/15

COASTAL PROTECTION & RESTORATION
AUTHORITY OF LOUISIANA

WEST BELLE PASS BARRIER HEADLAND RESTORATION PROJECT
TOPOGRAPHIC & BATHYMETRIC SURVEY
PLAN VIEW
LAFOURCHE PARISH, LOUISIANA

JOHN CHANCE
LAND SURVEYS, INC.

GEODETIC DATUM: NAD83
PROJECTION: LOUISIANA SOUTH
GRID UNITS: US SURVEY FEET

SCALE IN FEET 0 1,000'

Job No.: 14-0587 | Date: 2/11/15 | Drwn: ECD | Chart: 1 Of: 2

Dwgfile: L:\2014\140587\CAD\E140587

T23S-R22E

SEC. 019 | SEC. 020 | SEC. 021 | SEC. 022

SEC. 030 | SEC. 029 | SEC. 028 | SEC. 027

TIMBALIER BAY

GULF OF MEXICO

GRID NORTH

TRANSECT 26 | TRANSECT 25 | TRANSECT 24 | TRANSECT 23 | TRANSECT 22 | TRANSECT 21 | TRANSECT 20 | TRANSECT 19 | TRANSECT 18 | TRANSECT 17 | TRANSECT 16 | TRANSECT 15 | TRANSECT 14 | TRANSECT 13 | TRANSECT 12 | TRANSECT 11 | TRANSECT 10 | TRANSECT 9 | TRANSECT 8 | TRANSECT 7 | TRANSECT 6 | TRANSECT 5 | TRANSECT 4 | TRANSECT 3 | TRANSECT 2 | TRANSECT 1

SP-1 | SP-2 | SP-3 | SP-4 | SP-5 | SP-6 | SP-7 | SP-8 | SP-9 | SP-10

2015 DATA
DENOTES CONTOURS
DENOTES SETTLEMENT PLATES
PIPELINES

RICARDO M. JOHNSON
PROFESSIONAL LAND SURVEYOR
LOUISIANA REGISTRATION NO. 4767

STATE OF LOUISIANA
Ricardo M. Johnson
REG No. 4767
REGISTERED PROFESSIONAL
LAND SURVEYOR

NOTE: GPS observations at elevations based on reference Monument TE23 SM-01 using vertical datum of NAVD88 adjusted with Geoid12A.

Aerial Image taken in January 2015.

Proj. Mgr.: RMJ
Revised:
Printed: 3/6/15

COASTAL PROTECTION & RESTORATION
AUTHORITY OF LOUISIANA

WEST BELLE PASS BARRIER HEADLAND RESTORATION PROJECT
TOPOGRAPHIC & BATHYMETRIC SURVEY
CONTOUR VIEW
LAFOURCHE PARISH, LOUISIANA

JOHN CHANCE
LAND SURVEYS, INC.

GEODETIC DATUM: NAD83
PROJECTION: LOUISIANA SOUTH
GRID UNITS: US SURVEY FEET

SCALE IN FEET 0 1,000'

Job No.: 14-0587 | Date: 2/11/15 | Drwn: ECD | Chart: 2 Of: 2

Dwgfile: L:\2014\140587\CAD\E140587